

# **FANUC AC SPINDLE MOTOR *βi* series**

## **DESCRIPTIONS**

- No part of this manual may be reproduced in any form.
- All specifications and designs are subject to change without notice.

The products in this manual are controlled based on Japan's "Foreign Exchange and Foreign Trade Law". The export from Japan may be subject to an export license by the government of Japan.

Further, re-export to another country may be subject to the license of the government of the country from where the product is re-exported. Furthermore, the product may also be controlled by re-export regulations of the United States government.

Should you wish to export or re-export these products, please contact FANUC for advice.

In this manual we have tried as much as possible to describe all the various matters.

However, we cannot describe all the matters which must not be done, or which cannot be done, because there are so many possibilities.

Therefore, matters which are not especially described as possible in this manual should be regarded as "impossible".

# SAFETY PRECAUTIONS

---

This "Safety Precautions" section describes the precautions which must be observed to ensure safety when using FANUC spindle motors.

Users of any spindle motor model are requested to read this manual carefully before using the spindle motor.

The users are also requested to read this manual carefully and understand each function of the motor for correct use.

The users are basically forbidden to do any behavior or action not mentioned in this manual. They are invited to ask FANUC previously about what behavior or action is prohibited.

For matters that are not described in this manual, a machine must be designed and assembled in accordance with EN60204-1 to ensure the safety of the machine and compliance with European specifications. For details, refer to the specification.

## Contents

|  |     |
|--|-----|
| DEFINITION OF WARNING, CAUTION, AND NOTE ..... | s-2 |
| WARNING .....                                  | s-3 |
| CAUTION .....                                  | s-5 |
| NOTE.....                                      | s-7 |
| CAUTION LABEL.....                             | s-9 |

## DEFINITION OF WARNING, CAUTION, AND NOTE

---

This manual includes safety precautions for protecting the user and preventing damage to the machine. Precautions are classified into Warning and Caution according to their bearing on safety. Also, supplementary information is described as a Note. Read the Warning, Caution, and Note thoroughly before attempting to use the machine.

**WARNING**

Applied when there is a danger of the user being injured or when there is a damage of both the user being injured and the equipment being damaged if the approved procedure is not observed.

**CAUTION**

Applied when there is a danger of the equipment being damaged, if the approved procedure is not observed.

**NOTE**

The Note is used to indicate supplementary information other than Warning and Caution.

- Read this manual carefully, and store it in a safe place.

## WARNING

---

|  |
|--|
|  <b>WARNING</b> |
|--|

**- Be safely dressed when handling a motor.**

Wear safety shoes or gloves when handling a motor as you may get hurt on any edge or protrusion on it or electric shocks.

**- Use a crane or lift to move a motor from one place to another.**

A motor is heavy. If you lift the motor by hand, you may get a backache, or you may be seriously injured when you drop the motor. A suitable crane or lift must be used to move the motor. (For the weight of motors, refer to this manual.)

When moving a motor using a crane or lift, use a hanging bolt if the motor has a corresponding tapped hole, or textile rope if it has no tapped hole. If a motor is attached with a machine or any other heavy stuff, do not use a hanging bolt to move the motor as the hanging bolt and/or motor may get broken.

**- Before starting to connect a motor to electric wires, make sure they are isolated from an electric power source.**

A failure to observe this caution is very dangerous because you may get electric shocks.

**- Be sure to secure power wires and short-bars.**

If operation is performed with a terminal loose, the terminal block may become abnormally hot, possibly causing a fire. Also, the terminal may become disconnected, causing a ground fault or short-circuit, and possibly giving you electric shocks. See the section in this manual that gives the tightening torque for attaching power wires and short-bars to the terminal block.

**- Be sure to ground a motor frame.**

To avoid electric shocks, be sure to connect the grounding terminal in the terminal box to the grounding terminal of the machine.

**- Do not ground a motor power wire terminal or short-circuit it to another power wire terminal.**

A failure to observe this caution may cause electric shocks or a burned wiring.

**- Do not supply the power to the motor while any terminal is exposed.**

A failure to observe this caution is very dangerous because you may get electric shocks if your body or any conductive stuff touches an exposed terminal.

**- Do not bring any dangerous stuff near a motor.**

Motors are connected to a power line, and may get hot. If a flammable is placed near a motor, it may be ignited, catch fire, or explode.

**⚠ WARNING****- Do not get close to a rotary section of a motor when it is rotating.**

You may get your clothes or fingers caught in a rotary section, and may be injured. Before starting a motor, ensure that there is no stuff that can fly away (such as a key) on the motor.

**- Do not touch a motor with a wet hand.**

A failure to observe this caution is vary dangerous because you may get electric shocks.

**- Before touching a motor, shut off the power to it.**

Even if a motor is not rotating, there may be a voltage across the terminals of the motor.

Especially before touching a power supply connection, take sufficient precautions.

Otherwise you may get electric shocks.

**- Do not touch any terminal of a motor for a while (at least 5 minutes) after the power to the motor is shut off.**

High voltage remains across power line terminals of a motor for a while after the power to the motor is shut off. So, do not touch any terminal or connect it to any other equipment. Otherwise, you may get electric shocks or the motor and/or equipment may get damaged.

**- To drive a motor, use a specified amplifier and parameters.**

An incorrect combination of a motor, amplifier, and parameters may cause the motor to behave unexpectedly. This is dangerous, and the motor may get damaged.

**- Before driving a motor, be sure to secure it.**

If a motor is drove without being secured, it may roll over during acceleration or deceleration, injuring the user.

## CAUTION

---

|  |
|--|
|  <b>CAUTION</b> |
|--|

- **Do not touch a motor when it is running or immediately after it stops.**

A motor may get hot when it is running. Do not touch the motor before it gets cool enough. Otherwise, you may get burned.

- **Be careful not get your hair or cloths caught in a fan.**

Be careful especially for a fan used to generate an inward air flow.

Be careful also for a fan even when the motor is stopped, because it continues to rotate while the amplifier is turned on.

- **FANUC motors are designed for use with machines. Do not use them for any other purpose.**

If a FANUC motor is used for an unintended purpose, it may cause an unexpected symptom or trouble. If you want to use a motor for an unintended purpose, previously consult with FANUC.

- **Ensure that a base or frame on which a motor is mounted is strong enough.**

Motors are heavy. If a base or frame on which a motor is mounted is not strong enough, it is impossible to achieve the required precision.

- **Ensure that motors and related components are mounted securely.**

If a motor or its component slips out of place or comes off when the motor is running, it is very dangerous.

- **Be sure to connect motor cables correctly.**

An incorrect connection of a cable cause abnormal heat generation, equipment malfunction, or failure. Always use a cable with an appropriate current carrying capacity (or thickness). For how to connect cables to motors, refer to their respective specification manuals.

- **Ensure that motors are cooled if they are those that require forcible cooling.**

If a motor that requires forcible cooling is not cooled normally, it may cause a failure or trouble. For a fan-cooled motor, ensure that it is not clogged or blocked with dust and dirt. For a liquid-cooled motor, ensure that the amount of the liquid is appropriate and that the liquid piping is not clogged. For both types, perform regular cleaning and inspection.

- **When attaching a component having inertia, such as a pulley, to a motor, ensure that any imbalance between the motor and component is minimized.**

If there is a large imbalance, the motor may vibrates abnormally, resulting in the motor being broken.

**CAUTION**

- **Be sure to attach a key to a motor with a keyed shaft.**

If a motor with a keyed shaft runs with no key attached, it may impair torque transmission or cause imbalance, resulting in the motor being broken. With the  $\beta i$  series, a shaft with no key is used as standard.



## NOTE

---

### NOTE

**- Do not step or sit on a motor.**

If you step or sit on a motor, it may get deformed or broken. Do not put a motor on another unless they are in packages.

**- When storing a motor, put it in a dry (non-condensing) place at room temperature (0 to 40 °C).**

If a motor is stored in a humid or hot place, its components may get damaged or deteriorated. In addition, keep a motor in such a position that its shaft is held horizontal and its terminal box is at the top.

**- Do not remove a nameplate from a motor.**

If a nameplate comes off, be careful not to lose it. If the nameplate is lost, the motor becomes unidentifiable, resulting in maintenance becoming impossible. For a nameplate for a built-in spindle motor, keep the nameplate with the spindle.

**- Do not apply shocks to a motor or cause scratches to it.**

If a motor is subjected to shocks or is scratched, its components may be adversely affected, resulting in normal operation being impaired. Be very careful when handling plastic portions, sensors, and windings, because they are very liable to break. Especially, avoid lifting a motor by pulling its plastic portion, winding, or power cable.

**- Do not conduct dielectric strength or insulation test for a sensor.**

Such a test can damage elements in the sensor.

**- When testing the winding or insulation resistance of a motor, satisfy the conditions stipulated in IEC34.**

Testing a motor under a condition severer than those specified in IEC34 may damage the motor.

**- Do not disassemble a motor.**

Disassembling a motor may cause a failure or trouble in it. If disassembly is in need because of maintenance or repair, please contact a service representative of FANUC.

**- Do not modify a motor.**

Do not modify a motor unless directed by FANUC. Modifying a motor may cause a failure or trouble in it.

**- Use a motor under an appropriate environmental condition.**

Using a motor in an adverse environment may cause a failure or trouble in it. Refer to their respective specification manuals for details of the operating and environmental conditions for motors.

**NOTE**

- **Do not apply a commercial power source voltage directly to a motor.**

Applying a commercial power source voltage directly to a motor may result in its windings being burned. Be sure to use a specified amplifier for supplying voltage to the motor.

- **For a motor with a terminal box, make a conduit hole for the terminal box in a specified position.**

When making a conduit hole, be careful not to break or damage unspecified portions. Refer to an applicable specification manual.

- **Before using a motor, measure its winding and insulation resistances, and make sure they are normal.**

Especially for a motor that has been stored for a prolonged period of time, conduct these checks. A motor may deteriorate depending on the condition under which it is stored or the time during which it is stored. For the winding resistances of motors, refer to their respective specification manuals, or ask FANUC. For insulation resistances, see the following table.

- **To use a motor as long as possible, perform periodic maintenance and inspection for it, and check its winding and insulation resistances.**

Note that extremely severe inspections (such as dielectric strength tests) of a motor may damage its windings. For the winding resistances of motors, refer to their respective specification manuals, or ask FANUC. For insulation resistances, see the following table.

**MOTOR INSULATION RESISTANCE MEASUREMENT**


Measure an insulation resistance between each winding and motor frame using an insulation resistance meter (500 VDC). Judge the measurements according to the following table.

| <b>Insulation resistance</b> | <b>Judgment</b>   |
|------------------------------|---|
| 100 MΩ or higher             | Acceptable  |
| 10 to 100 MΩ                 | The winding has begun deteriorating. There is no problem with the performance at present. Be sure to perform periodic inspection. |
| 1 to 10 MΩ                   | The winding has considerably deteriorated. Special care is in need. Be sure to perform periodic inspection.                       |
| Lower than 1 MΩ              | Unacceptable. Replace the motor.  |

## CAUTION LABEL

---

The following label is attached to the motor.  
Attach this label to a prominent place on the motor to call attention to the user.



Heat caution label  
(compliance with the IEC  
standard)

### Heat caution label

Since the motor is heated to a high temperature during operation or immediately after a stop, touching the motor may cause a burn. So, attach this label to a prominent place to call attention when the surface is exposed and may be touched.

#### Remark:

The mark of this label conforms to the IEC standard, which is a global standard.

The mark has the meaning of heat caution, so the description is omitted.



# PREFACE

---

The models covered by this manual, and their abbreviations are:

| <b>Series</b>      | <b>Model</b>  |
|--------------------|---|
| <i>βiI</i> series  | <i>βiI</i> 3/10000, <i>βiI</i> 6/10000, <i>βiI</i> 8/10000, <i>βiI</i> 12/8000    |
| <i>βiIP</i> series | <i>βiIP</i> 8/6000, <i>βiIP</i> 12/6000, <i>βiIP</i> 15/6000, <i>βiIP</i> 18/6000 |



# TABLE OF CONTENTS

---

|   |            |
|---|------------|
| <b>SAFETY PRECAUTIONS</b> .....   | <b>s-1</b> |
| DEFINITION OF WARNING, CAUTION, AND NOTE .....  | s-2        |
| WARNING .....   | s-3        |
| CAUTION .....   | s-5        |
| NOTE .....  | s-7        |
| CAUTION LABEL .....   | s-9        |
| <b>PREFACE</b> .....  | <b>p-1</b> |
| <b>I. MOTOR TYPES AND USAGE</b>   |            |
| <b>1 MOTOR TYPES</b> .....  | <b>3</b>   |
| <b>2 NOTES ON INSTALLATION</b> .....  | <b>4</b>   |
| 2.1 COMMON.....   | 5          |
| 2.2 METHOD OF USING THE MOTOR WITH CONSIDERATION GIVEN TO<br>ITS ENVIRONMENTAL RESISTANCE ..... | 11         |
| 2.3 POWER LEAD CONNECTION.....  | 19         |
| 2.4 FAN MOTOR CONNECTION .....  | 20         |
| 2.5 WHEN A MOTOR IS CONNECTED TO A SPINDLE VIA A BELT .....                                     | 22         |
| 2.6 WHEN A MOTOR IS CONNECTED TO A SPINDLE VIA A GEAR .....                                     | 26         |
| 2.7 WHEN A MOTOR IS DIRECTLY CONNECTED TO A SPINDLE VIA<br>A COUPLING.....                      | 27         |
| <b>3 NOTES ON OPERATION</b> .....   | <b>29</b>  |
| <b>4 DETERMINING THE ACCELERATION TIME</b> .....  | <b>30</b>  |
| <b>5 DETERMINING THE ALLOWABLE DUTY CYCLE</b> .....   | <b>31</b>  |
| <b>6 DISPOSAL OF SPINDLE MOTORS BY MATERIAL TYPE</b> .....                                      | <b>33</b>  |
| <b>II. FANUC AC SPINDLE MOTOR <math>\beta</math>iI SERIES</b>                                   |            |
| <b>1 GENERAL</b> .....  | <b>37</b>  |
| <b>2 SPECIFICATIONS</b> .....   | <b>38</b>  |
| <b>3 OUTPUT/TORQUE CHARACTERISTICS</b> .....  | <b>40</b>  |
| 3.1 MODEL $\beta$ iI 3/10000.....   | 41         |
| 3.2 MODEL $\beta$ iI 6/10000.....   | 41         |
| 3.3 MODEL $\beta$ iI 8/10000.....   | 42         |

|          |   |           |
|----------|---|-----------|
| 3.4      | MODEL $\beta i\bar{I}$ 12/8000.....                         | 42        |
| <b>4</b> | <b>CONNECTIONS .....</b>                                    | <b>43</b> |
| 4.1      | CONNECTION OF POWER LEAD AND FAN MOTOR CABLE .....          | 44        |
| 4.2      | CONNECTION OF SIGNAL LEAD .....                             | 45        |
| <b>5</b> | <b>ALLOWABLE RADIAL LOAD .....</b>                          | <b>46</b> |
| <b>6</b> | <b>ASSEMBLING ACCURACY .....</b>                            | <b>47</b> |
| <b>7</b> | <b>EXTERNAL DIMENSIONS.....</b>                             | <b>48</b> |
| 7.1      | MODEL $\beta i\bar{I}$ 3/10000 (FLANGE MOUNTING TYPE) ..... | 49        |
| 7.2      | MODEL $\beta i\bar{I}$ 3/10000 (FOOT MOUNTING TYPE).....    | 50        |
| 7.3      | MODEL $\beta i\bar{I}$ 6/10000 (FLANGE MOUNTING TYPE) ..... | 51        |
| 7.4      | MODEL $\beta i\bar{I}$ 6/10000 (FOOT MOUNTING TYPE).....    | 52        |
| 7.5      | MODEL $\beta i\bar{I}$ 8/10000 (FLANGE MOUNTING TYPE) ..... | 53        |
| 7.6      | MODEL $\beta i\bar{I}$ 8/10000 (FOOT MOUNTING TYPE).....    | 54        |
| 7.7      | MODEL $\beta i\bar{I}$ 12/8000 (FLANGE MOUNTING TYPE) ..... | 55        |
| 7.8      | MODEL $\beta i\bar{I}$ 12/8000 (FOOT MOUNTING TYPE).....    | 56        |

## II. FANUC AC SPINDLE MOTOR $\beta i\bar{I}_P$ SERIES

|          |   |           |
|----------|---|-----------|
| <b>1</b> | <b>GENERAL .....</b>  | <b>59</b> |
| <b>2</b> | <b>SPECIFICATIONS.....</b>                                    | <b>60</b> |
| <b>3</b> | <b>OUTPUT/TORQUE CHARACTERISTICS .....</b>                    | <b>62</b> |
| 3.1      | MODEL $\beta i\bar{I}_P$ 8/6000 .....                         | 63        |
| 3.2      | MODEL $\beta i\bar{I}_P$ 12/6000 .....                        | 63        |
| 3.3      | MODEL $\beta i\bar{I}_P$ 15/6000 .....                        | 64        |
| 3.4      | MODEL $\beta i\bar{I}_P$ 18/6000 .....                        | 64        |
| <b>4</b> | <b>CONNECTIONS .....</b>                                      | <b>65</b> |
| 4.1      | CONNECTION OF POWER LEAD AND FAN MOTOR CABLE .....            | 66        |
| 4.2      | CONNECTION OF SIGNAL LEAD .....                               | 67        |
| <b>5</b> | <b>ALLOWABLE RADIAL LOAD .....</b>                            | <b>68</b> |
| <b>6</b> | <b>ASSEMBLING ACCURACY .....</b>                              | <b>69</b> |
| <b>7</b> | <b>EXTERNAL DIMENSIONS.....</b>                               | <b>70</b> |
| 7.1      | MODEL $\beta i\bar{I}_P$ 8/6000 (FLANGE MOUNTING TYPE) .....  | 71        |
| 7.2      | MODEL $\beta i\bar{I}_P$ 8/6000 (FOOT MOUNTING TYPE).....     | 72        |
| 7.3      | MODEL $\beta i\bar{I}_P$ 12/6000 (FLANGE MOUNTING TYPE) ..... | 73        |
| 7.4      | MODEL $\beta i\bar{I}_P$ 12/6000 (FOOT MOUNTING TYPE).....    | 74        |



|     |  |    |
|-----|--|----|
| 7.5 | MODEL $\beta iIP$ 15/6000 (FLANGE MOUNTING TYPE) ..... | 75 |
| 7.6 | MODEL $\beta iIP$ 15/6000 (FOOT MOUNTING TYPE).....    | 76 |
| 7.7 | MODEL $\beta iIP$ 18/6000 (FLANGE MOUNTING TYPE) ..... | 77 |
| 7.8 | MODEL $\beta iIP$ 18/6000 (FOOT MOUNTING TYPE).....    | 78 |



# **I. MOTOR TYPES AND USAGE**



# 1

## MOTOR TYPES

Each model includes the types of motors listed below, and the user can make an optimal choice according to the spindle driving structure. See the ordering list (B-65311EN) for available motors.

| Item                          | Type  | Use  | Remarks   |
|-------------------------------|---|--|---|
| Mounting types                | Flange mounting type  | Connected to spindle via a gear<br>Directly connected to a spindle<br>Connected to spindle via a belt                      | The motor can be positioned accurately.   |
|                               | Foot mounting type  | Connected to spindle via a belt  |   |
| Built-in sensor               | $\alpha iM$ sensor  | When connected to the spindle via a belt or gear at a deceleration ratio other than 1:1<br>(When the spindle has a sensor) | For a detailed explanation, refer to the following descriptions:<br>FANUC SERVO AMPLIFIER $\beta i$ series DESCRIPTIONS (B-65322EN)   |
|                               | $\alpha iMZ$ sensor   | When connected to the spindle via a belt, gear, or coupling on a 1:1 basis<br>(When the spindle has no sensor)             |   |
| Shaft figure                  | With no key   | Connected to a pulley  | A shaft with no key is used as standard to facilitate pulley and gear balance correction and acceleration/ deceleration operation.<br>When a shaft with a key is needed, contact your FANUC sales representative. |
| Cooling air exhaust direction | Rearward exhaust<br>(Exhaust from side opposite the output shaft) | When the machine is positioned at the output shaft side  | Direct the exhaust out and away from the machine.   |
|                               | Forward exhaust<br>(Exhaust from the output shaft side)           | When the machine is positioned at the side opposite the output shaft   |   |
| Output shaft seal             | Oil seal  | Gear connection, direct connection, and belt driving   | Used in flange mounting type standard-speed models.   |
|                               | Labyrinth   | Belt driving and direct connection<br>(Only when no lubricant or coolant splashes onto the flange surface of the motor)    |   |
|                               | No seal   | Belt driving<br>(Only when no lubricant splashes onto the flange surface of the motor)                                     | Foot-mounting type models have no output shaft seal, but can be changed to a model with an oil seal or labyrinth.<br>For the models that can be changed, refer to "Order List" (B-65311EN).                       |

# 2

## NOTES ON INSTALLATION

---

Chapter 2, "NOTES ON INSTALLATION", consists of:

|     |   |    |
|-----|---|----|
| 2.1 | COMMON .....  | 5  |
| 2.2 | METHOD OF USING THE MOTOR WITH<br>CONSIDERATION GIVEN TO ITS ENVIRONMENTAL<br>RESISTANCE..... | 11 |
| 2.3 | POWER LEAD CONNECTION .....   | 19 |
| 2.4 | FAN MOTOR CONNECTION .....  | 20 |
| 2.5 | WHEN A MOTOR IS CONNECTED TO A SPINDLE VIA A<br>BELT.....                                     | 22 |
| 2.6 | WHEN A MOTOR IS CONNECTED TO A SPINDLE VIA A<br>GEAR.....                                     | 26 |
| 2.7 | WHEN A MOTOR IS DIRECTLY CONNECTED TO A<br>SPINDLE VIA A COUPLING .....                       | 27 |

## 2.1 COMMON


Be sure to observe the following, regardless of the connection method of the motor:

**WARNING**

When connecting a metallic conduit to a plastic terminal box, connect the conduit to ground on the power magnetics cabinet side.


**CAUTION**

- 1 Mount the motor so that the output shaft points in a direction ranging within 45 degrees above the horizontal to vertically downwards.
- 2 When the motor needs to be pointed to more than 45 degrees above the horizontal, consult you FANUC representative.



- 3 Use the eyebolt of the motor to lift only a single motor, (gear and pulley may be attached).

- 4 Place a cover over an air-cooled motor to prevent the motor from being exposed to coolant or lubricant.
- 5 Limit the vibration acceleration at the rear bracket of the motor to 0.5 G ( $4.9 \text{ m/s}^2$ ) to ensure the long-term reliability of each part of the motor.  
 In particular, to limit the acceleration in the case of direct connection to 0.5 G, carefully perform centering with the mating spindle and make the motor shaft parallel with the spindle.
- Details of the measuring method  
 Measuring instrument:  
 Equivalent to the VM-3314A or VM-3304 manufactured by IMV CORPORATION.  
 Condition: At the time of highest-speed rotation with no load  
 Measurement frequency range with no load at the highest speed:  
 10 to 1000 Hz  
 Criteria: 0.5 G ( $4.9 \text{ m/s}^2$ ) or less at the rear bracket





## 6 Dynamic balance

During high-speed operation, a small imbalance may cause a large vibration, resulting in an unusual sound, premature bearing damage, or some other abnormality.

Therefore, reduce the amount of the imbalance with the dynamic balance of the other rotation shafts, as well as the gear and pulley mounted on the output shaft of the motor, as much as possible.

- Balance correction


With the  $\beta i$  series, a shaft with no key is used as standard to facilitate the balance correction of a pulley, gear, and coupling attached to the shaft. Use a completely symmetric pulley, gear, or coupling, and use a backlash-less tightening part such as a SPANN ELEMENTE to secure a pulley, gear, or coupling to the shaft. When attaching a pulley to a shaft, for example, adjust the periphery vibration to within 20  $\mu\text{m}$ . This basically eliminates the need for balance correction. To further reduce the vibration level, make a field balance correction, for example, by tightening a screw into the tapped hole for balance correction provided on a component such as a pulley.

**NOTE**


When a shaft with a key is required, contact your FANUC sales representative.

7 Vibrations applied to the motor must be 5Gs or less in a state where the motor is attached to the machine.

8 The edge of the fauset joint to mount the flange mounting type motor should be chamfered about C1.




- 9 Please space 30 mm or more between the fan cover and the partition to keep the cooling ability well.  
We recommend to take a structure such as you can clean air holes and the fan cover easily.



### NOTE

- 1 Cable wiring  
Follow the procedure below to install the cable.
- (1) Use a hammer to strike the portion for the cable hole on the terminal box and open the hole.  
This time, pay attention not to break the other place except hole.
  - (2) Thread the cable through a conduit. Connect the conduit with the connector.
  - (3) Tighten the connector at the cable hole of the terminal box using a nut. (\*1, \*2)
  - (4) Connect each terminal appropriately in the terminal box with screws.




When a hole once made is not used, purchase the following rubber bushing and mount it at the hole.

| Model   | Ordering number |
|---|-----------------|
| $\beta iI$ 3/10000 to $\beta iI$ 12/8000<br>$\beta iIp$ 8/6000 to $\beta iIp$ 18/6000 | A06B-0754-K001  |

\*1 When the 90 degrees connector is used in the following models, the mounting direction of the conduit is restricted to prevent interference between the conduit and the motor. To allow the conduit to be mounted in any direction, use the 45 degrees connector.


(In a model other than the following, the conduit can be mounted in any direction even when the 90 degrees connector is used.)

Applicable models:  $\beta iIp$  15/6000,  $\beta iIp$  18/6000




\*2 The nut used to fasten the connector to the terminal box must be smaller than the size listed below. (Any larger nut interferes with the terminal box.) For the diameter of the cable hole in each model, refer to the outside dimension drawing of the respective models.

| Cable hole diameter | Outside diameter e | Width t        |
|---------------------|--------------------|----------------|
| φ42.5 mm            | 53 mm (maximum)    | 9 mm (maximum) |



2 Center of gravity  
 The distance L from the flange end face to the center of gravity in each model is listed below.



| $\beta i I$ series  | $\beta i I P$ series  | Center of gravity [mm] |
|---------------------|-----------------------|------------------------|
| $\beta i I$ 3/10000 |                       | 125±5                  |
| $\beta i I$ 6/10000 |                       | 170±5                  |
| $\beta i I$ 8/10000 | $\beta i I P$ 8/6000  | 150±5                  |
| $\beta i I$ 12/8000 | $\beta i I P$ 12/6000 | 185±5                  |
|                     | $\beta i I P$ 15/6000 | 160±5                  |
|                     | $\beta i I P$ 18/6000 | 180±5                  |

## 2.2 METHOD OF USING THE MOTOR WITH CONSIDERATION GIVEN TO ITS ENVIRONMENTAL RESISTANCE

---

### CAUTION

The motor is an electric part, and if the lubricant or cutting fluid falls on the motor, it will enter the inside of the motor, possibly adversely affecting the motor. In particular, if the cutting fluid adheres to the motor, it will deteriorate the resin or rubber sealing members, causing a large amount of cutting fluid to enter the inside of the motor and possibly damaging the motor. When using the motor, note the points described below.

### 1. Level of motor protection

According to IEC 60034-5, the models equipped with an oil seal comply with the degree of protection IP54, and the other models comply with IP40. Even for the models complying with IP40, their motor main body excluding the output shaft end (with a simple labyrinth for the high-speed models or with no seal for the foot mounting type models) complies with IP54.

IP5x : Machine protected from dust

- Ingress of dust is not totally prevented, but dust does not enter in sufficient quantity to interfere with satisfactory operation of the motor.

IP4x : Machine protected from introduction of solid foreign matter over 1.0 mm

- Electric cables and wires with a diameter or thickness greater than 1.0 mm do not enter.

IPx4 : Machine protected from water spray

- Water sprayed on the motor from any direction will have no harmful effect.

IPx0 : Machine not protected


- No special protection is provided to prevent ingress of water.

Note that these models satisfy the provisions for short-time water immersion, and do not guarantee their water-proof performance in an atmosphere in which cutting fluid is applied directly to the motor. Before actual use, note the points described below.

## 2. Motor periphery

If the cutting fluid or lubricant falls on the motor, it will adversely affect the sealing properties of the motor surface, entering the inside of the motor and possibly damaging the motor.


- Make sure that the motor surface is never wet with the cutting fluid or lubricant, and also make sure that no fluid builds up around the motor. If there is a possibility of the surface being wet, a cover is required.



- If the cutting fluid is misted, the cutting fluid may be condensed on the inside of the cover and fall on the motor. Make sure that no condensed droplets fall on the motor.
- If the inside of the machine is full of misted cutting fluid, the cutting fluid adhered to the motor can enter the inside of the motor and damage the motor. Install a mist collector with an appropriate capacity to prevent the inside of the machine from becoming full of mist.
- Completely separate the machining area from the motor area, using a telescopic cover, accordion curtain, and so on. Note that partitions such as accordion curtains are consumable and require periodic inspection for damage.

### 3. Output shaft seal

To prevent cutting lubricant or dust from penetrating inside the motor, one of the following output shaft seals is provided on the output shaft. (For the use and applicable motors, see Chapter 3, "MOTOR TYPES.")



For those models with an oil seal, ensure that the surface of the lubricant is below the lip of the oil seal.


If a simple labyrinth is used as the output shaft seal or if no seal is provided (foot mounting type), ensure that lubricant does not splash onto the flange surface. If such a motor is directly mounted on a gear box, the lubricant may gradually penetrate inside the motor even when no lubricant splashes on flange surface, thus resulting in motor failure. Therefore, do not mount such a motor on a gear box directly.

When the motor is used in an environment in which lubricant does not splash onto the motor, the simple labyrinth type instead of the oil seal type may be selected. Generally in a dry environment, the motor temperature of the simple labyrinth type will increase more moderately than that of the oil seal type.

### 3.1 oil seal

The shaft of the motor is provided with an oil seal to prevent entry of lubricant and other fluids into the motor. (The foot mounting type is excluded.) It does not, however, completely prevent the entry of lubricant and other fluids depending on the working conditions.

- When the motor is rotating, the oil seal has an effect of discharging any oil that enters, but if it is pressurized for a long time when the motor is stopped, it may allow oil to enter through the lip. When lubrication with an oil bath is conducted for gear engagement, for example, the oil level must be below the lip of the oil seal of the shaft, and the oil level must be adjusted so that the oil does nothing but splash on the lip.



Diameters of the oil seal lips of motor shafts

| Motor model  | Oil seal diameter [mm] |
|--|------------------------|
| $\beta i I$ 3/10000, $\beta i I$ 6/10000, $\beta i I$ 8/10000<br>$\beta i IP$ 8/6000 | $\phi$ 40              |
| $\beta i I$ 12/8000, $\beta i IP$ 12/6000  | $\phi$ 50              |
| $\beta i IP$ 15/6000, $\beta i IP$ 18/6000   | $\phi$ 60              |

- If foreign matter such as cutting chips is caught by the oil seal lip, it will be easily worn, losing its sealing properties. When the motor is used within a splash guard, and so cutting chips may fall on the motor, for example, take measures to prevent cutting chips from entering near the lip.
- In an environment in which dry and wet states alternate, if cutting fluid splashes onto the lip after it has worn in a dry state, the cutting fluid may easily enter the inside of the motor. In this case, provide a cover to prevent cutting fluid from splashing onto the oil seal of the motor.
- Ensure that no pressure is applied to the lip of the oil seal.
- The oil seal shows its sealing effect when a part such as the gear coupling is lubricated by oil bath. Cutting fluid does not provide lubrication for the oil seal lip, so the cutting fluid may easily penetrate the seal. Therefore, provide a cover to prevent cutting fluid from splashing onto the oil seal.



### 3.2 When the oil seal is not used

When a simple labyrinth is used as the output shaft seal or when no seal is provided (foot mounting type), ensure that lubricant does not splash onto the flange surface directly. If such a motor is directly mounted on a gear box, lubricant may gradually enter the inside of the motor even when the flange surface is protected against lubricant splash, therefore resulting in motor failure. So, do not mount such a motor on a gear box directly.

#### NOTE

- 1 The foot mounting type motors are not equipped with an oil seal. When an oil seal is necessary, add #0002 to a motor drawing number when ordering the motor. For details, refer to the order list (B-65311EN).

Example)

Model  $\beta$ I 12/8000 (foot mounting type, with no key, rear exhaust)

To add an oil seal to A06B-1447-B200, order A06B-1447-B200#0002 .

- 2 When lubricant does not splash onto the oil seal, remove the coil spring of the oil seal to reduce friction between the lip and shaft.


This does not affect sealing from dry dust.

When the area in which the shaft touches the oil seal is dry, turning the shaft at a high speed may generate contact sound (abnormal sound) from that area or may damage the lip.

### 4. Motor coupling


When a coupling box is used to connect the motor to the machine, take measures as follows not to allow leaked cutting fluid to build up in the coupling box.

- Provide a cover for the top and sides of the coupling box.
- Provide a drain hole at the bottom of the coupling box. The hole must be large enough to avoid clogging.



#### <Fault example>


The cutting fluid leaks from a gap in the accordion curtain to the motor area, and builds up in the coupling box. While the spindle is moving, the cutting fluid ripples, splashing onto the oil seal of the motor. The cutting fluid enters the inside of the motor there in large quantities, deteriorating the insulation of the motor.




### 5. Terminal box and their surroundings

$\beta$ I series and  $\beta$ IP series use a terminal box to connect the power and signal cables.

- When a conduit is attached to the terminal box, use a water-proof connector with rubber packings to prevent lubricant and cutting fluid from entering the inside of the terminal box through its cable holes.
- On the inner side of the upper lid of the terminal box, a rubber water-proof packing is installed. Ensure that the packings are not damaged, then install the lid so that no foreign matter is caught.



- If the connector you want to use is smaller than the cable hole on the terminal box, prepare the bushing, nut, and O-ring shown below.



| Cable hole diameter<br>$\phi D$ | O-ring code |            |
|---------------------------------|-------------|------------|
|                                 | JIS B 2401  | ISO 3601-1 |
| $\phi 42.5$ mm                  | P46         | C0462G     |

**NOTE**


For the diameter of the cable hole in each model, refer to the outside dimension drawing of the respective models.

## 6. Fan motor and its surroundings

If lubricant or cutting fluid mist, particles, or cutting chips are drawn into the fan motor, the air holes in the motor and the blades of the fan motor will clog, causing the cooling capacity to reduce. Employ a machine structure that allows clean, cooling air to be fed into the motor.

Example)

When a duct with a filter is installed on a flange mounting type motor with a rear exhaust (The filter requires periodic cleaning.)



## 7 Notes on cutting fluid

Cutting fluid containing highly active sulfur, oil-free cutting fluid called synthetic cutting fluid, and highly alkaline, water-soluble cutting fluid in particular significantly affect the CNC, motor, or amplifier. Even when these components are protected from direct spraying of cutting fluid, problems as described below may arise. So special care should be taken.

- Cutting fluid containing highly active sulfur  
Some cutting fluids containing sulfur show extremely high activity of sulfur. Ingress of such cutting fluid into the CNC, motor, or amplifier can cause corrosion of copper, silver, and so on used as parts' materials, therefore resulting in parts' failures.
- Synthetic cutting fluid with high permeability  
Some synthetic type cutting fluids that use polyalkylene glycol (PAG) as a lubricant have extremely high permeability. Such cutting fluid can easily penetrate into the motor even if the motor is sealed well. Ingress of such cutting fluid into the CNC, motor, or amplifier can degrade insulation or lead to parts' failures.
- Highly alkaline, water-soluble cutting fluid  
Some cutting fluids that strengthen pH by alkanolamine show strong alkalinity of pH10 or higher when diluted to the standard level. Ingress of such cutting fluid into the CNC, motor, or amplifier can cause chemical reaction with plastic and so on and deteriorate them.

## 2.3 POWER LEAD CONNECTION

### WARNING

To attach the power leads, follow the procedure described in this section to make connections with specified torque. Driving a motor with terminals loosened could result in the terminal board overheating and causing a fire. In addition, it may remove terminal to cause a ground fault, short circuit, or electric shock.

### CAUTION

1. When attaching the power leads to the terminal board of a motor, tighten the screws with torque specified in the table. For the terminal size of a terminal board, refer to Chapter 4, "CONNECTIONS" in the manual of the corresponding series.

| Terminal size | Tightening torque [N·m] |
|---------------|-------------------------|
| M4            | 1.1 to 1.5              |
| M5            | 2.0 to 2.5              |

2. To maintain the required isolation distance, observe the following:
  - When attaching a crimp terminal at the end of a power lead, cover the crimped portion of the crimp terminal with insulating tube.

## 2.4 FAN MOTOR CONNECTION

### Fan motor current values

| $\beta iI$ , $\beta iIP$ series<br>spindle motor models                            | 50Hz                  |                         |                         |                           | 60Hz                  |                         |                         |                           |
|--|-----------------------|-------------------------|-------------------------|---------------------------|-----------------------|-------------------------|-------------------------|---------------------------|
|  | Usable<br>voltage [V] | Rated<br>voltage<br>[V] | Rated<br>current<br>[A] | Surge<br>current<br>[App] | Usable<br>voltage [V] | Rated<br>voltage<br>[V] | Rated<br>current<br>[A] | Surge<br>current<br>[App] |
| $\beta iI$ 3/10000, $\beta iI$ 6/10000,  | 170-240               | 200                     | 0.10                    | 0.41                      | 170-240               | 200                     | 0.10                    | 0.40                      |
| $\beta iI$ 8/10000, $\beta iI$ 12/8000,<br>$\beta iIP$ 8/6000, $\beta iIP$ 12/6000 | 170-240               | 200                     | 0.13                    | 0.50                      | 170-240               | 200                     | 0.14                    | 0.51                      |
| $\beta iIP$ 15/6000, $\beta iIP$ 18/6000   | 170-240               | 200                     | 0.22                    | 1.15                      | 170-240               | 200                     | 0.32                    | 1.10                      |

#### NOTE

- 1 The term "surge current" represents a peak-to-peak current that flows when the power is turned on.
- 2 The values listed below are a rough standard. They are not guaranteed.

### Cable for the fan motor

The machine tool builder is to prepare the following cable for the fan motor:


Vinyl heavy-duty power cord JIS C 3312 3-conductor

Conductor: 37/0.26 (2 mm<sup>2</sup>)


Sheath: PVC $\phi$ 11

Crimp terminal: T2-4S

For a non-screw terminal block (Peel off each wire sheath on the motor side by 8 to 9 mm.)



## Method of connection to a non-screw terminal for the fan motor




### Peel-off length of a wire sheath

By using an appropriate tool, peel off each wire sheath by 8 to 9 mm.

### Screwdriver

Use a flat-blade screwdriver with a blade size of  $3.5 \times 0.5$  mm. (210-120J (standard type), 210-350J (short type) manufactured by WAGO)


### Connection procedure




- <1> Insert the tip of the screwdriver into the screwdriver insertion slot (small rectangular hole) until the tip touches the spring. Next, while tilting the screwdriver toward the inside of the terminal block, push the screwdriver until it butts the conductive plate. In this state, the spring is opened completely, and the screwdriver is held in the terminal block. Ensure that the screwdriver is secured. Otherwise, the next step (wire insertion) cannot be conducted easily.
- <2> Check the peel-off length (8 to 9 mm), then insert the wire into the wire insertion slot (large rectangular hole) until it stops, by sliding the wire along the outer side of the hole slowly so that the conductor does not become loose. Be careful not to push a thin wire excessively.
- <3> While holding down the inserted wire by one hand, extract the screwdriver. The spring is closed to make a connection.
- <4> By slightly pulling the wire, check that the wire is connected firmly. The wire need not be pulled intensely.

### Cautions

- Only one wire must be connected to one spring.
- A wire, which may be a stranded wire or single conductor, can be directly connected without performing terminal processing if its sheath is peeled off. A wire after ferrule processing can also be connected.



Inside the terminal box



State of cable connection

## 2.5 WHEN A MOTOR IS CONNECTED TO A SPINDLE VIA A BELT

### CAUTION


- 1 Mounting the pulley
  - The gap between the inner surface of the motor pulley and output shaft should be  $10\mu\text{m}$  to  $15\mu\text{m}$ .
  - If the gap is large when the high-speed rotation ( $4500\text{ min}^{-1}$ ), fretting produced at the gap causes a large vibration, resulting in damage to the motor bearing.
  - As the vibration is intensified, fretting occurs in the gap mentioned above, and the pulley and shaft can stick to each other.
  - To secure a pulley, use a friction-tightening part such as a SPANN ELEMENTE or clamping sleeve.

### NOTE


The SPANN ELEMENTE RfN8006 is manufactured by RINGFEDER.

The clamping sleeve DSM is manufactured by SPIETH.

Example 1 Two sets of SPANN ELEMENTE RfN8006 are used. The collar is pinched at two points by the two sets.




Example 2 Clamping sleeve DSM is used.



- 2 After attaching a pulley to the motor, adjust the vibration of the belt groove to within  $20\mu\text{m}$  (T.I.R).
- 3 Before the belt is looped, FANUC recommends that the dynamic balance (field balance) be corrected.



- 4 Limit the radial load applied to the motor output shaft by the tension of the belt to the allowable value described in the manual for each series. If the allowable value is exceeded, the bearing or shaft may fail prematurely.
- 5 The tension of the belt is reduced as a result of abrasion during the initial several hours of operation. To transfer torque normally after this reduction in tension, the initial tension before operation should be set to a value 1.3 times the actually required tension  $T$ .



Recommended belts:

Ribace manufactured by BANDO.

Ribstar manufactured by MITSUBOSHI.

- 6 Use an appropriate tension gage to tension the belt.

Examples


Sonic type:

U-305 series manufactured by UNITTA.


Mechanical type:

BT-33-73F manufactured by KENT-MOORE of the United States

A mechanical type tension gage may give a false reading depending on the belt's number of peaks and length. To overcome this problem, hang an object of a known weight on the belt, read the tension value, then adjust the tension gage.



- 7 Reduce the deviation between the positions of the motor and machine pulleys in the shaft direction as much as possible and ensure that the center lines of the shafts are as parallel as possible.



## Example of belt design

Design must be made so that the static axial load by a belt that was subject to initial wear does not exceed the allowable radial load for each model. (A new belt is subject to initial wear after several hours operation and the static axial load becomes equal to that for the restretched belt in the following table.)

| Motor model  | $\beta i I$ 3/10000 | $\beta i I$ 6/10000 | $\beta i I$ 8/10000 | $\beta i I$ 12/8000 |
|--|---------------------|---------------------|---------------------|---------------------|
| Designed power<br>(15 min. rated output $\times$ 1.1) [kW] | 6.1                 | 8.3                 | 12.1                | 16.5                |
| Belt type  | 5M (5MS)            | 5M (5MS)            | 5M (5MS)            | 7M (7MS)            |
| Pulley dia. on the spindle side (PCD) [mm]                 | $\phi$ 165          | $\phi$ 165          | $\phi$ 210          | $\phi$ 210          |
| Pulley dia. on the motor side (PCD) [mm]                   | $\phi$ 132          | $\phi$ 132          | $\phi$ 168          | $\phi$ 168          |
| Gear reduction ratio                                       | 0.80                | 0.80                | 0.80                | 0.80                |
| Motor max. speed [min <sup>-1</sup> ]                      | 8,000               | 8,000               | 6,000               | 6,000               |
| Belt surface speed<br>(at the max. motor speed) [m/s]      | 55.3                | 55.3                | 52.8                | 52.8                |
| Number of belt crests                                      | 4                   | 6                   | 7                   | 4                   |
| Static axial load for new belts [N]                        | 1,200               | 1,638               | 1,904               | 2,604               |
| Static axial load for re-stretched belts [N]               | 923                 | 1,260               | 1,464               | 2,003               |
| Allowable radial load<br>(at the output axis center) [N]   | 999                 | 1,607               | 2,205               | 3,371               |


### NOTE

- 1 Prevent oil or dust from entering between the belt and the pulley. Otherwise, the belt may slip.
- 2 If the allowable radial load is exceeded, reduce the load by using support bearings on the machine side or directly connecting to the machine in order to secure reliability for a extended period of time.

## 2.6 WHEN A MOTOR IS CONNECTED TO A SPINDLE VIA A GEAR

**CAUTION**

- 1 Do not use a helical gear which applies a load in the motor axial direction.
- 2 To prevent unusual gear sounds, apply the following precautions:
  - (1) The deviation of the gear tooth surface should indicate the proper value.  
(Tip) Measuring the deviation of a gear tooth surface



- (2) The correct backlash should be provided.
  - (3) The perpendicularity of the motor flange mounting surface to the machine shaft should indicate the proper value.
- 3 Mount the motor on the machine so that the vibration acceleration is 0.5 G or less when it is measured using the method described in CAUTION 5 of Section 2.1.


## 2.7 WHEN A MOTOR IS DIRECTLY CONNECTED TO A SPINDLE VIA A COUPLING

### CAUTION

- 1 When connecting the spindle and motor shaft, be sure to use a flexible coupling.

(Flexible coupling examples)

- Diaphragm coupling (EAGLE INDUSTRY CO., LTD.)
- Oldham's coupling
- Gear coupling (MIKI PULLEY)



**Example of disk coupling**

Flexible coupling has three tolerances of degree of freedom: eccentricity, declination, and axial displacement. This enables coupling with less vibration and less noise to achieve high-speed rotation.

- Tolerances of eccentricity and declination: Slight eccentricity and declination that could not be absorbed by centering are absorbed.
- Tolerance of axial displacement: Extension of the spindle and motor shaft due to temperature increase is absorbed.

(Caution)

- These tolerances are criteria for preventing the coupling from being damaged, not criteria for preventing load from being applied to the spindle and motor bearings. Therefore, to perform rotation with low vibration and low noise before high-speed rotation is achieved, the spindle and motor shaft must be centered.
  - FANUC has confirmed that with a coupling (disk coupling) that permits only the degrees of freedom of declination and axial displacement, rotation can take place properly if centering has been performed with a concentricity of 5  $\mu\text{m}$ .
- 2 It is important to perform centering and obtain parallelism to avoid having to recourse to the flexibility of the coupling. At high speeds, any eccentricity may cause the bearing to fail prematurely.
  - 3 Check all machines before shipping to confirm that the vibration acceleration is 0.5 G or less when measured using the method described in CAUTION 5 of Section 2.1.

- 4 Set the torsional rigidity of the coupling to an appropriate high value. If the torsional rigidity is low, vibration may be produced during orientation.
- 5 When attaching the coupling to the motor shaft, never use a hammer or the like; otherwise, impact load is applied to the bearing.

# 3

## NOTES ON OPERATION

### WARNING

- 1 When supplying voltage to the spindle motor or the fan motor, ensure that the earth cable is connected to the earth terminal and secure that the spindle motor is put to earth certainly. In addition, be sure to check that the power cable are secured to the terminal block.

### CAUTION

- 1 Sound and vibration  
Check that there is no abnormal sound or vibration.
- 2 Cooling  
Clean off dust from the cooling air inlet and outlet of the stator every year, and check the flow of air carefully. The table given below indicates the direction of the rotation of the cooling fan when viewed from the rear side of the motor. Check that the actual rotating direction is correct.

| Model names | Rear exhaust<br>(Exhaust on side<br>opposite to load axis) | Front exhaust<br>(Exhaust on load axis<br>side) |
|-------------|--|---|
| All models  | Counterclockwise<br>(CCW)                                  | Clockwise<br>(CW)                               |

### NOTE

- 1 To increase the operating lifetime of a motor of these series, break in the motor. As a guideline, increase the speed of the motor from 1000 min<sup>-1</sup> to its maximum speed in 1000 min<sup>-1</sup> increments, and operate the motor at each speed for about 5 minutes.


# 4

## DETERMINING THE ACCELERATION TIME

Estimated output during acceleration is the 15 minutes rated output for each model multiplied by 1.1.

The time required for each acceleration for the acceleration/deceleration output characteristics shown below can be obtained from the following equation.

Since machine load torque is not taken into consideration, the actual time is slightly longer than the calculated time.



|                 |  |
|-----------------|--|
| $J_L$           | : Load inertia converted for the motor shaft [kgm <sup>2</sup> ] |
| $J_m$           | : Motor inertia [kgm <sup>2</sup> ]                              |
| $P_o, P_m$      | : Output [kW]  |
| $N_b, N_f, N_m$ | : Motor speed [min <sup>-1</sup> ]                               |

<1> Acceleration time ( $t_1$ ) in the constant-torque range (0 to  $N_b$ )

$$t_1 = 0.01097 \frac{(J_L + J_m) \cdot N_b^2}{P_o \cdot 1000} [\text{sec}]$$

<2> Acceleration time ( $t_2$ ) in the constant-output range ( $N_b$  to  $N_f$ )

$$t_2 = 0.01097 \frac{(J_L + J_m) \cdot (N_f^2 - N_b^2)}{2 \cdot P_o \cdot 1000} [\text{sec}]$$

<3> Acceleration time ( $t_3$ ) in the decreasing-output range ( $N_f$  to  $N_m$ )

$$t_3 = 0.01097 \frac{(J_L + J_m) \cdot (N_m - N_f) \left\{ (N_m - N_f) - \frac{P_o \cdot N_m - P_m \cdot N_f}{P_m - P_o} \cdot \ln \frac{P_m}{P_o} \right\}}{(P_m - P_o) \cdot 1000} [\text{sec}]$$

The total time ( $t$ ) required for acceleration in the range from 0 to  $N_m$  is  $t_1+t_2+t_3$  [sec]




# 5

## DETERMINING THE ALLOWABLE DUTY CYCLE

When machining requires the spindle to accelerate and decelerate frequently, the average output per cycle must not exceed the continuous rated output. The allowable duty cycle for a typical AC spindle motor can be obtained as shown below.

### Duty cycle and average output



$$\text{Average output } P_{av} = \sqrt{\frac{P_1^2 t_1 + P_2^2 t_2 + P_3^2 t_3 + P_4^2 t_4}{Dt}}$$

**NOTE** This is not a guaranteed value but a guideline.

#### NOTE

1 Cutting output P<sub>3</sub> at motor speed N which is lower than base speed Nb shall be calculated by the following equation.

$$P_3 = P_C \times Nb/N \text{ [kW]} \quad (P_C: \text{Actual cutting output})$$

2 In case that P<sub>3</sub> is calculated by the load indicator voltage, use the following equation.

$$P_3 = P_1 \times L_3/10 \text{ [kW]}$$

(L<sub>3</sub>: Load indicator voltage in cutting [V])


**Allowable duty cycle time Dt**

From the equation for getting the value of Pav[kW].

$$Dt = \frac{1}{P_{av}^2} \times (P_1^2 t_1 + P_2^2 t_2 + P_3^2 t_3 + P_4^2 t_4)$$

Substitute the continuous rated output of the used AC spindle motor for Pav [kW] in the equation above.

**Allowable duty cycle time Dt for repeated acceleration/deceleration**




# 6

## DISPOSAL OF SPINDLE MOTORS BY MATERIAL TYPE

### Disposal of motors by separating plastic parts from metal parts

After a motor is dismantled, the plastic parts (terminal box, terminal box cover, fan cover) must be separated for disposal. The plastic parts are made of the following material.

Plastic material : >(PBT+PC)-GF(30)FR(17)<





## **II. FANUC AC SPINDLE MOTOR $\beta$ iI SERIES**



# 1

## GENERAL

---

The FANUC AC SPINDLE MOTOR  $\beta i$ I series is a highly cost-effective series having sufficient basic performance as the core machine tool.

### Features

- High-output and high-torque are implemented defying its compact body.
- Spindle HRV control enables high-efficiency and low-heating driving.
- The built-in  $\alpha i$ M sensor or  $\alpha i$ MZ sensor enables synchronous spindle and Z-axis feed, rigid tapping, and Cs contouring.
- Improvement in machining of the motor housing enhances the accuracy of the mounting part.
- Waterproof and pressure-proof design conforming to the international standard (IEC) is employed to improve reliability and make it resistant to most environments.

## 2

## SPECIFICATIONS

| Series   |  | $\beta$ iI series   |                    |                    |                    |
|--|--|---|--------------------|--------------------|--------------------|
| Model  |  | $\beta$ iI 3/10000  | $\beta$ iI 6/10000 | $\beta$ iI 8/10000 | $\beta$ iI 12/8000 |
| Item   |  |   |                    |                    |                    |
| Rated output<br>(*1)   | Cont., 60 min rated kW<br>S3 40% (*2) (HP) | 3.7<br>(5.0)  | 5.5<br>(7.4)       | 7.5<br>(10)        | 11<br>(14.7)       |
|  | 15 min rated, S3 25% kW<br>(*2) (HP)       | 5.5<br>(7.4)  | 7.5<br>(10)        | 11<br>(14.7)       | 15<br>(20.1)       |
| Rated current A<br>(*3)  | Cont. rated                                | 18  | 40                 | 36                 | 43                 |
|  | 60 min, S3 40% rated (*2)                  | 22  | 47                 | 42                 | 49                 |
|  | 15min, S3 25% rated (*2)                   | 29  | 56                 | 56                 | 63                 |
| Speed<br>$\text{min}^{-1}$   | Base speed                                 | Cont. rated   | 2000               | 2000               | 2000               |
|  |  | Short time rated  | 1500               | 1500               | 1500               |
|  | Max. speed                                 | 10000   | 10000              | 10000              | 8000               |
| Cont. rated torque<br>at const. rated torque range N·m<br>(kgf·cm) |  | 17.7<br>(180)   | 26.3<br>(268)      | 35.8<br>(365)      | 52.5<br>(536)      |
| Rotor inertia  | $\text{kg}\cdot\text{m}^2$                 | 0.0078  | 0.0148             | 0.0179             | 0.0275             |
|  | $\text{kgf}\cdot\text{cm}\cdot\text{s}^2$  | 0.08  | 0.15               | 0.18               | 0.28               |
| Weight   | kgf  | 27  | 46                 | 51                 | 80                 |
| Vibration  |  | V5  |                    |                    |                    |
| Noise  |  | 75dB(A) or less   |                    |                    |                    |
| Cooling sysytem (*4)   |  | Totally enclosed and fan cooled IC0A6   |                    |                    |                    |
| Cooling fan W  |  | 17  |                    | 20                 |                    |
| Installation (*5)  |  | Mount the motor so that the output shaft points in a direction ranging within 45° degrees above the horizontal to vertically downwards.<br>IMB5,IMV1,IMB3,IMB6,IMB7,IMB8,IMV5 |                    |                    |                    |
| Allowable overload capacity (1 min) (*6)                           |  | 110% of 15 min rated output   |                    |                    |                    |
| Insulation   |  | Class H   |                    |                    |                    |
| Ambient temperature  |  | 0 to 40°C   |                    |                    |                    |
| Altitude   |  | Height above sea level not exceeding 1000m  |                    |                    |                    |
| Painting color   |  | Munsell system N2.5   |                    |                    |                    |
| Sensor   |  | $\alpha$ iM sensor or $\alpha$ iMZ sensor   |                    |                    |                    |
| Type of thermal protection (*7)                                    |  | TP211   |                    |                    |                    |
| Resolution of the MZi sensor /rev.                                 |  | 2048  |                    | 4096               |                    |
| Number of detected gear teeth per rotation<br>$\lambda$ /rev.      |  | 128   |                    | 256                |                    |
| Bearing lubrication  |  | Grease  |                    |                    |                    |
| Maximum output during acceleration (*8) kW                         |  | 6.1   | 8.3                | 12.1               | 16.5               |
| Applicable spindle amplifier module (*9)                           |  | $\beta$ iSVSP*-7.5  | $\beta$ iSVSP*-11  |                    | $\beta$ iSVSP*-15  |
| Model  |  | $\beta$ iI 3/10000  | $\beta$ iI 6/10000 | $\beta$ iI 8/10000 | $\beta$ iI 12/8000 |



- (\*1) The rated output is guaranteed at the rated voltage.  
(Amplifier input: 200/220/230VAC, 50/60 Hz)  
If the input voltage fluctuates, it is possible that the rated output cannot be obtained even when such fluctuations are within the allowable fluctuation range.
- (\*2) The cycle time is 10 minutes, S3 40%: ON 4 minutes, OFF 6 minutes, and S3 25%: ON 2.5 minutes, OFF 7.5 minutes.
- (\*3) The rated current is not a guaranteed value but a guideline for the maximum current at rated output.
- (\*4) IC code conforms to IEC 34-6.
- (\*5) IM code conforms to IEC 34-7.
- (\*6) This is not a guaranteed value but a guideline for the maximum motor output at a rated supply voltage.
- (\*7) Type conforms to IEC 34-11.
- (\*8) This is not a guaranteed value.
- (\*9) The applicable amplifiers in the table are the standard amplifiers.  
For the  $\beta i$  3/10000, the  $\beta i$ SVSP\*-11 and  $\beta i$ SVSP\*-15 can also be used.  
For the  $\beta i$  6/10000 and  $\beta i$  8/10000, the  $\beta i$ SVSP\*-15 can also be used.
- (\*10) Degree of protection:  
with oil seal: IP54, without oil seal: IP40.

# 3

## OUTPUT/TORQUE CHARACTERISTICS

---

### Reference Calculation for torque

Torque T can be obtained by the following equation.

$$T[\text{N}\cdot\text{m}] = P[\text{kW}] \times 1000 / 0.1047 / N[\text{min}^{-1}]$$


P[kW]: Motor output

N[ $\text{min}^{-1}$ ]: Motor speed


When the unit of T is [kgf·m],

$$T[\text{kgf}\cdot\text{m}] = P[\text{kW}] \times 1000 / 1.0269 / N[\text{min}^{-1}]$$


### 3.1 MODEL βiI 3/10000




### 3.2 MODEL βiI 6/10000



### 3.3 MODEL βiI 8/10000



### 3.4 MODEL βiI 12/8000



# 4

## CONNECTIONS

---

Chapter 4, "CONNECTIONS", consists of:

|  |    |
|--|----|
| 4.1 CONNECTION OF POWER LEAD AND FAN MOTOR<br>CABLE..... | 44 |
| 4.2 CONNECTION OF SIGNAL LEAD .....                      | 45 |

## 4.1 CONNECTION OF POWER LEAD AND FAN MOTOR CABLE

Cables for power lead and fan motor are connected to the terminal block.

| Size of screws used in the terminal block | Power lead | Fan motor                 |
|---|------------|---------------------------|
|   | U,V,W,G    | FMU,FMV,FMW               |
| <b>Model</b>                              |            |                           |
| $\beta$ i 3/10000 to $\beta$ i 12/8000    | M5         | Screw-less terminal block |

### Cable for the power lead

For the specifications of cables for power leads, refer to the FANUC SERVO AMPLIFIER  $\beta$ i series DESCRIPTIONS (B-65322EN).


### Current value of FAN MOTOR

For the current values and cable specifications of the fan motor, see Section 2.4, "FAN MOTOR CONNECTION" in Part I in this manual.

## 4.2 CONNECTION OF SIGNAL LEAD

The connector manufactured by Tyco Electronics AMP is used for connection of  $\alpha iM$  sensor signals,  $\alpha iMZ$  sensor signals, and thermistor signals. The housing and contact of the connector are included in the terminal box.


### Connector attachment for a motor with a built-in $\alpha iM$ sensor



Connector pins arrangement

|               |     |     |     |    |    |      |
|---------------|-----|-----|-----|----|----|------|
| <b>Number</b> | B1  | B2  | B3  | B4 | B5 | B6   |
| <b>Color</b>  |     |     |     |    |    |      |
| <b>Signal</b> |     | *VA | *VB |    | 0V | THR2 |
| <b>Number</b> | A1  | A2  | A3  | A4 | A5 | A6   |
| <b>Color</b>  |     |     |     |    |    |      |
| <b>Signal</b> | +5V | VA  | VB  |    | SS | THR1 |

### Connector attachment for a motor with a built-in $\alpha iMZ$ sensor



Connector pins arrangement

|               |     |     |     |     |    |      |
|---------------|-----|-----|-----|-----|----|------|
| <b>Number</b> | B1  | B2  | B3  | B4  | B5 | B6   |
| <b>Color</b>  |     |     |     |     |    |      |
| <b>Signal</b> |     | *VA | *VB | *VZ | 0V | THR2 |
| <b>Number</b> | A1  | A2  | A3  | A4  | A5 | A6   |
| <b>Color</b>  |     |     |     |     |    |      |
| <b>Signal</b> | +5V | VA  | VB  | VZ  | SS | THR1 |

### - Connector housing and contact specifications

Connector and contact :

Tyco Electronics AMP specification D-3000 series

|         | Motor side            |                           | Cable side           |                           |
|---------|-----------------------|---------------------------|----------------------|---------------------------|
|         | FANUC specification   | Manufacture specification | FANUC specification  | Manufacture specification |
| Housing | A63L-0001-0535/121KDF | 178964-6                  | A63L-0001-0460/121KD | 178289-6                  |
| Contact | A63L-0001-0456/ASMT   | 175288-2                  | A63L-0001-0456/ASM   | 1-175217-2                |

Crimping tool : 91559-1 Extractor : 234168-1

### - Thermistor specification

Signal THR1 corresponds to one of the thermistor terminals, and signal THR2, to the other terminal. The resistance of the thermistor is about 30 to 90 k $\Omega$  as measured at room temperature (20°C to 30°C).

# 5

## ALLOWABLE RADIAL LOAD

Use the motor output shaft below the allowable radial loads shown in the table below.

| Model       | Allowable radial load (kgf) |                        |
|-------------|-----------------------------|------------------------|
|             | At output shaft end         | At output shaft center |
| βiI 3/10000 | 882N (90kgf)                | 999N (102kgf)          |
| βiI 6/10000 | 1470N (150kgf)              | 1607N (164kgf)         |
| βiI 8/10000 | 1960N (200kgf)              | 2205N (225kgf)         |
| βiI 12/8000 | 2940N (300kgf)              | 3371N (344kgf)         |




### NOTE

- 1 When using a belt, adjust the tension so the allowable loads indicated above are not exceeded. If an excessive load is applied, consider the use of a support bearing on the machine side to maintain the long-term reliability of the motor. (If an excessive load is applied, it is possible that an abnormal sound may occur.)
- 2 When the belt tension is maximized at a point outside the output shaft end, the allowable loads are less than those at the output shaft end.
- 3 If a thrust load is applied when a helical gear is used, the shaft moves in the direction of the thrust. So, as a general rule, never apply a thrust load.



# 6

## ASSEMBLING ACCURACY

| Item   | Model<br>$\beta i I$ 3/10000 to $\beta i I$ 12/8000 | Measuring method   |
|--|---|--|
| Run-out at the end of the output shaft   | 20 $\mu$ m or less                                  |    |
| Run-out of the faucet joint for mounting the flange against the core of the shaft (only for flange type) | 40 $\mu$ m or less                                  |   |
| Run-out of the flange mounting surface against the core of the shaft (only for flange type)              | 80 $\mu$ m or less                                  |  |


# 7

## EXTERNAL DIMENSIONS

---


| Model name                                      | Section |
|---|---------|
| Model $\beta$ iI 3/10000 (flange mounting type) | 7.1     |
| Model $\beta$ iI 3/10000 (foot mounting type)   | 7.2     |
| Model $\beta$ iI 6/10000 (flange mounting type) | 7.3     |
| Model $\beta$ iI 6/10000 (foot mounting type)   | 7.4     |
| Model $\beta$ iI 8/10000 (flange mounting type) | 7.5     |
| Model $\beta$ iI 8/10000 (foot mounting type)   | 7.6     |
| Model $\beta$ iI 12/8000 (flange mounting type) | 7.7     |
| Model $\beta$ iI 12/8000 (foot mounting type)   | 7.8     |

# 7.1 MODEL βiI 3/10000 (FLANGE MOUNTING TYPE)




(Note) 1. Use hexagon head bolts M10, length 35mm or less for mounting.  
2. The reversed air flow direction is also available.

## 7.2 MODEL βiI 3/10000 (FOOT MOUNTING TYPE)




(Note) 1. Use hexagon head bolts M10, length 20mm or less for mounting.  
2. The reversed air flow direction is also available.

### 7.3 MODEL βiI 6/10000 (FLANGE MOUNTING TYPE)




- (Note) 1. Use hexagon head bolts M10, length 35mm or less for mounting.  
2. The reversed air flow direction is also available.

# 7.4 MODEL βiI 6/10000 (FOOT MOUNTING TYPE)




(Note) 1. Use hexagon head bolts M10, length 20mm or less for mounting.  
2. The reversed air flow direction is also available.

# 7.5 MODEL βiI 8/10000 (FLANGE MOUNTING TYPE)




(Note) 1. Use hexagon head bolts M12, length 35mm or less for mounting.  
2. The reversed air flow direction is also available.

# 7.6 MODEL βiI 8/10000 (FOOT MOUNTING TYPE)






# 7.7 MODEL βiI 12/8000 (FLANGE MOUNTING TYPE)



(Note) 1. Use hexagon head bolts M12, length 35mm or less for mounting.  
2. The reversed air flow direction is also available.

# 7.8 MODEL βiI 12/8000 (FOOT MOUNTING TYPE)



(Note) 1. Use hexagon head bolts M10, length 30mm or less for mounting.  
2. The reversed air flow direction is also available.

## **II. FANUC AC SPINDLE MOTOR $\beta$ iIP SERIES**




# 1

## GENERAL

The FANUC AC spindle motor  $\beta i P$  series produces almost the same torque even when combined with a small-capacity amplifier. The  $\beta i P$  series is best suited to low cost lathes.

### Features

- A large torque can be produced in spite of its compact body.
- The  $\beta i P$  series can produce almost the same torque even when combined with a small-capacity amplifier (for the  $\beta i P$  8/6000 and  $\beta i P$  12/6000)



- Spindle HRV control enables high-efficiency and low-heating driving.
- The built-in  $\alpha i M$  sensor or  $\alpha i M Z$  sensor enables synchronous spindle and Z-axis feed, rigid tapping, and Cs contouring.
- Waterproof and pressure-proof design conforming to the international standard (IEC) is employed to improve reliability and make it resistant to most environments.

## 2

## SPECIFICATIONS

| Series  |  | $\beta iP$ series   |                    |                    |                    |      |
|---|--|---|--------------------|--------------------|--------------------|------|
| Model   |  | $\beta iP$ 8/6000   | $\beta iP$ 12/6000 | $\beta iP$ 15/6000 | $\beta iP$ 18/6000 |      |
| Item  |  |   |                    |                    |                    |      |
| Rated output<br>(*1)  | Cont., 60 min rated kW<br>S3 40% (*2) (HP) | 3.7<br>(5.0)  | 5.5<br>(7.4)       | 7.5<br>(10)        | 9<br>(12)          |      |
|   | 15 min rated, S3 25% kW<br>(*2) (HP)       | 5.5<br>(7.4)  | 7.5<br>(10)        | 9<br>(12)          | 11<br>(14.7)       |      |
| Rated current A<br>(*3)   | Cont. rated                                |   | 25                 | 36                 | 39                 |      |
|   | 60 min, S3 40% rated (*2)                  |   | 30                 | 50                 | 49                 |      |
|   | 15min, S3 25% rated (*2)                   |   | 38                 | 59                 | 57                 |      |
| Speed<br>$\text{min}^{-1}$  | Base speed                                 | Cont. rated   | 1000               | 1200               | 1200               | 1000 |
|   |  | Short time rated  | 750                | 750                | 750                | 750  |
|   | Max. speed                                 | 6000  | 6000               | 6000               | 6000               |      |
| Cont. rated torque<br>at const. rated torque range N·m<br>(kgf·cm)  |  | 35.3<br>(360)   | 43.8<br>(446)      | 59.7<br>(609)      | 85.9<br>(876)      |      |
| Rotor inertia   | $\text{kg}\cdot\text{m}^2$                 | 0.0179  | 0.0275             | 0.07               | 0.09               |      |
|   | $\text{kgf}\cdot\text{cm}\cdot\text{s}^2$  | 0.18  | 0.28               | 0.7                | 0.9                |      |
| Weight  | kgf  | 51  | 80                 | 95                 | 110                |      |
| Vibration   |  | V5  |                    |                    |                    |      |
| Noise   |  | 75dB(A) or less   |                    |                    |                    |      |
| Cooling sysytem (*4)  |  | Totally enclosed and fan cooled IC0A6   |                    |                    |                    |      |
| Cooling fan W   |  | 20  |                    | 56                 |                    |      |
| Installation (*5)   |  | Mount the motor so that the output shaft points in a direction ranging within 45° degrees above the horizontal to vertically downwards.<br>IMB5,IMV1,IMB3,IMB6,IMB7,IMB8,IMV5 |                    |                    |                    |      |
| Allowable overload capacity (1 min) (*6)                            |  | 110% of 15 min rated output   |                    |                    |                    |      |
| Insulation  |  | Class H   |                    |                    |                    |      |
| Ambient temperature   |  | 0 to 40°C   |                    |                    |                    |      |
| Altitude  |  | Height above sea level not exceeding 1000m  |                    |                    |                    |      |
| Painting color  |  | Munsell system N2.5   |                    |                    |                    |      |
| Sensor  |  | $\alpha iM$ sensor or $\alpha iMZ$ sensor   |                    |                    |                    |      |
| Type of thermal protection (*7)                                     |  | TP211   |                    |                    |                    |      |
| Resolution of the MZi sensor /rev.                                  |  | 4096  |                    |                    |                    |      |
| Number of detected gear teeth per rotation<br>$\lambda/\text{rev.}$ |  | 256   |                    |                    |                    |      |
| Bearing lubrication   |  | Grease  |                    |                    |                    |      |
| Maximum output during acceleration (*8) kW                          |  | 6.1   | 8.3                | 12.1               | 16.5               |      |
| Applicable spindle amplifier module (*9)                            |  | $\beta iSVSP^*-7.5$   |                    | $\beta iSVSP^*-11$ |                    |      |
| Model   |  | $\beta iP$ 8/6000   | $\beta iP$ 12/6000 | $\beta iP$ 15/6000 | $\beta iP$ 18/6000 |      |

- (\*1) The rated output is guaranteed at the rated voltage.  
(Amplifier input: 200/220/230VAC, 50/60 Hz)  
If the input voltage fluctuates, it is possible that the rated output cannot be obtained even when such fluctuations are within the allowable fluctuation range.
- (\*2) The cycle time is 10 minutes, S3 40%: ON 4 minutes, OFF 6 minutes, and S3 25%: ON 2.5 minutes, OFF 7.5 minutes.
- (\*3) The rated current is not a guaranteed value but a guideline for the maximum current at rated output.
- (\*4) IC code conforms to IEC 34-6.
- (\*5) IM code conforms to IEC 34-7.
- (\*6) This is not a guaranteed value but a guideline for the maximum motor output at a rated supply voltage.
- (\*7) Type conforms to IEC 34-11.
- (\*8) This is not a guaranteed value.
- (\*9) The applicable amplifiers in this table are the standard amplifiers. The  $\beta iSVSP$  amplifier of the A06B-6134-Hxxx#D must be applied.  
For the  $\beta iP$  8/6000 and  $\beta iP$  12/6000, the  $\beta iSVSP^*-11$  and  $\beta iSVSP^*-15$  can also be used.  
For the  $\beta iP$  15/6000 and  $\beta iP$  18/6000, the  $\beta iSVSP^*-15$  can also be used.
- (\*10) Degree of protection:  
with oil seal: IP54, without oil seal: IP40.

# 3

## OUTPUT/TORQUE CHARACTERISTICS

### Reference Calculation for torque

Torque T can be obtained by the following equation.

$$T[\text{N}\cdot\text{m}] = P[\text{kW}] \times 1000 / 0.1047 / N[\text{min}^{-1}]$$

P[kW]: Motor output

N[ $\text{min}^{-1}$ ]: Motor speed

When the unit of T is [kgf·m],



$$T[\text{kgf}\cdot\text{m}] = P[\text{kW}] \times 1000 / 1.0269 / N[\text{min}^{-1}]$$

 **CAUTION**



To achieve the output characteristics shown in this chapter, the  $\beta$ iSVSP amplifier of the A06B-6134-Hxxx#D and special parameters are necessary.





### 3.1 MODEL βiP 8/6000





### 3.2 MODEL βiP 12/6000



### 3.3 MODEL βiP 15/6000



### 3.4 MODEL βiP 18/6000



# 4

## CONNECTIONS

---

Chapter 4, "CONNECTIONS", consists of:

|  |    |
|--|----|
| 4.1 CONNECTION OF POWER LEAD AND FAN MOTOR<br>CABLE..... | 66 |
| 4.2 CONNECTION OF SIGNAL LEAD .....                      | 67 |

## 4.1 CONNECTION OF POWER LEAD AND FAN MOTOR CABLE

Cables for power lead and fan motor are connected to the terminal block.

| Size of screws used in the terminal block | Power lead | Fan motor                 |
|---|------------|---------------------------|
|   | U,V,W,G    | FMU,FMV,FMW               |
| <b>Model</b>                              |            |                           |
| $\beta$ iP 8/6000 to $\beta$ iP 18/6000   | M5         | Screw-less terminal block |

### Cable for the power lead

For the specifications of cables for power leads, refer to the FANUC SERVO AMPLIFIER  $\beta$ i series DESCRIPTIONS (B-65322EN).


### Current value of FAN MOTOR

For the current values and cable specifications of the fan motor, see Section 2.4, "FAN MOTOR CONNECTION" in Part I in this manual.

## 4.2 CONNECTION OF SIGNAL LEAD

The connector manufactured by Tyco Electronics AMP is used for connection of  $\alpha iM$  sensor signals,  $\alpha iMZ$  sensor signals, and thermistor signals. The housing and contact of the connector are included in the terminal box.


### Connector attachment for a motor with a built-in $\alpha iM$ sensor



Connector pins arrangement

|               |     |     |     |    |    |      |
|---------------|-----|-----|-----|----|----|------|
| <b>Number</b> | B1  | B2  | B3  | B4 | B5 | B6   |
| <b>Color</b>  |     |     |     |    |    |      |
| <b>Signal</b> |     | *VA | *VB |    | 0V | THR2 |
| <b>Number</b> | A1  | A2  | A3  | A4 | A5 | A6   |
| <b>Color</b>  |     |     |     |    |    |      |
| <b>Signal</b> | +5V | VA  | VB  |    | SS | THR1 |

### Connector attachment for a motor with a built-in $\alpha iMZ$ sensor



Connector pins arrangement

|               |     |     |     |     |    |      |
|---------------|-----|-----|-----|-----|----|------|
| <b>Number</b> | B1  | B2  | B3  | B4  | B5 | B6   |
| <b>Color</b>  |     |     |     |     |    |      |
| <b>Signal</b> |     | *VA | *VB | *VZ | 0V | THR2 |
| <b>Number</b> | A1  | A2  | A3  | A4  | A5 | A6   |
| <b>Color</b>  |     |     |     |     |    |      |
| <b>Signal</b> | +5V | VA  | VB  | VZ  | SS | THR1 |

### - Connector housing and contact specifications

Connector and contact :

Tyco Electronics AMP specification D-3000 series

|         | Motor side            |                           | Cable side           |                           |
|---------|-----------------------|---------------------------|----------------------|---------------------------|
|         | FANUC specification   | Manufacture specification | FANUC specification  | Manufacture specification |
| Housing | A63L-0001-0535/121KDF | 178964-6                  | A63L-0001-0460/121KD | 178289-6                  |
| Contact | A63L-0001-0456/ASMT   | 175288-2                  | A63L-0001-0456/ASM   | 1-175217-2                |

Crimping tool : 91559-1 Extractor : 234168-1

### - Thermistor specification

Signal THR1 corresponds to one of the thermistor terminals, and signal THR2, to the other terminal. The resistance of the thermistor is about 30 to 90 k $\Omega$  as measured at room temperature (20°C to 30°C).

# 5

## ALLOWABLE RADIAL LOAD

Use the motor output shaft below the allowable radial loads shown in the table below.




| Model                                      | Allowable radial load (kgf) |                        |
|--|-----------------------------|------------------------|
|  | At output shaft end         | At output shaft center |
| $\beta$ iIP 8/6000                         | 1960N (200kgf)              | 2205N (225kgf)         |
| $\beta$ iIP 12/6000                        | 2940N (300kgf)              | 3371N (344kgf)         |
| $\beta$ iIP 15/6000<br>$\beta$ iIP 18/6000 | 2940N (300kgf)              | 3410N (348kgf)         |

### NOTE

- 1 When using a belt, adjust the tension so the allowable loads indicated above are not exceeded. If an excessive load is applied, consider the use of a support bearing on the machine side to maintain the long-term reliability of the motor. (If an excessive load is applied, it is possible that an abnormal sound may occur.)
- 2 When the belt tension is maximized at a point outside the output shaft end, the allowable loads are less than those at the output shaft end.
- 3 If a thrust load is applied when a helical gear is used, the shaft moves in the direction of the thrust. So, as a general rule, never apply a thrust load.

# 6

## ASSEMBLING ACCURACY

| Item   | Model<br>βiP 8/6000 to βiP 18/6000 | Measuring method   |
|--|------------------------------------|--|
| Run-out at the end of the output shaft   | 20μm or less                       |    |
| Run-out of the faucet joint for mounting the flange against the core of the shaft (only for flange type) | 40μm or less                       |   |
| Run-out of the flange mounting surface against the core of the shaft (only for flange type)              | 80μm or less                       |  |

# 7


## EXTERNAL DIMENSIONS

---

| Model name                                      | Section |
|---|---------|
| Model $\beta$ iP 8/6000 (flange mounting type)  | 7.1     |
| Model $\beta$ iP 8/6000 (foot mounting type)    | 7.2     |
| Model $\beta$ iP 12/6000 (flange mounting type) | 7.3     |
| Model $\beta$ iP 12/6000 (foot mounting type)   | 7.4     |
| Model $\beta$ iP 15/6000 (flange mounting type) | 7.5     |
| Model $\beta$ iP 15/6000 (foot mounting type)   | 7.6     |
| Model $\beta$ iP 18/6000 (flange mounting type) | 7.7     |
| Model $\beta$ iP 18/6000 (foot mounting type)   | 7.8     |




# 7.1 MODEL βiP 8/6000 (FLANGE MOUNTING TYPE)




(Note) 1. Use hexagon head bolts M12, length 35mm or less for mounting.  
 2. The reversed air flow direction is also available.

# 7.2 MODEL βiP 8/6000 (FOOT MOUNTING TYPE)




(Note) 1. Use hexagon head bolts M10, length 30mm or less for mounting.  
2. The reversed air flow direction is also available.

# 7.3 MODEL βiP 12/6000 (FLANGE MOUNTING TYPE)




(Note) 1. Use hexagon head bolts M12, length 35mm or less for mounting.  
2. The reversed air flow direction is also available.

# 7.4 MODEL βiP 12/6000 (FOOT MOUNTING TYPE)




(Note) 1. Use hexagon head bolts M10, length 30mm or less for mounting.  
2. The reversed air flow direction is also available.

## 7.5 MODEL βiIP 15/6000 (FLANGE MOUNTING TYPE)




- (Note) 1. Use hexagon head bolts M12, length 45mm or less for mounting.  
2. The reversed air flow direction is also available.

# 7.6 MODEL βiP 15/6000 (FOOT MOUNTING TYPE)




(Note) 1. Use hexagon head bolts M12, length 45mm or less for mounting.  
2. The reversed air flow direction is also available.

# 7.7 MODEL βiP 18/6000 (FLANGE MOUNTING TYPE)



(Note) 1. Use hexagon head bolts M12, length 45mm or less for mounting.  
 2. The reversed air flow direction is also available.

**7.8** MODEL  $\beta$ iP 18/6000 (FOOT MOUNTING TYPE)





# INDEX

|   |       |  |
|---|-------|--|
| <b>&lt;A&gt;</b>                        |       | PREFACE .....p-1                       |
| ALLOWABLE RADIAL LOAD.....              | 46,68 |  |
| ASSEMBLING ACCURACY .....               | 47,69 |  |
| <b>&lt;C&gt;</b>                        |       | <b>&lt;S&gt;</b>                       |
| CAUTION.....                            | s-5   | SAFETY PRECAUTIONS .....               |
| CAUTION LABEL.....                      | s-9   | SPECIFICATIONS .....                   |
| COMMON .....                            | 5     | 38,60                                  |
| CONNECTION OF POWER LEAD AND FAN        |       | <b>&lt;W&gt;</b>                       |
| MOTOR CABLE .....                       | 44,66 | WARNING .....                          |
| CONNECTION OF SIGNAL LEAD.....          | 45,67 | WHEN A MOTOR IS CONNECTED TO A SPINDLE |
| CONNECTIONS.....                        | 43,65 | VIA A BELT.....                        |
|   |       | 22                                     |
|   |       | WHEN A MOTOR IS CONNECTED TO A SPINDLE |
|   |       | VIA A GEAR.....                        |
|   |       | 26                                     |
|   |       | WHEN A MOTOR IS DIRECTLY CONNECTED TO  |
|   |       | A SPINDLE VIA A COUPLING .....         |
|   |       | 27                                     |
| <b>&lt;D&gt;</b>                        |       |  |
| DEFINITION OF WARNING, CAUTION, AND     |       |  |
| NOTE.....                               | s-2   |  |
| DETERMINING THE ACCELERATION TIME ..... | 30    |  |
| DETERMINING THE ALLOWABLE DUTY CYCLE.   | 31    |  |
| DISPOSAL OF SPINDLE MOTORS BY MATERIAL  |       |  |
| TYPE .....                              | 33    |  |
| <b>&lt;E&gt;</b>                        |       |  |
| EXTERNAL DIMENSIONS .....               | 48,70 |  |
| <b>&lt;F&gt;</b>                        |       |  |
| FAN MOTOR CONNECTION.....               | 20    |  |
| <b>&lt;G&gt;</b>                        |       |  |
| GENERAL.....                            | 37,59 |  |
| <b>&lt;M&gt;</b>                        |       |  |
| METHOD OF USING THE MOTOR WITH          |       |  |
| CONSIDERATION GIVEN TO ITS              |       |  |
| ENVIRONMENTAL RESISTANCE .....          | 11    |  |
| MOTOR TYPES .....                       | 3     |  |
| <b>&lt;N&gt;</b>                        |       |  |
| NOTE.....                               | s-7   |  |
| NOTES ON INSTALLATION .....             | 4     |  |
| NOTES ON OPERATION.....                 | 29    |  |
| <b>&lt;O&gt;</b>                        |       |  |
| OUTPUT/TORQUE CHARACTERISTICS.....      | 40,62 |  |
| <b>&lt;P&gt;</b>                        |       |  |
| POWER LEAD CONNECTION .....             | 19    |  |



Revision Record

FANUC AC SPINDLE MOTOR  $\beta$ i series DESCRIPTIONS (B-65312EN)

| Edition | Date       | Contents  | Edition | Date | Contents |
|---------|------------|---|---------|------|----------|
| 02      | Jul., 2007 | <ul style="list-style-type: none"><li>• Changing of model names of following series <math>\beta</math>i1 series</li><li>• Addition of following series <math>\beta</math>i1P series</li></ul> |         |      |          |
| 01      | May, 2003  | _____   |         |      |          |

