



Changes for the Better

CNC

MELDAS 60/60S Series

HANDBOOK



MELDAS is a registered trademark of Mitsubishi Electric Corporation.
Other company and product names that appear in this manual are trademarks or registered trademarks of the respective company.

PREFACE





This manual is the alarm/parameter guide required to use the MELDAS60/60S Series. This manual is prepared on the assumption that your machine is provided with all of the MELDAS60/60S Series functions. Confirm the functions available for your NC before proceeding to operation by referring to the specification issued by the machine manufacturer.

- * The "MELDAS60 Series" includes the M64A, M64, M65, M66 and M65V.
- * The "MELDAS60S Series" includes the M64AS, M64S, M65S and M66S.

Notes on Reading This Manual

- (1) This manual explains general parameters as viewed from the NC.
For information about each machine tool, refer to manuals issued from the machine manufacturer. If the descriptions relating to "restrictions" and "allowable conditions" conflict between this manual and the machine manufacturer's instruction manual, the later has priority over the former.
- (2) This manual is intended to contain as much descriptions as possible even about special operations. The operations to which no reference is made in this manual should be considered impossible.
- (3) The "M64D system" explained in this manual includes the M64AS, M64S, M65S and M66S.
- (4) The "special display unit" explained in this manual is the display unit incorporated by the machine manufacturer, and is not the MELDAS standard display unit.

Caution

-  If the descriptions relating to the "restrictions" and "allowable conditions" conflict between this manual and the machine manufacturer's instruction manual, the latter has priority over the former.
-  The operations to which no reference is made in this manual should be considered impossible.
-  This manual is compiled on the assumption that your machine is provided with all optional functions. Confirm the functions available for your machine before proceeding to operation by referring to the specification issued by the machine manufacturer.
-  In some NC system versions, there may be cases that different pictures appear on the screen, the machine operates in a different way or some function is not activated.

Precautions for Safety

Always read the specifications issued by the machine maker, this manual, related manuals and attached documents before installation, operation, programming, maintenance or inspection to ensure correct use. Understand this numerical controller, safety items and cautions before using the unit. This manual ranks the safety precautions into "DANGER", "WARNING" and "CAUTION".




When the user may be subject to imminent fatalities or major injuries if handling is mistaken.



When the user may be subject to fatalities or major injuries if handling is mistaken.



When the user may be subject to injuries or when physical damage may occur if handling is mistaken.

Note that even items ranked as "  **CAUTION**", may lead to major results depending on the situation. In any case, important information that must always be observed is described.

DANGER





Not applicable in this manual.

WARNING


Not applicable in this manual.

CAUTION

1. Items related to product and manual

-  If the descriptions relating to the "restrictions" and "allowable conditions" conflict between this manual and the machine manufacturer's instruction manual, the latter has priority over the former.
-  The operations to which no reference is made in this manual should be considered impossible.
-  This manual is compiled on the assumption that your machine is provided with all optional functions. Confirm the functions available for your machine before proceeding to operation by referring to the specification issued by the machine manufacturer.
-  In some NC system versions, there may be cases that different pictures appear on the screen, the machine operates in a different way on some function is not activated.

2. Items related to faults and abnormalities




-  If the BATTERY LOW alarm is output, save the machining programs, tool data and parameters to an input/output device, and then replace the battery. If the BATTERY alarm occurs, the machining programs, tool data and parameters may be damaged. After replacing the battery, reload each data item.

[Continued on next page]




 **CAUTION**

[Continued]

3. Items related to maintenance

-  Do not replace the battery while the power is ON.
-  Do not short-circuit, charge, heat, incinerate or disassemble the battery.
-  Dispose of the spent battery according to local laws.

4. Items related to servo parameters and spindle parameters

-  With the MDS-C1 Series, only the serial encoder is compatible as the motor end detector. The OHE/OHA type detector cannot be used as the motor end detector.
-  Do not adjust or change the parameter settings greatly as operation could become unstable.
-  In the explanation on bits, set all bits not used, including blank bits, to "0".

CONTENTS

I EXPLANATION OF ALARMS

1. LIST OF ALARMS	1
1.1 OPERATION ALARMS	1
1.2 STOP CODES	9
1.3 SERVO • SPINDLE ALARMS.....	14
1.4 MCP ALARM	24
1.5 SYSTEM ALARMS	27
1.6 ABSOLUTE POSITION DETECTION SYSTEM ALARMS.....	32
1.7 MESSAGES DURING EMERGENCY STOP	35
1.8 AUXILIARY AXIS ALARMS	37
1.9 COMPUTER LINK ERRORS.....	44
1.10 USER PLC ALARMS	45
1.11 NETWORK SERVICE ERRORS	46
2. OPERATION MESSAGES ON SETTING AND DISPLAY UNIT	47
2.1 OPERATION ERRORS	47
2.2 OPERATOR MESSAGES.....	57
2.2.1 SEARCH AND OPERATION RELATED	57
2.2.2 MDI/EDITING RELATED	58
2.2.3 DATA INPUT/OUTPUT RELATED	59
2.2.4 S-ANALOG OUTPUT ADJUSTMENT RELATED	60
2.2.5 AUXILIARY AXIS	60
2.2.6 PARAMETER BACKUP RELATED	60
2.2.7 OTHERS	61
3. PROGRAM ERROR	62

II EXPLANATION OF PARAMETERS

1. SCREEN CONFIGURATION	1
1.1 SCREEN TRANSITION CHARTS	1
2. MACHINING PARAMETERS	3
2.1 PROCESS PARAMETERS.....	3
2.2 CONTROL PARAMETERS	10
2.3 AXIS PARAMETERS	12
2.4 BARRIER DATA	14
2.5 TOOL MEASUREMENT PARAMETES.....	16
3. I/O PARAMETERS	17
3.1 BASE PARAMETERS.....	17
3.2 I/O DEVICE PARAMETERS.....	18
3.3 COMPUTER LINK PARAMETERS	20
4. SETUP PARAMETERS	22
5. BASE SPECIFICATIONS PARAMETERS	23
6. AXIS SPECIFICATIONS PARAMETERS	92
6.1 AXIS SPECIFICATIONS PARAMETERS.....	92
6.2 ZERO POINT RETURN PARAMETERS	99
6.3 ABUSOLUTE POSITION PARAMETERS	102
6.4 AXIS SPECIFICATIONS PARAMETERS 2.....	104
7. SERVO PARAMETERS	112
7.1 MDS-B-SV12	114
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE).....	140
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)	168
7.4 SUPPLEMENT.....	198
7.4.1 D/A OUTPUT SPECIFICATIONS	198
7.4.2 ELECTRONIC GEARS	204
7.4.3 LOST MOTION COMPENSATION	206

8. MDS-B-SP/SPH,SPJ2 SPINDLE PARAMETERS	207
8.1 MDS-B-SP/SPH,SPJ2 SPINDLE BASE SPECIFICATIONS PARAMETERS	207
8.2 MDS-B-SP12	215
8.3 MDS-B-SP/SPH,MDS-C1-SP/SPH.....	235
8.4 MDS-C1-SPM	268
8.5 SUPPLEMENT.....	300
8.5.1 D/A OUTPUT SPECIFICATIONS	300
9. MACHINE ERROR COMPENSATION.....	303
9.1 FUNCTION OUTLINE.....	303
9.2 SETTING COMPENSATION DATA	307
9.3 EXAMPLE IN USING A LINEAR AXIS AS THE BASE AXIS	309
9.4 EXAMPLE IN USING A ROTATION AXIS AS THE BASE AXIS.....	313
10. PLC CONSTANTS.....	314
10.1 PLC TIMER.....	314
10.2 PLC COUNTER	314
10.3 PLC CONSTANTS.....	315
10.4 SELECTING THE PLC BIT.....	315
11. MACRO LIST.....	318
12. POSITION SWITCH.....	320
12.1 OUTLINE OF FUNCTION.....	320
12.2 CANCELING THE POSITION SWITCH	322
13. AUXILIARY AXIS PARAMETER.....	323

III PLC DEVICES

1. PLC INTERFACE INPUT X.....	1
2. PLC INTERFACE INPUT R.....	25
3. PLC INTERFACE OUTPUT Y.....	33
4. PLC INTERFACE OUTPUT R.....	61
5. OTHER PLC INTERFACES.....	67

I EXPLANATION OF ALARMS

1. LIST OF ALARMS

1.1 OPERATION ALARMS

(The bold characters are the messages displayed on the screen.)

M01 OPERATION ERROR		Alarms occurring due to incorrect operation by the operator during NC operation and those by machine trouble are displayed.
Error No.	Details	Remedy
0001	DOG OVERRUN (Dog overrun) When returning to the reference point, the near-point detection limit switch did not stop over the dog, but overran the dog.	<ul style="list-style-type: none"> • Increase the length of the near-point dog. • Reduce the reference point return speed.
0002	Z-AX NO CRSS One of the axes did not pass the Z-phase during the initial reference point return after the power was turned ON.	<ul style="list-style-type: none"> • Move the detector one rotation or more in the opposite direction of the reference point, and repeat reference point return.
0003	INVALID RET (Invalid return) When manually returning to the reference point, the return direction differs from the axis movement direction selected with the AXIS SELECTION key.	<ul style="list-style-type: none"> • The selection of the AXIS SELECTION key's +/- direction is incorrect. The error is canceled by feeding the axis in the correct direction.
0004	EXT INTRLK (External interlock) The external interlock function has activated (the input signal is "OFF") and one of the axes has entered the interlock state.	<ul style="list-style-type: none"> • As the interlock function has activated, release it before resuming operation. • Check the sequence on the machine side. • Check for broken wires in the interlock signal line.
0005	INTRL INTRLK (Internal interlock) The internal interlock state has been entered. The absolute position detector axis has been removed. A command for the manual/automatic simultaneous valid axis was issued from the automatic mode.	<ul style="list-style-type: none"> • The servo OFF function is valid, so release it first. • An axis that can be removed has been issued, so perform the correct operations. • The command is issued in the same direction as the direction where manual skip turned ON, so perform the correct operations. • During the manual/automatic simultaneous mode, the axis commanded in the automatic mode became the manual operation axis. Turn OFF the manual/ automatic valid signal for the commanded axis. • Turn ON the power again, and perform absolute position initialization.

1. LIST OF ALARMS
1.1 OPERATION ALARMS

Error No.	Details	Remedy
0006	H/W STRK END (H/W stroke end) The stroke end function has activated (the input signal is "OFF") and one of the axes is in the stroke end status.	<ul style="list-style-type: none"> • Move the machine manually. • Check for broken wires in the stroke end signal wire. • Check for trouble in the limit switch.
0007	S/W STRK END (S/W stroke end) The stored stroke limit I, II, IIB or IB function has activated.	<ul style="list-style-type: none"> • Move it manually. • If the stored stroke limit in the parameter is incorrectly set, correct it.
0008	Chuck/tail-stock barrier stroke end axis found The chuck/tail-stock barrier function turned ON, and an axis entered the stroke end state.	<ul style="list-style-type: none"> • Reset the alarm with reset, and move the machine in the reverse direction.
0009	Reference point return number illegal Return to the No. 2 reference point was performed before return to the No. 1 reference point was completed.	<ul style="list-style-type: none"> • Execute No. 1 reference point return.
0019	Sensor signal illegal ON The sensor signal was already ON when the tool measurement mode (TLM) signal was validated. The sensor signal turned ON when there was no axis movement after the tool measurement mode (TLM) signal was validated. The sensor signal turned ON at a position within 100μm from the final entry start position.	<ul style="list-style-type: none"> • Turn the tool measurement mode signal input OFF, and move the axis in a safe direction. • The operation alarm will turn OFF even when the sensor signal is turned OFF. <p>(Note) When the tool measurement mode signal input is turned OFF, the axis can be moved in either direction. Pay attention to the movement direction.</p>
0020	Reference point return illegal Return to the reference point was performed before the coordinates had not been established.	<ul style="list-style-type: none"> • Execute reference point return
0024	Zero point return disabled during absolute position detection alarm A zero point return signal was input during an absolute position detection alarm.	<ul style="list-style-type: none"> • Reset the absolute position detection alarm, and then perform zero point return.
0025	Zero point return disabled during zero point initialization A zero point return signal was input during zero point initialization of the absolute position detection system.	<ul style="list-style-type: none"> • Complete zero point initialization, and then perform zero point return.

1. LIST OF ALARMS
1.1 OPERATION ALARMS

Error No.	Details	Remedy
0050	Chopping axis zero point return incomplete The chopping axis has not completed zero point return before entering the chopping mode. All axes interlock will be applied.	<ul style="list-style-type: none"> • Reset or turn the chopping signal OFF, and then carry out zero point return.
0051	Synchronization error too large The synchronization error of the master and slave axes exceeded the allowable value under synchronous control. A deviation exceeding the synchronization error limit value was found with the synchronization deviation detection.	<ul style="list-style-type: none"> • Select the correction mode and move one of the axes in the direction in which the errors are reduced. • Increase the allowable value or reset it to 0 (check disabled). • When using simple C-axis synchronous control, set the contents of the R435 register to 0. • Check the parameter (#2024 synerr).
0101	NOT OP MODE (Not operation mode)	<ul style="list-style-type: none"> • Check for a broken wire in the input mode signal wire. • Check for trouble in the mode selector switch. • Check the sequence program.
0102	OVERRIDE ZERO (Override zero) "The cutting feed override" switch on the machine operation panel is set to zero.	<ul style="list-style-type: none"> • Set "the cutting feed override" switch to a value other than zero to release the error. • If "the cutting feed override" switch is set to a value other than zero, check for a short circuit in the signal wire. • Check the sequence program.
0103	EX F SPD ZRO (External feed speed zero) "The manual feed speed" switch on the machine operation panel is set to zero when the machine is in the jog mode or automatic dry run mode. The "Manual feedrate B speed" is set to zero during the jog mode when manual feedrate B is valid. The "each axis manual feedrate B speed" is set to zero during the jog mode when each axis manual feedrate B is valid.	<ul style="list-style-type: none"> • Set "the manual feed speed" switch to a value other than zero to release the error. • If "the manual feed speed" switch is set to a value other than zero, check for a short circuit in the signal wire. • Check the sequence program.
0104	F1 SPD ZRO (F1-digit speed zero) The F1-digit feedrate is set to zero when the F1-digit feed command is being executed.	<ul style="list-style-type: none"> • Set the F1-digit feedrate on the setup parameter screen.

1. LIST OF ALARMS
1.1 OPERATION ALARMS

Error No.	Details	Remedy
0105	SPINDLE STP (Spindle stop) The spindle stopped during the synchronous feed command.	<ul style="list-style-type: none"> • Rotate the spindle. • If the workpiece is not being cut, start dry run. • Check for a broken wire in the spindle encoder cable. • Check the connections for the spindle encoder connectors. • Check the spindle encoder pulse.
0106	HNDL FD NOW (Handle feed axis No. illegal) An axis not found in the specifications was designated for handle feed or the handle feed axis was not selected.	<ul style="list-style-type: none"> • Check for broken wires in the handle feed axis selection signal wire. • Check the sequence program. • Check the No. of axes listed in the specifications.
0107	SPDL RPM EXS (Spindle rotation speed excessive) The spindle rotation speed exceeded the axis clamp speed during the thread cutting command.	<ul style="list-style-type: none"> • Lower the commanded spindle rotation speed.
0108	Fixed point mode feed axis No. illegal: An axis not found in the specifications was designated for the fixed point mode feed or the fixed point mode feedrate is illegal.	<ul style="list-style-type: none"> • Check for broken wires in the fixed mode feed axis selection signal wire and fixed point mode feedrate wire. • Check the fixed point mode feed specifications.
0109	BLK ST INTLK (Block start interlock) An interlock signal that locks the start of the block has been input.	<ul style="list-style-type: none"> • Check the sequence program.
0110	CTBL ST INTLK (Cutting block start interlock) An interlock signal that locks the start of the cutting block has been input.	<ul style="list-style-type: none"> • Check the sequence program.
0111	Restart switch ON The restart switch was turned ON before the restart search was completed, and the manual mode was selected.	<ul style="list-style-type: none"> • Search the block to be restarted. • Turn OFF the restart switch.
0112	Program Check Mode The automatic start button was pressed during program check or in program check mode.	<ul style="list-style-type: none"> • Press the reset button to cancel the program check mode.
0113	Automatic start during buffer correction The automatic start button was pressed during buffer correction.	<ul style="list-style-type: none"> • Press the automatic start button after buffer correction is completed.

1. LIST OF ALARMS
1.1 OPERATION ALARMS

Error No.	Details	Remedy
0115	<p>RESETTING The automatic start button was pressed during resetting or tape rewinding.</p>	<ul style="list-style-type: none"> • When rewinding the tape, wait for the winding to end, or press the reset button to stop the winding, and then press the automatic start button. • During resetting, wait for resetting to end, and then press the automatic start button.
0117	<p>PLAYBACK NOT POSSIBLE The playback switch was turned ON during editing or full-character mode (9-inch).</p>	<ul style="list-style-type: none"> • During editing, cancel the function by pressing the input or previous screen key, and then turn ON the playback switch. • Set the edit screen (9-inch) to the half-character mode, and then turn ON the playback switch.
0118	<p>Block joint turn stop during normal line control The turning angle at the block joint exceeded the limit during normal line control.</p> <p>Normal line control type I The normal line control axis turning speed (#1523 C_feed) has not been set.</p> <p>Normal line control type II When turning in the inside of the arc, the parameter "#8041 C-rot. R" setting value is larger than the arc radius.</p>	<ul style="list-style-type: none"> • Check the program. • Set the normal line control axis turning speed. (Parameter "#1523 C_feed") • Set the C axis turning diameter smaller than the arc radius, or check the setting value of the C axis turning diameter. (Parameter "#8041 C rot. R")
0120	<p>Synchronization correction mode ON The synchronous correction mode switch was pressed in a non-handle mode.</p>	<ul style="list-style-type: none"> • Select the handle or manual feed mode. • Turn OFF the correction mode switch.
0121	<p>No synchronous control option The synchronous control system (register R435) was set with no synchronous control option.</p>	<ul style="list-style-type: none"> • Set 0 in register R435.
0123	<p>Computer link B The cycle start was attempted before resetting was completed.</p> <p>The operation of the computer link B was attempted in the 2nd part system of the 2-part system.</p>	<ul style="list-style-type: none"> • Perform the cycle start after resetting is completed. • Set 0 in #8109 HOST LINK, and then set 1 again before performing the cycle start. • The operation of the computer link B cannot be performed in the 2nd part system of the 2-part system.
0124	<p>Simultaneous axis movement prohibited during inclined axis control valid The basic axis corresponding to the inclined axis was started simultaneously in the manual mode while the inclined axis control was valid.</p>	<ul style="list-style-type: none"> • Turn the inclined axis and basic axis start OFF for both axes. (This also applied for manual/automatic simultaneous start.) • Invalidate the basic axis compensation, or command one axis at a time.

1. LIST OF ALARMS
1.1 OPERATION ALARMS

Error No.	Details	Remedy
0126	Program restart machine lock Machine lock was applied on the return axis while manually returning to the restart position.	<ul style="list-style-type: none"> • Release the machine lock before resuming operations.
0150	Chopping override zero	<ul style="list-style-type: none"> • Check the chopping override (R135). • Check the rapid traverse override (R134).
0151	Command axis chopping axis A chopping axis movement command was issued from the program during the chopping mode. (This alarm will not occur when the movement amount is commanded as 0.) (All axes interlock state will be applied.)	<ul style="list-style-type: none"> • Reset, or turn OFF the chopping signal. When the chopping signal is turned OFF, the axis will return to the reference position, and then the program movement command will be executed.
0153	Bottom dead center position zero The bottom dead center position is set to the same position as the upper dead center position.	<ul style="list-style-type: none"> • Correctly set the bottom dead center position.
0154	Chopping axis handle selection axis Chopping was started when the chopping axis was selected as the handle axis.	<ul style="list-style-type: none"> • Select an axis other than the chopping axis as the handle axis, or start chopping after changing the mode to another mode.
0160	Axis with no maximum speed set for the outside of the soft limit range Returned from the outside of the soft limit range for the axis with no maximum speed set for the outside of the soft limit range.	<ul style="list-style-type: none"> • Set the maximum speed for the outside of the soft limit range. (Parameter "#2021 out_f") • Change the soft limit range. (Parameter "#2013 OT-" "#2014 OT+")
1005	An attempt was made to execute G114.* during execution of G114.*. G51.2 was commanded when the G51.2 spindle-spindle polygon machining mode was already entered with a separate system.	<ul style="list-style-type: none"> • Issue G113 to cancel G114.*. • Issue the spindle synchronous cancel signal (Y2E8: SPSYC) to cancel G114.*. • Cancel with G50.2. • Cancel with the spindle-spindle polygon cancel signal (Y359).
1007	The spindle is being used in synchronized tapping.	<ul style="list-style-type: none"> • Cancel synchronized tapping.
1026	Spindle C axis and other position control were commanded simultaneously. C axis mode command was issued for polygon machining spindle. C axis mode command was issued for synchronized tapping spindle. Polygon command was issued for synchronized tapping spindle. Spindle is being used as spindle/C axis.	<ul style="list-style-type: none"> • Cancel the C axis command. • Cancel the polygon machining command. • Cancel the C axis with servo OFF.

1. LIST OF ALARMS
1.1 OPERATION ALARMS

Error No.	Details	Remedy
1030	<p>Synchronization mismatch Different M codes were commanded in the two systems as the synchronization M codes.</p> <p>Synchronization with the "!" code was commanded in another system during M code synchronization.</p> <p>Synchronization with the M code was commanded in another system during synchronization with the "!" code.</p>	<ul style="list-style-type: none"> • Correct the program so that the M codes match. • Correct the program so that the same synchronization codes are commanded.
1031	<p>The C axis selection signal was changed when multiple C axes could not be selected.</p> <p>An axis that cannot be controlled as the multiple C axes selection was selected.</p>	<ul style="list-style-type: none"> • Check and correct the parameters and program.
1032	<p>Tap return spindle selection illegal during multi-spindle Tap return was executed when a different spindle was selected. Cutting feed will wait until synchronization is completed.</p>	<ul style="list-style-type: none"> • Select the spindle for which tap cycle was halted before the tap return signal was turned ON.
1033	<p>Spindle-spindle polygon (G51.2) cutting interlock Cutting feed will wait until synchronization is completed.</p>	<ul style="list-style-type: none"> • Wait for synchronization to end.
1034	<p>Cross machining command illegal Cross machining control exceeding the number of control axes was attempted.</p> <p>Cross machining control with duplicated axis addresses was attempted.</p>	<ul style="list-style-type: none"> • Check the parameter settings for cross machining control.
1035	<p>Cross machining control disable modal Cross machining control was commanded for a system in which cross machining control is disabled as shown below.</p> <ul style="list-style-type: none"> • During nose R compensation mode • During pole coordinate interpolation mode • During cylindrical interpolation mode • During balance cut mode • During fixed cycle machining mode • During facing turret mirror image 	<ul style="list-style-type: none"> • Check the program.

1. LIST OF ALARMS
1.1 OPERATION ALARMS

Error No.	Details	Remedy
1036	<p>Synchronous control designation disable The synchronous control operation method selection (R435 register) was set when the mode was not the C axis mode.</p> <p>The synchronous control operation method selection (R435 register) was set in the zero point not set state.</p> <p>Mirror image disable state The external mirror image or parameter mirror image was commanded during facing turret mirror image.</p>	<ul style="list-style-type: none"> • Set the R435 register to 0. • Check the program and parameters.
1037	Synchronous control was started or canceled when synchronous control could not be started or canceled.	<ul style="list-style-type: none"> • Check the program and parameters.
1038	A movement command was issued to a synchronous axis in synchronous control.	<ul style="list-style-type: none"> • Check the program.
1043	<p>No spindle speed clamp The constant surface speed command (G96) was issued to the spindle which is not selected for the spindle speed clamp command (G92/G50) under Multiple spindle control II.</p>	<p>Press the reset key and carry out the remedy below.</p> <ul style="list-style-type: none"> • Select the spindle before commanding G92/G50. <p>(Applicable only to M65V series and M64 C version series)</p>
1106	<p>Spindle synchronous phase calculation illegal The spindle synchronization phase alignment command was issued while the spindle synchronization phase calculation request signal was ON.</p>	<ul style="list-style-type: none"> • Check the program. • Check the sequence program.

(The bold characters are the messages displayed on the screen.)

Error No.	Details	Remedy
M90 PARAM SET MODE		M90 Messages output when the setup parameter lock function is enabled are displayed.
-	<p>Setup parameter lock released The setup parameter lock is released. Automatic start is disabled when setup parameters can be set.</p>	<ul style="list-style-type: none"> • Refer to the manual issued by the machine manufacturer.

1. LIST OF ALARMS
1.2 STOP CODES

1.2 STOP CODES

These codes indicate a status that caused the controller to stop for some reason.
(The bold characters are the messages displayed on the screen.)

T01 CAN'T CYCLE ST		This indicates the state where automatic operation cannot be started when attempting to start it from the stop state.
Error No.	Details	Remedy
0101	AX IN MOTION (axis in motion) Automatic start is not possible as one of the axes is moving.	<ul style="list-style-type: none"> • Try automatic start again after all axes have stopped.
0102	READY OFF Automatic start is not possible as the NC is not ready.	<ul style="list-style-type: none"> • Another alarm has occurred. Check the details and remedy.
0103	RESET ON Automatic start is not possible as the reset signal has been input.	<ul style="list-style-type: none"> • Turn OFF the reset input signal. • Check that the reset switch is not ON constantly due to trouble. • Check the sequence program.
0104	A-OP STP SGL (Automatic operation stop signal ON) The FEED HOLD switch on the machine operation panel is ON (valid).	<ul style="list-style-type: none"> • Check the FEED HOLD switch. • The feed hold switch is the B contact. • Check for broken wires in the feed hold signal wire. • Check the sequence program.
0105	H/W STRK END (H/W stroke end axis) Automatic start is not possible as one of the axes is at the stroke end.	<ul style="list-style-type: none"> • If one of the axis' ends is at the stroke end, move the axis manually. • Check for broken wire in the stroke end signal wire. • Check for trouble in the stroke end limit switch.
0106	S/W STRK END (S/W stroke end axis) Automatic start is not possible as one of the axes is at the stored stroke limit.	<ul style="list-style-type: none"> • Move the axis manually. • If an axis is not at the end, check the parameter details.
0107	NO OP MODE (NO operation mode) The operation mode has not been selected.	<ul style="list-style-type: none"> • Select the automatic operation mode. • Check for broken wires in the automatic operation mode (memory, tape, MDI) signal wire.

1. LIST OF ALARMS
1.2 STOP CODES

Error No.	Details	Remedy
0108	OP MODE DUPL (Operation mode duplicated) Two or more automatic operation modes are selected.	<ul style="list-style-type: none"> • Check for a short circuit in the mode selection signal wire (memory, tape, MDI). • Check for trouble in the switch. • Check the sequence program.
0109	OP MODE SHFT (Operation mode shift) The automatic operation mode changed to another automatic operation mode.	<ul style="list-style-type: none"> • Return to the original automatic operation mode, and start automatic start.
0110	Tape search execution Automatic start is not possible as tape search is being executed.	<ul style="list-style-type: none"> • Begin automatic start after the tape search is completed.
0112	Program restart position return incomplete Automatic start is not possible as the axis has not been returned to the restart position.	<ul style="list-style-type: none"> • Manually return to the restart position. • Turn the automatic restart valid parameter ON, and then execute automatic start.
0113	Thermal alarm Automatic start is not possible because a thermal alarm (Z53 TEMP. OVER) has occurred.	<ul style="list-style-type: none"> • The NC controller temperature has exceeded the specified temperature. • Take appropriate measures to cool the unit.
0115	In host communication Automatic start cannot be executed as the NC is communicating with the host computer.	<ul style="list-style-type: none"> • Execute automatic start after the communication with the host computer is completed.
0138	Disabled start during absolute position detection alarm A start signal was input during an absolute position detection alarm.	<ul style="list-style-type: none"> • Reset the absolute position detection alarm, and then input the start signal.
0139	Disabled start during zero point initialization A start signal was input while initializing the absolute position detector's zero point.	<ul style="list-style-type: none"> • Complete zero point initialization before inputting the start signal.
0190	Automatic start disabled Automatic start is disabled because setup parameters can be set.	<ul style="list-style-type: none"> • Refer to the manual issued by the machine manufacturer.
0191	Automatic start disabled Automatic start was caused during file deletion or writing.	<ul style="list-style-type: none"> • Cause automatic start after file deletion or writing is completed.

1. LIST OF ALARMS

1.2 STOP CODES

T02 FEED HOLD		The feed hold state been entered due to a condition in the automatic operation.
Error No.	Details	Remedy
0201	H/W STRK END (H/W stroke end axis) An axis is at the stroke end.	<ul style="list-style-type: none"> Manually move the axis away from the stroke end limit switch. The machining program must be corrected.
0202	S/W STRK END (S/W stroke end axis) An axis is at the stored stroke limit.	<ul style="list-style-type: none"> Manually move the axis. The machining program must be corrected.
0203	RESET SIGNAL ON (Reset signal on) The reset signal has been input.	<ul style="list-style-type: none"> The program execution position has returned to the start of the program. Execute automatic operation from the start of the machining program.
0204	AUTO OP STOP (Automatic operation stop) The FEED HOLD switch is ON.	<ul style="list-style-type: none"> Resume automatic operation by pressing the "CYCLE START" switch.
0205	AUTO MD CHING (Automatic mode change) The operation mode changed to another mode during automatic operation.	<ul style="list-style-type: none"> Return to the original automatic operation mode, and resume automatic operation by pressing the "CYCLE START" switch.
0206	Acceleration and deceleration time constants too large The acceleration and deceleration time constants are too large. (This problem occurs at the same time as system alarm Z59.)	<ul style="list-style-type: none"> Increase the set value of the parameter "#1206 G1bF". Decrease the set value of the parameter "#1207 G1btL". Lower the cutting speed.
0215	Absolute position detection alarm stop An absolute position detection alarm occurred.	<ul style="list-style-type: none"> Reset the absolute position detection alarm.

1. LIST OF ALARMS

1.2 STOP CODES

T03 BLOCK STOP		This indicates that automatic operation stopped after executing one block of the program.
Error No.	Details	Remedy
0301	SNGL BLK ON (Single block on) The SINGLE BLOCK switch on the machine operation panel is ON. The single block or machine lock switch changed.	<ul style="list-style-type: none"> Automatic operation can be resumed by turning the CYCLE START switch ON.
0302	User macro stop The block stop command was issued in the user macro program.	<ul style="list-style-type: none"> Automatic operation can be resumed by turning the CYCLE START switch ON.
0303	Mode change The automatic mode changed to another automatic mode.	<ul style="list-style-type: none"> Return to the original automatic operation mode, and resume automatic operation by turning the CYCLE START switch ON.
0304	MDI completion The last block of MDI was completed.	<ul style="list-style-type: none"> Set MDI again, and turn the CYCLE START switch ON to resume MDI operation.
0305	Block start interlock The interlock signal that locks the block start is entered.	<ul style="list-style-type: none"> Check the sequence program.
0306	Block cutting start interlock The interlock signal that locks the block cutting start is entered.	<ul style="list-style-type: none"> Check the sequence program.
0310	Offset change of inclined Z-axis during program operation Whether to validate the offset of the inclined Z-axis switched during program operation.	<ul style="list-style-type: none"> Automatic operation can be restarted by turning ON the cycle start switch.

T04 COLLATION STOP		Collation stop was applied during automatic operation.
Error No.	Details	Remedy
0401	Collation stop occurred.	<ul style="list-style-type: none"> Automatic operation can be restarted with automatic start.


1. LIST OF ALARMS
1.2 STOP CODES

T10 FIN WAIT	This indicates the operation state when an alarm did not occur during automatic operation, and nothing seems to have happened.																																																																																																																			
Error No.	Details																																																																																																																			
0□□□	<p>The error number is displayed while each of the completion wait modes listed in the table below is ON. It disappears when the mode is canceled.</p> <div style="text-align: center; margin-bottom: 10px;"> </div> <table border="1" style="display: inline-table; margin-right: 20px;"> <thead> <tr> <th>Alarm No.</th> <th>Unclamp signal wait <small>Note 2)</small></th> <th>In dwell execution</th> </tr> </thead> <tbody> <tr><td>0</td><td></td><td></td></tr> <tr><td>1</td><td></td><td>×</td></tr> <tr><td>8</td><td>×</td><td></td></tr> <tr><td>9</td><td>×</td><td>×</td></tr> </tbody> </table> <table border="1" style="display: inline-table; margin-right: 20px;"> <thead> <tr> <th>Alarm No.</th> <th>Door open <small>Note 1)</small></th> <th>Waiting for spindle position to be looped</th> </tr> </thead> <tbody> <tr><td>0</td><td></td><td></td></tr> <tr><td>1</td><td></td><td>×</td></tr> <tr><td>8</td><td>×</td><td></td></tr> <tr><td>9</td><td>×</td><td>×</td></tr> </tbody> </table> <table border="1" style="display: inline-table;"> <thead> <tr> <th>Alarm No.</th> <th>Waiting for spindle orientation to complete</th> <th>Waiting for cutting speed deceleration</th> <th>Waiting for rapid traverse deceleration</th> <th>Waiting for MSTB completion</th> </tr> </thead> <tbody> <tr><td>0</td><td></td><td></td><td></td><td></td></tr> <tr><td>1</td><td></td><td></td><td></td><td>×</td></tr> <tr><td>2</td><td></td><td></td><td>×</td><td></td></tr> <tr><td>3</td><td></td><td></td><td>×</td><td>×</td></tr> <tr><td>4</td><td></td><td>×</td><td></td><td></td></tr> <tr><td>5</td><td></td><td>×</td><td></td><td>×</td></tr> <tr><td>6</td><td></td><td>×</td><td>×</td><td></td></tr> <tr><td>7</td><td></td><td>×</td><td>×</td><td>×</td></tr> <tr><td>8</td><td>×</td><td></td><td></td><td></td></tr> <tr><td>9</td><td>×</td><td></td><td></td><td>×</td></tr> <tr><td>A</td><td>×</td><td></td><td>×</td><td></td></tr> <tr><td>B</td><td>×</td><td></td><td>×</td><td>×</td></tr> <tr><td>C</td><td>×</td><td>×</td><td></td><td></td></tr> <tr><td>D</td><td>×</td><td>×</td><td></td><td>×</td></tr> <tr><td>E</td><td>×</td><td>×</td><td>×</td><td></td></tr> <tr><td>F</td><td>×</td><td>×</td><td>×</td><td>×</td></tr> </tbody> </table> <p>Note 1: This mode is enabled by the door interlock function. Note 2: The system is waiting for the index table indexing unclamp signal to turn ON or OFF</p>	Alarm No.	Unclamp signal wait <small>Note 2)</small>	In dwell execution	0			1		×	8	×		9	×	×	Alarm No.	Door open <small>Note 1)</small>	Waiting for spindle position to be looped	0			1		×	8	×		9	×	×	Alarm No.	Waiting for spindle orientation to complete	Waiting for cutting speed deceleration	Waiting for rapid traverse deceleration	Waiting for MSTB completion	0					1				×	2			×		3			×	×	4		×			5		×		×	6		×	×		7		×	×	×	8	×				9	×			×	A	×		×		B	×		×	×	C	×	×			D	×	×		×	E	×	×	×		F	×	×	×	×
Alarm No.	Unclamp signal wait <small>Note 2)</small>	In dwell execution																																																																																																																		
0																																																																																																																				
1		×																																																																																																																		
8	×																																																																																																																			
9	×	×																																																																																																																		
Alarm No.	Door open <small>Note 1)</small>	Waiting for spindle position to be looped																																																																																																																		
0																																																																																																																				
1		×																																																																																																																		
8	×																																																																																																																			
9	×	×																																																																																																																		
Alarm No.	Waiting for spindle orientation to complete	Waiting for cutting speed deceleration	Waiting for rapid traverse deceleration	Waiting for MSTB completion																																																																																																																
0																																																																																																																				
1				×																																																																																																																
2			×																																																																																																																	
3			×	×																																																																																																																
4		×																																																																																																																		
5		×		×																																																																																																																
6		×	×																																																																																																																	
7		×	×	×																																																																																																																
8	×																																																																																																																			
9	×			×																																																																																																																
A	×		×																																																																																																																	
B	×		×	×																																																																																																																
C	×	×																																																																																																																		
D	×	×		×																																																																																																																
E	×	×	×																																																																																																																	
F	×	×	×	×																																																																																																																

1.3 SERVO · SPINDLE ALARMS

This section describes alarms occurred by the errors in the servo system such as the drive unit, motor and encoder, etc. The alarm message, alarm No. and axis name will display on the alarm message screen. The axis where the alarm occurred and the alarm No. will also display on the servo monitor screen and the spindle monitor screen respectively. If several alarms have occurred, up to two errors per axis will display on the servo monitor screen and the spindle monitor screen respectively.

(The bold characters are the messages displayed on the screen.)



(Note 1) The alarm class and alarm reset class combinations are preset.
(Refer to the separate table for S02, S51 and S52.)

Alarm class	Alarm reset class	Resetting methods
S01	PR	After removing the cause of the alarm, reset the alarm by turning the NC power ON again.
S03	NR	After removing the cause of the alarm, reset the alarm by inputting the NC RESET key.
S04	AR	After removing the cause of the alarm, reset the alarm by turning the drive unit power ON again.

(Note 2) The resetting method may change according to the alarm class.
For example, even if "S03 SERVO ALARM: NR" is displayed, it may be necessary to turn the NC power ON again.

Alarm No.	Name	Meaning
10	Insufficient voltage	Insufficient PN bus voltage was detected in main circuit.
11	Axis selection error	Setting of the axis No. selection switch is incorrect.
12	Memory error 1	A CPU error or an internal memory error was detected during the power ON self-check.
13	Software processing error 1	Software processing has not finished within the specified time.
14	Software processing error 2	Software processing has not finished within the specified time.
15	Memory error 2	A CPU error or an internal memory error was detected during the power ON self-check.
16	Magnetic pole position detection error	Initial magnetic pole for motor control has not been formed yet.
17	A/D converter error	An error was detected in the A/D converter for detecting current FB.
18	Motor side detector: Initial communication error	Initial communication with the motor end detector failed.
19	Detector communication error in synchronous control	Initial communication with the motor end detector on master axis failed when setting closed-loop current synchronous control. Or the communication was interrupted.

1. LIST OF ALARMS
1.3 SERVO SPINDLE ALARMS

Alarm No.	Name	Meaning
1A	Machine side detector: Initial communication error	Initial communication with the linear scale or the ball screw end detector failed.
1B	Machine side detector: CPU error 1	CPU initial error was detected in the linear scale or in the ball screw end detector.
1C	Machine side detector: EEPROM/LED error	An error was detected in the stored data of the linear scale memory. Or the LED deterioration was detected in the ball screw end detector.
1D	Machine side detector: Data error	An error data was detected in the linear scale or in the ball screw end detector.
1E	Machine side detector: Memory error	An internal memory error was detected in the linear scale.
1F	Machine side detector: Communication error	An error was detected in communication data with the linear scale or the ball screw end detector. Or the communication was interrupted.
20	Motor side detector: No signal	No signals were detected in A,B,Z-phase or U,V,W-phase of the pulse motor end detector in a servo system, or in Z-phase of PLG in a spindle system.
21	Machine side detector: No signal	No signals were detected in A,B,Z-phase of the pulse linear scale or the ball screw end detector in a servo system. Or no encoder signals were detected in a spindle system.
22	LSI error	LSI operation error was detected in the drive unit.
23	Excessive speed error 1	A difference between the speed command and speed feedback was continuously exceeding 50 r/min for longer than the setting time.
24	Grounding	The motor power cable is in contact with FG (Frame Ground).
25	Absolute position data lost	The absolute position was lost, as the backup battery voltage dropped in the absolute position detector.
26	Unused axis error	A power module error occurred in the axis whose axis No. selection switch was set to "F"(free axis).
27	Machine side detector: CPU error 2	A CPU error was detected in the linear scale.
28	Machine side detector: Overspeed	The specified max. speed was detected in the linear scale.
29	Machine side detector: Absolute position data error	An error was detected in the absolute position detection circuit of the linear scale.
2A	Machine side detector: Relative position data error	An error was detected in the relative position detection circuit of the linear scale.
2B	Motor side detector: CPU error 1	A CPU initial error was detected in the motor end detector or in the linear scale of a linear servo system.
2C	Motor side detector: EEPROM/LED error	The LED deterioration was detected in the motor end detector. Or an error was detected in the stored data of the linear scale memory of a linear servo system.

1. LIST OF ALARMS
1.3 SERVO SPINDLE ALARMS

Alarm No.	Name	Meaning
2D	Motor side detector: Data error	A data error was detected in the motor end detector or in the linear scale of a linear servo system.
2E	Motor side detector: Memory error	An internal memory error was detected in the linear scale of a linear servo system.
2F	Motor side detector: Communication error	An error was detected in communication data with the motor end detector or with the linear scale of a linear servo system. Or the communication was interrupted.
30	Over regeneration	Over-regeneration detection level became over 100%. The regenerative resistor is overloaded.
31	Overspeed	The motor was detected to rotate at a speed exceeding the allowable speed.
32	Power module overcurrent	Overcurrent protection function in the power module has started its operation.
33	Overvoltage	PN bus voltage in main circuit exceeded the allowable value.
34	NC-DRV communication: CRC error	An error was detected in the data received from the CNC.
35	NC command error	The travel command data that was received from the CNC was excessive.
36	NC-DRV communication: Communication error	The communication with the CNC was interrupted.
37	Initial parameter error	An incorrect parameter was detected among the parameters received from the CNC at the power ON.
38	NC-DRV communication: Protocol error 1	An error was detected in the communication frames received from the CNC.
39	NC-DRV communication: Protocol error 2	An error was detected in the axis information data received from the CNC.
3A	Overcurrent	Excessive current was detected in the motor drive current.
3B	Power module overheat	Thermal protection function in the power module has started its operation.
3C	Regeneration circuit error	An error was detected in the regenerative transistor or in the regenerative resistor.
3D	Spindle speed blocked	The spindle motor failed to rotate faster than 45 r/min, even when the max. torque command was given.
3E	Spindle speed overrun	1. The spindle motor speed feedback was detected to be accelerated exceeding the commanded speed. 2. The spindle motor was detected to be rotated at a speed exceeding the parameter value, while the speed command was "0" (including the case of operation stoppage during the position control).
3F	Excessive speed error 2	A difference between the speed command and speed feedback was detected to exceed the setting amount or setting time in a constant speed operation.

1. LIST OF ALARMS
1.3 SERVO SPINDLE ALARMS

Alarm No.	Name	Meaning
40	Detector selection unit switching error	An error was detected in the motor switching signals that were received from the detector selection unit, while controlling one drive unit and two motors.
41	Detector selection unit communication error	An error was detected in the communication with the detector selection unit, while controlling one drive unit and two motors.
42	Feedback error 1	An error was detected in the feedback signals of the pulse motor end detector in a servo system, or in PLG's feedback signals in a spindle system.
43	Feedback error 2	Excessive difference was detected in position data between the motor end detector and the machine end detector in a servo system. In a spindle system, an error was detected in the encoder feedback signals.
44	Inappropriate coil selected for C axis	When using a coil changeover motor, C-axis was controlled while the high-speed coil was selected.
45	Fan stop	A cooling fan built in the drive unit stopped, and the loads on the unit exceeded the specified value.
46	Motor overheat	Thermal protection function of the motor or in the detector, has started its operation.
47	Regenerative resistor overheat	Thermal protection function of the regenerative resistor, has started its operation.
48	Motor side detector: CPU error 2	A CPU error was detected in the linear scale of a linear servo system.
49	Motor side detector: Overspeed	The specified max. speed was detected in the linear scale of the linear servo system.
4A	Motor side detector: Absolute position data error	An error was detected in the absolute position detection circuit in the linear scale of a linear servo system.
4B	Motor side detector: Relative position data error	An error was detected in the relative position detection circuit in the linear scale of a linear servo system.
4C	Current error at magnetic pole detection	A current error was detected in the IPM spindle motor when the initial magnetic pole was being formed.
4E	NC command mode error	The mode outside the specification was input in spindle control mode selection.
4F	Instantaneous power interruption	The power was momentarily interrupted.
50	Overload 1	Overload detection level became over 100%. The motor or the drive unit is overloaded.
51	Overload 2	Current command of more than 95% of the unit's max. current was being continuously given for longer than 1 second in a servo system. In a spindle system, the load over the continuous rating was being applied for longer than 30 minutes.
52	Excessive error 1	A difference between the actual and theoretical motor positions during servo ON exceeded the setting value in a servo system. In a spindle system, a difference between the position command and position feedback exceeded the setting value.

1. LIST OF ALARMS
1.3 SERVO SPINDLE ALARMS

Alarm No.	Name	Meaning
53	Excessive error 2	A difference between the actual and theoretical motor positions during servo OFF exceeded the setting value.
54	Excessive error 3	When an excessive error 1 occurred, detection of the motor current failed.
55	External emergency stop error	There is no contactor shutoff command, even after 30 seconds has passed since the external emergency stop was input.
57	Option error	An invalid option function was selected.
58	Collision detection 1: G0	When collision detection function was valid, the disturbance torque in rapid traverse (G0) exceeded the collision detection level.
59	Collision detection 1: G1	When collision detection function was valid, the disturbance torque in cutting feed (G1) exceeded the collision detection level.
5A	Collision detection 2	When collision detection function was valid, the command torque reached the max. motor torque.
5C	Orientation feedback error	After orientation was achieved, a difference between the command and feedback exceeded the parameter setting.
5D	Speed monitoring: Input mismatch	As for door state signal of speed monitoring control, a mismatch between the external input signal and the control signal received from the CNC was detected.
5E	Speed monitoring: Feedback speed error	In speed monitoring control, the spindle speed was exceeding the setting speed with the door open.
5F	External contactor error	A contact of the external contactor is welding. Or the contactor fails to be ON during ready ON.
61	Power module overcurrent	Overcurrent protection function in the power module has started its operation.
62	Frequency error	The input power supply frequency increased above the specification range.
63	Supplementary regeneration error	The supplementary regenerative transistor is being ON.
65	Rush relay error	A resistor relay for rush short circuit fails to be ON.
67	Phase interruption	An open-phase condition was detected in input power supply circuit.
68	Watchdog	The system does not operate correctly.
69	Grounding	The motor power cable is in contact with FG (Frame Ground).
6A	External contactor welding	A contact of the external contactor is welding.
6B	Rush relay welding	A resistor relay for rush short circuit fails to be OFF.
6C	Main circuit error	An error was detected in charging operation of the main circuit capacitor.
6D	Parameter error	The capacity of the power supply unit and the regenerative resistor type that was set in the parameter are mismatched.
6E	Memory error	An internal memory error was detected.
6F	Power supply error	A power supply unit is not connected. Or an error was detected in A/D converter of the power supply unit.
71	Instantaneous power interruption	The power was momentarily interrupted.

1. LIST OF ALARMS
1.3 SERVO SPINDLE ALARMS

Alarm No.	Name	Meaning
73	Over regeneration	Over-regeneration detection level became over 100%. The regenerative resistor is overloaded.
74	Regenerative resistor overheat	Thermal protection function of the regenerative resistor, has started its operation.
75	Overvoltage	PN bus voltage in main circuit exceeded the allowable value.
76	External emergency stop setting error	As for the external emergency stop settings, the setting on the rotary switch and the parameter setting are mismatched.
77	Power module overheat	Thermal protection function in the power module has started its operation.
7F	Drive unit power supply restart request	A mismatch of program mode selection was detected. Turn the drive unit power ON again.
80	Detector converting unit 1: Connection error	A connection error was detected between the analog output linear scale and the unit MDS-B-HR that is used in a linear servo system.
81	Detector converting unit 1: Communication error	A communication error was detected between the serial output linear scale and the unit MDS-B-HR that is used in a linear servo system.
83	Detector converting unit 1: Judgment error	Judgment of the linear scale analog frequency failed in the unit MDS-B-HR that is used in a linear servo system.
84	Detector converting unit 1: CPU error	A CPU error was detected in the unit MDS-B-HR that is used in a linear servo system.
85	Detector converting unit 1: Data error	A data error was detected in the unit MDS-B-HR that is used in a linear servo system.
86	Detector converting unit 1: Magnetic pole error	An error was detected in the magnetic pole of the unit MDS-B-HR that is used in a linear servo system.
88	Watchdog	The system does not operate correctly.
89	Detector converting unit 2: Connection error	A connection error was detected between the analog output linear scale and the unit MDS-B-HR in a servo system. In a spindle system, the initial communication with MDS-B-PJEX failed.

1. LIST OF ALARMS
1.3 SERVO SPINDLE ALARMS

Alarm No.	Name	Meaning
8A	Detector converting unit 2: Communication error	An error was detected in the communication with the serial output linear scale of the unit MDS-B-HR in a servo system. In a spindle system, an error was detected in the communication with MDS-B-PJEX.
8B	Detector converting unit 2: Automatic tuning error	An abnormal signal was detected from PLG in automatic PLG tuning.
8C	Detector converting unit 2: Judgment error	The detector type outside the specification was designated in MDS-B-PJEX.
8D	Detector converting unit 2: CPU error	A CPU error was detected in the unit MDS-B-HR in a servo system, or in the unit MDS-B-PJEX in a spindle system.
8E	Detector converting unit 2: Data error	A data error was detected in the unit MDS-B-HR.

<p>S02 INIT PARAM ERR <u>AAAA</u> □</p> <div style="margin-left: 100px;"> Axis name { Servo : Axis name Spindle : "S", "T", "M", "N" </div> <div style="margin-left: 100px;"> Alarm No. (parameter No.) </div>		
<p>An error was found in the parameters transmitted from the controller to the drive unit when the power was turned ON. Remove the cause of the alarm, and then reset the alarm by turning the controller power OFF once.</p>		
Alarm No.	Details	Remedy
2201 - 2264	The servo parameter setting data is illegal. The alarm No. is the No. of the servo parameter where the error occurred.	Check the descriptions for the appropriate servo parameters and correct them.
2301	The number of constants to be used in the following functions is too large: <ul style="list-style-type: none"> • Electronic gears • Position loop gain • Speed feedback conversion 	Check that all the related parameters are specified correctly. sv001:PC1, sv002:PC2, sv003:PGN1 sv018:PIT, sv019:RNG1, sv020:RNG2
2302	High-speed serial incremental detector Parameters for absolute position detection are set to ON during OSE104 and OSE105 connection. Set the parameters for absolute position detection to OFF. To detect an absolute position, replace the incremental specification detector with an absolute position detector.	Check that all the related parameters are specified correctly. sv017:SPEC, sv025:MTYP
2303	No servo option is found. The closed loop (including the ball screw-end detector) or dual feedback control is an optional function.	Check that all the related parameters are specified correctly. sv025:MTYP/pen sv017:SPEC/dfbx

1. LIST OF ALARMS
1.3 SERVO SPINDLE ALARMS

Alarm No.	Details	Remedy
2304	No servo option is found. The SHG control is an optional function.	Check that all the related parameters are specified correctly. sv057:SHGC sv058:SHGCsp
2305	No servo option is found. The adaptive filtering is an optional function.	Check that all the related parameters are specified correctly. sv027:SSF1/aflt
3201 - 3584	The spindle parameter setting data is illegal. The alarm No. is the No. of the spindle parameter where the error occurred.	Check the descriptions for the appropriate spindle parameters and correct them. Refer to Spindle Drive Maintenance Manual.

1. LIST OF ALARMS
1.3 SERVO SPINDLE ALARMS

S51 PARAMETER ERROR	$\Delta\Delta\Delta\Delta$ \square Axis name — Servo : Axis name — Spindle : "S", "T", "M", "N" Alarm No. (parameter No.)	
A warning appears if a parameter set outside the tolerable range is set. Illegal settings will be ignored. This alarm will be reset when the correct value is set.		
Alarm No.	Details	Remedy
2201 - 2264	Servo parameter setting data is illegal. The alarm No. is the No. of the servo parameter where the warning occurred.	Check the descriptions for the appropriate servo parameters and correct them.
3201 - 3584	Spindle parameter setting data is illegal. The alarm No. is the No. of the spindle parameter where the warning occurred.	Check the descriptions for the appropriate spindle parameters and correct them. Refer to Spindle Drive Maintenance Manual.

S52 SERVO WARNING	$00\Delta\Delta$ \square Axis name — Servo : Axis name — Spindle : "S", "T", "M", "N" Alarm No. (Warning No.)	
The drive unit warning is displayed.		
Alarm No.	Name	Meaning
90	Detector: Initial communication error	Initial communication with the absolute position linear scale failed.
91	Detector: Communication error	An error was detected in the communication with the detector in absolute position detection system.
92	Detector: Protocol error	A data error was detected in absolute position detection system.
93	Initial absolute position fluctuation	The position data have fluctuated during the absolute position initializing.
96	Scale feedback error	An excessive deviation was detected between the motor end detector and MP scale feedback data in a MP scale absolute position detection system.
97	Scale offset error	An error was detected in the offset data received from the MP scale in a MP scale absolute position detection system.
9B	Detector converting unit: Magnetic pole shift warning	An error was detected in the shift distance of the magnetic pole in a linear servo system.
9C	Detector converting unit: Magnetic pole warning	A data error was detected in the magnetic pole of MDS-B-HR after passing Z-phase in a linear servo system.

1. LIST OF ALARMS
1.3 SERVO SPINDLE ALARMS

Alarm No.	Name	Meaning
9E	Absolute position detector: Revolution counter error	An error was detected in the revolution counter of the absolute position detector. The absolute position data cannot be compensated.
9F	Battery voltage drop	The battery voltage that is supplied to the absolute position detector dropped. The absolute position data is retained.
A6	Fan stop warning	A cooling fan built in the drive unit stopped.
A8	Turret indexing warning	The designated position shift amount of turret indexing is outside the setting range.
A9	Orientation feedback warning	As an orientation feedback error occurred, the retrial has been conducted.
E0	Over regeneration warning	Over-regeneration detection level exceeded 80%.
E1	Overload warning	Overload detection level exceeded 80%.
E2	Continuous high-speed revolution warning	The motor was continuously rotated at a speed exceeding the rated speed.
E3	Absolute position counter warning	Deviation between the absolute and relative position data was detected.
E4	Set parameter warning	A parameter setting was outside the setting range.
E6	Control axis detachment warning	Control axis detachment was commanded.
E7	In NC emergency stop state	Emergency stop was input from the CNC.
E8	Excessive supplementary regeneration frequency	Regeneration that are beyond the power supply limitation has frequently occurred.
E9	Instantaneous power interruption warning	The power was momentarily interrupted.
EA	In external emergency stop state	External emergency stop signal was input.
EB	Over regeneration warning	Over-regeneration detection level exceeded 80%.

1. LIST OF ALARMS
1.4 MCP ALARM

1.4 MCP ALARM

An error has occurred in the drive unit and other interfaces. (The bold characters are the messages displayed on the screen.)

Y02 SYSTEM ALARM		An error occurred in the data transmitted between the MCP and drive unit after the power was turned ON.	
Error No.	Details		Remedy
0050	Background error		The software or hardware may be damaged. Contact the service center.
0051	0000	CRC error (10 times/910.2 ms)	A communication error has occurred between the controller and drive unit. <ul style="list-style-type: none"> • Take measures against noise. • Check that the communication cable connector between the controller and drive unit and one between the drive units are tight. • Check whether the communication cable between the controller and drive unit and one between the drive units are disconnected. • A drive unit may be faulty. Take a note of the 7-segment LED contents of each drive unit and report to the Service Center.
	0001	CRC error (2 continuous times)	
	0002	Reception timing error (2 continuous times)	
	××03	Data ID error (2 continuous times) ××: Axis No.	
××04	No. of reception frames error (2 continuous times) ××: Axis No.		

Y03 AMP. UNEQUIPPED		Check the drive unit mounting state.	
The drive unit is not correctly connected		<ul style="list-style-type: none"> • Check the end of the cable wiring. • Check the cable for broken wires. • Check the connector insertion. • The drive unit input power is not being input. • The drive unit axis No. switch is illegal. 	
Error No.	Details		
Alphabet (axis name)	Servo axis drive unit not mounted		
1 - 4	PLC axis drive unit not mounted		
S	No.1 spindle axis drive unit not mounted		
T	No.2 spindle axis drive unit not mounted		

Y05 INIT PARAM ERR <u>□□□□</u>	
↑ □□□□ : Error parameter number	
Details	Remedy
There is a problem in the value set for the number of axes or the number of systems.	Check the value set for the corresponding parameters. #1001 SYS_ON #1002 axisno #1039 spinno etc.

1. LIST OF ALARMS
1.4 MCP ALARM

Y06 mcp_no ERROR		There are differences in the MCP and axis parameters when the NC power is turned ON.	
Error No.	Details	Remedy	
0001	There is a skipped number in the channels.	Check the values set for the following parameters. #1021 mcp_no #3031 smcp_no #3032 mbmcp_no	
0002	The random layout setting is duplicated.		
0003	The drive unit fixed setting "0000" and random layout setting "****" are both set.		
0004	The spindle/C axis "#3031 mcp_no" and "#3032 smcp_no" are set to the same values.		
0005	A random layout is set for the "#1154 pdoor" =1 two-system.		
0006	The channel No. parameter is not within the setting range.		

Y51 PARAMETER ERROR		An error occurred in a parameter that causes an alarm while the control axis was operating.	
Error No.	Details	Remedy	
1	LN FEED ABNL (Linear feed abnormal) The time constant has not been set or the setting exceeded the setting range.	• Check "#2004 G0tL".	
2	CT FEED ABNL (Cutting feed abnormal) The time constant has not been set or the setting exceeded the setting range.	• Check "#2007 G1tL".	
3	DLY F-F ABNL (Delayed fast feed abnormal) The time constant has not been set or the setting exceeded the setting range.	• Check "#2005 G0t1".	
4	DLY CUTG ABNL (Delayed cutting feed abnormal) The time constant has not been set or the setting exceeded the setting range.	• Check "#2008 G1t1".	
9	GRID SPACE ERROR	• Check "#2029 grspc".	
12	SYNCHRONOUS TAP CYCLE ACCELERATION/DECELERATION TIME CONSTANT ERROR The time constant has not been set or the setting exceeded the setting range.	• Check spindle parameters #3017 stapt1 to #3020 stapt4.	
15	LN SKIP ABNL (Linear skip abnormal) The time constant has not been set or the setting exceeded the setting range.	• Check "#2102 skip_tL".	
16	DLY SKIP ABNL (Delayed skip abnormal) The time constant has not been set or the setting exceeded the setting range.	• Check "#2103 skip_t1".	
17	"#1205 G0bdcc" for the 2nd system is set to acceleration/deceleration before G0 interpolation.	• Check "#1205 G0bdcc".	

1. LIST OF ALARMS
1.4 MCP ALARM

Error No.	Details	Remedy
101	ROTARY AXIS GEAR RATIO EXCESSIVE (ABSOLUTE POSITION DETECTION)	<ul style="list-style-type: none"> • Check "#2201 PC1" and "#2202 PC2".

Alarm No.	Details	Remedy																																
<p>Y90 SP. NON SIGNAL</p> <p>(Alarm No.)</p> <div style="display: flex; align-items: center; margin-left: 20px;"> <div style="margin-right: 10px;"> <table border="1" style="border-collapse: collapse;"> <tr> <td style="width: 20px; text-align: center;">0</td> <td style="width: 20px; text-align: center;">0</td> <td style="width: 20px; text-align: center;">□</td> <td style="width: 20px; text-align: center;">□</td> </tr> </table> </div> <div style="margin-right: 10px;"> <p>No.1 spindle →</p> <p>No.2 spindle →</p> </div> </div>			0	0	□	□																												
0	0	□	□																															
<table border="1" style="border-collapse: collapse; margin: auto;"> <thead> <tr> <th style="text-align: center;">Alarm No.</th> <th style="text-align: center;">Z open phase</th> <th style="text-align: center;">B open phase</th> <th style="text-align: center;">A open phase</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">1</td> <td></td> <td></td> <td style="text-align: center;">×</td> </tr> <tr> <td style="text-align: center;">2</td> <td></td> <td style="text-align: center;">×</td> <td></td> </tr> <tr> <td style="text-align: center;">3</td> <td></td> <td style="text-align: center;">×</td> <td style="text-align: center;">×</td> </tr> <tr> <td style="text-align: center;">4</td> <td style="text-align: center;">×</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">5</td> <td style="text-align: center;">×</td> <td></td> <td style="text-align: center;">×</td> </tr> <tr> <td style="text-align: center;">6</td> <td style="text-align: center;">×</td> <td style="text-align: center;">×</td> <td></td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">×</td> <td style="text-align: center;">×</td> <td style="text-align: center;">×</td> </tr> </tbody> </table>			Alarm No.	Z open phase	B open phase	A open phase	1			×	2		×		3		×	×	4	×			5	×		×	6	×	×		7	×	×	×
Alarm No.	Z open phase	B open phase	A open phase																															
1			×																															
2		×																																
3		×	×																															
4	×																																	
5	×		×																															
6	×	×																																
7	×	×	×																															
0001 - 0007	There is an error in the spindle encoder signal. The data transmission to the drive unit is stopped when this error occurs.	<ul style="list-style-type: none"> • Check the spindle encoder's feedback cable and the encoder. 																																

1.5 SYSTEM ALARMS

The following messages are displayed with the register at the time when the error occurred if the system stops due to a system error.

Message	Details	Remedy
Parity error	RAM error	<ul style="list-style-type: none"> Write down the displayed register, and contact the service center.
Bus error	A non-existing memory was accessed.	
Zero divide	The division with a 0 denominator was attempted.	
Watch dog error	The software process is not functioning correctly.	
Illegal exception	The alarm was caused by an illegal software function not listed above.	
Address error	An illegal memory was accessed.	
Illegal instruction	The software process is not functioning correctly.	
Stack overflow		

Z30 ETHERNET ERROR □□□□	
↑ Warning No.	
Warning No.	Explanation
0001	Socket open error (socket)
0002	Socket bind error (bind)
0003	Connection wait queue error (listen)
0004	Connection request acceptance error (accept)
0005	Data receive error (socket error)
0006	Data receive error (data shortage or disconnection)
0007	Data receive error (socket error)
0008	Data receive error (data shortage or disconnection)
000A	Socket close error (close)

Note: If warning No. 0001, 0002, 0003, or 000A is displayed, set the parameters, then turn power OFF and turn it ON again.

1. LIST OF ALARMS
 1.5 SYSTEM ALARMS

Z31 DATA SERVER ERROR □□□□ ↑ Warning No.	
Warning No.	Explanation
0001	Socket open error (socket)
0002	Socket bind error (bind)
0003	Connection wait queue error (listen)
0004	Connection request acceptance error (accept)
0005	Data receive error (socket error)
0006	Data receive error (data shortage or disconnection)
0007	Data receive error (socket error)
0008	Data receive error (data shortage or disconnection)
000A	Socket close error (close)

Note: If warning No. 0001, 0002, 0003, or 000A is displayed, set the parameters, then turn power OFF and turn it ON again.

Message	Details	Remedy
Z40 FORMAT NOT MET	This appears when the parameter MemVal is formatted at 0, and MemVal is set to 1.	<ul style="list-style-type: none"> • Either return the MemVal setting, or format and restart.

1. LIST OF ALARMS
1.5 SYSTEM ALARMS

The bold characters are the messages displayed on the screen.

Message	Details	Remedy
Z51 EE ROM ERROR 000x	<p>This occurs when the parameters were not correctly written into the EEROM.</p> <p>Formatting of the machine manufacturer macro program area did not end correctly.</p> <p>The machine manufacturer macro program was not written into the FROM correctly.</p> <p><Type> Z51 ROM error 0001: Open error Z51 ROM error 0002: Erase error Z51 ROM error 0003: Write error Z51 ROM error 0004: Verify error</p>	<ul style="list-style-type: none"> • If the same alarm is output by the same operation, the cause is an H/W fault. Contact the Service Center. • Reformat the area. • Write to the FROM again.
Z52 BATTERY FAULT	<p>The voltage of the battery inserted in the NC control unit has dropped. (The battery used to save the internal data)</p>	<ul style="list-style-type: none"> • Replace the battery of the NC control unit. • After treating the battery, check the machining program,
Z53 TEMP. OVER	<p>The controller or operation board temperature has risen above the designated value. (Note 1)</p>	<ul style="list-style-type: none"> • Cooling measures are required. Turn OFF the controller power, or lower the temperature with a cooler, etc.
Z55 RIO NOT CONNECT	<p>This occurs when an error occurs in the communication between the controller and remote I/O unit.</p> <ul style="list-style-type: none"> • Cable breakage • Remote I/O unit fault • Power supply to remote I/O unit fault <p style="text-align: right;">(Note 2)</p>	<ul style="list-style-type: none"> • Check and replace the cables. • Replace the remote I/O unit. • Check the power supply. (existence of supply, voltage)
Z57 SYSTEM WARNING	<p>The program memory capacity setting value cannot be formatted. The expansion cassette (HR437) is not mounted after formatting. An expansion cassette different from the expansion cassette (HR437) mounted during formatting is mounted.</p> <p style="text-align: right;">(Note 3)</p>	<p>Check the state of the following items.</p> <ul style="list-style-type: none"> • Program memory capacity • Status of expansion cassette (HR437) mounting • APLC open option
Z58 ROM WR UNFIN	<p>The machine manufacturer macro program was not written to the FROM after being registered, edited, copied, condensed, merged, the number changed, or deleted.</p>	<ul style="list-style-type: none"> • Write the machine manufacturer macro program to the FROM. * If the operations, such as editing, done while the NC power was OFF can be invalidated, the program does not need to be written to the FROM.

1. LIST OF ALARMS
1.5 SYSTEM ALARMS

Message	Details	Remedy
Z59 TIME CONSTANT	Acceleration and deceleration time constants are too large. (This alarm is output at the same time as "T02 FEED HOLD 0206.")	<ul style="list-style-type: none"> • Increase the value specified as the #1206 G1bF parameter. • Decrease the value specified as the #1207 G1btL parameter. • Lower the feedrate.

⚠ CAUTION

❗ If the battery low warning is issued, save the machining programs, tool data and parameters in an input/output device, and then replace the battery. When the battery alarm is issued, the machining programs, tool data and parameters may be destroyed. Reload the data after replacing the battery.


- ⚠ Do not replace the battery while the power is ON.
- ⚠ Do not short circuit, charge, heat, incinerate or disassemble the battery.
- ⚠ Dispose of the spent battery following local laws.

Note 1: Temperature warning

If the alarm is displayed when an overheat alarm is detected, the overheat signal will be output simultaneously. If the machine is in automatic operation, the operation will be continued, but restarting will not be possible after resetting or stopping with M02/M30. (Starting will be possible after block stop or feed hold.) The alarm will be reset and the overheat signal will turn OFF when the temperature drops below the specified temperature.

Z53 TEMP. OVER	000x	
	↑	
	0001	: The temperature in the controller is high.
	0002	: The temperature around the communication terminal (setting and display unit) is high.
	0003	: The temperature in the controller and around the communication terminal (setting and display unit) is high.


The ambient temperature must be lowered immediately when a "Z53 TEMP.OVER" alarm occurs, but if machining must be continued, the alarm can be invalidated by turning the following parameter OFF.



1. LIST OF ALARMS
1.5 SYSTEM ALARMS

Note 2: RIO communication interrupt

If communication between the control unit and remote I/O unit fails, the alarm and remote I/O unit number are displayed.



(a) and (b) above indicate the following matters.

Alarm number	RIO (seventh station)	RIO (sixth station)	RIO (fifth station)	RIO (fourth station)
0				
1				X
2			X	
3			X	X
4		X		
5		X		X
6		X	X	
7		X	X	X
8	X			
9	X			X
A	X		X	
B	X		X	X
C	X	X		
D	X	X		X
E	X	X	X	
F	X	X	X	X

Alarm number	RIO (third station)	RIO (second station)	RIO (first station)	RIO (0th station)
0				
1				X
2			X	
3			X	X
4		X		
5		X		X
6		X	X	
7		X	X	X
8	X			
9	X			X
A	X		X	
B	X		X	X
C	X	X		
D	X	X		X
E	X	X	X	
F	X	X	X	X

This applies for both the remote I/O 1st system communication interrupted station and board connection remote I/O communication interrupted station.

Note 3: System warning

Z57	SYSTEM WARNING	00xx	0000
		↑	
		001x	:When the expansion cassette (HR437) is not mounted, a program memory capacity exceeding 1280m was designated.
		002x	:When the APLC open option was validated, 5120m was designated for the program memory capacity.
		00x1	: After formatting the program memory capacity to 1280m or more, the expansion cassette (HR437) was removed, or an expansion cassette (HR437) not used during formatting was mounted.

1.6 ABSOLUTE POSITION DETECTION SYSTEM ALARMS

Z70 ABS. ILLEGAL □□□□ □□□□ (Error No.) (Axis name)		This error is displayed if the absolute position data is lost in the absolute position detection system.			
Error No.	Details	Remedy	Zero point initialization	Alarm reset when power is turned OFF	Servo alarm No.
0001	Zero point initialization is incomplete. Otherwise, the spindle was removed.	Complete zero point initialization.	Required	-	-
0002	The absolute position reference point data saved in the NC has been destroyed.	Input the parameters. If the reference point data cannot be restored, perform zero point initialization.	(Required)	-	-
0003	The parameters used to detect the absolute position have been changed. #1003 iunit #2201 PC1 #1016 iout #2202 PC2 #1017 rot #2218 PIT #1018 ccw #2219 RNG1 #1040 M_inch #2220 RNG2 #2049 type #2225 MTyp	Correctly set the parameters. Turn the power on again, and perform zero point initialization.	Required	-	-
0004	The zero point initialization point is not at the grid position.	Reperform zero point initialization.	Required	-	-
0005	Restoration was possible with parameter input in the above No.0002 state.	Turn the power on again, and operation will be possible.	Not required	-	-
0080	The absolute value data was lost, because the multi-rotation counter data in the detector was incorrect, etc.	Replace the detector and complete zero point initialization.	Required	-	(9E) etc.
0101	The power was turned ON again after the servo alarm No. 25 displayed.	Reperform zero point initialization.	Required	-	(25)
0106	The power was turned ON again after the servo alarm No. E3 displayed.	Reperform zero point initialization.	Required	-	(E3)

Note: To release alarm "Z70 ABS. ILLEGAL", enter the parameter data output when establishing the absolute position and turn ON the power again. For the rotation axis, however, the alarm cannot be released by entering the parameter data.

1. LIST OF ALARMS
1.6 ABSOLUTE POSITION DETECTION SYSTEM ALARMS

Z71 DETECTOR ERROR □□□□ □□□□ (Error No.) (Axis name)			This alarm is displayed if an error is found in the detector for the absolute position detection system.		
Error No.	Details	Remedy	Zero point initialization	Alarm reset when power is turned OFF	Servo alarm No.
0001	The backup voltage in the absolute position detector dropped.	Replace the battery, check the cable connections, and check the detector. Turn the power ON again, and perform zero point initialization.	Required	- (Z70-0101 displays after power is turned ON again.)	25
0003	Communication with the absolute position detector was not possible.	Check and replace the cables, card or detector. Turn the power ON again, and perform zero point initialization.	(Required) Only when detector is replaced.	Reset	91
0004	The absolute position data fluctuated when establishing the absolute position.	Check and replace the cables, card or detector. Turn the power ON again, and perform zero point initialization.	(Required) Only when detector is replaced.	Reset	93
0005	An error was found in the serial data from the absolute position detector.	Check and replace the cables, card or detector. Turn the power ON again, and perform zero point initialization.	(Required) Only when detector is replaced.	Reset	92
0006	Servo alarm E3 Absolute position counter warning	Operation is possible until the power is turned off.	(Required) When power is turned ON again.	Reset (Z70-0106 displays after power is turned ON again.)	E3
0007	Initial communication with the absolute position detector was not possible.	Check and replace the cables, card or detector. Turn the power ON again, and perform zero point initialization.	(Required) Only when detector is replaced.	Reset	18

1. LIST OF ALARMS
1.6 ABSOLUTE POSITION DETECTION SYSTEM ALARMS

Z72 COMPARE ERROR □□□□ □□□□ (Alarm No.) (Axis name)		This alarm is displayed if an error is detected when comparing the detector's absolute position and controller coordinate values in the absolute position system.
Alarm No.	Details	Remedy

Z73 ABS. WARNING □□□□ □□□□ (Warning No.) (Axis name)		This displays a warning in the absolute position detection system.
Alarm No.	Details	Remedy
0001	Servo alarm 9F Battery voltage drop	The battery voltage dropped or a cable is broken. Absolute position initialization is not required.

1.7 MESSAGES DURING EMERGENCY STOP

EMG EMERGENCY ****		
<div style="margin-left: 20px;"> Error items Refer to the explanations for details. </div>		
Error No.	Details	Remedy
PLC	The user PLC has entered the emergency stop state during the sequence process.	<ul style="list-style-type: none"> Investigate and remove the cause of the user PLC emergency stop.
EXIN	The emergency stop input signal is significant (open).	<ul style="list-style-type: none"> Cancel the emergency stop input signal. Check the wiring to see if any wiring is broken.
SRV	An alarm occurred in the servo system causing an emergency stop.	<ul style="list-style-type: none"> Investigate and remove the cause of the servo alarm.
STOP	The user PLC (ladder sequence) is not running.	<ul style="list-style-type: none"> Check if the rotary switch CS2 on the top of the controller front panel is set to 1. Check if the PLC edit file save screen (onboard function) [4RUN/SP] (run/stop) switch is turned ON.
SPIN	Spindle amplifier not mounted The spindle amplifier is not mounted.	<ul style="list-style-type: none"> Cancel the causes of the other emergency stop. Check emergency stop signal input in the spindle amplifier.
PC_H	High-speed PC processing abnormal	<ul style="list-style-type: none"> Check the sequence program. (To stop monitoring the high-speed PC processing temporarily, set 1 in #1219 aux03 bit1. Disable the monitoring function only as a temporary measure.)
PARA	Setting of the door open II fixed device is illegal. The dog signal random assignment parameter setting is illegal.	<ul style="list-style-type: none"> Specify the #1155 DOOR_m and #1156 DOOR_s parameters correctly. (When the door open II fixed device is not used, set #1155 DOOR_m and #1156 DOOR_s to 100.) Correctly set the #2073 zrn_dog, #2074 H/W_OT+, #2075 H/W_OT-and #1226 aux 10 bit 5 parameters.
LINK	If the FROM/TO instruction is not executed within 500 ms, an emergency stop occurs.	<ul style="list-style-type: none"> Try to execute the FROM or TO instruction one or more times every 500 ms. * Measure the time in which no interrupt request is issued from MELSEC and store the result in the R register. R1880: Current time-out counter R1881: Counter for maximum time-out after power-on R1882: Counter for maximum time-out after system start-up (backed up)


1. LIST OF ALARMS
1.7 MESSAGES DURING EMERGENCY STOP

Error No.	Details	Remedy
LINK	MELSEC is held in error and reset states.	<ul style="list-style-type: none"> • Check the MELSEC states.
	The contents of MELSEC-specific code area in buffer memory have been destroyed.	<ul style="list-style-type: none"> • Check the MELSEC states.
	PLC serial link communication has stopped. Note: When WAIT is entered for the PLC serial link, only the preparation sequence has been established before the communication stops. Therefore, it is supposed that the basic specification parameters or serial link parameters #1902 and #1903 are incorrect or the #1909 set-time "Tout (ini)" is too short.	<ul style="list-style-type: none"> • Check that HR571 card wiring and external sequencer transmission are normal. • Check the diagnostic screen for link communication errors. • Check whether the basic specification parameters or serial link parameters are specified correctly.
WAIT	The preparation sequence is not sent from the master station. Otherwise, the contents of the received preparation sequence are inconsistent with those of the parameters, so that the usual sequence cannot be started. Note: When LINK is also entered for the PLC serial link, refer to "Note" in the section, "LINK".	<ul style="list-style-type: none"> • Check that the HR571 card rotary switch and wiring and the external sequencer transmission are normal. • Check the diagnostic screen for link communication errors.
XTEN	The HR571 card operates abnormally or the rotary switch is set incorrectly.	<ul style="list-style-type: none"> • Check the HR571 card rotary switch and replace the HR571 card if required.
LAD	The user PLC (ladder sequence) has an illegal code.	<ul style="list-style-type: none"> • Check the user PLC (ladder sequence) to see if it uses illegal device numbers or constants.

1.8 AUXILIARY AXIS ALARMS

Display example

S01 AUX SERVO ALM



(1) S01 AUX SERVO ALM

Alarm information	Details		Remedy
0011	PCB error 1	An error occurred in the amplifier's internal PCB.	<ul style="list-style-type: none"> Replace servo amplifier.
0013	Software processing timeout, clock error	An error occurred in the amplifier's internal reference clock.	<ul style="list-style-type: none"> Replace servo amplifier.
0016	Motor type, detector type error	Motor type error	<ul style="list-style-type: none"> Use a correct amplifier and motor combination.
		Detector initial communication error.	<ul style="list-style-type: none"> Connect correctly. Replace the motor. Replace or repair cable.
		Detector CPU error	<ul style="list-style-type: none"> Replace the motor (detector).
0017	PCB error (A/D conversion initial error)	An error occurred in the amplifier's internal A/D converter.	<ul style="list-style-type: none"> Replace servo amplifier.
0025	Absolute position lost	An error occurred in the detector's internal absolute position data.	<ul style="list-style-type: none"> Turn the power ON for 2 to 3 minutes while the alarm is occurring, and then turn the power ON again. Replace the battery, and initialize the absolute position again.
0034	CRC error	An error occurred in the communication with the NC.	<ul style="list-style-type: none"> Take countermeasures against noise.
0036	Communication timeout, NC down	Communication with the NC was cut off.	<ul style="list-style-type: none"> Connect correctly. Turn the NC power ON. Replace the amplifier or NC.
0037	Parameter error (Regenerative resistance error)	The parameter setting value is incorrect.	<ul style="list-style-type: none"> Set the parameter correctly.
0038	Frame error	An error occurred in the communication with the NC.	<ul style="list-style-type: none"> Take countermeasures against noise.
0039	INFO error	Undefined data was transferred from the NC.	<ul style="list-style-type: none"> Change the NC software version to a compatible version.

1. LIST OF ALARMS
1.8 AUXILIARY AXIS ALARMS

(2) S02 AUX SERVO ALM

Alarm information	Details		Remedy
0011	PCB error 1 (drive circuit error)	An error occurred in the amplifier's internal PCB.	<ul style="list-style-type: none"> • Replace servo amplifier.
0013	Software processing timeout, clock error	An error occurred in the amplifier's internal reference clock.	<ul style="list-style-type: none"> • Replace servo amplifier.
0015	EEROM error	A write error occurred to the EEROM in the amplifier.	<ul style="list-style-type: none"> • Replace servo amplifier.
0017	PCB error (A/D conversion error)	An error occurred in the amplifier's internal A/D converter.	<ul style="list-style-type: none"> • Replace servo amplifier.
0018	PCB error (LSI error)	An error occurred in the amplifier's internal LSI.	<ul style="list-style-type: none"> • Replace servo amplifier.
0020	Detector error	An error occurred in the communication between the servo amplifier and detector.	<ul style="list-style-type: none"> • Connect correctly. • Replace or repair cable.
0024	Ground fault detection	A ground fault of the output was detected when the power was turned ON.	<ul style="list-style-type: none"> • Repair the ground fault section. • Replace the cable or motor.

(3) S03 AUX SERVO ALM

Alarm information	Details		Remedy
0010	Undervoltage	The power voltage is 160V or less.	<ul style="list-style-type: none"> • Review the power supply. • Replace the servo amplifier.
0030	Regeneration error	The tolerable regeneration power of the internal regenerative resistor or external regenerative option was exceeded.	<ul style="list-style-type: none"> • Set the parameter #002 correctly. • Connect correctly. • Lower the positioning frequency. • Change the regenerative option to a larger capacity. • Lower the load. • Review the power supply.
		Regenerative transistor error	<ul style="list-style-type: none"> • Replace the servo amplifier.
0031	Overspeed	The motor's rotation speed exceeded the tolerable momentary speed.	<ul style="list-style-type: none"> • Increase the acceleration/ deceleration time constant. • Review the gear ratio. • Replace the detector.
0032	Overcurrent	A current exceeding the servo amplifier's tolerable current flowed.	<ul style="list-style-type: none"> • Repair the wiring. • Replace the servo amplifier. • Take countermeasures against noise.

1. LIST OF ALARMS
1.8 AUXILIARY AXIS ALARMS

Alarm information	Details		Remedy
0033	Overvoltage	The voltage of the converter in the servo amplifier was 400V or more.	<ul style="list-style-type: none"> • Wire correctly. • Replace the servo amplifier. • For the internal regenerative resistor, replace the amplifier. • For the external regenerative option, replace the regenerative option.
0046	Motor overheating	An operation state causing the motor to overheat continued.	<ul style="list-style-type: none"> • Reduce the motor load. • Review the operation pattern.
0050	Overload 1	The servo amplifier or servomotor overload protection function activated.	<ul style="list-style-type: none"> • Reduce the motor load. • Review the operation pattern. • Change to a motor or amplifier with large output. • Change the setting of the automatic tuning response characteristics. • Correct the connection. • Replace the servomotor.
0051	Overload 2	The max. output current flowed for several seconds due to a machine collision or overload.	<ul style="list-style-type: none"> • Review the operation pattern. • Change the setting of the automatic tuning response characteristics. • Correct the connection. • Replace the servomotor.
0052	Excessive error	A position deflection exceeding the excessive error detection setting value occurred.	<ul style="list-style-type: none"> • Increase the acceleration/ deceleration time constant. • Increase the torque limit value. • Review the power facility capacity. • Review the operation pattern. • Replace the servomotor. • Connect correctly. • Repair or replace the cable.

1. LIST OF ALARMS
1.8 AUXILIARY AXIS ALARMS

(4) S52 AUX SERVO WRN

Alarm information	Details		Remedy
0092	Battery voltage drop	The absolute position detection battery voltage dropped.	<ul style="list-style-type: none"> • Mount a battery. • Replace the battery and initialize the absolute position.
00E0	Over-regeneration warning	The regeneration power may have exceeded the tolerable range of the built-in regenerative resistor or external regenerative option.	<ul style="list-style-type: none"> • Lower the positioning frequency. • Change the regenerative option to a larger one. • Lower the load.
00E1	Overload warning	The overload alarm 1 could occur.	<ul style="list-style-type: none"> • Refer to the items for S030050.
00E3	Absolute position counter warning	There is an error in the absolute position detector internal data.	<ul style="list-style-type: none"> • Take countermeasures against noise. • Replace the servomotor.
00E9	Main circuit OFF warning	The servo ON signal was input while the main circuit power was OFF. The contactor operation is faulty.	<ul style="list-style-type: none"> • Turn ON the main circuit power.

(5) Z70 AUX POS. ERR

Alarm information	Details	Cause	Remedy
0001	Zero point initialization incomplete	The zero point (reference point) has not been initialized in the absolute position system.	<ul style="list-style-type: none"> • Initialize the zero point (reference point).
0002	Absolute position data lost	The absolute position coordinate data in the amplifier has been lost.	<ul style="list-style-type: none"> • Initialize the zero point (reference point).
0003	Absolute position system related parameter error	The absolute position system related parameters have been changed or lost.	<ul style="list-style-type: none"> • Correctly set the parameters and then initialize the zero point (reference point).

(6) Z71 AUX DETEC. ERR

Alarm information	Details	Cause	Remedy
0001	Absolute position memory battery voltage drop	The data in the detector has been lost. Battery voltage drop. Detector cable wire breakage or looseness.	<ul style="list-style-type: none"> • Check the battery and detector cable and then initialize the zero point (reference point).

1. LIST OF ALARMS
1.8 AUXILIARY AXIS ALARMS

(7) Z73 AUX SYSTEM WRN

Alarm information	Details	Cause	Remedy
0001	Absolute position memory battery voltage warning	Battery voltage drop. Detector cable wire breakage or looseness.	<ul style="list-style-type: none"> Check the battery and detector cable. The zero point does not need to be initialized.
0003	Absolute position counter warning	An error occurred in the detector's absolute position counter.	<ul style="list-style-type: none"> Replace the detector.

(8) M00 AUX OPER. ALM

Alarm information	Details	Cause	Remedy
0001	Near-point dog length insufficient	When executing dog-type reference point, the zero point return speed is too fast or the dog length is too short.	<ul style="list-style-type: none"> Lower the zero point return speed or increase the dog length.
0003	Reference point return direction illegal	When executing reference point return, the axis was moved in the opposite of the designated direction.	<ul style="list-style-type: none"> Move the axis in the correct direction.
0004	External interlock	The axis interlock function is valid.	<ul style="list-style-type: none"> Cancel the interlock signal
0005	Internal interlock	An interlock was established by the servo OFF function.	<ul style="list-style-type: none"> Cancel the servo OFF.
0007	Soft limit	The soft limit was reached.	<ul style="list-style-type: none"> Check the soft limit setting and machine position
0024	In absolute position alarm. Reference point return not possible.	Reference point return was executed during an absolute position alarm.	<ul style="list-style-type: none"> Initialize the absolute position reference point and then fix the absolute position coordinates.
0025	In initializing absolute position. Reference point return not possible.	Reference point return was executed while initializing the absolute position.	<ul style="list-style-type: none"> Initialize the absolute position reference point and then fix the absolute position coordinates.

1. LIST OF ALARMS
1.8 AUXILIARY AXIS ALARMS

(9) M01 AUX OPER. ALM

Alarm information	Details	Cause	Remedy
0101	No operation mode	The operation mode is not designated, or the operation mode was changed during axis movement.	<ul style="list-style-type: none"> • Correctly designate the operation mode.
0103	Feedrate 0	The operation parameter's feedrate setting is zero. The operation parameter feedrate setting is zero. Or, the override is valid, and the override value is zero.	<ul style="list-style-type: none"> • Set a value other than zero in the feedrate setting or override value.
0160	Station No. designation illegal. Starting not possible.	A station No. exceeding the No. of indexed divisions was designated.	<ul style="list-style-type: none"> • Correctly designate the station No.
0161	Reference point return incomplete. Starting not possible.	Automatic/manual operation was started before reference point return was executed with the incremental system.	<ul style="list-style-type: none"> • Execute the reference point return.
0162	In initializing reference point. Starting not possible.	The start signal was input while initializing the absolute position reference point.	<ul style="list-style-type: none"> • Complete the absolute position reference point initialization.
0163	In absolute position alarm. Starting not possible.	The start signal was input during an absolute position alarm.	<ul style="list-style-type: none"> • Initialize the absolute position reference point and then fix the absolute position coordinates.
0164	In random positioning mode. Manual operation not possible.	The manual operation mode was started during the random positioning mode.	<ul style="list-style-type: none"> • Turn the random positioning mode OFF before switching to the manual operation mode.
0165	Uneven indexing station No. illegal. Starting not possible.	The commanded station No. was higher than 9 or the number of indexing stations during uneven indexing.	<ul style="list-style-type: none"> • Check the commanded station No. and the parameter "#100 station" setting.

1. LIST OF ALARMS
1.8 AUXILIARY AXIS ALARMS

AUXILIARY AXIS MCP ALARMS

Y02 AUX SYSTEM ALM		An error occurred in the data transmitted between the MCP and auxiliary axis amplifier after the power was turned ON.	
Error No.	Details		Remedy
0050	Background error		The software or hardware may be damaged. Contact the service center.
0051	0000	CRC error (10 times/910.2ms)	A communication error has occurred between the controller and amplifier. <ul style="list-style-type: none"> • Take measures against noise. • Check that the communication cable connector between the controller and amplifier and one between the amplifiers are tight. • Check whether the communication cable between the controller and amplifier and one between the amplifiers are disconnected. • A driving amplifier may be faulty. Take a note of the 7-segment LED contents of each driving amplifier and report to the Service Center.
	0001	CRC error (2 continuous times)	
	0002	Reception timing error (2 continuous times)	
	xx03	Data ID error (2 continuous times) xx: Axis No.	
	xx04	No. of reception frames error (2 continuous times) xx: Axis No.	

Y03 AUX AMP UNEQU.		Check the auxiliary axis amplifier mounting state. <ul style="list-style-type: none"> • Check the end of the cable wiring. • Check the cable for broken wires. • Check the connector insertion. The auxiliary axis amplifier input power is not being input. The auxiliary axis amplifier axis No. switch is illegal.	
The amplifier is not correctly connected.			
Error No.	Details		
Axis No.1 to 4	bit correspondence (bit 0 : 1st axis, bit 1: 2 nd axis, bit 2: 3rd axis, bit 3: 4th axis)		

1. LIST OF ALARMS
1.9 COMPUTER LINK ERRORS

1.9 COMPUTER LINK ERRORS

Error Message	Error No.	Details	Remedy
L01 DNC ERROR	-4	Communication ends with timeout. CNC has a 248-byte receive buffer. The time during which CNC receives 248 bytes exceeds the "TIME-OUT" value set in the I/O device parameter.	(1) Set a greater timeout value in the input/output device parameter. (2) Recheck the HOST software as to whether or not the HOST transmits data in response to DC1 from CNC (data request). (3) Check whether or not start code of computer link parameter is set to 0.
	-10	HOST ER (CNC DR) signal is not turned ON.	(1) Check whether or not the cable is disconnected from the connector. (2) Check whether or not the cable is broken. (3) Check whether or not the HOST power is turned ON.
	-15	Communication ends with parity H.	(1) Recheck the HOST software as to whether or not the data to be transmitted to CNC is ISO code.
	-16	Communication ends with parity V.	(1) Recheck the data to be transmitted to CNC.
	-17	Although CNC transmits DC3 (request to stop data transfer) to the HOST, it receives data of 10 bytes or more from the HOST, thus terminates communication. When CNC is transmitting data to the HOST, it receives data of 10 bytes or more from the HOST.	(1) Recheck the software as to whether or not the HOST stops transmitting data within 10 bytes after receiving DC3. (2) Recheck the HOST software as to whether or not the HOST transmits data such as a command or header to CNC during receiving a work program.

1. LIST OF ALARMS
1.10 USER PLC ALARMS

1.10 USER PLC ALARMS

Message	Sub-status		Details	Remedy
	1	2		
U01 No PLC	-	-	The ladder is not a GPPW ladder or PLC4B ladder. (Note) Emergency stop (EMG) will be applied.	Download the ladder of the format selected with the PLC environment selection parameters (bit selection #51/bit 4).
U10 Illegal PLC	0x0010	-	Scan time error The scan time is 1 second or longer.	Edit the ladder size to a smaller size.
	0x0040	-	Ladder operation mode illegal A ladder different from the designated mode was downloaded. (Note) Emergency stop (EMG) will be applied.	Download the ladder having the same format as when the power was reset or turned ON.
	0x0080	-	GPPW ladder code error (Note) Emergency stop (EMG) will be applied.	Download the correct GPPW format ladder.
	0x008x	-	PLC4B ladder code error An illegal circuit was found in the PLC4B ladder. bit1: PC medium-speed circuit illegal bit2: PC high-speed circuit illegal (Note) Emergency stop (EMG) will be applied.	Download the correct PLC4B format ladder.
	0x0400	Number of ladder steps	Software illegal interrupt The ladder process stopped abnormally due to an illegal software command code. (Note) Emergency stop (EMG) will be applied.	Turn the power ON again. If the error is not reset, download the correct ladder.
	0x800x	Number of ladder steps	Software exceptional interrupt The ladder process stopped abnormally due to a bus error, etc.	Refer to the methods for using the BCD and BIN function commands.
bit 0: BIN command operation error bit 1: BCD command operation error				
bit6: CALL/CALLS/RET command error bit7: IRET command execution error (Note) Emergency stop (EMG) is applied for bit 6/7.			Turn the power ON again. If the error is not reset, download the correct ladder.	
U50 Stop PLC			The ladder is stopped.	Start the ladder.

(Note) The number of ladder steps displayed on the screen may not match the actual number of error occurrence steps because of the ladder timing. Use this as a guideline of the occurrence place.

1. LIST OF ALARMS
1.11 NETWORK SERVICE ERRORS

1.11 NETWORK SERVICE ERRORS

Message	Details	Remedy
N001 Modem init err	<ul style="list-style-type: none">• There is an error in the modem connection when the power is turned ON.	<ul style="list-style-type: none">• Check the connection between the NC and modem, connection port and modem power.
N002 Redial over	<ul style="list-style-type: none">• The dial transmission failed more than the designated No. of redial times.	<ul style="list-style-type: none">• Wait a while, and then transmit again.
N003 TEL unconnect	<ul style="list-style-type: none">• The phone line is not connected.	<ul style="list-style-type: none">• Check the modem's phone line connection.
N004 Net com. error	<ul style="list-style-type: none">• An error other than the above errors occurred during communication.	<ul style="list-style-type: none">• Note down the circumstances under which this error occurred, and contact the Service Center.
N005 Bad net com.	<ul style="list-style-type: none">• The modem connection port is being used for another function such as input/output.• The modem connection port settings are incorrect.	<ul style="list-style-type: none">• Quit using the modem connection port with the other function, and then turn the power ON again.• Check the modem connection port settings.

2. OPERATION MESSAGES ON SETTING AND DISPLAY UNIT

If a setting operation error occurs on any setting and display unit screen, the error No. E00 and a message describing the details of the error will display in the line above the data setting area or the menu display area.

2.1 OPERATION ERRORS

△: Message requiring resetting and restarting

x: Message requiring restarting after canceling error conditions

(The bold characters are the messages displayed on the screen.)

Error No.	Error message	Details
E01	SETTING ERROR	<p>△</p> <ul style="list-style-type: none"> • The setting data is incorrect. An alphabetic character was set when only number can be set, etc. • Data was input without setting number (#). <p>(Word editing)</p> <ul style="list-style-type: none"> • Even though no retrieval data was set, menu key [↓] or [↑] was pressed. • Even though no data is stored in edit buffers, menu key "Replace" was pressed. • One of the following characters was entered as the first character of the retrieval data and edit buffers: 0 to 9, ". ", " " (space), "+", "-", "=", "*", "[]", and ' " " '. • When the incremental detection system was used, the parameter (#0 absolute position setting) was set on the absolute position setting screen. • The data input for the standard parameter setting or during execution of formatting is not "Y" or "N". • A value from 4 to 10 was specified for #1043 lang. • Even though no language data exists, its output and comparison were attempted. Check the numbers (0253 and 0254) of the language data to be output. • When the machine manufacturer macro program memory area is the SRAM area, the setup parameter #1060 SETUP was set to "20". • When the machine manufacturer macro program memory area is the SRAM area, writing of the machine manufacturer macro program was attempted on PROGRAM COPY screen.

2. OPERATION MESSAGES ON SETTING AND DISPLAY UNIT
2.1 OPERATION ERRORS

Error No.	Error message	Details
E02	DATA OVER	<div style="display: flex; align-items: center;"> <div style="margin-right: 10px;">△</div> <ul style="list-style-type: none"> • The setting data exceeded the setting range. • The compensation data specification exceeded the range when inputting the tool offset data on tape, so that block could not be input. Press the INPUT key again while the input screen is displayed, and the input will continue from the next block. • When workpiece coordinate offsets are measured, the calculation results given by pressing the CALC key are exceeding the specified range. Correctly specify the tool length or the wear data of cutting edges used for the calculation. • #1003 iunit was set to D when the least command increment 0.01μm option was not available. • When there was no option, 2 or more was specified for #1043 lang. Otherwise, an option was added and 23 or more was specified for #1043 lang. </div>
E03	No. NOT FOUND	<div style="display: flex; align-items: center;"> <div style="margin-right: 10px;">△</div> <ul style="list-style-type: none"> • The corresponding setting No. (#) was not found. This error occurs if a setting No. not found on the screen was set and input, or if a variable No. not found in the specifications was set and input for the common variables. • When the tool length was measured manually, a nonexisting tool wear compensation number was specified and the sensor was turned ON. Specify the R register of the offset number correctly. </div>
E04	DEV. NOT READY	<div style="display: flex; align-items: center;"> <div style="margin-right: 10px;">×</div> <ul style="list-style-type: none"> • The input/output unit power is not ON. • The cable is disconnected. • Setting of the transfer speed (baud rate) does not agree. </div>

2. OPERATION MESSAGES ON SETTING AND DISPLAY UNIT
2.1 OPERATION ERRORS

Error No.	Error message	Details
E05	NOT ACCEPTABLE	<p>×</p> <ul style="list-style-type: none"> • The PLC timer cannot be set from the screen when the program is valid. (When machine parameter bit selection #6449 bit 1 is set to 1.) • The PLC counter cannot be set from the screen when the program is valid. (When machine parameter bit selection #6449 bit 0 is set to 1.) • The tool registration data setting is prohibited. (When special relay E71 is valid by the PLC.) • Setting from the tool life management screen is prohibited. • Absolute position setting screen's #1 "ORIGIN" and #2 "ZERO" cannot be set when #0 "INIT SET" is invalid. • The total of axes set in #1001 SYS_ON, #1002 axisno is illegal. Set so that the total No. of axes is within the specifications range for the target model. • #1037 cmdtyp is not within the setting range. • The INPUT key was pressed to perform search for the program that is in background edit status on the word edit screen. • The menu keys (Replace and Insert) on the word edit screen were manipulated when a running program is displayed (PDISP signal: ON). • An attempt was made to set MDI data in an MDI setting lock state (the MDI setting lock parameter is specified with 0 and a non-MDI mode is valid). • Language data in display selection status was entered. Change the display selection status once before entering the data. (#1043 lang) • When the manual value command protection (#1228 aux12/bit7) function is valid, the first monitor screen was manipulated by manual command operation (M, S, and T keys).
E06	NO SPEC	<p>×</p> <ul style="list-style-type: none"> • The menu key for a function not in the specifications was pressed. • A parameter not in the specifications was set. • A language that was not added as an option was selected. (#1043 lang) • Set up parameter #1049 mmac_R was set to "1" when the machine manufacturer macro option was not valid. • Set up parameter #1060 SETUP was set to "20" when the machine manufacturer macro option was not valid. • Writing of the machine manufacturer macro program with the PROGRAM COPY screen was attempted when the machine manufacturer macro option was not valid.

2. OPERATION MESSAGES ON SETTING AND DISPLAY UNIT
2.1 OPERATION ERRORS

Error No.	Error message		Details
E07	RESET END	Δ	<ul style="list-style-type: none"> The input/output operations were forcibly stopped by reset, etc. (including EMG).
E08	PHYSICAL ERR	×	<ul style="list-style-type: none"> The input/output parameter setting or input/output unit side setting was incorrect.
E09	TIME OUT	×	<ul style="list-style-type: none"> The input/output unit parameter "#9116 TIME-OUT SET" setting was too short. There is no EOB code in the machining program.
E10	MEMORY OVER	×	<ul style="list-style-type: none"> The program cannot be written because the memory capacity is exceeded. This error occurs when the MDI data setting on the MDI screen exceeds 500 characters, or when saving MDI, editing or making a program on the edit screen, input on the data input/output screen, program copy, etc.
E11	PROG. No. DUPLI	Δ	<ul style="list-style-type: none"> When registering a machining program in the memory, a program with the same No. as the designated program No. was found in the memory. Refer to the program file to find a program No. not being used, and reset the program No. A program with the same No. as the machining program to be copied from the memory was found in the IC card. This error occurs during MDI registration in the MDI screen or during creation of a program in the edit screen.
E12	FILE ENTRY OVER	×	<ul style="list-style-type: none"> When registering a machining program in the memory, the No. of programs determined in the specifications is exceeded, preventing registration. This error occurs during MDI registration in the MDI screen, creation of a program in the edit screen, data input in the data input/output screen, and program copy.
E13	NB NOT FOUND	Δ	<ul style="list-style-type: none"> The block with the designated sequence No. or block No. does not exist in the designated program.
E14	PROG. NOT FOUND	Δ	<ul style="list-style-type: none"> The designated program is not found in the memory. The corresponding program No. was not found with search of tape memory during graphic check.
E15	EDIT LOCK B	×	<ul style="list-style-type: none"> An operation (edit, input/output, buffer correction, etc.) inhibited for machining program B was attempted.
E16	EDIT LOCK C	×	<ul style="list-style-type: none"> An operation (edit, input/output, buffer correction, etc.) inhibited for machining program C was attempted.
E17	PARITY H ERR	×	<ul style="list-style-type: none"> A parity H error was detected during data input, etc. Check the paper tape or input device. This error may occur if the paper tape is dirtied with oil, etc.
E18	PARITY V ERR	×	<ul style="list-style-type: none"> A parity V error was detected during data input. Check the paper tape to see whether the number of characters in the significant information section of a block is odd. Also check the state (cable wiring, noise measures, etc.) of the connected equipment.

2. OPERATION MESSAGES ON SETTING AND DISPLAY UNIT
2.1 OPERATION ERRORS

Error No.	Error message	Details
E20	OVER RUN ERR	× <ul style="list-style-type: none"> • The control method using the DC codes, etc., for the input/output operation is incorrect. • Check the settings of the input/output unit parameters, and the settings on the input/output unit side, and reset if necessary.
E21	PROGRAM RUNNING	× <ul style="list-style-type: none"> • Deletion of a machining program was attempted during operation. • Search was attempted during operation. • Change of data such as parameters was attempted during operation. • Start of graphic check was attempted during operation. • When using the two systems, the program being buffer corrected was running with the other system. • Erasing or inputting (IC → NC) of a program in the IC card being used was attempted. • Formatting of the IC card was attempted during automatic start. • Accessing to the host computer was attempted during automatic operation.
E22	CODE CHANGE ERR	× <ul style="list-style-type: none"> • There was an illegal code on the paper tape.
E24	PLC RUN	× <ul style="list-style-type: none"> • Data input/output or comparison was attempted when the PLC was not stopped. • Analog output adjustment was attempted when the PLC was not stopped. • An attempt was made to input or output language data during PLC execution. • When the machine manufacturer macro program memory area was set to the FROM area, formatting of the FROM area (#1060 SETUP "20") was attempted when the PLC was not stopped, writing of the machine manufacturer macro program was attempted on the PROGRAM COPY screen, or input of the macro program was attempted. (Measures) Stop the PLC. • Set the control unit rotary switch to 1. • Set the onboard file screen RUN/STOP setting to 1.
E25	DATA MEMORY ERR	× <ul style="list-style-type: none"> • When inputting the tool offset data onto tape, an offset type exceeding the specifications range was designated, and that block could not be input. If the INPUT key is pressed again in the input screen, the input will continue from the next block.
E26	NO CHARACTERS	△ <ul style="list-style-type: none"> • The designated character string was not found from the block displayed on the screen to the end of the program when searching with data search in the edit screen. Press the INPUT key again' and the search will start at the head of the program.
E35	COMPARE ERROR	× <ul style="list-style-type: none"> • An inconsistency was found in the paper tape and memory data during comparison.
E40	OP MODE ERROR	× <ul style="list-style-type: none"> • Continuous or step graphic check was not possible because the operation mode was illegal.

2. OPERATION MESSAGES ON SETTING AND DISPLAY UNIT
2.1 OPERATION ERRORS

Error No.	Error message		Details
E50	FILE ERR	×	<ul style="list-style-type: none"> If one of these errors occurs, the editing or input/output operations cannot be continued. Contact the Service Center. <p>As for E50, a classification No. will display at the end of the message. Inform the service center of this No. as well.</p>
E51	FILE OPEN ERR		
E52	FILE CLOSE ERR		
E53	FILE SEEK ERR		
E54	FILE READ ERR		
E55	FILE DELETE ERR		
E56	FILE INSERT ERR		
E60	IOP ERR□□	×	<p>A classification number is displayed after the message for E60.</p> <p>Refer to the section shown in parentheses, and remedy the problem.</p> <p>E60 IOP ERROR - 2 (Port already being used) E60 IOP ERROR - 4 (E09 TIME OUT) E60 IOP ERROR - 5 (E08 PHYSICAL ERR) E60 IOP ERROR - 7 (E07 RESET END) E60 IOP ERROR - 10 (E04 DEV. NOT READY) E60 IOP ERROR - 15 (E17 PARITY H ERR) E60 IOP ERROR - 16 (E18 PARITY V ERR) E60 IOP ERROR - 17 (E20 OVER RUN ERR) E60 IOP ERROR - 18 (E22 CODE CHANGE ERR) E60 IOP ERROR - 20 (framing and H/W errors)</p> <ul style="list-style-type: none"> Setting for the bit length is incorrect. (Baud rate, stop bit, and character length) Check the setting of the I/O device system and its parameters and set it again. Check the situations of the connected devices (cable wiring and noise measures). Data was input/output or the tape search was executed during the host link. Set 0 in #8109 HOST LINK, and then set 1 again before performing the cycle start. (IOP error -2) The host link parameter was turned ON during connecting to the Anshin-net. Turn the Anshin-net valid OFF. (IOP error -2) When #10812 Anshin-net/ Machine builders network system valid is set to 1, the modem connection port of the Anshin-net or machine builders network system is occupied. Perform inputting or outputting using a port other than the modem connection port. (IOP error -2) When connecting the GX Developer (when the bit selection parameter #6451 bit5 is set to 1), the port 2 of the RS232C communication port is always used. Use a port other than the port 2 of the RS232C communication port. (IOP error -2)

2. OPERATION MESSAGES ON SETTING AND DISPLAY UNIT
2.1 OPERATION ERRORS

Error No.	Error message	Details
E62	I/O PARAM ERR	△ <ul style="list-style-type: none"> • The "EIA code" data set for I/O parameter is of an unusable code. • The unusable codes are those used as the EIA standard codes and the even hole codes.
E64	PROGRAM No. ERR	△ <ul style="list-style-type: none"> • The same No. as the program No. designated for program copy was found in the memory. • During tape input, the first character of the machining program block is the program No. address "O" or "L".
E65	PROG. No. DUPLI	△ <ul style="list-style-type: none"> • During tape input, the same No. as the specified program was found in the memory.
E66	NO PROG. NUMBER	△ <ul style="list-style-type: none"> • During tape input, the program No. was not found on the paper tape, and a program No. was not designated on the screen's data setting area. Set the program No., and input again.
E69	PROG. CHECK MODE	× <ul style="list-style-type: none"> • Search (operation search) was attempted during program check (continuous or step). • Retry search after the program check is completed, or after resetting the program search
E70	TOOL No. DUPLI	△ <ul style="list-style-type: none"> • A tool No. already registered was newly registered on the tool life management screen.
E71	TOOL ENTRY OVER	× <ul style="list-style-type: none"> • Registration of data exceeding the max. No. of registerable tools was attempted on the tool life management screen. • When inputting the tool offset data onto tape, a compensation number exceeding the specifications range was specified, and that block could not be input. If the INPUT key is pressed again in the input screen' the input will continue from the next block.
E73	CAN'T CALCULATE	× <ul style="list-style-type: none"> • The coordinate value of the hole center cannot be obtained. • Reset the measurement point, which must not applied to the following conditions. The measurement A point is the same as the Y coordinate of the C point. The measurement B is the same as the Y coordinate of the C point. The slope of the line through A and C point is the same as the slope of the line through B and C point.
E74	MENU IMPOSSIBLE	× <ul style="list-style-type: none"> • Press the operation menu "= Input" or "+ input" during the tool measurement. • Press the operation menu "= Input" or "+ input" during the manual value command mode. • Press the screen selection menu on which "↓" is displayed during the tool measurement. • Press the screen selection menu on which "↓" is displayed during the manual value command mode.

2. OPERATION MESSAGES ON SETTING AND DISPLAY UNIT
2.1 OPERATION ERRORS

Error No.	Error message	Details
E75	TLM ILL. SIGNAL	<ul style="list-style-type: none"> • The sensor signal was already ON when the tool measurement mode (TLM) signal was validated. • After the tool measurement mode (TLM) signal was validated, the sensor signal turned ON when there was no axis movement. • The sensor signal turned ON at a position within 100μm from the final entry start position. • Turn the tool measurement mode signal input OFF, or turn the sensor signal OFF and move the axis in a safe direction. <p>Note) This display will be erased when another screen is opened. The display will not be erased even if the tool measurement mode signal input is turned OFF, or if the axis is moved in a direction away from the sensor.</p>
E76	TOOL No. ERROR	<p style="text-align: center;">×</p> <ul style="list-style-type: none"> • The offset No. to be used for workpiece coordinate system offset data measurement was invalid. Restart from tool selection. (Correctly specify the R register that contains the offset number.)
E77	AXIS No. REF-RET	<p style="text-align: center;">×</p> <ul style="list-style-type: none"> • Zero point return has not been completed for the axis being measured. Return the axis to the zero point.
E78	AX UNMATCH (TLM)	<p style="text-align: center;">×</p> <ul style="list-style-type: none"> • During movement of two or more axes, the sensor turned ON and the tool length was measured. Keep off from the sensor and perform the measurement for one axis at a time.
E79	NO REF-RTN (TLM)	<p style="text-align: center;">×</p> <ul style="list-style-type: none"> • The sensor turned on for an axis that has not completed dog-type reference point return, and the tool length was measured. Return the axis to the zero point.
E80	TOP SEARCH ERR	<p style="text-align: center;">×</p> <ul style="list-style-type: none"> • The program head search (unmodal type search) was not executed before type 2 (standard specification) restart search was executed for program restart. Set the type to unmodal, search for the head of the program, and then search for the restart block with type 2.
E82	ALREADY RESEARCH	<p style="text-align: center;">×</p> <ul style="list-style-type: none"> • After completing the type 1 or type 2 search for program restart, the unmodal type, type 1 or type 2 search was attempted again. <p>If program restart is continued (if the axis is return to the restart position with automatic or manual operations), the program will restart from the block searched for first. To search again, cancel the previous search by resetting, and then search again.</p>
E84	CAN'T IN/OUT	<p style="text-align: center;">×</p> <ul style="list-style-type: none"> • An attempt was made to input a parameter in the setup parameter locked state. Refer to the manual issued by the machine manufacturer. • The parameter "#1925 EtherNet" of the high-speed program server function is set to 0. • When writing data to the IC card, the file name is illegal. (Exceeding 8 characters of file name + 3 characters of extension.) • Input of maintenance data from the host or IC card was attempted.

2. OPERATION MESSAGES ON SETTING AND DISPLAY UNIT
2.1 OPERATION ERRORS

Error No.	Error message	Details
E86	INPUT DATA ERR	<ul style="list-style-type: none"> × • When inputting the tool offset data, the data format was not correct, so that block could not be input. • If the INPUT key is pressed again in the input screen, the input will continue from the next block. • When data is read from parameter tape, its format is incorrect. • The format of file written to the NC memory is illegal.
E87	NOT EDIT PROG.	<ul style="list-style-type: none"> × • Playback edit was executed for a fixed cycle subprogram. Playback edit of a fixed cycle subprogram is not possible.
E88	CAN'T ADD BLOCK	<ul style="list-style-type: none"> × • Playback edit cannot be executed unless the block being edited with playback is displayed to the end (EOB) on the left side of the machining program display area. Press the cursor key and display the whole block to the end. Then, input the data.
E91	MODE ERROR (PBK)	<ul style="list-style-type: none"> × • G90 was set when "PB_G90" was OFF. • G91 was set when "PB_G90" was ON.
E98	CAN'T RESEARCH	<ul style="list-style-type: none"> × • When restarting the program, the type 3 restart search was attempted with a program containing no T command. Check the program. • When restarting the program, the T command corresponding to the type 3 restart search was not found in the program. Check the program. • When restarting a program for 2-systems, restart search was performed simultaneously for the 1st and 2nd systems, and then the 2nd system was searched again. If program restart is continued (if the axis is return to the restart position with automatic or manual operations), the program will restart from the block searched for first. To search again, cancel the previous search by resetting, and then search again. • When carrying our program restart, type 3 restart search was attempted while the machine was at the negative (-) side of the restart limit parameters. Manually move the machine to the positive (+) side of the restart limit parameters, and search again.
E165	AUX RUNNING	<ul style="list-style-type: none"> × • The keys other than Function/Menu/Previous page/Next page were pressed in Auxiliary monitor screen during auxiliary axis operation.
E190	FORE EDITING	<ul style="list-style-type: none"> × • An attempt was made to perform background search for the program that is in foreground search status. (Word editing)
E191	NOT COM. SEARCH	<ul style="list-style-type: none"> × • Operation search was attempted in tape mode.
E200	ADJUST ERROR	<ul style="list-style-type: none"> × • The hardware status can't be read correctly, so automatic adjustment was not possible. • Check the remote I/O unit. • A Z55 RIO NOT CONNECT occurred. • Adjust manually. • Unit defect (replace unit)

2. OPERATION MESSAGES ON SETTING AND DISPLAY UNIT
2.1 OPERATION ERRORS

Error No.	Error message		Details
E201	UNIT NOT EQUIP	×	<ul style="list-style-type: none"> • The analog output unit is not mounted. • Confirm the remote I/O unit. • Prepare a unit having analog output. • Check the connection (power and signal wires) • Unit defect (replace unit)
E301	CONNECT ERROR	×	<ul style="list-style-type: none"> • A socket connection attempt failed during Ethernet communication. • Check the host address, the setting of the port No. and that the host computer is turned ON.
E302	LOGIN ERR	×	<ul style="list-style-type: none"> • A login attempt failed during Ethernet communication. Check the user name and password. • Check the account settings, such as the home directory.
E303	TIME OUT	×	<ul style="list-style-type: none"> • Transmission of a file with Ethernet communication ended because of timeout.
E311	DOWNLOAD ERR	×	<ul style="list-style-type: none"> • An attempt to read a host file failed during Ethernet communication.
E312	UPLOAD ERR	×	<ul style="list-style-type: none"> • An attempt to write to a host file failed during Ethernet communication.
E313	NO FILE	×	<ul style="list-style-type: none"> • The file specified by host receive (host → IC) operation during Ethernet communication is not found in the host. • The file specified by host send (IC → host) operation during Ethernet communication is not found in the IC card.
E314	FILE DUPLICATE	×	<ul style="list-style-type: none"> • The file name specified to be stored by host receive (host → IC) operation during Ethernet communication already exists in the IC card. • The file name specified to be loaded by host send (IC → host) operation during Ethernet communication already exists in the host.
E315	FILE WRITE ERR	×	<ul style="list-style-type: none"> • An attempt to write to the IC card failed during Ethernet communication.
E316	FILE READ ERR	×	<ul style="list-style-type: none"> • An attempt to read a file from the IC card failed during Ethernet communication.
E317	MEMORY OVER	×	<ul style="list-style-type: none"> • IC card memory is full. • NC memory is full.
E318	OVER FLOW ERR	×	<ul style="list-style-type: none"> • A host directory contains too many files.
E319	DIRECTORY ERR	×	<ul style="list-style-type: none"> • An attempt to move a directory failed. • In the IC card device, accessing a directory in the nineteenth layer or more was attempted.
E320	HR437 UNEQU	×	<ul style="list-style-type: none"> • When backup or writing of the expansion cassette into/from the FROM, the expansion cassette (HR437) was not mounted in CBUS#1 or was incorrectly mounted. • When backup or writing of the expansion cassette into/from the FROM, a card other than the expansion cassette (HR437) was mounted in CBUS#1. • When the program memory was formatted to 1280m or more, the expansion cassette (HR437) was not mounted in CBUS#1.

2.2 OPERATOR MESSAGES

The following messages indicate the status of the setting and display functions, and are not operation errors. They are mainly used to show that operation is normal, and serve as guides for the following operations. There is no classification by numbers.

2.2.1 SEARCH AND OPERATION RELATED

Message	Message details
SEARCH EXECUTION	<ul style="list-style-type: none"> • Search is being executed normally.
SEARCH COMPLET	<ul style="list-style-type: none"> • Search was completed normally.
BUFFER EDIT	The buffer is being corrected. This appears when the cursor or a tab key is pressed and the buffer correction mode is entered. This is erased when INPUT is pressed.
CAN'T BUF. EDIT	When using 2 systems, the program being buffer corrected is being used by the other system. Buffer correcting of a machine manufacturer macro program was attempted.
DATA PROTECTING	Buffer correcting is prohibited since the data protection key 3 is valid.

2.2.2 MDI/EDITING RELATED

Message	Message details
MDI NO SETTING	<ul style="list-style-type: none"> • Only display of MDI data (no execution)
MDI SETTING COMPLETE	<ul style="list-style-type: none"> • The MDI data setting has been completed (execution is now possible).
MDI ENTRY COMPLETE	<ul style="list-style-type: none"> • The MDI data was saved in the memory with the specified program No.
MDI RUNNING	<ul style="list-style-type: none"> • The NC is operating with an MDI program, and the MDI data cannot be corrected.
PUSH KEY SERCH/PROG	<ul style="list-style-type: none"> • Status in which no programs to be edited have been called on the editing screen. To edit, press the SEARCH or PROGRAM edit key.
EDITING	<ul style="list-style-type: none"> • The details of a program are being edited on the screen. Press INPUT to write the data in the memory.
PROGRAM RUNNING	<ul style="list-style-type: none"> • A machining program to be edited is currently being run with memory operation, and cannot be edited.
DELETE? (Y/N)	<ul style="list-style-type: none"> • Waiting for a key entry (whether to delete the program) in word edit status (when the background search menu is selected)
BACK GROUND EDITING	<ul style="list-style-type: none"> • Background edit mode
EDIT POSSIBLE	<ul style="list-style-type: none"> • Editing can be performed in foreground edit mode.
EDIT IMPOSSIBLE	<ul style="list-style-type: none"> • Editing cannot be performed in foreground edit mode. • This state also occurs during feed hold or fixed cycle mode (single-block stop).
WORD SEARCH FIN	<ul style="list-style-type: none"> • The word matching the search data was searched on word editing.

2.2.3 DATA INPUT/OUTPUT RELATED

Message	Message details
DATA IN EXECUTION	<ul style="list-style-type: none"> Data is being read without error from the paper tape.
DATA WRITING IN PROGRESS	<ul style="list-style-type: none"> Data has been entered normally and the input data is being written to the ROM.
DATA IN COMPLETE	<ul style="list-style-type: none"> Data has been stored without error.
COMPARE EXECUTION	<ul style="list-style-type: none"> Comparison is being executed without error.
COMPARE COMPLETE	<ul style="list-style-type: none"> Comparison has completed without error.
DATA OUT EXECUTION	<ul style="list-style-type: none"> Data is being output without error.
DATA OUT COMPLETE	<ul style="list-style-type: none"> Data has been output without error.
ERASE EXECUTION	<ul style="list-style-type: none"> Data is being erased without error.
ERASE COMPLETE	<ul style="list-style-type: none"> Data has been erased without error.
COPY EXECUTION	<ul style="list-style-type: none"> The machining program is being copied without error.
COPY COMPLETE	<ul style="list-style-type: none"> The machining program has been copied without error.
CONDENSE EXECUTION	<ul style="list-style-type: none"> The machining program is being condensed without error.
CONDENSE COMPLETE	<ul style="list-style-type: none"> The machining program has been condensed without error.
MERGE EXECUTION	<ul style="list-style-type: none"> The machining program is being merged without error.
MERGE COMPLETE	<ul style="list-style-type: none"> The machining program has been merged without error.
No. CHANGE EXECUTION	<ul style="list-style-type: none"> The machining program No. is being changed without error.
No. CHANGE COMPLETE	<ul style="list-style-type: none"> The machining program No. has been changed without error.

2.2.4 S-ANALOG OUTPUT ADJUSTMENT RELATED

Message	Message details
ADJUST EXECUTION	<ul style="list-style-type: none"> Analog output adjustment is being executed without error.
ADJUST COMPLETE	<ul style="list-style-type: none"> Analog output adjustment has completed without error.

2.2.5 AUXILIARY AXIS

Message	Message details
CONTINUE Y/N	<ul style="list-style-type: none"> Type "Y" or "N" to specify whether to perform operation.
BACKUP EXECUTION	<ul style="list-style-type: none"> The auxiliary axis parameters are being backed up in SRAM.
BACKUP COMPLETE	<ul style="list-style-type: none"> The backup of the auxiliary axis parameters in SRAM has been completed.
AUX. WRITING EXEC.	<ul style="list-style-type: none"> The auxiliary axis parameters in SRAM is being written to MR-J2-CT.
WRITE COMPLETE	<ul style="list-style-type: none"> The writing of the auxiliary axis parameters in SRAM to MR-J2-CT has been completed.
ABS POS RESTORED	<ul style="list-style-type: none"> The absolute position in SRAM has been restored in MR-J2-CT.

2.2.6 PARAMETER BACKUP RELATED

Message	Message details
BACKUP EXEC. Y/N	Type "Y" or "N" to specify whether to perform the operation.
BACKUP EXECUTION	The parameters are being backed up.
BACKUP COMPLTE	Backup of the parameters has been completed.
RESTORE EXEC. Y/N	Type "Y" or "N" to specify whether to perform the operation.
RESTORE EXECUTION	The parameters are being restored.
RESTORE COMPLETE	Restoration of the parameters has been completed.

2. OPERATION MESSAGES ON SETTING AND DISPLAY UNIT
2.2 OPERATION MESSAGES

2.2.7 OTHERS

Message	Message details
DATA PROTECTING	<ul style="list-style-type: none"> The data protection key is valid, and the various data cannot be set or erased, etc.
BASE PARA. SET? (Y/N)	<ul style="list-style-type: none"> Waiting for the key input of standard parameter setting (Y/N).
BASE PARA EXECUTION	<ul style="list-style-type: none"> The standard parameters are being set.
EXECUTE FORMAT? (Y/N)	<ul style="list-style-type: none"> Waiting for the key input of execute format (Y/N).
FORMAT EXECUTION	<ul style="list-style-type: none"> Formatting is being executed.
SETUP COMPLETE	<ul style="list-style-type: none"> The simple setup has been completed. Setup with #1060 SETUP "1" has been completed. Formatting with #1060 SETUP "20" has been completed.
NON SETUP	<ul style="list-style-type: none"> Completed without executing simple setup. (When "N" has been set for both "BASE PARA. SET? (Y/N)" and "EXECUTE FORMAT? (Y/N)".)
CONFIRM OPE? (Y/N)	<ul style="list-style-type: none"> Confirmation for erasing operating time or alarm history.
INPUT? (Y/N)	<ul style="list-style-type: none"> Waiting for the key input of tool length data by manual measurement.
V-ANALIZER EXEC.	<ul style="list-style-type: none"> Waveform display data cannot be output while waveform is displayed.
ROM WRITE? (Y/N)	<ul style="list-style-type: none"> The system is waiting for a key input to indicate whether to write the macro programs into the FROM.
DATA WRITING	<ul style="list-style-type: none"> The macro program is being written into the FROM.
WRITE COMPLETE	<ul style="list-style-type: none"> The macro program has been written into the FROM.

3. PROGRAM ERROR

(The bold characters are the message displayed in the screen.)

These alarms occur during automatic operation, and the causes of these alarms are mainly program errors which occur, for instance, when mistakes have been made in the preparation of the machining programs or when programs which conform to the specification have not been prepared.

Error No.	Details	Remedy
P 10	EXCS. AXIS No. The number of axis addresses commanded in the same block exceeds the specifications.	<ul style="list-style-type: none"> • Divide the alarm block command into two. • Check the specifications.
P 11	AXIS ADR. ERROR The axis address commanded by the program and the axis address set by the parameter do not match.	<ul style="list-style-type: none"> • Revise the axis names in the program.
P 20	DIVISION ERROR An axis command which cannot be divided by the command unit has been issued.	<ul style="list-style-type: none"> • Check the program.
P 29	NOT ACCEPT CMND The normal line control command (G40.1, G41.1, G42.1) has been issued during the modal in which the normal line control is not acceptable.	<ul style="list-style-type: none"> • Check the program.
P 30	PARITY H The number of holes per character on the paper tape is even for EIA code and odd for ISO code.	<ul style="list-style-type: none"> • Check the paper tape. • Check the tape puncher and tape reader.
P 31	PARITY V The number of characters per block on the paper tape is odd.	<ul style="list-style-type: none"> • Make the number of characters per block on the paper tape even. • Set the parameter parity V selection OFF.
P 32	ADDRESS ERROR An address not listed in the specifications has been used.	<ul style="list-style-type: none"> • Check and revise the program address. • Check and correct the parameters values. • Check the specifications.
P 33	FORMAT ERROR The command format in the program is not correct.	<ul style="list-style-type: none"> • Check the program.

3. PROGRAM ERROR

Error No.	Details	Remedy
P 34	G-CODE ERROR A G code not listed in the specifications has been used. An illegal G code was commanded during the coordinate rotation command (G68).	<ul style="list-style-type: none"> • Check and correct the G code address in the program.
	G51.2 or G50.2 was commanded when the rotary tool axis No. (#1501 polyax) was set to "0". G51.2 or G50.2 was commanded when the tool axis was set to the linear axis (#1017 rot "0").	<ul style="list-style-type: none"> • Check the parameter setting values.
P 35	CMD-VALUE OVER The setting range for the addresses has been exceeded.	<ul style="list-style-type: none"> • Check the program.
P 36	PROGRAM END ERR "EOR" has been read during tape and memory operation.	<ul style="list-style-type: none"> • Enter the M02 and M30 command at the end of the program. • Enter the M99 command at the end of the subprogram.
P 37	PROG. NO. ZERO A zero has been specified for program and sequence numbers.	<ul style="list-style-type: none"> • The program numbers are designated across a range from 1 to 99999999. • The sequence numbers are designated across a range from 1 to 99999.
P 39	NO SPEC ERR <ul style="list-style-type: none"> • A non-specified G code was specified. • The high-speed program server operation specifications are not provided. 	<ul style="list-style-type: none"> • Check the specifications.
P 40	PREREAD BL. ERR When tool radius compensation is executed, there is an error in the pre-read block and so the interference check is disabled.	<ul style="list-style-type: none"> • Reconsider the program.
P 60	OVER CMP. LENG. The commanded movement distance is excessive. (Over 2 ³¹)	<ul style="list-style-type: none"> • Reconsider the axis address command.
P 62	F-CMD. NOTHING <ul style="list-style-type: none"> • No feed rate command has been issued. • There is no F command in the cylindrical interpolation or pole coordinate interpolation immediately after the G95 mode is commanded. 	<ul style="list-style-type: none"> • The default movement modal command at power ON is G01. This causes the machine to move without a G01 command if a movement command is issued in the program, and an alarm results. Use an F command to specify the feedrate. • Specify F with a thread lead command.
P 65	NO G05P3 SPEC	<ul style="list-style-type: none"> • Check the high-speed mode III specifications.

3. PROGRAM ERROR

Error No.	Details	Remedy
P 70	ARC ERROR <ul style="list-style-type: none"> • There is an error in the arc start and end points as well as in the arc center. • The difference of the involute curve through the start point and the end point is large. • When arc was commanded, one of the two axes configuring the arc plane was a scaling valid axis. 	<ul style="list-style-type: none"> • Check the numerical values of the addresses that specify the start and end points, arc center as well as the radius in the program. • Check the "+" and "-" directions of the address numerical values.
P 71	ARC CENTER <ul style="list-style-type: none"> • The arc center is not sought during R-specified circular interpolation. • The curvature center of the involute curve cannot be obtained. 	<ul style="list-style-type: none"> • Check the numerical values of the addresses in the program. • Check whether the start point or end point is on the inner side of the base circle for involute interpolation. When carrying out tool radius compensation, check that the start point and end point after compensation are not on the inner side of the base circle for involute interpolation. • Check whether the start point and end point are at an even distance from the center of the base circle for involute interpolation.
P 72	NO HELICAL SPEC A helical command has been issued though it is not included in the specifications.	<ul style="list-style-type: none"> • Check the helical specifications. • An Axis 3 command was issued by the circular interpolation command. If there is no helical specification, the linear axis is moved to the next block.
P 90	NO THREAD SPEC A thread cutting command has been issued though it is not included in the specifications.	<ul style="list-style-type: none"> • Check the specifications.
P 93	SCREW PITCH ERR The screw pitch has not been set correctly when the thread cutting command is issued.	<ul style="list-style-type: none"> • Issue the thread cutting command and then set the screw pitch command properly.
P100	NO CYLIND SPEC Cylindrical interpolation was commanded when the cylindrical interpolation specifications were not provided.	<ul style="list-style-type: none"> • Check the specifications.
P111	PLANE CHG (CR) Plane selection commands (G17, G18, and G19) were issued when a coordinate rotation command (G68) was issued.	<ul style="list-style-type: none"> • Before issuing the plane selection commands, issue G68 and then G69 (coordinate rotation cancel).

3. PROGRAM ERROR

Error No.	Details	Remedy
P112	<p>PLANE CHG (CC)</p> <ul style="list-style-type: none"> • A plane selection command (G17, G18, G19) has been issued when the tool radius compensation command (G41, G42) or nose R compensation command (G41, G42, G46) is issued. • The plane selection command was issued when nose R compensation is completed, there is no axial movement command after the G40 command, and the compensation has not been canceled. 	<ul style="list-style-type: none"> • Issue the plane selection command after the tool radius compensation command or nose R compensation command has been canceled (issue axial movement command after the G40 cancel command).
P113	<p>ILLEGAL PLANE</p> <p>The arc command axis is not on the selected plane.</p>	<ul style="list-style-type: none"> • Issue arc command on the correctly selected plane.
P122	<p>NO AUTO C-OVR</p> <p>An automatic corner override command (G62) has been issued though it is not included in the specifications.</p>	<ul style="list-style-type: none"> • Check the specifications. • Delete the G62 command from the program.
P130	<p>2nd AUX. ADDR</p> <p>The 2nd miscellaneous function address specified in the program does not match that set by the parameter.</p>	<ul style="list-style-type: none"> • Check and correct the 2nd miscellaneous function address in the program.
P131	<p>NO G96 SPEC</p> <p>(No constant peripheral speed) The constant peripheral speed command (G96) was issued despite the fact that such a command does not exist in the specifications.</p>	<ul style="list-style-type: none"> • Check the specifications. • Change from the constant peripheral speed command (G96) to the rotation speed command (G97).
P132	<p>SPINDLE S = 0</p> <p>No spindle speed command has been specified.</p>	<ul style="list-style-type: none"> • Reconsider the program.
P133	<p>G96 P-No. ERR</p> <p>An invalid constant peripheral speed control axis has been specified.</p>	<ul style="list-style-type: none"> • Reconsider the parameter specified for the constant peripheral speed control axis.
P134	<p>G96 Clamp Err.</p> <p>The constant surface speed control command (G96) was issued without commanding the spindle speed clamp (G92/G50).</p>	<p>Press the reset key and carry out the remedy below.</p> <ul style="list-style-type: none"> • Check the program. • Issue the G92/G50 command before the G96 command. • Command the constant surface speed cancel (G97) to switch to the rotation speed command. <p>(Applicable only to M65V series and M64 C version series)</p>
P140	<p>NO T-POS OFST</p> <p>The position compensation command (G45 to G48) specifications are not available.</p>	<ul style="list-style-type: none"> • Check the specifications.

3. PROGRAM ERROR

P141	<p>PAT-ROT ERROR Position compensation was commanded during the figure rotation or coordinate rotation command.</p>	<ul style="list-style-type: none"> • Reconsider the program.
P142	<p>T-OFFS G2 ERR A position compensation invalid arc command was commanded.</p>	<ul style="list-style-type: none"> • Reconsider the program.
P150	<p>NO R-CMP SPEC</p> <ul style="list-style-type: none"> • Even though there were no tool radius compensation specifications, tool radius compensation commands (G41 and G42) were issued. • Even though there were no nose R compensation specifications, nose R compensation commands (G41, G42, and G46) were issued. 	<ul style="list-style-type: none"> • Check the specifications.
P151	<p>G2, 3 CMP. ERR A compensation command (G40, G41, G42, G43, G44, G46) has been issued in the arc mode (G02, G03).</p>	<ul style="list-style-type: none"> • Issue the linear command (G01) or rapid traverse command (G00) in the compensation command block or cancel block. (Set the modal to linear interpolation.)
P152	<p>I.S.P NOTHING In interference block processing during execution of a tool radius compensation (G41 or G42) or nose R compensation (G41, G42, or G46) command, the intersection point after one block is skipped cannot be determined.</p>	<ul style="list-style-type: none"> • Reconsider the program.
P153	<p>I.F ERROR An interference error has arisen while the tool radius compensation command (G41, G42) or nose R compensation command (G41, G42, G46) was being executed.</p>	<ul style="list-style-type: none"> • Reconsider the program.
P155	<p>F-CYC ERR (CC) A fixed cycle command has been issued in the radius compensation mode.</p>	<ul style="list-style-type: none"> • The radius compensation mode is established when a fixed cycle command is executed and so the radius compensation cancel command (G40) should be issued.
P156	<p>BOUND DIRECT At the start of G46 nose R compensation, the compensation direction is undefined if this shift vector is used.</p>	<ul style="list-style-type: none"> • Change the vector to that with which the compensation direction is defined. • Exchange with a tool having a different tip point number.
P157	<p>SIDE REVERSED During G46 nose R compensation, the compensation direction is inverted.</p>	<ul style="list-style-type: none"> • Change the G command to that which allows inversion of the compensation direction (G00, G28, G30, G33, or G53). • Exchange with a tool having a different tip point number. • Turn ON the #8106 G46 inversion error avoidance parameter.
P158	<p>ILLEGAL TIP P. During G46 nose R compensation, the tip point is illegal (other than 1 to 8).</p>	<ul style="list-style-type: none"> • Change the tip point number to a legal one.

3. PROGRAM ERROR

Error No.	Details	Remedy												
P170	<p>NO CORR. No.</p> <p>The compensation number (DOO, TOO, HOO) command was not given when the radius compensation (G41, G42, G43, G46) command was issued. Alternatively, the compensation number is larger than the number of sets in the specifications.</p>	<ul style="list-style-type: none"> • Add the compensation number command to the compensation command block. • Check the number of compensation number sets a correct it to a compensation number command within the permitted number of compensation sets. 												
P172	<p>G10 L-No. ERR (G10 L-number error)</p> <p>The L address command is not correct when the G10 command is issued.</p>	<ul style="list-style-type: none"> • Check the address L-Number of the G10 command and correct the number. 												
P173	<p>G10 P-No. ERR (G10 compensation error)</p> <p>When the G10 command is issued, a compensation number outside the permitted number of sets in the specifications has been commanded for the compensation number command.</p>	<ul style="list-style-type: none"> • First check the number of compensation sets and then set the address P designation to within the permitted number of sets. 												
P177	<p>LIFE COUNT ACT</p> <p>Registration of tool life management data with G10 was attempted when the used data count valid signal was ON.</p>	<ul style="list-style-type: none"> • The tool life management data cannot be registered when counting the used data. Turn the used data count valid signal OFF. 												
P178	<p>LIFE DATA OVER</p> <p>The No. of registration groups, total No. of registered tools or the No. of registrations per group exceeded the specifications range.</p>	<ul style="list-style-type: none"> • Review the No. of registrations. The maximum No. of registrations is shown below. <table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th style="text-align: center;">System</th> <th style="text-align: center;">System 1</th> <th style="text-align: center;">System 2</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">No. of groups</td> <td style="text-align: center;">80</td> <td style="text-align: center;">40/40</td> </tr> <tr> <td style="text-align: center;">No. of tools</td> <td style="text-align: center;">80</td> <td style="text-align: center;">40/40</td> </tr> <tr> <td style="text-align: center;">Per group</td> <td colspan="2" style="text-align: center;">16</td> </tr> </tbody> </table>	System	System 1	System 2	No. of groups	80	40/40	No. of tools	80	40/40	Per group	16	
System	System 1	System 2												
No. of groups	80	40/40												
No. of tools	80	40/40												
Per group	16													
P179	<p>GROUP No. ILL.</p> <ul style="list-style-type: none"> • When registering the tool life management data with G10, the group No. was commanded in duplicate. • A group No. that was not registered was designated during the T□□□□99 command. • An M code command must be issued as a single command but coexists in the same block as that of another M code command. • The M code commands set in the same group exist in the same block. 	<ul style="list-style-type: none"> • The group No. cannot be commanded in duplicate. When registering the group data, register it in group units. • Correct to the correct group No. 												

3. PROGRAM ERROR

Error No.	Details	Remedy
P180	NO BORING CYC. A fixed cycle command was issued though there are not fixed cycle (G72 - G89) specifications.	<ul style="list-style-type: none"> • Check the specifications. • Correct the program.
P181	NO S-CMD (TAP) The spindle rotation speed command has not been issued when the hole drilling fixed cycle command is given.	<ul style="list-style-type: none"> • Issue the spindle rotation speed command (S) when the hole drilling fixed cycle command G84, G74 (G84, G88) is given.
P182	SYN TAP ERROR Connection to the main spindle unit was not established.	<ul style="list-style-type: none"> • Check connection to the main spindle. • Check that the main spindle encoder exists.
P183	PTC/THD, No. The pitch or thread number command has not been issued in the tap cycle of a hole drilling fixed cycle command.	<ul style="list-style-type: none"> • Specify the pitch data and the number of threads by F or E command.
P184	NO PTC/THD CMD The pitch or the number of threads per inch is illegal in the tap cycle of the hole drilling fixed cycle command.	<ul style="list-style-type: none"> • Check the pitch or the number of threads per inch.
P190	NO CUTTING CYC A lathe cutting cycle command was input although the lathe cutting cycle was undefined in the specification.	<ul style="list-style-type: none"> • Check the specification. • Delete the lathe cutting cycle command.
P191	TAPER LENG ERR In the lathe cutting cycle, the specified length of taper section is illegal.	<ul style="list-style-type: none"> • The radius set value in the lathe cycle command must be smaller than the axis shift amount.
P192	CHAMFERING ERR Chamfering in the thread cutting cycle is illegal.	<ul style="list-style-type: none"> • Set a chamfering amount not exceeding the cycle.
P200	NO MRC CYC SPC The fixed cycle for compound lathe I (G70 to G73) was commanded when the fixed cycle for compound lathe I specifications were not provided.	<ul style="list-style-type: none"> • Check the specification.
P201	PROG. ERR (MRC) <ul style="list-style-type: none"> • When called with a fixed cycle for compound lathe I command, the subprogram contained at least one of the following commands: <ul style="list-style-type: none"> • Reference point return command (G27, G28, G29, G30) • Thread cutting (G33, G34) • Fixed cycle skip-function (G31) • The first move block of the finish shape program in fixed cycle for compound lathe I contains an arc command. 	<ul style="list-style-type: none"> • Delete the following G codes from this subprogram that is called with the fixed cycle for compound lathe I commands (G70 to G73): G27, G28, G29, G30, G31, G33, G34, fixed cycle G-code. • Remove G2 and G3 from the first move block of the finish shape program in fixed cycle for compound lathe I.

3. PROGRAM ERROR

Error No.	Details	Remedy
P202	BLOCK OVR (MRC) The number of blocks in the shape program of the fixed cycle for compound lathe I is over 50 or 200 (this differs according to the model).	<ul style="list-style-type: none"> Specify 50 or a less value. The number of blocks in the shape program called by the fixed cycle for compound lathe I commands (G70 to G73) must be decreased below 50 or 200 (this differs according to the model).
P203	CONF. ERR (MRC) The fixed cycle for compound lathe I (G70 to G73) shape program could not cut the work normally because it defined an abnormal shape.	<ul style="list-style-type: none"> Check the fixed cycle for compound lathe I (G70 to G73) shape program.
P204	VALUE ERR (MRC) A command value of the fixed cycle for compound lathe (G70 to G76) is illegal.	<ul style="list-style-type: none"> Check the fixed cycle for compound lathe (G70 to G76) command value.
P210	NO PAT CYC SPC A fixed cycle for compound lathe II (G74 to G76) command was input although it was undefined in the specification.	<ul style="list-style-type: none"> Check the specification.
P220	NO SPECIAL CYC No special fixed cycle specifications are available.	<ul style="list-style-type: none"> Check the specifications.
P221	NO HOLE (S_CYC) A 0 has been specified for the number of holes in special fixed cycle mode.	<ul style="list-style-type: none"> Reconsider the program.
P222	G36 ANGLE ERR A G36 command specifies 0 for angle intervals.	<ul style="list-style-type: none"> Reconsider the program.
P223	G12 G13 R ERR The radius value specified with a G12 or G13 command is below the compensation amount.	<ul style="list-style-type: none"> Reconsider the program.
P224	NO G12, G13 SPC There are no circular cutting specifications.	<ul style="list-style-type: none"> Check the specifications.
P230	NESTING OVER <ul style="list-style-type: none"> A subprogram has been called 4 or more times in succession from the subprogram. The program in the IC card contains the M198 command. The program in the IC card has been called more than once (the program in the IC card can be called only once at a time). 	<ul style="list-style-type: none"> Check the number of subprogram calls and correct the program so that it does not exceed 4 times. When using the IC card, the IC card and the number of IC card program calls.
P231	NO N-NUMBER At subprogram call time, the sequence number set at return from the subprogram or specified by GOTO, was not set.	<ul style="list-style-type: none"> Specify the sequence numbers in the call block of the subprogram. When using an IC card, check the program and its No. in the IC card.

3. PROGRAM ERROR

Error No.	Details	Remedy
P232	NO PROGRAM No. The subprogram has not been found when the subprogram is called.	<ul style="list-style-type: none"> • Enter the subprogram. • Check the program number in the IC card.
P241	NO VARI NUMBER The variable number commanded is higher than the numbers in the specifications.	<ul style="list-style-type: none"> • Check the specifications. • Check the program variable number.
P242	EQL. SYM. MSSG. The "=" sign has not been commanded when a variable is defined.	<ul style="list-style-type: none"> • Designate the "=" sign in the variable definition of the program.
P243	VARIABLE ERR. An invalid variable has been specified in the left or right side of an operation expression.	<ul style="list-style-type: none"> • Correct the program.
P252	PAT.&COORD-ROT A coordinate rotation related command (G68, G69) was issued during figure rotation.	<ul style="list-style-type: none"> • Reconsider the program.
P260	NO COOD-RT SPC Even though there were no coordinate rotation specifications, a coordinate rotation command was issued.	<ul style="list-style-type: none"> • Check the specifications.
P270	NO MACRO SPEC A macro specification was commanded though there are no such command specifications.	<ul style="list-style-type: none"> • Check the specifications.
P271	NO MACRO INT. A macro interrupt command has been issued though it is not included in the specifications.	<ul style="list-style-type: none"> • Check the specifications.
P272	MACRO ILL. A statement and a macro statement exist together in the same block.	<ul style="list-style-type: none"> • Reconsider the program and place the executable statement and macro statement in separate blocks.
P273	MACRO OVERCALL The number of macro call nests exceeded the specifications.	<ul style="list-style-type: none"> • Reconsider the program and correct it so that the macro calls do not exceed the limit imposed by the specification.
P275	MACRO ARG. EX. The number of macro call argument type II sets has exceeded the limit.	<ul style="list-style-type: none"> • Reconsider the program.
P276	CALL CANCEL A G67 command was issued though it was not during the G66 command modal.	<ul style="list-style-type: none"> • Reconsider the program. • The G67 command is the call cancel command and so the G66 command must be designated first before it is issued.
P277	MACRO ALM MESSG An alarm command has been issued in #3000.	<ul style="list-style-type: none"> • Refer to the operator messages on the DIAG screen. • Refer to the instruction manual issued by the machine manufacturer.

3. PROGRAM ERROR

Error No.	Details	Remedy
P280	EXC. [, The number of parentheses "[" or "]" which can be commanded in a single block has exceeded five.	<ul style="list-style-type: none"> Reconsider the program and correct it so the number of "[" or "]" does not exceed five.
P281	[,] ILLEGAL The number of "[" and "]" parentheses commanded in a single block does not match.	<ul style="list-style-type: none"> Reconsider the program and correct it so that "[" and "]" parentheses are paired up properly.
P282	CALC. IMPOSS. The arithmetic formula is incorrect.	<ul style="list-style-type: none"> Reconsider the program and correct the formula.
P283	DIVIDE BY ZERO The denominator of the division is zero.	<ul style="list-style-type: none"> Reconsider the program and correct it so that the denominator for division in the formula is not zero.
P290	IF SNT. ERROR There is an error in the IF conditional GOTO□ statement.	<ul style="list-style-type: none"> Reconsider the program.
P291	WHILE SNT. ERR There is an error in the WHILE conditional DO□-END□ statement.	<ul style="list-style-type: none"> Reconsider the program.
P292	SETVN SNT. ERR There is an error in the SETVN□ statement when the variable name setting was made.	<ul style="list-style-type: none"> Reconsider the program. The number of characters in the variable name of the SETVN statement must be 7 or less.
P293	DO-END EXCESS The number of □'s for DO-END□ in the WHILE conditional DO□ - END□ statement has exceed 27.	<ul style="list-style-type: none"> Reconsider the program and correct it so that the number of 's in the DO - END statement does not exceed 27.
P294	DO-END MMC. The DO's and END's are not paired off properly.	<ul style="list-style-type: none"> Reconsider the program and correct it so that the DO's and END's are paired off properly.
P295	WHILE/GOTO TPE There is a WHILE or GOTO statement on the tape during tape operation.	<ul style="list-style-type: none"> During tape operation, a program which includes a WHILE or GOTO statement cannot be executed and so the memory operation mode is established instead.
P296	NO ADR (MACRO) A required address has not been specified in the user macro.	<ul style="list-style-type: none"> Review the program.
P297	ADR-A ERR. The user macro does not use address A as a variable.	<ul style="list-style-type: none"> Review the program.
P298	PTR OP (MACRO) User macro G200, G201, or G202 was specified during tape or MDI operation.	<ul style="list-style-type: none"> Review the program.
P300	VER. NAME ERROR The variable names have not been commanded properly.	<ul style="list-style-type: none"> Reconsider the variable names in the program and correct them.

3. PROGRAM ERROR

Error No.	Details	Remedy
P301	VAR NAME DUPLI The name of the variable has been duplicated.	<ul style="list-style-type: none"> • Correct the program so that the name is not duplicated.
P350	NO SCALING SPC The scaling command (G50, G51) was issued when the scaling specifications were not available.	<ul style="list-style-type: none"> • Check the specifications.
P360	NO PROG.MIRR. A mirror image (G50.1 or G51.1) command has been issued though the programmable mirror image specifications are not provided.	<ul style="list-style-type: none"> • Check the specifications.
P370	NO OPOS MR SPC The facing turret mirror image specifications are not provided.	<ul style="list-style-type: none"> • Check the specifications.
P371	MIRR ILLEGAL Facing turret mirror image was commanded to an axis for which external mirror image or parameter mirror image is valid. Facing turret mirror image validating mirror image for a rotary axis was commanded.	<ul style="list-style-type: none"> • Check the program. • Check the parameters.
P380	NO CORNER R/C A command was issued for corner chamfering/corner rounding though there are no such specifications.	<ul style="list-style-type: none"> • Check the specifications. • Remove the corner chamfering/corner rounding command from the program.
P381	NO ARC R/C SPC Corner chamfering/corner rounding was specified in the arc interpolation block although corner chamfering/corner rounding II is unsupported.	<ul style="list-style-type: none"> • Check the specifications.
P382	CORNER NO MOVE The block next to corner chamfering/corner rounding is not a movement command.	<ul style="list-style-type: none"> • Replace the block succeeding the corner chamfering/corner rounding command by G01 command.
P383	CORNER SHORT In the corner chamfering/corner rounding command, the movement distance was shorter than the value in the corner chamfering/corner rounding command.	<ul style="list-style-type: none"> • Make the corner chamfering/corner rounding less than the movement distance since this distance is shorter than the corner chamfering/corner rounding.
P384	CORNER SHORT When the corner chamfering/corner rounding command was input, the movement distance in the following block was shorter than the length of the corner chamfering/corner rounding.	<ul style="list-style-type: none"> • Make the corner chamfering/corner rounding less than the movement distance since this distance in the following block is shorter than the corner chamfering/corner rounding.

3. PROGRAM ERROR

Error No.	Details	Remedy
P385	G0 G33 IN CONR A block with corner chamfering/corner rounding was given during G00 or G33 modal.	<ul style="list-style-type: none"> • Recheck the program.
P390	NO GEOMETRIC A geometric command was issued though there are no geometric specifications.	<ul style="list-style-type: none"> • Check the specifications.
P391	NO GEOMETRIC 2 There are no geometric IB specifications.	<ul style="list-style-type: none"> • Check the specifications.
P392	LES AGL (GEOMT) The angular difference between the geometric line and line is 1° or less.	<ul style="list-style-type: none"> • Correct the geometric angle.
P393	INC ERR (GEOMT) The second geometric block was specified by an incremental value.	<ul style="list-style-type: none"> • Specify this block by an absolute value.
P394	NO G01 (GEOMT) The second geometric block contains no linear command.	<ul style="list-style-type: none"> • Specify the G01 command.
P395	NO ADRS (GEOMT) The geometric format is invalid.	<ul style="list-style-type: none"> • Recheck the program.
P396	PL CHG. (GEOMT) A plane switching command was executed during geometric command processing.	<ul style="list-style-type: none"> • Execute the plane switching command before geometric command processing.
P397	ARC ERR (GEOMT) In geometric IB, the circular arc end point does not contact or cross the next block start point.	<ul style="list-style-type: none"> • Recheck the geometric circular arc command and the preceding and following commands.
P398	NO GEOMETRIC 1B Although the geometric IB specifications are not included, a geometric command is given.	<ul style="list-style-type: none"> • Check the specifications.
P421	PRAM. IN ERROR <ul style="list-style-type: none"> • The specified parameter number or set data is illegal. • An illegal G command address was input in parameter input mode. • A parameter input command was input during fixed cycle modal or nose R compensation. 	<ul style="list-style-type: none"> • Check the program.
P430	AXIS NOT RET. <ul style="list-style-type: none"> • A command was issued to move an axis, which has not returned to the reference point, away from that reference point. • A command was issued to an axis removal axis. 	<ul style="list-style-type: none"> • Execute reference point return manually. • The command was issued to an axis for which axis removal is validated so invalidate axis removal.
P431	NO 2nd REF. SPC A command for second, third or fourth reference point return was issued though there are no such command specifications.	<ul style="list-style-type: none"> • Check the specifications.

3. PROGRAM ERROR

P434	<p>COLLATION ERR One of the axes did not return to the start position when the origin point collate command (G27) was executed.</p>	<ul style="list-style-type: none"> • Check the program.
P435	<p>G27/M ERROR An M command was issued simultaneously in the G27 command block.</p>	<ul style="list-style-type: none"> • An M code command cannot be issued in a G27 command block and so the G27 command and M code command must be placed in separate blocks.
P436	<p>G29/M ERROR An M command was issued simultaneously in the G29 command block.</p>	<ul style="list-style-type: none"> • An M code command cannot be issued in a G29 command block and so the G29 command and M code command must be placed in separate blocks.
P438	<p>NOT USE (G52) A local coordinate system command was issued during execution of the G54.1 command.</p>	<ul style="list-style-type: none"> • Review the program.
P450	<p>NO CHUCK BARR. The chuck barrier on command (G22) was specified although the chuck barrier was undefined in the specification.</p>	<ul style="list-style-type: none"> • Check the specification.
P460	<p>TAPE I/O ERROR An error has arisen in the tape reader or, alternatively, in the printer during macro printing.</p>	<ul style="list-style-type: none"> • Check the power and cable of the connected devices. • Check the I/O device parameters.
P461	<p>FILE I/O ERROR A file of the machining program cannot be read.</p>	<ul style="list-style-type: none"> • In memory mode, the programs stored in memory may have been destroyed. Output all of the programs and tool data once and format them. • Ensure that the external device (including a floppy disk drive and IC card) that contains the file is mounted.
P462	<p>DNC ERROR A communication error occurred during the BTR operation.</p>	<ul style="list-style-type: none"> • L01 DNC ERROR is displayed simultaneously, so remedy the problem according to the error No.
P480	<p>NO MILL SPEC</p> <ul style="list-style-type: none"> • Milling was commanded when the milling specifications were not provided. • Pole coordinate interpolation was commanded when the pole coordinate interpolation specifications were not provided. 	<ul style="list-style-type: none"> • Check the specification.

3. PROGRAM ERROR

Error No.	Details	Remedy
P481	MILL ILL. G <ul style="list-style-type: none"> • An illegal G code was used during the milling mode. • An illegal G code was used during cylindrical interpolation or pole coordinate interpolation. • The G07.1 command was issued during the tool radius compensation. 	<ul style="list-style-type: none"> • Check the program.
P482	MILL ILL. AXIS <ul style="list-style-type: none"> • A rotary axis was commanded during the milling mode. • Milling was executed even though an illegal value was set for the milling axis No. • Cylindrical interpolation or pole coordinate interpolation was commanded during mirror image. • Cylindrical interpolation or pole coordinate interpolation was commanded before the tool compensation was completed after the T command. • G07.1 was commanded when cylindrical interpolation was not possible (there is no rotary axis, or external mirror image is ON). • An axis other than a cylindrical coordinate system axis was commanded during cylindrical interpolation. 	<ul style="list-style-type: none"> • Check the machining program, parameters and PLC I/F signal.
P484	MILL AXIS RET. <ul style="list-style-type: none"> • Movement was commanded to an axis that had not completed reference point return during the milling mode. • Movement was commanded to an axis that had not completed reference point return during cylindrical interpolation or pole coordinate interpolation. 	<ul style="list-style-type: none"> • Carry out manual reference point return.

3. PROGRAM ERROR

Error No.	Details	Remedy
P485	<p>MILL ILL. MODAL</p> <ul style="list-style-type: none"> • The milling mode was turned ON during nose R compensation or constant surface speed control. • A T command was issued during the milling mode. • The mode was switched from milling to cutting during tool compensation. • Cylindrical interpolation or pole coordinate interpolation was commanded during the constant surface speed control mode (G96). • The command unacceptable in the cylindrical interpolation was issued. • A T command was issued during the cylindrical interpolation or pole coordinate interpolation mode. • A movement command was issued when the plane was not selected just before or after the G07.1 command. • A plane selection command was issued during the pole coordinate interpolation mode. • Cylindrical interpolation or pole coordinate interpolation was commanded during tool radius compensation. • The G16 plane in which the radius value of a cylinder is 0 was specified. • A cylindrical interpolation or pole coordinate interpolation command was issued during program coordinate rotation (G68). 	<ul style="list-style-type: none"> • Check the program. • Before issuing G12.1, issue G40 or G97. • Before issuing G12.1, issue a T command. • Before issuing G13.1, issue G40. • Specify the radius value of a cylinder other than 0, or specify the X axis's current value other than 0 before issuing G12.1/G16.
P486	<p>MILLING ERROR</p> <ul style="list-style-type: none"> • The milling command was issued during the mirror image (when parameter or external input is turned ON). • Pole coordinate interpolation, cylindrical interpolation or milling interpolation was commanded during facing turret mirror image. • The start command of the cylindrical interpolation or polar coordinate interpolation was issued during the normal line control. 	<ul style="list-style-type: none"> • Check the program.

3. PROGRAM ERROR

Error No.	Details	Remedy
P511	SYNC CODE ERR <ul style="list-style-type: none"> • Two or more synchronization M codes were commanded in the same block. • The synchronization M code and "!" code were commanded in the same block. 	<ul style="list-style-type: none"> • Check the program.
P600	NO AUTO TLM. An automatic tool length measurement command (G37) was execute though there are no such command specifications.	<ul style="list-style-type: none"> • Check the specifications.
P601	NO SKIP SPEC. A skip command (G31) was issued though there are no such command specifications.	<ul style="list-style-type: none"> • Check the specifications.
P602	NO MULTI SKIP A multiple skipping command (G31.1, G31.2 or G31.3) was issued though there are no such command specifications.	<ul style="list-style-type: none"> • Check the specifications.
P603	SKIP SPEED 0 The skip speed is 0.	<ul style="list-style-type: none"> • Specify the skip speed.
P604	TLM ILL. AXIS No axis or more than one axis was specified in the automatic tool length measurement block.	<ul style="list-style-type: none"> • Specify only one axis.
P605	T-CMD IN BLOCK The T code is in the same block as the automatic tool length measurement block.	<ul style="list-style-type: none"> • Specify this T code before the block.
P606	NO T-CMD BEFOR The T code was not yet specified in automatic tool length measurement.	<ul style="list-style-type: none"> • Specify this T code before the block.
P607	TLM ILL. SIGNAL Before the area specified by the D command or decelerating area parameter d, the measurement position arrival signal went ON. The signal remains OFF to the end.	<ul style="list-style-type: none"> • Check the program.
P608	SKIP ERROR (CC) A skip command was specified during radius compensation processing.	<ul style="list-style-type: none"> • Specify a radius compensation cancel (G40) command' or remove the skip command.


3. PROGRAM ERROR


Error No.	Details	Remedy
P610	ILLEGAL PARA. <ul style="list-style-type: none"> • The parameter setting is not correct. • G114.1 was commanded when the spindle synchronization with PLC I/F command was selected. • G113 was commanded when the spindle-spindle polygon machining option was OFF and the spindle synchronization with PLC I/F command was selected. 	<ul style="list-style-type: none"> • Check whether #1549 lv0vR1 to #1553 lv0vR5 are set in descending order (in order of large values). • Check whether #1554 lv0rd2 to #1557 lv0rd5 are set in descending order. • Check and correct #1514 expLinax and #1515 expRotax. • Check the program. • Check the parameter.
P612	EXP. ERROR A movement command for exponential function interpolation was issued during facing turret mirror image.	<ul style="list-style-type: none"> • Check the program.
P700	CMD-VALUE ILL. Spindle synchronization was commanded to a spindle that is not connected serially.	<ul style="list-style-type: none"> • Check the program. • Check the parameter.
P900	NO TANZ. SPEC A normal line control command (G40.1, G41.1, G42.1) was issued when the normal line control specifications were not provided.	<ul style="list-style-type: none"> • Check the specifications.
P901	TAN. AXIS G92 A coordinate system preset command (G92) was issued to a normal line control axis during normal line control.	<ul style="list-style-type: none"> • Check the program.
P902	TAN. AXIS LINE <ul style="list-style-type: none"> • The normal line control axis was set to a linear axis. • The normal line control axis was set to the linear type rotary axis II axis. • The normal line control axis has not been set. • The normal line control axis was the same as the plane selection axis. 	<ul style="list-style-type: none"> • Correct the normal line control axis.
P903	PLANE CHG (TAN) The plane selection command (G17, G18, G19) was issued during normal line control.	<ul style="list-style-type: none"> • Delete the plane selection command (G17, G18, G19) from the program for normal line control.
P990	PREPRO S/W ERR Combining commands that required pre-reading (nose R offset, corner chamfering/corner rounding, geometric I, geometric IB, and fixed cycle for compound lathe) resulted in eight or more pre-read blocks.	<ul style="list-style-type: none"> • Reduce the number of commands that require pre-reading or delete such commands.

II EXPLANATION OF PARAMETERS



1. SCREEN CONFIGURATION

1.1 SCREEN TRANSITION CHARTS

When the function selection key  is pressed, the following menu appears:
TOOL menu is displayed after the power is turned on. To display PARAM menu, use menu key on the TOOL screen.




PARAM menu
No.1 to 4



TOOL menu The contents of TOOL menu depends on the system.

1. SCREEN CONFIGURATION

1.1 SCREEN TRANSITION CHARTS

Press the menu key  to display the setup selection screen.


If the setup parameter menu opening option is specified in this screen, the setup parameters can be set up and displayed.

Parameter menu display (No.1 to 4)


Tool offset menu display (No.1 to 4)

Setup parameter menu display (No.5 to 8)

Setup parameter menu display (No.1 to 4)




Setup parameter menu
No.1 to 4




Basic specification parameter #1001 to #1024	Axis specification parameter #2001 to #2012	Servo specification parameter	Basic specification parameter of spindle #3001 to #3036
·	Axis specification parameter #2013 to #2024	Servo adjustment parameter	Spindle specification parameter
·	Zero point return parameter #2025 to #2036	Servo parameter #2201 to #2212	Spindle specification parameter
#1925 to #1936	Zero point return parameter #2037 to #2048	·	Spindle offset parameter
·	Absolute position parameter #2049 to #2060	#2261 to #2265	Spindle offset parameter
·	Axis specification parameter #2061 to #2072	·	Spindle parameter #3201 to #3212
·	Axis specification parameter #2073 to #2084	·	·
·	Axis specification parameter #2085 to #2096	·	·
·	·	·	#3573 to #3584

Setup parameter menu
No.5 to 8



Machining error correction #4000 to #4047	PLC timer #6000 to #6055	Macro list M macro #7001 to #7103	Position switch #7501 to #7574
Machining error correction #4051 to #4097	·	G macro #7201 to #7313	
Machining offset data #4101 to #4184	·	ASCII macro #7401 to #7415	
·	PLC counter #6200 to #6223		
·	PLC constant #6301 to #6348		
#5109 to #5124	#6349 to #6396		
·	Bit selection #6401 to #6460		
·	·		
·	#6581 to #6596		



2. MACHINING PARAMETERS

2.1 PROCESS PARAMETERS

<WRK COUNT> (No. of workpieces machined)

#	Item	Contents	Setup range (unit)
8001	WRK COUNT M	Set the M code that counts the No. of workpiece repeated machining. The No. will not be counted when set to 0.	0 to 99
8002	WRK COUNT	The current machining No. is displayed. Set the initial value.	0 to 999999
8003	WRK LIMIT	Set the maximum No. of workpieces machined. A signal is output to PLC when the No. of machining times is counted to this limit.	0 to 999999

<AUTO TLM> (Automatic tool length measurement)

#	Item	Contents	Setup range (unit)
8004	SPEED	Set the feedrate during automatic tool length measurement.	1 to 60000 (mm/min)
8005	ZONE r	Set the distance between the measurement position and deceleration start point.	0 to 99999.999 (mm)
8006	ZONE d	Set the tolerable zone of the measurement position. If the sensor signal turns ON in front of d before the measurement position, or if the signal does not turn ON after d is passed, an alarm will occur.	0 to 99999.999 (mm)

<AUTO CORNER OVR> (Automatic corner override)

#	Item	Contents	Setup range (unit)
8007	OVERRIDE	Set the override value for automatic corner override.	0 to 100 (%)
8008	MAX ANGLE	Set the max. corner opening angle where deceleration should start automatically. If the angle is larger than this value, deceleration will not start.	0 to 180 (°)
8009	DSC. ZONE	Set the position where deceleration starts at the corner. Designate at which length point before the corner deceleration should start.	0 to 99999.999 (mm)

<T-TIP OFFSET> (Wear data input)

#	Item	Contents	Setup range (unit)
8010	ABS. MAX. (For L system only)	Set the max. value when inputting the tool wear compensation amount. A value exceeding this setting value cannot be set.	0 to 999.999 (mm)
8011	INC. MAX. (For L system only)	Set the max. value for when inputting the tool wear compensation amount in the addition mode.	0 to 999.999 (mm)


2. MACHINING PARAMETERS
2.1 PROCESS PARAMETERS

<FIXED C.> (Fixed cycle)

#	Item	Contents	Setup range (unit)
8012	G73 n (For M system only)	Set the return amount for G73 (step cycle).	0 to 99999.999 (mm)
8013	G83 n	Set the return amount for G83 (deep hole drilling cycle).	0 to 99999.999 (mm)
8014	CDZ-VALE (For L system only)	Set the screw cut up amount for G76, G78 (thread cutting cycle).	0 to 127 (0.1 lead)
8015	CDZ-ANGLE (For L system only)	Set the screw cut up angle for G76, G78 (thread cutting cycle).	0 to 89 (°)
8016	G71 MINIMUM (For L system only)	Set the minimum cut amount for the final cutting in G71, G72 (rough cutting cycle). If the final cutting amount is smaller than this value, the final cut will not be performed.	0 to 999.999 (mm)
8017	DELTA-D (For L system only)	Set the change amount to the command cut amount D for G71, G72 (rough cutting cycle). Each cut amount will be the value obtained by adding or subtracting this value from command D, and thus, the amount can be changed each cut.	0 to 999.999 (mm)
8018	G84/G74 return (For M system only)	Set up return length m at a G84/G74 pecking tap cycle. Note: Set "0" to specify a usual tap cycle.	0 to 999.999 (mm)

2. MACHINING PARAMETERS
2.1 PROCESS PARAMETERS

<PRECISION> (High precision control)

#	Item	Contents	Setup range (unit)
8019	R COMP	<p>Set up a compensation factor for reducing a control error in the reduction of a corner roundness and arch radius.</p> <p>Indicates a maximum control error (mm) in parentheses.</p> <p>The larger the setup value, the smaller the theoretical error will be. However, since the speed at the corner goes down, the cycle time is extended.</p> <p>Coefficient = 100 - setting value</p> <p>Note: This is valid when "#8021 COMP CHANGE" is set to "0".</p>	0 to 99 (%)
8020	DCC ANGLE	<p>Set up the minimum value of an angle (external angle) that should be assumed to be a corner. When an inter-block angle (external angle) in high-precision mode is larger than the set value, it is determined as a corner and the speed goes down to sharpen the edge.</p> <div style="text-align: center;">  </div> <p>Note: If "0" is set, it will be handled as 5 degrees. The standard setting value is "0".</p>	0 to 89 (degrees) 0: The angle will be 5°.
8021	COMP CHANGE	<p>Select whether to share or separate the compensation coefficient at the corner/curve during the high-accuracy control mode.</p> <p>0: Share (#8019 R COMP)</p> <p>1: Separate</p> <ul style="list-style-type: none"> • Corner (#8022 CORNER COMP) • Curve (#8023 CURVE COMP) <p>(Note) Set "1" when using SSS control.</p>	0/1
8022	CORNER COMP	<p>Set the compensation coefficient to further reduce or increase the roundness at the corner during the high-accuracy control mode.</p> <p>Coefficient = 100 - setting value</p> <p>Note: This is valid when "#8021 COMP CHANGE" is set to "1".</p>	-1000 to 99 (%)
8023	CURVE COMP	<p>Set the compensation coefficient to further reduce or increase the radius reduction amount at the curve (arc, involute, spline) during the high-accuracy control mode.</p> <p>Coefficient = 100 - setting value</p> <p>Note: This is valid when "#8021 COMP CHANGE" is set to "1".</p>	-1000 to 99 (%)
8024	EDGE ANGLE	Not used.	-

2. MACHINING PARAMETERS
2.1 PROCESS PARAMETERS

<PRECISION> (High precision control)

#	Item	Contents	Setup range (unit)
8025	SPLINE ON (for M system only)	Specify whether to enable the spline function. 0: Disable the spline function. 1: Enable the spline function.	0/1
8026	CANCEL ANG. (for M system only)	When the angle made by blocks exceeds the set value, spline interpolation is canceled temporarily. In consideration of the pick feed, set a value a little smaller than the pick feed angle.	0 to 180° 0: 180°
8027	Toler-1 (for M system only)	Specify the maximum chord error in a block that includes an inflection point. Set the tolerance applicable when the applicable block is developed to fine segments by CAM. (normally about 10 μm) When 0.000 is set, the applicable block is linear.	At 1μm 0.000 to 100.000mm At 0.1μm 0.0000 to 10.0000mm
8028	Toler-2 (for M system only)	Specify the maximum chord error in a block that includes no inflection point. Set the tolerance applicable when the applicable block is developed to fine segments by CAM. (normally about 10 μm) When 0.000 is set, the applicable block is linear.	At 1μm 0.000 to 100.000mm At 0.1μm 0.0000 to 10.0000mm
8029	FairingL (for M system only)	Set the length of the block subject to fairing. (Valid when #8033 Fairing ON is set to 1.)	0 to 100.000mm
8030	MINUTE LENGTH (for M system only)	When the length of one block exceeds the set value, spline interpolation is canceled temporarily and linear interpolation is performed. Set a value a little smaller than linear block length of the workpiece to be machined. If - 1 is set, spline interpolation is performed regardless of block length.	-1 to 127mm 0: 1mm
8033	Fairing ON (for M system only)	Set whether to use the fairing function. 0: Fairing invalid 1: Fairing valid	0/1
8034	AccClamp ON (for M system only)	Set the method for clamping the cutting speed. 0: Clamp with parameter "#2002 clamp" or the corner deceleration function. 1: Clamp the cutting speed with acceleration judgment. (Valid when #8033 Fairing ON is set to 1.)	0/1
8035	AccClampMag	Not used.	
8036	CordecJudge (for M system only)	Change the conditions for judging a corner. 0: Judge the corner from the angle of the neighboring block. 1: Judge the corner from the angle of the neighboring block, excluding minute blocks. (Valid when #8033 Fairing ON is set to 1.)	0/1
8037	CorJudgeL (for M system only)	Set the length of the block to be excluded. (Valid when #8036 CordecJudge is set to 1.)	0 to 99999.999 (mm)

2. MACHINING PARAMETERS
2.1 PROCESS PARAMETERS

<C axis normal line>

#	Item	Contents	Setup range (unit)
8041	C-rot.R	This is valid with normal line control type II. Set the length from the center of the normal line control axis to the end of the tool. This is used to calculate the turning speed at the block joint.	0.000 to 99999.999 (mm)
8042	C-ins.R	This is valid with normal line control type I. Set the radius of the arc to be automatically inserted into the corner during normal line control.	0.000 to 99999.999 (mm)

<Fixed cycle>

#	Item	Contents	Setup range (unit)
8051	G71 THICK	Set the amount of cut-in by the rough cutting cycle (G71, G72)	0 to 99999.999 (mm)
8052	PULL UP	Set the amount of recess after cutting by the rough cutting cycle (G71, G72).	0 to 99999.999 (mm)
8053	G73 U	Set the X-axis cutting margin of the forming rough cutting cycle (G73).	-99999.999 to 99999.999 (mm)
8054	W	Set the Z-axis cutting margin of the forming rough cutting cycle (G73).	-99999.999 to 99999.999 (mm)
8055	R	Set the number of times cutting is performed by the forming rough cutting cycle (G73).	0 to 99999 (times)
8056	G74 RETRACT	Set the amount of retract (amount of cut-up) of the push-cut cycle (G74, G75).	0 to 999.999 (mm)
8057	G76 LAST-D	Set the amount of final cut-in by the composite threading cycle (G76).	0 to 999.999 (mm)
8058	TIMES	Set the number of times the amount of final cut-in (G76 finish margin) is divided in the composite threading cycle (G76).	0 to 99 (times)
8059	ANGLE	Set the angle (thread angle) of the tool nose in the composite threading cycle (G76).	0 to 99 (°)

<Three-dimensional cutter compensation>

#	Item	Contents	Setup range (unit)
8071	3-D CMP (for M system only)	Value of p in the following denominator constants for three-dimensional tool radius compensation $V_x = i \times r/p$, $V_y = j \times r/p$, $V_z = k \times r/p$ V_x, V_y, V_z : X, Y, and Z axes or vectors of horizontal axes i, j, k: Program command value r: Offset $p = \sqrt{i^2 + j^2 + k^2}$ when the set value is 0.	0 to 99999.999

2. MACHINING PARAMETERS
2.1 PROCESS PARAMETERS

< Scale factor>

#	Item	Contents	Setup range (unit)
8072	SCALING P (for M system only)	Set the scale factor for reduction or magnification for the machining program for which the G50 or G51 command is issued. This parameter is effective when the program specifies no scale factor.	0 to 99.999999

<Tool ID>

#	Item	Contents	Setup range (unit)
8073	OffsetPosition (for M system only)	Set the tool offset memory number position for writing the tool information data's tool length offset amount, tool radius compensation amount, tool length wear amount and tool radius wear amount into the tool offset data. Note: If 0 or a value exceeding the number of tool compensation sets is set, the data will not be written into the tool offset data.	0 to 999
8074	IDMacroTop (for M system only)	Set the head position when writing the tool information data's user areas 4 to 9 in the macro variables.	0 to 999

<Spiral interpolation>

#	Item	Contents	Setup range (unit)
8075	SpiralEndErr (for M system only)	Designate the tolerable error range (absolute value) when the end point position commanded with the command format type 2 spiral interpolation or conical interpolation command differs from the end point position obtained from the speed and increment/ decrement amount.	0 to 99999.999 (mm)
8076	SpiralMinRad (for M system only)	Not used.	

<Involute interpolation>

#	Item	Contents	Setup range (unit)
8077	InvoluteErr (for M system only)	Set the tolerable error value of the involute curve that passes through the start point and the involute curve that passes through the end point during involute interpolation.	0 to 99999.999 (mm)

<Screen saver>

#	Item	Contents	Setup range (unit)
8078	Screen Saver	Set the time to turn the screen OFF. The screen saver will not turn ON if 0 is set. (Note) This parameter setting is valid only for the LCD display unit.	0 to 60 (min) 0: Do not turn screen OFF.

2. MACHINING PARAMETERS
2.1 PROCESS PARAMETERS

<Deep hole drilling cycle>

#	Item	Contents	Setup range (unit)
8083	G83S modeM (for M system only)	Set the M command code for changing to the small diameter deep hole drilling cycle mode.	1 to 99999999
8084	G83S Clearanse (for M system only)	Set the clearance amount for the G83 small diameter deep hole drilling cycle.	0 to 999.999 (mm)
8085	G83S Forward F (for M system only)	Set the feedrate from the R point to the cutting start position in the G83 small diameter deep hole drilling cycle.	0 to 99999 (mm/min)
8086	G83S Back F (for M system only)	Set the speed for returning from the hole base during the G83 small diameter deep hole drilling cycle.	0 to 99999 (mm/min)

<SSS control>

#	Item	Contents	Setup range (unit)
8090	SSS ON (for M system only)	Set whether to validate SSS control with G05 P10000. 0: Invalid 1: Valid	0/1
8091	StdLength (for M system only)	Adjust the maximum value of the range for recognizing the shape. To eliminate the effect of steps or errors, etc., set a large value. To enable sufficient deceleration, set a small value. If "0.000" is set, the standard value (1.000mm) will be applied.	0 to 100.000 (mm)
8092	ClampCoeff (for M system only)	Adjust the clamp speed at the curved section configured of fine segments. Coefficient = $\sqrt{\quad}$ setting value	1 to 100
8093	StepLeng (for M system only)	Set the width of the step at which the speed is not to be decelerated. (Approximately the same as the CAM path difference [Tolerance].) If 0 is set, the standard value (5 μ m) will be applied. If a minus value is set, the speed will decelerate at all minute steps.	-0.001 to 0.100 (mm)
8094	DccWaitAdd (for M system only)	Set the time to wait for deceleration when the speed FB does not drop to the clamp speed.	0 to 100 (ms)
8095	Tolerance (for M system only)	Set the tolerable error when the error between the command path and tool path is large. The error will decrease when a small value is set, but the machining time will increase. If "0.000" is set, the error will not be adjusted.	0 to 100.000 (mm)

2.2 CONTROL PARAMETERS

#	Item	Contents	Setup range (unit)
8101	MACRO SINGLE	Select the control of the blocks where the user macro command continues. 0: Do not stop while macro block continues. 1: Stop every block during signal block operation.	0/1
8102	COLL. ALM OFF	Select the interference (bite) control to the workpiece from the tool diameter during tool radius compensation and nose R compensation. 0: An alarm is output and operation stops when an interference is judged. 1: Changes the path to avoid interference.	0/1
8103	COLL. CHK OFF	Select the interference (bite) control to the workpiece from the tool diameter during tool radius compensation and nose R compensation. 0: Performs interference check. 1: Does not perform interference check.	0/1
8105	EDIT LOCK B	Select the edit lock for program Nos. 8000 to 9999. 0: Program can be edited. 1: Editing of above program is prohibited.	0/1
8106	G46 NO REV-ERR (For L system only)	Select the control for the compensation direction reversal in G46 (nose R compensation). 0: An alarm is output and operation stops when the compensation direction is reversed (G41 → G42, G42 → G41). 1: An alarm does not occur when the compensation direction is reversed, and the current compensation direction is maintained.	0/1
8107	R COMPENSATION	0: In arc cutting mode, the machine moves to the inside because of a delay in servo response to a command, making the arc smaller than the command value. 1: In arc cutting mode, the machine compensates the movement to the inside because of a delay in servo response to a command	0/1
8108	R COMP Select	Specify whether to perform arc radius error correction over all axes or axis by axis. 0: Perform correction over all axes. 1: Perform correction over axis by axis. Note: This parameter is effective only when #8107 R COMPENSATION is 1.	0/1

2. MACHINING PARAMETERS
2.2 CONTROL PARAMETERS

#	Item	Contents	Setup range (unit)														
8109	HOST LINK	Specify whether to enable computer link B instead of the RS-232C port. 0: Disable computer link B to enable normal RS-232C communication. 1: Enable computer link B to disable normal RS-232C communication.	0/1														
8110	G71/G72 POCKET	Set the pocket machining if there is a dimple (pocket) in the rough cutting cycle (G71, G72) finishing program. 0: Pocket machining OFF 1: Pocket machining ON	0/1														
8111	Milling Radius	Select the diameter and radius of the linear axis for milling (cylindrical/pole coordinate) interpolation. 0: All axes radius command 1: Each axis setting (follows #1019 dia diameter designated axis) Note: This parameter is valid only in the milling (cylindrical/pole coordinate) interpolation mode.	0/1														
8112	DECIMAL PNT-P	0: The decimal point command for G04 address P is invalidated. 1: The decimal point command for G04 address P is validated.	0/1														
8113	MillingInitG16	Designate which plane to use for milling machining after the power is turned ON or reset. <table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th>#8113</th> <th>#8114</th> <th>Plane</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>0</td> <td>G17 plane</td> </tr> <tr> <td>0</td> <td>1</td> <td>G19 plane</td> </tr> <tr> <td>1</td> <td>0</td> <td rowspan="2">G16 plane</td> </tr> <tr> <td>1</td> <td>1</td> </tr> </tbody> </table>	#8113	#8114	Plane	0	0	G17 plane	0	1	G19 plane	1	0	G16 plane	1	1	0: Plane other than G16 1: Select G16 plane
#8113	#8114		Plane														
0	0	G17 plane															
0	1	G19 plane															
1	0	G16 plane															
1	1																
8114	MillingInitG19	Note: This parameter is valid for the G code system 2, 3 (#1037 cmdtyp=3, 4).	0: Plane other than G19 1: Select G19 plane														

2. MACHINING PARAMETERS
2.3 AXIS PARAMETERS

2.3 AXIS PARAMETERS

Set up the parameter required for each axis.

#	Item	Contents	Setup range (unit)
8201	AX. RELEASE	Select the function to remove the control axis from the control target. 0: Control as normal. 1: Remove from control target.	0/1
8202	OT-CHECK OFF	Select the stored stroke limit II function set in #8204 and #8205. 0: Stored stroke limit II valid 1: Stored stroke limit II invalid	0/1
8203	OT-CHECK-CANCEL	When the simple absolute position method (#2049 type is 9) is selected, the stored stroke limits I, II (or IIB) and IB will be invalid until the first zero point return is executed after the power is turned ON. 0: Stored stroke limit II valid (according to #8202) 1: Stored stroke limit II invalid Note: Temporary cancel of #8203 soft limit affects all the stored stroke limits.	0/1
8204	OT-CHECK-N	This sets the coordinates of the (-) direction in the moveable range of the stored stroke limit II or the lower limit coordinates of the prohibited range of stored stroke limit IIB. If the sign and value are the same as #8205, the stored stroke limit II (or IIB) will be invalid. If the stored stroke limit IIB function is selected, the prohibited range will be between two points even when #8204 and #8205 are set in reverse. When II is selected, the entire range will be prohibited.	±99999.999 (mm)
8205	OT-CHECK-P	This sets the coordinates of the (+) direction in the moveable range of the stored stroke limit II or the upper limit coordinates of the prohibited range of stored stroke limit IIB.	±99999.999 (mm)
8206	TOOL CHG. P	Set the coordinates of the tool change position for G30. n (tool change position return). Set with coordinates in the basic machine coordinate system.	±99999.999 (mm)
8207	G76/87 IGNR (For M system only)	Select the shift operation at G76 (fine boring) and G87 (back boring).	0: Shift effective 1: No shift
8208	G76/87 (-) (For M system only)	Specifies the shift direction at G76 and G87.	0: Shift to (+) direction 1: Shift to (-) direction
8209	G60 SHIFT (For M system only)	Set the last positioning direction and distance for a G60 (uni-directional positioning) command.	±99999.999 (mm)

2. MACHINING PARAMETERS
2.3 AXIS PARAMETERS

#	Item	Contents	Setup range (unit)
8210	OT INSIDE	The stored stroke limit function to be set in #8204 and #8205 prevents the machine from moving to the inside or outside of the specified range. 0: Inhibits outside area (select stored stroke limit II.) 1: Inhibits inside area (select stored stroke limit II B.)	0/1
8211	MIRR. IMAGE	Enable or disable the parameter mirror image function. 0: Disable 1: Enable	0/1

2. MACHINING PARAMETERS
2.4 BARRIER DATA

2.4 BARRIER DATA

#	Item	Contents	Setup range (unit)
8300	P0 (For L system only)	Set the reference X-coordinates of the chuck and the tail stock barrier. Set the center coordinate (Radius value) of workpiece by the basic machine coordinate system.	±99999.999 (mm)
8301 8302 8303 8304 8305 8306	P1 P2 P3 P4 P5 P6 (For L system only)	Set the area of the chuck and tail stock barrier. (Radius value) Set the coordinate value from the center of workpiece for X-axis. Set the coordinate value by basic machine coordinate system for Z-axis.	±99999.999 (mm)
8310	Barrier ON (For L system only)	Select the validity of the chuck and tailstock barrier. 0: Invalid (Setting from special display unit valid) 1: Valid	0/1
8311 8312	P7 P8 (For L system only)	Set the area of the left spindle section. • X axis: Set the coordinate value from the workpiece center (P0). (radius value) • Z axis: Set the coordinates in the basic machine coordinate system.	±99999.999 (mm)
8313 8314	P9 P10 (For L system only)	Set the area of the right spindle section. • X axis: Set the coordinate value from the workpiece center (P0). (radius value) • Z axis: Set the coordinates in the basic machine coordinate system.	±99999.999 (mm)
8315	BARRIER TYPE (L) (For L system only)	Set the shape of the left chuck and tailstock barrier. 0: No area 1: Chuck 2: Tailstock	0/1/2
8316	BARRIER TYPE (R) (For L system only)	Set the shape of the right chuck and tailstock barrier. 0: No area 1: Chuck 2: Tailstock	0/1/2

2. MACHINING PARAMETERS
2.4 BARRIER DATA

#	Item	Contents	Setup range (unit)
8317	DELIV. AX. NAME (For L system only)	When the right chuck and tailstock barrier is movable, set the name of the delivery axis. When using the 2-system method and the delivery axis is an axis in the other system, designate the system as 1A, 1B or 2A, 2B. If the system is not designated as A and B, the set system will be used.	A/B/.. (axis address) 1A/1B/.. 2A/2B/.. (system designation) 0 (cancel)
8318	STOCK ANGLE (L) (For L system only)	Set the angle for the left tailstock end section. The angle will be interpreted as 90° if there is no setting (0).	0 to 180 (°) 0: 90° default
8319	STOCK ANGLE (R) (For L system only)	Set the angle for the right tailstock end section. The angle will be interpreted as 90° if there is no setting (0).	0 to 180 (°)

2. MACHINING PARAMETERS
2.5 TOOL MEASUREMENT PARAMETERS

2.5 TOOL MEASUREMENT PARAMETERS

Set up the parameter of the tool (touch tool sensor), etc, used for measurement.

#	Item	Contents	Setup range (unit)
8701	Tool length	Set the length to the end of the touch tool.	±99999.999 (mm)
8702	Tool Dia	Set the spherical diameter of the touch tool end.	±99999.999 (mm)
8703	OFFSET X	Set the spindle center deviation amount from the touch tool center in the X axis direction.	±99999.999 (mm)
8704	Y	Set the spindle center deviation amount from the touch tool center in the Y axis direction.	±99999.999 (mm)
8705	RETURN	Set the return distance to contact the touch tool against the workpiece again.	±99999.999 (mm)
8706	FEED	Set the feedrate when contacting the touch tool against the workpiece again.	1 to 60000 (mm/min)

3. I/O PARAMETERS

Pressing the menu key  displays the I/O BASE PARAM screen.

There are basically two types of input/output parameters which must be set when inputting, outputting or referring to data, or when performing tape operation. One type is the parameters related to the input/output device. The baud rate, etc., is set according to each device. Up to five types of input/output devices can be registered. The other type of input/output parameters is the I/O base parameters which determine which device is connected to which channel per input/output application.

3.1 BASE PARAMETERS

<I/O>	#	<PORT No.>	#	<DEV. No.> <DEV. NAME>
		Specify the board No. to which the serial input/output device is connected to 2. <ul style="list-style-type: none"> • Set "1" to use ch1. • Set "2" to use ch2. 		Set the input/output device No. for each application. The device Nos. are 0 to 4 and correspond to the input/output device parameters. The device name set in the input/output device parameter is also displayed for identification.
DATA IN	9001	Specify the port for inputting the data such as machine program and parameters.	9002	Specify the No. of the device that inputs the data.
DATA OUT	9003	Specify the port for outputting the data such as machine program and parameters.	9004	Specify the No. of the device that outputs the data.
TAPE MODE	9005	Specify the input port for running with the tape mode.	9006	Specify the No. of the device to be run with the tape mode.
MACRO PRINT	9007	Specify the output port for the user macro DPRINT command.	9008	Specify the No. of the device for the DPRINT command.
PLC IN/OUT	9009	Specify the port for inputting/outputting various data with PLC.	9010	Specify the No. of the device for the PLC input/output.
REMOTE PROG IN	9011	Specify the port for inputting remote programs.	9012	Specify the number of the device used to input remote programs.
EXT UNIT	9013	Specify the port for communication with an external unit.	9014	Specify the number of the unit used for communication with an external unit

#	Item	Contents	Setup range (unit)
9015	PORT NO. (tool ID)	Set the number of the port connected with the tool ID. (Either ch1 or ch2 can be used.) <ul style="list-style-type: none"> • Set "1" to use ch1. • Set "2" to use ch2. 	1/2 (M64)
9016	DEV. NO. (tool ID)	Set the number of the input/output device to be used. (Any device No. can be used.)	0 to 4 (M64)

3. I/O PARAMETERS
3.2 I/O DEVICE PARAMETERS

3.2 I/O DEVICE PARAMETERS

Parameters for up to five types of input/output devices can be set in DEV <0> to <4>.


#	Item	Contents	Setup range (unit)
9101	DEVICE NAME	Set the device name corresponding to the device No. Set a simple name for quick identification.	Use alphabet characters, numerals and symbols to set a name within 3 characters.
9102	BAUD RATE	Set the serial communication speed.	0:19200 (bps) 1: 9600 2: 4800 3: 2400 4: 1200 5: 600 6: 300 7: 150
9103	STOP BIT	Set the stop bit length used in the start-stop system.	1: 1 (bit) 2: 1.5 3: 2
9104	PARITY CHECK	Specify whether to add the parity check bit to the data during communication.	0: Parity bit not added 1: Parity bit added
9105	EVEN PARITY	Specify the odd or even parity when it is added to the data.	0: Odd parity 1: Even parity
9106	CHR. LENGTH	Set the length of the data bit.	0: 5 (bit) 1: 6 2: 7 3: 8
9107	TERMINATOR TYPE	The code to terminate data reading can be selected.	0 and 3: EOR 1 and 2: EOB or EOR
9108	HAND SHAKE	Specify the transmission control method. The method will be no procedure if a value except 1 to 3 is set.	1: RTS/CTS method 2: No procedure (No handshaking) 3: DC code method
9109	DC CODE PARITY	Specify the DC code when the DC code method is selected.	0: No parity to DC code (DC3 = 13H) 1: DC code with parity (DC3 = 93H)
9111	DC2/DC4 OUTPUT	Specify the DC code handling when outputting data to the output device.	DC2 / DC4 0: None / None 1: Yes / None 2: None / Yes 3: Yes / Yes
9112	CR OUTPUT	Specify whether to insert the <CR> code just before the EOB (L/F) code during output.	0: Do not add 1: Add

3. I/O PARAMETERS
3.2 I/O DEVICE PARAMETERS

#	Item	Contents	Setup range (unit)
9113	EIA OUTPUT	In data output mode, select the ISO or EIA code for data output. In data input mode, the ISO and EIA codes are identified automatically.	0: ISO code output 1: EIA code output
9114	FEED CHR.	Specify the length of the tape feed to be output at the start and end of the data during tape output.	0 to 999 (characters)
9115	PARITY V	Specify whether to check the parity of the No. of characters in block during data input. The No. of characters is factory-set so that the check is valid at all times.	0: Do not perform parity V check 1: Perform parity V check
9116	TIME-OUT	Set the time out time to detect an interruption in communication. Time out check will not be executed when set to 0 to 30 seconds.	0 to 30 (s)
9117	DR OFF	Specify whether to check the DR data at the data input/output.	0: DR valid 1: DR invalid
9118	DATA ASC II	0: Output in ISO/EIA code (Depends on whether #9113, #9213, #9313, #9413, or #9513 EIA output parameter is set up) 1: Output in ASC II code	0/1
9119	INPUT FORM	Specify the mode for input (collation). 0: Standard input (Data from the very first EOB is handled as significant information.) 1: EOBs following the first EOB of the input data are skipped until data other than EOB is input.	0/1
9121 9122 9123 9124 9125 9126 9127 9128	EIA CODE [] # * = : \$!	When output with EIA code, data can be output using the alternate code in which the special ISO code not included in EIA is specified. Specify the codes which do not duplicate the existing EIA codes by hexadecimal for respective special codes.	0 to FF (hexadecimal)

9201 ~	Set the same settings for device 1.	
9301 ~	Set the same settings for device 2.	
9401 ~	Set the same settings for device 3.	
9501 ~	Set the same settings for device 4.	

3.3 COMPUTER LINK PARAMETERS

#	Item	Contents	Setup range (unit)
9601	BAUD RATE	Specify the rate at which data is transferred.	0:19200 (bps) 1: 9600 2: 4800 3: 2400 4: 1200 5: 600 6: 300 7: 110 8: 38400
9602	STOP BIT	Specify stop bit length used in start-stop mode. See "PARITY EFFECTIVE" in #9603. The number of characters is adjusted in output mode so that no problems occur if the parity check is enabled.	1: 1 2: 1.5 3: 2
9603	PARITY EFFECTIVE	<p>This parameter is set when using a parity bit separately from the data bit.</p>  <p>Set this to match the input/output device specifications.</p>	0: No parity bit used in I/O mode 1: Parity bit used in I/O mode
9604	EVEN PARITY	Specify whether even or odd parity is used when parity is used. This parameter is ignored when no parity is used.	0: Odd parity 1: Even parity
9605	CHR. LENGTH	Specify data bit length. See "PARITY EFFECTIVE" in #9603.	2: 7 3: 8
9606	HAND SHAKE	RS-232C transmission control mode DC control mode should be set for computer line B.	0: No control 1: RTS/CTS method 2: No handshaking 3: DC control mode
9607	TIME-OUT SET	Specify time-out time at which an interruption of data transfer during data input/output should be detected. If 0 is set, time infinity is specified.	0 to 999 (1/10s)
9608	DATA CODE	Specify the code to be used. See "PARITY EFFECTIVE" in #9603.	0: ASCII code 1: ISO code

3. I/O PARAMETERS
3.3 COMPUTER LINK PARAMETERS


#	Item	Contents	Setup range (unit)
9609	LINK PARAM. 1	<p>Bit 1: DC1 output after NAK or SYN Specify whether to output the DC1 code after the NAK or SYN code is output.</p> <p>Bit 7: Enable/disable resetting Specify whether to enable resetting in the computer link.</p>	<p>0: Don't output the DC1 code. 1: Output the DC1 code.</p> <p>0: Enable resetting in the computer link. 1: Disable resetting in the computer link</p>
9610	LINK PARAM. 2	<p>Bit 2: Specify the control code parity (even parity for the control code). Set the parity in accordance with the I/O device specifications.</p> <p>Bit 3: Parity V Specify whether to enable checking of parity V in one block in data input mode.</p>	<p>0: No control code parity added 1: Control code parity added</p> <p>0: Disable 1: Enable</p>
9611	LINK PARAM. 3	Not used	
9612	LINK PARAM.4	Not used	
9613	LINK PARAM.5	Not used	
9614	START CODE	<p>Specify the code by which file data transfer begins at first. This parameter is used for a specific user, and set 0 in this parameter for normal operation.</p>	<p>0: DC1 (11H) 1: BEL (07H)</p>
9615	CTRL. CODE OUT	<p>Bit 0: NAK output Specify whether to send the NAK code to the host if a communication error occurs in computer link B.</p> <p>Bit 1: SYN output Specify whether to send the SYN code to the host if NC resetting or an emergency stop occurs in computer link B.</p> <p>Bit 3: DC3 output Specify whether to send the DC3 code to the host when communication ends in computer link B.</p>	<p>0: Do not output the NAK code. 1: Output the NAK code.</p> <p>0: Do not output the SYN code. 1: Output the SYN code.</p> <p>0: Do not output the DC3 code. 1: Output the DC3 code.</p>
9616	CTRL. INTERVAL	Not used	
9617	WAIT TIME	Not used	
9618	PACKET LENGTH	Not used	
9619	BUFFER SIZE	Not used	
9620	START SIZE	Not used	
9621	DC1 OUT SIZE	Not used	
9622	POLLING TIMER	Not used	
9623	TRANS. WAIT TMR	Not used	
9624	RETRY COUNTER	Not used	

4. SETUP PARAMETERS

Pressing the menu key  displays the OPEN SETUP PARAM screen.

The system's basic parameters are normally hidden as setup parameters to prevent mistaken operations and to simplify the display.

The setup parameters can be displayed and set by making a declaration to open the setup parameters on this screen.



- 1) Select the setup parameter.
Key-in "Y" in # (), and then press INPUT.
The basic specification parameter screen appears and the normally hidden setup parameter menu will display.
The required menu can be selected to display and set the setup parameters.
- 2) Cancel the setup parameter selection.
Key-in "N" in # (), and then press INPUT.
The setup parameter menu will disappear.
Note: The setup parameters are not displayed when the power is turned ON.

(Note 1) Refer to "5. Base Specifications Parameters" to "13. Position Switch" for details on the setup parameters.

(Note 2) Be sure to turn OFF the power supply after selecting the setup parameter.

(Note 3) If a key other than the screen changeover key is pressed when the setup parameters are locked, the message "Data Protected" will appear.

5. BASE SPECIFICATIONS PARAMETERS

After setting up the parameter (PR) listed in the table, turn OFF the NC power. To validate the parameter, turn ON the power again.

(SETUP PARAM 1. 1/15)

#	Items	Details	Setting range (unit)												
1001 (PR)	SYS_ON System validation setup	Specify the existence of the 1st system, 2nd system and PLC axis with 1 or 0.	0: Not used 1: Used												
1002 (PR)	axisno Number of axes	Set No. of axes in each system and the No. of PLC axes. Specify 6 as the maximum value for each system and 4 as that for the PLC axis so that the total of those values is 6 or less.	0 to 6												
1003 (PR)	iunit Input setup unit	Specify the input setting value for each system and the PLC axis. The parameter units will follow this specification.	B: 1 μm C: 0.1 μm D: 0.01 μm												
1013	axname Axis name	Specify each axis' name address with an alphabetic character. Use the characters X, Y, Z, U, V, W, A, B or C. Do not specify the same address in one system. The same address can be specified for the 1st and 2nd system. The PLC address does not need to be set. (The axis name is displayed as 1 and 2.)	Axis addresses such as X, Y, Z, U, V, W, A, B, and C												
1014	incax Increment command axis name	When specifying the program movement rate's absolute or incremental method with an address, specify the incremental command axis name address with an alphabetic character. The address that can be used is the same as #1013 axname. Specify an address that is different from that #1013. Setting is not required if absolute/incremental specification with addresses is not performed (#1076 AbsInc = 0).													
1015 (PR)	cunit Command unit	Specify the minimum unit of the program movement amount. cunit Movement amount for movement command 1 0: Follow #1003 iunit 1: 0.0001 mm (0.1 μm) 10: 0.001 mm (1 μm) 100: 0.01 mm (10 μm) 1000: 0.1 mm (100 μm) 10000: 1.0 mm If there is a decimal point in the movement command, the decimal point position will be handled as 1mm regardless of this setting.	<table border="1"> <tr> <td>0</td> <td>#1003 iunit</td> </tr> <tr> <td>1</td> <td>0.1 μm</td> </tr> <tr> <td>10</td> <td>1 μm</td> </tr> <tr> <td>100</td> <td>10 μm</td> </tr> <tr> <td>1000</td> <td>100 μm</td> </tr> <tr> <td>10000</td> <td>1 mm</td> </tr> </table>	0	#1003 iunit	1	0.1 μm	10	1 μm	100	10 μm	1000	100 μm	10000	1 mm
0	#1003 iunit														
1	0.1 μm														
10	1 μm														
100	10 μm														
1000	100 μm														
10000	1 mm														

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1016 (PR)	iout Inch output	Specify whether the machine system (ball screw pitch, position detection unit) is an inch unit system or metric unit system.	0: Metric unit system 1: Inch unit system
1017 (PR)	rot Rotational axis	Specify whether the axis is a rotary axis or linear axis. For the rotary axis, the position display will be 360°, and the axis will return to 0°. If the position display is to be continuously displayed even with the rotary axis, set the axis as a linear axis	0: Linear axis 1: Rotary axis
1018 (PR)	ccw Motor CCW	Specify the direction of the motor rotation to the command direction. 0: Rotates clockwise (looking from motor shaft) with the forward rotation command. 1: Rotates counterclockwise (looking from motor shaft) with the forward rotation command.	0: Rotates clockwise 1: Rotates counterclockwise
1019 (PR)	dia Diameter specification axis	Specify whether the program movement amount is to be commanded with the diameter dimension or as movement amount. When the movement amount is commanded with the diameter dimensions, 5mm will be moved when the command is a movement distance of 10mm. The movement amount per pulse will also be halved during manual pulse feed. Among parameters concerning length, the tool length, the wear compensation amount and the workpiece coordinate offset are displayed in diameter value when diameter is specified, but other parameters are always displayed in radius value.	0: Command with movement amount 1: Command with diameter dimension
1020 (PR)	sp_ax Spindle Interpolation	Specify 1 when the NC control axis is used as the spindle.	0: The NC control axis is used as the servo axis. 1: The NC control axis is used as the spindle.
1021 (PR)	mcp_no Amplifier I/F channel No. (servo)	Using a 4-digit number, set the amplifier interface channel No. and which axis in that channel is to be used when connecting an axis amplifier. High-order two digits : Amplifier interface channel No. Low-order two digits : Axis No. When using the conventional fixed layout, set all axes to "0000".	0000 0101 to 0107 0201 to 0207
1022 (PR)	axname 2 2nd axis name	Set the name of the axis displayed on the screen with two characters. (X1, Z2, etc.)	Two digits between A to Z and 1 to 9 (Setting is cleared when 0 is set)

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1023 (PR)	crsadr Command address during cross machining	Set the address for issuing a command to this axis during cross machining control.	A to Z (Setting is cleared when 0 is set)
1024 (PR)	crsinc Incremental command address during cross machining	Set the address for issuing an incremental command to this axis during cross machining control.	A to Z (Setting is cleared when 0 is set)

(SETUP PARAM 1. 2/15)

#	Items	Details	Setting range (unit)
1025	I_plane Initial plane selection	Specify the plane to be selected when the power is turned ON or reset. When 0 is specified, 1 is assumed (X-Y plane).	1: X-Y plane (G17 command state) 2: Z-X plane (G18 command state) 3: Y-Z plane (G19 command state)
1026 1027 1028	base_I Base axis I base_J Base axis J base_K Base axis K	Specify the basic axis address that composes the plane. Specify the axis address set in #1013 axname. If all three items do not need to be specified, such as for 2-axis specifications, input "0", and the parameter will be blank. Normally, when X, Y and Z are specified respectively for base_I,_J,_K, the following relation will be established: G17: X-Y G18: Z-X G19: Y-Z Specify the desired address to set an axis address other than the above.	Control axis addresses such as X, Y, and Z
1029	aux_I Flat axis I	If there is an axis parallel to #1026 base_I, specify that axis address.	Control axis addresses such as X, Y, and Z
1030	aux_J Flat axis J	If there is an axis parallel to #1027 base_J, specify that axis address.	Control axis addresses such as X, Y, and Z
1031	aux_K Flat axis K	If there is an axis parallel to #1028 base_K, specify that axis address.	Control axis addresses such as X, Y, and Z

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)																											
1037	cmdtyp Command type	<p>Specify the program G code series and compensation type.</p> <table border="1"> <thead> <tr> <th>cmdtyp</th> <th>G code series</th> <th>Compensation type</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>System 1 (for M)</td> <td>Type A (one compensation amount for one compensation number)</td> </tr> <tr> <td>2</td> <td>System 2 (for M)</td> <td>Type B (shape and wear amounts for one compensation number)</td> </tr> <tr> <td>3</td> <td>System 2 (for L)</td> <td>Type C (two kinds of compensation amount of shape and wear per compensation No.)</td> </tr> <tr> <td>4</td> <td>System 3 (for L)</td> <td>Same as above</td> </tr> <tr> <td>5</td> <td>System 4 (for special L)</td> <td>Same as above</td> </tr> <tr> <td>6</td> <td>System 5 (for special L)</td> <td>Same as above</td> </tr> <tr> <td>7</td> <td>System 6 (for special L)</td> <td>Same as above</td> </tr> <tr> <td>8</td> <td>System 7 (for special L)</td> <td>Same as above</td> </tr> </tbody> </table> <p>There are some items in the specifications that can be used or cannot be used according to the value set in this parameter. The file structure may also change depending on the compensation data type. Thus, after changing this parameter, initialize the system with #1060 SETUP.</p>	cmdtyp	G code series	Compensation type	1	System 1 (for M)	Type A (one compensation amount for one compensation number)	2	System 2 (for M)	Type B (shape and wear amounts for one compensation number)	3	System 2 (for L)	Type C (two kinds of compensation amount of shape and wear per compensation No.)	4	System 3 (for L)	Same as above	5	System 4 (for special L)	Same as above	6	System 5 (for special L)	Same as above	7	System 6 (for special L)	Same as above	8	System 7 (for special L)	Same as above	1 to 8
cmdtyp	G code series	Compensation type																												
1	System 1 (for M)	Type A (one compensation amount for one compensation number)																												
2	System 2 (for M)	Type B (shape and wear amounts for one compensation number)																												
3	System 2 (for L)	Type C (two kinds of compensation amount of shape and wear per compensation No.)																												
4	System 3 (for L)	Same as above																												
5	System 4 (for special L)	Same as above																												
6	System 5 (for special L)	Same as above																												
7	System 6 (for special L)	Same as above																												
8	System 7 (for special L)	Same as above																												
1038	plcsel Ladder selection	Specify the PLC type.	0: User custom PLC 1: Standard PLC 2: Exclusive PLC for MELSEC bus link																											
1039	spinno Number of spindles	Specify the existence of a spindle.	0: No spindle 1: One spindle 2: Two spindles 3: Three spindles 4: Four spindles																											
1040 (PR)	M_inch Constant input (inch)	Specify the parameter unit system for the position and length.	0: Metric system 1: Inch system																											
1041 (PR)	I_inch Initial state (inch)	Specify the unit system for the program movement amount when the power is turned ON or reset and for position display. Designate an internal unit.	0: Metric system 1: Inch system																											
1042 (PR)	pcinch PLC axis command (inch)	Specify the unit system for the commands to the PLC axis.	0: Metric system 1: Inch system																											

5. BASE SPECIFICATIONS PARAMETERS

#	Items		Details	Setting range (unit)
1043	lang	Select language displayed	<p>Specify the display language.</p> <p>0: Japanese display (Standard) 1: English display (Standard) 2: Third language displayed (Note) (Option) 3: Fourth language displayed (Note) (Option)</p> <p>11: Display in German (Option) 12: Display in French (Option) 13: Display in Italian (Option) 14: Display in Spanish (Option) 15: Display in Chinese (traditional Chinese) (Option) 16: Display in Korean (Option) 17: Display in Portuguese (Option) 18: Display in Dutch (Option) 19: Display in Swedish (Option) 20: Display in Hungarian (Option) 22: Display in Chinese (simplified Chinese) (Option)</p> <p>Note: If no character package is available for a specified language, the screen is displayed in English.</p>	0 to 3 11 to 22
1044 (PR)	auxno	MR-J2-CT Connections	Specify the number of MR-J2-CTs connected.	0 to 4
1045 (PR)	nskno	Megatorque motor connections	Specify the number of NSK megatorque motors connected. When a value other than 0 is specified, 2nd miscellaneous function data is output as signed binary data.	0 to 16
1049 (PR)	mmac_R	Machine maker macro RAM-ROM changeover	<p>Select the memory area for the machine manufacturer macro program.</p> <p>0: SRAM area 1: FROM area</p> <p>When this parameter is changed, the power must be turned OFF and ON, and the area must be formatted.</p> <p>Note: "1" cannot be set if the machine manufacturer macro option is not valid.</p>	0/1

Note: Selection of inch and metric unit

When set value of #1041 I_inch is changed, the unit of length is changed after reset.

Among parameters concerning length, following items are not changed automatically, therefore change the set values to agree with the new unit system when the unit system is changed.

5. BASE SPECIFICATIONS PARAMETERS

Tool compensation amount (Tool length compensation amount, tool wear compensation amount and tool tip compensation amount)			
Workpiece coordinate offset			
Machining parameter	#8004 SPEED	#8027 Toler-1	#8056 G74 RETRACT
	#8005 ZONE r	#8028 Toler-2	#8057 G76 LAST-D
	#8006 ZONE d	#8029 FairingL	#8075 SpiralEndErr
	#8009 DSC. ZONE	#8030 MINUTE LENG S	#8077 InvoluteErr
	#8010 ABS. MAX.	#8037 CorJudgeL	
	#8011 INC. MAX.	#8041 C-rot. R	#8084 G83S
	#8012 G73n	#8042 C-ins. R	Clearanse
	#8013 G83n	#8051 G71 THICK	#8085 G83S Forward F
	#8016 G71 MINIMUM	#8052 PULL UP	#8086 G83S Back F
	#8017 G71 DELTA-D	#8053 G73U	
	#8018 G84/G74n	#8054 W	
	Axis parameter	#8204 OT-CHECK-N	
#8205 OT-CHECK-P			
#8206 TOOL CHG.P			
#8209 G60 Shift			
Barrier data	#8300 - #8306, #8311 - #8314		
Basic specification parameter	#1084 RadErr		

#8004 SPEED is 10 inches/min. unit for the inch system.

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)															
1050 (PR)	MemPrg Definition of program save area	<table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th style="text-align: center;">Setting</th> <th style="text-align: center;">0</th> <th style="text-align: center;">1</th> <th style="text-align: center;">2</th> <th style="text-align: center;">3</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">Machining program</td> <td style="text-align: center;">○</td> <td style="text-align: center;">△</td> <td style="text-align: center;">○</td> <td style="text-align: center;">△</td> </tr> <tr> <td style="text-align: center;">MDI data</td> <td style="text-align: center;">○</td> <td style="text-align: center;">○</td> <td style="text-align: center;">△</td> <td style="text-align: center;">△</td> </tr> </tbody> </table> <p>(Machining program) ○: System common Machining program save area is shared by systems. △: System independent Machining programs can be registered for each system.</p> <p>(MDI data) ○: System common MDI data is shared by systems. △: System independent MDI data can be set for each system.</p> <p>When this parameter is changed, the power must be turned OFF and ON, and the system formatted. (Note) This parameter is valid when #1001 SYS_ON[2] is 1.</p>	Setting	0	1	2	3	Machining program	○	△	○	△	MDI data	○	○	△	△	0 to 3
Setting	0	1	2	3														
Machining program	○	△	○	△														
MDI data	○	○	△	△														
1051 (PR)	MemTol Tool compensation memory common for systems	<p>0: Tool compensation memory separate for systems 1: Tool compensation memory common for systems</p>	0/1															
1052 (PR)	MemVal No. of common variables shared in system designation	<p>0: Common variables common for system (number fixed) #100 to : Per system #500 to : Common for systems 1: Common variables common for system (number fixed) #100 to : Designate with V1comN #500 to : Designate with V0comN</p> <p>* When this parameter is changed, the method of reading the file system will change after the power is turned ON, so always reformat again. Setting order</p> <div style="text-align: center;"> <pre> graph LR A[MemVal change-over] --> B[Format Mismatch displays] B --> C[Format] C --> D[Turn power ON again] </pre> </div>	0/1															

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1060	SETUP Activate setup processing	<p>Execute the functions required for initializing the system.</p> <p>1: Execute one-touch setup</p> <pre> graph TD Start["#(1060) Data(1)()"] --> Input1[INPUT] Input1 --> Prompt1[""BASE PARA. SET? (Y/N)" is displayed."] Prompt1 --> Y1["Y"] Prompt1 --> N1["N"] Y1 --> Desc1["To initialize the parameters."] N1 --> Desc2["To retain the current parameters."] Desc1 --> Input2[INPUT] Desc2 --> Input2 Input2 --> Prompt2[""FORMAT?(Y/N)" is displayed."] Prompt2 --> Y2["Y"] Prompt2 --> N2["N"] Y2 --> Desc3["To initialize the machining program file and tool offset file."] N2 --> Desc4["To retain the current machining program file and tool offset file."] Desc3 --> Input3[INPUT] Desc4 --> Input3 Input3 --> End[""SETUP COMPLETE" is displayed."] </pre> <p>The parameters are initialized according to the setting values in #1001 to #1043.</p> <p>The above files are initialized and the standard canned cycle program is input.</p> <p>Note: Most setup parameters will be initialized with one-touch setup, so confirm the data before executing.</p> <p>This parameter will automatically be set to 0 when the power is turned ON.</p>	1

5. BASE SPECIFICATIONS PARAMETERS

(SETUP PARAM 1. 3/15)

#	Items		Details	Setting range (unit)															
1061 (PR)	intabs	Manual ABS updating	Defines whether to update the absolute value data during automatic handle interrupt. This parameter is valid only when #1145 I_abs is set to 1.	0: Do not update (shift coordinates the amount of the interruption) 1: Update (same coordinates as when interrupt did not occur will be applied.)															
1062	T_cmp	Tool offset function	Specify whether the tool length offset and wear compensation is valid during T command execution. <table border="1"> <thead> <tr> <th>Setting value</th> <th>Tool length offset</th> <th>Wear compensation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>Valid</td> <td>Valid</td> </tr> <tr> <td>1</td> <td>Valid</td> <td>Invalid</td> </tr> <tr> <td>2</td> <td>Invalid</td> <td>Valid</td> </tr> <tr> <td>3</td> <td>Invalid</td> <td>Invalid</td> </tr> </tbody> </table>	Setting value	Tool length offset	Wear compensation	0	Valid	Valid	1	Valid	Invalid	2	Invalid	Valid	3	Invalid	Invalid	0 to 3
Setting value	Tool length offset	Wear compensation																	
0	Valid	Valid																	
1	Valid	Invalid																	
2	Invalid	Valid																	
3	Invalid	Invalid																	
1063	mandog	Manual dog-type	The initial return to the reference point is performed with dog-type return after the power is turned ON, and the coordinate system is established. Specify the manual reference point return method after the coordinate system is established with this parameter. (This setting is not required when using absolute position detection.)	0: High speed return 1: Dog-type															
1064 (PR)	svof	Error correction	Specify whether to correct the error when the servo is OFF.	0: Do not correct the error 1: Correct the error															

5. BASE SPECIFICATIONS PARAMETERS

#	Items		Details	Setting range (unit)
1065	JOG_H	JOG response type	<p>Set up an improved JOG response type.</p> <p>0: Conventional specification The system is started and stopped by signal via ladder without reference to external input signals.</p> <p>1: Type 1 The system is started up and stopped by external signal.</p> <p>2: Type 2 The system is started up and stopped by performing the AND operation for external signals and those via ladder.</p> <p>3: Type 3 The system is started up when signals via ladder rise. It is stopped when external signals and those via ladder fall.</p> <p>4: Type 4 Zero point return mode: The system is started up and stopped by signal via ladder without reference to external input signals (conventional specification). Non-zero point return mode: The system is started up and stopped by performing AND for external signals and those via ladder (type 2).</p>	0 to 4
1066	JOG_HP	Select JOG activation (+) device	Specify the number of the device that inputs +JOG activation signals. The device type is specified by JOG_D in #1071. The effective range of set values vary depending on the device type. A value outside of the effective range is invalid if specified.	<p>X: 0000 to 013F (hexadecimal)</p> <p>G: 0000 to 3071</p> <p>M: 0000 to 5119 (decimal)</p>
1067	JOG_HN	Select JOG activation (-) device	Specify the number of the device that inputs -JOG activation signals. The device type is specified by JOG_D in #1071. The effective range of set values vary depending on the device type. A value outside of the effective range is invalid if specified.	<p>X: 0000 to 013F (hexadecimal)</p> <p>G: 0000 to 3071</p> <p>M: 0000 to 5119 (decimal)</p>
1068 (PR)	slavno	Slave axis number	Specify the number of the slave axis for synchronous control. The axis number is an NC number excluding the spindle and PLC axis. Two or more slave axes cannot be set up for one master axis. slavno cannot be set up for a slave axis. A dual system cannot be set up so that the relationship between the master and slave axes extends over a system.	<p>0: No slave axis</p> <p>1 to 4: First to fourth axes</p> <p>1 to 14: 1st axis to 14th axis (For simple C axis synchronous control)</p>

5. BASE SPECIFICATIONS PARAMETERS

#	Items		Details	Setting range (unit)
1069 (PR)	no_dsp	Axis with no counter display	Set up an axis that displays no counter. This option is valid on the counter display screen (relative value screen).	0: Displays the counter 1: Does not display the counter.
1070	axoff	Axis removal	Define an axis that enables axis removal control.	0: Disables axis removal. 1: Enables axis removal
1071 (PR)	JOG_D	±JOG activation signal device name	Specify the number of the device that inputs ±JOG activation signals. 0: X device 1: G device 2: M device Set the JOG_HP (#1066) and JOG_HN (#1067) parameters according to this device specification parameter.	0 to 2
1072	chop_ax	Chopping axis	Designate the chopping axis.	0: Non-chopping axis 1: Chopping axis

5. BASE SPECIFICATIONS PARAMETERS

(SETUP PARAM 1. 4/15)

#	Items	Details	Setting range (unit)
1073	I_Absm Initial absolute value	Specify the absolute value/incremental value mode for when the power is turned ON or reset. 0: Incremental value command mode 1: Absolute value command mode	0: Incremental value command mode 1: Absolute value command mode
1074	I_Sync Initial synchronous feed	Specify the feedrate specification mode for when the power is turned ON or reset. 0: Asynchronous feed (feed per minute) 1: Synchronous feed (feed per rotation)	0: Asynchronous feed 1: Synchronous feed
1075	I_G00 Initial G00	Specify the linear command mode for when the power is turned ON or reset. 0: Linear interpolation (G01 command state) 1: Positioning (G00 command state)	0: Linear interpolation 1: Positioning
1076	AbsInc (For L system only) ABS/INC address	The absolute value/incremental commands can be issued by using the absolute value address and incremental value address for the same axis. 0: Absolute/incremental with G command 1: Absolute/incremental with address code (The #1013 axname address will be the absolute value command, and #1014 incax address will be the incremental value command)	0: Absolute/incremental with G command 1: Absolute/incremental with address code
1077	radius Incremental command for diameter specification axis	Specify if the diameter specification axis' (#1019 dia is set to 1) incremental value command uses the diameter value or radius value	0: Diameter value 1: Radius value
1078	Decpt2 Decimal point type 2	Specify the unit of position commands that do not have a decimal point. 0: The min. input command unit is used (follows #1015 cunit) 1: 1mm (or 1inch) unit is used (For the dwell time, 1s unit is used.)	0: The min. input command unit is used 1: 1mm (or 1inch) unit is used
1079	F1digit Validate F1 digit	Specify whether to execute the F command with a 1-digit code command or with a direct numerical command. 0: Direct numerical command (command feedrate during feed per minute or rotation) 1: 1-digit code command (feedrate specified with #1185 spd_F1 - #1189 F5)	0: Direct numerical command 1: 1-digit code command
1080	Dril_Z (For D system only) Specify boring axis	Specify a fixed cycle hole drilling axis. 0: Use an axis vertical to the selected plane as the hole drilling axis. 1: Use the Z axis as the hole drilling axis regardless of the selected plane.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items		Details	Setting range (unit)
1081	Gmac_P	Give priority to G code parameter	Specify the G code priority relationship during the macro call with the G command. 0: G code used in system is priority. 1: Registered G code for call out is priority.	0/1
1082	Geomet (For L system only)	Geometric	Specify whether to use the geometric I or IB function. 0: Do not use. 1: Use only geometric I. 2: Use geometric I and IB. With geometric, specific address codes are used for exclusive meanings. Thus, if A or C is used for the axis address or 2nd miscellaneous command code, the A used for the axis address may function as the geometric's angle designation. Take special care when designating the axis name, etc., when using this function.	0/1/2
1084	RadErr	Arc error	Specify the tolerable error range when a deviation occurs in the end point and center coordinate in the circular command.	0 to 1.000 (mm)
1085	G00Drn	G00 dry run	Specify whether to apply dry run (feed with manual setting speed instead of command feedrate) to the G00 command. 0: Do not apply to G00. (move at rapid traverse rate) 1: Apply to G00. (move at manual set feedrate)	0: Do not apply to G00 1: Apply to G00
1086	G0Intp	G00 non-interpolation	Specify the G00 movement path type 0: Move linearly toward the end point. (interpolation type) 1: Move to the end point of each axis at the rapid traverse feedrate for each axis. (non-interpolation)	0/1
1087	G96_G0	Constant surface speed control by rapid traverse feed command	Specify how to handle the cycle speed for the G00 command when using the constant surface speed control function. 0: Calculate the cycle speed constantly even during G00 movement. 1: Calculate the cycle speed at the block end point in the G00 command.	0/1
1088	G30SL	Disable G30 soft limit	Specify how to handle the soft limit during G30 (2nd reference point return) movement. 0: Soft limit valid during G30 movement 1: Soft limit invalid during G30 movement	0: Soft limit valid 1: Soft limit invalid
1089	Cut_RT	Short cut for rotary axis	Specify how to handle the short cut control for the rotary axis (#1017 rot is set to 1). 0: No short cut (move toward end point) 1: Use short cut (when using the absolute value command, move in the direction where the movement amount will be 180° or less)	0: No short cut 1: Use short cut

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1090	Lin_RT Linear rotary axis	Specify how to handle a command for the rotary axis that exceeds 360°. 0: For absolute value commands that exceed 360°, the value will be converted into a remainder of 360° and the axis will move. Example: If the command is 420°, the applied value will be 60°. 1: For absolute value commands that exceed 360°, the axis will move in the same manner as a linear axis. Example: If the command is 420°, the axis will pass the 360° position and will move to the 60° position.	0/1
1091	Mpoint Ignore middle point	Specify how to handle the middle point during G28 and G30 reference point return. 0: Move to the reference point after passing the middle point designated in the program. 1: Ignore the middle point designated in the program and move straight to the reference point.	0/1
1092	Tchg_A Replace tools for additional axis	Specify the movement of the additional axis during tool change position return. 0: The additional axis does not move with the tool change position return command. 1: After returning the standard axis with the tool change position return command, the additional axis also returns to the tool change position.	0/1
1093	Wmvfin Inter-system waiting method	Specify the method for waiting between systems when using two systems. When the movement command is found in the wait command (!, M) block: 0: Wait before executing movement command 1: Wait after executing movement command	0/1
1094	TI_SBK (for L system only) Select life count for single block	Select whether to count the data units to be used for a single block when using the tool life management II function (L system). 0: Does not count the data units. 1: Count the data units.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1095	T0tfof TF output	Select how to handle TF for T00 command. 0: TF is output. 1: TF is not output	0/1
1096	T_Ltyp (for L system type only) Tool life management type	Specify the tool life management type.	1: Life management type I 2: Life management type II
1097	T1digit Tool wear compensation number 1-digit command	Specify the No. of digits in the tool wear compensation No. in the T command. 0: The 2 high-order digits are the tool No., and the 2 low-order digits are the wear compensation No. 1: The 3 high-order digits are the tool No., and the 1 low-order digit is the wear compensation No. This parameter will be fixed to 0 when tool life management II is selected.	0/1
1098	Tlno. Tool length offset number	Specify the No. of digits in the tool length offset No. in the T command. 0: The 2 or 3 high-order digits are the tool No. The 2 or 1 low-order digits are the tool length offset and wear compensation Nos. 1: The 2 or 3 high-order digits are the tool No. and tool length offset Nos. The 2 or 1 low-order digits are the wear compensation No.	0/1
1099	Treset Cancel tool wear compensation amount	Specify how to handle tool compensation vector when resetting system. 0: Clear the tool length and wear compensation vectors when resetting. 1: Save the tool length and wear compensation vectors when resetting. When the values are cleared, the compensation will not be applied, so the axis will move the compensation amount in the next compensation operation. When the values are saved, the compensation will be applied, so the axis will shift the differential amount of the compensation amount in the next compensation operation.	0: Clear 1: Save

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1100	Tmove Tool wear compensation	Specify the period to perform tool length offset and wear compensation. 0: Compensate when T command is executed. 1: Superimpose and compensate with the movement command in the block where the T command is located. If there is no movement command in the same block, compensation will be executed after the movement command is superimposed in the next movement command block. 2: Compensate when the T command is executed. 1: Superimpose and compensate a tool length offset with the movement command in the same block. If there is no movement command in the same block, compensation will be executed after the movement command is superimposed in the next movement command block.	0 to 2
1101	Tabsmv Tool wear compensation method	Specify the type of movement command when #1100 Tmove is set to 1. 0: Compensate regardless of the movement command type. 1: Compensate only at the movement command in the absolute value command.	0: Compensate regardless of the command type. 1: Compensate only with the absolute value command.
1102	tIm (For L system only) Manual tool length measuring system	Specify the measurement method for manual tool measurement I. 0: Align tool with reference position 1: Input measurement results	0: Reference position method 1: Measured value input method
1103	T_life Validate life management	Select the usage of the tool life management function.	0: Do not use. 1: Perform tool life management control.
1104	T_Com2 Tool command method 2	Select the command method for when #1103 T_Life is set to 1. 0: Handle the program tool command as the group No. 1: Handle the program tool command as the tool No.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items		Details	Setting range (unit)
1105	T_Sel2	Tool selection method 2	Select the tool selection method for when #1103 T_Life is set to 1. 0: Select in order of registered No. from the tools used in the same group. 1: Select the tool with the longest remaining life from tools used in the same group and the unused tools.	0/1
1106	Tcount (For L system only)	Life management count	Specify the function when address N is omitted when inputting data (G10 L3 command) for tool life management function II.	0: Time specified input 1: No. of times specified input
1107	TlIfsc (For L system only)	Split life management display screen	Set up the number of groups to be displayed on the tool life management II (L system) screen. 0: Displayed group count 1, maximum number of registered tools: 16 1: Displayed group count 2, maximum number of registered tools: 8 2: Displayed group count 4, maximum number of registered tools: 4	0 to 2
1108	TirectM (For L system only)	Life management re-count M code	Set up the M code for tool life management II (L system) re-count.	0 to 99
1109 (PR)	subs_M	Validate alternate M code	Select the user macro interrupt with the substitute M code.	0: Alternate M code invalid 1: Alternate M code valid
1110	M96_M	M96 alternate M code	Specify an M code to replace M96 when #1109 subs_M is set to 1.	3 to 97 (excluding 30)
1111	M97_M	M97 alternate M code	Specify an M code to replace M97 when #1109 subs_M is set to 1.	3 to 97 (excluding 30)
1112 (PR)	S_TRG	Validate status trigger system	Specify the validity conditions for the user macro interrupt signal. 0: Valid when interrupt signal (UIT) turns OFF to ON. 1: Valid when interrupt signal (UIT) is ON.	0: Valid when interrupt signal (UIT) turns OFF to ON. 1: Valid when interrupt signal (UIT) is ON.
1113 (PR)	INT_2	Validate interrupt method type 2	Specify the movement after user macro interrupt signal (UIT) input. 0: Execute interrupt program without waiting for block being executed to end. 1: Execute interrupt program after completing block being executed.	0/1

5. BASE SPECIFICATIONS PARAMETERS


#	Items	Details	Setting range (unit)
1114	mcrint Macro argument initialization	Select whether to clear statements other than specified arguments by macro call. Also, select whether to clear local variables by power-ON and resetting. 0: Delete non-specified arguments by macro call. 1: Retain non-specified arguments by macro call. 2: Retain non-specified arguments by macro call and clear local variables by power-ON and resetting.	0/1/2
1115	thwait Waiting for thread cutting	Set the queue number during screw thread cutting when the chamfering is not valid.	0 to 99 (Approx. 4 ms.) Standard set value: 4
1116	G30SLM Invalidate soft limit (manual operation)	Enable this function when disabling the soft limit check function from the second to the fourth zero point return by manual operation.	0: Enable soft limit function. 1: Disable soft limit function.
1117	H_sens Handle response switch	Switch the handle response mode when feeding the handle. 0: Standard handle response 1: High-speed handle response	0/1
1118	mirr_A (For L system only) Select how to set up the length of tools on cutter tables (opposed tables)	Select one of the following two methods: • Set up the current length of tools on each facing turret. • Set up a value, assuming that the tools on each facing turret are in the same direction as that of those on the base turret. 0: Current length of the tools on each facing turret 1: Value, assuming that the tools on each facing turret are in the same direction as that of those on the base turret.	0/1
1119	Tmiron (For L system only) Select the mirror image of each facing turret with T command	Select whether to validate the mirror image of each facing turret with the T command.	0: Invalid 1: Valid
1120 (PR)	TofVal Change macro variable	Specify whether to change the macro variable (tool offset) numbers for shape compensation and wear compensation. 0: Do not change. (Conventional specifications) 1: Change the shape and wear compensation variable numbers each for X, Z, and R.	0/1

5. BASE SPECIFICATIONS PARAMETERS


(SETUP PARAM 1. 5/15)

#	Items	Details	Setting range (unit)	
1121	edlk_c	Edit lock C	Specify whether to prohibit editing of program Nos. 9000 to 9999. Note: If #1122 is set to 1 or 2, 1 will be set in #1121 when the power is turned ON.	0: Editing possible 1: Editing prohibited
1122 (PR)	pglk_c	Program display lock	The display and search of program Nos. 9000 to 9999 can be prohibited. Specify whether to prohibit display and search. 0: Display and search is possible. 1: Program details are not displayed. 2: Program details are not displayed, and operation search is prohibited. The program details will not be displayed, but the program No. and sequence No. will display in the prohibited state. Note: If #1122 is set to 1 or 2, 1 will be set in #1121 when the power is turned ON.	0 to 2
1123	origin	Origin zero inhibition	Select whether to use the origin zero function.	0: Use 1: Do not use
1124	ofsfix	Fix tool wear compensation number	Specify whether to automatically increment the offset No. by 1 with the input or to display the No. as it is in the setting on the tool offset screen. 0: Increment the # No. by 1 when the input key is pressed. (Same as general parameters) 1: # No. does not change even if INPUT key is pressed. When making settings in sequence, 0 is handier. When changing and setting repeatedly while adjusting one offset value, 1 is handier	0/1
1125	real_f	Actual feedrate display	Specify the feedrate display on the monitor screen.	0: Command speed 1: Real movement feedrate
1126	PB_G90	Playback G90	Specify whether the playback movement amount when performing playback editing is to be an absolute value or incremental value.	0: Incremental value 1: Absolute value
1127	DPRINT	DPRINT alignment	Specify the alignment for printing out with the DPRINT function. 0: No alignment, data is printed with left justification. 1: Align the minimum digit and output.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items		Details	Setting range (unit)
1128	RstVCI	Clear variables by resetting	Specify how to handle the common variables when resetting. 0: Common variables do not change after resetting. 1: The following common variables are cleared by resetting: During variable 100 group specifications: #100 to #149 are cleared. During variable 200 group and 300 group specifications: #100 to #199 are cleared.	0/1
1129	PwrVCI	Clear variables by power-ON	Specify how to handle the common variables when the power is turned ON. 0: The common variables are in the same state as before turning the power OFF. 1: The following common variables are cleared when the power is turned ON. During variable 100 group specifications: #100 to #149 are cleared. During variable 200 group and 300 group specifications: #100 to #199 are cleared.	0/1
1130	set_t	Display selected tool number	Specify the tool command value display on the POSITION screen. 0: T-modal value of program command is displayed. 1: Tool number sent from PLC is displayed.	0/1
1131 (PR)	Fldcc	Feed forward filter	Parameter to suppress acceleration changes with a filter when starting acceleration or deceleration Specify the parameter in bits. 	bit1: 7.1 (ms) bit2: 14.2 (ms) bit3: 28.4 (ms) bit4: 56.8 (ms) bit5: 113.6 (ms) If bit 1 to bit 5 are all 0 or two or more bits of bit 1 to bit 5 are 1, 3.5 ms is set up.
1132	CRT	CRT brightness control	This parameter adjusts the brightness of the CRT display unit. 3: Highest luminance (Brightest state) -3: Lowest luminance (Darkest state) Adjust this parameter to an appropriate brightness between -3 and 3. The EL display unit does not have brightness adjustment, so setting is not required.	-3 to 3


5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1133	ofsmem Select how to set up tool wear compensation screen	Select the number stored by previous setup when selecting the tool wear compensation screen. 0: Does not display the number when selecting the screen. 1: Displays the stored number when selecting the screen.	0/1
1134	LCDneg LCD reverse display	Specify 1 to reverse the display on the 10.4-type monochrome LCD.	0: Normal display 1: Reverse display
1135	unt_nm Unit name	Set up a unit name. Set up the unit name with 4 or less characters consisting of both alphabets and numbers. If 0 is set up, the unit name is not displayed.	4 or less characters consisting of both alphabets and numbers
1136	optype Operation menu display valid	This parameter validates the operation menu display. Specify the setting method for the tool offset data's absolute value or incremental value. 0: Mode selection method (Conventional specification) 1: Menu selection method This parameter is valid on the following screens. • TOOL TIP OFFSET screen (L system) • TOOL DATA screen (L system) • NOSE-R screen (L system) • TOOL OFFSET screen type I (M system) • TOOL OFFSET screen type II (M system)	0/1
1137	Cntsel Coordinate value screen display counter select	Set the type of the position counter to be displayed on the COORDINATE screen. 	1st digit : 0 to 3 2nd digit: 0 to 3 (Default : 00)
1138	Pnosel Select screen by parameter number:	Specify whether to enable the function to select a screen by specifying a parameter number.	0: Disable 1: Enable


5. BASE SPECIFICATIONS PARAMETERS

#	Items		Details	Setting range (unit)
1139	edtype	Edit type selection	Set up an edit type. 0: Screen edit type (M50 or equivalent operation) 1: Screen edit type (The screen of EDIT or MDI is changed automatically according to the selected operation mode.) 2: Word edit type (The screen of EDIT or MDI is changed automatically according to the selected operation mode.) 3: Screen edit type (type 0 + retaining cursor position) (Applicable only to M64 D version series) 4: Screen edit type (type 1 + retaining cursor position) (Applicable only to M64 D version series)	0/1/2/3/4
1140	Mn100	M code number	First number of M code that corresponds to setup number from 100 to 199	0 to 99999999
1141	Mn200	M code number	First number of M code that corresponds to setup number from 200 to 299	0 to 99999999
1142	Mn300	M code number	First number of M code that corresponds to setup number from 300 to 399	0 to 99999999
1143	Mn400	M code number	First number of M code that corresponds to setup number from 400 to 499	0 to 99999999
1144	mdlkof	MDI setup lock	Select whether to enable MDI setup in non-MDI mode.	0: Disable MDI setup 1: Enable MDI setup
1145	I_abs	Manual ABS parameter	Specify how to handle the absolute value data during automatic handle interrupt. 0: Absolute value data is renewed if manual ABS switch is ON. Data is not renewed if switch is OFF. 1: Follows the intabs state when #1061 intabs is valid.	0/1
1146	Sclamp	Spindle rotation speed clamp function	Specify how to handle the spindle rotation speed clamp function with the G92S command. 0: G92S command is handled as a clamp command only in the G96 state (during constant surface speed control). G92S will be handled as normal S command in G97 state (constant surface speed OFF). 1: The S command in the same block as G92 is constantly handled as a clamp command.	0/1
1147	smin_V	Minimum spindle rotation speed clamp type	Specify the type of spindle min. rotation speed clamp value. 0: Rotation speed setting 1: Output voltage coefficient setting Set the #3023 smini parameter according to this type setting.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)	
1148	I_G61 1	Initial high precision	The modal state when the power is turned ON is set to the high accuracy control mode. 0: OFF 1: ON	0/1
1149	cireft	Arc deceleration speed change	Specify whether to enable deceleration at the arc entrance or exit. 0: Disable 1: Enable	0/1
1150	Fldc0	G00 feed forward filter	This parameter is used to filter acceleration changes at the start of rapid acceleration/deceleration. Specify the filters in bit units.  <p>0: Common 1: Separation</p>	bit1: 7.1 (ms) bit2: 14.2 (ms) bit3: 28.4 (ms) bit4: 56.8 (ms) bit5: 113.6 (ms) When bits 1 to 5 are all 0 or when two or more of bits 1 to 5 are 1, 3.5 (ms) is assumed.
1151	rstint	Reset initial	Specify whether to initialize (power ON state) the modals by resetting. 0: Do not initialize modal state. 1: Initialize modal state.	0/1
1152	I_G20	Initial command unit	Specify whether the default mode after power-ON or resetting, inch command or metric command mode. 0: Metric command (G21 command state) 1: Inch command (G20 command state) Valid when reset input is made. Related parameter: Bit 6 "Select setting and display unit" of #1226	0/1
1153	FixbDc	Hole bottom deceleration check	Specify whether to perform a deceleration check or in-position check at the hole bottom in the hole drilling cycle. This parameter is valid only for a hole drilling cycle in which no dwell command can be issued at the hole bottom. 0: Perform no deceleration check and in-position check. 1: Perform a deceleration check. 2: Perform an in-position check.	0 to 2

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1154 (PR)	pdoor Door interlock II (for each system)	<p>Specify whether to control door interlock II independently for each of the two systems. When door interlock II is controlled for each system of the two systems, system 1 is connected to SV1 (channel 1) of the base I/O unit and system 2 is connected to SV2 (channel 2) of the base I/O unit.</p> <p>Base I/O unit</p>  <p>When the auxiliary axis (MR-J2-CT) is used, connect it to the SV2 side (after the spindle). This validates door interlock II of system 2.</p> <ul style="list-style-type: none"> 0: Do not use door interlock II independently for channels. 1: Use door interlock II independently for channels. (Separate systems when using two systems) 2: Use door interlock II independently for channels. (Use independently for system 1 channels) (Use both for system 2) <p>When 0 is specified for this parameter, "Signal input device 1 for door interlock II (#1155 DOOR_m)" and "Signal input device 2 for door interlock II (#1156 DOOR_s)" are valid. When 1 is specified, "Signal input device 1 for door interlock II: for each system (#1511 DOORPm)" and "Signal input device 2 for door interlock II: for each system (#1512 DOORPs)".</p>	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1155	DOOR_m Signal input device 1 for door interlock II	Set up a fixed device number (X??) for door interlock II signal input. A device number from X01 to XFF can be set up. Device number 000 is invalid. Set up device number 100 when using no fixed device number for door interlock II signal input. Related parameter: #1154 pdoor Door interlock II (for each system)	000 to 100 (Hexadecimal)
1156	DOOR_s Device number 2 for door interlock II signal input	Set up a fixed device number (X??) for door interlock II signal input. (Set up the same value as that of #1155.) Related parameter: #1154 pdoor Door interlock II (for each system)	000 to 100 (Hexadecimal)
1157	F0atrn F0 automatic running	Not used	
1158	F0atno F0 automatic running program	Not used	
1165	p_trans Parameter FROM backup	The parameters are written, read and compared. 0: No process 1: The backed up parameters are read from the FROM. 2: The parameters are written into the FROM. 3: The parameters are compared with those backed up in the FROM.	0 to 3
1166	fixpro Fixed cycle editing	Select whether to use the edit, program list and data input/output functions for the fixed cycles, machine manufacturer macro programs or general programs. 0: General programs can be edited, etc. 1: The fixed cycles can be edited, etc. Password No.: The machine manufacturer macro programs can be edited, etc.	0 to 99999999
1167	e2rom	Not used.	
1168	test Simulation test	Specify the test mode for the control unit. The test mode does not use reference point return, and tests with a hypothetical zero point return completed state. This is limited to test operation of the control unit itself, and must not be used when connected to the machine.	0: Normal operation mode 1: Test mode

5. BASE SPECIFICATIONS PARAMETERS

(SETUP PARAM 1. 6/15)

#	Items	Details	Setting range (unit)																																							
1169	system name	System name Set the name of each system. This must be set only when using two systems. This name is displayed on the screen only when the systems must be identified. Use a max. of four alphabetic characters or numerals.	A max. of four alphabetic characters or numerals.																																							
1170	M2name	Second miscellaneous code Set this address code when using the 2nd miscellaneous command. Set an address with A, B and C that is not used with #1013 axname or #1014 incax.	A, B, C																																							
1171	taprov	Tap return override Set the tap return override value for the synchronous tap.	1 to 100 (%)																																							
1172	tapovr	Tap return override Set the override value when leaving the tap end point in the synchronous tap cycle. The setting range is 1 to 999, and the unit is %. When a value less than 100 is set, it will be judged as 100%.	1 to 999 (%)																																							
1173	dwlskp	G04 skip condition Specify the skip signal for ending the G04 (dwell) command.	Skip condition 0 to 7 <table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th rowspan="2">Set-ting</th> <th colspan="3">PLC interface input signal</th> </tr> <tr> <th>Skip 3</th> <th>Skip 2</th> <th>Skip 1</th> </tr> </thead> <tbody> <tr><td>0</td><td>×</td><td>×</td><td>×</td></tr> <tr><td>1</td><td>×</td><td>×</td><td>○</td></tr> <tr><td>2</td><td>×</td><td>○</td><td>×</td></tr> <tr><td>3</td><td>×</td><td>○</td><td>○</td></tr> <tr><td>4</td><td>○</td><td>×</td><td>×</td></tr> <tr><td>5</td><td>○</td><td>×</td><td>○</td></tr> <tr><td>6</td><td>○</td><td>○</td><td>×</td></tr> <tr><td>7</td><td>○</td><td>○</td><td>○</td></tr> </tbody> </table> <p style="text-align: right;">End when ○ signal is input.</p>	Set-ting	PLC interface input signal			Skip 3	Skip 2	Skip 1	0	×	×	×	1	×	×	○	2	×	○	×	3	×	○	○	4	○	×	×	5	○	×	○	6	○	○	×	7	○	○	○
Set-ting	PLC interface input signal																																									
	Skip 3	Skip 2	Skip 1																																							
0	×	×	×																																							
1	×	×	○																																							
2	×	○	×																																							
3	×	○	○																																							
4	○	×	×																																							
5	○	×	○																																							
6	○	○	×																																							
7	○	○	○																																							
1174	skip_F	G31 skip speed Specify the feedrate when there is no F command in the program at G31 (skip) command.	1 to 999999 (mm/min)																																							
1175	skip1	G31.1 skip condition Skip signal specified at G31.1	Skip condition 0 to 7 <table border="1" style="margin-left: auto; margin-right: auto;"> <thead> <tr> <th rowspan="2">Set-ting</th> <th colspan="3">PLC interface input signal</th> </tr> <tr> <th>Skip 3</th> <th>Skip 2</th> <th>Skip 1</th> </tr> </thead> <tbody> <tr><td>0</td><td>×</td><td>×</td><td>×</td></tr> <tr><td>1</td><td>×</td><td>×</td><td>○</td></tr> <tr><td>2</td><td>×</td><td>○</td><td>×</td></tr> <tr><td>3</td><td>×</td><td>○</td><td>○</td></tr> <tr><td>4</td><td>○</td><td>×</td><td>×</td></tr> <tr><td>5</td><td>○</td><td>×</td><td>○</td></tr> <tr><td>6</td><td>○</td><td>○</td><td>×</td></tr> <tr><td>7</td><td>○</td><td>○</td><td>○</td></tr> </tbody> </table> <p style="text-align: right;">Skip feedrate 1 to 999999 (mm/min)</p>	Set-ting	PLC interface input signal			Skip 3	Skip 2	Skip 1	0	×	×	×	1	×	×	○	2	×	○	×	3	×	○	○	4	○	×	×	5	○	×	○	6	○	○	×	7	○	○	○
Set-ting	PLC interface input signal																																									
	Skip 3	Skip 2		Skip 1																																						
0	×	×		×																																						
1	×	×		○																																						
2	×	○		×																																						
3	×	○	○																																							
4	○	×	×																																							
5	○	×	○																																							
6	○	○	×																																							
7	○	○	○																																							
1176	1f	G31.2 skip speed Skip feedrate at G31.1																																								
1177	2	G31.2 skip condition Skip signal specified at G31.2																																								
1178	2f	G31.2 skip speed Skip feedrate at G31.2																																								
1179	3	G31.3 skip condition Skip signal specified at G31.3																																								
1180	3f	G31.3 skip speed Skip feedrate at G31.3																																								

5. BASE SPECIFICATIONS PARAMETERS


#	Items	Details	Setting range (unit)
1181	G96_ax Constant surface speed control	Specify the axis to be targeted for constant surface speed control. 0: Program specification will be invalidated, and the axis will always be fixed to the 1st axis. 1: 1st axis specification 2: 2nd axis specification 3: 3rd axis specification 4: 4th axis specification The program specification will be the priority for all settings other than 0.	0 to 4
1182	thr_F Thread cutting speed	Set the screw cut up speed when not using chamfering in the thread cutting cycle. 0: Cutting feed clamp feedrate 1 to 60000 mm/min: Set feedrate	0 to 60000 (mm/min)
1183	clmp_M M code for clamp	Set the M code for C-axis clamp in the hole drilling cycle.	0 to 99999999
1184	clmp_D Dwelling time after outputting M code for unclamp	Set the dwell time after outputting the M code for C-axis unclamp in the hole drilling cycle.	0.000 to 99999.999 (s)
1185	spd_F1 F1 digit feedrate	Specify the feedrate for the F command in the F1-digit command (#1079 F1 digit is set to 1). Feedrate when F1 is issued (mm/min)	1 to 60000 (mm/min)
1186	F2 F2	Feedrate when F2 is issued (mm/min)	
1187	F3 F3	Feedrate when F3 is issued (mm/min)	
1188	F4 F4	Feedrate when F4 is issued (mm/min)	
1189	F5 F5	Feedrate when F5 is issued (mm/min)	
1190 (PR)	s_xcnt (For L system only) Validate inclined-axis control	Specify whether to disable or enable inclined-axis control. 0: Disable inclined-axis control 1: Enable inclined-axis control	0/1
1191 (PR)	s_angl (For L system only) Inclination angle	Specify the inclination angle (θ). Note: If 0 is specified for this parameter, the angle determined by three-side setting is valid.	± 80.000 ($^{\circ}$)
1192 (PR)	s_zrmv (For L system only) Compensation at origin return	Specify whether to perform compensation for the base axis corresponding to the inclined axis at original return. 0: Perform compensation. 1: Don't perform compensation.	0/1

5. BASE SPECIFICATIONS PARAMETERS

(SETUP PARAM 1. 7/15)

#	Items	Details	Setting range (unit)	
1193	inpos	The setting is selected with "#1306 InpsTyp Deceleration check specification type". 0: Deceleration check method 1 1: Validate in-position check	/	
		Deceleration check method 1	Specify the deceleration check method for G0. 0: Command deceleration check 1: In-position check	0/1
		Validate in-position check	Specify the deceleration confirmation method for the positioning or cutting command. 0: G0, G1+G9 Command deceleration check 1: G0, G1+G9 In-position check	0/1
1194	H_acdc	Time constant 0 for handle feed Specify the time constant for the manual handle feed. 0: Use time constant for G01 1: Time constant 0 (step)	0/1	
1195 1196 1197 1198	Mmac Smac Tmac M2mac	Macro call for M command Macro call for S command Macro call for T command Macro call with 2nd miscellaneous code	Specify the user macro M, S or T command macro call out. Macro call out with M command Macro call out with S command Macro call out with T command Macro call out with 2nd miscellaneous command	0: Invalid 1: Valid
1199	Sselect	Select initial spindle control	Select the initial condition of spindle control after power is turned ON. 0: 1st spindle control mode (G43.1) 1: Selected spindle control mode (G44.1) 2: All spindle simultaneously control mode (G47.1) Note: Spindle No. when G44.1 is commanded is selected with #1534 SnG44.1.	0: G43.1 1: G44.1 2: G47.1
1200 (PR)	G0_acc	Validate acceleration and deceleration with inclination angle constant G0	Set up acceleration and deceleration types when a rapid traverse command is issued 0: Acceleration and deceleration (conventional) with time constant 1: Acceleration and deceleration with inclination angle constant	0: Acceleration and deceleration with time constant 1: Acceleration and deceleration with inclination angle constant

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1201 (PR)	G1_acc Validate acceleration and deceleration with inclination constant G1	Set up acceleration and deceleration types when a liner interpolation command is issued. 0: Acceleration and deceleration (conventional) with time constant 1: Acceleration and deceleration with inclination angle constant	0: Acceleration and deceleration with time constant 1: Acceleration and deceleration with inclination angle constant
1202	mirofs (For L system only) Distance between facing turrets	Set up the distance between tools (edges) (between facing turrets).	0 to 99999.999 (mm)
1203	TmirS1 (For L system only) Select turrets as facing turrets with T command	Set up turrets as shown in the mirror image of facing turrets with the T command that corresponds to tool numbers 1 to 32.	0 to FFFFFFFF
1204	TmirS2 (For L system only) Select turrets as facing turrets with T command	Set up turrets as shown in the mirror image of facing turrets with the T command that corresponds to tool numbers 33 to 64.	0 to FFFFFFFF
1205	G0bdcc Acceleration and deceleration before G0 interpolation	0: G00 acceleration and deceleration are selected as those after interpolation. 1: The G00 acceleration/deceleration is the acceleration/decelerate before interpolation regardless of whether the mode is the high accuracy control mode. (Note)"1" cannot be set for the 2nd system.	0/1
1206	G1bF Maximum speed	Set up a cutting feedrate when selecting acceleration and deceleration before interpolation.	1 to 999999 (mm/min)
1207	G1btL Time constant	Set up a cutting feed time constant when selecting acceleration and deceleration before interpolation. 	1 to 5000 (ms)
1208	RCK Arc radius error compensation factor	An arc radius error compensation can be increased and decreased from -60.0 to 20.0%.	-60.0 to +20.0 (%)

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)																																																																
1209	cirdcc Arc deceleration speed	Specify the deceleration speed at the arc entrance or exit.	1 to 999999 (mm/min)																																																																
1210	RstGmd Modal G code reset	<p>Specify whether to initialize each G code group modal and the H and D codes when the system is reset. Specify the initialization items in bit correspondence.</p> <p>0. Initialize. 1: Don't initialize.</p> <p>M system</p> <table border="1"> <tr><td>0</td><td>Group 1 Move G modal</td></tr> <tr><td>1</td><td>Group 2 Flat selection modal</td></tr> <tr><td>2</td><td>Group 3 Absolute/increment command modal</td></tr> <tr><td>3</td><td></td></tr> <tr><td>4</td><td>Group 5 Feed G modal</td></tr> <tr><td>5</td><td>Group 6 Inch/metric modal</td></tr> <tr><td>6</td><td>Group 7 Radius compensation modal</td></tr> <tr><td>7</td><td>Group 8 Length compensation modal</td></tr> <tr><td>8</td><td></td></tr> <tr><td>9</td><td>Group 10 Fixed cycle return command modal</td></tr> <tr><td>A</td><td></td></tr> <tr><td>B</td><td>Group 12 Workpiece coordinate system modal</td></tr> <tr><td>C</td><td>Group 13 Cut modal</td></tr> <tr><td>D</td><td></td></tr> <tr><td>E</td><td>Group 15 Normal line control modal</td></tr> <tr><td>F</td><td></td></tr> </table> <table border="1"> <tr><td>10</td><td>Group 17 Constant surface speed control command modal</td></tr> <tr><td>11</td><td>Group 18 pole coordinate command modal</td></tr> <tr><td>12</td><td>Group 19 G command mirror modal</td></tr> <tr><td>13</td><td>Group 20 Spindle 2 control modal</td></tr> <tr><td>14</td><td></td></tr> <tr><td>15</td><td></td></tr> <tr><td>16</td><td></td></tr> <tr><td>17</td><td></td></tr> <tr><td>18</td><td>H, D codes</td></tr> <tr><td>19</td><td>Spindle clamp rotation speed</td></tr> <tr><td>1A</td><td></td></tr> <tr><td>1B</td><td></td></tr> <tr><td>1C</td><td></td></tr> <tr><td>1D</td><td></td></tr> <tr><td>1E</td><td></td></tr> <tr><td>1F</td><td></td></tr> </table> <p>The H code indicates the tool length offset number, and the D code indicates the tool radius compensation number.</p> <p>When bit 18 is set to ON, the H and D codes and group 8 G modal area retained.</p> <p>When bit 7 is set to ON, the H code and group 8 G modal are retained.</p> <p>(To be continued to the next page)</p>	0	Group 1 Move G modal	1	Group 2 Flat selection modal	2	Group 3 Absolute/increment command modal	3		4	Group 5 Feed G modal	5	Group 6 Inch/metric modal	6	Group 7 Radius compensation modal	7	Group 8 Length compensation modal	8		9	Group 10 Fixed cycle return command modal	A		B	Group 12 Workpiece coordinate system modal	C	Group 13 Cut modal	D		E	Group 15 Normal line control modal	F		10	Group 17 Constant surface speed control command modal	11	Group 18 pole coordinate command modal	12	Group 19 G command mirror modal	13	Group 20 Spindle 2 control modal	14		15		16		17		18	H, D codes	19	Spindle clamp rotation speed	1A		1B		1C		1D		1E		1F		Specify a hexadecimal number.
0	Group 1 Move G modal																																																																		
1	Group 2 Flat selection modal																																																																		
2	Group 3 Absolute/increment command modal																																																																		
3																																																																			
4	Group 5 Feed G modal																																																																		
5	Group 6 Inch/metric modal																																																																		
6	Group 7 Radius compensation modal																																																																		
7	Group 8 Length compensation modal																																																																		
8																																																																			
9	Group 10 Fixed cycle return command modal																																																																		
A																																																																			
B	Group 12 Workpiece coordinate system modal																																																																		
C	Group 13 Cut modal																																																																		
D																																																																			
E	Group 15 Normal line control modal																																																																		
F																																																																			
10	Group 17 Constant surface speed control command modal																																																																		
11	Group 18 pole coordinate command modal																																																																		
12	Group 19 G command mirror modal																																																																		
13	Group 20 Spindle 2 control modal																																																																		
14																																																																			
15																																																																			
16																																																																			
17																																																																			
18	H, D codes																																																																		
19	Spindle clamp rotation speed																																																																		
1A																																																																			
1B																																																																			
1C																																																																			
1D																																																																			
1E																																																																			
1F																																																																			

5. BASE SPECIFICATIONS PARAMETERS

#	Items		Details	Setting range (unit)																																																																
			<p>(Continued from the previous page)</p> <p>L system</p> <table border="1" data-bbox="542 344 1165 846"> <tr><td>0</td><td>Group 1 Move G modal</td></tr> <tr><td>1</td><td>Group 2 Flat selection modal</td></tr> <tr><td>2</td><td>Group 3 Absolute/increment command modal</td></tr> <tr><td>3</td><td>Group 4 Barrier check modal</td></tr> <tr><td>4</td><td>Group 5 Feed G modal</td></tr> <tr><td>5</td><td>Group 6 Inch/metric modal</td></tr> <tr><td>6</td><td>Group 7 Nose R compensation modal</td></tr> <tr><td>7</td><td></td></tr> <tr><td>8</td><td></td></tr> <tr><td>9</td><td>Group 10 Fixed cycle return command modal</td></tr> <tr><td>A</td><td></td></tr> <tr><td>B</td><td>Group 12 Workpiece coordinate system modal</td></tr> <tr><td>C</td><td>Group 13 Cut modal</td></tr> <tr><td>D</td><td></td></tr> <tr><td>E</td><td></td></tr> <tr><td>F</td><td></td></tr> </table> <table border="1" data-bbox="542 962 1165 1464"> <tr><td>10</td><td>Group 17 Constant surface speed control command modal</td></tr> <tr><td>11</td><td>Group 18 Balance cut</td></tr> <tr><td>12</td><td></td></tr> <tr><td>13</td><td>Group 20 Spindle 2 control modal</td></tr> <tr><td>14</td><td>Group 15 Facing turret mirror image</td></tr> <tr><td>15</td><td></td></tr> <tr><td>16</td><td></td></tr> <tr><td>17</td><td></td></tr> <tr><td>18</td><td></td></tr> <tr><td>19</td><td></td></tr> <tr><td>1A</td><td></td></tr> <tr><td>1B</td><td></td></tr> <tr><td>1C</td><td></td></tr> <tr><td>1D</td><td></td></tr> <tr><td>1E</td><td></td></tr> <tr><td>1F</td><td></td></tr> </table>	0	Group 1 Move G modal	1	Group 2 Flat selection modal	2	Group 3 Absolute/increment command modal	3	Group 4 Barrier check modal	4	Group 5 Feed G modal	5	Group 6 Inch/metric modal	6	Group 7 Nose R compensation modal	7		8		9	Group 10 Fixed cycle return command modal	A		B	Group 12 Workpiece coordinate system modal	C	Group 13 Cut modal	D		E		F		10	Group 17 Constant surface speed control command modal	11	Group 18 Balance cut	12		13	Group 20 Spindle 2 control modal	14	Group 15 Facing turret mirror image	15		16		17		18		19		1A		1B		1C		1D		1E		1F		Specify a hexadecimal number.
0	Group 1 Move G modal																																																																			
1	Group 2 Flat selection modal																																																																			
2	Group 3 Absolute/increment command modal																																																																			
3	Group 4 Barrier check modal																																																																			
4	Group 5 Feed G modal																																																																			
5	Group 6 Inch/metric modal																																																																			
6	Group 7 Nose R compensation modal																																																																			
7																																																																				
8																																																																				
9	Group 10 Fixed cycle return command modal																																																																			
A																																																																				
B	Group 12 Workpiece coordinate system modal																																																																			
C	Group 13 Cut modal																																																																			
D																																																																				
E																																																																				
F																																																																				
10	Group 17 Constant surface speed control command modal																																																																			
11	Group 18 Balance cut																																																																			
12																																																																				
13	Group 20 Spindle 2 control modal																																																																			
14	Group 15 Facing turret mirror image																																																																			
15																																																																				
16																																																																				
17																																																																				
18																																																																				
19																																																																				
1A																																																																				
1B																																																																				
1C																																																																				
1D																																																																				
1E																																																																				
1F																																																																				
1211	FHtyp	Feed hold stop type	Specify the type of the external signal used for feed hold. 0: Disable the external signal. 1: Enable the external signal (contact A) 2: Enable the external signal (contact B)	0 to 2																																																																
1212	FHno	Feed hold external signal device	Specify the number (X??) of the device used to input the feed hold signal.	000 to 13F (hexadecimal)																																																																
1213	proaxy (For L system only)	Side 1 of inclination angle	Specify the length on the rectangular coordinates of the inclined axis in the triangle made up of the inclination angle.	±9999.999																																																																

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)	
1214	macaxy (For L system only)	Side 2 of inclination angle	Specify the length of the actual base axis corresponding to the inclined axis in the triangle made up of the inclination angle.	±9999.999
1215	macaxx (For L system only)	Side 3 of inclination angle	Specify the length of the actual axis of the inclined axis in the triangle made up of the inclination angle.	±9999.999
1216	extdcc	External deceleration level	Use an upper limit value at the feedrate indicated when validating external deceleration signals. This parameter is valid when #1239 set11/bit6 is set to 0.	1 to 999999 (mm/min)

5. BASE SPECIFICATIONS PARAMETERS


(SETUP PARAM 1. 8/15)

#	Items	Details	Setting range (unit)
1217	aux01	Not used	
1218	aux02 (bit3)	Parameter input/output format 0: Type I 1: Type II (related to #1218 aux02/bit5)	0/1
	aux02 (bit4)	Tool number selection Specify the R register that contains the tool number used for automatic calculation when measuring the coordinate offset of an external workpiece. 0: Conforms to #1130 set_t. 1: Uses the tool number indicated by user PLC	0/1
	aux02 (bit5)	Parameter I/O II spindle specification address Specify the spindle specification address of parameter I/O type II. 0: C 1: T This parameter also applies to the spindle specification address for input and collation. Note: This parameter is valid only for parameter I/O type II (bit 3 of aux02 in #1218 is 1).	0/1
	aux02 (bit6)	Set No. valid when program input Specify which program No. is selected when inputting operation using "#1 MAIN PROGRAM" in Data I/O screen. 0: The No. in the input data is valid. 1: The No. set in the data setting area is valid.	0/1
	aux02 (bit7)	Input by program overwrite (1) When inputting operation using "#1 MAIN PROGRAM" in Data I/O screen, select one of the following options when the input program has already been registered: 0: An operation error (E65) occurs. 1: Input by overwrite. (2) When using the high-speed program server, select the operation if the name of the file to be transmitted with transmission (IC → host) operations already exists in the host. 0: Overwrite prohibit 1: Overwrite valid	0/1
1219	aux03 (bit1)	Stop high-speed PC monitoring function Set 1 to disable the function that stops the system when the high-speed processing time is extended. Disable the monitoring function only as a temporary measure.	0/1
	aux03 (bit2)	Improve skip coordinate accuracy 0: Skip accuracy (conventional specification) 1: Changes skip accuracy (correct a position in skip coordinates when entering skip signals).	0/1
	aux03 (bit5)	Dog-type intermediate point Select whether to move to the intermediate point during automatic dog-type reference point return. 0: Do not move to intermediate point during dog-type reference point return. 1: Move to intermediate point during dog-type reference point return.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1220	aux04 (bit 0) (For L system only)	Tool life check timing selection Specify the life check standard applicable when the use count is incremented in tool life management II. 0: Determine that the tool life is over when the incremented use count exceeds the life count. (Use count > life count) 1: Determine that the tool life is over when the incremented use count has reached the life count. (Use count ≥ life count)	0/1 (Default: 0)
	aux04 (bit1)	Validity of space code in comment Validate or invalidate the space code described in the comment statements in the machining program in edit operation with the special display. 0: Invalidate the space code in the comment statements of the machining program. 1: Validate the space code in the comment statements of the machining program.	0/1 (Default: 0)
	aux04 (bit2)	Not used.	
	aux04 (bit3)	Not used.	
	aux04 (bit4)	Data input/output unit selection Specify the input/output data unit for tool data and user parameter input/output. 0: Internal unit (metric) 1: Follows command mode set with #1152 I_G20 Metric when set to 0 Inch when #1152 I_G20 is set to 1 This parameter is valid when initial metric (#1041 I_inch 0) is set and the setting and display unit is the command unit (#1226 aux10 bit6 1). In all other cases, the tool data will be input and output with the internal units.	0/1
	aux04 (bit7)	Host communication validity during automatic operation Set whether Ethernet communication is enabled during automatic operation. 0: Ethernet communication disabled during automatic operation 1: Ethernet communication enabled during automatic operation (Note) If Ethernet communication is enabled during automatic operation, interrupt processes required for communication will be carried out, so the machining performance could be affected.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1221	aux05 (bit7) Current value B valid	<p>Select the type of counter to be displayed on the POSITION screen.</p> <p>0: Displays a relative value (value that includes tool length offset amount, tool radius compensation amount and workpiece coordinate offset amount)</p> <p>1: Displays current value B (value that does not include tool length offset amount, tool radius compensation amount and workpiece coordinate offset amount)</p>  <p>(Note1) When "#1221 aux05/bit7" is set to "1", the current value B is selected regardless of the bit type of #1287 ext23. When the current value B is valid, the counter zero or origin zero is invalid.</p> <p>(Note2) The following limits apply to M64A/M64:</p> <ul style="list-style-type: none"> • This is compatible only with the lathe system. • The relative value counter on the COORDINATE screen will also display the current value B. • When "#1287 ext23/bit3" is set to 0, the relative value will be displayed instead of the current value B regardless of this parameter setting. 	0/1
1222	aux06 (bit0) Validity of tool length measurement confirmation message	<p>0: Display no confirmation message when tool compensation data is set.</p> <p>1: Display a confirmation message when tool compensation data is set. (Applicable only to M64 D version series)</p>	0/1
	aux06 (bit1) Height axis specification	<p>When 1 is set in this parameter, the axis specified by base specification parameter #1028 base_k is measured and no other axes are measured if they move. (Applicable only to M64 D version series)</p>	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
	aux06 (bit2) Servo waveform display	Specify whether to enable the waveform display function. (Applicable only to M64 D version series) 0: Disable the waveform display function. 1: Enable the waveform display function.	0/1
	aux06 (bit3) Enable/disable setup parameter lock	Specify whether to enable the setup parameter lock function. 0: Disable 1: Enable	0/1
	aux06 (bit4) Minimum cut-in amount selection	Select the minimum cut-in amount command value for the compound thread cutting cycle (G76 command). 0: The minimum cut-in amount (Q) is "0". 1: The minimum cut-in amount (Q) is the CNC internal data.	0/1
	aux06 (bit5) Fixed cycle for compound lath command format check selection	Select the operation to be made if the 1st block of the fixed cycle for compound lathe is omitted when the conventional format is selected (#1265 ext01/bit0 "0"). 0: Program error (P33) occurs. 1: Parameter setting value is used.	0/1
	aux06 (bit7) Zero point return deceleration check method	Set the deceleration check method used during automatic reference point return. (Applicable only to M64 D version series) 0: In-position check 1: Commanded deceleration check	0/1
1223	aux07 (bit0) Rapid traverse inclination constant multi-stage acceleration and deceleration	Specify whether to enable the rapid traverse inclination constant multi-stage acceleration/deceleration function. (Applicable only to M64 D version series) 0: Disable 1: Enable Related parameters: #2064 rapid2 Speed 2 #2065 G0tL2 Time constant 2 #2066 rapid3 Speed 3 #2067 G0tL3 Time constant 3	0/1
	aux07 (bit1) Deceleration check method 2	Select the deceleration check method in G1+G9. 0: Command deceleration check in G1+G9 1: In-position check in G1+G9 The deceleration check is not performed except G1+G9. When "#1306 InpsTyp deceleration check specification type" is set to 1 (Deceleration check specification type 2), this parameter will be invalid.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
aux07 (bit2)	Synchronous tap R-point in-position check	0: Disable the synchronous tap I-point → R-point in-position check. 1: Enable the synchronous tap I-point → R-point in-position check. (Applicable only to M64 D version series) Note: This parameter is valid only when 1 (in-position check is valid) is set in bit 3 of #1223 aux07 (synchronous tap in-position check improvement).	0/1
aux07 (bit3)	Synchronous tap in-position check improvement	Specify whether to enable the synchronous tap in-position check improvement function. (Applicable only to M64 D version series) 0: Disable 1: Enable Related parameters: #1223 bit 2 Synchronous tap R-point in-position check bit 4 Synchronous tap hole bottom in-position check bit 5 Synchronous tap R-point in-position check 2	0/1
aux07 (bit4)	Synchronous tap hole bottom in-position check	0: Disable the synchronous tap hole bottom in-position check. 1: Enable the synchronous tap hole bottom in-position check. (Applicable only to M64 D version series) Note: This parameter is valid only when 1 (in-position check is valid) is set in bit 3 of #1223 aux07 (synchronous tap in-position check improvement).	0/1
aux07 (bit5)	Synchronous tap R-point in-position check 2	0: Disable synchronous tape R-point in-position check. 1: Enable synchronous tape R-point in-position check. (Applicable only to M64 D version series) Note: This parameter is valid only when 1 (in-position check is valid) is set in bit 3 of #1223 aux07 (synchronous tap in-position check improvement).	0/1
aux07 (bit6)	Cancel synchronous tap (,S) return	0: Retains a spindle rotation speed (, S) when performing synchronous tap return. 1: Cancels a spindle rotation speed (, S) by return with G80.	0/1
aux07 (bit7)	Synchronous tap method	Specify a synchronous tap method. 0: Synchronous tap (multi-step acceleration and deceleration and rapid return) 1: Conventional type synchronous tap	0/1
1224 aux08 (bit0)	Sampling data output	Set the validity of the sampling data output. 0: Sampling output invalid 1: Sampling output valid	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)	
1225	aux09 (bit0)	PLC Interface Diagnosis screen changeover	Set this to change to the PLC Interface Diagnosis screen. 0: 40-character compatible screen 1: 80-character compatible screen	0/1
	aux09 (bit7)	Enable/disable spindle rotation speed clamp	Specify whether to enable spindle rotation speed clamp by the spindle rotation speed clamp command (G92S, Q) instead of the spindle rotation speed command (R108) specified by the user ladder. 0: Enable 1: Disable	0/1
1226	aux10 (bit0)	Tool compen- sation data for external workpiece coordinate offset measurement	Select the tool offset data to be used for external workpiece coordinate offset measurement. 0: Tool length data and tool nose wear data 1: Tool length data	0/1
	aux10 (bit1)	Optional block skip type	Specify whether to enable optional block skipping in the middle of a block. 0: Enable block skipping only at the beginning of a block. 1: Enable block skipping at the beginning of the block and in the middle of a block.	0/1
	aux10 (bit2)	Single block stop timing	Specify the time at which the single block signal is activated. 0: When the signal goes ON while automatic operation is starting, the block stops after it is finished. 1: When the signal is ON at the end of the block, the block stops.	0/1
	aux10 (bit3)	C-axis reference point return type	Specify the C-axis reference point return type. 0: Origin return is performed by the G28 reference point return command or when manual reference point return is activated. The origin dog is used. 1: When the first C-axis command is issued after the C-axis mode is entered in automatic mode, reference point return is performed before execution of the block. Also, reference return is performed by the G28 reference point return command or when manual reference point return is activated. The Z phase of the encoder is used.	0/1
	aux10 (bit4)	S command during constant surface speed	Specify whether to output a strobe signal when the S command is issued in constant surface speed mode. 0: Output no strobe signal in constant surface speed mode. 1: Output strobe signals in constant surface speed mode.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
	aux10 (bit5) Arbitrary allocation of dog signal	Specify whether to enable the arbitrary allocation parameter for the origin dog and H/W OT. 0: Disable arbitrary allocation. (Fixed device) 1: Enable arbitrary allocation. (Device specified by the parameter)	0/1
	aux10 (bit6) Setup and display unit	Specify the unit to be used as the setup/display unit or handle feed unit, the command unit or internal unit. The machining program variables (system variables for coordinate system) are changed simultaneously. 0: Internal unit 1: Unit specified by command Note 1: This parameter is valid only in initial millimeter mode (0 is set in 14041 I_inch). The internal unit is always used in initial inch mode (1 is set in 14041 I_inch). Note 2: This parameter is validated immediately after it is set. Note 3: If addition setting is performed for tool and workpiece offset data with the command unit being inch and internal unit being mm, an error may be generated. Note 4: If "1" is set for this parameter and two systems are used, the operation will follow the unit commanded for each system. Note 5: The internal data is an internal unit determined with #1041 I_inch. Note 6: This parameter is not related to the PLC axis. Related parameter: #1152 I_G20 (Initial command unit)	0/1
	aux10 (bit7) Shorten JOG stop time	Specify whether to shorten the JOG stop time. 0: Do not shorten the JOG stop time. (Same as before) 1: Shorten the JOG stop time.	0/1
1227	aux11 (bit0) Select PLC signal or spindle feedrate attained	Set up this option when disabling the cutting start interlock by spindle feedrate attained. 0: Cutting start interlock by PLC signal 1: Cutting start interlock by spindle feedrate attained	0/1
	aux11 (bit1) Select H or D code	Set up this option to validate the data that is set up on the tool life management screen when issuing the H99 or D99 command. 0: The H and D codes validate the data that is set up on the management setup screen. 1: Validates the data that is set up on the management setup screen when issuing the H99 or D99 command.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)																																								
aux11 (bit2)	Measures against tool setter chattering	Select a condition where a relieving operation completes after measurement with tools. 0: Sensor signals has stopped for 500 ms or longer. 1: 100 μs or longer has passed after sensor signals stopped.	0/1																																								
aux11 (bit3)	Absolute coordinate switching (nose R) [Special display unit compatible]	Select whether to display a tool nose position or coordinate value with the absolute coordinate counter. 0: Displays the tool nose position. 1: Displays the position specified by program command.	0/1																																								
aux11 (bit4)	Program address check	Specify whether to simply check the program address when the machining program is executed. 0: Don't check the program address. 1: Check the program address.	0/1																																								
aux11 (bit5)	Spindle rotation speed clamp	Specify whether to clamp the rotation in constant surface speed mode when the spindle rotation speed clamp command is issued. 0: Clamp the rotation regardless of the constant surface speed mode. 1: Clamp the rotation only in constant surface speed mode.	0/1																																								
aux11 (bit6)	Word edit menu	Select the word edit menu format. Set 0 in this parameter to select the following menu format: <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <table border="1" style="width: 100%; text-align: center;"> <tr> <td>LOOK UP</td> <td>DELETE</td> <td>REPLACE</td> <td>INSERT</td> <td>MENU</td> </tr> <tr> <td>COPY</td> <td></td> <td></td> <td>PROGRAM</td> <td>MENU</td> </tr> <tr> <td>SEARCH</td> <td>B.G. SRH</td> <td>B.G. END</td> <td>COMMENT</td> <td>RETURN</td> </tr> <tr> <td>WORD ↓</td> <td>WORD ↑</td> <td>STR ↓</td> <td>STR ↑</td> <td>RETURN</td> </tr> </table> </div> <p>Set 1 in this parameter to select the following menu format:</p> <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <table border="1" style="width: 100%; text-align: center;"> <tr> <td>COPY</td> <td></td> <td></td> <td>PROGRAM</td> <td>MENU</td> </tr> <tr> <td>LOOK UP</td> <td>DELETE</td> <td>REPLACE</td> <td>INSERT</td> <td>MENU</td> </tr> <tr> <td>SEARCH</td> <td>B.G. SRH</td> <td>B.G. END</td> <td>COMMENT</td> <td>RETURN</td> </tr> <tr> <td>WORD ↓</td> <td>WORD ↑</td> <td>STR ↓</td> <td>STR ↑</td> <td>RETURN</td> </tr> </table> </div>	LOOK UP	DELETE	REPLACE	INSERT	MENU	COPY			PROGRAM	MENU	SEARCH	B.G. SRH	B.G. END	COMMENT	RETURN	WORD ↓	WORD ↑	STR ↓	STR ↑	RETURN	COPY			PROGRAM	MENU	LOOK UP	DELETE	REPLACE	INSERT	MENU	SEARCH	B.G. SRH	B.G. END	COMMENT	RETURN	WORD ↓	WORD ↑	STR ↓	STR ↑	RETURN	0/1
LOOK UP	DELETE	REPLACE	INSERT	MENU																																							
COPY			PROGRAM	MENU																																							
SEARCH	B.G. SRH	B.G. END	COMMENT	RETURN																																							
WORD ↓	WORD ↑	STR ↓	STR ↑	RETURN																																							
COPY			PROGRAM	MENU																																							
LOOK UP	DELETE	REPLACE	INSERT	MENU																																							
SEARCH	B.G. SRH	B.G. END	COMMENT	RETURN																																							
WORD ↓	WORD ↑	STR ↓	STR ↑	RETURN																																							

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
	aux11 (bit7) Switch the range of tool life data to be input (For M system only)	set up the range of tool life data to be input or compared. 0: Inputs or compares all of the data output. 1: Inputs or compares part of the data output 1) Tool life management I data to be input or compared tool number (D), lifetime (E), life count (F), and auxiliary data (B). 2) Tool life management II data to be input or compared Group number (G), method (M), life (E/F), tool number (D), and compensation number (H) Note: When the maintenance function data input/output #(99) () is set, all data will be input and compared.	0/1
1228	aux12 (bit0) Switch coordinate value screen	Set up this option to switch the coordinate value screen. 0: 80-character screen 1: 40-character screen	0/1
	aux12 (bit1) Switch offset and parameter screen	Set up this option to switch the offset and parameter screen to the parameter screen. 0: Displays the offset and parameter screen. 1: Displays the parameter screen.	0/1
	aux12 (bit2) Switch data protection in data transmission mode	Set up the range of data protection in data transmission mode. 0: Protects both send and receive data. 1: Protects receive data only.	0/1
	aux12 (bit3) Nose R specification	Select whether to specify the nose R compensation by shape or wear number. 0: Specifies the nose R compensation by shape number. 1: Specifies the nose R compensation by wear number.	0/1
	aux12 (bit4) Select operation error or stop code	Specify both block cutting start interlock and cutting start interlock as the operation error or stop code. 0: Operation error 1: Stop code	0/1
	aux12 (bit5) Select constant surface speed coordinates	Select constant surface speed coordinates. 0: Workpiece coordinate value 1: Absolute coordinate value	0/1
	aux12 (bit6) Switch relative values displayed	Select whether to preset the relative coordinates with workpiece coordinate preset (G92.1) or counter preset (G92). 0: Preset relative coordinates. 1: Do not preset relative coordinates.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
	aux12 (bit7)	Protection with manual value command Set up this option to protect a manual value command. 0: Does not protect the manual value command (same as before). 1: Protects the manual value command.	0/1
1229	set01 (bit0)	Subprogram interrupt 0: Specifies the user macro interrupt of macro type. 1: Specifies the user macro interrupt of sub-program type.	0/1
	set01 (bit1)	Accurate thread cutting E 0: Address E specifies the number of threads per inch for inch screw cutting. 1: Address E specifies precise reading for inch screw cutting.	0/1
	set01 (bit2)	Radius compensation type B (For M system only) 0: When the start-up and cancel commands are operated during radius compensation, their blocks are not handled by intersection operation processing; they are handled as offset vectors in the direction vertical to that of the commands. 1: When the start-up and cancel commands are operated during radius compensation, the intersection operation processing of the command block and the next block is executed.	0/1
	set01 (bit2)	Nose R compensation type B (For L system only) 0: When the start-up and cancel commands are operated during nose R and radius compensation, their blocks are not handled by intersection operation processing; they are handled as offset vectors in the direction vertical to that of the commands. 1: When the start-up and cancel commands are operated during nose R and radius compensation, the intersection operation processing of the command block and the next block is executed.	0/1
	set01 (bit3)	Initial constant surface speed 0: The initial state after power-ON is a constant surface speed control cancel mode. 1: The initial state after power-ON is a constant surface speed control mode.	0/1
	set01 (bit4)	Synchronous tap 0: Handles the G74 and G84 tap cycles as the tap cycles with a floating tap chuck. 1: Handles the G74 and G84 tap cycles as the tap cycles without a floating tap chuck.	0/1
	set01 (bit5)	Start point alarm Select an operation when the operation start point cannot be found while moving the next block of G117. 0: Enables an auxiliary function after the block has been moved. 1: Outputs a program error (P33) when the operation start point is not found.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)	
	set01 (bit6)	Grid display selection	Select a grid type to be displayed on the servo monitor screen during dog type reference point return. 0: Selects the distance between dog OFF and zero point (including a grid mask amount). 1: Selects a value given by reducing a grid mask amount from the distance between dog OFF and zero point.	0/1
1230	set02 (bit7)	Macro interface input/output for each system	0: The macro interface input/output are shared by the systems. 1: The macro interface input/output are used independently by the systems.	0/1
1231	set03 (bit1)	Switch graphic coordinates	Select whether to draw graphics with the machine coordinate value or the tool position coordinate value (position being machined, obtained by subtracting the tool compensation amount from machine coordinate values) when displaying the trace function. 0: Machine coordinate value (same as conventional method) 1: Tool position coordinate value The counter display and counter name are sequenced with this.	0/1
	set03 (bit2)	Switch graphic check trace	Select whether to draw both the machine coordinate value (tool center path) and tool position coordinate value (program path) or draw only the coordinates selected with switch graphic coordinates (#1231 set03/bit1) when using the program check function. 0: Both machine coordinates and tool position coordinates (same as conventional method) 1: Only coordinates designated with switch graphic coordinates.	0/1
	set03 (bit3)	Hold display range information	Select whether to hold the display range information (drawing position and scale value) for graphic displays. 0: Hold. 1: Do not hold. (Initialize each time ... same as conventional method)	0/1
	set03 (bit4)	Switch zero point mark display position	Select the position for displaying the zero point mark in the graphic display. 0: Machine coordinate zero point (same as conventional method) 1: Workpiece coordinate zero point	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)	
1232	set04 (bit0)	Switch load monitor	Select whether to detect the load with the load monitor's load detection, excluding during acceleration/deceleration. 0: Detect also during acceleration/deceleration. (Conventional) 1: Do not detect during acceleration/deceleration.	0/1
	set04 (bit1)	Program format (IC card)	Select the format of the file output during copying (NC → IC). 0: Add "%" to the head of the file. 1: The head of the file is No. 0.	0/1
1233	set05 (bit1)	Spindle clamp selection	Select whether to validate the spindle override for the spindle speed clamp command (G92 S?). 0: Spindle override invalid 1: Spindle override valid	0/1
1234	set06 (bit6)		Not used.	0/1
	set06 (bit7)	Enable/disable MELDASNET	Enable or disable the MELDASNET function. 0: Enable 1: Disable	0/1
1235	set07 (bit0)	Helical interpolation speed 2	0: Select normal speed designation also for 3rd axis 1: Select arc plane element speed designation	0/1 (MAGIC64)
	set07 (bit1)	File server selection for version upgrade	0: Set upper limit of program file size to 2 gigabytes. 1: Set upper limit of program file size to 16 megabytes.	0/1 (MAGIC64)
	set07 (bit2)	Fixed type chopping compensation valid only at start	When the fixed type compensation value is selected, the method is changed to the compensation value sequential update type after the first four cycles. 0: Method changeover invalid 1: Method changeover valid	0/1
1236	set08 (bit0)	Manual rotation axis feedrate unit	Select the unit of manual rotation axis feedrate. 0: Fixed to [°/min] 1: Same speed as before	0/1
	set08 (bit1)	Spindle speed detection	Select the pulse input source of actual spindle rotation speed output (R18/19) when spindle encoder serial connection (#3025 enc-on: 2) is selected. 0: Serial input 1: Encoder input connector	0/1
	set08 (bit2)	Current limit droop cancel invalid	Set whether to cancel the position droop when the current limit changeover signal is canceled. 0: Cancel droop. 1: Do not cancel droop.	0/1
	set08 (bit7)		Not used.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1237 (PR)	set09 (bit0) External workpiece offset	Set up this function to use the external workpiece coordinates by shifting them to the Z axis. 0: Does not reverse the sign of external workpiece offsets (Z shift) (same as before). 1: Reverses the sign of external workpiece offsets (Z shift). Note: When the sign of external workpiece offsets (Z shift) has been reversed, do not measure those external workpiece offsets. However, the external workpiece offsets can be measured by tool pre-setter.	0/1
	set09 (bit1) Switch PC I/F F modal	The feedrate display for the special display unit is changed. 0: Display as feed per minute. 1: Change between feed per minute and feed per rotation according to the modal state.	0/1
	set09 (bit2) Switch PC I/F T modal	The T command display for the special display unit is changed. (Only L system) 0: Display tool No. (excluding low-order two digits). 1: Display including the compensation No.	0/1
	set09 (bit3) Switch PC I/F remaining distance dwell time display	The dwell time display for the special display unit is changed. 0: Display at feedrate display position. 1: Display at remaining distance display position.	0/1
	set09 (bit4) Switch PC I/F execution program display/ comment display	The display of the program being executed for the special display unit is displayed. 0: Display as searched state, regardless of operation mode. 1: If operation mode and searched program differ, program is not displayed. Comment is displayed for head block search.	0/1
	set09 (bit5) Switch PC I/F modal S	This parameter is for the special display unit I/F. 0: The S command commanded last is returned. 1: When #1039 spinno is 1 The 1st spindle data is returned. When #1039 spinno is 2 If #1199 Sselect for 2nd system is set to 1 with 2nd system setting, the 2nd spindle data is returned. When another command is issued, the 1st spindle data is returned. Note: When using constant surface speed control (G96 modal), the actual rotation speed command is returned.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)	
1238 (PR)	set10 (bit0)	Switch G36 function	If a G code system containing the G36 (automatic tool length measurement X) function is selected, select whether to use G36 for the automatic tool length measurement or arc thread cutting (CCW) function. 0: Automatic tool length measurement 1: Arc thread cutting (CCW)	0/1
	set10 (bit6)		Not used.	0/1
	set10 (bit7)	Switch operation alarm	Select whether to validate the NC alarm 5 (AL5) signal output. 0: NC alarm 5 (AL5) invalid All operation alarms are output to NC alarm 4 (AL4). All operation alarms are recorded in the alarm history. 1: NC alarm 5 (AL5) valid The following operation alarms are not output to NC alarm 4 (AL4). These are output to NC alarm 5 (AL5). The operation alarms output to NC alarm 5 (AL5) are not recorded in the alarm history. <ul style="list-style-type: none"> • External interlock axis found • Cutting override zero • External feedrate zero • Block start interlock • Cutting block start interlock • Cutting interlock for spindle-spindle polygon (G51.2) 	0/1 (Default: 0)
1239 (PR)	set11 (bit0)	Coil switching method	0: Via PLC. (Y2D7) 1: NC internal processing. (Y2D7 is invalid.)	0/1
	set11 (bit1)		Not used.	0/1
	set11 (bit2)		Not used.	0/1
	set11 (bit3)	Polygon machining mode at reset	Select whether to cancel the polygon machining mode when reset is applied. 0: Do not cancel. 1: Cancel.	0/1
	set11 (bit4)	Invalidate G51.1 phase command	Select whether to carry out phase control with the spindle-spindle polygon function. 0: Always validate phase control. * When R is not commanded, it is handled as R0. 1: Validate phase control only at R command	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)	
	set11 (bit5)	Door interlock spindle speed clamp valid	Select whether to validate the spindle clamp speed changeover function by the PLC signal. 0: Invalid 1: Valid	0/1
	set11 (bit6)	External deceleration axis compliance valid	Designate the method for setting the external deceleration speed. 0: Set speed common for all axes (#1216 extdcc external deceleration speed) 1: Set speed for each axis (#2086 exdcax external deceleration speed)	0/1
	set11 (bit7)	APLC software working environment setting	0: Run the APLC software with the ROM. 1: Run the APLC software with the RAM.	0/1
1240 (PR)	set12 (bit0)	Handle input pulse	Select the handle input pulse. 0: MELDAS standard handle pulse 1: Handle 400 pulse	0/1
	set12 (bit1)	Megatorque motor handle feed magnification	Select the magnification of megatorque motor handle 1 pulse. 0: Double the handle 1 pulse magnification specified by the handle feed magnification signal (Y2C0 to Y2C2). 1: Use the handle 1 pulse magnification specified by the handle feed magnification signal (Y2C0 to Y2C2) as is.	0/1
	set12 (bit2)	Zero point shift amount magnification	If "1" is set, the following magnification will be applied on the #2027 G28sft reference point shift amount, #2057 zero point proximity + and #2058 zero point proximity - settings. For 0.1 μ m : 10-fold For 0.01 μ m: 100-fold	0/1

5. BASE SPECIFICATIONS PARAMETERS

(SETUP PARAM 1. 9/15)

#	Items	Details	Setting range (unit)	
1265 (PR)	ext01 (bit0)	Command format 1	Select the command format for the fixed cycle for compound lathe. 0: Conventional format 1: MELDAS special format (1 block command method)	0/1
	ext01 (bit1)	Command format 2	Select the command format for the lathe fixed cycle. 0: Conventional format 1: MELDAS special format	0/1
	ext01 (bit2)	Command format 3	Select the command format for the hole drilling fixed cycle. 0: Conventional format 1: MELDAS special format	0/1
1266 (PR)	ext02		Not used.	
1267 (PR)	ext03 (bit0)	G code type	Select the high-speed high-accuracy G code type. 0: Conventional format 1: F format	0/1
1268 (PR)	ext04		Not used.	
1269 (PR)	ext05		Not used.	
1270 (PR)	ext06 (bit7)	Handle C axis coordinate during cylindrical interpolation	Specify whether the rotary axis coordinate before the cylindrical interpolation start command is issued is kept during the cylindrical interpolation or not. 0: Do not keep 1: keep	0/1
1271 (PR)	ext07 (bit0)	Mirror image operation	Select the type of mirror image operation. (Applicable only to M65 and M66) 0: Type 1 - The program mirror image, external mirror image, and parameter mirror image are exclusive to each other. - An increment command moves the image to the position indicated by the move amount with the sign inverted. 1: Type 2 - Mirror image operation is enabled when the program mirror image (G51.1) command is issued or when the external signal or parameter is ON. - An increment command moves the image to the position determined by applying the mirror image to the absolute program coordinates.	0/1 (Default: 0)

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
ext07 (bit1)	Address specifying fixed cycle repetition count (For M system only)	Specify the address that specifies the fixed cycle repetition count. (Applicable only to M65 and M66) 0: Address L only 1: Addresses K and L If addresses K and L are specified simultaneously, the data at address K is used for operation.	0/1 (Default: 0)
ext07 (bit2)	F-command unit	Specify the unit to be used if a thread cutting read command contains on decimal point. (Applicable only to M65 and M66) 0: Type 1 (conventional specifications) F1 → 1 mm/rev, 1 inch/rev 1: Type 2 F1 → 0.01 mm/rev, 0.0001 inch/rev	0/1 (Default: 0)
ext07 (bit3)	G-code group for unidirectional positioning (for M system only)	Specify the G-code group for unidirectional positioning. (Applicable only to M65 and M66) 0: Unmodal G code (group 00) 1: Modal G code (group 01) Related parameter: #8209 G60 SHIFT (Set the last positioning direction and distance for each axis applicable when the unidirectional positioning command is issued.)	0/1
ext07 (bit4)	Operation by independent G40 command	Specify the mode of canceling radius compensation vector by the independent G40 command. (Applicable only to M65 and M66) (Default: 0) 0: Type 1 (conventional specifications) The independent G40 command cancels the radius compensation vector. 1: Type 2 The radius compensation vector is not canceled by the independent G40 command but is canceled by the next move command for the radius compensation plane.	0/1 (Default: 0)
ext07 (bit5)	Cut start position (For L system only)	Specify the position from where cutting begins in a fixed cycle for compound lathe. 0: Conventional specifications The cut start position is determined by the final shaping program. 1: Extended specifications The cut start position is determined from the cycle start point.	0/1 (Default: 0)

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
	ext07 (bit6) Nose R compensation (For L system only)	Specify whether to apply nose R compensation to shapes in a rough cutting cycle. 0: Conventional specifications If nose R compensation is enabled for the final shaping program, the shape obtained after applying nose R compensation to the final shaping program is used as the rough cutting shape. 1: Extended specifications The shape made by the final shaping program, without nose R compensation, is used as the rough cutting shape.	0/1 (Default: 0)
	ext07 (bit7) Cut amount (For L system only)	Specify the operation to be performed when the program-specified cut amount exceeds the cut amount of the final shaping program. 0: Conventional specifications A program error occurs if the program-specified cut amount exceeds the cut amount of the final shaping program. 1: Extended specifications Rough cutting is performed by one cut if the program-specified cut amount exceeds the cut amount of the final shaping program.	0/1 (Default: 0)
1272 (PR)	ext08 (bit0) Switch pocket machining operation	0: Conventional specifications Pocket machining is selected with the H designation. The pull direction when pocket machining is ON is the Z direction. 1: Extended specifications If there is an X and Z axis in the first movement block after the finished shape start block is started, pocket machining will start. The pull direction when pocket machining is ON is the X direction.	0/1
	ext08 (bit1) M function synchronous tap cycle	Specify whether to enable the M function synchronous tap cycle. 0: Invalid 1: Valid	
	ext08 (bit2) Spiral/conical interpolation command format 2	Select the command format for spiral interpolation and conical interpolation. 0: Type 1 (conventional specifications) 1: Type 2 (spiral speed L designation, increment designation)	0/1
	ext08 (bit3) Switch macro call function	Select whether to shift the argument to the subprogram if nests are overlapped when per block call (G66.1) is commanded. 0: Shift argument even if nests are overlapped. 1: Do not shift arguments if nests differ. (Conventional specifications)	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)	
ext08 (bit4)	Tap cycle selection	Select the tap cycle. 0: Pecking tap cycle 1: Deep hole tap cycle	0/1	
ext08 (bit5)	Deep hole tap cycle override selection	Select whether to validate override on the pulling operation during synchronized tapping with the deep hole tap cycle. 0: Invalid 1: Valid	0/1	
ext08 (bit6)	Switch corner chamfering/corner R command format	The corner chamfering/corner R command format is extended. 0: Command format I (conventional format) Issue a command with comma (,C and ,R). 1: Command format II In addition to command format I, commands can be issued with an address that does not have a comma. Corner chamfering: I/K or C, corner R: R	0/1	
ext08 (bit7)	Return position after macro interrupt in fixed cycle selection	Select the destination to return to after a macro interrupt in the fixed cycle. 0: Return to block in fixed cycle. 1: Return to block after fixed cycle.	0/1	
1273 (PR)	ext09 (bit0)	Switch ASIN calculation results range	Select the ASIN calculation results range. 0: -90° to 90° 1: 90° to 270°	0/1
	ext09 (bit1)	Switch system variable unit	Select the unit for the system variable #3002 (time during automatic start). 0: 1ms unit 1: 1 hour unit	0/1
	ext09 (bit2)	Switch G71, G72, G73 cutting direction judgment	Select whether to determine the cutting direction with the finished shape, or according to the commanded finishing allowance and cutting allowance when the longitudinal rough cutting cycle (G71), face rough cutting cycle (G72) or closed loop cutting cycle (G73) is commanded. 0: Conventional specifications Determined according to the finished shape program. 1: Extended specifications Determined according to the finishing allowance and cutting allowance commanded in the program.	0/1
	ext09 (bit3)	Facing turret mirror image coordinate value type	Select the coordinate values of the axis for which facing turret mirror image is valid. 0: Move axis in same direction as machine value. 1: Move axis in direction opposite machine value.	0/1
	ext09 (bit4)	Facing turret mirror image valid axis selection	Select the axis for which facing turret mirror image is valid. 0: Fixed to 1st axis. 1: Determined according to plane selected when facing turret mirror image is commanded.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1274 (PR)	ext10 (bit7) Word range check	Select whether to check that the operation expression of the word date in the program is enclosed in brackets ([]) when the machine program is executed. This check is also applied to the 08000 to 09999 and the machine manufacture macro program. 0: Check valid 1: Check invalid	0/1
1275 (PR)	ext11	Not used.	
1276 (PR)	ext12	Not used.	
1277 (PR)	ext13 (bit0) Tool life management II count type 2	Specify how and when the mount or use count is incremented in tool life management II. 0: Type 1 The count is incremented when the spindle is used for cutting. 1: Type 2 The count is incremented for the tool used or mounted for one program. The increment is enabled by resetting.	0/1 (Default: 0)
1278 (PR)	ext14 (bit0) Program restart method selection	Select the program restart method. 0: Conventional format 1: F format	0/1
1279 (PR)	ext15 (bit0) System synchroniza- tion method	Select the system synchronization method. 0: If one system is not in automatic operation, ignore the synchronization command and execute the next block. 1: Operate according to the synchronization ignore signal. If the synchronization ignore signal is set to "1", the synchronization command will be ignored. When set to "0", synchronization will be applied.	0/1
	ext15 (bit1) Interrupt amount during machine lock	Select the manner to handle the interruption amount during machine lock. 0: Cancel when reset. 1: Do not cancel when reset. Instead cancel during manual zero point return.	0/1
	ext15 (bit2) Selection of cutting start interlock target block	Select whether the cutting start interlock is valid for successive cutting blocks. 0: Valid for successive cutting blocks. 1: Invalid for successive cutting blocks.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#		Items	Details	Setting range (unit)
1280 (PR)	ext16 (bit0)	I/F per axis during cross machining control	<p>Set the handling of the following PLC I/F for axes interchanged with cross machining control.</p> <ul style="list-style-type: none"> • Mirror image • Manual/automatic interlock • Manual/automatic machine lock <p>0: Follows axis configuration before cross machining control. 1: Follows axis configuration after cross machining control.</p> <p>(Example) Set as follows for the automatic interlock (+) device for X1 when carrying out cross machining with the 1st axis (X1) in the 1st system and 1st axis (X2) in the 2nd system. Setting value 0: Y1A8 (I/F for 1st axis in 1st system) Setting value 1: W28 (I/F for 1st axis in 2nd system)</p> <p>Note: If the number of axes in the system changes with cross machining, the I/F of the target axis may change when this parameter is set to "1".</p> <p>(Example) When 1st system's C axis is moved to 2nd system with a 1st system (X, Z, C, Y) and 2nd system (X, Z) configuration: When setting value is 1: W2A, W12 and W4A, etc., will be the I/F for the C axis moved to the 2nd system. However, Y192, Y1AA and Y1CA, etc., will change to the I/F of the Y axis in the 1st system because the axes following the removed C axis (third place) are shifted up.</p>	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1280 (PR)	ext16 (bit1) Cross machining control cancel with reset	Select whether to cancel the cross machining control when reset is applied. 0: Cancel cross machining control with reset. 1: Do not cancel cross machining control with reset	0/1
	ext16 (bit2) Interchange coordinate value display	Set whether to interchange (or move) the coordinate values when displaying. This setting will be followed when the axes are interchanged and when the axes are moved. 0: Interchange (or move) coordinate values with cross machining control, and display. 1: Display coordinate values for cross machining control without interchanging (or moving). (Example)When 1st system's C axis is moved to 2nd system with a 1st system (X, Z, C, Y) and 2nd system (X, Z) configuration: 1st system: X, Z and Y coordinate values are displayed. 2nd system: X, Z and C coordinate values are displayed.	0/1
	ext16 (bit3) Reset operation for synchroniza- tion/super- imposition control	Select whether to cancel synchronization/superimposition control with resetting. 0: Cancel. 1: Do not cancel.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1281 (PR)	ext17 (bit0) Zero point return operation changeover parameter	<p>(Zero point setting operation) The "Operation error 1036" will occur regardless of this parameter, and regardless of manual or automatic operation.</p> <p>(High-speed zero point return) 0: <During manual operation> The master axis and slave axis will simultaneously start zero point return. Even if one of the axes reaches the zero point, the other axis will continue to move until it reaches the zero point. Thus, if the difference of the master axis and slave axis feedback position before zero point return is larger than the tolerable synchronization error amount, the error "Operation error 0051" will occur during zero point return.</p> <p><During automatic operation> The master axis and slave axis will simultaneously start zero point return. When the master axis reaches the zero point, the slave axis will stop. Thus, the positional relation of the master axis and slave axis established before zero point return is maintained.</p> <p>1: <During manual operation> <During automatic operation> The master axis and slave axis will simultaneously start zero point return. When the master axis reaches the zero point, the slave axis will stop. Thus, the positional relation of the master axis and slave axis established before zero point return is maintained.</p>	0/1
	ext17 (bit1) Tool offset addition axis selection	<p>0: Follows TchG34 1: Plane selection Base J setting name is set as the 3rd axis compensation axis.</p>	0/1
1282 (PR)	ext18	Not used.	
1283 (PR)	ext19	Not used.	
1284 (PR)	ext20 (bit0) Spindle speed clamp check	<p>Select whether to check the spindle speed clamp under the constant surface speed control.</p> <p>0: Check the spindle speed clamp. 1: Not check the spindle speed clamp.</p> <p>(Note) This parameter is enabled when the parameter "#1146 Sclamp" is set to "1". (Applicable only to M65V series and M64 C version series)</p>	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)	
1285 (PR)	ext21 (bit0)	Multi-system program generation and operation	0: When a machining program is newly registered, it is registered as a program for the selected system. 1: When a program is newly registered, a system common program No. is generated unconditionally. If there are no contents in the subprogram when a subprogram is called during automatic operation, the program will be searched for and executed from \$1.	0/1
	ext21 (bit1)	Changeover of method to select operation program	0: Select the program in the selected system with operation search. 1: Select a common system program with operation search. (A common system program No. will be selected.)	0/1
1286 (PR)	ext22 (bit0)	Program input/output method selection	0: Only the programs in the selected system are input/output. 1: The designated programs are output for all systems. The systems are delimited with the "\$" mark. The programs delimited with the \$ mark are assigned and input into each system. (If the program does not have a \$ mark, it will be handled as system 1.)	0/1
	ext22 (bit1)		Not used.	
	ext22 (bit2)	0 No. for program input No.	Select the action to be taken when the same program No. is input during data input. 0: The 0 No. when the same 0 No. is input successively is handled as a character string data. 1: The 0 No. is handled as a program No. when the same 0 No. is input successively. Whether to overwrite the program or cause an error is set with #1218 bit 7 "Input by program overwrite".	0/1
	ext22 (bit3)	No 0 No. at machining program input	This setting enables the machining program input even if there is no program No. (0 No.). The program No. is fixed to 01 in this case. 0: Input disabled 1: Input enabled	0/1
1287 (PR)	ext23 (bit0)	Workpiece coordinate display	Select the mode of displaying the workpiece coordinate counter. 0: Don't update the display immediately after workpiece coordinate data is changed. 1: Update the display immediately after workpiece coordinate data is changed.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
ext23 (bit3)	Counter display expanded function selection	0: Display the command value that does not consider the tool length offset amount or workpiece coordinate offset amount. 1: The counter display expanded function is validated. (bit4 to bit7)	0/1 (Version D, M65)
ext23 (bit4)	Relative coordinate display	(M system) 0: Display the actual position including tool length offset. 1: Display the machining position in terms of a program command excluding tool length offset. (L system) 0: Display the actual position including tool shape compensation. 1: Display the machining position in terms of a program command excluding tool shape compensation.	0/1 (Version D, M65)
ext23 (bit5)	Relative coordinate display	(M system) 0: Display the actual position including tool radius compensation. 1: Display the machining position in terms of a program command excluding tool radius compensation. (L system) 0: Display the actual position including nose R compensation. 1: Display the machining position in terms of a program command excluding nose R compensation.	0/1 (Version D, M65)
ext23 (bit6)	Absolute coordinate display [Special display unit compatible]	(M system) 0: Display the actual position including tool length offset. 1: Display the machining position in terms of a program command excluding tool length offset. (L system) 0: Display the actual position including tool shape compensation. 1: Display the machining position in terms of a program command excluding tool shape compensation.	0/1 (Version D, M65)

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
	ext23 (bit7) Absolute coordinate display [Special display unit compatible]	(M system) 0: Display the actual position including tool radius compensation. 1: Display the machining position in terms of a program command excluding tool radius compensation. (L system) 0: Display the actual position including nose R compensation. 1: Display the machining position in terms of a program command excluding nose R compensation. With the L system, the effect onto the nose R compensation's absolute coordinate counter is also affected by the L system coordinate changeover parameter (#1227 aux11/bit 3 absolute coordinate changeover (nose R)). In actual use, if this parameter is set to 1, or if #1227 aux 11/bit 3 is set to 1, the position in the program commands will be displayed with the absolute coordinate counter.	0/1 (Version D, M65)
1288 (PR)	ext24 (bit0) MDI program clear	Select whether to initialize the MDI buffer when MDI operation ends, the power is turned ON again, reset is input, or emergency stop is canceled. 0: Do not clear programs registered with MDI. 1: Clear programs registered with MDI, and save only % programs.	0/1
1289 (PR)	ext25	Not used.	
1290 (PR)	ext26	Not used.	
1291 (PR)	ext27	Not used.	
1292 (PR)	ext28	Not used.	
1293 (PR)	ext29	Not used.	
1294 (PR)	ext30	Not used.	
1295 (PR)	ext31	Not used.	
1296 (PR)	ext32	Not used.	
1297 (PR)	ext33	Not used.	
1298 (PR)	ext34	Not used.	

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1299 (PR)	ext35		Not used.
1300 (PR)	ext36 (bit0)	Multiple spindle control II	Select multiple spindle control I or II. 0: Multiple spindle control I 1: Multiple spindle control II (select from ladder)
	ext36 (bit7)	Spindle synchronization command method	Select the spindle synchronization command method. 0: Spindle synchronization with PLC I/F 1: Spindle synchronization with G command

5. BASE SPECIFICATIONS PARAMETERS

(SETUP PARAM 1. 10/15)

#	Items	Details	Setting range (unit)
1301	nrfchk Origin neighboring check method	Select the high-speed check method of the origin neighboring signal. 0: Do not check positions near the origin at high speeds. (Conventional specifications) 1: Check positions near the origin at high speeds using command machine positions. 2: Check positions near the origin at high speeds using detector feedback positions.	0 to 2
1302	AutoRP Automatic return by program restart	0: Return the system to the restart position manually and then restart the program. 1: For program restarting, the first activation automatically moves the system to the restart position.	0/1
1303 (PR)	V1comN No. of #100 address system common variables	Set the number of common variables common for the system starting from address #100.	0 to 100
1304 (PR)	V0comN No. of #500 address system common variables	Set the number of common variables common for the system starting from address #500.	0 to 500
1305	corjug Corner deceleration tangent judgment	Select whether to judge corner deceleration with a polygon shape or tangent during helical interpolation and spiral interpolation. 0: Polygon judgment Helical interpolation is interpreted as polygonal, and the corner deceleration is judged with the approximate vector. 1: Tangent judgment The vector is calculated from the center of the helical interpolation, the start point and the end point, and corner deceleration is judged.	0/1
1306	InpsTyp Deceleration check specification type	Select the parameter specification type for the G0 or G1 deceleration check. 0: Deceleration check specification type 1 G0 is specified with "#1193 inpos", and G1+G9 with "#1223 aux07/BIT1". 1: Deceleration check specification type 2 G0 or G1+G9 is specified with "#1193 inpos".	0/1
1310	WtMmin Minimum value for synchronization M code	Set the minimum value for the M code. When "0" is set, the synchronization M code will be invalid.	0, 100 to 99999999

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1311	WtMmax Maximum value for synchronization M code	Set the maximum value for the M code. When "0" is set, the synchronization M code will be invalid.	0, 100 to 99999999
1312	T_base Tool life management standard number	When the T code command is issued while specifying a value that exceeds the value set in this parameter, the value obtained by subtracting the set value from the command value is used as the tool group number for tool life management. The value specified by the T code command is equal to or less than the value set in this parameter, the T code is handled as a normal T code and not subjected to tool life management. When 0 is set in this parameter, the T code command always specifies a group number. (This parameter is valid for M-system tool life management II.)	0 to 9999
1313	TapDw1 Synchronous tap hole bottom wait time	Specify the hole bottom wait time for synchronous tapping. When the P address is specified, the greater value is used as the hole bottom wait time. When an in-position check is performed at the hole bottom, dwelling for the specified time is completed after the in-position check is complete. (Applicable only to the M64 D version series) Note: This parameter is valid only when 1 is set in #1223 aux07 bit 3 (synchronous tap in-position check improvement).	0 to 999 (ms)
1314	TapInp Synchronous tap in-position check width (tap axis)	Specify the hole bottom in-position check width for synchronous tapping. (Applicable only to the M64 D version series) Note: This parameter is valid only when 1 is set in #1223 aux07 bit 3 (synchronous tap in-position check improvement).	1 to 32767 (1μm steps)
1324	Chop_R Chopping compensation value fixing method	Head number of the R register used as the compensation amount save area during fixed compensation amount method.	1900 to 2782

5. BASE SPECIFICATIONS PARAMETERS

(SETUP PARAM 1. 11/15)

#	Items	Details	Setting range (unit)	
1501	polyax (For L system only)	Rotational tool axis number	Specify the number of the rotational tool axis (servo axis) used for polygon machining (G51.2). Set 0 when not using polygon machining (spindle-servo axis), or when using spindle-spindle polygon machining. A value exceeding the base specification parameter #1002 axisno cannot be specified. This parameter is valid when the G code system is 6 or 7 (7 or 8 is set in base specification parameter #1037 cmdtyp).	0 to controlled axis number
1502	G0lpfg	G1 → G0 deceleration check	0: Do not perform a deceleration check when the move direction is changed from G1 to G0. 1: Perform a deceleration check when the move direction is changed from G1 to G0. (Applicable only to the M64 D version series)	0/1
1503	G1lpfg	G1 → G1 deceleration check	0: Do not perform a deceleration check when the move direction is changed from G1 to G1. 1: Perform a deceleration check when the move direction is changed from G1 to G1. (Applicable only to the M64 D version series)	0/1
1505	ckref2	Second origin return check	Specify the trigger for a check at the specified position in manual second original return mode. 0: Completion of spindle orientation 1: Generation of second origin return interlock signal	0/1
1506	F1_FM	Upper limit of F1 digit feedrate	Specify the maximum value up to which the F1 digit feedrate can be changed. (Applicable only to M65 and M66)	0 to 60000 (mm/min)
1507	F1_K	F1 digit feedrate change constant	Specify the constant that determines the speed change rate per manual handle graduation in F1 digit feedrate change mode. (Applicable only to M65 and M66)	0 to 32767
1510	DOOR_H	Shorten door interlock II axis stop time	Specify whether to shorten the time during which the axis is stopped when the door is opened. 0: Use the conventional axis stop time. 1: Shorten the axis stop time. Note: When the door interlock II signal is input via a ladder, the conventional axis stop time is used.	0/1
1511	DOORPm	Signal input device 1 for door interlock II: for each system	Specify the fixed device number (X??) for door interlock II signal input for each system. A device number from X01 to XFF can be specified. Device number 000 is invalid. Specify device number 100 when using no fixed device number for door interlock II signal input. Related parameter: #1154 pdoor (Door interlock II for each system)	000 to 100 (hexadecimal)

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)	
1512	DOORPs	Signal input device 2 for door interlock II: for each system	Specify the fixed device number (X??) for door interlock II signal input for each system. (Specify the same value as that of #1155.) Related parameter: #1154 pdoor (Door interlock II for each system)	000 to 100 (hexadecimal)
1513	stapM	M code for synchronous tap selection	Select the synchronous tap mode using the miscellaneous function code of the value set in this parameter. The M function command can be issued immediately before the tap command or in the same block. This function is valid only when 1 is set in #1272 ext08/bit 1 (Enable/disable M-function synchronous tap cycle). Note: Do not use M00, 01 02, 30, 98, and 99.	0 to 99999999
1514	expLinax	Exponential function interpolation linear axis	Set the axis address name for the linear axis used in exponential function interpolation.	A to Z
1515	expRotax	Exponential function interpolation rotary axis	Set the axis address name for the rotary axis used in exponential function interpolation.	A to Z
1516	mill_ax	Milling axis name	Set the name of the rotary axis used in milling interpolation. Only one rotary axis can be set. When there is no E command in issuing the G12.1 command, this parameter will be followed.	A to Z
1517	mill_C	Milling interpolation hypothetical axis name	Select the hypothetical axis command name for milling interpolation. When there is no D command in issuing the G12.1 command, this parameter will be followed. 0: Y axis command 1: Command rotary axis name.	0/1
1518	polm	Spindle-spindle polygon Workpiece spindle No.	Set the number of the workpiece spindle used in spindle-spindle polygon machining. Note: The 1st spindle will be selected when "0" is set.	0 to number of spindles
1519	pols	Spindle-spindle polygon Tool spindle No.	Set the number of the tool spindle used in spindle-spindle polygon machining. Note: The 2nd spindle will be selected when "0" is set.	0 to number of spindles
1520 (PR)	Tchg34	Additional axis tool compensation operation	Select whether to carry out the additional axis' tool compensation function with the 3rd axis or 4th axis. 0: Select 3rd axis. 1: Select 4th axis.	0/1
1521	C_min	Minimum turning angle	Set the minimum turning angle of the normal line control axis at the block joint during normal line control.	0.000 to 360.000 (°)

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1522 (PR)	C_axis Normal line control axis	Set the number of the axis for normal line control. Designate a rotary axis.	0: Normal line control disabled 1 to 6: Axis No. (number of control axes)
1523	C_feed Normal line control axis turning speed	This is valid with normal line control type I. Designate the turning speed of the normal line control axis at the block joint during normal line control. Set a value that does not exceed the normal line control axis' clamp speed (#2002 clamp).	0 to 1000000 (°/min)
1524	C_type Normal line control type	Set the normal line control type.	0: Normal line control type I 1: Normal line control type II
1525	laxlen L axis length	Special function	
1526	raxlen R axis length	Special function	
1527	flclen Distance between support points	Special function	
1528	rflch R point support point height	Special function	
1529	laxcmp L axis compensation amount	Special function	
1530	raxcmp R axis compensation amount	Special function	
1531	flccmp Distance between support point compensation amount	Special function	
1532	G01rsm G00 L/R interpolation simultaneous reach	Special function	
1533	millPax Pole coordinate linear axis name	Set the linear axis used for pole coordinate interpolation.	Control axis address such as X, Y or Z

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)																								
1534	SnG44.1 Spindle No. for G44.1 command	Set the selected spindle No. for the G44.1 command. <table border="1" style="margin-left: 20px;"> <thead> <tr> <th>#1199</th> <th>#1534</th> <th>Selected spindle</th> </tr> </thead> <tbody> <tr> <td>0:G43.1</td> <td>Not used.</td> <td>1st spindle</td> </tr> <tr> <td>1:G44.1</td> <td>0</td> <td>2nd spindle</td> </tr> <tr> <td></td> <td>1</td> <td>1st spindle</td> </tr> <tr> <td></td> <td>2</td> <td>2nd spindle</td> </tr> <tr> <td></td> <td>3</td> <td>3rd spindle</td> </tr> <tr> <td></td> <td>4</td> <td>4th spindle</td> </tr> <tr> <td>2:G47.1</td> <td>Not used.</td> <td>All spindles</td> </tr> </tbody> </table>	#1199	#1534	Selected spindle	0:G43.1	Not used.	1st spindle	1:G44.1	0	2nd spindle		1	1st spindle		2	2nd spindle		3	3rd spindle		4	4th spindle	2:G47.1	Not used.	All spindles	0: 2nd spindle 1: 1st spindle 2: 2nd spindle 3: 3rd spindle 4: 4th spindle If a spindle that does not exist is set, the 2nd spindle will be used. Note that if there is only one spindle, the 1st spindle will be used.
#1199	#1534	Selected spindle																									
0:G43.1	Not used.	1st spindle																									
1:G44.1	0	2nd spindle																									
	1	1st spindle																									
	2	2nd spindle																									
	3	3rd spindle																									
	4	4th spindle																									
2:G47.1	Not used.	All spindles																									
1535	C_leng Minimum turning movement amount	Set the minimum turning movement amount of the normal line control axis at the block joint during normal line control.	0.000 to 99999.999 (mm)																								
1537 to 1544	crsax[1] to crsax[8] Cross machining control axis	Set the axis to be interchanged during cross machining control. Using two digits, set the name of the axis interchanged with that where the cross machining control request signal is input, or that moves to the position where the signal is input.	Two digits between A to Z and 1 to 9 (Setting is cleared when 0 is set)																								

(SETUP PARAM 1. 12/15)

#	Items	Details	Setting range (unit)
1549	lv0vr1 Override 1 start curvature radius	Set the override 1 start curvature radius for executing involute interpolation with the high-speed high-accuracy II mode.	0.001 to 99999.999 (mm)
1550	lv0vr2 Override 2 start curvature radius	Set the override 2 start curvature radius for executing involute interpolation with the high-speed high-accuracy II mode.	0.001 to 99999.999 (mm)
1551	lv0vr3 Override 3 start curvature radius	Set the override 3 start curvature radius for executing involute interpolation with the high-speed high-accuracy II mode.	0.001 to 99999.999 (mm)
1552	lv0vr4 Override 4 start curvature radius	Set the override 4 start curvature radius for executing involute interpolation with the high-speed high-accuracy II mode.	0.001 to 99999.999 (mm)
1553	lv0vr5 Override 5 start curvature radius	Set the override 5 start curvature radius for executing involute interpolation with the high-speed high-accuracy II mode.	0.001 to 99999.999 (mm)
1554	lv0rd2 Involute interpolation override 2	Set the override value at the curvature radius lv0vr2 for executing involute interpolation with the high-speed high-accuracy II mode. Note: If the override value is not set (setting value: 0), the setting will be invalid, and the override will be 100%.	1 to 100 (%)

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1555	Iv0rd3	Involute interpolation override 3 Set the override value at the curvature radius Iv0vR3 for executing involute interpolation with the high-speed high-accuracy II mode. Note: If the override value is not set (setting value: 0), the setting will be invalid, and the override will be 100%.	1 to 100 (%)
1556	Iv0rd4	Involute interpolation override 4 Set the override value at the curvature radius Iv0vR4 for executing involute interpolation with the high-speed high-accuracy II mode. Note: If the override value is not set (setting value: 0), the setting will be invalid, and the override will be 100%.	1 to 100 (%)
1557	Iv0rd5	Involute interpolation override 5 Set the override value at the curvature radius Iv0vR5 for executing involute interpolation with the high-speed high-accuracy II mode. Note: If the override value is not set (setting value: 0), the setting will be invalid, and the override will be 100%.	1 to 100 (%)
1558	Iv0Min	Involute interpolation override lower limit value Set the lower limit value of the involute interpolation override. Note: If the override value is not set (setting value: 0), the setting will be invalid, and the override will be 100%.	1 to 100 (%)
1559	IvAMax	Involute interpolation maximum acceleration rate Set the maximum acceleration rate of the constant acceleration control for executing involute interpolation with the high-speed high-accuracy II mode. Note: If this parameter is not set (setting value: 0), the setting will be invalid, and the normal acceleration rate (#1207 G1btL) will be applied.	1 to 32767 (ms)
1560	IvFMin	Involute interpolation minimum feedrate Set the minimum feedrate of the constant acceleration control for executing involute interpolation with the high-speed high-accuracy II mode. (Valid when executing compensation with the accuracy coefficient.) Note: If this parameter is not set (setting value: 0), the feedrate will not be clamped.	1 to 32767 (ms)
1571	SSSdis	SSS control adjustment coefficient fixed value selection The shape recognition range for SSS control is fixed.	0/1

5. BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
1572	Cirorp Arc command overlap	Fluctuation of the speed at the arc and linear or arc and arc joints will be eliminated during the high-speed high-accuracy II mode. 0: Do not overlap arc command blocks. 1: Overlap arc command blocks. (Eliminate the speed fluctuation) Note: This parameter is invalid during SSS control.	0/1

(SETUP PARAM 1. 13/15)

#	Items	Details	Setting range (unit)
1801	Hacc_c	Arc radius clam acceleration	-99999999 to +99999999
1802	Macc_c	Acceleration check at middle speed	-99999999 to +99999999
1803	Lacc_c	Acceleration check at low speed	-99999999 to +99999999
1811	Hcof_A	X-axis high acceleration coefficient β	-99999999 to +99999999
1812	Hcof_B	X-axis high acceleration coefficient α	-99999999 to +99999999
1813	Mcof_A	X-axis middle acceleration coefficient β	-99999999 to +99999999
1814	Mcof_B	X-axis middle acceleration coefficient α	-99999999 to +99999999
1815	Lcof_A	X-axis low acceleration coefficient β	-99999999 to +99999999
1816	Lcof_B	X-axis low acceleration coefficient α	-99999999 to +99999999
1817	mag_C	X-axis change magnification θ [%] Set 0 when no compensation or change is executed.	-99999999 to +99999999
1821	Hcof_A	Y-axis high acceleration coefficient β	-99999999 to +99999999
1822	Hcof_B	Y-axis high acceleration coefficient α	-99999999 to +99999999
1823	Mcof_A	Y-axis middle acceleration coefficient β	-99999999 to +99999999
1824	Mcof_B	Y-axis middle acceleration coefficient α	-99999999 to +99999999
1825	Lcof_A	Y-axis low acceleration coefficient β	-99999999 to +99999999
1826	Lcof_B	Y-axis low acceleration coefficient α	-99999999 to +99999999
1827	mag_C	Y-axis change magnification θ [%] Set 0 when no compensation or change is executed.	-99999999 to +99999999

5. BASE SPECIFICATIONS PARAMETERS

(SETUP PARAM 1. 14/15)

#	Items	Details	Setting range (unit)
1901 (PR)	station addr	Set up a station address number (the NC is the n-th slave station).	1 to 7
1902 (PR)	Din size	Set up the size of the data to be transferred from the PC to the NC (from the master station to the slave station) in bytes (8 points).	0 to 32 (bytes (8 bits))
1903 (PR)	Dout size	Set up the size of the data to be transferred from the NC to the PC (from the slave station to the master station) in bytes (8 points).	0 to 32 (bytes (8 bits))
1904 (PR)	data length	Set up the data length of a character.	0 to 2: 7 bits 3 : 8 bits
1905 (PR)	baud rate	Set up a data transfer rate. The transfer rate differs according to operation clock rates	Clock: 6 MHz/ 10 MHz 0: 38400 / 57600 1: 19200 / 28800 2: 9600 / 14400 3: 4800 / 7200 4: 2400 / 3600 5: 1200 / 1800 6: 600 / 900 (bps)
1906 (PR)	stop bit	Set up the stop bit length.	0 and 1: 1 bit 2 and 3: 2 bits
1907 (PR)	parity check	Select whether to make a parity check.	0: Invalid 1: Valid
1908 (PR)	even parity	Select the odd or even parity bit. If no parity check is specified, this parameter is ignored.	0: Odd parity 1: Even parity
1909 (PR)	Tout (ini)	(ini) specifies a time-out from when the connection check sequence finishes to when the first usual sequence (input) finishes.	0 to 999 (0.1 s)
1910 (PR)	(run)	(run) specifies a time-out from when the NC (slave station) outputs usual sequence data to when the next usual sequence data is input. If the time-out is exceeded, an emergency stop occurs and the system waits for the preparation sequence to start. If the set value is 0, no time-out occurs or no communication stop can be detected.	
1911 (PR)	clock select	Select an operation cycle.	0: 6 MHz 1: 10 MHz

5. BASE SPECIFICATIONS PARAMETERS

(SETUP PARAM 1. 15/15)

#	Items		Details	Setting range (unit)
1925	EtherNet	Start of service	Start or stop the Ethernet communication function. 0: Stop 1: Start	0/1
1926	IP address	IP address	Specify the NC IP address	Set these parameters in accordance with the network rules in the connection environment.
1927	Subnet mask	Subnet mask	Specify the subnet mask.	
1928	Gateway address	Gateway	Specify the gateway IP address.	
1929	Port number	Port No.	Set the port No. for the service function.	1 to 9999 (Set 2000 when not connected to the Ethernet.)
1930	Host address	Host address	Set the host's IP address.	1 to 255
1931	Host number	Host No.	Set the host's port No.	1 to 9999

(Note) Always set #1925 to #1931 when the FCU6-EP203-1 is mounted.

6. AXIS SPECIFICATIONS PARAMETERS

6.1 AXIS SPECIFICATIONS PARAMETERS

After setting up the parameter (PR) listed in the table, turn OFF the NC power. To validate the parameter, turn ON the power again.




(SETUP PARAM 2. 1/8)

#	Items		Details	Setting range (unit)																																	
2001	rapid	Rapid traverse rate	Set up the rapid traverse feedrate for each axis. The maximum value to be set differs with mechanical systems.	1 to 999999 (mm/min)																																	
2002	clamp	Cutting feedrate for clamp function	Define the maximum cutting feedrate for each axis. Even if the feedrate in G01 exceeds this value, the clamp will be applied at this feedrate.	1 to 999999 (mm/min)																																	
2003 (PR)	smgst	Acceleration and deceleration modes	<p>Specify acceleration and deceleration control modes.</p> <table border="1" style="margin-left: 20px;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td><td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td></td><td>OT3</td><td>OT2</td><td>OT1</td><td>C3</td><td></td><td>C1</td><td>LC</td><td>R3</td><td></td><td>R1</td><td>LR</td> </tr> </table> <p>Note: Set 0 in null bits.</p> <p>Rapid traverse feed acceleration and deceleration types LR: Linear acceleration/deceleration R1: Primary delay R3: Exponential acceleration and linear deceleration</p> <p>Note: Designate "F" with bits 0 to 3 for rapid traverse with acceleration/deceleration by software.</p> <p>Cutting feed acceleration and deceleration types LC: Linear acceleration/deceleration C1: Primary delay C3: Exponential acceleration and linear deceleration</p> <p>Note: Designate "F" with bits 4 to 7 for cutting feed with acceleration/deceleration by software.</p> <p>(To be continued to the next page)</p>	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0							OT3	OT2	OT1	C3		C1	LC	R3		R1	LR	Specify the modes in hexadecimal notation.
F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																						
						OT3	OT2	OT1	C3		C1	LC	R3		R1	LR																					




6. AXIS SPECIFICATIONS PARAMETERS
 6.1 AXIS SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)																					
		<p>(Continued from the previous page) <Combination of acceleration and deceleration patterns></p> <p>Command speed</p> <p>Linear to linear LR=1 (LC=1) Step LR=0 (LC=0)</p> <p>Primary delay R1=1 (C1=1)</p> <p>Exponential to linear R3=1 (C3=1) Step R1-R3=0 (C1-C3=0)</p> <p>Parameters in parentheses are for cutting feed.</p> <p>R1 > R3 when both R1 and R3 contain 1. <Stroke end stop types></p> <table border="1"> <thead> <tr> <th>Type</th> <th>OT2</th> <th>OT3</th> </tr> </thead> <tbody> <tr> <td>Linear deceleration</td> <td>0</td> <td>0</td> </tr> <tr> <td>Position loop step stop</td> <td>1</td> <td>0</td> </tr> <tr> <td>Speed loop step stop</td> <td>0</td> <td>1</td> </tr> <tr> <td>Position loop step stop</td> <td>1</td> <td>1</td> </tr> </tbody> </table> <table border="1"> <tbody> <tr> <td>OT1</td> <td>0</td> <td>Deceleration by G0t1</td> </tr> <tr> <td></td> <td>1</td> <td>Deceleration by 2 × G0t1</td> </tr> </tbody> </table> <p>Speed</p> <p>Stroke end signal</p> <p>Time</p> <p>G0t1</p> <p>2 × G0t1 (OT1=1, OT2=OT3=0)</p> <p>G0t1 (OT1=OT2=OT3=0)</p> <p>OT1 is valid under the following conditions (valid for dog type zero point return): Stop type: Linear deceleration Acceleration mode: Exponential Deceleration mode: Linear</p>	Type	OT2	OT3	Linear deceleration	0	0	Position loop step stop	1	0	Speed loop step stop	0	1	Position loop step stop	1	1	OT1	0	Deceleration by G0t1		1	Deceleration by 2 × G0t1	
Type	OT2	OT3																						
Linear deceleration	0	0																						
Position loop step stop	1	0																						
Speed loop step stop	0	1																						
Position loop step stop	1	1																						
OT1	0	Deceleration by G0t1																						
	1	Deceleration by 2 × G0t1																						

6. AXIS SPECIFICATIONS PARAMETERS
6.1 AXIS SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (unit)
2004	G0tL G0 time constant (linear)	<p>Set up a linear control time constant for rapid traverse acceleration and deceleration. The time constant is validated when LR (rapid traverse feed with linear acceleration or deceleration) or F (acceleration or deceleration by software) is selected in acceleration or deceleration mode "#2003 smgst".</p> 	1 to 4000 (ms)
2005	G0t1 G0 time constant (primary delay) Second-step time constant for acceleration and deceleration by software	<p>Set up a primary-delay time constant for rapid traverse acceleration and deceleration. The time constant is validated when R1 (rapid traverse feed with primary delay) or R3 (exponential acceleration and linear deceleration) is selected in acceleration or deceleration mode "#2003 smgst".</p> <p>When acceleration or deceleration by software is selected, the second-step time constant is used.</p> <p><Rapid traverse feed with primary delay></p>  <p><Rapid traverse feed with exponential acceleration and linear deceleration></p> 	1 to 5000 (ms)
2006	G0t2	Not used.	0

6. AXIS SPECIFICATIONS PARAMETERS
6.1 AXIS SPECIFICATIONS PARAMETERS


#		Items	Details	Setting range (unit)
2007	G1tL	G1 time constant (linear)	<p>Set up a linear control time constant for cutting acceleration and deceleration.</p> <p>The time constant is validated when LC (cutting feed with linear acceleration and deceleration) or F (acceleration and deceleration by software) is selected in acceleration or deceleration mode "#2003 smgst".</p> 	1 to 4000 (ms)
2008	G1t1	<p>G1 time constant (primary delay)</p> <p>Second stage time constant for acceleration and deceleration by software</p>	<p>Set up the primary delay time constant for cutting acceleration and deceleration.</p> <p>The time constant is validated when C1 (cutting feed with the primary delay) or C3 (cutting feed with exponential acceleration and linear deceleration) is selected in acceleration or deceleration mode "#2003 smgst".</p> <p>When acceleration or deceleration by software is selected, the second stage time constant is used.</p> <p><Cutting feed with primary time constant></p>  <p><Cutting feed with exponential acceleration and linear deceleration></p> 	1 to 5000 (ms)
2009	G1t2		Not used.	0

6. AXIS SPECIFICATIONS PARAMETERS
 6.1 AXIS SPECIFICATIONS PARAMETERS

#	Items		Details	Setting range (unit)
2010	fwd_g	Feed forward gain	Set up a feed forward gain for pre-interpolation acceleration and deceleration. The larger the set value, the smaller the theoretical control error will be. However, if a mechanical vibration occurs, the set value must be reduced.	0 to 100 (%)
2011	G0back	G0 backlash	Set up the backlash compensation amount when the direction is reversed with the movement command in rapid traverse feed mode or in manual mode.	-32768 to 32767
2012	G1back	G1 backlash	Set up the backlash compensation amount when the direction is reversed with the movement command in cutting mode.	-32768 to 32767

6. AXIS SPECIFICATIONS PARAMETERS
6.1 AXIS SPECIFICATIONS PARAMETERS

(SETUP PARAM 2. 2/8)

#	Items	Details	Setting range (unit)
2013 2014	OT - OT +	Soft limit I - soft limit I +	±99999.999 (mm)
		<p>Set up a soft limit area with reference to the zero point of the basic mechanical coordinates. For the movable area of stored stroke limit 1, set the coordinate in the negative direction in #2013 and the coordinate in the positive direction in #2014.</p> <p>To narrow the available range in actual use, use the parameters #8204 OT- and #8205 OT+.</p> <p>When the same value (other than 0) is set in #2013 and #2014, this function is disabled.</p> 	
2015	t1m1-	Negative direction sensor of tool setter or TLM standard length	±99999.999 (mm)
2016	t1m1+	Positive direction sensor of tool setter	±99999.999 (mm)
2017	tap_g	Axis servo gain	1.00 to 200.00 (rad/s)
2018	no_srv	Operation with no servo control	0/1

6. AXIS SPECIFICATIONS PARAMETERS
6.1 AXIS SPECIFICATIONS PARAMETERS


#	Items	Details	Setting range (unit)	
2019	revnum	Return steps	Set up the steps required for reference point return for each axis. 0: Does not execute reference point return. 1 to max. number of NC axes: Sets up the steps required for reference point return.	0 to max. number of NC axes
2020	o_chkp	Spindle orientation completion check during second zero point return	Set up the distance from the second zero point to the position for checking that the spindle orientation has completed during second zero point return. If the set value is 0, the above check is omitted.	0 to 99999.999 (mm)
2021	out_f	Maximum speed outside soft limit range	Set up the maximum speed outside the soft limit range.	0 to 999999
2022	G30SL X	Validate soft limit (automatic and manual)	Set up this function to disable a soft limit check during the second to the fourth zero point return in both automatic and manual operation modes. 0: Enables soft limit check. 1: Disables soft limit check.	0/1
2023	ozfmin	Set up ATC speed lower limit	Set up the minimum speed outside the soft limit range during the second to the fourth zero point return in both automatic and manual operation modes.	0 to 999999
2024	synerr	Allowable error	Set up the following for the master axis: the maximum synchronization error that is allowed to check for synchronization errors When 0 is set up, the error check is not carried out.	0 to 99999.999 (mm) During spindle C axis synchronization control: 0 to 99999.999 (°)

6. AXIS SPECIFICATIONS PARAMETERS
6.2 ZERO POINT RETURN PARAMETERS

6.2 ZERO POINT RETURN PARAMETERS

After setting up the parameter (PR) listed in the table, turn OFF the NC power. To validate the parameter, turn ON the power again.

(SETUP PARAM 2. 3/8)


#	Items	Details	Setting range (unit)	
2025	G28rap	G28 rapid traverse rate	Set up a rapid traverse rate for dog type reference point return command.	1 to 999999 (mm/min)
2026	G28crp	G28 approach speed	Set up the speed of approach to the reference point in the reference point return command. This speed is attained after the system stops with deceleration by dog detection. Note) The G28 approach speed unit is (10°/min) only when using the Z-phase type encoder (#1226 aux10 bit3=1) for the spindle/C-axis reference point return type. The same unit is used for both the micron and sub-micron specifications.	1 to 60000 (mm/min)
2027	G28sft	Reference point shift distance	Set up the distance from the electrical zero-point detection position to the actual machine reference point during reference point return control. Note) When #1240 set12 (bit2) is ON, a magnification (C: 10-fold, D: 100-fold) corresponding to the input setting unit (#1003 iunit) will be applied on the setting value.	0 to 65535 (μm)
2028	grmask	Grip mask amount	Set up a distance where the grid point is ignored when near-point dog OFF signals are close to that grid point during reference point return.  The grid mask is valid by one grid.	0 to 65535 (μm) Even for the specifications in sub-microns, set up the value in units of μm.
2029	grspc	Grid interval	Set up a detector grid interval. Generally, set up the value equal to the ball screw pitch. However, if the detector grid interval is not equal to the screw pitch when measured with a linear scale, set up the detector grid interval. To reduce the grid interval, use its divisors. To use 0.001 mm as minimum setup units, set up the negative value. Example) Setup value 1 → 1.000 mm (°) -1 → 0.001 mm (°) Even when the specifications in sub-microns are used, 0.001 mm is specified for the minimum setup units.	-32767 to 999 (mm)

6. AXIS SPECIFICATIONS PARAMETERS
6.2 ZERO POINT RETURN PARAMETERS

#		Items	Details	Setting range (unit)
2030 (PR)	dir (-)	Reference point direction (-)	<p>Set which side of the near-point dog the reference point is at during reference point return. <For dog type reference point return></p> <p style="text-align: center;">Direction in which zero point is established as viewed from the near-point dog</p>	<p>0: Positive direction 1: Negative direction</p>
2031	noref	Axis without reference point	Specify the axis that does not have a reference point. Before automatic operation starts, reference point return is not required.	<p>0: Normal controlled axis 1: Axis without reference point</p>
2032	nochk	Whether reference point return is completed not checked	The absolute and incremental commands can be executed even if dog type (or Z phase pulse system) reference point return is not completed. Specify whether to check that the reference point return is completed.	<p>0: Reference point return completion is checked. 1: Reference point return completion is not checked.</p>
2033	zp_no	Z phase pulse system reference point return spindle encoder No.	The reference point return is performed with the Z phase pulse of the spindle encoder. Set the spindle encoder No. to be used.	<p>0: Dog type 1 to 4: Spindle No.</p>

6. AXIS SPECIFICATIONS PARAMETERS
 6.2 ZERO POINT RETURN PARAMETERS

(SETUP PARAM 2. 4/8)

#	Items	Reference	Details	Setting range (unit)
2037	G53ofs	Reference	Set up the position of the first, second, third, and fourth reference points from the zero point of the basic mechanical coordinates. 	±999999.999 (mm)
2038	#2_rfp	point #1 to #4		
2039	#3_rfp			
2040	#4_rfp			

6. AXIS SPECIFICATIONS PARAMETERS
6.3 ABSOLUTE POSITION PARAMETERS

6.3 ABSOLUTE POSITION PARAMETERS

(SETUP PARAM 2. 5/8)

#	Items	Details	Setting range (unit)
2049 (PR)	type Absolute position detection method	Specify the absolute position zero point alignment method. 0: Not absolute position detection 1: Stopper method (push with mechanical stopper) 2: Origin point alignment method (align with marked point) 3: Dog-type (align with dog and proximity switch) 4: Reference point alignment method II (align to alignment mark) (Type that does not return grid after reference alignment) 9: Simple absolute position (Not absolute position detection, but the position when the power is turned off is registered.) Automatic initial setting is valid only when the stopper method is selected.	0 to 9
2050	absdir Base point of Z direction	Set the direction of the absolute position reference point (grid point immediately before) seen from the machine reference point for when using reference point alignment.	0: Positive direction 1: Negative direction
2051	check Check	Set the tolerable range for the movement amount (deviation amount) when the power is turned OFF. 0: Not checked 1 to 99999.999mm: If the difference of the position when the power is turned OFF and turned ON again is larger than this value, an alarm will be output.	0 to 99999.999 (mm)
2052	absg28	Not used.	
2053	absm02	Not used.	
2054	clpush Current limit (%)	Set up the current limit value for the initial setting when detecting an absolute position with a dog-less system. The setup value is the ratio of the current limit value to the rated value.	0 to 100 (%)
2055	pushf Push speed	Set the feedrate for the automatic initial setting during stopper method.	1 to 999 (mm/min)
2056	aproch Approach	Set the approach distance for the automatic initial setting in the push method. Approach distance: After using stopper once, the tool returns this distance, and then use stopper again. When set to 0, the reference point coordinates set in #2037 G53ofs will be used as the approach start position.	0 to 999.999 (mm)

6. AXIS SPECIFICATIONS PARAMETERS
6.3 ABSOLUTE POSITION PARAMETERS

#		Items	Details	Setting range (unit)
2057	nrefp	Near zero point +	Set the width where the near-reference-point signal is output. (Positive direction width) When set to 0, the width is equivalent to the grid width setting. Note: When #1240 set12 (bit2) is ON, a magnification (C: 10-fold, D: 100-fold) corresponding to the input setting unit (#1003 iunit) will be applied on the setting value.	0 to 32.767 (mm)
2058	nrefn	Near zero point -	Set the width where the near-reference-point signal is output. (Negative direction width) When set to 0, the width is equivalent to the grid width setting. Note: When #1240 set12 (bit2) is ON, a magnification (C: 10-fold, D: 100-fold) corresponding to the input setting unit (#1003 iunit) will be applied on the setting value.	0 to 32.767 (mm)
2059	zerbas	Select zero point parameter and reference point	Specify the position to be the zero point coordinate during absolute position initial setting. 0: Position that was stopped during stopper method Specify the coordinates of the alignment mark position when using the reference point method. 1: Grid point just before stopper Specify the coordinates of the grid point just before the alignment mark.	0/1

6.4 AXIS SPECIFICATIONS PARAMETERS 2

(SETUP PARAM 2. 6/8)

#	Items	Details	Setting range (unit)
2061	OT_1B - Soft limit IB-	Set up the coordinates of the lower limit of the inhibited area of stored stroke limit IB. Specify a value in the basic mechanical coordinates system. If the same value (non-zero) with the same sign as that of #2062 OT_IB+ is specified, the stored stroke limit IB function is disabled.	±99999.999 (mm)
2062	OT_1B + Soft limit IB+	Set up the coordinates of the upper limit of the inhibited area of stored stroke limit IB. Specify a value in the basic mechanical coordinates system.	±99999.999 (mm)
2063	OT_1B type Soft limit IB type	Select OT_IB or OT_IC in which OT_IB+/- is used in stored stroke limit I. 0: Soft limit IB valid 1: Soft limit IB and IC invalid 2: Soft limit IC valid 3: When using the inclined axis specifications, the soft limit is checked with the program coordinate system. Note: This is invalid for axes other than the inclined axis' base axis and inclined axis.	0/1/2/3
2064	rapid2 Speed 2	Specify the speed applicable to the speed area for 2-stage acceleration/deceleration. If the following conditions are not satisfied, inclination constant acceleration/deceleration is used for operation. (0 < rapid2 < rapid and rapid3 = 0 and 0 < G0tL2 < G0tL and G0tL3 = 0) (Applicable only to M64 D version series) Related parameters: #1223 aux07 bit 0 (Rapid traverse content multistage acceleration/deceleration) #2065 G0tL2 (Time constant 2)	0 to 999999 (mm/min) 0: No setting
2065	G0tL2 Time constant 2	Specify the time constant applicable to the speed area for 2-stage acceleration/deceleration. If the following conditions are not satisfied, inclination constant acceleration/deceleration is used for operation. (0 < rapid2 < rapid and rapid3 = 0 and 0 < G0tL2 < G0tL and G0tL3 = 0) (Applicable only to M64 D version series) Related parameters: #1223 aux07 bit 0 (Rapid traverse content multistage acceleration/deceleration) #2064 rapid2 (Speed 2)	1 to 4000 (ms) 0: No setting

6. AXIS SPECIFICATIONS PARAMETERS
6.4 AXIS SPECIFICATIONS PARAMETERS 2

#	Items		Details	Setting range (unit)
2066	rapid3	Speed 3	Specify the speed applicable to the speed area for 2-stage or 3-stage acceleration/deceleration. If the following conditions are not satisfied, inclination constant acceleration/deceleration is used for operation. ($0 < \text{rapid3} < \text{rapid2} < \text{rapid}$ and $0 < \text{G0tL3} < \text{G0tL2} < \text{G0tL}$) (Applicable only to M64 D version series) Related parameters: #1223 aux07 bit 0 (Rapid traverse content multistage acceleration/deceleration) #2067 G0tL3 (Time constant 3)	0 to 999999 (mm/min) 0: No setting
2067	G0tL3	Time constant 3	Specify the time constant applicable to the speed area for 2-stage or 3-stage acceleration/deceleration. If the following conditions are not satisfied, inclination constant acceleration/deceleration is used for operation. ($0 < \text{rapid3} < \text{rapid2} < \text{rapid}$ and $0 < \text{G0tL3} < \text{G0tL2} < \text{G0tL}$) (Applicable only to M64 D version series) Related parameters: #1223 aux07 bit 0 (Rapid traverse content multistage acceleration/deceleration) #2066 rapid3 (Speed 3)	1 to 4000 (ms) 0: No setting
2068	G0fwdg	G00 feed forward gain	Specify the feed forward gain applicable to acceleration/deceleration before G00 interpolation. The greater the set value, the shorter the positioning time during in-position checking. If machine vibration occurs, decrease the set value.	0 to 200 (%)
2069	Rcoeff	Axis arc radius error correction efficient	The amount of arc radius error correction can be increased or decreased between -100% to +100% for each axis.	-100.0 to +100.0 (%)
2070 (PR)	div_RT	Rotational axis division count	Specify the number of divisions of one turn of the rotational axis for purpose of control. Example: When 36 is set, one turn is supposed to be 36.000. Note 1: When 0 is set, the normal rotational axis (360.000 degrees for one turn) is assumed. Note 2: If this parameter is changed when the absolute position detection specification is used, absolute position data is lost. Initialization must be performed again.	0 to 999

6. AXIS SPECIFICATIONS PARAMETERS
6.4 AXIS SPECIFICATIONS PARAMETERS 2

#	Items	Details	Setting range (unit)
2071	s_axis (For L system only)	Inclined axis selection Select the axis subjected to inclined-axis control or the base axis corresponding to the inclined axis. 0: Axis not subjected to inclined-axis control 1: Inclined axis 2: Base axis corresponding to inclined axis Note: Set 1 or 2 for only one axis. If it is set for two or more axes, inclined-axis control does not work.	0 to 2
2072	rslimt	Restart limit If the machine is positioned on the minus (-) side of the set value in T-command restart mode, restart search in type 3 is disabled.	±9999.999 (mm)

6. AXIS SPECIFICATIONS PARAMETERS
6.4 AXIS SPECIFICATIONS PARAMETERS 2

(SETUP PARAM 2. 7/8)

#	Items	Details	Setting range (unit)
2073	zrn_dog Origin dog	<p>Under the standard specifications, the origin dog signal is assigned to a fixed device. When it is desired to assign the origin dog signal to a position other than the fixed device, specify the input device in this parameter.</p> <p>Note 1: This parameter is valid when 1 is set in #1226 aux10 bit 5.</p> <p>Note 2: When this parameter is valid, do not set the same device number. If the same device number exists, an emergency stop occurs. However, no device number check is performed for an axis to which a signal that ignores the near-point dog signal (R157) is input.</p>	00 to FF (HEX)
2074	H/W_OT+ H/W OT+	<p>Under the standard specifications, the OT (+) signal is assigned to a fixed device. When it is desired to assign the OT (+) g signal to a position other than the fixed device, specify the input device in this parameter.</p> <p>Note 1: This parameter is valid when 1 is set in #1226 aux10 bit 5.</p> <p>Note 2: When this parameter is valid, do not set the same device number. If the same device number exists, an emergency stop occurs. However, no device number check is performed for an axis to which a signal that ignores the OT signal (R156) is input.</p>	00 to FF (HEX)
2075	H/W_OT- H/W OT-	<p>Under the standard specifications, the OT (-) signal is assigned to a fixed device. When it is desired to assign the OT (-) g signal to a position other than the fixed device, specify the input device in this parameter.</p> <p>Note 1: This parameter is valid when 1 is set in #1226 aux10 bit 5.</p> <p>Note 2: When this parameter is valid, do not set the same device number. If the same device number exists, an emergency stop occurs. However, no device number check is performed for an axis to which a signal that ignores the OT signal (R156) is input.</p>	00 to FF (HEX)

6. AXIS SPECIFICATIONS PARAMETERS
6.4 AXIS SPECIFICATIONS PARAMETERS 2

#	Items	Details	Setting range (unit)
2076	index_x Index table indexing axis	Specify the index table indexing axis. 0: Normal axis 1: Index table indexing axis Note: This parameter is valid only for the NC axis. The parameter is invalid if specified for the PLC axis.	0/1
2077	G0inps G0 in-position width	When an in-position check is performed for G0, this parameter is valid. (Comparison of SV024 and this parameter, the parameter that the in-position width is wider is applied.) When 0 is set, this parameter is invalid. (Applicable only to SV024)	0 to 32767 (μm) M64 specifies a 0.5 μm unit.
2078	G1inps G1 in-position width	When an in-position check is performed for G1, this parameter is valid. (Comparison of SV024 and this parameter, the parameter that the in-position width is wider is applied.) When 0 is set, this parameter is invalid. (Applicable only to SV024)	0 to 32767 (μm) M64 specifies a 0.5 μm unit.
2079	chcomp Chopping compensation coefficient	Set the coefficient applied on the compensation amount for the insufficient amount caused by servo delay during chopping.	0 to 10 (standard value: 8)
2080	chwid Bottom dead center position width	Set the tolerance between the commanded stroke and actual stroke. During chopping, if the (command width - maximum stroke of top/bottom dead center position /2) is within this tolerance, compensation will be applied.	Micron: 0 to 10000 (μm) Sub-micron: 0 to 10000 (0.1 μm)
2081	chclsp Maximum chopping speed	Set the chopping axis clamp speed applied during chopping.	Micron: 0 to 60000 (mm/min) Sub-micron: 0 to 60000 (0.1 mm)/min
2082	a_rstax Restart position return order	Designate the order for automatically returning to the restart position. 0: Do not return. When 0 is designated for all axes, all of the axes will return simultaneously.	0 to 6

6. AXIS SPECIFICATIONS PARAMETERS
6.4 AXIS SPECIFICATIONS PARAMETERS 2

#		Items	Details	Setting range (unit)
2083	rot_2	Linear type rotary axis II	<p>The linear type rotary axis II is validated.</p> <p>0: Invalidate linear type rotary axis II. 1: Validate linear type rotary axis II.</p> <p>Note that this is valid only when the power is turned ON, and the rotary axis parameters must be validated.</p> <p>The axis type is determined by the combination with the existing rotary axis parameters (#1017 rot rotary axis). If #1017 is set to 0, the linear axis will be applied. When #1017 is set to 1 and this parameter is set to 0, the rotary axis will be applied, and when set to 1, the linear type rotary axis II will be applied.</p> <p><Related parameters></p> <p>#1089: Cut_RT Short cut for rotary axis #1090: Lin_RT Linear type rotary axis #2070: div_RT Rotary axis division count #2076: index_x Index table indexing axis</p> <p>Note: These parameters are invalid when the linear type rotary axis II is set.</p>	0/1
2084	G60_ax	Unidirectional positioning operation selection	<p>Select the unidirectional positioning with G00.</p> <p>Select the axis for carrying out the positioning per time operation when the positioning command is issued regardless of the unidirectional positioning command and modal.</p> <p>0: Carry out unidirectional positioning according to the command and modal. 1: When the positioning command (G00) is issued, carry out unidirectional positioning regardless of the command and modal.</p> <p><Related parameters></p> <p>#8209 G60 SHIFT: The final positioning direction and distance for the unidirectional positioning command is set for each axis.</p> <p>#2076 Index table indexing axis: Set the indexing axis for each axis.</p>	0/1

6. AXIS SPECIFICATIONS PARAMETERS
6.4 AXIS SPECIFICATIONS PARAMETERS 2

(SETUP PARAM 2. 8/8)

#	Items	Details	Setting range (unit)	
2086	exdcax	External deceleration speed	Set the upper limit of the feedrate for each axis when the external deceleration signal is valid. This parameter is valid when the #1239 set11/bit6 external deceleration axis compliance valid is set to 1.	1 to 999999 (mm/min)
2087	syncnt	Synchronization/superimposition control setting for each axis	BIT0: Polarity of synchronous axis in respect to reference axis 0: Polarity with reference axis is positive 1: Polarity with reference axis is negative	0 to FF (hexadecimal)
2088	bsax_sy	Reference axis for synchronous control	Set the reference axis for synchronous control with the 2nd axis name (axname2).	1st character: A to Z 2nd character: A to Z, 1 to 9
2089	bsax_pl	Reference axis for superimposition control	Set the reference axis for superimposition control with the 2nd axis name (axname2).	1st character: A to Z 2nd character: A to Z, 1 to 9
2090	plrapid	Rapid traverse rate for superimposition control	Set the rapid traverse rate for superimposition control. (Equivalent to #2001 rapid (rapid traverse rate).)	1 to 999999 (mm/min)
2091	plclamp	Cutting feed clamp speed for superimposition control	Set the cutting feed clamp speed for superimposition control. (Equivalent to #2002 clamp (cutting feed clamp speed).)	1 to 999999 (mm/min)
2092	plG0tL	G0 time constant for superimposition control (linear)	Set the G0 time constant (linear) for superimposition control. (Equivalent to #2004 G0tL (G0 time constant (linear).))	1 to 4000 (ms)
2093	plG0t1	G0 time constant for superimposition control (primary delay)	Set the G0 time constant (primary delay) for superimposition control. (Equivalent to #2005 G0t1 (G0 time constant (primary delay).))	1 to 5000 (ms)
2094	plG1tL	G1 time constant for superimposition control (linear)	Set the G1 time constant (linear) for superimposition control. (Equivalent to #2007 G1tL (G1 time constant (linear).))	1 to 4000 (ms)

6. AXIS SPECIFICATIONS PARAMETERS
6.4 AXIS SPECIFICATIONS PARAMETERS 2

#	Items	Details	Setting range (unit)
2095	pIG1t1 G1 time constant for superimposition control (primary delay)	Set the G1 time constant (primary delay) for superimposition control. (Equivalent to #2008 G1t1 (G1 time constant (primary delay).))	1 to 5000 (ms)
2096	crncsp Minimum corner deceleration speed	Set the minimum clamp speed for corner deceleration during the high-accuracy control mode. Normally set "0". Note: This parameter is invalid during SSS control.	0 to 1000000 (mm/min)
2099	igContr Axis excluded from corner angle calculation	Set the axis excluded from the corner angle calculation. For example, set this for the Cs axis during spring machining.	0/1
2102	skip_tL Skip time constant linear	Set up a linear control time constant for variable speed skip acceleration and deceleration. The time constant is validated when LC (cutting feed with linear acceleration and deceleration) or F (acceleration and deceleration by software) is selected in acceleration or deceleration mode "#2003 smgst".	1 to 4000 (ms)
2103	skip_t1 Skip time constant primary delay acceleration and deceleration by software second stage	Set up a primary-delay time constant for variable speed skip acceleration and deceleration. The time constant is validated when C1 (cutting feed with primary delay) or C3 (exponential acceleration and linear deceleration) is selected in acceleration or deceleration mode "#2003 smgst". When acceleration or deceleration by software is selected, the second-step time constant is used.	1 to 5000 (ms)

7. SERVO PARAMETERS

The parameters can be changed from any screen.

The valid servo parameters will differ according to the motor type. The setting values and meanings may also differ. Follow the correspondence table given below, and set the correct parameters.

Refer to each Instruction Manual or the following manuals for details on each motor.

MELDAS AC Servo/ Spindle MDS-A Series MDS-B Series Specification Manual... BNP-B3759

MELDAS AC Servo MDS-B-SVJ2 Series Specification and Instruction Manual BNP-B3937

MELDAS AC Servo/ Spindle MDS-C1 Series Specification Manual BNP-C3000

Parameter		Corresponding model		
		MDS-B-SVJ2	MDS-C1-Vx (High-gain) (MDS-B-Vx4)	MDS-C1-Vx (Standard) (MDS-B-Vx)
SV001	Motor side gear ratio	○	○	○
SV002	Machine side gear ratio	○	○	○
SV003	Position loop gain 1	○	○	○
SV004	Position loop gain 2	○	○	○
SV005	Speed loop gain 1	○	○	○
SV006	Speed loop gain 2	-	○	○
SV007	Speed loop delay compensation	-	○	○
SV008	Speed loop lead compensation	○	○	○
SV009	Current loop q axis lead compensation	○	○	○
SV010	Current loop d axis lead compensation	○	○	○
SV011	Current loop q axis gain	○	○	○
SV012	Current loop d axis gain	○	○	○
SV013	Current limit value	○	○	○
SV014	Current limit value in special control	○	○	○
SV015	Acceleration rate feed forward gain	○	○	○
SV016	Lost motion compensation 1	○	○	○
SV017	Servo specification selection	○	○	○
SV018	Ball screw pitch	○	○	○
SV019	Position detector resolution	○	○	○
SV020	Speed detector resolution	○	○	○
SV021	Overload detection time constant	○	○	○
SV022	Overload detection level	○	○	○
SV023	Excessive error detection width during servo ON	○	○	○
SV024	In-position detection width	○	○	○
SV025	Motor/Detector type	○	○	○
SV026	Excessive error detection width during servo OFF	○	○	○
SV027	Servo function selection 1	○	○	○
SV028	Linear motor magnetic pole shift length	-	-	-
SV029	Speed at the change of speed loop gain	-	○	○
SV030	Voltage dead time compensation	-/○	○/○	○/○
SV031	Overshooting compensation 1	○	○	○
SV032	Torque offset	○	○	○

7. SERVO PARAMETERS

Parameter		Corresponding model		
		MDS-B-SVJ2	MDS-C1-Vx (High-gain) (MDS-B-Vx4)	MDS-C1-Vx (Standard) (MDS-B-Vx)
SV033	Servo function selection 2	○	○	○
SV034	Servo function selection 3	○	○	○
SV035	Servo function selection 4	○	○	○
SV036	Regenerative resistor type	○	○	○
SV037	Load inertia scale	○	○	○
SV038	Notch filter frequency 1	-	○	○
SV039	Lost motion compensation timing	-	○	○
SV040	Non-sensitive band in feed forward control	-/○	○/○	○/○
SV041	Lost motion compensation 2	○	○	○
SV042	Overshooting compensation 2	○	○	○
SV043	Disturbance observer filter frequency	○	○	○
SV044	Disturbance observer gain	○	○	○
SV045	Frictional torque	-/○	○/○	○/○
SV046	Notch filter frequency 2	-	○	-
SV047	Inductive voltage compensation gain	○	○	○
SV048	Vertical axis drop prevention time	○	○	○
SV049	Position loop gain 1 in spindle synchronous control	○	○	○
SV050	Position loop gain 2 in spindle synchronous control	○	○	○
SV051	Dual feedback control time constant	-	○	○
SV052	Dual feedback control non-sensitive band	-	○	○
SV053	Excessive error detection width in special control	○	○	○
SV054	Overrun detection width in closed loop control	-/-	○/○	○/○
SV055	Max. gate off delay time after emergency stop	-	○	○
SV056	Deceleration time constant at emergency stop	○	○	○
SV057	SHG control gain	○	○	○
SV058	SHG control gain in spindle synchronous control	○	○	○
SV059	Collision detection torque estimating gain	○	○	○
SV060	Collision detection level	○	○	○
SV061	D/A output channel 1 data No.	○	○	○
SV062	D/A output channel 2 data No.	○	○	○
SV063	D/A output channel 1 output scale	○	○	○
SV064	D/A output channel 2 output scale	○	○	○
SV065	Tool end compensation spring constant	-	○	-

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

7.1 MDS-B-SVJ2

(1) Details for servo parameters

For parameters marked with a (PR) in the table, turn the NC power OFF after setting. After the power is turned ON again, the parameter is validated.

⚠ CAUTION

⚠ In the explanation on bits, set all bits not used, including blank bits, to "0".

No.	Items	Details	Setting range
2201 (PR)	SV001 PC1	Motor side gear ratio	1 to 32767
2202 (PR)	SV002 PC2	Machine side gear ratio	1 to 32767
2203	SV003 PGN1	Position loop gain 1	1 to 200 (rad/s)
2204	SV004 PGN2	Position loop gain 2	0 to 999 (rad/s)
2205	SV005 VGN1	Speed loop gain	1 to 999
2206		Not used. Set to "0".	0
2207		Not used. Set to "0".	0
2208	SV008 VIA	Speed loop lead compensation	1 to 9999
2209	SV009 IQA	Current loop q axis lead compensation	1 to 20480
2210	SV010 IDA	Current loop d axis lead compensation	1 to 20480
2211	SV011 IQG	Current loop q axis gain	1 to 2560
2212	SV012 IDG	Current loop d axis gain	1 to 2560

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range	
2213	SV013 ILMT	Current limit value	Set the normal current (torque) limit value. (Limit values for both + and - direction.) When the value is "500" (a standard setting), the maximum torque is determined by the specification of the motor.	0 to 500 (Stall [rated] current %)
2214	SV014 ILMTsp	Current limit value in special control	Set the current (torque) limit value in a special control (initial absolute position setting, stopper control, etc). (Limit values for both of the + and - directions.) Set to "500" when not using.	0 to 500 (Stall [rated] current %)
2215	SV015 FFC	Acceleration rate feed forward gain	When a relative error in the synchronous control is large, apply this parameter to the axis that is delaying. The standard setting value is "0". For the SHG control, set to "100". To adjust a relative error in acceleration/ deceleration, increase the value by 50 to 100 at a time.	0 to 999 (%)
2216	SV016 LMC1	Lost motion compensation 1	Set this when the protrusion (that occurs due to the non-sensitive band by friction, torsion, backlash, etc) at quadrant change is too large. This compensates the torque at quadrant change. This is valid only when the lost motion compensation (SV027 (SSF1/lmc)) is selected.	
			Type 1: When SV027 (SSF1)/ bit9, 8 (lmc)=01 Set the compensation amount based on the motor torque before the quadrant change. The standard setting is "100". Setting to "0" means the compensation amount is zero. Normally, use Type 2.	-1 to 200 (%)
			Type 2: When SV027 (SSF1)/ bit9, 8 (lmc)=10 Set the compensation amount based on the stall (rated) current of the motor. The standard setting is double of the friction torque. Setting to "0" means the compensation amount is zero.	-1 to 100 (Stall [rated] current %)
			When you wish different compensation amount depending on the direction When SV041 (LMC2) is "0", compensate with the value of SV016 (LMC1) in both of the + and -directions. If you wish to change the compensation amount depending on the command direction, set this and SV041 (LMC2). (SV016: + direction, SV041: - direction. However, the directions may be opposite depending on other settings.) When "-1" is set, the compensation won't be performed in the direction of the command.	

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																																				
2217 (PR)	SV017 SPEC	Servo specification selection	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 12.5%;">F</td> <td style="width: 12.5%;">E</td> <td style="width: 12.5%;">D</td> <td style="width: 12.5%;">C</td> <td style="width: 12.5%;">B</td> <td style="width: 12.5%;">A</td> <td style="width: 12.5%;">9</td> <td style="width: 12.5%;">8</td> </tr> <tr> <td style="height: 15px;"></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td style="text-align: center;">abs</td> <td></td> <td style="text-align: center;">vdir</td> <td></td> <td style="text-align: center;">mc</td> <td></td> <td></td> <td style="text-align: center;">dmk</td> </tr> </table>	F	E	D	C	B	A	9	8									7	6	5	4	3	2	1	0	abs		vdir		mc			dmk																				
			F	E	D	C	B	A	9	8																																													
			7	6	5	4	3	2	1	0																																													
			abs		vdir		mc			dmk																																													
			<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">bit</th> <th style="width: 10%;">Meaning when "0" is set</th> <th style="width: 80%;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">dmk</td> <td>Deceleration control stop (SVJ2 standard)</td> </tr> <tr> <td style="text-align: center;">1</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">2</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">mc</td> <td>Contactor control output invalid</td> </tr> <tr> <td style="text-align: center;">4</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">5</td> <td style="text-align: center;">vdir</td> <td>HA053N to HA33N motor Detector installation position standard (A, C)</td> </tr> <tr> <td style="text-align: center;">6</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">abs</td> <td>Incremental control</td> </tr> <tr> <td style="text-align: center;">8</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">9</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">A</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">B</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">C</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">D</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">E</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">F</td> <td></td> <td></td> </tr> </tbody> </table>	bit	Meaning when "0" is set	Meaning when "1" is set	0	dmk	Deceleration control stop (SVJ2 standard)	1			2			3	mc	Contactor control output invalid	4			5	vdir	HA053N to HA33N motor Detector installation position standard (A, C)	6			7	abs	Incremental control	8			9			A			B			C			D			E			F			
			bit	Meaning when "0" is set	Meaning when "1" is set																																																		
			0	dmk	Deceleration control stop (SVJ2 standard)																																																		
			1																																																				
			2																																																				
3	mc	Contactor control output invalid																																																					
4																																																							
5	vdir	HA053N to HA33N motor Detector installation position standard (A, C)																																																					
6																																																							
7	abs	Incremental control																																																					
8																																																							
9																																																							
A																																																							
B																																																							
C																																																							
D																																																							
E																																																							
F																																																							
(Note) Set to "0" for bits with no particular description.																																																							
2218 (PR)	SV018 PIT	Ball screw pitch	Set the ball screw pitch. Set to "360" for the rotary axis.	1 to 32767 (mm/rev)																																																			
2219 (PR)	SV019 RNG1	Position detector resolution	For both parameters, set the number of pulses per one revolution of the motor detector.	8 to 100 (kp/rev)																																																			
		Motor model name	Setting value																																																				
			SV01 9																																																				
			SV02 0																																																				
2220 (PR)	SV020 RNG2	Speed detector resolution	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 60%;">HC*-E42/A42/A47, HC*R-E42/A42/A47 HA*N-E42/A42</td> <td style="width: 10%; text-align: center;">100</td> <td style="width: 10%; text-align: center;">100</td> </tr> <tr> <td>HC*-E33/A33, HC*R-E33/A33 HA*N-E33/A33</td> <td style="text-align: center;">25</td> <td style="text-align: center;">25</td> </tr> <tr> <td>HC-SF, HC-RF</td> <td style="text-align: center;">16</td> <td style="text-align: center;">16</td> </tr> <tr> <td>HA-FF, HC-MF</td> <td style="text-align: center;">8</td> <td style="text-align: center;">8</td> </tr> </table>	HC*-E42/A42/A47, HC*R-E42/A42/A47 HA*N-E42/A42	100	100	HC*-E33/A33, HC*R-E33/A33 HA*N-E33/A33	25	25	HC-SF, HC-RF	16	16	HA-FF, HC-MF	8	8																																								
HC*-E42/A42/A47, HC*R-E42/A42/A47 HA*N-E42/A42	100	100																																																					
HC*-E33/A33, HC*R-E33/A33 HA*N-E33/A33	25	25																																																					
HC-SF, HC-RF	16	16																																																					
HA-FF, HC-MF	8	8																																																					
2221	SV021 OLT	Overload detection time constant	Set the detection time constant of Overload 1 (Alarm 50). Set to "60" as a standard. (For machine tool builder adjustment.)	1 to 300 (s)																																																			
2222	SV022 OLL	Overload detection level	Set the current detection level of Overload 1 (Alarm 50) in respect to the stall (rated) current. Set to "150" as a standard. (For machine tool builder adjustment.)	50 to 180 (Stall [rated] current %)																																																			

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range
2223	SV023 OD1 Excessive error detection width during servo ON	Set the excessive error detection width when servo ON. <Standard setting value> $\text{OD1}=\text{OD2}=\frac{\text{Rapid traverse rate (mm/min)}}{60*\text{PGN1}}/2 \text{ (mm)}$ When "0" is set, the excessive error detection will not be performed.	0 to 32767 (mm)
2224	SV024 INP In-position detection width	Set the in-position detection width. Set the accuracy required for the machine. The lower the setting is, the higher the positioning accuracy gets, however, the cycle time (setting time) becomes longer. The standard setting is "50".	0 to 32767 (μm)

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																																																																																																																																																																																																																																																																																																																																	
2225 (PR)	SV025 MTYP	Motor/ Detector type	<table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td colspan="4">pen</td><td colspan="4">ent</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td colspan="8">mtyp</td> </tr> </table>	F	E	D	C	B	A	9	8	pen				ent				7	6	5	4	3	2	1	0	mtyp																																																																																																																																																																																																																																																																																																																								
			F	E	D	C	B	A	9	8																																																																																																																																																																																																																																																																																																																																										
			pen				ent																																																																																																																																																																																																																																																																																																																																													
			7	6	5	4	3	2	1	0																																																																																																																																																																																																																																																																																																																																										
			mtyp																																																																																																																																																																																																																																																																																																																																																	
			<table border="1" style="width:100%; text-align:center;"> <tr> <th>bit</th> <th>Explanation</th> </tr> <tr> <td>0</td> <td>Set the motor type.</td> </tr> <tr> <td>1</td> <td rowspan="16"> <table border="1" style="width:100%; text-align:center;"> <tr> <th>Set- ting</th> <th>0x</th> <th>1x</th> <th>2x</th> <th>3x</th> <th>4x</th> <th>5x</th> <th>6x</th> <th>7x</th> <th>8x</th> </tr> <tr> <td>x0</td> <td>HA40N</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF43</td> <td>HA43N</td> </tr> <tr> <td>x1</td> <td>HA80N</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF63</td> <td>HA83N</td> </tr> <tr> <td>x2</td> <td>HA100N</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td>HA103N</td> </tr> <tr> <td>x3</td> <td>HA200N</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x4</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x5</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x6</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x7</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x8</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x9</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>xA</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td>HA93N</td> </tr> <tr> <td>xB</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>xC</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF053</td> <td>HA053N</td> </tr> <tr> <td>xD</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF13</td> <td>HA13N</td> </tr> <tr> <td>xE</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF23</td> <td>HA23N</td> </tr> <tr> <td>xF</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF33</td> <td>HA33N</td> </tr> </table> </td> </tr> <tr> <td>2</td> <td rowspan="16">mtyp</td> <td>x0</td> <td>HA40N</td> <td></td><td></td><td></td><td></td><td></td> <td>HA-FF43</td> <td>HA43N</td> </tr> <tr> <td>3</td> <td>x1</td> <td>HA80N</td> <td></td><td></td><td></td><td></td><td></td> <td>HA-FF63</td> <td>HA83N</td> </tr> <tr> <td>4</td> <td>x2</td> <td>HA100N</td> <td></td><td></td><td></td><td></td><td></td> <td></td> <td>HA103N</td> </tr> <tr> <td>5</td> <td>x3</td> <td>HA200N</td> <td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td>x4</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td>x5</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>x6</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>x7</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>x8</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>x9</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>xA</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td>HA93N</td> </tr> <tr> <td></td> <td>xB</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>xC</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF053</td> <td>HA053N</td> </tr> <tr> <td></td> <td>xD</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF13</td> <td>HA13N</td> </tr> <tr> <td></td> <td>xE</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF23</td> <td>HA23N</td> </tr> <tr> <td></td> <td>xF</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF33</td> <td>HA33N</td> </tr> </table>	bit	Explanation	0	Set the motor type.	1	<table border="1" style="width:100%; text-align:center;"> <tr> <th>Set- ting</th> <th>0x</th> <th>1x</th> <th>2x</th> <th>3x</th> <th>4x</th> <th>5x</th> <th>6x</th> <th>7x</th> <th>8x</th> </tr> <tr> <td>x0</td> <td>HA40N</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF43</td> <td>HA43N</td> </tr> <tr> <td>x1</td> <td>HA80N</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF63</td> <td>HA83N</td> </tr> <tr> <td>x2</td> <td>HA100N</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td>HA103N</td> </tr> <tr> <td>x3</td> <td>HA200N</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x4</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x5</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x6</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x7</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x8</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x9</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>xA</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td>HA93N</td> </tr> <tr> <td>xB</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>xC</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF053</td> <td>HA053N</td> </tr> <tr> <td>xD</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF13</td> <td>HA13N</td> </tr> <tr> <td>xE</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF23</td> <td>HA23N</td> </tr> <tr> <td>xF</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF33</td> <td>HA33N</td> </tr> </table>	Set- ting	0x	1x	2x	3x	4x	5x	6x	7x	8x	x0	HA40N							HA-FF43	HA43N	x1	HA80N							HA-FF63	HA83N	x2	HA100N								HA103N	x3	HA200N									x4										x5										x6										x7										x8										x9										xA									HA93N	xB										xC								HA-FF053	HA053N	xD								HA-FF13	HA13N	xE								HA-FF23	HA23N	xF								HA-FF33	HA33N	2	mtyp	x0	HA40N						HA-FF43	HA43N	3	x1	HA80N						HA-FF63	HA83N	4	x2	HA100N							HA103N	5	x3	HA200N								6	x4									7	x5										x6										x7										x8										x9										xA								HA93N		xB										xC							HA-FF053	HA053N		xD							HA-FF13	HA13N		xE							HA-FF23	HA23N		xF							HA-FF33	HA33N
			bit	Explanation																																																																																																																																																																																																																																																																																																																																																
			0	Set the motor type.																																																																																																																																																																																																																																																																																																																																																
			1	<table border="1" style="width:100%; text-align:center;"> <tr> <th>Set- ting</th> <th>0x</th> <th>1x</th> <th>2x</th> <th>3x</th> <th>4x</th> <th>5x</th> <th>6x</th> <th>7x</th> <th>8x</th> </tr> <tr> <td>x0</td> <td>HA40N</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF43</td> <td>HA43N</td> </tr> <tr> <td>x1</td> <td>HA80N</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF63</td> <td>HA83N</td> </tr> <tr> <td>x2</td> <td>HA100N</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td>HA103N</td> </tr> <tr> <td>x3</td> <td>HA200N</td> <td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x4</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x5</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x6</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x7</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x8</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>x9</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>xA</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td>HA93N</td> </tr> <tr> <td>xB</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td></td> <td></td> </tr> <tr> <td>xC</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF053</td> <td>HA053N</td> </tr> <tr> <td>xD</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF13</td> <td>HA13N</td> </tr> <tr> <td>xE</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF23</td> <td>HA23N</td> </tr> <tr> <td>xF</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td> <td>HA-FF33</td> <td>HA33N</td> </tr> </table>	Set- ting	0x	1x	2x		3x	4x	5x	6x	7x	8x	x0	HA40N							HA-FF43	HA43N	x1	HA80N							HA-FF63	HA83N	x2	HA100N								HA103N	x3	HA200N									x4										x5										x6										x7										x8										x9										xA									HA93N	xB										xC								HA-FF053	HA053N	xD								HA-FF13	HA13N	xE								HA-FF23	HA23N	xF								HA-FF33	HA33N																																																																																																																																																																					
			Set- ting		0x	1x	2x	3x		4x	5x	6x	7x	8x																																																																																																																																																																																																																																																																																																																																						
x0	HA40N									HA-FF43	HA43N																																																																																																																																																																																																																																																																																																																																									
x1	HA80N									HA-FF63	HA83N																																																																																																																																																																																																																																																																																																																																									
x2	HA100N										HA103N																																																																																																																																																																																																																																																																																																																																									
x3	HA200N																																																																																																																																																																																																																																																																																																																																																			
x4																																																																																																																																																																																																																																																																																																																																																				
x5																																																																																																																																																																																																																																																																																																																																																				
x6																																																																																																																																																																																																																																																																																																																																																				
x7																																																																																																																																																																																																																																																																																																																																																				
x8																																																																																																																																																																																																																																																																																																																																																				
x9																																																																																																																																																																																																																																																																																																																																																				
xA											HA93N																																																																																																																																																																																																																																																																																																																																									
xB																																																																																																																																																																																																																																																																																																																																																				
xC									HA-FF053	HA053N																																																																																																																																																																																																																																																																																																																																										
xD									HA-FF13	HA13N																																																																																																																																																																																																																																																																																																																																										
xE								HA-FF23	HA23N																																																																																																																																																																																																																																																																																																																																											
xF								HA-FF33	HA33N																																																																																																																																																																																																																																																																																																																																											
2	mtyp	x0	HA40N						HA-FF43	HA43N																																																																																																																																																																																																																																																																																																																																										
3		x1	HA80N						HA-FF63	HA83N																																																																																																																																																																																																																																																																																																																																										
4		x2	HA100N							HA103N																																																																																																																																																																																																																																																																																																																																										
5		x3	HA200N																																																																																																																																																																																																																																																																																																																																																	
6		x4																																																																																																																																																																																																																																																																																																																																																		
7		x5																																																																																																																																																																																																																																																																																																																																																		
		x6																																																																																																																																																																																																																																																																																																																																																		
		x7																																																																																																																																																																																																																																																																																																																																																		
		x8																																																																																																																																																																																																																																																																																																																																																		
		x9																																																																																																																																																																																																																																																																																																																																																		
		xA								HA93N																																																																																																																																																																																																																																																																																																																																										
		xB																																																																																																																																																																																																																																																																																																																																																		
		xC							HA-FF053	HA053N																																																																																																																																																																																																																																																																																																																																										
		xD							HA-FF13	HA13N																																																																																																																																																																																																																																																																																																																																										
		xE							HA-FF23	HA23N																																																																																																																																																																																																																																																																																																																																										
		xF							HA-FF33	HA33N																																																																																																																																																																																																																																																																																																																																										

(To be continued to the next page)

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																																																																
		(Continued from the previous page)																																																																																	
		<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">bit</th> <th style="width: 10%;">ent</th> <th style="width: 80%;">Explanation</th> </tr> </thead> <tbody> <tr> <td>8</td> <td rowspan="4">ent</td> <td rowspan="4">Set the speed detector type. Set to "2".</td> </tr> <tr> <td>9</td> </tr> <tr> <td>A</td> </tr> <tr> <td>B</td> </tr> <tr> <td>C</td> <td rowspan="4">pen</td> <td rowspan="4">Set the position detector type. Set to "2".</td> </tr> <tr> <td>D</td> </tr> <tr> <td>E</td> </tr> <tr> <td>F</td> </tr> </tbody> </table>		bit	ent	Explanation	8	ent	Set the speed detector type. Set to "2".	9	A	B	C	pen	Set the position detector type. Set to "2".	D	E	F																																																																	
bit	ent	Explanation																																																																																	
8	ent	Set the speed detector type. Set to "2".																																																																																	
9																																																																																			
A																																																																																			
B																																																																																			
C	pen	Set the position detector type. Set to "2".																																																																																	
D																																																																																			
E																																																																																			
F																																																																																			
2226	SV026 OD2	Excessive error detection width during servo OFF	0 to 32767 (mm)																																																																																
2227	SV027 SSF1	Servo function selection 1																																																																																	
		<table style="width: 100%; text-align: center; border-collapse: collapse;"> <tr> <td style="border: none;">F</td> <td style="border: none;">E</td> <td style="border: none;">D</td> <td style="border: none;">C</td> <td style="border: none;">B</td> <td style="border: none;">A</td> <td style="border: none;">9</td> <td style="border: none;">8</td> </tr> <tr> <td style="border: 1px solid black;">aflt</td> <td style="border: 1px solid black;">zrn2</td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;">ovs</td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;">lmc</td> <td style="border: 1px solid black;"></td> </tr> <tr> <td style="border: none;">7</td> <td style="border: none;">6</td> <td style="border: none;">5</td> <td style="border: none;">4</td> <td style="border: none;">3</td> <td style="border: none;">2</td> <td style="border: none;">1</td> <td style="border: none;">0</td> </tr> <tr> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;">vfct</td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;">zup</td> </tr> </table> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">bit</th> <th style="width: 10%;">Meaning when "0" is set</th> <th style="width: 80%;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>zup</td> <td>Vertical axis lift-up control stop</td> </tr> <tr> <td>1</td> <td></td> <td>Vertical axis lift-up control start</td> </tr> <tr> <td>2</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td rowspan="2">vfct</td> <td rowspan="2">Set the jitter compensation No. of compensation pulses with a binary. 00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses</td> </tr> <tr> <td>5</td> </tr> <tr> <td>6</td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> </tr> <tr> <td>8</td> <td rowspan="2">lmc</td> <td rowspan="2">Set the compensation amount with SV016 (LMC1) and SV041 (LMC2). 00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Lost motion compensation type 2 11: Setting prohibited</td> </tr> <tr> <td>9</td> </tr> <tr> <td>A</td> <td rowspan="2">ovs</td> <td rowspan="2">Set the compensation amount with SV031 (OVS1) and SV042 (OVS2). 00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Setting prohibited</td> </tr> <tr> <td>B</td> </tr> <tr> <td>C</td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> </tr> <tr> <td>E</td> <td>zrn2</td> <td>Set to "1".</td> </tr> <tr> <td>F</td> <td>aflt</td> <td>Adoptive filter stops</td> </tr> <tr> <td></td> <td></td> <td>Adoptive filter starts</td> </tr> </tbody> </table> <p>(Note) Set to "0" for bits with no particular description.</p>		F	E	D	C	B	A	9	8	aflt	zrn2			ovs		lmc		7	6	5	4	3	2	1	0			vfct					zup	bit	Meaning when "0" is set	Meaning when "1" is set	0	zup	Vertical axis lift-up control stop	1		Vertical axis lift-up control start	2			3			4	vfct	Set the jitter compensation No. of compensation pulses with a binary. 00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses	5	6			7			8	lmc	Set the compensation amount with SV016 (LMC1) and SV041 (LMC2). 00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Lost motion compensation type 2 11: Setting prohibited	9	A	ovs	Set the compensation amount with SV031 (OVS1) and SV042 (OVS2). 00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Setting prohibited	B	C			D			E	zrn2	Set to "1".	F	aflt	Adoptive filter stops			Adoptive filter starts
F	E	D	C	B	A	9	8																																																																												
aflt	zrn2			ovs		lmc																																																																													
7	6	5	4	3	2	1	0																																																																												
		vfct					zup																																																																												
bit	Meaning when "0" is set	Meaning when "1" is set																																																																																	
0	zup	Vertical axis lift-up control stop																																																																																	
1		Vertical axis lift-up control start																																																																																	
2																																																																																			
3																																																																																			
4	vfct	Set the jitter compensation No. of compensation pulses with a binary. 00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses																																																																																	
5																																																																																			
6																																																																																			
7																																																																																			
8	lmc	Set the compensation amount with SV016 (LMC1) and SV041 (LMC2). 00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Lost motion compensation type 2 11: Setting prohibited																																																																																	
9																																																																																			
A	ovs	Set the compensation amount with SV031 (OVS1) and SV042 (OVS2). 00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Setting prohibited																																																																																	
B																																																																																			
C																																																																																			
D																																																																																			
E	zrn2	Set to "1".																																																																																	
F	aflt	Adoptive filter stops																																																																																	
		Adoptive filter starts																																																																																	
2228	SV028	Not used. Set to "0".	0																																																																																
2229	SV029	Not used. Set to "0".	0																																																																																

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range
2230	SV030 IVC	Voltage dead time compensation When 100% is set, the voltage equivalent to the logical non-energized time will be compensated. Adjust in increments of 10% from the default value 100%. If increased too much, vibration or vibration noise may be generated. When not using, set to "0".	0 to 200 (%)
2231	SV031 OVS1	Overshooting compensation 1 Set this if overshooting occurs during positioning. This compensates the motor torque during positioning. This is valid only when the overshooting compensation SV027 (SSF1/ovs) is selected. Type 1: When SV027 (SSF1)/ bit11, 10 (ovs)=01 Set the compensation amount based on the motor's stall (rated) current. Increase by 1% and determine the amount that overshooting doesn't occur. In Type 1, compensation during the feed forward control during circular cutting won't be performed. Type 2: When SV027 (SSF1)/ bit11, 10 (ovs)=10 Use this if you perform the overshooting compensation during the feed forward control during circular cutting. The setting method is the same in Type 1. When you wish different compensation amount depending on the direction When SV042 (OVS2) is "0", compensate with the value of SV031 (OVS1) in both of the + and -directions. If you wish to change the compensation amount depending on the command direction, set this and SV042 (OVS2). (SV031: + direction, SV042: - direction. However, the directions may be opposite depending on other settings.) When "-1" is set, the compensation won't be performed in the direction of the command.	-1 to 100 (Stall [rated] current %)
2232	SV032 TOF	Torque offset Set the unbalance torque of vertical axis and inclined axis.	-100 to 100 (Stall [rated] current %)

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																
2233	SV033 SSF2	Servo function selection 2	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 12.5%; text-align: center;">F</td> <td style="width: 12.5%; text-align: center;">E</td> <td style="width: 12.5%; text-align: center;">D</td> <td style="width: 12.5%; text-align: center;">C</td> <td style="width: 12.5%; text-align: center;">B</td> <td style="width: 12.5%; text-align: center;">A</td> <td style="width: 12.5%; text-align: center;">9</td> <td style="width: 12.5%; text-align: center;">8</td> </tr> <tr> <td colspan="8" style="text-align: center; border: 1px solid black;">afs</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td colspan="4" style="text-align: center; border: 1px solid black;">fhz2</td> <td colspan="4" style="text-align: center; border: 1px solid black;">nfd</td> </tr> </table>	F	E	D	C	B	A	9	8	afs								7	6	5	4	3	2	1	0	fhz2				nfd			
			F	E	D	C	B	A	9	8																									
			afs																																
			7	6	5	4	3	2	1	0																									
			fhz2				nfd																												
			bit	Meaning when "0" is set	Meaning when "1" is set																														
			0	Set the filter depth for Notch filter (SV038: FHZ1).																															
			1	The control is stabilized by making the filter shallower.																															
			2	nfd	Value 0 2 4 6 8 A C E																														
			3	Depth (dB)	Infntly deep -18.1 -12.0 -8.5 -6.0 -4.1 -2.5 -1.2																														
		Deep← → Shallow																																	
4	fhz2	Set the operation frequency of Notch filter 2.																																	
5		00: No operation 01:2250Hz 10:1125Hz 11:750Hz																																	
6																																			
7																																			
8	afs	Set the vibration sensitivity of the adaptive filter. If the filter depth is not deep enough (generally 70% or more) and the vibration cannot be sufficiently eliminated, raise the value.																																	
9																																			
A																																			
B																																			
C																																			
D																																			
E																																			
F																																			

(Note) Set to "0" for bits with no particular description.

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																
2234	SV034 SSF3 Servo function selection 3	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 12.5%; text-align: center;">F</td> <td style="width: 12.5%; text-align: center;">E</td> <td style="width: 12.5%; text-align: center;">D</td> <td style="width: 12.5%; text-align: center;">C</td> <td style="width: 12.5%; text-align: center;">B</td> <td style="width: 12.5%; text-align: center;">A</td> <td style="width: 12.5%; text-align: center;">9</td> <td style="width: 12.5%; text-align: center;">8</td> </tr> <tr> <td style="border: none;"></td> <td style="border: none;"></td> <td style="border: none;"></td> <td style="border: none;"></td> <td style="border: none;"></td> <td style="border: none;"></td> <td style="border: none;"></td> <td style="border: none;"></td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td style="text-align: center;">daf2</td> <td style="text-align: center;">daf1</td> <td style="text-align: center;">dac2</td> <td style="text-align: center;">dac1</td> <td colspan="4" style="text-align: center;">mon</td> </tr> </table>	F	E	D	C	B	A	9	8									7	6	5	4	3	2	1	0	daf2	daf1	dac2	dac1	mon				
		F	E	D	C	B	A	9	8																										
		7	6	5	4	3	2	1	0																										
		daf2	daf1	dac2	dac1	mon																													
		bit	Meaning when "0" is set	Meaning when "1" is set																															
		0	NC servo monitor MAX current display data changeover																																
		1	Set-ting	MAX current 1	MAX current 2																														
		2	mon	0	0																														
		3	1	1	1																														
	2	2	2																																
	3	3	-																																
	4	4	Adaptive filter operation gain (%)																																
	5	5	Regenerative operation frequency monitor (The number of times/sec)																																
	6	6	Max. current FB value for one second (%)																																
	7	7	Max. disturbance torque for two seconds (%)																																
	8 to F	Setting prohibited																																	
4	dac1	D/A output ch.1 overflow setting	D/A output ch.1 clamp setting																																
5	dac2	D/A output ch.2 overflow setting	D/A output ch.2 clamp setting																																
6	daf1	D/A output ch.1 no filter	D/A output ch.1 filter setting																																
7	daf2	D/A output ch.2 no filter	D/A output ch.2 filter setting																																
8																																			
9																																			
A																																			
B																																			
C																																			
D																																			
E																																			
F																																			

(Note) Set to "0" for bits with no particular description.

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																																									
2235	SV035 SSF4	Servo function selection 4																																																										
		<table style="margin: auto; border-collapse: collapse;"> <tr> <td style="padding: 2px;">F</td> <td style="padding: 2px;">E</td> <td style="padding: 2px;">D</td> <td style="padding: 2px;">C</td> <td style="padding: 2px;">B</td> <td style="padding: 2px;">A</td> <td style="padding: 2px;">9</td> <td style="padding: 2px;">8</td> </tr> <tr> <td style="border: 1px solid black; padding: 2px;">cl2n</td> <td colspan="2" style="border: 1px solid black; padding: 2px;">clG1</td> <td style="border: 1px solid black; padding: 2px;"></td> <td style="border: 1px solid black; padding: 2px;"></td> <td style="border: 1px solid black; padding: 2px;"></td> <td style="border: 1px solid black; padding: 2px;"></td> <td style="border: 1px solid black; padding: 2px;"></td> </tr> <tr> <td style="padding: 2px;">7</td> <td style="padding: 2px;">6</td> <td style="padding: 2px;">5</td> <td style="padding: 2px;">4</td> <td style="padding: 2px;">3</td> <td style="padding: 2px;">2</td> <td style="padding: 2px;">1</td> <td style="padding: 2px;">0</td> </tr> <tr> <td style="border: 1px solid black; padding: 2px;"></td> <td style="border: 1px solid black; padding: 2px;"></td> <td style="border: 1px solid black; padding: 2px;"></td> <td style="border: 1px solid black; padding: 2px;"></td> <td style="border: 1px solid black; padding: 2px;"></td> <td style="border: 1px solid black; padding: 2px;"></td> <td style="border: 1px solid black; padding: 2px;"></td> <td style="border: 1px solid black; padding: 2px;"></td> </tr> </table>	F	E	D	C	B	A	9	8	cl2n	clG1							7	6	5	4	3	2	1	0																																		
F	E	D	C	B	A	9	8																																																					
cl2n	clG1																																																											
7	6	5	4	3	2	1	0																																																					
		<table border="1" style="margin: auto; border-collapse: collapse; width: 100%;"> <thead> <tr> <th style="width: 10%;">bit</th> <th style="width: 45%;">Meaning when "0" is set</th> <th style="width: 45%;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr><td>0</td><td></td><td></td></tr> <tr><td>1</td><td></td><td></td></tr> <tr><td>2</td><td></td><td></td></tr> <tr><td>3</td><td></td><td></td></tr> <tr><td>4</td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td></tr> <tr> <td>C</td> <td colspan="2">Collision detection method 1</td> </tr> <tr> <td>D</td> <td colspan="2">Set the collision detection level during cutting feed (G1).</td> </tr> <tr> <td>clG1</td> <td colspan="2">The G1 collision detection level=SV060*clG1.</td> </tr> <tr> <td>E</td> <td colspan="2">When clG1=0, the collision detection method 1 during cutting feed won't function.</td> </tr> <tr> <td>F</td> <td>cl2n</td> <td>Collision detection method 2 valid</td> </tr> <tr> <td></td> <td></td> <td>Collision detection method 2 invalid</td> </tr> </tbody> </table>	bit	Meaning when "0" is set	Meaning when "1" is set	0			1			2			3			4			5			6			7			8			9			A			B			C	Collision detection method 1		D	Set the collision detection level during cutting feed (G1).		clG1	The G1 collision detection level=SV060*clG1.		E	When clG1=0, the collision detection method 1 during cutting feed won't function.		F	cl2n	Collision detection method 2 valid			Collision detection method 2 invalid	
bit	Meaning when "0" is set	Meaning when "1" is set																																																										
0																																																												
1																																																												
2																																																												
3																																																												
4																																																												
5																																																												
6																																																												
7																																																												
8																																																												
9																																																												
A																																																												
B																																																												
C	Collision detection method 1																																																											
D	Set the collision detection level during cutting feed (G1).																																																											
clG1	The G1 collision detection level=SV060*clG1.																																																											
E	When clG1=0, the collision detection method 1 during cutting feed won't function.																																																											
F	cl2n	Collision detection method 2 valid																																																										
		Collision detection method 2 invalid																																																										
		(Note) Set to "0" for bits with no particular description.																																																										

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range																																																																			
2236 (PR)	SV036 PTYP	Regenerative resistor type	<table border="1" style="width: 100%; text-align: center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td colspan="4">amp</td> <td colspan="4">rtyp</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td colspan="4">emgx</td> <td></td><td></td><td></td><td></td> </tr> </table>	F	E	D	C	B	A	9	8	amp				rtyp				7	6	5	4	3	2	1	0	emgx																																										
			F	E	D	C	B	A	9	8																																																												
			amp				rtyp																																																															
			7	6	5	4	3	2	1	0																																																												
			emgx																																																																			
			<table border="1" style="width: 100%; text-align: center;"> <tr> <th>bit</th> <th colspan="2">Explanation</th> </tr> <tr> <td>0</td> <td colspan="2">Always set to "0(0000)".</td> </tr> <tr> <td>1</td> <td colspan="2"></td> </tr> <tr> <td>2</td> <td colspan="2"></td> </tr> <tr> <td>3</td> <td colspan="2"></td> </tr> <tr> <td>4</td> <td colspan="2">Set the external emergency stop function. (Setting is prohibited for values with no description.)</td> </tr> <tr> <td>5</td> <td rowspan="4">emgx</td> <td> <table border="1" style="width: 100%; text-align: center;"> <tr> <th>Setting</th> <th>Explanation</th> </tr> <tr> <td>0</td> <td>External emergency stop invalid</td> </tr> <tr> <td>4</td> <td>External emergency stop valid</td> </tr> </table> </td> </tr> <tr> <td>6</td> <td></td> </tr> <tr> <td>7</td> <td></td> </tr> <tr> <td>8</td> <td rowspan="8">rtyp</td> <td>Set the regenerative resistor type.</td> </tr> <tr> <td>9</td> <td> <table border="1" style="width: 100%; text-align: center;"> <tr> <th>Setting</th> <th>Explanation</th> </tr> <tr> <td>0</td> <td>Drive unit standard built-in resistor (SVJ2-01 doesn't have a built-in resistor)</td> </tr> <tr> <td>1</td> <td>Setting prohibited</td> </tr> <tr> <td>2</td> <td>MR-RB032</td> </tr> <tr> <td>3</td> <td>MR-RB12 or GZG200W390HMK</td> </tr> <tr> <td>4</td> <td>MR-RB32 or GZG200W1200HMK: 3 units connected in parallel</td> </tr> <tr> <td>5</td> <td>MR-RB30 or GZG200W390HMK: 3 units connected in parallel</td> </tr> <tr> <td>6</td> <td>MR-RB50 or GZG300W390HMK: 3 units connected in parallel</td> </tr> <tr> <td>7 to F</td> <td>Setting prohibited</td> </tr> </table> </td> </tr> <tr> <td>A</td> <td></td> </tr> <tr> <td>B</td> <td></td> </tr> <tr> <td>C</td> <td rowspan="4">amp</td> <td>Always set to "0(0000)".</td> </tr> <tr> <td>D</td> <td></td> </tr> <tr> <td>E</td> <td></td> </tr> <tr> <td>F</td> <td></td> </tr> </table>	bit	Explanation		0	Always set to "0(0000)".		1			2			3			4	Set the external emergency stop function. (Setting is prohibited for values with no description.)		5	emgx	<table border="1" style="width: 100%; text-align: center;"> <tr> <th>Setting</th> <th>Explanation</th> </tr> <tr> <td>0</td> <td>External emergency stop invalid</td> </tr> <tr> <td>4</td> <td>External emergency stop valid</td> </tr> </table>	Setting	Explanation	0	External emergency stop invalid	4	External emergency stop valid	6		7		8	rtyp	Set the regenerative resistor type.	9	<table border="1" style="width: 100%; text-align: center;"> <tr> <th>Setting</th> <th>Explanation</th> </tr> <tr> <td>0</td> <td>Drive unit standard built-in resistor (SVJ2-01 doesn't have a built-in resistor)</td> </tr> <tr> <td>1</td> <td>Setting prohibited</td> </tr> <tr> <td>2</td> <td>MR-RB032</td> </tr> <tr> <td>3</td> <td>MR-RB12 or GZG200W390HMK</td> </tr> <tr> <td>4</td> <td>MR-RB32 or GZG200W1200HMK: 3 units connected in parallel</td> </tr> <tr> <td>5</td> <td>MR-RB30 or GZG200W390HMK: 3 units connected in parallel</td> </tr> <tr> <td>6</td> <td>MR-RB50 or GZG300W390HMK: 3 units connected in parallel</td> </tr> <tr> <td>7 to F</td> <td>Setting prohibited</td> </tr> </table>	Setting	Explanation	0	Drive unit standard built-in resistor (SVJ2-01 doesn't have a built-in resistor)	1	Setting prohibited	2	MR-RB032	3	MR-RB12 or GZG200W390HMK	4	MR-RB32 or GZG200W1200HMK: 3 units connected in parallel	5	MR-RB30 or GZG200W390HMK: 3 units connected in parallel	6	MR-RB50 or GZG300W390HMK: 3 units connected in parallel	7 to F	Setting prohibited	A		B		C	amp	Always set to "0(0000)".	D		E		F	
			bit	Explanation																																																																		
			0	Always set to "0(0000)".																																																																		
			1																																																																			
			2																																																																			
3																																																																						
4	Set the external emergency stop function. (Setting is prohibited for values with no description.)																																																																					
5	emgx	<table border="1" style="width: 100%; text-align: center;"> <tr> <th>Setting</th> <th>Explanation</th> </tr> <tr> <td>0</td> <td>External emergency stop invalid</td> </tr> <tr> <td>4</td> <td>External emergency stop valid</td> </tr> </table>	Setting	Explanation	0	External emergency stop invalid	4	External emergency stop valid																																																														
Setting		Explanation																																																																				
0		External emergency stop invalid																																																																				
4		External emergency stop valid																																																																				
6																																																																						
7																																																																						
8	rtyp	Set the regenerative resistor type.																																																																				
9		<table border="1" style="width: 100%; text-align: center;"> <tr> <th>Setting</th> <th>Explanation</th> </tr> <tr> <td>0</td> <td>Drive unit standard built-in resistor (SVJ2-01 doesn't have a built-in resistor)</td> </tr> <tr> <td>1</td> <td>Setting prohibited</td> </tr> <tr> <td>2</td> <td>MR-RB032</td> </tr> <tr> <td>3</td> <td>MR-RB12 or GZG200W390HMK</td> </tr> <tr> <td>4</td> <td>MR-RB32 or GZG200W1200HMK: 3 units connected in parallel</td> </tr> <tr> <td>5</td> <td>MR-RB30 or GZG200W390HMK: 3 units connected in parallel</td> </tr> <tr> <td>6</td> <td>MR-RB50 or GZG300W390HMK: 3 units connected in parallel</td> </tr> <tr> <td>7 to F</td> <td>Setting prohibited</td> </tr> </table>	Setting	Explanation	0	Drive unit standard built-in resistor (SVJ2-01 doesn't have a built-in resistor)	1	Setting prohibited	2	MR-RB032	3	MR-RB12 or GZG200W390HMK	4	MR-RB32 or GZG200W1200HMK: 3 units connected in parallel	5	MR-RB30 or GZG200W390HMK: 3 units connected in parallel	6	MR-RB50 or GZG300W390HMK: 3 units connected in parallel	7 to F	Setting prohibited																																																		
Setting		Explanation																																																																				
0		Drive unit standard built-in resistor (SVJ2-01 doesn't have a built-in resistor)																																																																				
1		Setting prohibited																																																																				
2		MR-RB032																																																																				
3		MR-RB12 or GZG200W390HMK																																																																				
4		MR-RB32 or GZG200W1200HMK: 3 units connected in parallel																																																																				
5	MR-RB30 or GZG200W390HMK: 3 units connected in parallel																																																																					
6	MR-RB50 or GZG300W390HMK: 3 units connected in parallel																																																																					
7 to F	Setting prohibited																																																																					
A																																																																						
B																																																																						
C	amp	Always set to "0(0000)".																																																																				
D																																																																						
E																																																																						
F																																																																						

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range
2237	SV037 JL	Load inertia scale Set "the motor inertia + motor axis conversion load inertia" in respect to the motor inertia. $SV037 (JL) = \frac{Jl+Jm}{Jm} * 100$ Jm: Motor inertia Jl: Motor axis conversion load inertia	0 to 5000 (%)
2238	SV038 FHZ1	Notch filter frequency 1 Set the vibration frequency to suppress if machine vibration occurs. (Valid at 72 or more) When not using, set to "0".	0 to 3000 (Hz)
2239	SV039 LMCD	Lost motion compensation timing Set this when the lost motion compensation timing does not match. Adjust by increasing the value by 10 at a time.	0 to 2000 (ms)
2240	SV040 LMCT	Non-sensitive band in feed forward control Set the non-sensitive band of the lost motion compensation and overshooting compensation during the feed forward control. When "0" is set, the actual value that will be set is 2µm. Adjust by increasing by 1µm.	0 to 100 (µm)
2241	SV041 LMC2	Lost motion compensation 2 Set this with SV016 (LMC1) only when you wish to set the lost motion compensation amount to be different depending on the command directions. Set to "0" as a standard.	-1 to 200 (Stall [rated] current %)
2242	SV042 OVS2	Overshooting compensation 2 Set this with SV031 (OVS1) only when you wish to set the overshooting compensation amount to be different depending on the command directions. Set to "0" as a standard.	-1 to 100 (Stall [rated] current %)
2243	SV043 OBS1	Disturbance observer filter frequency Set the disturbance observer filter band. The standard setting is "300". Lower the setting by 50 at a time if vibration occurs. To use the disturbance observer, also set SV037 (JL) and SV044 (OBS2). When not using, set to "0".	0 to 1000 (rad/s)
2244	SV044 OBS2	Disturbance observer gain Set the disturbance observer gain. The standard setting is "100" to "300". To use the disturbance observer, also set SV037 (JL) and SV043 (OBS1). When not using, set to "0".	0 to 1000 (%)
2245	SV045 TRUB	Frictional torque Set the frictional torque when using the collision detection function.	0 to 100 (Stall [rated] current %)
2246	SV046	Not used. Set to "0".	0
2247	SV047 EC	Inductive voltage compensation gain Set the inductive voltage compensation gain. Set to "100" as a standard. If the current FB peak exceeds the current command peak, lower the gain.	0 to 200 (%)
2248	SV048 EMGrT	Vertical axis drop prevention time Input a length of time to prevent the vertical axis from dropping by delaying Ready OFF until the brake works when the emergency stop occurs. Increase the setting by 100ms at a time and set the value where the axis does not drop.	0 to 2000 (ms)

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range	
2249	SV049 PGN1sp	Position loop gain 1 in spindle synchronous control	Set the position loop gain during the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). Set the same value as the value of the spindle parameter, position loop gain in synchronous control. When performing the SHG control, set this with SV050 (PGN2sp) and SV058 (SHGCsp).	1 to 200 (rad/s)
2250	PGN2sp	Position loop gain 2 in spindle synchronous control	Set this with SV049 (PGN1sp) and SV058 (SHGCsp) if you wish to perform the SHG control in the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2251	SV051		Not used. Set to "0".	0
2252	SV052		Not used. Set to "0".	0
2253	SV053 OD3	Excessive error detection width in special control	Set the excessive error detection width when servo ON in a special control (initial absolute position setting, stopper control, etc.). If "0" is set, excessive error detection won't be performed when servo ON during a special control.	0 to 32767 (mm)
2254	SV054		Not used. Set to "0".	0
2255	SV055		Not used. Set to "0".	0
2256	SV056 EMGt	Deceleration time constant at emergency stop	Set the time constant used for the deceleration control at emergency stop. Set a length of time that takes from rapid traverse rate (rapid) to stopping. Normally, set the same value as the rapid traverse acceleration/deceleration time constant.	0 to 5000 (ms)
2257	SV057 SHGC	SHG control gain	When performing the SHG control, set this with S003 (PGN1) and SV004 (PGN2). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2258	SV058 SHGCsp	SHG control gain in spindle synchronous control	Set this with SV049 (PGN1sp) and SV050 (PGN2sp) if you wish to perform the SHG control in the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2259	SV059 TCNV	Collision detection torque estimating gain	To use the collision detection function, set the torque estimating gain. In the case of MDS-B-SVJ2, the value is the same as the load inertia ratio that includes the motor inertia. (=SV037:JL) If acceleration/deceleration is performed after setting SV034.mon=3 and SV060=0, the load inertia ratio will be displayed on the NC monitor screen.	0 to 5000 (%)
2260	SV060 TLMT	Collision detection level	When using the collision detection function, set the collision detection level during the G0 feeding. If "0" is set, none of the collision detection function will work.	0 to 200 (Stall [rated] current %)

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

No.	Items	Details	Setting range
2261	SV061 DA1NO	D/A output channel 1 data No.	0 to 102
2262	SV062 DA2NO	D/A output channel 2 data No.	
2263	SV063 DA1MPY	D/A output channel 1 output scale	-32768 to 32767 (Unit: 1/256)
2264	SV064 DA2MPY	D/A output channel 2 output scale	
2265	SV065	Not used. Set to "0".	0

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

(2) Initial setting value

(a) HC**/HC**R series

Motor		HC 52	HC 102*	HC 102	HC 152*	HC 152	HC 202*	HC 202	HC 352*
Drive unit capacity		06	07	10	10	20	10	20	20
SV001	PC1	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0
SV005	VGN1	50	80	50	80	50	115	80	130
SV006		0	0	0	0	0	0	0	0
SV007		0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	8192	4096	8192	4096	8192	2048	4096	2048
SV010	IDA	8192	4096	8192	4096	8192	2048	4096	2048
SV011	IQG	512	256	384	256	384	256	384	256
SV012	IDG	512	256	384	256	384	256	384	256
SV013	ILMT	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150
SV023	OD1	-	-	-	-	-	-	-	-
SV024	INP	50	50	50	50	50	50	50	50
SV025	MTYP	22B0	22B1	22B1	22B2	22B2	22B3	22B3	22B4
SV026	OD2	-	-	-	-	-	-	-	-
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0
SV029		0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

Motor		HC 52	HC 102*	HC 102	HC 152*	HC 152	HC 202*	HC 202	HC 352*
Drive unit capacity		06	07	10	10	20	10	20	20
SV033	SSF2	0	0	0	0	0	0	0	0
SV034	SSF3	0	0	0	0	0	0	0	0
SV035	SSF4	0	0	0	0	0	0	0	0
SV036	PTYP	-	-	-	-	-	-	-	-
SV037	JL	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0
SV051		0	0	0	0	0	0	0	0
SV052		0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0
SV054		0	0	0	0	0	0	0	0
SV055		0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

Motor		HC 53	HC 103	HC 153	HC 203*	HC 103R	HC 153R	HC 203R
Drive unit capacity		06	10	20	20	10	10	20
SV001	PC1	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0
SV005	VGN1	80	80	80	100	10	10	10
SV006		0	0	0	0	0	0	0
SV007		0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	2048	8192	8192	8192
SV010	IDA	4096	4096	4096	2048	8192	8192	8192
SV011	IQG	256	256	256	200	384	384	256
SV012	IDG	256	256	256	200	384	384	256
SV013	ILMT	500	500	500	500	500	500	500
SV014	ILMT _{sp}	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150
SV023	OD1	-	-	-	-	-	-	-
SV024	INP	50	50	50	50	50	50	50
SV025	MTYP	22C0	22C1	22C2	22C3	22E1	22E2	22E3
SV026	OD2	-	-	-	-	-	-	-
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0
SV029		0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

Motor		HC 53	HC 103	HC 153	HC 203*	HC 103R	HC 153R	HC 203R
Drive unit capacity		06	10	20	20	10	10	20
SV033	SSF2	0	0	0	0	0	0	0
SV034	SSF3	0	0	0	0	0	0	0
SV035	SSF4	0	0	0	0	0	0	0
SV036	PTYP	-	-	-	-	-	-	-
SV037	JL	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0
SV051		0	0	0	0	0	0	0
SV052		0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0
SV054		0	0	0	0	0	0	0
SV055		0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

(b) HA**N series

Motor		HA 40N	HA 80N	HA 100N	HA 200N*	HA 053N	HA 13N	HA 23N	HA 33N	HA 43N	HA 83N	HA 103N*
Drive unit capacity		06	10	20	20	01	01	03	03	06	10	20
SV001	PC1	-	-	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0	0	0	0
SV005	VGN1	90	150	150	220	35	35	35	35	120	150	180
SV006		0	0	0	0	0	0	0	0	0	0	0
SV007		0	0	0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048	2048	2048	2048	2048	2048
SV011	IQG	512	512	512	200	256	256	256	256	512	512	512
SV012	IDG	512	512	512	200	256	256	256	256	512	512	512
SV013	ILMT	500	500	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150	150	150
SV023	OD1	-	-	-	-	-	-	-	-	-	-	-
SV024	INP	50	50	50	50	50	50	50	50	50	50	50
SV025	MTYP	2200	2201	2202	2203	228 C	228 D	228E	228F	2280	2281	2282
SV026	OD2	-	-	-	-	-	-	-	-	-	-	-
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0	0	0
SV029		0	0	0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

Motor		HA 40N	HA 80N	HA 100N	HA 200N*	HA 053N	HA 13N	HA 23N	HA 33N	HA 43N	HA 83N	HA 103N*
Drive unit capacity		06	10	20	20	01	01	03	03	06	10	20
SV033	SSF2	0	0	0	0	0	0	0	0	0	0	0
SV034	SSF3	0	0	0	0	0	0	0	0	0	0	0
SV035	SSF4	0	0	0	0	0	0	0	0	0	0	0
SV036	PTYP	-	-	-	-	-	-	-	-	-	-	-
SV037	JL	0	0	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0	0	0
SV051		0	0	0	0	0	0	0	0	0	0	0
SV052		0	0	0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0	0	0
SV054		0	0	0	0	0	0	0	0	0	0	0
SV055		0	0	0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

(c) HC-SF series

Motor		HC-SF 52	HC-SF 102	HC-SF 152	HC-SF 202	HC-SF 352	HC-SF 53	HC-SF 103	HC-SF 153	HC-SF 203	HC-SF 353
Drive unit capacity		06	07	10	10	20	06	07	10	10	20
SV001	PC1	-	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0	0	0
SV005	VGN1	80	80	80	120	130	90	90	130	180	180
SV006		0	0	0	0	0	0	0	0	0	0
SV007		0	0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	8192	4096	4096	2048	2048	4096	4096	2048	2048	2048
SV010	IDA	8192	4096	4096	2048	2048	4096	4096	2048	2048	2048
SV011	IQG	500	300	300	300	250	250	250	200	200	200
SV012	IDG	500	300	300	300	250	250	250	200	200	200
SV013	ILMT	500	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-	-
SV019	RNG1	16	16	16	16	16	16	16	16	16	16
SV020	RNG2	16	16	16	16	16	16	16	16	16	16
SV021	OLT	60	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150	150
SV023	OD1	-	-	-	-	-	-	-	-	-	-
SV024	INP	50	50	50	50	50	50	50	50	50	50
SV025	MTYP	22B0	22B1	22B2	22B3	22B4	22C0	22C1	22C2	22C3	22C4
SV026	OD2	-	-	-	-	-	-	-	-	-	-
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0	0
SV029		0	0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

Motor		HC-SF 52	HC-SF 102	HC-SF 152	HC-SF 202	HC-SF 352	HC-SF 53	HC-SF 103	HC-SF 153	HC-SF 203	HC-SF 353
Drive unit capacity		06	07	10	10	20	06	07	10	10	20
SV033	SSF2	0	0	0	0	0	0	0	0	0	0
SV034	SSF3	0	0	0	0	0	0	0	0	0	0
SV035	SSF4	0	0	0	0	0	0	0	0	0	0
SV036	PTYP	-	-	-	-	-	-	-	-	-	-
SV037	JL	0	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0	0
SV051		0	0	0	0	0	0	0	0	0	0
SV052		0	0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0	0
SV054		0	0	0	0	0	0	0	0	0	0
SV055		0	0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

(d) HC-RF/HA-FF series

Motor		HC-RF 103	HC-RF 153	HC-RF 203	HA-FF 053	HA-FF 13	HA-FF 23	HA-FF 33	HA-FF 43	HA-FF 63
Drive unit capacity		10	10	20	01	01	03	03	04	06
SV001	PC1	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0	0
SV005	VGN1	10	10	10	10	13	13	18	20	20
SV006		0	0	0	0	0	0	0	0	0
SV007		0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	8192	8192	8192	8192	4096	4096	4096	4096	4096
SV010	IDA	8192	8192	8192	8192	4096	4096	4096	4096	4096
SV011	IQG	384	384	256	500	300	700	500	700	700
SV012	IDG	384	384	256	500	300	700	500	700	700
SV013	ILMT	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-
SV019	RNG1	16	16	16	8	8	8	8	8	8
SV020	RNG2	16	16	16	8	8	8	8	8	8
SV021	OLT	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150
SV023	OD1	-	-	-	-	-	-	-	-	-
SV024	INP	50	50	50	50	50	50	50	50	50
SV025	MTYP	22E1	22E2	22E3	227C	227D	227E	227F	2270	2271
SV026	OD2	-	-	-	-	-	-	-	-	-
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0
SV029		0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

Motor		HC-RF 103	HC-RF 153	HC-RF 203	HA-FF 053	HA-FF 13	HA-FF 23	HA-FF 33	HA-FF 43	HA-FF 63
Drive unit capacity		10	10	20	01	01	03	03	04	06
SV033	SSF2	0	0	0	0	0	0	0	0	0
SV034	SSF3	0	0	0	0	0	0	0	0	0
SV035	SSF4	0	0	0	0	0	0	0	0	0
SV036	PTYP	-	-	-	-	-	-	-	-	-
SV037	JL	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0
SV051		0	0	0	0	0	0	0	0	0
SV052		0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0
SV054		0	0	0	0	0	0	0	0	0
SV055		0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

(e) HC-MF series

Motor		HC-MF 053	HC-MF 13	HC-MF 23	HC-MF 43	HC-MF 73
Drive unit capacity		01	01	03	04	07
SV001	PC1	-	-	-	-	-
SV002	PC2	-	-	-	-	-
SV003	PGN1	33	33	33	33	33
SV004	PGN2	0	0	0	0	0
SV005	VGN1	6	6	6	6	8
SV006		0	0	0	0	0
SV007		0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	4096	4096
SV010	IDA	4096	4096	4096	4096	4096
SV011	IQG	200	300	400	300	300
SV012	IDG	200	300	400	300	300
SV013	ILMT	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500
SV015	FFC	0	0	0	0	0
SV016	LMC1	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-
SV019	RNG1	8	8	8	8	8
SV020	RNG2	8	8	8	8	8
SV021	OLT	60	60	60	60	60
SV022	OLL	150	150	150	150	150
SV023	OD1	-	-	-	-	-
SV024	INP	50	50	50	50	50
SV025	MTYP	229C	229D	229E	2290	2291
SV026	OD2	-	-	-	-	-
SV027	SSF1	4000	4000	4000	4000	4000
SV028		0	0	0	0	0
SV029		0	0	0	0	0
SV030	IVC	0	0	0	0	0
SV031	OVS1	0	0	0	0	0
SV032	TOF	0	0	0	0	0

7. SERVO PARAMETERS
7.1 MDS-B-SVJ2

Motor		HC-MF 053	HC-MF 13	HC-MF 23	HC-MF 43	HC-MF 73
Drive unit capacity		01	01	03	04	07
SV033	SSF2	0	0	0	0	0
SV034	SSF3	0	0	0	0	0
SV035	SSF4	0	0	0	0	0
SV036	PTYP	-	-	-	-	-
SV037	JL	0	0	0	0	0
SV038	FHz1	0	0	0	0	0
SV039	LMCD	0	0	0	0	0
SV040	LMCT	0	0	0	0	0
SV041	LMC2	0	0	0	0	0
SV042	OVS2	0	0	0	0	0
SV043	OBS1	0	0	0	0	0
SV044	OBS2	0	0	0	0	0
SV045	TRUB	0	0	0	0	0
SV046		0	0	0	0	0
SV047	EC	100	100	100	100	100
SV048	EMGr	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0
SV051		0	0	0	0	0
SV052		0	0	0	0	0
SV053	OD3	0	0	0	0	0
SV054		0	0	0	0	0
SV055		0	0	0	0	0
SV056	EMGt	0	0	0	0	0
SV057	SHGC	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0
SV059	TCNV	0	0	0	0	0
SV060	TLMT	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0
SV065		0	0	0	0	0

7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)


(1) Details for servo parameters

For parameters marked with a (PR) in the table, turn the NC power OFF after setting. After the power is turned ON again, the parameter is validated.

⚠ CAUTION

⚠ In the explanation on bits, set all bits not used, including blank bits, to "0".

No.	Items	Details	Setting range
2201 (PR)	SV001 PC1	Motor side gear ratio	1 to 32767
2202 (PR)	SV002 PC2	Machine side gear ratio	1 to 32767
2203	SV003 PGN1	Position loop gain 1	1 to 200 (In case of MDS-B-Vx4, 1 to 400) (rad/s)
2204	SV004 PGN2	Position loop gain 2	0 to 999 (rad/s)
2205	SV005 VGN1	Speed loop gain 1	1 to 999
2206	SV006 VGN2	Speed loop gain 2	-1000 to 1000



7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range	
2207	SV007 VIL	Speed loop delay compensation	Set this when the limit cycle occurs in the full-closed loop, or overshooting occurs in positioning. Select the control method with SV027 (SSF1)/bit1, 0 (vcnt). Normally, use "Changeover type 2". When you set this parameter, make sure to set the torque offset (SV032 (TOF)). When not using, set to "0".	0 to 32767
		No changeover When SV027 (SSF1)/ bit1, 0 (vcnt)=00 The delay compensation control is always valid.		
		Changeover type 1 When SV027 (SSF1)/ bit1, 0 (vcnt)=01 The delay compensation control works when the command from the NC is "0". Overshooting that occurs during pulse feeding can be suppressed.		
		Changeover type 2 When SV027 (SSF1)/ bit1, 0 (vcnt)=10 The delay compensation control works when the command from the NC is "0" and the position droop is "0". Overshooting or the limit cycle that occurs during pulse feeding or positioning can be suppressed.		
2208	SV008 VIA	Speed loop lead compensation	Set the gain of the speed loop integration control. The standard setting is "1364". During the SHG control, the standard setting is "1900". Adjust the value by increasing/decreasing it by about 100 at a time. Raise this value to improve contour tracking precision in high-speed cutting. Lower this value when the position droop vibrates (10 to 20Hz).	1 to 9999
2209	SV009 IQA	Current loop q axis lead compensation	Set the gain of current loop. As this setting is determined by the motor's electrical characteristics, the setting is fixed for each type of motor.	1 to 20480
2210	SV010 IDA	Current loop d axis lead compensation	Set the standard values for all the parameters depending on each motor type.	
2211	SV011 IQG	Current loop q axis gain		
2212	SV012 IDG	Current loop d axis gain		
2213	SV013 ILMT	Current limit value	Set the normal current (torque) limit value. (Limit values for both + and - direction.) When the value is "500" (a standard setting), the maximum torque is determined by the specification of the motor.	0 to 999 (Stall [rated] current %)
2214	SV014 ILMTsp	Current limit value in special control	Set the current (torque) limit value in a special control (initial absolute position setting, stopper control, etc). (Limit values for both of the + and - directions.) Set to "500" when not using.	0 to 999 (Stall [rated] current %)

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range
2215	SV015 FFC	Acceleration rate feed forward gain When a relative error in the synchronous control is large, apply this parameter to the axis that is delaying. The standard setting value is "0". For the SHG control, set to "100". To adjust a relative error in acceleration/deceleration, increase the value by 50 to 100 at a time.	0 to 999(%)
2216	SV016 LMC1	<p>Lost motion compensation 1</p> <p>Set this when the protrusion (that occurs due to the non-sensitive band by friction, torsion, backlash, etc) at quadrant change is too large. This compensates the torque at quadrant change. This is valid only when the lost motion compensation (SV027 (SSF1/lmc)) is selected.</p> <p>Type 1: When SV027 (SSF1)/ bit9, 8 (lmc)=01 Set the compensation amount based on the motor torque before the quadrant change. The standard setting is "100". Setting to "0" means the compensation amount is zero. Normally, use Type 2.</p> <p>Type 2: When SV027 (SSF1)/ bit9, 8 (lmc)=10 Set the compensation amount based on the stall (rated) current of the motor. The standard setting is double of the friction torque. Setting to "0" means the compensation amount is zero.</p> <p>When you wish different compensation amount depending on the direction When SV041 (LMC2) is "0", compensate with the value of SV016 (LMC1) in both of the + and -directions. If you wish to change the compensation amount depending on the command direction, set this and SV041 (LMC2). (SV016: + direction, SV041: - direction. However, the directions may be opposite depending on other settings.) When "-1" is set, the compensation won't be performed in the direction of the command.</p>	<p></p> <p>-1 to 200 (%)</p> <p>-1 to 100 (Stall [rated] current %)</p> <p></p>

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range																																
2217 (PR)	SV017 SPEC	Servo specification selection	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 12.5%; text-align: center;">F</td> <td style="width: 12.5%; text-align: center;">E</td> <td style="width: 12.5%; text-align: center;">D</td> <td style="width: 12.5%; text-align: center;">C</td> <td style="width: 12.5%; text-align: center;">B</td> <td style="width: 12.5%; text-align: center;">A</td> <td style="width: 12.5%; text-align: center;">9</td> <td style="width: 12.5%; text-align: center;">8</td> </tr> <tr> <td colspan="4" style="text-align: center; border: 1px solid black;">spm</td> <td style="text-align: center; border: 1px solid black;">drvall</td> <td style="text-align: center; border: 1px solid black;">drvup</td> <td style="text-align: center; border: 1px solid black;">mpt3</td> <td style="text-align: center; border: 1px solid black;">mp</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td style="text-align: center; border: 1px solid black;">abs</td> <td style="text-align: center; border: 1px solid black;"></td> <td style="text-align: center; border: 1px solid black;">vdir</td> <td style="text-align: center; border: 1px solid black;">fdir</td> <td style="text-align: center; border: 1px solid black;">vfb</td> <td style="text-align: center; border: 1px solid black;">seqh</td> <td style="text-align: center; border: 1px solid black;">dfbx</td> <td style="text-align: center; border: 1px solid black;">fdir2</td> </tr> </table>	F	E	D	C	B	A	9	8	spm				drvall	drvup	mpt3	mp	7	6	5	4	3	2	1	0	abs		vdir	fdir	vfb	seqh	dfbx	fdir2
			F	E	D	C	B	A	9	8																									
			spm				drvall	drvup	mpt3	mp																									
			7	6	5	4	3	2	1	0																									
			abs		vdir	fdir	vfb	seqh	dfbx	fdir2																									
			bit	Meaning when "0" is set	Meaning when "1" is set																														
			0	fdir2	Speed feedback forward polarity	Speed feedback reverse polarity																													
			1	dfbx	Dual feedback control stop	Dual feedback control start																													
			2	seqh	READY/Servo ON time normal	READY/Servo ON time high speed																													
			3	vfb	Speed feedback filter stop	Speed feedback filter stop (2250Hz)																													
4	fdir	Position feedback forward polarity	Position feedback reverse polarity																																
5	vdir	Standard setting	HA motor (4 pole motor) Detector installation position 90 degrees (B, D)																																
6																																			
7	abs	Incremental control	Absolute position control																																
8	mp	MP scale 360P (2mm pitch)	MP scale 720P (1mm pitch)																																
9	mpt3	MP scale ABS detection type 1, 2	MP scale ABS detection type 3																																
A	drvup	Standard setting	Possible to connect a drive unit whose capacity is 1 rank higher/lower than the standard one.																																
B	drvall	Setting for normal use	Possible to connect a drive unit with any capacity.																																
C		0 : Setting for normal use																																	
D		1 : When using the S type drive unit (Only in the case of MDS-C1-Vx)																																	
E	spm																																		
F		2 to F : Setting prohibited																																	
			(Note 1) Set to "0" for bits with no particular description. (Note 2) bit3 (vfb) is only for MDS-C1-Vx.																																

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range																																							
2218 (PR)	SV018 PIT	Ball screw pitch	Set the ball screw pitch. Set to "360" for the rotary axis.	1 to 32767 (mm/rev)																																						
2219 (PR)	SV019 RNG1	Position detector resolution	In the case of the semi-closed loop control Set the same value as SV020 (RNG2). (Refer to the explanation of SV020.)	1 to 9999 (kp/rev)																																						
			In the case of the semi-closed loop control Set the same value as SV020 (RNG2). (Refer to the explanation of SV020.)	1 to 9999 (kp/pit)																																						
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">Detector model name</th> <th style="text-align: center;">Resolution</th> <th style="text-align: center;">SV019 setting</th> </tr> </thead> <tbody> <tr> <td>OHE25K-ET, OHA25K-ET</td> <td style="text-align: center;">100,000(p/rev)</td> <td style="text-align: center;">100</td> </tr> <tr> <td>OSE104-ET, OSA104-ET</td> <td style="text-align: center;">100,000(p/rev)</td> <td style="text-align: center;">100</td> </tr> <tr> <td>OSE105-ET, OSA105-ET</td> <td style="text-align: center;">1,000,000(p/rev)</td> <td style="text-align: center;">1000</td> </tr> <tr> <td>RCN723 (Heidenhain)</td> <td style="text-align: center;">8,000,000(p/rev)</td> <td style="text-align: center;">8000</td> </tr> <tr> <td>Relative position detection scale</td> <td>Refer to specification manual for each detector</td> <td style="text-align: center;">PIT/Resolution (μm)</td> </tr> <tr> <td>AT41 (Mitsutoyo)</td> <td style="text-align: center;">1 (μm/p)</td> <td style="text-align: center;">The same as SV018 (PIT)</td> </tr> <tr> <td>FME type, FLE type (Futaba)</td> <td>Refer to specification manual for each detector</td> <td style="text-align: center;">PIT/Resolution (μm)</td> </tr> <tr> <td>MP type (Mitsubishi Heavy Industries)</td> <td>Refer to specification manual for each detector</td> <td style="text-align: center;">PIT/Resolution (μm)</td> </tr> <tr> <td>AT342 (Mitsutoyo)</td> <td style="text-align: center;">0.5 (μm/p)</td> <td style="text-align: center;">Twice as big as SV018 (PIT)</td> </tr> <tr> <td>AT343 (Mitsutoyo)</td> <td style="text-align: center;">0.05 (μm/p)</td> <td style="text-align: center;">20 times as big as SV018 (PIT)</td> </tr> <tr> <td>LC191M (Heidenhain)</td> <td>Refer to specification manual for each detector</td> <td style="text-align: center;">PIT/Resolution (μm)</td> </tr> <tr> <td>LC491M (Heidenhain)</td> <td>Refer to specification manual for each detector</td> <td style="text-align: center;">PIT/Resolution (μm)</td> </tr> </tbody> </table>				Detector model name	Resolution	SV019 setting	OHE25K-ET, OHA25K-ET	100,000(p/rev)	100	OSE104-ET, OSA104-ET	100,000(p/rev)	100	OSE105-ET, OSA105-ET	1,000,000(p/rev)	1000	RCN723 (Heidenhain)	8,000,000(p/rev)	8000	Relative position detection scale	Refer to specification manual for each detector	PIT/Resolution (μm)	AT41 (Mitsutoyo)	1 (μm/p)	The same as SV018 (PIT)	FME type, FLE type (Futaba)	Refer to specification manual for each detector	PIT/Resolution (μm)	MP type (Mitsubishi Heavy Industries)	Refer to specification manual for each detector	PIT/Resolution (μm)	AT342 (Mitsutoyo)	0.5 (μm/p)	Twice as big as SV018 (PIT)	AT343 (Mitsutoyo)	0.05 (μm/p)	20 times as big as SV018 (PIT)	LC191M (Heidenhain)	Refer to specification manual for each detector	PIT/Resolution (μm)	LC491M (Heidenhain)	Refer to specification manual for each detector	PIT/Resolution (μm)
Detector model name	Resolution	SV019 setting																																								
OHE25K-ET, OHA25K-ET	100,000(p/rev)	100																																								
OSE104-ET, OSA104-ET	100,000(p/rev)	100																																								
OSE105-ET, OSA105-ET	1,000,000(p/rev)	1000																																								
RCN723 (Heidenhain)	8,000,000(p/rev)	8000																																								
Relative position detection scale	Refer to specification manual for each detector	PIT/Resolution (μm)																																								
AT41 (Mitsutoyo)	1 (μm/p)	The same as SV018 (PIT)																																								
FME type, FLE type (Futaba)	Refer to specification manual for each detector	PIT/Resolution (μm)																																								
MP type (Mitsubishi Heavy Industries)	Refer to specification manual for each detector	PIT/Resolution (μm)																																								
AT342 (Mitsutoyo)	0.5 (μm/p)	Twice as big as SV018 (PIT)																																								
AT343 (Mitsutoyo)	0.05 (μm/p)	20 times as big as SV018 (PIT)																																								
LC191M (Heidenhain)	Refer to specification manual for each detector	PIT/Resolution (μm)																																								
LC491M (Heidenhain)	Refer to specification manual for each detector	PIT/Resolution (μm)																																								
2220 (PR)	SV020 RNG2	Speed detector resolution	Set the number of pulses per one revolution of the motor end detector.	1 to 9999 (kp/rev)																																						
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">Detector model name</th> <th style="text-align: center;">SV020 setting</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">OSE104, OSA104</td> <td style="text-align: center;">100</td> </tr> <tr> <td style="text-align: center;">OSE105, OSA105</td> <td style="text-align: center;">1000</td> </tr> </tbody> </table>				Detector model name	SV020 setting	OSE104, OSA104	100	OSE105, OSA105	1000																																	
Detector model name	SV020 setting																																									
OSE104, OSA104	100																																									
OSE105, OSA105	1000																																									
2221	SV021 OLT	Overload detection time constant	Set the detection time constant of Overload 1 (Alarm 50). Set to "60" as a standard. (For machine tool builder adjustment.)	1 to 999 (s)																																						
2222	SV022 OLL	Overload detection level	Set the current detection level of Overload 1 (Alarm 50) in respect to the stall (rated) current. Set to "150" as a standard. (For machine tool builder adjustment.)	110 to 500 (Stall [rated] current %)																																						

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range
2223	SV023 OD1	Excessive error detection width during servo ON Set the excessive error detection width when servo ON. <Standard setting value> $\text{OD1}=\text{OD2}=\frac{\text{Rapid traverse rate (mm/min)}}{60*\text{PGN1}}/2 \text{ (mm)}$ When "0" is set, the excessive error detection will not be performed.	0 to 32767 (mm)
2224	SV024 INP	In-position detection width Set the in-position detection width. Set the accuracy required for the machine. The lower the setting is, the higher the positioning accuracy gets, however, the cycle time (setting time) becomes longer. The standard setting is "50".	0 to 32767 (μm)

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range																																																																																																																																																									
2225 (PR)	SV025 MTYP	Motor /Detector type	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">E</td> <td style="text-align: center;">D</td> <td style="text-align: center;">C</td> <td style="text-align: center;">B</td> <td style="text-align: center;">A</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> </tr> <tr> <td colspan="4" style="text-align: center; border-top: 1px solid black;">pen</td> <td colspan="4" style="text-align: center; border-top: 1px solid black;">ent</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td colspan="8" style="text-align: center; border-top: 1px solid black;">mtyp</td> </tr> </table>	F	E	D	C	B	A	9	8	pen				ent				7	6	5	4	3	2	1	0	mtyp																																																																																																																																
			F	E	D	C	B	A	9	8																																																																																																																																																		
			pen				ent																																																																																																																																																					
			7	6	5	4	3	2	1	0																																																																																																																																																		
			mtyp																																																																																																																																																									
			bit	Explanation																																																																																																																																																								
			0	Set the motor type.																																																																																																																																																								
			1	Set this along with SV017 (SPEC)/spm.																																																																																																																																																								
			2	1) When SV017/spm=0 (Normal drive unit)																																																																																																																																																								
			3		<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">Set- ting</th> <th style="width: 10%;">0x</th> <th style="width: 10%;">1x</th> <th style="width: 10%;">2x</th> <th style="width: 10%;">3x</th> <th style="width: 10%;">4x</th> <th style="width: 10%;">5x</th> <th style="width: 10%;">6x</th> <th style="width: 10%;">7x</th> </tr> </thead> <tbody> <tr><td>x0</td><td>HA40N</td><td></td><td>HA50L</td><td>HA53L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x1</td><td>HA80N</td><td></td><td>HA100L</td><td>HA103L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x2</td><td>HA100N</td><td></td><td>HA200L</td><td>HA203L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x3</td><td>HA200N</td><td></td><td>HA300L</td><td>HA303L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x4</td><td>HA300N</td><td></td><td>HA500L</td><td>HA503L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x5</td><td>HA700N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x6</td><td>HA900N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x7</td><td></td><td></td><td>HA-LH11K2</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x8</td><td></td><td></td><td>HA-LH15K2</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x9</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xA</td><td></td><td></td><td>HA150L</td><td>HA153L</td><td></td><td></td><td></td><td></td></tr> <tr><td>xB</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xC</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xD</td><td></td><td></td><td>HA-LF15K2</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xE</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xF</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table>	Set- ting	0x	1x	2x	3x	4x	5x	6x	7x	x0	HA40N		HA50L	HA53L					x1	HA80N		HA100L	HA103L					x2	HA100N		HA200L	HA203L					x3	HA200N		HA300L	HA303L					x4	HA300N		HA500L	HA503L					x5	HA700N								x6	HA900N								x7			HA-LH11K2						x8			HA-LH15K2						x9									xA			HA150L	HA153L					xB									xC									xD			HA-LF15K2						xE									xF						
Set- ting	0x	1x	2x	3x	4x	5x	6x	7x																																																																																																																																																				
x0	HA40N		HA50L	HA53L																																																																																																																																																								
x1	HA80N		HA100L	HA103L																																																																																																																																																								
x2	HA100N		HA200L	HA203L																																																																																																																																																								
x3	HA200N		HA300L	HA303L																																																																																																																																																								
x4	HA300N		HA500L	HA503L																																																																																																																																																								
x5	HA700N																																																																																																																																																											
x6	HA900N																																																																																																																																																											
x7			HA-LH11K2																																																																																																																																																									
x8			HA-LH15K2																																																																																																																																																									
x9																																																																																																																																																												
xA			HA150L	HA153L																																																																																																																																																								
xB																																																																																																																																																												
xC																																																																																																																																																												
xD			HA-LF15K2																																																																																																																																																									
xE																																																																																																																																																												
xF																																																																																																																																																												
4	mtyp																																																																																																																																																											
5																																																																																																																																																												
6																																																																																																																																																												
7																																																																																																																																																												
		<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">Set- ting</th> <th style="width: 10%;">8x</th> <th style="width: 10%;">9x</th> <th style="width: 10%;">Ax</th> <th style="width: 10%;">Bx</th> <th style="width: 10%;">Cx</th> <th style="width: 10%;">Dx</th> <th style="width: 10%;">Ex</th> <th style="width: 10%;">Fx</th> </tr> </thead> <tbody> <tr><td>x0</td><td>HA43N</td><td></td><td></td><td>HC52</td><td>HC53</td><td></td><td></td><td></td></tr> <tr><td>x1</td><td>HA83N</td><td></td><td></td><td>HC102</td><td>HC103</td><td></td><td>HC103R</td><td></td></tr> <tr><td>x2</td><td>HA103N</td><td></td><td></td><td>HC152</td><td>HC153</td><td></td><td>HC153R</td><td></td></tr> <tr><td>x3</td><td>HA203N</td><td></td><td></td><td>HC202</td><td>HC203</td><td></td><td>HC203R</td><td></td></tr> <tr><td>x4</td><td>HA303N</td><td></td><td></td><td>HC352</td><td>HC353</td><td></td><td>HC353R</td><td></td></tr> <tr><td>x5</td><td>HA703N</td><td></td><td></td><td>HC452</td><td>HC453</td><td></td><td>HC503R</td><td></td></tr> <tr><td>x6</td><td></td><td></td><td></td><td>HC702</td><td>HC703</td><td></td><td></td><td></td></tr> <tr><td>x7</td><td></td><td></td><td></td><td>HC902</td><td></td><td></td><td></td><td></td></tr> <tr><td>x8</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x9</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xA</td><td>HA93N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xB</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xC</td><td>HA053N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xD</td><td>HA13N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xE</td><td>HA23N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xF</td><td>HA33N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table>	Set- ting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx	x0	HA43N			HC52	HC53				x1	HA83N			HC102	HC103		HC103R		x2	HA103N			HC152	HC153		HC153R		x3	HA203N			HC202	HC203		HC203R		x4	HA303N			HC352	HC353		HC353R		x5	HA703N			HC452	HC453		HC503R		x6				HC702	HC703				x7				HC902					x8									x9									xA	HA93N								xB									xC	HA053N								xD	HA13N								xE	HA23N								xF	HA33N								
Set- ting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx																																																																																																																																																				
x0	HA43N			HC52	HC53																																																																																																																																																							
x1	HA83N			HC102	HC103		HC103R																																																																																																																																																					
x2	HA103N			HC152	HC153		HC153R																																																																																																																																																					
x3	HA203N			HC202	HC203		HC203R																																																																																																																																																					
x4	HA303N			HC352	HC353		HC353R																																																																																																																																																					
x5	HA703N			HC452	HC453		HC503R																																																																																																																																																					
x6				HC702	HC703																																																																																																																																																							
x7				HC902																																																																																																																																																								
x8																																																																																																																																																												
x9																																																																																																																																																												
xA	HA93N																																																																																																																																																											
xB																																																																																																																																																												
xC	HA053N																																																																																																																																																											
xD	HA13N																																																																																																																																																											
xE	HA23N																																																																																																																																																											
xF	HA33N																																																																																																																																																											
		(Continued to the next page)																																																																																																																																																										

7.2 7. SERVO PARAMETERS
MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range																																																																																																																																																																																												
(Continued from the previous page)																																																																																																																																																																																															
		<table border="1"> <thead> <tr> <th data-bbox="512 290 608 325">bit</th> <th colspan="8" data-bbox="608 290 1203 325">Explanation</th> </tr> </thead> <tbody> <tr> <td colspan="9" data-bbox="512 325 1203 360">2) When SV017/spm=1 (S type drive unit)</td> </tr> <tr> <td data-bbox="512 360 608 395"></td> <td data-bbox="608 360 743 395">Setting</td> <td data-bbox="743 360 804 395">8x</td> <td data-bbox="804 360 865 395">9x</td> <td data-bbox="865 360 925 395">Ax</td> <td data-bbox="925 360 986 395">Bx</td> <td data-bbox="986 360 1046 395">Cx</td> <td data-bbox="1046 360 1107 395">Dx</td> <td data-bbox="1107 360 1168 395">Ex</td> <td data-bbox="1168 360 1203 395">Fx</td> </tr> <tr><td></td><td>x0</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>x1</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>x2</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>x3</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>x4</td><td></td><td></td><td>HC353</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>x5</td><td></td><td>HC452</td><td>HC453</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>x6</td><td></td><td>HC702</td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>x7</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>x8</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>x9</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>xA</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>xB</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>xC</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>xD</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>xE</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td></td><td>xF</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table>	bit	Explanation								2) When SV017/spm=1 (S type drive unit)										Setting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx		x0										x1										x2										x3										x4			HC353							x5		HC452	HC453							x6		HC702								x7										x8										x9										xA										xB										xC										xD										xE										xF									
bit	Explanation																																																																																																																																																																																														
2) When SV017/spm=1 (S type drive unit)																																																																																																																																																																																															
	Setting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx																																																																																																																																																																																						
	x0																																																																																																																																																																																														
	x1																																																																																																																																																																																														
	x2																																																																																																																																																																																														
	x3																																																																																																																																																																																														
	x4			HC353																																																																																																																																																																																											
	x5		HC452	HC453																																																																																																																																																																																											
	x6		HC702																																																																																																																																																																																												
	x7																																																																																																																																																																																														
	x8																																																																																																																																																																																														
	x9																																																																																																																																																																																														
	xA																																																																																																																																																																																														
	xB																																																																																																																																																																																														
	xC																																																																																																																																																																																														
	xD																																																																																																																																																																																														
	xE																																																																																																																																																																																														
	xF																																																																																																																																																																																														
		<table border="1"> <tbody> <tr> <td data-bbox="512 1024 608 1059">8</td> <td data-bbox="608 1024 1203 1059">Set the detector type.</td> <td data-bbox="1203 1024 1439 1059"></td> </tr> <tr> <td data-bbox="512 1059 608 1094">9</td> <td data-bbox="608 1059 1203 1094">Set the position detector type for "pen", and the speed detector type for "ent". In the case of the semi-closed loop control, set the same value for "pen" and "ent".</td> <td data-bbox="1203 1059 1439 1094"></td> </tr> <tr> <td data-bbox="512 1094 608 1128">A</td> <td data-bbox="608 1094 1203 1128">ent</td> <td data-bbox="1203 1094 1439 1128"></td> </tr> <tr> <td data-bbox="512 1128 608 1163">B</td> <td data-bbox="608 1128 1203 1163"></td> <td data-bbox="1203 1128 1439 1163"></td> </tr> <tr> <td data-bbox="512 1163 608 1198">C</td> <td data-bbox="608 1163 1203 1198">pen</td> <td data-bbox="1203 1163 1439 1198"></td> </tr> <tr> <td data-bbox="512 1198 608 1233">D</td> <td data-bbox="608 1198 1203 1233"></td> <td data-bbox="1203 1198 1439 1233"></td> </tr> <tr> <td data-bbox="512 1233 608 1268">E</td> <td data-bbox="608 1233 1203 1268"></td> <td data-bbox="1203 1233 1439 1268"></td> </tr> <tr> <td data-bbox="512 1268 608 1303">F</td> <td data-bbox="608 1268 1203 1303"></td> <td data-bbox="1203 1268 1439 1303"></td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th data-bbox="512 1303 608 1373"></th> <th data-bbox="608 1303 743 1373">pen setting</th> <th data-bbox="743 1303 879 1373">ent setting</th> <th data-bbox="879 1303 1439 1373">Detector model name</th> </tr> </thead> <tbody> <tr><td></td><td>0</td><td>0</td><td>OSE104</td></tr> <tr><td></td><td>1</td><td>1</td><td>OSA104</td></tr> <tr><td></td><td>2</td><td>2</td><td>OSE105, OSA105</td></tr> <tr><td></td><td>3</td><td>3</td><td></td></tr> <tr><td></td><td>4</td><td>Setting impossible</td><td>OHE25K-ET, OSE104-ET</td></tr> <tr><td></td><td>5</td><td>Setting impossible</td><td>OHA25K-ET, OSA104-ET</td></tr> <tr><td></td><td>6</td><td>Setting impossible</td><td>OSE105-ET, OSA105-ET, RCN723 (Heidenhain)</td></tr> <tr><td></td><td>7</td><td>Setting impossible</td><td></td></tr> <tr><td></td><td>8</td><td>Setting impossible</td><td>Relative position detection scale, MP type (Mitsubishi Heavy Industries)</td></tr> <tr><td></td><td>9</td><td>Setting impossible</td><td>AT41 (Mitsutoyo), FME type, FLE type (Futaba)</td></tr> <tr><td></td><td>A</td><td>Setting impossible</td><td>AT342,AT343 (Mitsutoyo), LC191M/491M (Heidenhain), MDS-B-HR</td></tr> <tr><td></td><td>B</td><td>Setting impossible</td><td></td></tr> <tr><td></td><td>C</td><td>C (Current synchronization)</td><td>The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.</td></tr> <tr><td></td><td>D</td><td>E (Current synchronization)</td><td>The setting of the slave axis in the speed/current synchronization control. When the master axis is the full-closed control. (Current synchronization control is only for MDS-C2-Vx.)</td></tr> <tr><td></td><td>E</td><td>Setting impossible</td><td></td></tr> <tr><td></td><td>F</td><td>Setting impossible</td><td></td></tr> </tbody> </table>	8	Set the detector type.		9	Set the position detector type for "pen", and the speed detector type for "ent". In the case of the semi-closed loop control, set the same value for "pen" and "ent".		A	ent		B			C	pen		D			E			F				pen setting	ent setting	Detector model name		0	0	OSE104		1	1	OSA104		2	2	OSE105, OSA105		3	3			4	Setting impossible	OHE25K-ET, OSE104-ET		5	Setting impossible	OHA25K-ET, OSA104-ET		6	Setting impossible	OSE105-ET, OSA105-ET, RCN723 (Heidenhain)		7	Setting impossible			8	Setting impossible	Relative position detection scale, MP type (Mitsubishi Heavy Industries)		9	Setting impossible	AT41 (Mitsutoyo), FME type, FLE type (Futaba)		A	Setting impossible	AT342,AT343 (Mitsutoyo), LC191M/491M (Heidenhain), MDS-B-HR		B	Setting impossible			C	C (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.		D	E (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the full-closed control. (Current synchronization control is only for MDS-C2-Vx.)		E	Setting impossible			F	Setting impossible																																																																																																		
8	Set the detector type.																																																																																																																																																																																														
9	Set the position detector type for "pen", and the speed detector type for "ent". In the case of the semi-closed loop control, set the same value for "pen" and "ent".																																																																																																																																																																																														
A	ent																																																																																																																																																																																														
B																																																																																																																																																																																															
C	pen																																																																																																																																																																																														
D																																																																																																																																																																																															
E																																																																																																																																																																																															
F																																																																																																																																																																																															
	pen setting	ent setting	Detector model name																																																																																																																																																																																												
	0	0	OSE104																																																																																																																																																																																												
	1	1	OSA104																																																																																																																																																																																												
	2	2	OSE105, OSA105																																																																																																																																																																																												
	3	3																																																																																																																																																																																													
	4	Setting impossible	OHE25K-ET, OSE104-ET																																																																																																																																																																																												
	5	Setting impossible	OHA25K-ET, OSA104-ET																																																																																																																																																																																												
	6	Setting impossible	OSE105-ET, OSA105-ET, RCN723 (Heidenhain)																																																																																																																																																																																												
	7	Setting impossible																																																																																																																																																																																													
	8	Setting impossible	Relative position detection scale, MP type (Mitsubishi Heavy Industries)																																																																																																																																																																																												
	9	Setting impossible	AT41 (Mitsutoyo), FME type, FLE type (Futaba)																																																																																																																																																																																												
	A	Setting impossible	AT342,AT343 (Mitsutoyo), LC191M/491M (Heidenhain), MDS-B-HR																																																																																																																																																																																												
	B	Setting impossible																																																																																																																																																																																													
	C	C (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.																																																																																																																																																																																												
	D	E (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the full-closed control. (Current synchronization control is only for MDS-C2-Vx.)																																																																																																																																																																																												
	E	Setting impossible																																																																																																																																																																																													
	F	Setting impossible																																																																																																																																																																																													

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range																																																																															
2226	SV026 OD2	Excessive error detection width during servo OFF	0 to 32767 (mm)																																																																															
2227	SV027 SSF1	Servo function selection 1	<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <tr> <td style="width: 12.5%;">F</td> <td style="width: 12.5%;">E</td> <td style="width: 12.5%;">D</td> <td style="width: 12.5%;">C</td> <td style="width: 12.5%;">B</td> <td style="width: 12.5%;">A</td> <td style="width: 12.5%;">9</td> <td style="width: 12.5%;">8</td> </tr> <tr> <td>aflt</td> <td>zrn2</td> <td>afse</td> <td>ovs</td> <td>lmc</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td>6</td> <td>5</td> <td>4</td> <td>3</td> <td>2</td> <td>1</td> <td>0</td> </tr> <tr> <td>omr</td> <td>zrn3</td> <td>vfct</td> <td></td> <td>upc</td> <td>vcnt</td> <td></td> <td></td> </tr> </table> <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th style="width: 5%;">bit</th> <th style="width: 15%;">Meaning when "0" is set</th> <th style="width: 80%;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td>0</td> <td rowspan="2">vcnt</td> <td rowspan="2">Set the execution changeover type of the speed loop delay compensation. 00: Delay compensation changeover invalid 01: Delay compensation changeover type 1 10: Delay compensation type 2 11: Setting prohibited</td> </tr> <tr> <td>1</td> </tr> <tr> <td>2</td> <td>upc</td> <td>Start torque compensation invalid</td> </tr> <tr> <td>3</td> <td></td> <td>Start torque compensation valid</td> </tr> <tr> <td>4</td> <td rowspan="2">vfct</td> <td rowspan="2">Set the number of compensation pulses of the jitter compensation. 00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses</td> </tr> <tr> <td>5</td> </tr> <tr> <td>6</td> <td>zrn3</td> <td>ABS scale: Set to "1" in using AT342, AT343, LC191M/491M.</td> </tr> <tr> <td>7</td> <td>omr</td> <td>Machine end compensation invalid</td> </tr> <tr> <td></td> <td></td> <td>Machine end compensation valid</td> </tr> <tr> <td>8</td> <td rowspan="2">lmc</td> <td rowspan="2">Set the compensation amount with SV016 (LMC1) and SV041 (LMC2). 00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Overshooting compensation type 2 11: Setting prohibited</td> </tr> <tr> <td>9</td> </tr> <tr> <td>A</td> <td rowspan="2">ovs</td> <td rowspan="2">Set the compensation amount with SV031 (OVS1) and SV042 (OVS2). 00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Overshooting compensation type 3</td> </tr> <tr> <td>B</td> </tr> <tr> <td>C</td> <td rowspan="2">afse</td> <td rowspan="2">00: Adoptive filter sensitivity standard 11: Adoptive filter sensitivity increase (Set 2bits at a time)</td> </tr> <tr> <td>D</td> </tr> <tr> <td>E</td> <td>zrn2</td> <td>Set to "1".</td> </tr> <tr> <td>F</td> <td>aflt</td> <td>Adoptive filter stop</td> </tr> <tr> <td></td> <td></td> <td>Adoptive filter start</td> </tr> </tbody> </table> <p>(Note) Set to "0" for bits with no particular description.</p>	F	E	D	C	B	A	9	8	aflt	zrn2	afse	ovs	lmc				7	6	5	4	3	2	1	0	omr	zrn3	vfct		upc	vcnt			bit	Meaning when "0" is set	Meaning when "1" is set	0	vcnt	Set the execution changeover type of the speed loop delay compensation. 00: Delay compensation changeover invalid 01: Delay compensation changeover type 1 10: Delay compensation type 2 11: Setting prohibited	1	2	upc	Start torque compensation invalid	3		Start torque compensation valid	4	vfct	Set the number of compensation pulses of the jitter compensation. 00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses	5	6	zrn3	ABS scale: Set to "1" in using AT342, AT343, LC191M/491M.	7	omr	Machine end compensation invalid			Machine end compensation valid	8	lmc	Set the compensation amount with SV016 (LMC1) and SV041 (LMC2). 00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Overshooting compensation type 2 11: Setting prohibited	9	A	ovs	Set the compensation amount with SV031 (OVS1) and SV042 (OVS2). 00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Overshooting compensation type 3	B	C	afse	00: Adoptive filter sensitivity standard 11: Adoptive filter sensitivity increase (Set 2bits at a time)	D	E	zrn2	Set to "1".	F	aflt	Adoptive filter stop			Adoptive filter start
F	E	D	C	B	A	9	8																																																																											
aflt	zrn2	afse	ovs	lmc																																																																														
7	6	5	4	3	2	1	0																																																																											
omr	zrn3	vfct		upc	vcnt																																																																													
bit	Meaning when "0" is set	Meaning when "1" is set																																																																																
0	vcnt	Set the execution changeover type of the speed loop delay compensation. 00: Delay compensation changeover invalid 01: Delay compensation changeover type 1 10: Delay compensation type 2 11: Setting prohibited																																																																																
1																																																																																		
2	upc	Start torque compensation invalid																																																																																
3		Start torque compensation valid																																																																																
4	vfct	Set the number of compensation pulses of the jitter compensation. 00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses																																																																																
5																																																																																		
6	zrn3	ABS scale: Set to "1" in using AT342, AT343, LC191M/491M.																																																																																
7	omr	Machine end compensation invalid																																																																																
		Machine end compensation valid																																																																																
8	lmc	Set the compensation amount with SV016 (LMC1) and SV041 (LMC2). 00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Overshooting compensation type 2 11: Setting prohibited																																																																																
9																																																																																		
A	ovs	Set the compensation amount with SV031 (OVS1) and SV042 (OVS2). 00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Overshooting compensation type 3																																																																																
B																																																																																		
C	afse	00: Adoptive filter sensitivity standard 11: Adoptive filter sensitivity increase (Set 2bits at a time)																																																																																
D																																																																																		
E	zrn2	Set to "1".																																																																																
F	aflt	Adoptive filter stop																																																																																
		Adoptive filter start																																																																																
2228	SV028	Not used. Set to "0".	0																																																																															
2229	SV029	Speed at the change of speed loop gain	0 to 9999 (r/min)																																																																															

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range
2230	The higher order 8bits and lower order 8bits are used for different functions. "The setting value of SV030" = (Icx*256) + IVC		0 to 32767
	SV030 IVC (Low order)	Voltage dead time compensation When 100% is set, the voltage equivalent to the logical non-energized time will be compensated. When "0" is set, a 100% compensation will be performed. Adjust in increments of 10% from the default value 100%. If increased too much, vibration or vibration noise may be generated.	0 to 255 (%)
	SV030 Icx (High order)	Current bias 1 Set to "0" as a standard. Use this in combination with SV040 and the high order 8bits of SV045.	0 to 127
2231	SV031 OVS1	Overshooting compensation 1 Set this if overshooting occurs during positioning. This compensates the motor torque during positioning. This is valid only when the overshooting compensation SV027 (SSF1/ovs) is selected. Type 1: When SV027 (SSF1)/ bitB, A (ovs)=01 Set the compensation amount based on the motor's stall current. This compensates overshooting that occurs during pulse feeding. Normally, use Type 2. Type 2: When SV027 (SSF1)/ bitB, A (ovs)=10 Set the compensation amount based on the motor's stall current. Increase by 1% and determine the amount that overshooting doesn't occur. In Type 2, compensation during the feed forward control during circular cutting won't be performed. Type 3: When SV027 (SSF1)/ bitB, A (ovs)=11 Use this to perform the overshooting compensation during circular cutting or the feed forward control. The setting method is the same in Type 2. When you wish different compensation amount depending on the direction When SV042 (OVS2) is "0", compensate with the value of SV031 (OVS1) in both of the + and -directions. If you wish to change the compensation amount depending on the command direction, set this and SV042 (OVS2). (SV031: + direction, SV042: - direction. However, the directions may be opposite depending on other settings.) When "-1" is set, the compensation won't be performed in the direction of the command.	-1 to 100 (Stall [rated] current %)
2232	SV032 TOF	Torque offset Set the unbalance torque of vertical axis and inclined axis.	-100 to 100 (Stall [rated] current %)

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range																																
2233	SV033 SSF2 Servo function selection 2	<table style="width: 100%; border-collapse: collapse; margin-bottom: 5px;"> <tr> <td style="width: 12.5%; text-align: center;">F</td> <td style="width: 12.5%; text-align: center;">E</td> <td style="width: 12.5%; text-align: center;">D</td> <td style="width: 12.5%; text-align: center;">C</td> <td style="width: 12.5%; text-align: center;">B</td> <td style="width: 12.5%; text-align: center;">A</td> <td style="width: 12.5%; text-align: center;">9</td> <td style="width: 12.5%; text-align: center;">8</td> </tr> <tr> <td colspan="6" style="text-align: center; border-bottom: 1px solid black;">dos</td> <td style="text-align: center; border-bottom: 1px solid black;">hvx</td> <td style="text-align: center; border-bottom: 1px solid black;">svx</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td colspan="3" style="text-align: center; border-bottom: 1px solid black;">nfd2</td> <td style="text-align: center; border-bottom: 1px solid black;">nf3</td> <td colspan="3" style="text-align: center; border-bottom: 1px solid black;">nfd1</td> <td style="text-align: center; border-bottom: 1px solid black;">zck</td> </tr> </table>	F	E	D	C	B	A	9	8	dos						hvx	svx	7	6	5	4	3	2	1	0	nfd2			nf3	nfd1			zck	
		F	E	D	C	B	A	9	8																										
		dos						hvx	svx																										
		7	6	5	4	3	2	1	0																										
		nfd2			nf3	nfd1			zck																										
		bit	Meaning when "0" is set	Meaning when "1" is set																															
		0	zck	Z phase check valid (Alarm 42)	Z phase check invalid																														
		1	Set the filter depth for Notch filter 1 (SV038).																																
		2	nfd1	Value	000 001 010 011 100 101 110 111																														
		3	nfd1	Depth (dB)	Infntly deep -18.1 -12.0 -8.5 -6.0 -4.1 -2.5 -1.2																														
				Deep←	→ Shallow																														
		4	nf3	Notch filter 3 stop	Notch filter 3 start (1125Hz)																														
		5	Set the operation frequency of Notch filter 2 (SV046).																																
		6	nfd2	Value	000 001 010 011 100 101 110 111																														
		7	nfd2	Depth (dB)	Infntly deep -18.1 -12.0 -8.5 -6.0 -4.1 -2.5 -1.2																														
		Deep←	→ Shallow																																
8	svx	Set the performance mode of the servo control. (Only for MDS-C1-Vx)																																	
9	hvx	00: By current loop gain 01: MDS-B-Vx compatible mode selected 10: High gain mode selected 11: High gain mode selected																																	
A																																			
B																																			
C	Digital signal output selection																																		
D	dos	0 : MP scale absolute position detection, offset demand signal output																																	
E	1 : Specified speed signal output																																		
F	2 to F : Setting prohibited																																		
(Note) Set to "0" for bits with no particular description.																																			

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range																																																														
2234	SV034 SSF3 Servo function selection 3	<table style="margin: auto; border-collapse: collapse;"> <tr> <td style="border: none;">F</td> <td style="border: none;">E</td> <td style="border: none;">D</td> <td style="border: none;">C</td> <td style="border: none;">B</td> <td style="border: none;">A</td> <td style="border: none;">9</td> <td style="border: none;">8</td> </tr> <tr> <td colspan="8" style="text-align: center; border: none;">ovsn</td> </tr> <tr> <td style="border: none;">7</td> <td style="border: none;">6</td> <td style="border: none;">5</td> <td style="border: none;">4</td> <td style="border: none;">3</td> <td style="border: none;">2</td> <td style="border: none;">1</td> <td style="border: none;">0</td> </tr> <tr> <td style="border: none;"></td> <td style="border: none;">os2</td> <td style="border: none;">zeg</td> <td style="border: none;"></td> <td style="border: none;"></td> <td style="border: none;">mohn</td> <td style="border: none;">has2</td> <td style="border: none;">has1</td> </tr> </table>	F	E	D	C	B	A	9	8	ovsn								7	6	5	4	3	2	1	0		os2	zeg			mohn	has2	has1																															
		F	E	D	C	B	A	9	8																																																								
		ovsn																																																															
		7	6	5	4	3	2	1	0																																																								
			os2	zeg			mohn	has2	has1																																																								
		<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">bit</th> <th style="width: 10%;"></th> <th style="width: 40%;">Meaning when "0" is set</th> <th style="width: 40%;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">has1</td> <td>Setting for normal use (Except for HC)</td> <td>HAS control 1 valid (HC: High acceleration rate support)</td> </tr> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">has2</td> <td>Setting for normal use (Except for HC)</td> <td>HAS control 2 valid (HC: Overshooting support)</td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">mohn</td> <td>MDS-B-HR motor thermal valid</td> <td>MDS-B-HR motor thermal ignored</td> </tr> <tr> <td style="text-align: center;">3</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">4</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">5</td> <td style="text-align: center;">zeg</td> <td>Z phase normal edge detection (Setting for normal use)</td> <td>Z phase reverse edge detection (Valid only when SV027/bit6=1)</td> </tr> <tr> <td style="text-align: center;">6</td> <td style="text-align: center;">os2</td> <td>Setting for normal use</td> <td>Overspeed detection level changeover</td> </tr> <tr> <td style="text-align: center;">7</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">8</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">9</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">A</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">B</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">C</td> <td></td> <td colspan="2" rowspan="4">Set the non-sensitive band of the overshooting compensation type 3 in increments of 2μm at a time. In the feed forward control, the non-sensitive band of the model position droop is set, and overshooting of the model is ignored. Set the same value as the standard SV040.</td> </tr> <tr> <td style="text-align: center;">D</td> <td></td> </tr> <tr> <td style="text-align: center;">E</td> <td style="text-align: center;">ovsn</td> </tr> <tr> <td style="text-align: center;">F</td> <td></td> </tr> </tbody> </table>	bit		Meaning when "0" is set	Meaning when "1" is set	0	has1	Setting for normal use (Except for HC)	HAS control 1 valid (HC: High acceleration rate support)	1	has2	Setting for normal use (Except for HC)	HAS control 2 valid (HC: Overshooting support)	2	mohn	MDS-B-HR motor thermal valid	MDS-B-HR motor thermal ignored	3				4				5	zeg	Z phase normal edge detection (Setting for normal use)	Z phase reverse edge detection (Valid only when SV027/bit6=1)	6	os2	Setting for normal use	Overspeed detection level changeover	7				8				9				A				B				C		Set the non-sensitive band of the overshooting compensation type 3 in increments of 2μm at a time. In the feed forward control, the non-sensitive band of the model position droop is set, and overshooting of the model is ignored. Set the same value as the standard SV040.		D		E	ovsn	F		
		bit		Meaning when "0" is set	Meaning when "1" is set																																																												
		0	has1	Setting for normal use (Except for HC)	HAS control 1 valid (HC: High acceleration rate support)																																																												
		1	has2	Setting for normal use (Except for HC)	HAS control 2 valid (HC: Overshooting support)																																																												
		2	mohn	MDS-B-HR motor thermal valid	MDS-B-HR motor thermal ignored																																																												
3																																																																	
4																																																																	
5	zeg	Z phase normal edge detection (Setting for normal use)	Z phase reverse edge detection (Valid only when SV027/bit6=1)																																																														
6	os2	Setting for normal use	Overspeed detection level changeover																																																														
7																																																																	
8																																																																	
9																																																																	
A																																																																	
B																																																																	
C		Set the non-sensitive band of the overshooting compensation type 3 in increments of 2μm at a time. In the feed forward control, the non-sensitive band of the model position droop is set, and overshooting of the model is ignored. Set the same value as the standard SV040.																																																															
D																																																																	
E	ovsn																																																																
F																																																																	
(Note) Set to "0" for bits with no particular description.																																																																	

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range																																
2235	SV035 SSF4 Servo function selection 4	<table style="margin: auto; border-collapse: collapse;"> <tr> <td style="border: none;">F</td> <td style="border: none;">E</td> <td style="border: none;">D</td> <td style="border: none;">C</td> <td style="border: none;">B</td> <td style="border: none;">A</td> <td style="border: none;">9</td> <td style="border: none;">8</td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">clt</td> <td colspan="3" style="border: 1px solid black; text-align: center;">clG1</td> <td style="border: 1px solid black; text-align: center;">cl2n</td> <td style="border: 1px solid black; text-align: center;">clet</td> <td colspan="2" style="border: 1px solid black; text-align: center;">cltq</td> </tr> <tr> <td style="border: none; text-align: center;">7</td> <td style="border: none; text-align: center;">6</td> <td style="border: none; text-align: center;">5</td> <td style="border: none; text-align: center;">4</td> <td style="border: none; text-align: center;">3</td> <td style="border: none; text-align: center;">2</td> <td style="border: none; text-align: center;">1</td> <td style="border: none; text-align: center;">0</td> </tr> <tr> <td colspan="2" style="border: 1px solid black; text-align: center;">ckab</td> <td style="border: 1px solid black; text-align: center;">iup</td> <td colspan="5" style="border: 1px solid black; text-align: center;">tdt</td> </tr> </table>	F	E	D	C	B	A	9	8	clt	clG1			cl2n	clet	cltq		7	6	5	4	3	2	1	0	ckab		iup	tdt					
		F	E	D	C	B	A	9	8																										
		clt	clG1			cl2n	clet	cltq																											
		7	6	5	4	3	2	1	0																										
		ckab		iup	tdt																														
		bit	Meaning when "0" is set	Meaning when "1" is set																															
		0	Td creation time setting Set to "0". (For machine tool builder adjustment)																																
		1																																	
		2		tdt																															
		3																																	
4																																			
5																																			
6	iup	Set to "1" when using any of motors from HC152 to HC702 and from HC153 to HC453.																																	
7	ckab	Setting for normal use	No signal 2 (Alarm 21) special detection																																
8	cltq	Set the retracting torque for collision detection in respect to the maximum torque of the motor.																																	
9		00: 100% 01: 90% 10: 80% (Standard) 11: 70%																																	
A	clet	Setting for normal use	The disturbance torque peak of the latest two seconds is displayed in MPOS of the servo monitor screen.																																
B	cl2n	Collision detection method 2 valid	Collision detection method 2 invalid																																
C	clG1	Collision detection method 1																																	
D		Set the collision detection level during cutting feed (G1).																																	
E		The G1 collision detection level=SV060*clG1.																																	
F		When clG1=0, the collision detection method 1 during cutting feed won't function.																																	
F	clt	Setting for normal use	The guide value of the SV059 setting value is displayed in MPOS of the servo monitor screen.																																
(Note) bit7 (ckab) is only for MDS-C1-Vx.																																			

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range																																																																																																																																						
2236 (PR)	SV036 PTYP	Power supply type	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">E</td> <td style="text-align: center;">D</td> <td style="text-align: center;">C</td> <td style="text-align: center;">B</td> <td style="text-align: center;">A</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> </tr> <tr> <td colspan="4" style="text-align: center; border-bottom: 1px solid black;">amp</td> <td colspan="4" style="text-align: center; border-bottom: 1px solid black;">rtyp</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td colspan="8" style="text-align: center; border-bottom: 1px solid black;">ptyp</td> </tr> </table>	F	E	D	C	B	A	9	8	amp				rtyp				7	6	5	4	3	2	1	0	ptyp																																																																																																													
			F	E	D	C	B	A	9	8																																																																																																																															
			amp				rtyp																																																																																																																																		
			7	6	5	4	3	2	1	0																																																																																																																															
			ptyp																																																																																																																																						
			0	ptyp	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">bit</th> <th colspan="9">Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td colspan="9" rowspan="3">When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.</td> </tr> <tr> <td>1</td> </tr> <tr> <td>2</td> </tr> <tr> <td>3</td> <td style="text-align: center;">Set-ting</td> <td style="text-align: center;">0x</td> <td style="text-align: center;">1x</td> <td style="text-align: center;">2x</td> <td style="text-align: center;">3x</td> <td style="text-align: center;">4x</td> <td style="text-align: center;">5x</td> <td style="text-align: center;">6x7x</td> <td style="text-align: center;">8x</td> </tr> <tr> <td>4</td> <td>x0</td> <td>Not used</td> <td></td> <td></td> <td>CV-300</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td>x1</td> <td></td> <td>CV-110</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-10</td> </tr> <tr> <td>6</td> <td>x2</td> <td></td> <td></td> <td>CV-220</td> <td></td> <td></td> <td></td> <td></td> <td>CR-15</td> </tr> <tr> <td>7</td> <td>x3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-22</td> </tr> <tr> <td></td> <td>x4</td> <td>CV-37</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-37</td> </tr> <tr> <td></td> <td>x5</td> <td></td> <td>CV-150</td> <td></td> <td></td> <td>CV-450</td> <td>CV-550</td> <td></td> <td></td> </tr> <tr> <td></td> <td>x6</td> <td>CV-55</td> <td></td> <td>CV-260</td> <td></td> <td></td> <td></td> <td></td> <td>CR-55</td> </tr> <tr> <td></td> <td>x7</td> <td></td> <td></td> <td></td> <td>CV-370</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>x8</td> <td>CV-75</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-75</td> </tr> <tr> <td></td> <td>x9</td> <td></td> <td>CV-185</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-90</td> </tr> </tbody> </table>	bit	Explanation									0	When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.									1	2	3	Set-ting	0x	1x	2x	3x	4x	5x	6x7x	8x	4	x0	Not used			CV-300					5	x1		CV-110						CR-10	6	x2			CV-220					CR-15	7	x3								CR-22		x4	CV-37							CR-37		x5		CV-150			CV-450	CV-550				x6	CV-55		CV-260					CR-55		x7				CV-370						x8	CV-75							CR-75		x9		CV-185						CR-90
			bit			Explanation																																																																																																																																			
			0			When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.																																																																																																																																			
			1																																																																																																																																						
			2																																																																																																																																						
3	Set-ting	0x	1x			2x	3x	4x	5x	6x7x	8x																																																																																																																														
4	x0	Not used					CV-300																																																																																																																																		
5	x1		CV-110								CR-10																																																																																																																														
6	x2					CV-220					CR-15																																																																																																																														
7	x3										CR-22																																																																																																																														
	x4	CV-37							CR-37																																																																																																																																
	x5		CV-150			CV-450	CV-550																																																																																																																																		
	x6	CV-55		CV-260					CR-55																																																																																																																																
	x7				CV-370																																																																																																																																				
	x8	CV-75							CR-75																																																																																																																																
	x9		CV-185						CR-90																																																																																																																																
8	rtyp	Set the regenerative resistor type when MDS-A-CR is used. <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 5px;"> <thead> <tr> <th style="width: 5%;">Set-ting</th> <th style="width: 35%;">Regenerative resistor model name</th> <th style="width: 20%;">Resistance value</th> <th style="width: 20%;">Capacity</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td>MDS-C1-CV (Setting when using power supply regeneration)</td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">1</td> <td>GZG200W260HMJ</td> <td style="text-align: center;">26Ω</td> <td style="text-align: center;">80W</td> </tr> <tr> <td style="text-align: center;">2</td> <td>GZG300W130HMJ×2</td> <td style="text-align: center;">26Ω</td> <td style="text-align: center;">150W</td> </tr> <tr> <td style="text-align: center;">3</td> <td>MR-RB30</td> <td style="text-align: center;">13Ω</td> <td style="text-align: center;">300W</td> </tr> <tr> <td style="text-align: center;">4</td> <td>MR-RB50</td> <td style="text-align: center;">13Ω</td> <td style="text-align: center;">500W</td> </tr> <tr> <td style="text-align: center;">5</td> <td>GZG200W200HMJ×3</td> <td style="text-align: center;">6.7Ω</td> <td style="text-align: center;">350W</td> </tr> <tr> <td style="text-align: center;">6</td> <td>GZG300W200HMJ×3</td> <td style="text-align: center;">6.7Ω</td> <td style="text-align: center;">500W</td> </tr> <tr> <td style="text-align: center;">7</td> <td>R-UNIT-1</td> <td style="text-align: center;">30Ω</td> <td style="text-align: center;">700W</td> </tr> <tr> <td style="text-align: center;">8</td> <td>R-UNIT-2</td> <td style="text-align: center;">15Ω</td> <td style="text-align: center;">700W</td> </tr> <tr> <td style="text-align: center;">9</td> <td>R-UNIT-3</td> <td style="text-align: center;">15Ω</td> <td style="text-align: center;">2100W</td> </tr> <tr> <td style="text-align: center;">A to F</td> <td>No setting</td> <td></td> <td></td> </tr> </tbody> </table>	Set-ting	Regenerative resistor model name	Resistance value	Capacity	0	MDS-C1-CV (Setting when using power supply regeneration)			1	GZG200W260HMJ	26Ω	80W	2	GZG300W130HMJ×2	26Ω	150W	3	MR-RB30	13Ω	300W	4	MR-RB50	13Ω	500W	5	GZG200W200HMJ×3	6.7Ω	350W	6	GZG300W200HMJ×3	6.7Ω	500W	7	R-UNIT-1	30Ω	700W	8	R-UNIT-2	15Ω	700W	9	R-UNIT-3	15Ω	2100W	A to F	No setting																																																																																									
Set-ting			Regenerative resistor model name	Resistance value	Capacity																																																																																																																																				
0			MDS-C1-CV (Setting when using power supply regeneration)																																																																																																																																						
1			GZG200W260HMJ	26Ω	80W																																																																																																																																				
2			GZG300W130HMJ×2	26Ω	150W																																																																																																																																				
3			MR-RB30	13Ω	300W																																																																																																																																				
4			MR-RB50	13Ω	500W																																																																																																																																				
5			GZG200W200HMJ×3	6.7Ω	350W																																																																																																																																				
6			GZG300W200HMJ×3	6.7Ω	500W																																																																																																																																				
7			R-UNIT-1	30Ω	700W																																																																																																																																				
8	R-UNIT-2	15Ω	700W																																																																																																																																						
9	R-UNIT-3	15Ω	2100W																																																																																																																																						
A to F	No setting																																																																																																																																								
A																																																																																																																																									
B																																																																																																																																									
C		Always set to "0".																																																																																																																																							
D	amp																																																																																																																																								
E																																																																																																																																									
F																																																																																																																																									

2237	SV037 JL	Load inertia scale	Set "the motor inertia + motor axis conversion load inertia" in respect to the motor inertia. $SV037 (JL) = \frac{Jl+Jm}{Jm} * 100$ Jm: Motor inertia Jl: Motor axis conversion load inertia	0 to 5000 (%)
------	-------------	--------------------	--	---------------

2238	SV038 FHZ1	Notch filter frequency 1	Set the vibration frequency to suppress if machine vibration occurs. (Valid at 36 or more) When not using, set to "0".	0 to 9000 (Hz)
------	---------------	--------------------------	---	----------------

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items		Details	Setting range	
2239	SV039 LMCD	Lost motion compensation timing	Set this when the lost motion compensation timing does not match. Adjust by increasing the value by 10 at a time.	0 to 2000 (ms)	
2240	The higher order 8bits and lower order 8bits are used for different functions. "Setting value of SV040" = (lcy*256) + LMCT			0 to 32767	
	SV040 LMCT (Low order)	Lost motion compensation non-sensitive band	Set the non-sensitive band of the lost motion compensation in the feed forward control. When "0" is set, the actual value that is set is 2µm. Adjust by increasing by 1µm at a time.		0 to 100 (µm)
	SV040 lcy (High order)	Current bias 2	Normally, set to "40" if you use HC202 to HC902, HC203 to HC703. Use this in combination with SV030 and the high order 8bits of SV045.		0 to 127
2241	SV041 LMC2	Lost motion compensation 2	Set this with SV016 (LMC1) only when you wish to set the lost motion compensation amount to be different depending on the command directions. Set to "0" as a standard.	-1 to 200 (Stall [rated] current %)	
2242	SV042 OVS2	Overshooting compensation 2	Set this with SV031 (OVS1) only when you wish to set the overshooting compensation amount to be different depending on the command directions. Set to "0" as a standard.	-1 to 100 (Stall [rated] current %)	
2243	SV043 OBS1	Disturbance observer filter frequency	Set the disturbance observer filter band. Set to "100" as a standard. To use the disturbance observer, also set SV037 (JL) and SV044 (OBS2). When not using, set to "0".	0 to 1000 (rad/s)	
2244	SV044 OBS2	Disturbance observer gain	Set the disturbance observer gain. The standard setting is "100" to "300". To use the disturbance observer, also set SV037 (JL) and SV043 (OBS1). When not using, set to "0".	0 to 500 (%)	
2245	The higher order 8bits and lower order 8bits are used for different functions. "Setting value of SV045" = (lcy*256) + LMCT			0 to 32767	
	SV045 TRUB (Low order)	Frictional torque	When you use the collision detection function, set the frictional torque.		0 to 100 (Stall [rated] current %)
	SV045 lb1 (High order)	Current bias 3	Set to "0" as a standard. Use this in combination with SV030 and the high order 8bits of SV040.		0 to 127
2246	SV046 FHz2	Notch filter frequency 2	Set the vibration frequency to suppress if machine vibration occurs. (Valid at 36 or more) When not using, set to "0".	0 to 9000 (Hz)	
2247	SV047 EC	Inductive voltage compensation gain	Set the inductive voltage compensation gain. Set to "100" as a standard. If the current FB peak exceeds the current command peak, lower the gain.	0 to 200 (%)	
2248	SV048 EMGrT	Vertical axis drop prevention time	Input a length of time to prevent the vertical axis from dropping by delaying Ready OFF until the brake works when the emergency stop occurs. Increase the setting by 100ms at a time and set the value where the axis does not drop.	0 to 20000 (ms)	

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range	
2249	SV049 PGN1sp	Position loop gain 1 in spindle synchronous control	Set the position loop gain during the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). Set the same value as the value of the spindle parameter, position loop gain in synchronous control. When performing the SHG control, set this with SV050 (PGN2sp) and SV058 (SHGCsp).	1 to 200 (rad/s)
2250	PGN2sp	Position loop gain 2 in spindle synchronous control	Set this with SV049 (PGN1sp) and SV058 (SHGCsp) if you wish to perform the SHG control in the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2251	SV051 DFBT	Dual feed back control time constant	Set the control time constant in dual feed back. When "0" is set, the actual value that is set is 1ms. The higher the time constant is, the closer it gets to the semi-closed control, so the limit of the position loop gain is raised.	0 to 9999 (ms)
2252	SV052 DFBN	Dual feedback control non-sensitive band	Set the non-sensitive band in the dual feedback control. Set to "0" as a standard.	0 to 9999 (μ m)
2253	SV053 OD3	Excessive error detection width in special control	Set the excessive error detection width when servo ON in a special control (initial absolute position setting, stopper control, etc.). If "0" is set, excessive error detection won't be performed when servo ON during a special control.	0 to 32767 (mm)

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range
2254	When SV035 (SSF4)/ bitF (ckab)=0		-1 to 32767 (mm)
	SV054 ORE	Overrun detection width in closed loop control Set the overrun detection width in the full-closed loop control. If the gap between the motor end detector and the linear scale (machine end detector) exceeds the value set by this parameter, it is judged to be overrun and Alarm 43 will be detected. When "-1" is set, the alarm detection won't be performed. When "0" is set, overrun is detected with a 2mm width.	
	When SV035 (SSF4)/ bitF (ckab)=1 (Note) This applies to only MDS-C1-Vx. The higher order 8bits and lower order 8bits are used for different functions. "Setting value of SV054" =(NSE*256)+ORE		0 to 32767
	SV054 ORE (Low order)	Overrun detection-width in closed loop control Set the overrun detection width in the full-closed loop control. If the gap between the motor end detector and the linear scale (machine end detector) exceeds the value set by this parameter, it is judged to be overrun and Alarm 43 will be detected. When "255" is set, the alarm detection won't be performed. When "0" is set, overrun is detected with a 2mm width.	0 to 255 (mm)
SV054 NSE (High order)	Special detection width for No signal 2 When SV035 (SSF4)/ bitF (ckab) =1, this setting is valid. Set the special detection width for No signal 2 (Alarm 21). When "0" is set, overrun is detected with a 15μm width.	0 to 127 (μm)	
2255	SV055 EMGx	Max. gate off delay time after emergency stop Set a length of time from the point when the emergency stop is input to the point when READY OFF is compulsorily executed. Normally, set the same value as the absolute value of SV056. In preventing the vertical axis from dropping, the gate off is delayed for the length of time set by SV048 if SV055's value is smaller than that of SV048.	0 to 20000 (ms)
2256	SV056 EMGt	Deceleration time constant at emergency stop In the vertical axis drop prevention time control, set the time constant used for the deceleration control at emergency stop. Set a length of time that takes from rapid traverse rate (rapid) to stopping. Normally, set the same value as the rapid traverse acceleration/deceleration time constant. When executing the synchronous operation, put the minus sign to the settings of both of the master axis and slave axis.	-20000 to 20000 (ms)
2257	SV057 SHGC	SHG control gain When performing the SHG control, set this with S003 (PGN1) and SV004 (PGN2). When not performing the SHG control, set to "0".	0 to 1200 (rad/s)
2258	SV058 SHGCsp	SHG control gain in spindle synchronous control Set this with SV049 (PGN1sp) and SV050 (PGN2sp) if you wish to perform the SHG control in the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). When not performing the SHG control, set to "0".	0 to 1200 (rad/s)

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

No.	Items	Details	Setting range
2259	SV059 TCNV	Collision detection torque estimating gain	-32768 to 32767
2260	SV060 TLMT	Collision detection level	0 to 999 (Stall [rated] current %)
2261	SV061 DA1NO	D/A output channel 1 data No.	-1 to 127
2262	SV062 DA2NO	D/A output channel 2 data No.	
2263	SV063 DA1MPY	D/A output channel 1 output scale	-32768 to 32767 (Unit: 1/256)
2264	SV064 DA2MPY	D/A output channel 2 output scale	
2265	SV065 TLC	Tool end compensation spring constant	-32768 to 32767

$$\text{Compensation amount} = \frac{F (\text{mm/min})^2 * \text{SV065}}{R (\text{mm}) * 10^9} (\mu\text{m})$$

F: Commanded speed
R: Radius

When not using, set to "0".

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

(2) Initial setting value

(a) HC**/HC**R series

Motor		HC 52	HC 102	HC 152	HC 202	HC 352	HC 452		HC 702		HC 902
Drive unit capacity		05	10	20	20	35	45s	45	70s	70	90
SV001	PC1	-	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-	-
SV003	PGN1	47	47	47	47	47	47	47	47	47	47
SV004	PGN2	0	0	0	0	0	0	0	0	0	0
SV005	VGN1	200	200	200	200	200	200	200	200	200	200
SV006	VGN2	0	0	0	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	4096	4096	4096	4096	4096	4096	4096
SV010	IDA	4096	4096	4096	4096	4096	4096	4096	4096	4096	4096
SV011	IQG	768	768	768	768	768	768	768	768	768	768
SV012	IDG	768	768	768	768	768	768	768	768	768	768
SV013	ILMT	500	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	1000	0000	1000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50	50	50	50
SV025	MTYP	xxB0	xxB1	xxB2	xxB3	xxB4	xx95	xxB5	xx96	xxB6	xxB7
SV026	OD2	6	6	6	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

Motor		HC 52	HC 102	HC 152	HC 202	HC 352	HC 452		HC 702		HC 902
Drive unit capacity		05	10	20	20	35	45s	45	70s	70	90
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0003	0003	0003	0003	0003	0003	0003	0003	0003	0003
SV035	SSF4	0000	0000	0040	0040	0040	0040	0040	0040	0040	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	10240	10240	10240	10240	10240	10240	10240
SV041	LMC2	0	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0	0
SV046	FHz2	0	0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0	0
SV065	TLC	0	0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

Motor		HC 53	HC 103	HC 153	HC 203	HC 353		HC 453		HC 703
Drive unit capacity		05	10	20	35	45s	45	70s	70	90
SV001	PC1	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-
SV003	PGN1	47	47	47	47	47	47	47	47	47
SV004	PGN2	0	0	0	0	0	0	0	0	0
SV005	VGN1	200	200	200	200	200	200	200	200	200
SV006	VGN2	0	0	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	4096	4096	4096	4096	4096	4096
SV010	IDA	4096	4096	4096	4096	4096	4096	4096	4096	4096
SV011	IQG	768	768	768	768	768	768	768	768	768
SV012	IDG	768	768	768	768	768	768	768	768	768
SV013	ILMT	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	1000	0000	1000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50	50	50
SV025	MTYP	xxC0	xxC1	xxC2	xxC3	xxA4	xxC4	xxA5	xxC5	xxC6
SV026	OD2	6	6	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

Motor		HC 53	HC 103	HC 153	HC 203	HC 353		HC 453		HC 703
Drive unit capacity		05	10	20	35	45s	45	70s	70	90
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0003	0003	0003	0003	0003	0003	0003	0003	0003
SV035	SSF4	0000	0000	0040	0040	0040	0040	0040	0040	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	10240	10240	10240	10240	10240	10240
SV041	LMC2	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0
SV046	FHz2	0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0
SV065	TLC	0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

Motor		HC 103R	HC 153R	HC 203R	HC 353R
Drive unit capacity		10	10	20	35
SV001	PC1	-	-	-	-
SV002	PC2	-	-	-	-
SV003	PGN1	33	33	33	33
SV004	PGN2	0	0	0	0
SV005	VGN1	15	15	20	40
SV006	VGN2	0	0	0	0
SV007	VIL	0	0	0	0
SV008	VIA	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	4096
SV010	IDA	4096	4096	4096	4096
SV011	IQG	256	256	256	256
SV012	IDG	512	512	512	512
SV013	ILMT	500	500	500	500
SV014	ILMT _{sp}	500	500	500	500
SV015	FFC	0	0	0	0
SV016	LMC1	0	0	0	0
SV017	SPEC	0000	0000	0000	0000
SV018	PIT	-	-	-	-
SV019	RNG1	-	-	-	-
SV020	RNG2	-	-	-	-
SV021	OLT	60	60	60	60
SV022	OLL	150	150	150	150
SV023	OD1	6	6	6	6
SV024	INP	50	50	50	50
SV025	MTYP	xxE1	xxE2	xxE3	xxE4
SV026	OD2	6	6	6	6
SV027	SSF1	4000	4000	4000	4000
SV028		0	0	0	0
SV029	VCS	0	0	0	0
SV030	IVC	0	0	0	0
SV031	OVS1	0	0	0	0
SV032	TOF	0	0	0	0

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

Motor		HC 103R	HC 153R	HC 203R	HC 353R
Drive unit capacity		10	10	20	35
SV033	SSF2	0200	0200	0200	0200
SV034	SSF3	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000
SV037	JL	0	0	0	0
SV038	FHz1	0	0	0	0
SV039	LMCD	0	0	0	0
SV040	LMCT	0	0	0	0
SV041	LMC2	0	0	0	0
SV042	OVS2	0	0	0	0
SV043	OBS1	0	0	0	0
SV044	OBS2	0	0	0	0
SV045	TRUB	0	0	0	0
SV046	FHz2	0	0	0	0
SV047	EC	100	100	100	100
SV048	EMGrt	0	0	0	0
SV049	PGN1sp	15	15	15	15
SV050	PGN2sp	0	0	0	0
SV051	DFBT	0	0	0	0
SV052	DFBN	0	0	0	0
SV053	OD3	0	0	0	0
SV054	ORE	0	0	0	0
SV055	EMGx	0	0	0	0
SV056	EMGt	0	0	0	0
SV057	SHGC	0	0	0	0
SV058	SHGCsp	0	0	0	0
SV059	TCNV	0	0	0	0
SV060	TLMT	0	0	0	0
SV061	DA1NO	0	0	0	0
SV062	DA2NO	0	0	0	0
SV063	DA1MPY	0	0	0	0
SV064	DA2MPY	0	0	0	0
SV065	TLC	0	0	0	0

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

(b) HA**N series

Motor		HA 40N	HA 80N	HA 100N	HA 200N	HA 300N	HA 700N	HA 900N
Drive unit capacity		05	10	20	35	45	70	90
SV001	PC1	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	25	25
SV004	PGN2	0	0	0	0	0	0	0
SV005	VGN1	150	150	150	150	150	250	250
SV006	VGN2	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	4096	4096	4096	4096
SV010	IDA	4096	4096	4096	4096	4096	4096	4096
SV011	IQG	768	768	768	768	768	768	768
SV012	IDG	768	768	768	768	768	768	768
SV013	ILMT	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50
SV025	MTYP	xx00	xx01	xx02	xx03	xx04	xx05	xx06
SV026	OD2	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

Motor		HA 40N	HA 80N	HA 100N	HA 200N	HA 300N	HA 700N	HA 900N
Drive unit capacity		05	10	20	35	45	70	90
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0000	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000	0000
SV036	PTYT	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0
SV046	FHz2	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0
SV065	TLC	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

Motor		HA 43N	HA 83N	HA 93N	HA 103N	HA 203N	HA 303N	HA 703N	HA 053N	HA 13N	HA 23N	HA 33N
Drive unit capacity		05	10	20	35	45	70	90	01	01	03	03
SV001	PC1	-	-	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	25	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0	0	0	0
SV005	VGN1	150	150	150	150	150	150	250	70	70	100	100
SV006		0	0	0	0	0	0	0	0	0	0	0
SV007		0	0	0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	4096	4096	4096	4096	4096	4096	4096	4096	4096	4096	4096
SV010	IDA	4096	4096	4096	4096	4096	4096	4096	4096	4096	4096	4096
SV011	IQG	768	768	768	768	768	768	768	768	768	768	768
SV012	IDG	768	768	768	768	768	768	768	768	768	768	768
SV013	ILMT	500	500	500	500	500	500	500	500	500	500	500
SV014	ILMT _{sp}	500	500	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50	50	50	50	50
SV025	MTYP	xx80	xx81	xx8A	xx82	xx83	xx84	xx85	xx8C	xx8D	xx8E	xx8F
SV026	OD2	6	6	6	6	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0	0	0
SV029		0	0	0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.2 MDS-C1-Vx HIGH-GAIN (MDS-B-Vx4 COMPATIBLE)

Motor		HA 43N	HA 83N	HA 93N	HA 103N	HA 203N	HA 303N	HA 703N	HA 053N	HA 13N	HA 23N	HA 33N
Drive unit capacity		05	10	20	35	45	70	90	01	01	03	03
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0	0	0
SV046	FHz2	0	0	0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0	0	0
SV065	TLC	0	0	0	0	0	0	0	0	0	0	0

7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)


(1) Details for servo parameters

For parameters marked with a (PR) in the table, turn the NC power OFF after setting. After the power is turned ON again, the parameter is validated.

⚠ CAUTION

⚠ In the explanation on bits, set all bits not used, including blank bits, to "0".

No.	Items	Details	Setting range
2201 (PR)	SV001 PC1	Motor side gear ratio	1 to 32767
2202 (PR)	SV002 PC2	Machine side gear ratio	1 to 32767
2203	SV003 PGN1	Position loop gain 1	1 to 200 (rad/s)
2204	SV004 PGN2	Position loop gain 2	0 to 999 (rad/s)
2205	SV005 VGN1	Speed loop gain 1	1 to 999
2206	SV006 VGN2	Speed loop gain 2	-1000 to 1000



7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range	
2207	SV007 VIL	Speed loop delay compensation	Set this when the limit cycle occurs in the full-closed loop, or overshooting occurs in positioning. Select the control method with SV027 (SSF1)/bit1, 0 (vcnt). Normally, use "Changeover type 2". When you set this parameter, make sure to set the torque offset (SV032 (TOF)). When not using, set to "0".	0 to 32767
		No changeover When SV027 (SSF1)/ bit1, 0 (vcnt)=00 The delay compensation control is always valid.		
		Changeover type 1 When SV027 (SSF1)/ bit1, 0 (vcnt)=01 The delay compensation control works when the command from the NC is "0". Overshooting that occurs during pulse feeding can be suppressed.		
		Changeover type 2 When SV027 (SSF1)/ bit1, 0 (vcnt)=10 The delay compensation control works when the command from the NC is "0" and the position droop is "0". Overshooting or the limit cycle that occurs during pulse feeding or positioning can be suppressed.		
2208	SV008 VIA	Speed loop lead compensation	Set the gain of the speed loop integration control. The standard setting is "1364". During the SHG control, the standard setting is "1900". Adjust the value by increasing/decreasing it by about 100 at a time. Raise this value to improve contour tracking precision in high-speed cutting. Lower this value when the position droop vibrates (10 to 20Hz).	1 to 9999
2209	SV009 IQA	Current loop q axis lead compensation	Set the gain of current loop. As this setting is determined by the motor's electrical characteristics, the setting is fixed for each type of motor.	1 to 20480
2210	SV010 IDA	Current loop d axis lead compensation	Set the standard values for all the parameters depending on each motor type.	1 to 20480
2211	SV011 IQG	Current loop q axis gain		1 to 2560
2212	SV012 IDG	Current loop d axis gain		1 to 2560
2213	SV013 ILMT	Current limit value	Set the normal current (torque) limit value. (Limit values for both + and - direction.) When the value is "500" (a standard setting), the maximum torque is determined by the specification of the motor.	0 to 999 (Stall [rated] current %)
2214	SV014 ILMTsp	Current limit value in special control	Set the current (torque) limit value in a special control (initial absolute position setting, stopper control, etc). (Limit values for both of the + and - directions.) Set to "500" when not using.	0 to 999 (Stall [rated] current %)

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range
2215	SV015 FFC	Acceleration rate feed forward gain When a relative error in the synchronous control is large, apply this parameter to the axis that is delaying. The standard setting value is "0". For the SHG control, set to "100". To adjust a relative error in acceleration/deceleration, increase the value by 50 to 100 at a time.	0 to 999 (%)
2216	SV016 LMC1	Lost motion compensation 1 Set this when the protrusion (that occurs due to the non-sensitive band by friction, torsion, backlash, etc) at quadrant change is too large. This compensates the torque at quadrant change. This is valid only when the lost motion compensation (SV027 (SSF1/lmc)) is selected. Type 1: When SV027 (SSF1)/ bit9, 8 (lmc)=01 Set the compensation amount based on the motor torque before the quadrant change. The standard setting is "100". Setting to "0" means the compensation amount is zero. Normally, use Type 2. Type 2: When SV027 (SSF1)/ bit9, 8 (lmc)=10 Set the compensation amount based on the stall (rated) current of the motor. The standard setting is double of the friction torque. Setting to "0" means the compensation amount is zero. When you wish different compensation amount depending on the direction When SV041 (LMC2) is "0", compensate with the value of SV016 (LMC1) in both of the + and -directions. If you wish to change the compensation amount depending on the command direction, set this and SV041 (LMC2). (SV016: + direction, SV041: - direction. However, the directions may be opposite depending on other settings.) When "-1" is set, the compensation won't be performed in the direction of the command.	-1 to 200 (%) -1 to 100 (Stall [rated] current %)

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range																																																																		
2217 (PR)	SV017 SPEC	Servo specification selection	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">E</td> <td style="text-align: center;">D</td> <td style="text-align: center;">C</td> <td style="text-align: center;">B</td> <td style="text-align: center;">A</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> </tr> <tr> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; width: 30px; height: 15px; text-align: center;">mpt3</td> <td style="border: 1px solid black; width: 30px; height: 15px; text-align: center;">mp</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">abs</td> <td style="border: 1px solid black; width: 30px; height: 15px;"></td> <td style="border: 1px solid black; text-align: center;">vdir</td> <td style="border: 1px solid black; text-align: center;">fdir</td> <td style="border: 1px solid black; text-align: center;">spwv</td> <td style="border: 1px solid black; text-align: center;">seqh</td> <td style="border: 1px solid black; text-align: center;">dfbx</td> <td style="border: 1px solid black; text-align: center;">fdir2</td> </tr> </table>	F	E	D	C	B	A	9	8							mpt3	mp	7	6	5	4	3	2	1	0	abs		vdir	fdir	spwv	seqh	dfbx	fdir2																																		
			F	E	D	C	B	A	9	8																																																											
									mpt3	mp																																																											
			7	6	5	4	3	2	1	0																																																											
			abs		vdir	fdir	spwv	seqh	dfbx	fdir2																																																											
			<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">bit</th> <th style="text-align: center;">Meaning when "0" is set</th> <th style="text-align: center;">Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">fdir2</td> <td>Speed feedback forward polarity</td> <td>Speed feedback reverse polarity</td> </tr> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">dfbx</td> <td>Dual feedback control stop</td> <td>Dual feedback control start</td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">seqh</td> <td>READY/Servo ON time normal</td> <td>READY/Servo ON time high speed</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">spwv</td> <td>Normal mode</td> <td>High gain servo synchronous mode</td> </tr> <tr> <td style="text-align: center;">4</td> <td style="text-align: center;">fdir</td> <td>Position feedback forward polarity</td> <td>Position feedback reverse polarity</td> </tr> <tr> <td style="text-align: center;">5</td> <td style="text-align: center;">vdir</td> <td rowspan="2">Standard setting</td> <td>HA motor (4 pole motor)</td> </tr> <tr> <td style="text-align: center;">6</td> <td style="text-align: center;"></td> <td>Detector installation position 90 degrees (B, D)</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">abs</td> <td>Incremental control</td> <td>Absolute position control</td> </tr> <tr> <td style="text-align: center;">8</td> <td style="text-align: center;">mp</td> <td>MP scale 360P (2mm pitch)</td> <td>MP scale 720P (1mm pitch)</td> </tr> <tr> <td style="text-align: center;">9</td> <td style="text-align: center;">mpt3</td> <td>MP scale ABS detection type 1, 2</td> <td>MP scale ABS detection type 3</td> </tr> <tr> <td style="text-align: center;">A</td> <td style="text-align: center;"></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">B</td> <td style="text-align: center;"></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">C</td> <td style="text-align: center;"></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">D</td> <td style="text-align: center;"></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">E</td> <td style="text-align: center;"></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;"></td> <td></td> <td></td> </tr> </tbody> </table>	bit	Meaning when "0" is set	Meaning when "1" is set	0	fdir2	Speed feedback forward polarity	Speed feedback reverse polarity	1	dfbx	Dual feedback control stop	Dual feedback control start	2	seqh	READY/Servo ON time normal	READY/Servo ON time high speed	3	spwv	Normal mode	High gain servo synchronous mode	4	fdir	Position feedback forward polarity	Position feedback reverse polarity	5	vdir	Standard setting	HA motor (4 pole motor)	6		Detector installation position 90 degrees (B, D)	7	abs	Incremental control	Absolute position control	8	mp	MP scale 360P (2mm pitch)	MP scale 720P (1mm pitch)	9	mpt3	MP scale ABS detection type 1, 2	MP scale ABS detection type 3	A				B				C				D				E				F			
			bit	Meaning when "0" is set	Meaning when "1" is set																																																																
			0	fdir2	Speed feedback forward polarity	Speed feedback reverse polarity																																																															
			1	dfbx	Dual feedback control stop	Dual feedback control start																																																															
			2	seqh	READY/Servo ON time normal	READY/Servo ON time high speed																																																															
			3	spwv	Normal mode	High gain servo synchronous mode																																																															
			4	fdir	Position feedback forward polarity	Position feedback reverse polarity																																																															
5	vdir	Standard setting	HA motor (4 pole motor)																																																																		
6			Detector installation position 90 degrees (B, D)																																																																		
7	abs	Incremental control	Absolute position control																																																																		
8	mp	MP scale 360P (2mm pitch)	MP scale 720P (1mm pitch)																																																																		
9	mpt3	MP scale ABS detection type 1, 2	MP scale ABS detection type 3																																																																		
A																																																																					
B																																																																					
C																																																																					
D																																																																					
E																																																																					
F																																																																					
(Note) Set to "0" for bits with no particular description.																																																																					
2218 (PR)	SV018 PIT	Ball screw pitch	Set the ball screw pitch. Set to "360" for the rotary axis. 1 to 32767 (mm/rev)																																																																		

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range																											
2219 (PR)	SV019 RNG1	Position detector resolution	In the case of the semi-closed loop control Set the same value as SV020 (RNG2). (Refer to the explanation of SV020.)	1 to 9999 (kp/rev)																										
			In the case of the full-closed loop control Set the number of pulses per ball screw pitch.	1 to 9999 (kp/pit)																										
		<table border="1"> <thead> <tr> <th>Detector model name</th> <th>Resolution</th> <th>SV019 setting</th> </tr> </thead> <tbody> <tr> <td>OHE25K-ET, OHA25K-ET</td> <td>100,000(p/rev)</td> <td>100</td> </tr> <tr> <td>OSE104-ET, OSA104-ET</td> <td>100,000(p/rev)</td> <td>100</td> </tr> <tr> <td>OSE105-ET, OSA105-ET</td> <td>1,000,000(p/rev)</td> <td>1000</td> </tr> <tr> <td>Relative position detection scale</td> <td>Refer to specification manual for each detector</td> <td>PIT/Resolution (μm)</td> </tr> <tr> <td>AT41 (Mitsutoyo)</td> <td>1 (μm/p)</td> <td>The same as SV018 (PIT)</td> </tr> <tr> <td>FME type, FLE type (Futaba)</td> <td>Refer to specification manual for each detector</td> <td>PIT/Resolution (μm)</td> </tr> <tr> <td>MP type (Mitsubishi Heavy Industries)</td> <td>Refer to specification manual for each detector</td> <td>PIT/Resolution (μm)</td> </tr> <tr> <td>AT342 (Mitsutoyo)</td> <td>0.5 (μm/p)</td> <td>Twice as big as SV018 (PIT)</td> </tr> </tbody> </table>	Detector model name	Resolution	SV019 setting	OHE25K-ET, OHA25K-ET	100,000(p/rev)	100	OSE104-ET, OSA104-ET	100,000(p/rev)	100	OSE105-ET, OSA105-ET	1,000,000(p/rev)	1000	Relative position detection scale	Refer to specification manual for each detector	PIT/Resolution (μm)	AT41 (Mitsutoyo)	1 (μm/p)	The same as SV018 (PIT)	FME type, FLE type (Futaba)	Refer to specification manual for each detector	PIT/Resolution (μm)	MP type (Mitsubishi Heavy Industries)	Refer to specification manual for each detector	PIT/Resolution (μm)	AT342 (Mitsutoyo)	0.5 (μm/p)	Twice as big as SV018 (PIT)	
Detector model name	Resolution	SV019 setting																												
OHE25K-ET, OHA25K-ET	100,000(p/rev)	100																												
OSE104-ET, OSA104-ET	100,000(p/rev)	100																												
OSE105-ET, OSA105-ET	1,000,000(p/rev)	1000																												
Relative position detection scale	Refer to specification manual for each detector	PIT/Resolution (μm)																												
AT41 (Mitsutoyo)	1 (μm/p)	The same as SV018 (PIT)																												
FME type, FLE type (Futaba)	Refer to specification manual for each detector	PIT/Resolution (μm)																												
MP type (Mitsubishi Heavy Industries)	Refer to specification manual for each detector	PIT/Resolution (μm)																												
AT342 (Mitsutoyo)	0.5 (μm/p)	Twice as big as SV018 (PIT)																												
2220 (PR)	SV020 RNG2	Speed detector resolution	Set the number of pulses per one revolution of the motor end detector.	1 to 9999 (kp/rev)																										
			<table border="1"> <thead> <tr> <th>Detector model name</th> <th>SV020 setting</th> </tr> </thead> <tbody> <tr> <td>Equipped to HA053, HA13 (Only for MDS-B-Vx)</td> <td>10</td> </tr> <tr> <td>OHE25K, OHA25K (Only for MDS-B-Vx)</td> <td>100</td> </tr> <tr> <td>OSE104, OSA104</td> <td>100</td> </tr> <tr> <td>OSE105, OSA105</td> <td>1000</td> </tr> </tbody> </table>		Detector model name	SV020 setting	Equipped to HA053, HA13 (Only for MDS-B-Vx)	10	OHE25K, OHA25K (Only for MDS-B-Vx)	100	OSE104, OSA104	100	OSE105, OSA105	1000																
Detector model name	SV020 setting																													
Equipped to HA053, HA13 (Only for MDS-B-Vx)	10																													
OHE25K, OHA25K (Only for MDS-B-Vx)	100																													
OSE104, OSA104	100																													
OSE105, OSA105	1000																													
2221	SV021 OLT	Overload detection time constant	Set the detection time constant of Overload 1 (Alarm 50). Set to "60" as a standard. (For machine tool builder adjustment.)	1 to 999 (s)																										
2222	SV022 OLL	Overload detection level	Set the current detection level of Overload 1 (Alarm 50) in respect to the stall (rated) current. Set to "150" as a standard. (For machine tool builder adjustment.)	110 to 500 (Stall [rated] current %)																										
2223	SV023 OD1	Excessive error detection width during servo ON	Set the excessive error detection width when servo ON. <Standard setting value> $OD1=OD2= \frac{\text{Rapid traverse rate (mm/min)}}{60 \cdot \text{PGN1}} / 2 \text{ (mm)}$ When "0" is set, the excessive error detection will not be performed.	0 to 32767 (mm)																										

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range																																																																																																																																																																																																																																																																																																																																																								
2224	SV024 INP	In-position detection width	0 to 32767 (μm)																																																																																																																																																																																																																																																																																																																																																								
2225 (PR)	SV025 MTYP	Motor/ Detector type	<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <tr> <td style="width: 12.5%;">F</td><td style="width: 12.5%;">E</td><td style="width: 12.5%;">D</td><td style="width: 12.5%;">C</td><td style="width: 12.5%;">B</td><td style="width: 12.5%;">A</td><td style="width: 12.5%;">9</td><td style="width: 12.5%;">8</td> </tr> <tr> <td colspan="4">pen</td><td colspan="4">ent</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td colspan="8">mtyp</td> </tr> </table> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">bit</th> <th style="width: 95%;">Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>Set the motor type.</td> </tr> <tr> <td>1</td> <td rowspan="16" style="vertical-align: middle;"> <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th style="width: 5%;">Set- ting</th> <th style="width: 10%;">0x</th> <th style="width: 5%;">1x</th> <th style="width: 10%;">2x</th> <th style="width: 10%;">3x</th> <th style="width: 5%;">4x</th> <th style="width: 5%;">5x</th> <th style="width: 5%;">6x</th> <th style="width: 5%;">7x</th> </tr> </thead> <tbody> <tr><td>x0</td><td>HA40N</td><td></td><td>HA50L</td><td>HA53L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x1</td><td>HA80N</td><td></td><td>HA100L</td><td>HA103L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x2</td><td>HA100N</td><td></td><td>HA200L</td><td>HA203L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x3</td><td>HA200N</td><td></td><td>HA300L</td><td>HA303L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x4</td><td>HA300N</td><td></td><td>HA500L</td><td>HA503L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x5</td><td>HA700N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x6</td><td>HA900N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x7</td><td></td><td></td><td>HA-LH11K2</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x8</td><td></td><td></td><td>HA-LH15K2</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x9</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xA</td><td></td><td></td><td>HA150L</td><td>HA153L</td><td></td><td></td><td></td><td></td></tr> <tr><td>xB</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xC</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xD</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xE</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xF</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table> <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th style="width: 5%;">Set- ting</th> <th style="width: 10%;">8x</th> <th style="width: 5%;">9x</th> <th style="width: 5%;">Ax</th> <th style="width: 10%;">Bx</th> <th style="width: 10%;">Cx</th> <th style="width: 5%;">Dx</th> <th style="width: 5%;">Ex</th> <th style="width: 5%;">Fx</th> </tr> </thead> <tbody> <tr><td>x0</td><td>HA43N</td><td></td><td></td><td>HC52</td><td>HC53</td><td></td><td></td><td></td></tr> <tr><td>x1</td><td>HA83N</td><td></td><td></td><td>HC102</td><td>HC103</td><td></td><td>HC103R</td><td></td></tr> <tr><td>x2</td><td>HA103N</td><td></td><td></td><td>HC152</td><td>HC153</td><td></td><td>HC153R</td><td></td></tr> <tr><td>x3</td><td>HA203N</td><td></td><td></td><td>HC202</td><td>HC203</td><td></td><td>HC203R</td><td></td></tr> <tr><td>x4</td><td>HA303N</td><td></td><td></td><td>HC352</td><td>HC353</td><td></td><td>HC353R</td><td></td></tr> <tr><td>x5</td><td>HA703N</td><td></td><td></td><td>HC452</td><td>HC453</td><td></td><td>HC503R</td><td></td></tr> <tr><td>x6</td><td></td><td></td><td></td><td>HC702</td><td>HC703</td><td></td><td></td><td></td></tr> <tr><td>x7</td><td></td><td></td><td></td><td>HC902</td><td></td><td></td><td></td><td></td></tr> <tr><td>x8</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x9</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xA</td><td>HA93N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xB</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xC</td><td>HA053(N)</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xD</td><td>HA13(N)</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xE</td><td>HA23N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xF</td><td>HA33N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table> </td> </tr> </tbody> </table> <p style="text-align: right; margin-right: 50px;">(To be continued to the next page)</p>	F	E	D	C	B	A	9	8	pen				ent				7	6	5	4	3	2	1	0	mtyp								bit	Explanation	0	Set the motor type.	1	<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th style="width: 5%;">Set- ting</th> <th style="width: 10%;">0x</th> <th style="width: 5%;">1x</th> <th style="width: 10%;">2x</th> <th style="width: 10%;">3x</th> <th style="width: 5%;">4x</th> <th style="width: 5%;">5x</th> <th style="width: 5%;">6x</th> <th style="width: 5%;">7x</th> </tr> </thead> <tbody> <tr><td>x0</td><td>HA40N</td><td></td><td>HA50L</td><td>HA53L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x1</td><td>HA80N</td><td></td><td>HA100L</td><td>HA103L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x2</td><td>HA100N</td><td></td><td>HA200L</td><td>HA203L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x3</td><td>HA200N</td><td></td><td>HA300L</td><td>HA303L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x4</td><td>HA300N</td><td></td><td>HA500L</td><td>HA503L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x5</td><td>HA700N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x6</td><td>HA900N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x7</td><td></td><td></td><td>HA-LH11K2</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x8</td><td></td><td></td><td>HA-LH15K2</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x9</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xA</td><td></td><td></td><td>HA150L</td><td>HA153L</td><td></td><td></td><td></td><td></td></tr> <tr><td>xB</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xC</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xD</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xE</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xF</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table> <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th style="width: 5%;">Set- ting</th> <th style="width: 10%;">8x</th> <th style="width: 5%;">9x</th> <th style="width: 5%;">Ax</th> <th style="width: 10%;">Bx</th> <th style="width: 10%;">Cx</th> <th style="width: 5%;">Dx</th> <th style="width: 5%;">Ex</th> <th style="width: 5%;">Fx</th> </tr> </thead> <tbody> <tr><td>x0</td><td>HA43N</td><td></td><td></td><td>HC52</td><td>HC53</td><td></td><td></td><td></td></tr> <tr><td>x1</td><td>HA83N</td><td></td><td></td><td>HC102</td><td>HC103</td><td></td><td>HC103R</td><td></td></tr> <tr><td>x2</td><td>HA103N</td><td></td><td></td><td>HC152</td><td>HC153</td><td></td><td>HC153R</td><td></td></tr> <tr><td>x3</td><td>HA203N</td><td></td><td></td><td>HC202</td><td>HC203</td><td></td><td>HC203R</td><td></td></tr> <tr><td>x4</td><td>HA303N</td><td></td><td></td><td>HC352</td><td>HC353</td><td></td><td>HC353R</td><td></td></tr> <tr><td>x5</td><td>HA703N</td><td></td><td></td><td>HC452</td><td>HC453</td><td></td><td>HC503R</td><td></td></tr> <tr><td>x6</td><td></td><td></td><td></td><td>HC702</td><td>HC703</td><td></td><td></td><td></td></tr> <tr><td>x7</td><td></td><td></td><td></td><td>HC902</td><td></td><td></td><td></td><td></td></tr> <tr><td>x8</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x9</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xA</td><td>HA93N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xB</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xC</td><td>HA053(N)</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xD</td><td>HA13(N)</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xE</td><td>HA23N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xF</td><td>HA33N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table>	Set- ting	0x	1x	2x	3x	4x	5x	6x	7x	x0	HA40N		HA50L	HA53L					x1	HA80N		HA100L	HA103L					x2	HA100N		HA200L	HA203L					x3	HA200N		HA300L	HA303L					x4	HA300N		HA500L	HA503L					x5	HA700N								x6	HA900N								x7			HA-LH11K2						x8			HA-LH15K2						x9									xA			HA150L	HA153L					xB									xC									xD									xE									xF									Set- ting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx	x0	HA43N			HC52	HC53				x1	HA83N			HC102	HC103		HC103R		x2	HA103N			HC152	HC153		HC153R		x3	HA203N			HC202	HC203		HC203R		x4	HA303N			HC352	HC353		HC353R		x5	HA703N			HC452	HC453		HC503R		x6				HC702	HC703				x7				HC902					x8									x9									xA	HA93N								xB									xC	HA053(N)								xD	HA13(N)								xE	HA23N								xF	HA33N							
F	E	D	C	B	A	9	8																																																																																																																																																																																																																																																																																																																																																				
pen				ent																																																																																																																																																																																																																																																																																																																																																							
7	6	5	4	3	2	1	0																																																																																																																																																																																																																																																																																																																																																				
mtyp																																																																																																																																																																																																																																																																																																																																																											
bit	Explanation																																																																																																																																																																																																																																																																																																																																																										
0	Set the motor type.																																																																																																																																																																																																																																																																																																																																																										
1	<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th style="width: 5%;">Set- ting</th> <th style="width: 10%;">0x</th> <th style="width: 5%;">1x</th> <th style="width: 10%;">2x</th> <th style="width: 10%;">3x</th> <th style="width: 5%;">4x</th> <th style="width: 5%;">5x</th> <th style="width: 5%;">6x</th> <th style="width: 5%;">7x</th> </tr> </thead> <tbody> <tr><td>x0</td><td>HA40N</td><td></td><td>HA50L</td><td>HA53L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x1</td><td>HA80N</td><td></td><td>HA100L</td><td>HA103L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x2</td><td>HA100N</td><td></td><td>HA200L</td><td>HA203L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x3</td><td>HA200N</td><td></td><td>HA300L</td><td>HA303L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x4</td><td>HA300N</td><td></td><td>HA500L</td><td>HA503L</td><td></td><td></td><td></td><td></td></tr> <tr><td>x5</td><td>HA700N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x6</td><td>HA900N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x7</td><td></td><td></td><td>HA-LH11K2</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x8</td><td></td><td></td><td>HA-LH15K2</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x9</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xA</td><td></td><td></td><td>HA150L</td><td>HA153L</td><td></td><td></td><td></td><td></td></tr> <tr><td>xB</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xC</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xD</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xE</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xF</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table> <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th style="width: 5%;">Set- ting</th> <th style="width: 10%;">8x</th> <th style="width: 5%;">9x</th> <th style="width: 5%;">Ax</th> <th style="width: 10%;">Bx</th> <th style="width: 10%;">Cx</th> <th style="width: 5%;">Dx</th> <th style="width: 5%;">Ex</th> <th style="width: 5%;">Fx</th> </tr> </thead> <tbody> <tr><td>x0</td><td>HA43N</td><td></td><td></td><td>HC52</td><td>HC53</td><td></td><td></td><td></td></tr> <tr><td>x1</td><td>HA83N</td><td></td><td></td><td>HC102</td><td>HC103</td><td></td><td>HC103R</td><td></td></tr> <tr><td>x2</td><td>HA103N</td><td></td><td></td><td>HC152</td><td>HC153</td><td></td><td>HC153R</td><td></td></tr> <tr><td>x3</td><td>HA203N</td><td></td><td></td><td>HC202</td><td>HC203</td><td></td><td>HC203R</td><td></td></tr> <tr><td>x4</td><td>HA303N</td><td></td><td></td><td>HC352</td><td>HC353</td><td></td><td>HC353R</td><td></td></tr> <tr><td>x5</td><td>HA703N</td><td></td><td></td><td>HC452</td><td>HC453</td><td></td><td>HC503R</td><td></td></tr> <tr><td>x6</td><td></td><td></td><td></td><td>HC702</td><td>HC703</td><td></td><td></td><td></td></tr> <tr><td>x7</td><td></td><td></td><td></td><td>HC902</td><td></td><td></td><td></td><td></td></tr> <tr><td>x8</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>x9</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xA</td><td>HA93N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xB</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xC</td><td>HA053(N)</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xD</td><td>HA13(N)</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xE</td><td>HA23N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>xF</td><td>HA33N</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr> </tbody> </table>	Set- ting	0x	1x	2x	3x	4x	5x	6x	7x	x0	HA40N		HA50L	HA53L					x1	HA80N		HA100L	HA103L					x2	HA100N		HA200L	HA203L					x3	HA200N			HA300L	HA303L					x4	HA300N		HA500L	HA503L					x5	HA700N								x6	HA900N								x7			HA-LH11K2						x8			HA-LH15K2						x9									xA			HA150L	HA153L					xB									xC									xD									xE									xF									Set- ting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx	x0	HA43N			HC52	HC53				x1	HA83N			HC102	HC103		HC103R		x2	HA103N			HC152	HC153		HC153R		x3	HA203N			HC202	HC203		HC203R		x4	HA303N			HC352	HC353		HC353R		x5	HA703N			HC452	HC453		HC503R		x6				HC702	HC703				x7				HC902					x8									x9									xA	HA93N								xB									xC	HA053(N)								xD	HA13(N)								xE	HA23N								xF	HA33N																																														
Set- ting		0x	1x	2x	3x	4x	5x	6x	7x																																																																																																																																																																																																																																																																																																																																																		
x0		HA40N		HA50L	HA53L																																																																																																																																																																																																																																																																																																																																																						
x1		HA80N		HA100L	HA103L																																																																																																																																																																																																																																																																																																																																																						
x2		HA100N		HA200L	HA203L																																																																																																																																																																																																																																																																																																																																																						
x3		HA200N		HA300L	HA303L																																																																																																																																																																																																																																																																																																																																																						
x4		HA300N		HA500L	HA503L																																																																																																																																																																																																																																																																																																																																																						
x5		HA700N																																																																																																																																																																																																																																																																																																																																																									
x6		HA900N																																																																																																																																																																																																																																																																																																																																																									
x7				HA-LH11K2																																																																																																																																																																																																																																																																																																																																																							
x8				HA-LH15K2																																																																																																																																																																																																																																																																																																																																																							
x9																																																																																																																																																																																																																																																																																																																																																											
xA				HA150L	HA153L																																																																																																																																																																																																																																																																																																																																																						
xB																																																																																																																																																																																																																																																																																																																																																											
xC																																																																																																																																																																																																																																																																																																																																																											
xD																																																																																																																																																																																																																																																																																																																																																											
xE																																																																																																																																																																																																																																																																																																																																																											
xF																																																																																																																																																																																																																																																																																																																																																											
Set- ting	8x	9x	Ax	Bx	Cx	Dx	Ex	Fx																																																																																																																																																																																																																																																																																																																																																			
x0	HA43N			HC52	HC53																																																																																																																																																																																																																																																																																																																																																						
x1	HA83N			HC102	HC103		HC103R																																																																																																																																																																																																																																																																																																																																																				
x2	HA103N			HC152	HC153		HC153R																																																																																																																																																																																																																																																																																																																																																				
x3	HA203N			HC202	HC203		HC203R																																																																																																																																																																																																																																																																																																																																																				
x4	HA303N			HC352	HC353		HC353R																																																																																																																																																																																																																																																																																																																																																				
x5	HA703N			HC452	HC453		HC503R																																																																																																																																																																																																																																																																																																																																																				
x6				HC702	HC703																																																																																																																																																																																																																																																																																																																																																						
x7				HC902																																																																																																																																																																																																																																																																																																																																																							
x8																																																																																																																																																																																																																																																																																																																																																											
x9																																																																																																																																																																																																																																																																																																																																																											
xA	HA93N																																																																																																																																																																																																																																																																																																																																																										
xB																																																																																																																																																																																																																																																																																																																																																											
xC	HA053(N)																																																																																																																																																																																																																																																																																																																																																										
xD	HA13(N)																																																																																																																																																																																																																																																																																																																																																										
xE	HA23N																																																																																																																																																																																																																																																																																																																																																										
xF	HA33N																																																																																																																																																																																																																																																																																																																																																										

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range																																																																																	
		(Continued from the previous page)																																																																																		
		<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">bit</th> <th colspan="3" style="text-align: center;">Explanation</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">8</td> <td rowspan="4" style="text-align: center; vertical-align: middle;">ent</td> <td colspan="2" rowspan="4"></td> <td rowspan="4">Set the detector type. Set position detector type for "pen", and speed detector type for "ent". In the case of the semi-closed loop control, set the same value for "pen" and "ent".</td> </tr> <tr><td style="text-align: center;">9</td></tr> <tr><td style="text-align: center;">A</td></tr> <tr><td style="text-align: center;">B</td></tr> <tr> <td style="text-align: center;">C</td> <td rowspan="14" style="text-align: center; vertical-align: middle;">pen</td> <td style="text-align: center;">pen setting</td> <td style="text-align: center;">ent setting</td> <td style="text-align: center;">Detector model name</td> </tr> <tr> <td style="text-align: center;">D</td> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> <td>OHE25K (Only for MDS-B-Vx), OSE104</td> </tr> <tr> <td style="text-align: center;">E</td> <td style="text-align: center;">1</td> <td style="text-align: center;">1</td> <td>OHA25K (Only for MDS-B-Vx), OSA104</td> </tr> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">2</td> <td style="text-align: center;">2</td> <td>OSE105, OSA105</td> </tr> <tr> <td></td> <td style="text-align: center;">3</td> <td style="text-align: center;">3</td> <td>Equipped to HA053, HA13 (Only for MDS-B-Vx)</td> </tr> <tr> <td></td> <td style="text-align: center;">4</td> <td style="text-align: center;">Setting impossible</td> <td>OHE25K-ET, OSE104-ET</td> </tr> <tr> <td></td> <td style="text-align: center;">5</td> <td style="text-align: center;">Setting impossible</td> <td>OHA25K-ET, OSA104-ET</td> </tr> <tr> <td></td> <td style="text-align: center;">6</td> <td style="text-align: center;">Setting impossible</td> <td>OSE105-ET, OSA105-ET</td> </tr> <tr> <td></td> <td style="text-align: center;">7</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">8</td> <td style="text-align: center;">Setting impossible</td> <td>Relative position detection scale, MP type (Mitsubishi Heavy Industries)</td> </tr> <tr> <td></td> <td style="text-align: center;">9</td> <td style="text-align: center;">Setting impossible</td> <td>AT41 (Mitsutoyo), FME type, FLE type (Futaba)</td> </tr> <tr> <td></td> <td style="text-align: center;">A</td> <td style="text-align: center;">Setting impossible</td> <td>AT342 (Mitsutoyo)</td> </tr> <tr> <td></td> <td style="text-align: center;">B</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">C</td> <td style="text-align: center;">C (Current synchronization)</td> <td>The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.</td> </tr> <tr> <td></td> <td style="text-align: center;">D</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">E</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">F</td> <td style="text-align: center;">Setting impossible</td> <td></td> </tr> </tbody> </table>	bit	Explanation			8	ent			Set the detector type. Set position detector type for "pen", and speed detector type for "ent". In the case of the semi-closed loop control, set the same value for "pen" and "ent".	9	A	B	C	pen	pen setting	ent setting	Detector model name	D	0	0	OHE25K (Only for MDS-B-Vx), OSE104	E	1	1	OHA25K (Only for MDS-B-Vx), OSA104	F	2	2	OSE105, OSA105		3	3	Equipped to HA053, HA13 (Only for MDS-B-Vx)		4	Setting impossible	OHE25K-ET, OSE104-ET		5	Setting impossible	OHA25K-ET, OSA104-ET		6	Setting impossible	OSE105-ET, OSA105-ET		7	Setting impossible			8	Setting impossible	Relative position detection scale, MP type (Mitsubishi Heavy Industries)		9	Setting impossible	AT41 (Mitsutoyo), FME type, FLE type (Futaba)		A	Setting impossible	AT342 (Mitsutoyo)		B	Setting impossible			C	C (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.		D	Setting impossible			E	Setting impossible			F	Setting impossible		
bit	Explanation																																																																																			
8	ent			Set the detector type. Set position detector type for "pen", and speed detector type for "ent". In the case of the semi-closed loop control, set the same value for "pen" and "ent".																																																																																
9																																																																																				
A																																																																																				
B																																																																																				
C	pen	pen setting	ent setting	Detector model name																																																																																
D		0	0	OHE25K (Only for MDS-B-Vx), OSE104																																																																																
E		1	1	OHA25K (Only for MDS-B-Vx), OSA104																																																																																
F		2	2	OSE105, OSA105																																																																																
		3	3	Equipped to HA053, HA13 (Only for MDS-B-Vx)																																																																																
		4	Setting impossible	OHE25K-ET, OSE104-ET																																																																																
		5	Setting impossible	OHA25K-ET, OSA104-ET																																																																																
		6	Setting impossible	OSE105-ET, OSA105-ET																																																																																
		7	Setting impossible																																																																																	
		8	Setting impossible	Relative position detection scale, MP type (Mitsubishi Heavy Industries)																																																																																
		9	Setting impossible	AT41 (Mitsutoyo), FME type, FLE type (Futaba)																																																																																
		A	Setting impossible	AT342 (Mitsutoyo)																																																																																
		B	Setting impossible																																																																																	
		C	C (Current synchronization)	The setting of the slave axis in the speed/current synchronization control. When the master axis is the semi-closed control.																																																																																
	D	Setting impossible																																																																																		
	E	Setting impossible																																																																																		
	F	Setting impossible																																																																																		
2226	SV026 OD2	Excessive error detection width during servo OFF	<p>Set the excessive error detection width when servo ON.</p> <p>For the standard setting, refer to the explanation of SV023 (OD1).</p> <p>When "0" is set, the excessive error detection will not be performed.</p>	0 to 32767 (mm)																																																																																

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range																																
2227	SV027 SSF1 Servo function selection 1	<table style="width: 100%; border-collapse: collapse; margin-bottom: 5px;"> <tr> <td style="width: 12.5%; text-align: center;">F</td> <td style="width: 12.5%; text-align: center;">E</td> <td style="width: 12.5%; text-align: center;">D</td> <td style="width: 12.5%; text-align: center;">C</td> <td style="width: 12.5%; text-align: center;">B</td> <td style="width: 12.5%; text-align: center;">A</td> <td style="width: 12.5%; text-align: center;">9</td> <td style="width: 12.5%; text-align: center;">8</td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">aflt</td> <td style="border: 1px solid black; text-align: center;">zrn2</td> <td style="border: 1px solid black; text-align: center;">afse</td> <td style="border: 1px solid black; text-align: center;"> </td> <td style="border: 1px solid black; text-align: center;">ovs</td> <td style="border: 1px solid black; text-align: center;"> </td> <td style="border: 1px solid black; text-align: center;">lmc</td> <td style="border: 1px solid black; text-align: center;"> </td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td style="border: 1px solid black; text-align: center;"> </td> <td style="border: 1px solid black; text-align: center;">zrn3</td> <td style="border: 1px solid black; text-align: center;">vfct</td> <td style="border: 1px solid black; text-align: center;"> </td> <td style="border: 1px solid black; text-align: center;"> </td> <td style="border: 1px solid black; text-align: center;">upc</td> <td style="border: 1px solid black; text-align: center;"> </td> <td style="border: 1px solid black; text-align: center;">vcnt</td> </tr> </table>	F	E	D	C	B	A	9	8	aflt	zrn2	afse		ovs		lmc		7	6	5	4	3	2	1	0		zrn3	vfct			upc		vcnt	
		F	E	D	C	B	A	9	8																										
		aflt	zrn2	afse		ovs		lmc																											
		7	6	5	4	3	2	1	0																										
			zrn3	vfct			upc		vcnt																										
		bit	Meaning when "0" is set	Meaning when "1" is set																															
		0	vcnt	Set the execution changeover type of the speed loop delay compensation.																															
		1		00: Delay compensation changeover invalid 01: Delay compensation changeover type 1 10: Delay compensation type 2 11: Setting prohibited																															
		2	upc	Start torque compensation invalid	Start torque compensation valid																														
		3																																	
		4	vfct	Set the number of compensation pulses of the jitter compensation.																															
		5		00: Jitter compensation invalid 01: Jitter compensation 1 pulse 10: Jitter compensation 2 pulses 11: Jitter compensation 3 pulses																															
		6	zrn3	ABS scale: Set to "1" in using AT342, AT343, LC191M/491M.																															
		7																																	
		8	lmc	Set the compensation amount with SV016 (LMC1) and SV041 (LMC2).																															
9		00: Lost motion compensation stop 01: Lost motion compensation type 1 10: Lost motion compensation type 2 11: Setting prohibited																																	
A	ovs	Set the compensation amount with SV031 (OVS1) and SV042 (OVS2).																																	
B		00: Overshooting compensation stop 01: Overshooting compensation type 1 10: Overshooting compensation type 2 11: Overshooting compensation type 3																																	
C		00: Adoptive filter sensitivity standard																																	
D	afse	11: Adoptive filter sensitivity increase (Set 2bits at a time)																																	
E	zrn2	Set to "1".																																	
F	aflt	Adoptive filter stops	Adoptive filter starts																																
(Note) Set to "0" for bits with no particular description.																																			
2228	SV028	Not used. Set to "0".	0																																
2229	SV029 VCS	Speed at the change of speed loop gain If the noise is bothersome at high speed during rapid traverse, etc, lower the speed loop gain. Set the speed at which the speed loop gain changes, and use this with SV006 (VGN2). (Refer to SV006.) When not using, set to "0".	0 to 9999 (r/min)																																

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range
2230	The higher order 8bits and lower order 8bits are used for different functions. "The setting value of SV030" = (Icx*256) + IVC		0 to 32767
	SV030 IVC (Low order)	Voltage dead time compensation When 100% is set, the voltage equivalent to the logical non-energized time will be compensated. When "0" is set, a 100% compensation will be performed. Adjust in increments of 10% from the default value 100%. If increased too much, vibration or vibration noise may be generated.	0 to 255 (%)
	SV030 Icx (High order)	Current bias 1 Set to "0" as a standard. Use this in combination with SV040 and the high order 8bits of SV045.	0 to 127
2231	SV031 OVS1 1	Overshooting compensation Set this if overshooting occurs during positioning. This compensates the motor torque during positioning. This is valid only when the overshooting compensation SV027 (SSF1/ovs) is selected.	-1 to 100 (Stall [rated] current%)
		Type 1: When SV027 (SSF1)/ bitB, A (ovs)=01 Set the compensation amount based on the motor's stall current. This compensates overshooting that occurs during pulse feeding. Normally, use Type 2.	
		Type 2: When SV027 (SSF1)/ bitB, A (ovs)=10 Set the compensation amount based on the motor's stall current. Increase by 1% and determine the amount that overshooting doesn't occur. In Type 2, compensation during the feed forward control during circular cutting won't be performed.	
		Type 3: When SV027 (SSF1)/ bitB, A (ovs)=11 Use this to perform the overshooting compensation during circular cutting or the feed forward control. The setting method is the same in Type 2.	
		When you wish different compensation amount depending on the direction When SV042 (OVS2) is "0", compensate with the value of SV031 (OVS1) in both of the + and -directions. If you wish to change the compensation amount depending on the command direction, set this and SV042 (OVS2). (SV031: + direction, SV042: - direction. However, the directions may be opposite depending on other settings.) When "-1" is set, the compensation won't be performed in the direction of the command.	

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range																																																																																																																							
2232	SV032 TOF	Torque offset	Set the unbalance torque of vertical axis and inclined axis.																																																																																																																							
			-100 to 100 (Stall [rated] current %)																																																																																																																							
2233	SV033 SSF2	Servo function selection 2	<table border="1" style="width: 100%; text-align: center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td colspan="4">dos</td> <td></td><td></td><td>hvx</td><td>svx</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td colspan="4">fhz2</td> <td colspan="3">nfd</td><td>zck</td> </tr> </table> <table border="1" style="width: 100%; text-align: center;"> <thead> <tr> <th>bit</th> <th>Meaning when "0" is set</th> <th>Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>zck</td> <td>Z phase check valid (Alarm 42)</td> <td>Z phase check invalid</td> </tr> <tr> <td>1</td> <td>nfd1</td> <td colspan="2">Set the filter depth for Notch filter 1 (SV038).</td> </tr> <tr> <td>2</td> <td></td> <td>Value</td> <td>000 001 010 011 100 101 110 111</td> </tr> <tr> <td>3</td> <td></td> <td>Depth (dB)</td> <td>Infntly deep -18.1 -12.0 -8.5 -6.0 -4.1 -2.5 -1.2</td> </tr> <tr> <td></td> <td></td> <td colspan="2">Deep ← → Shallow</td> </tr> <tr> <td>4</td> <td></td> <td colspan="2">Set the operation frequency of Notch filter 2.</td> </tr> <tr> <td>5</td> <td rowspan="4">fhz2</td> <td>0: Invalid</td> <td>3: 750Hz</td> </tr> <tr> <td>6</td> <td>1: 2250Hz</td> <td>4: 563Hz</td> </tr> <tr> <td>7</td> <td>2: 1125Hz</td> <td>5: 450Hz</td> </tr> <tr> <td></td> <td>6: 375Hz</td> <td>7: 321Hz</td> </tr> <tr> <td>8</td> <td>svx</td> <td colspan="2" rowspan="2">Set the performance mode of the servo control. (Only for MDS-C1-Vx)</td> </tr> <tr> <td>9</td> <td>hvx</td> </tr> <tr> <td></td> <td></td> <td colspan="2">00: By current loop gain</td> </tr> <tr> <td></td> <td></td> <td colspan="2">01: MDS-B-Vx compatible mode selected</td> </tr> <tr> <td></td> <td></td> <td colspan="2">10: High gain mode selected</td> </tr> <tr> <td></td> <td></td> <td colspan="2">11: High gain mode selected</td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td colspan="2">Digital signal output selection</td> </tr> <tr> <td>D</td> <td rowspan="4">dos</td> <td colspan="2">0 : MP scale absolute position detection, offset demand signal output</td> </tr> <tr> <td>E</td> <td colspan="2">1 : Specified speed signal output</td> </tr> <tr> <td>F</td> <td colspan="2">2 to F : Setting prohibited</td> </tr> <tr> <td></td> <td colspan="2"></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	dos						hvx	svx	7	6	5	4	3	2	1	0	fhz2				nfd			zck	bit	Meaning when "0" is set	Meaning when "1" is set	0	zck	Z phase check valid (Alarm 42)	Z phase check invalid	1	nfd1	Set the filter depth for Notch filter 1 (SV038).		2		Value	000 001 010 011 100 101 110 111	3		Depth (dB)	Infntly deep -18.1 -12.0 -8.5 -6.0 -4.1 -2.5 -1.2			Deep ← → Shallow		4		Set the operation frequency of Notch filter 2.		5	fhz2	0: Invalid	3: 750Hz	6	1: 2250Hz	4: 563Hz	7	2: 1125Hz	5: 450Hz		6: 375Hz	7: 321Hz	8	svx	Set the performance mode of the servo control. (Only for MDS-C1-Vx)		9	hvx			00: By current loop gain				01: MDS-B-Vx compatible mode selected				10: High gain mode selected				11: High gain mode selected		A				B				C		Digital signal output selection		D	dos	0 : MP scale absolute position detection, offset demand signal output		E	1 : Specified speed signal output		F	2 to F : Setting prohibited				
F	E	D	C	B	A	9	8																																																																																																																			
dos						hvx	svx																																																																																																																			
7	6	5	4	3	2	1	0																																																																																																																			
fhz2				nfd			zck																																																																																																																			
bit	Meaning when "0" is set	Meaning when "1" is set																																																																																																																								
0	zck	Z phase check valid (Alarm 42)	Z phase check invalid																																																																																																																							
1	nfd1	Set the filter depth for Notch filter 1 (SV038).																																																																																																																								
2		Value	000 001 010 011 100 101 110 111																																																																																																																							
3		Depth (dB)	Infntly deep -18.1 -12.0 -8.5 -6.0 -4.1 -2.5 -1.2																																																																																																																							
		Deep ← → Shallow																																																																																																																								
4		Set the operation frequency of Notch filter 2.																																																																																																																								
5	fhz2	0: Invalid	3: 750Hz																																																																																																																							
6		1: 2250Hz	4: 563Hz																																																																																																																							
7		2: 1125Hz	5: 450Hz																																																																																																																							
		6: 375Hz	7: 321Hz																																																																																																																							
8	svx	Set the performance mode of the servo control. (Only for MDS-C1-Vx)																																																																																																																								
9	hvx																																																																																																																									
		00: By current loop gain																																																																																																																								
		01: MDS-B-Vx compatible mode selected																																																																																																																								
		10: High gain mode selected																																																																																																																								
		11: High gain mode selected																																																																																																																								
A																																																																																																																										
B																																																																																																																										
C		Digital signal output selection																																																																																																																								
D	dos	0 : MP scale absolute position detection, offset demand signal output																																																																																																																								
E		1 : Specified speed signal output																																																																																																																								
F		2 to F : Setting prohibited																																																																																																																								
			(Note) Set to "0" for bits with no particular description.																																																																																																																							

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range																																
2234	SV034 SSF3 Servo function selection 3	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">E</td> <td style="text-align: center;">D</td> <td style="text-align: center;">C</td> <td style="text-align: center;">B</td> <td style="text-align: center;">A</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> </tr> <tr> <td colspan="8" style="text-align: center; border: 1px solid black;">ovsn</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;">os2</td> <td style="border: 1px solid black;">zeg</td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;"></td> <td style="border: 1px solid black;">has2</td> <td style="border: 1px solid black;">has1</td> </tr> </table>	F	E	D	C	B	A	9	8	ovsn								7	6	5	4	3	2	1	0		os2	zeg				has2	has1	
		F	E	D	C	B	A	9	8																										
		ovsn																																	
		7	6	5	4	3	2	1	0																										
			os2	zeg				has2	has1																										
		bit	Meaning when "0" is set	Meaning when "1" is set																															
		0	has1 Setting for normal use (Except for HC)	HAS control 1 valid (HC: High acceleration rate support)																															
		1	has2 Setting for normal use (Except for HC)	HAS control 2 valid (HC: Overshooting support)																															
		2																																	
		3																																	
4																																			
5	zeg Z phase normal edge detection (Setting for normal use)	Z phase reverse edge detection (Valid only when SV027/bit6=1)																																	
6	os2 Setting for normal use	Overspeed detection level changeover																																	
7																																			
8																																			
9																																			
A																																			
B																																			
C	Set the non-sensitive band of the overshooting compensation type 3 in increments of 2μm at a time.																																		
D	In the feed forward control, the non-sensitive band of the model position droop is set, and overshooting of the model is ignored. Set the same value as the standard SV040.																																		
E	ovsn																																		
F																																			
(Note) Set to "0" for bits with no particular description.																																			

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range																																
2235	SV035 SSF4	Servo function selection4	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 12.5%; text-align: center;">F</td> <td style="width: 12.5%; text-align: center;">E</td> <td style="width: 12.5%; text-align: center;">D</td> <td style="width: 12.5%; text-align: center;">C</td> <td style="width: 12.5%; text-align: center;">B</td> <td style="width: 12.5%; text-align: center;">A</td> <td style="width: 12.5%; text-align: center;">9</td> <td style="width: 12.5%; text-align: center;">8</td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">clt</td> <td colspan="3" style="border: 1px solid black; text-align: center;">clG1</td> <td style="border: 1px solid black; text-align: center;">cl2n</td> <td style="border: 1px solid black; text-align: center;">clet</td> <td colspan="2" style="border: 1px solid black; text-align: center;">cltq</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td colspan="2" style="border: 1px solid black; text-align: center;">iup</td> <td colspan="6" style="border: 1px solid black; text-align: center;">tdt</td> </tr> </table>	F	E	D	C	B	A	9	8	clt	clG1			cl2n	clet	cltq		7	6	5	4	3	2	1	0	iup		tdt					
			F	E	D	C	B	A	9	8																									
			clt	clG1			cl2n	clet	cltq																										
			7	6	5	4	3	2	1	0																									
			iup		tdt																														
			bit	Meaning when "0" is set	Meaning when "1" is set																														
			0	Td creation time setting Set to "0". (For machine tool builder adjustment)																															
			1																																
			2																																
			3																																
4																																			
5																																			
6	iup	Set to "1" in the case of any motors from HC152 to HC702 and from HC153 to HC453.																																	
7																																			
8	cltq	Set the retracting torque for collision detection in respect to the maximum torque of the motor. 00: 100% 01: 90% 10: 80% (Standard) 11: 70%																																	
9																																			
A	clet	Setting for normal use	The disturbance torque peak of the latest two seconds is displayed in MPOS of the servo monitor screen.																																
B	cl2n	Collision detection method 2 valid	Collision detection method 2 invalid																																
C	clG1	Collision detection method 1																																	
D		Set the collision detection level during cutting feed (G1). The G1 collision detection level=SV060*clG1.																																	
E		When clG1=0, the collision detection method 1 during cutting feed won't function.																																	
F	clt	Setting for normal use	The guide value of the SV059 setting value is displayed in MPOS of the servo monitor screen.																																

(Note) Set to "0" for bits with no particular description.

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range																																																																																																																																																			
2236 (PR)	SV036 PTYP	Power supply type	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">E</td> <td style="text-align: center;">D</td> <td style="text-align: center;">C</td> <td style="text-align: center;">B</td> <td style="text-align: center;">A</td> <td style="text-align: center;">9</td> <td style="text-align: center;">8</td> </tr> <tr> <td colspan="4" style="text-align: center; border: 1px solid black;">amp</td> <td colspan="4" style="text-align: center; border: 1px solid black;">rtyp</td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">6</td> <td style="text-align: center;">5</td> <td style="text-align: center;">4</td> <td style="text-align: center;">3</td> <td style="text-align: center;">2</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> </tr> <tr> <td colspan="8" style="text-align: center; border: 1px solid black;">ptyp</td> </tr> </table>	F	E	D	C	B	A	9	8	amp				rtyp				7	6	5	4	3	2	1	0	ptyp																																																																																																																										
			F	E	D	C	B	A	9	8																																																																																																																																												
			amp				rtyp																																																																																																																																															
			7	6	5	4	3	2	1	0																																																																																																																																												
			ptyp																																																																																																																																																			
			0	ptyp	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">bit</th> <th colspan="10">Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td colspan="10" rowspan="3">When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.</td> </tr> <tr> <td>1</td> </tr> <tr> <td>2</td> </tr> <tr> <td>3</td> <td style="text-align: center;">Set-ting</td> <td style="text-align: center;">0x</td> <td style="text-align: center;">1x</td> <td style="text-align: center;">2x</td> <td style="text-align: center;">3x</td> <td style="text-align: center;">4x</td> <td style="text-align: center;">5x</td> <td style="text-align: center;">6x</td> <td style="text-align: center;">7x</td> <td style="text-align: center;">8x</td> </tr> <tr> <td>4</td> <td style="text-align: center;">x0</td> <td style="text-align: center;">Not used</td> <td></td> <td></td> <td style="text-align: center;">CV-300</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td style="text-align: center;">x1</td> <td></td> <td style="text-align: center;">CV-110</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-10</td> </tr> <tr> <td>6</td> <td style="text-align: center;">x2</td> <td></td> <td></td> <td style="text-align: center;">CV-220</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-15</td> </tr> <tr> <td>7</td> <td style="text-align: center;">x3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-22</td> </tr> <tr> <td></td> <td style="text-align: center;">x4</td> <td style="text-align: center;">CV-37</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-37</td> </tr> <tr> <td></td> <td style="text-align: center;">x5</td> <td></td> <td style="text-align: center;">CV-150</td> <td></td> <td style="text-align: center;">CV-450</td> <td style="text-align: center;">CV-550</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">x6</td> <td style="text-align: center;">CV-55</td> <td></td> <td style="text-align: center;">CV-260</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-55</td> </tr> <tr> <td></td> <td style="text-align: center;">x7</td> <td></td> <td></td> <td></td> <td style="text-align: center;">CV-370</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">x8</td> <td style="text-align: center;">CV-75</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-75</td> </tr> <tr> <td></td> <td style="text-align: center;">x9</td> <td></td> <td style="text-align: center;">CV-185</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td style="text-align: center;">CR-90</td> </tr> </tbody> </table>	bit	Explanation										0	When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.										1	2	3	Set-ting	0x	1x	2x	3x	4x	5x	6x	7x	8x	4	x0	Not used			CV-300						5	x1		CV-110							CR-10	6	x2			CV-220						CR-15	7	x3									CR-22		x4	CV-37								CR-37		x5		CV-150		CV-450	CV-550						x6	CV-55		CV-260						CR-55		x7				CV-370							x8	CV-75								CR-75		x9		CV-185							CR-90
			bit			Explanation																																																																																																																																																
			0			When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.																																																																																																																																																
			1																																																																																																																																																			
			2																																																																																																																																																			
3	Set-ting	0x	1x			2x	3x	4x	5x	6x	7x	8x																																																																																																																																										
4	x0	Not used					CV-300																																																																																																																																															
5	x1		CV-110									CR-10																																																																																																																																										
6	x2					CV-220						CR-15																																																																																																																																										
7	x3											CR-22																																																																																																																																										
	x4	CV-37								CR-37																																																																																																																																												
	x5		CV-150		CV-450	CV-550																																																																																																																																																
	x6	CV-55		CV-260						CR-55																																																																																																																																												
	x7				CV-370																																																																																																																																																	
	x8	CV-75								CR-75																																																																																																																																												
	x9		CV-185							CR-90																																																																																																																																												
8	rtyp	Set the regenerative resistor type when MDS-A-CR is used.	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">Set-ting</th> <th style="width: 35%;">Regenerative resistor model name</th> <th style="width: 20%;">Resistance value</th> <th style="width: 20%;">Capacity</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td colspan="3">MDS-C1-CV (Setting when using power supply regeneration)</td> </tr> <tr> <td style="text-align: center;">1</td> <td>GZG200W260HMJ</td> <td style="text-align: center;">26Ω</td> <td style="text-align: center;">80W</td> </tr> <tr> <td style="text-align: center;">2</td> <td>GZG300W130HMJ×2</td> <td style="text-align: center;">26Ω</td> <td style="text-align: center;">150W</td> </tr> <tr> <td style="text-align: center;">3</td> <td>MR-RB30</td> <td style="text-align: center;">13Ω</td> <td style="text-align: center;">300W</td> </tr> <tr> <td style="text-align: center;">4</td> <td>MR-RB50</td> <td style="text-align: center;">13Ω</td> <td style="text-align: center;">500W</td> </tr> <tr> <td style="text-align: center;">5</td> <td>GZG200W200HMJ×3</td> <td style="text-align: center;">6.7Ω</td> <td style="text-align: center;">350W</td> </tr> <tr> <td style="text-align: center;">6</td> <td>GZG300W200HMJ×3</td> <td style="text-align: center;">6.7Ω</td> <td style="text-align: center;">500W</td> </tr> <tr> <td style="text-align: center;">7</td> <td>R-UNIT-1</td> <td style="text-align: center;">30Ω</td> <td style="text-align: center;">700W</td> </tr> <tr> <td style="text-align: center;">8</td> <td>R-UNIT-2</td> <td style="text-align: center;">15Ω</td> <td style="text-align: center;">700W</td> </tr> <tr> <td style="text-align: center;">9</td> <td>R-UNIT-3</td> <td style="text-align: center;">15Ω</td> <td style="text-align: center;">2100W</td> </tr> <tr> <td style="text-align: center;">A to F</td> <td colspan="3">No setting</td> </tr> </tbody> </table>	Set-ting	Regenerative resistor model name	Resistance value	Capacity	0	MDS-C1-CV (Setting when using power supply regeneration)			1	GZG200W260HMJ	26Ω	80W	2	GZG300W130HMJ×2	26Ω	150W	3	MR-RB30	13Ω	300W	4	MR-RB50	13Ω	500W	5	GZG200W200HMJ×3	6.7Ω	350W	6	GZG300W200HMJ×3	6.7Ω	500W	7	R-UNIT-1	30Ω	700W	8	R-UNIT-2	15Ω	700W	9	R-UNIT-3	15Ω	2100W	A to F	No setting																																																																																																					
Set-ting				Regenerative resistor model name	Resistance value	Capacity																																																																																																																																																
0				MDS-C1-CV (Setting when using power supply regeneration)																																																																																																																																																		
1				GZG200W260HMJ	26Ω	80W																																																																																																																																																
2				GZG300W130HMJ×2	26Ω	150W																																																																																																																																																
3				MR-RB30	13Ω	300W																																																																																																																																																
4	MR-RB50	13Ω	500W																																																																																																																																																			
5	GZG200W200HMJ×3	6.7Ω	350W																																																																																																																																																			
6	GZG300W200HMJ×3	6.7Ω	500W																																																																																																																																																			
7	R-UNIT-1	30Ω	700W																																																																																																																																																			
8	R-UNIT-2	15Ω	700W																																																																																																																																																			
9	R-UNIT-3	15Ω	2100W																																																																																																																																																			
A to F	No setting																																																																																																																																																					
A																																																																																																																																																						
B																																																																																																																																																						
C																																																																																																																																																						
D																																																																																																																																																						
E																																																																																																																																																						
F																																																																																																																																																						

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items		Details	Setting range
2237	SV037 JL	Load inertia scale	Set "the motor inertia + motor axis conversion load inertia" in respect to the motor inertia. $SV037 (JL) = \frac{Jl+Jm}{Jm} * 100$ Jm: Motor inertia Jl: Motor axis conversion load inertia	0 to 5000 (%)
2238	SV038 FHZ1	Notch filter frequency 1	Set the vibration frequency to suppress if machine vibration occurs. (Valid at 72 or more) When not using, set to "0".	0 to 3000 (Hz)
2239	SV039 LMCD	Lost motion compensation timing	Set this when the lost motion compensation timing does not match. Adjust by increasing the value by 10 at a time.	0 to 2000 (ms)
2240	The higher order 8bits and lower order 8bits are used for different functions. "Setting value of SV040" = (lcy*256) + LMCT			0 to 32767
	SV040 LMCT (Low order)	Lost motion compensation non-sensitive band	Set the non-sensitive band of the lost motion compensation in the feed forward control. When "0" is set, the actual value that is set is 2μm. Adjust by increasing by 1μm at a time.	0 to 100 (μm)
	SV040 lcy (High order)	Current bias 2	Normally, set to "40" if you use HC202 to HC902, HC203 to HC703. Use this in combination with SV030 and the high order 8bits of SV045.	0 to 127
2241	SV041 LMC2	Lost motion compensation 2	Set this with SV016 (LMC1) only when you wish to set the lost motion compensation amount to be different depending on the command directions. Set to "0" as a standard.	-1 to 200 (Stall [rated] current %)
2242	SV042 OVS2	Overshooting compensation 2	Set this with SV031 (OVS1) only when you wish to set the overshooting compensation amount to be different depending on the command directions. Set to "0" as a standard.	-1 to 100 (Stall [rated] current %)
2243	SV043 OBS1	Disturbance observer filter frequency	Set the disturbance observer filter band. Set to "100" as a standard. To use the disturbance observer, also set SV037 (JL) and SV044 (OBS2). When not using, set to "0".	0 to 1000 (rad/s)
2244	SV044 OBS2	Disturbance observer gain	Set the disturbance observer gain. The standard setting is "100" to "300". To use the disturbance observer, also set SV037 (JL) and SV043 (OBS1). When not using, set to "0".	0 to 500 (%)
2245	The higher order 8bits and lower order 8bits are used for different functions. "Setting value of SV045" = (lcy*256) + LMCT			0 to 32767
	SV045 TRUB (Low order)	Frictional torque	When you use the collision detection function, set the frictional torque.	0 to 100 (Stall [rated] current %)
	SV045 lb1 (High order)	Current bias 3	Set to "0" as a standard. Use this in combination with SV030 and the high order 8bits of SV040.	0 to 127

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range	
2246	SV046		Not used. Set to "0".	0
2247	SV047 EC	Inductive voltage compensation gain	Set the inductive voltage compensation gain. Set to "100" as a standard. If the current FB peak exceeds the current command peak, lower the gain.	0 to 200 (%)
2248	SV048 EMGrt	Vertical axis drop prevention time	Input a length of time to prevent the vertical axis from dropping by delaying Ready OFF until the brake works when the emergency stop occurs. Increase the setting by 100ms at a time and set the value where the axis does not drop.	0 to 20000 (ms)
2249	SV049 PGN1sp	Position loop gain 1 in spindle synchronous control	Set the position loop gain during the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). Set the same value as the value of the spindle parameter, position loop gain in synchronous control. When performing the SHG control, set this with SV050 (PGN2sp) and SV058 (SHGCsp).	1 to 200 (rad/s)
2250	PGN2sp	Position loop gain 2 in spindle synchronous control	Set this with SV049 (PGN1sp) and SV058 (SHGCsp) if you wish to perform the SHG control in the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2251	SV051 DFBT	Dual feed back control time constant	Set the control time constant in dual feed back. When "0" is set, the actual value that is set is 1ms. The higher the time constant is, the closer it gets to the semi-closed control, so the limit of the position loop gain is raised.	0 to 9999 (ms)
2252	SV052 DFBN	Dual feedback control non-sensitive band	Set the non-sensitive band in the dual feedback control. Set to "0" as a standard.	0 to 9999 (μm)
2253	SV053 OD3	Excessive error detection width in special control	Set the excessive error detection width when servo ON in a special control (initial absolute position setting, stopper control, etc.). If "0" is set, excessive error detection won't be performed when servo ON during a special control.	0 to 32767 (mm)
2254	SV054 ORE	Overrun detection width in closed loop control	Set the overrun detection width in the full-closed loop control. If the gap between the motor end detector and the linear scale (machine end detector) exceeds the value set by this parameter, it is judged to be overrun and Alarm 43 will be detected. When "-1" is set, the alarm detection won't be performed. When "0" is set, overrun is detected with a 2mm width.	-1 to 32767 (mm)
2255	SV055 EMGx	Max. gate off delay time after emergency stop	Set a length of time from the point when the emergency stop is input to the point when READY OFF is compulsorily executed. Normally, set the same value as the absolute value of SV056. In preventing the vertical axis from dropping, the gate off is delayed for the length of time set by SV048 if SV055's value is smaller than that of SV048.	0 to 20000 (ms)

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

No.	Items	Details	Setting range	
2256	SV056 EMGt	Deceleration time constant at emergency stop	In the vertical axis drop prevention control, set the time constant used for the deceleration control at emergency stop. Set a length of time that takes from rapid traverse rate (rapid) to stopping. Normally, set the same value as the rapid traverse acceleration/deceleration time constant. When executing the synchronous operation, put the minus sign to the settings of both of the master axis and slave axis.	-20000 to 20000 (ms)
2257	SV057 SHGC	SHG control gain	When performing the SHG control, set this with S003 (PGN1) and SV004 (PGN2). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2258	SV058 SHGCsp	SHG control gain in spindle synchronous control	Set this with SV049 (PGN1sp) and SV050 (PGN2sp) if you wish to perform the SHG control in the spindle synchronous control (synchronous tapping, synchronous control with spindle/C axis). When not performing the SHG control, set to "0".	0 to 999 (rad/s)
2259	SV059 TCNV	Collision detection torque estimating gain	Set the torque estimating gain when using the collision detection function. After setting as SV035/bitF(ctl)=1 and performing acceleration/deceleration, set the value displayed in MPOS of the NC servo monitor screen. Set to "0" when not using the collision detection function.	-32768 to 32767
2260	SV060 TLMT	Collision detection level	When using the collision detection function, set the collision detection level during the G0 feeding. If "0" is set, none of the collision detection function will work.	0 to 999 (Stall [rated] current %)
2261	SV061 DA1NO	D/A output channel 1 data No.	Input the data number you wish to output to D/A output channel. In the case of MDS-C1-V2, set the axis on the side to which the data will not be output to "-1".	-1 to 127
2262	SV062 DA2NO	D/A output channel 2 data No.		
2263	SV063 DA1MPY	D/A output channel 1 output scale	Set the scale with a 1/256 unit. When "0" is set, output is done with the standard output unit.	-32768 to 32767 (Unit: 1/256)
2264	SV064 DA2MPY	D/A output channel 2 output scale		
2265	SV065		Not used. Set to "0".	0

(2) Initial setting value

(a) HC**/HC**R series

Motor		HC 52	HC 102	HC 152	HC 202	HC 352	HC 452	HC 702	HC 902
Drive unit capacity		05	10	20	20	35	45	70	90
SV001	PC1	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0
SV005	VGN1	100	100	100	100	100	100	150	150
SV006	VGN2	0	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048	2048	2048
SV011	IQG	512	512	512	256	256	256	200	200
SV012	IDG	512	512	512	512	512	512	256	256
SV013	ILMT	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50	50
SV025	MTYP	xxB0	xxB1	xxB2	xxB3	xxB4	xxB5	xxB6	xxB7
SV026	OD2	6	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

Motor		HC 52	HC 102	HC 152	HC 202	HC 352	HC 452	HC 702	HC 902
Drive unit capacity		05	10	20	20	35	45	70	90
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0003	0003	0003	0003	0003	0003	0003	0003
SV035	SSF4	0000	0000	0040	0040	0040	0040	0040	0040
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	10240	10240	10240	10240	10240
SV041	LMC2	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

Motor		HC 53	HC 103	HC 153	HC 203	HC 353	HC 453	HC 703	HC 103R	HC 153R	HC 203R	HC 353R
Drive unit capacity		05	10	20	35	45	70	90	10	10	20	35
SV001	PC1	-	-	-	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0	0	0	0
SV005	VGN1	100	100	100	100	100	100	100	15	15	20	40
SV006	VGN2	0	0	0	0	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048	2048	4096	4096	4096	4096
SV010	IDA	2048	2048	2048	2048	2048	2048	2048	4096	4096	4096	4096
SV011	IQG	256	256	256	256	256	256	256	256	256	256	256
SV012	IDG	512	512	512	512	512	512	512	512	512	512	512
SV013	ILMT	500	500	500	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50	50	50	50	50
SV025	MTYP	xxC0	xxC1	xxC2	xxC3	xxC4	xxC5	xxC6	xxE1	xxE2	xxE3	xxE4
SV026	OD2	6	6	6	6	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

Motor		HC 53	HC 103	HC 153	HC 203	HC 353	HC 453	HC 703	HC 103R	HC 153R	HC 203R	HC 353R
Drive unit capacity		05	10	20	35	45	70	90	10	10	20	35
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0003	0003	0003	0003	0003	0003	0003	0000	0000	0000	0000
SV035	SSF4	0000	0000	0040	0040	0040	0040	0040	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	1024	1024	1024	1024	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100	100	100	100
SV048	EMGr	0	0	0	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

(b) HA**N series

Motor		HA 40N	HA 80N	HA 100N	HA 200N	HA 300N	HA 700N	HA 900N
Drive unit capacity		05	10	20	35	45	70	90
SV001	PC1	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	25	25
SV004	PGN2	0	0	0	0	0	0	0
SV005	VGN1	150	150	150	150	150	250	250
SV006	VGN2	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048	2048
SV011	IQG	512	512	256	256	256	200	200
SV012	IDG	512	512	512	512	512	256	256
SV013	ILMT	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50
SV025	MTYP	xx00	xx01	xx02	xx03	xx04	xx05	xx06
SV026	OD2	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

Motor		HA 40N	HA 80N	HA 100N	HA 200N	HA 300N	HA 700N	HA 900N
Drive unit capacity		05	10	20	35	45	70	90
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0000	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

Motor		HA 43N	HA 83N	HA 93N	HA 103N	HA 203N	HA 303N	HA 703N
Drive unit capacity		05	10	20	35	45	70	90
SV001	PC1	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	25
SV004	PGN2	0	0	0	0	0	0	0
SV005	VGN1	150	150	150	150	150	150	250
SV006	VGN2	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048	2048
SV011	IQG	256	256	256	256	256	256	200
SV012	IDG	512	512	512	512	512	512	256
SV013	ILMT	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50
SV025	MTYP	xx80	xx81	xx8A	xx82	xx83	xx84	xx85
SV026	OD2	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

Motor		HA 43N	HA 83N	HA 93N	HA 103N	HA 203N	HA 303N	HA 703N
Drive unit capacity		05	10	20	35	45	70	90
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0000	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

Motor		HA 053	HA 13	HA 053N	HA 13N	HA 23N	HA 33N
Drive unit capacity		01	01	01	01	03	03
SV001	PC1	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0
SV005	VGN1	70	70	70	70	100	100
SV006	VGN2	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048
SV011	IQG	256	256	256	256	224	224
SV012	IDG	256	256	256	256	224	224
SV013	ILMT	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-
SV019	RNG1	10	10	-	-	-	-
SV020	RNG2	10	10	-	-	-	-
SV021	OLT	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50
SV025	MTYP	338C	338D	xx8C	xx8D	xx8E	xx8F
SV026	OD2	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0

(Note) The HA053 and HA13 are dedicated for the MDS-B-Vx.

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

Motor		HA 053	HA 13	HA 053N	HA 13N	HA 23N	HA 33N
Drive unit capacity		01	01	01	01	03	03
SV033	SSF2	0000	0000	0000	0000	0000	0000
SV034	SSF3	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0
SV046		0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0
SV065		0	0	0	0	0	0

(Note) The HA053 and HA13 are dedicated for the MDS-B-Vx.

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

(c) HA**L series

Motor		HA 50L	HA 100L	HA 150L	HA 200L	HA 300L	HA 500L	HA- A11KL	HA- A15KL
Drive unit capacity		05	10	10	20	35	45	110	150
SV001	PC1	-	-	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0	0	0
SV005	VGN1	30	30	30	30	30	50	150	150
SV006	VGN2	0	0	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048	2048	2048
SV011	IQG	512	512	512	512	256	256	512	512
SV012	IDG	512	512	512	512	512	512	512	512
SV013	ILMT	500	500	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60	60	3
SV022	OLL	150	150	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50	50	50
SV025	MTYP	xx20	xx21	xx2A	xx22	xx23	xx24	xx27	xx28
SV026	OD2	6	6	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

Motor		HA 50L	HA 100L	HA 150L	HA 200L	HA 300L	HA 500L	HA- A11KL	HA- A15KL
Drive unit capacity		05	10	10	20	35	45	110	150
SV033	SSF2	0000	0000	0000	0000	0000	0000	0000	0000
SV034	SSF3	0000	0000	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0	0	0
SV046		0	0	0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0	0	0
SV065		0	0	0	0	0	0	0	0

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

Motor		HA 53L	HA 103L	HA 153L	HA 203L	HA 303L	HA 503L
Drive unit capacity		10	20	20	35	45	70
SV001	PC1	-	-	-	-	-	-
SV002	PC2	-	-	-	-	-	-
SV003	PGN1	33	33	33	33	33	33
SV004	PGN2	0	0	0	0	0	0
SV005	VGN1	30	30	30	30	30	50
SV006	VGN2	0	0	0	0	0	0
SV007	VIL	0	0	0	0	0	0
SV008	VIA	1364	1364	1364	1364	1364	1364
SV009	IQA	2048	2048	2048	2048	2048	2048
SV010	IDA	2048	2048	2048	2048	2048	2048
SV011	IQG	512	512	512	512	256	256
SV012	IDG	512	512	512	512	512	512
SV013	ILMT	500	500	500	500	500	500
SV014	ILMTsp	500	500	500	500	500	500
SV015	FFC	0	0	0	0	0	0
SV016	LMC1	0	0	0	0	0	0
SV017	SPEC	0000	0000	0000	0000	0000	0000
SV018	PIT	-	-	-	-	-	-
SV019	RNG1	-	-	-	-	-	-
SV020	RNG2	-	-	-	-	-	-
SV021	OLT	60	60	60	60	60	60
SV022	OLL	150	150	150	150	150	150
SV023	OD1	6	6	6	6	6	6
SV024	INP	50	50	50	50	50	50
SV025	MTYP	xx30	xx31	xx3A	xx32	xx33	xx34
SV026	OD2	6	6	6	6	6	6
SV027	SSF1	4000	4000	4000	4000	4000	4000
SV028		0	0	0	0	0	0
SV029	VCS	0	0	0	0	0	0
SV030	IVC	0	0	0	0	0	0
SV031	OVS1	0	0	0	0	0	0
SV032	TOF	0	0	0	0	0	0
SV033	SSF2	0000	0000	0000	0000	0000	0000

7. SERVO PARAMETERS
7.3 MDS-C1-Vx STANDARD SPECIFICATION (MDS-B-Vx COMPATIBLE)

Motor		HA 53L	HA 103L	HA 153L	HA 203L	HA 303L	HA 503L
Drive unit capacity		10	20	20	35	45	70
SV034	SSF3	0000	0000	0000	0000	0000	0000
SV035	SSF4	0000	0000	0000	0000	0000	0000
SV036	PTYP	0000	0000	0000	0000	0000	0000
SV037	JL	0	0	0	0	0	0
SV038	FHz1	0	0	0	0	0	0
SV039	LMCD	0	0	0	0	0	0
SV040	LMCT	0	0	0	0	0	0
SV041	LMC2	0	0	0	0	0	0
SV042	OVS2	0	0	0	0	0	0
SV043	OBS1	0	0	0	0	0	0
SV044	OBS2	0	0	0	0	0	0
SV045	TRUB	0	0	0	0	0	0
SV046		0	0	0	0	0	0
SV047	EC	100	100	100	100	100	100
SV048	EMGrt	0	0	0	0	0	0
SV049	PGN1sp	15	15	15	15	15	15
SV050	PGN2sp	0	0	0	0	0	0
SV051	DFBT	0	0	0	0	0	0
SV052	DFBN	0	0	0	0	0	0
SV053	OD3	0	0	0	0	0	0
SV054	ORE	0	0	0	0	0	0
SV055	EMGx	0	0	0	0	0	0
SV056	EMGt	0	0	0	0	0	0
SV057	SHGC	0	0	0	0	0	0
SV058	SHGCsp	0	0	0	0	0	0
SV059	TCNV	0	0	0	0	0	0
SV060	TLMT	0	0	0	0	0	0
SV061	DA1NO	0	0	0	0	0	0
SV062	DA2NO	0	0	0	0	0	0
SV063	DA1MPY	0	0	0	0	0	0
SV064	DA2MPY	0	0	0	0	0	0
SV065		0	0	0	0	0	0


7.4 SUPPLEMENT

7.4.1 D/A OUTPUT SPECIFICATIONS

(1) MDS-B-SVJ2

(a) D/A output specifications

Item	Explanation
No. of channels	2ch
Output cycle	888 μ s (min. value)
Output precision	8bit
Output voltage range	-10V to 0 to +10V
Output scale setting	$\pm 1/256$ to ± 128 times
Output pins	CN3 connector MO1 = pin 4 MO2 = pin 14 GND = pin 1,11
Function	Offset amount adjustment function Output clamp function Low path filter function
Option	Relay terminal: MR-J2CN3TM Connect from the CN3 connector using the SH21 cable as a lead-in wire.



7. SERVO PARAMETERS
7.4 SUPPLEMENT

(b) Setting the output data

Set the No. of the data to be outputted to each D/A output channel.

#	No.	Abbrev	Parameter name
2261	SV061	DA1NO	D/A output channel 1 data No.
2262	SV062	DA2NO	D/A output channel 2 data No.

No.	Output data	Standard output unit	Output cycle
0	0V test output	For offset amount adjustment	
1	Speed feedback	1000rpm / 2V	888μs
2	Current feedback	Stall (rated) 100% / 2V	888μs
3	Speed command	1000rpm / 2V	888μs
4	Current command	Stall (rated) 100% / 2V	888μs
5	V-phase current value	10A / V	888μs
6	W-phase current-value	10A / V	888μs
7	Estimated disturbance torque	Stall (rated) 100% / 2V	888μs
8	Collision detection disturbance torque	Stall (rated) 100% / 2V	888μs
9	Position feedback (stroke)	100mm / V	3.55ms
10	Position feedback (pulse)	10μm / V	3.55ms
11	Position droop	mm / V	3.55ms
12	Position droop (x10)	100μm / V	3.55ms
13	Position droop (x100)	10μm / V	3.55ms
14	Feedrate (FΔT)	10000(mm/min) / V	888μs
15	Feedrate (FΔT x 10)	1000(mm/min) / V	888μs
16	Model position droop	mm / V	3.55ms
17	Model position droop (x10)	100μm / V	3.55ms
18	Model position droop (x100)	10μm / V	3.55ms
19	q-axis current cumulative value	-	888μs
20	d-axis current cumulative value	-	888μs
21	Motor load level	100% / 5V	113.7ms
22	Amplifier load level	100% / 5V	113.7ms
23	Regenerative load level	100% / 5V	910.2ms
24	PN bus wire voltage	50V / V (1/50)	888μs
25	Speed cumulative item	-	888μs
26	Cycle counter	0-5V (Regardless of resolution)	888μs
27	Excessive error detection amount	mm / V	3.55ms
28	Collision detection estimated torque	Stall (rated) 100% / 2V	888μs
29	Position command (stroke)	100mm / V	3.55ms
30	Position command (pulse)	10μm / V	3.55ms
31 to 99	-		
100	5V test output	-	-
101	Saw-tooth wave test output	-5 to 5V Cycle: 113.7ms	888μs
102	Rectangular wave test output	0 to 5V Cycle: 227.5ms	888μs
103 to	Setting prohibited		

(c) Setting the output scale

When "0" is set, the output will be made with the standard output unit. To change the output unit, set a value other than "0".

The scale is set with a 1/256 unit. When 256 is set, the unit will be the same as the standard output.

#	No.	Abbrev	Parameter name
2263	SV063	DA1MPY	D/A output channel 1 output scale
2264	SV064	DA2MPY	D/A output channel 2 output scale

(Example 1) When SV061 = 5, SV063 = 2560

The V-phase current value will be output with 1 A/V unit to D/A output ch.1.


(Example 2) When SV063 = 11, SV064 = 128

The position droop will be output with a 2mm/Vunit to D/A output ch.2.

(2) MDS-C1-Vx, MDS-B-Vx, MDS-B-Vx4

(a) D/A Output specifications

Item	Explanation
No. of channels	2ch
Output cycle	888 μ s (min. value)
Output precision	8bit
Output voltage	0V to 2.5V to +5V
Output scale setting	$\pm 1/256$ to ± 128 times
Output pins	CN9 connector MO1 = pin 9 MO2 = pin 19 GND = pin 1,11
Function	Phase current feed back output function L-axis U-phase current FB : pin 7 L-axis V-phase current FB : pin 17 M-axis U-phase current FB : pin 6 M-axis V-phase current FB : pin 16
Option	An drive unit with 2 axes also has 2 channels for D/A output. Therefore, set the output data of the axis (SV061,62), which is not observed, to "-1".



7. SERVO PARAMETERS
7.4 SUPPLEMENT

(b) Setting the output data

Set the No. of the data to be outputted to each data D/A output channel.

#	No.	Abbrev	Parameter name
2261	SV061	DA1NO	D/A output channel 1 data No.
2262	SV062	DA2NO	D/A output channel 2 data No.

No.	Output data	Standard output unit	Standard setting value of output scale (Setting values in SV063, SV064)	Standard output unit	Output cycle
-1	D/A output non-selected	For a drive unit. with 2 axes (MDS-C1-V2). Set for the parameter of the axis which is not used.			
0	ch1: Speed feedback	r/min	13 (in case of 2000rpm)	1000rpm / V	3.55ms
			9 (in case of 3000rpm)	1500rpm / V	3.55ms
	ch2: Current command	Stall%	131	Stall 100% / V	3.55ms
1	Current command	Stall%	131	Stall 100% / V	3.55ms
2	-				
3	Current feedback	Stall%	131	Stall 100% / V	3.55ms
4	-				
5	-				
6	Position droop	NC display unit / 2	328 (When the display unit=1μm)	10μm / 0.5V	3.55ms
7	-				
8	Feedrate (FΔT)	(NC display unit / 2) / communication cycle	55 (When 1μm, 3.5ms)	1000 (mm/min) / 0.5V	3.55ms
9	-				
10	Position command	NC display unit / 2	328 (When the display unit=1μm)	10μm / 0.5V	3.55ms
11	-				
12	Position feedback	NC display unit / 2	328 (When the display unit=1μm)	10μm / 0.5V	3.55ms
13	-				
14	Collision detection estimated torque	Stall%	131	Stall 100% / V	3.55ms
15	Collision detection disturbance torque	Stall%	131	Stall 100% / V	3.55ms
64	Current command (High-speed)	Internal unit	8 (adjustment required)	-	888μs
65	Current feedback (High-speed)	Internal unit	8 (adjustment required)	-	888μs

(To be continued to the next page)

7. SERVO PARAMETERS
7.4 SUPPLEMENT

(Continued from the previous page)

No.	Output data	Standard output unit	Standard setting value of output scale (Setting values in SV063, SV064)	Standard output unit	Output cycle
77	Estimated disturbance torque	Internal unit	8 (adjustment required)	-	888μs
125	Saw-tooth wave test output	0V to 5V	0 (256)	Cycle: 227.5ms	888μs
126	Rectangular wave test output	0V to 5V	0 (256)	Cycle: 1.7ms	888μs
127	2.5V (data 0) test output	2.5V	0 (256)	-	888μs

(c) Setting the output scale

#	No.	Abbrev	Parameter name
2263	SV063	DA1MPY	D/A output channel 1 output scale
2264	SV064	DA2MPY	D/A output channel 2 output scale

Usually, the standard setting value is set for the output scale (SV063, SV 064). When "0" is set, the output will be made as well as when "256" is set.

$$\text{DATA} \times \frac{\text{SV063}}{256} \times \frac{5 [\text{V}]}{256 \text{ (8bit)}} + 2.5 [\text{V}] \text{ (offset)} = \text{Output voltage [V]}$$

(Example) When outputting the current FB with 100%/V-stall (SV061=3, SV063=131)

$$100 \times \frac{131}{256} \times \frac{5}{256} + 2.5 = 3.499 [\text{V}]$$

7.4.2 ELECTRONIC GEARS

By setting the ball screw lead, deceleration ratio (or acceleration ratio), and detector resolution correctly with parameters, the command movement amount and machine end movement amount can be matched.

The following parameters are related to these electronic gears, and directly affect the machine operation.

Take care to set these correctly.

Parameters related to electronic gears

SV001 (PC1), SV002 (PC2), SV003 (PGN1)(SV049(PGN1sp)), SV018 (PIT), SV019 (RNG1), SV020 (RNG2)

PC1 and PC2 setting range

As a principle, the setting range of SV001 (PC1) and SV002 (PC2) is 1 to 30. However, if the following conditions are satisfied, a value higher than 30 can be set. Note that the following conditions must be satisfied even when setting a value between 1 and 30.

For semi-closed loop:

$$\frac{\text{RNG1} \times \text{PC2}}{\text{PIT} \times \text{PC1} \times \text{IUNIT}} \quad \text{PC1}'' < 32767 / \text{PIT}'' / \text{IUNIT}''$$

$$\text{PC2}''' < 32767 / \text{RNG1}'''$$

For closed loop:

$$\frac{\text{PGN1} \times \text{RNG2} \times \text{PC2}}{30 \times \text{RNG1} \times \text{PC1}} \quad \text{PC1}''' < 32767 / \text{RNG1}''' / \text{C30}''$$

$$\text{PC2}''' < 32767 / \text{RNG2}''' / \text{PGN1}'$$

Meaning of symbols	
PC1'''	Value obtained by dividing PC1.
PC2''	Value obtained by dividing PC2.
PIT(')	Value obtained by dividing PIT once (twice).
RNG1'(')	Value obtained by dividing RNG1 once (twice).
RNG2'(')	Value obtained by dividing RNG2 once (twice).
PGN1'	Value obtained by dividing PGN1 once (twice).
IUNIT'(')	Value obtained by dividing CNC interpolation unit once (twice).
C30'(')	Value obtained by dividing a number "30" once (twice).

7. SERVO PARAMETERS
7.4 SUPPLEMENT

Example of calculating PC1 and PC2 setting range

To use a ball screw lead of 10mm, interpolation unit of 0.5 μ m and OSE104 or OSA104 motor end detector with semi-closed loop.

The following parameters are determined by the above conditions.

$$SV018 (PIT) = 10, SV019 (RNG1) = 100, SV020 (RNG2) = 100, IUNIT = 2$$

Divide the denominator and numerator.

$$PIT' = 1, RNG1' = 10 \text{ (Greatest common divisor} = 10)$$

$$IUNIT' = 1, RNG1'' = 5 \text{ (Greatest common divisor} = 2)$$

Obtain the maximum value of PC1 and PC2 with the calculation expression for the semi-closed loop.

$$PC1' < 32767 / 1 / 1 < 32767$$

$$PC2' < 32767 / 5 < 6553$$

With the above calculations, the setting range for PC1 is 1 to 32767 and for PC2 is 1 to 6553.

To use a rotation table, interpolation unit of 0.5 μ m and OSE104 or OSA104 motor end detector with semi-closed loop.

The following parameters are determined by the above conditions.

$$SV018 (PIT) = 360, SV019 (RNG1) = 100, SV020 (RNG2) = 100, IUNIT = 2$$

Divide the denominator and numerator.

$$PIT' = 18, RNG1' = 5 \text{ (Greatest common divisor} = 20)$$

Obtain the maximum value of PC1 and PC2 with the calculation expression for the closed loop.

$$PC1' < 32767 / 18 / 2 < 910$$

$$PC2' < 32767 / 5 < 6553$$

With the above calculations, the setting range for PC1 is 1 to 910 and for PC2 is 1 to 6553.

To use a ball screw lead of 10mm, interpolation unit of 0.5 μ m, position loop gain of 33, OSE104 or OSA104 motor end detector with closed loop, and 1 μ m scale machine end detector.

The following parameters are determined by the above conditions.

$$SV018 (PIT) = 10, SV019 (RNG1) = 10, SV020 (RNG2) = 100, IUNIT = 2, PGN1 = 33$$

Divide the denominator and numerator.

$$RNG1' = 1, RNG2' = 10 \text{ (Greatest common divisor} = 10)$$

$$C30' = 3, RNG2'' = 1 \text{ (Greatest common divisor} = 10)$$

$$C30'' = 1, PGN1' = 11 \text{ (Greatest common divisor} = 3)$$

Obtain the maximum value of PC1 and PC2 with the calculation expression for the closed loop.

$$PC1' < 32767 / 1 / 1 < 32767$$

$$PC2' < 32767 / 1 / 11 < 2978$$

With the above calculations, the setting range for PC1 is 1 to 32767 and for PC2 is 1 to 2978.

To use a ball screw lead of 10mm, interpolation unit of 0.5 μ m, position loop gain of 33, OSE105 or OSA105 motor end detector with closed loop, and 1 μ m scale machine end detector.

The following parameters are determined by the above conditions.

$$SV018 (PIT) = 12, SV019 (RNG1) = 12, SV020 (RNG2) = 1000, IUNIT = 2, PGN1 = 33$$

Divide the denominator and numerator.

$$RNG1' = 3, RNG2' = 250 \text{ (Greatest common divisor} = 4)$$

$$C30' = 3, RNG2'' = 25 \text{ (Greatest common divisor} = 10)$$

$$C30'' = 1, PGN1' = 11 \text{ (Greatest common divisor} = 3)$$

Obtain the maximum value of PC1 and PC2 with the calculation expression for the closed loop.

$$PC1' < 32767 / 3 / 1 < 10922$$

$$PC2' < 32767 / 25 / 11 < 119$$

With the above calculations, the setting range for PC1 is 1 to 10922 and for PC2 is 1 to 119.

7.4.3 LOST MOTION COMPENSATION


When the motor is to rotate in the clockwise direction (looking from the load side) at the command for the + direction, the command direction is CW. Conversely, when the motor is to rotate in the counterclockwise direction, the command direction is CCW.

This rotation direction can be set with the CNC machine parameters. Note that the meaning of the ± will differ for some servo parameters according to this motor rotation direction. The servo parameters affected by CW/CCW are shown below.

SV016 (LMC1), SV041 (LMC2) (When different values are set for SV016 and SV041)
SV031 (OVS1), SV042 (OVS2) (When different values are set for SV031 and SV042)

<Example> If the lost motion compensation amount is to be changed according to the direction, the compensation amount at the quadrant changeover point of each arc where the lost motion compensation is applied will be as shown below according to the command polarity.

	CW	CCW
A	X: SV041	X: SV016
B	Y: SV016	Y: SV041
C	X: SV016	X: SV041
D	Y: SV041	Y: SV016



(Note) The setting value for the parameter is "0" or "-1", the compensation amount is determined as shown below.

Setting value for SV016 (Setting value for SV031)	Setting value for SV041 (Setting value for SV041)	Compensation amount in + direction	Compensation amount in - direction
0	0	No compensation	No compensation
n	0	n	n
0	m	m	m
n	m	n	m
n	-1	n	No compensation
-1	m	No compensation	m

8. MDS-B-SP/SPH,SPJ2 SPINDLE PARAMETERS

The spindle parameter setting and display method will differ according to the CNC being used, so refer to Instruction Manual for each CNC and the following spindles.


MELDAS AC Servo and Spindle MDS-A Series MDS-B Series Specifications Manual
..... BNP-B3759

8.1 MDS-B-SP/SPH,SPJ2 SPINDLE BASE SPECIFICATIONS PARAMETERS


For parameters indicated with a (PR) in the table, turn the NC power OFF after setting. The setting is validated after the power is turned ON again.

No.	Items		Details	Setting range (Unit)		
3001 3002 3003 3004	slimit 1 2 3 4	Limit rotation speed	Set spindle rotation speed for maximum motor rotation speed with gears 00, 01, 10, 11. (Set the spindle speed for the S analog output 10V.)	0 to 99999 (r/min)		
3005 3006 3007 3008	smax 1 2 3 4				Maximum rotation speed Set to slimit ≥ smax. By comparing the S command value and the value of gear 1 to 4, a spindle gear shift command will be output automatically.	
3009 3010 3011 3012	ssift 1 2 3 4					Shift rotation speed Set spindle speed for gear shifting with gears 00, 01, 10, 11. (Note) Setting too large value may cause a gear nicks when changing gears.
3013 3014 3015 3016	stap 1 2 3 4					
3017 3018 3019 3020	stapt 1 2 3 4	Tap time constant Set time constants for constant inclination synchronous tap cycles for gears 00, 01, 10, 11 (linear acceleration/ deceleration pattern).				

Relationship between spindle limit rotation speed and maximum spindle rotation speed



Relation between the spindle limit rotation speed and the spindle tap time constant (for the constant inclination synchronous tap cycle)



8. MDS-B-SP/SPH,SPJ2 SPINDLE PARAMETERS
8.1 MDS-B-SP/SPH,SPJ2 SPINDLE BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (Unit)	
3021	sori	Orientation rotation speed	Set the spindle orientation rotation speed. Set the rotation speed for when the spindle rotates at the constant rotation speed.	0 to 32767 (r/min)
3022	sgear	Encoder gear ratio	Set the gear ratio of the spindle to the encoder.	0: 1/1 1: 1/2 2: 1/4 3: 1/8
3023	smini	Minimum rotation speed	Set the minimum rotation speed of the spindle. If an S command instructs the rotation speed below this setting, the spindle rotates at the minimum rotation speed set by this parameter.	0 to 32767 (r/min)
3024 (PR)	sout	Spindle connection	Set the type of the spindle to be connected. 0: No connection with the spindle 1: Serial connection (bus) 2 to 5: Analog output	0 to 5
3025	enc-on	Spindle encoder	Set connection information of the spindle encoder. 0: No connection 1: Spindle connection (Spindle encoder connection check function valid.) 2: Serial connection of encoder	0 to 2
3026	cs_ori	Selection of winding in orientation mode	0: Perform orientation using the winding selected when the orientation command is issued. 1: Use winding L whenever the orientation command is issued.	0/1
3027	cs_syn	Selection of winding in spindle synchronous mode	0: The winding H/L is selected by the actual spindle motor rotation speed (calculated from commanded rotation speed) when spindle synchronous control starts. (The winding is not switched during synchronous control. The control is carried out with the winding selected at start.) If the actual spindle motor rotation speed is less than SP020, the winding L is selected, and if more than the value, the winding H is selected. 1: Use winding H whenever the spindle synchronous command is issued.	0/1
3028	sprcmm	L system tap cycle spindle forward run/reverse run M command	Set the M code of the spindle forward run/reverse run command. High-order three digits: The spindle forward run command's M code is set. Low-order three digits: The spindle reverse run command's M code is set.	0 to 999999

8. MDS-B-SP/SPH,SPJ2 SPINDLE PARAMETERS
8.1 MDS-B-SP/SPH,SPJ2 SPINDLE BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (Unit)	
3029	tapsel	Asynchronous tap gear selection	Specify whether to use the tap rotation speed or maximum rotation speed for the gear that is selected when an asynchronous tap command is issued. 0: Tap rotation speed 1: Maximum rotation speed This parameter is valid only when the M-function synchronous tap cycle enable parameter (#1272 ext08 bit1) is ON.	0/1
3030 (PR)	mbsel	Selection of magnetic bearings	Select whether to use magnetic bearings. 0: Magnetic bearings invalid 1: Magnetic bearings valid	0/1
3031 (PR)	smcp_no	Amplifier I/F channel No. (spindle)	Using a 4-digit number, set the amplifier interface channel No. and which axis in that channel is to be used when connecting a spindle amplifier. High-order two digits : Amplifier interface channel No. Low-order two digits : Axis No. When using the conventional fixed layout, set all axes to "0000". Set "0000" when using an analog spindle.	0000 0101 to 0107 0201 to 0207
3032 (PR)	mbmcp_no	Amplifier I/F channel No. (magnetic bearing)	Using a 4-digit number, set the amplifier interface channel No. and which axis in that channel is to be used when connecting a magnetic bearing amplifier. High-order two digits : Amplifier interface channel No. Low-order two digits : Axis No. When using the conventional fixed layout, set all axes to "0000".	0000 0101 to 0107 0201 to 0207
3037 3038 3039 3040	taps21 22 23 24	Synchronous tap switching spindle speed 2	Set the spindle rotation speed at which the step-2 acceleration/deceleration time constant is to be switched at gear 00, 01, 10, or 11.	0 to 99999 (r/min)
3041 3042 3043 3044	tapt21 22 23 24	Synchronous tap switching time constant 2	Set the time constant to reach synchronous tap switching spindle rotation speed 2 (#3037 to #3040) at gear 00, 01, 10, or 11.	1 to 5000 (ms)
3045 3046 3047 3048	tapt31 32 33 34	Synchronous tap switching time constant 3	Set the time constant to reach the maximum rotation speed (#3005 to #3008) at gear 00, 01, 10, or 11.	1 to 5000 (ms)

8. MDS-B-SP/SPH,SPJ2 SPINDLE PARAMETERS
8.1 MDS-B-SP/SPH,SPJ2 SPINDLE BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (Unit)	
3049	spt	Spindle synchronization acceleration/ deceleration time constant	Set the acceleration/deceleration time constant for when the spindle synchronization command's rotation speed changes during spindle synchronous control.	0 to 9999 (ms)
3050	sprlv	Spindle synchronization rotation speed attainment level	The spindle rotation speed synchronization complete signal will turn ON when the difference of the reference spindle and synchronous spindle actual rotation speeds is less than the level set for the synchronous spindle rotation speed command value during spindle synchronous control.	0 to 4095 (pulse) (1 pulse = 0.088°)
3051	spplv	Spindle phase synchronization attainment level	The spindle phase synchronization complete signal will turn ON when the phase difference of the reference spindle and synchronous spindle is less than the set level during spindle phase synchronization control.	0 to 4095 (pulse) (1 pulse = 0.088°)
3052	spplr	Spindle motor spindle relative polarity	Set the spindle motor and spindle's relative polarity. Spindle CW rotation at motor CW rotation: Positive polarity Spindle CCW rotation at motor CW rotation: Negative polarity	0: Positive polarity 1: Negative polarity
3053	sppst	Spindle encoder Z -phase position	Set the deviation amount from the spindle's reference position to the spindle encoder's Z phase. The deviation amount is obtained using the clockwise direction looking from the front of the spindle as the positive direction.	0 to 359999 (1/1000°)
3054	sptc1	Spindle synchronization multi-step acceleration/ deceleration changeover speed 1	Set the spindle speed for changing the 1st step's acceleration/deceleration time constant.	0 to 99999 (r/min)

8. MDS-B-SP/SPH,SPJ2 SPINDLE PARAMETERS
8.1 MDS-B-SP/SPH,SPJ2 SPINDLE BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (Unit)
3055	sptc2 Spindle synchronization multi-step acceleration/deceleration changeover speed 2	Set the spindle speed for changing the 2nd step's acceleration/deceleration time constant.	0 to 99999 (r/min)
3056	sptc3 Spindle synchronization multi-step acceleration/deceleration changeover speed 3	Set the spindle speed for changing the 3rd step's acceleration/deceleration time constant.	0 to 99999 (r/min)
3057	sptc4 Spindle synchronization multi-step acceleration/deceleration changeover speed 4	Set the spindle speed for changing the 4th step's acceleration/deceleration time constant.	0 to 99999 (r/min)
3058	sptc5 Spindle synchronization multi-step acceleration/deceleration changeover speed 5	Set the spindle speed for changing the 5th step's acceleration/deceleration time constant.	0 to 99999 (r/min)
3059	sptc6 Spindle synchronization multi-step acceleration/deceleration changeover speed 6	Set the spindle speed for changing the 6th step's acceleration/deceleration time constant.	0 to 99999 (r/min)

8. MDS-B-SP/SPH,SPJ2 SPINDLE PARAMETERS
8.1 MDS-B-SP/SPH,SPJ2 SPINDLE BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (Unit)
3060	sptc7 Spindle synchronization multi-step acceleration/deceleration changeover speed 7	Set the spindle speed for changing the 7th step's acceleration/deceleration time constant.	0 to 99999 (r/min)
3061	spdiv1 Magnification for time constant changeover speed 1	Set the acceleration/deceleration time constant between the spindle synchronization multi-step acceleration/deceleration changeover speed 1 (sptc1) to the spindle synchronization multi-step acceleration/deceleration changeover speed 2 (sptc2) as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127
3062	spdiv2 Magnification for time constant changeover speed 2	Set the acceleration/deceleration time constant between the spindle synchronization multi-step acceleration/deceleration changeover speed 2 (sptc2) to the spindle synchronization multi-step acceleration/deceleration changeover speed 3 (sptc3) as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127
3063	spdiv3 Magnification for time constant changeover speed 3	Set the acceleration/deceleration time constant between the spindle synchronization multi-step acceleration/deceleration changeover speed 3 (sptc3) to the spindle synchronization multi-step acceleration/deceleration changeover speed 4 (sptc4) as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127
3064	spdiv4 Magnification for time constant changeover speed 4	Set the acceleration/deceleration time constant between the spindle synchronization multi-step acceleration/deceleration changeover speed 4 (sptc4) to the spindle synchronization multi-step acceleration/deceleration changeover speed 5 (sptc5) as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127
3065	spdiv5 Magnification for time constant changeover speed 5	Set the acceleration/deceleration time constant between the spindle synchronization multi-step acceleration/deceleration changeover speed 5 (sptc5) to the spindle synchronization multi-step acceleration/deceleration changeover speed 6 (sptc6) as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127

8. MDS-B-SP/SPH,SPJ2 SPINDLE PARAMETERS
8.1 MDS-B-SP/SPH,SPJ2 SPINDLE BASE SPECIFICATIONS PARAMETERS

#	Items	Details	Setting range (Unit)
3066	spdiv6 Magnification for time constant changeover speed 6	Set the acceleration/deceleration time constant between the spindle synchronization multi-step acceleration/deceleration changeover speed 6 (sptc6) to the spindle synchronization multi-step acceleration/deceleration changeover speed 7 (sptc7) as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127
3067	spdiv7 Magnification for time constant changeover speed 7	Set the acceleration/deceleration time constant for the spindle synchronization multi-step acceleration/deceleration changeover speed 7 (sptc7) and higher as a magnification in respect to the spindle synchronization acceleration/deceleration time constant (spt).	0 to 127
3068	symtm1 Phase synchronization start confirmation time	Set the time to confirm that synchronization is attained before phase synchronization control is started. When "0" is set, the time will be 2 seconds. When "100" or less is set, the time will be 100ms.	0 to 9999 (ms)
3069	symtm2 Phase synchronization end confirmation time	Set the time to wait for phase synchronization control to end as the time for the rotation speed to reach the attainment range. When "0" is set, the time will be 2 seconds. When "100" or less is set, the time will be 100ms.	0 to 9999 (ms)
3070	syprt Phase synchronization speed	Set the fluctuation amount to change the synchronous spindle rotation speed during phase synchronization control as the command speed and rate. When "0" is set, the amount will be 100%.	0 to 100 (%)
3071	(Not used.)		
3072	(Not used.)		

8. Spindle Parameters
8.2 MDS-B-SPJ2

8.2 MDS-B-SPJ2

For parameters marked with a (PR) in the tables, turn the NC power OFF after setting. The parameters will be valid after the power is turned ON again.

The valid spindle parameters will differ according to the motor and amplifier type. Follow the correspondence table given below, and set the correct parameters.

The spindle parameter setting and display method will differ according to the NC being used, so refer to Instruction Manual for each NC and the following spindles.

MELDAS AC Servo and Spindle MDS-A Series MDS-B Series Specifications Manual
..... BNP-B3759

The "fixed control constants" and "fixed control bits" in this section are set by Mitsubishi.

⚠ CAUTION

⚠ Do not make remarkable adjustments or changes of the parameters as the operation may become unstable.

⚠ In the explanation on bits, set all bits not used, including blank bits, to "0".

No.	Items		Details	Setting range	Standard setting	
3201	SP001	PGM	Magnetic detector and motor built-in encoder orientation-mode position loop gain	As the set value is larger, the orientation time becomes shorter and servo rigidity is increased. On the contrary, however, vibration is increased and the machine becomes likely to overshoot.	0 to 1000 (0.1 1/s)	100
3202	SP002	PGE	Encoder orientation-mode position loop gain	As the set value is larger, the orientation time becomes shorter and servo rigidity is increased. On the contrary, however, vibration is increased and the machine becomes likely to overshoot.	0 to 1000 (0.1 1/s)	100
3203	SP003			Not used. Set to "0".	0	0
3204	SP004	OINP	Orientation in-position width	Set the position error range in which an orientation completion signal is output.	1 to 2880 (1/16°)	16
3205 (PR)	SP005	OSP	Orientation mode changing speed limit value	Set the motor speed limit value to be used when the speed loop is changed to the position loop in orientation mode. When this parameter is set to "0", SP017 (TSP) becomes the limit value.	0 to 32767 (r/min)	0
3206	SP006	CSP	Orientation mode deceleration rate	As the set value is larger, the orientation time becomes shorter. On the contrary, however, the machine becomes likely to overshoot.	1 to 1000	20
3207	SP007	OPST	In-position shift amount for orientation	Set the stop position for orientation. Set the value by dividing 360° by 4096.	0 to 4095	0
3208	SP008			Not used. Set to "0".	0	0
3209	SP009	PGT	Synchronous tapping position loop gain	Set the spindle position loop gain in synchronous tapping mode.	1 to 100 (1/s)	15

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3210	SP010	PGS	Spindle synchronous position loop gain	Set the spindle position loop gain in spindle synchronization mode.	1 to 100 (1/s)	15
3211 to 3216	SP011 to SP016			Use not possible.	0	0
3217 (PR)	SP017	TSP	Maximum motor speed	Set the maximum motor speed of the spindle.	1 to 32767 (r/min)	6000
3218 (PR)	SP018	ZSP	Motor zero speed	Set the motor speed for which zero-speed output is performed.	1 to 1000 (r/min)	50
3219 (PR)	SP019	CSN1	Speed cushion 1	Set the time constant for a speed command from "0" to the maximum speed. (This parameter is invalid in position loop mode.)	0 to 32767 (10ms)	30
3220 (PR)	SP020	SDTS	Speed detection set value	Set the motor speed so for which speed detection output is performed. Usually, the setting value is 10% of SP017 (TSP).	0 to 32767 (r/min)	600
3221	SP021	TLM1	Torque limit 1	Set the torque limit rate for torque limit signal 001.	0 to 120 (%)	10
3222 (PR)	SP022	VGNP1	Speed loop gain proportional term under speed control	Set the speed loop proportional gain in speed control mode. When the gain is increased, response is improved but vibration and sound become larger.	0 to 1000 (1/s)	63
3223 (PR)	SP023	VGNI1	Speed loop gain integral term under speed control	Set the speed loop integral gain in speed control mode. Usually, set a value in proportion to SP022 (VGNP1).	0 to 1000 (0.1 1/s)	60
3224	SP024			Not used. Set to "0".	0	0
3225 (PR)	SP025	GRA1	Spindle gear teeth count 1	Set the number of gear teeth of the spindle corresponding to gear 000.	1 to 32767	1
3226 (PR)	SP026	GRA2	Spindle gear teeth count 2	Set the number of gear teeth of the spindle corresponding to gear 001.	1 to 32767	1
3227 (PR)	SP027	GRA3	Spindle gear teeth count 3	Set the number of gear teeth of the spindle corresponding to gear 010.	1 to 32767	1
3228 (PR)	SP028	GRA4	Spindle gear teeth count 4	Set the number of gear teeth of the spindle corresponding to gear 011.	1 to 32767	1
3229 (PR)	SP029	GRB1	Motor shaft gear teeth count 1	Set the number of gear teeth of the motor shaft corresponding to gear 000.	1 to 32767	1
3230 (PR)	SP030	GRB2	Motor shaft gear teeth count 2	Set the number of gear teeth of the motor shaft corresponding to gear 001.	1 to 32767	1
3231 (PR)	SP031	GRB3	Motor shaft gear teeth count 3	Set the number of gear teeth of the motor shaft corresponding to gear 010.	1 to 32767	1
3232 (PR)	SP032	GRB4	Motor shaft gear teeth count 4	Set the number of gear teeth of the motor shaft corresponding to gear 011.	1 to 32767	1

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																																																																												
3233 (PR)	SP033	SFNC1 Spindle function 1	<p>Set the spindle function 1 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>poff</td><td>hzs</td><td></td><td>ront</td><td></td><td></td><td></td><td></td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td>sftk</td><td>dflt</td><td>1a2m</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>1a2m</td> <td>1 amplifier 2 motor function: Invalid</td> <td>1 amplifier 2 motor function: Valid</td> </tr> <tr> <td>1</td> <td>dflt</td> <td>Default motor: Main</td> <td>Default motor: Sub</td> </tr> <tr> <td>2</td> <td>sftk</td> <td>SF-TK card invalid</td> <td>SF-TK card valid</td> </tr> <tr><td>3</td><td></td><td></td><td></td></tr> <tr><td>4</td><td></td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td><td></td></tr> <tr><td>B</td><td></td><td rowspan="5">This is a fixed control bit.</td><td rowspan="5"></td></tr> <tr><td>C</td><td>ront</td></tr> <tr><td>D</td><td></td></tr> <tr><td>E</td><td>hzs</td></tr> <tr><td>F</td><td>poff</td></tr> </tbody> </table>	F	E	D	C	B	A	9	8	poff	hzs		ront													7	6	5	4	3	2	1	0						sftk	dflt	1a2m	bit	Name	Meaning when set to 0	Meaning when set to 1	0	1a2m	1 amplifier 2 motor function: Invalid	1 amplifier 2 motor function: Valid	1	dflt	Default motor: Main	Default motor: Sub	2	sftk	SF-TK card invalid	SF-TK card valid	3				4				5				6				7				8				9				A				B		This is a fixed control bit.		C	ront	D		E	hzs	F	poff	0000 to FFFF HEX setting	0000								
F	E	D	C	B	A	9	8																																																																																																										
poff	hzs		ront																																																																																																														
7	6	5	4	3	2	1	0																																																																																																										
					sftk	dflt	1a2m																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	1a2m	1 amplifier 2 motor function: Invalid	1 amplifier 2 motor function: Valid																																																																																																														
1	dflt	Default motor: Main	Default motor: Sub																																																																																																														
2	sftk	SF-TK card invalid	SF-TK card valid																																																																																																														
3																																																																																																																	
4																																																																																																																	
5																																																																																																																	
6																																																																																																																	
7																																																																																																																	
8																																																																																																																	
9																																																																																																																	
A																																																																																																																	
B		This is a fixed control bit.																																																																																																															
C	ront																																																																																																																
D																																																																																																																	
E	hzs																																																																																																																
F	poff																																																																																																																
3234 (PR)	SP034	SFNC2 Spindle function 2	<p>Set the spindle function 2 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>mts1</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>mts1</td> <td>Special motor constant invalid</td> <td>Special motor constant setting valid</td> </tr> <tr><td>1</td><td></td><td></td><td></td></tr> <tr><td>2</td><td></td><td></td><td></td></tr> <tr><td>3</td><td></td><td></td><td></td></tr> <tr><td>4</td><td></td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td><td></td></tr> <tr><td>E</td><td></td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td><td></td></tr> </tbody> </table> <p>(Note1) To validate bit3(mkc2), NC side needs to prepare.</p> <p>(Note1) Always turn the bit2 at the same time to use bit3.</p>	F	E	D	C	B	A	9	8																	7	6	5	4	3	2	1	0								mts1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	mts1	Special motor constant invalid	Special motor constant setting valid	1				2				3				4				5				6				7				8				9				A				B				C				D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																										
7	6	5	4	3	2	1	0																																																																																																										
							mts1																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	mts1	Special motor constant invalid	Special motor constant setting valid																																																																																																														
1																																																																																																																	
2																																																																																																																	
3																																																																																																																	
4																																																																																																																	
5																																																																																																																	
6																																																																																																																	
7																																																																																																																	
8																																																																																																																	
9																																																																																																																	
A																																																																																																																	
B																																																																																																																	
C																																																																																																																	
D																																																																																																																	
E																																																																																																																	
F																																																																																																																	

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																																																																				
3235 (PR)	SP035	SFNC3 Spindle function3	<p>Set the spindle function 3 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td>hbsd</td><td><input type="checkbox"/></td><td>hwid</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>hwid</td> <td>H-coil wide-range constant output invalid</td> <td>H-coil wide-range constant output valid</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>hbsd</td> <td>H-coil base slide invalid</td> <td>H-coil base slide valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	7	6	5	4	3	2	1	0	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	hbsd	<input type="checkbox"/>	hwid	bit	Name	Meaning when set to 0	Meaning when set to 1	0	hwid	H-coil wide-range constant output invalid	H-coil wide-range constant output valid	1				2	hbsd	H-coil base slide invalid	H-coil base slide valid	3				4				5				6				7				8				9				A				B				C				D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																		
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	hbsd	<input type="checkbox"/>	hwid																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	hwid	H-coil wide-range constant output invalid	H-coil wide-range constant output valid																																																																																																						
1																																																																																																									
2	hbsd	H-coil base slide invalid	H-coil base slide valid																																																																																																						
3																																																																																																									
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8																																																																																																									
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									
3236 (PR)	SP036	SFNC4 Spindle function 4	<p>Set the spindle function 4 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td>dslm</td><td>dssm</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td>enc2</td><td>enc1</td><td>mag2</td><td>mag1</td><td>plg2</td><td>plg1</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>plg1</td> <td>PLG of motor 1 valid</td> <td>PLG of motor 1 invalid</td> </tr> <tr> <td>1</td> <td>plg2</td> <td>PLG of motor 2 valid</td> <td>PLG of motor 2 invalid</td> </tr> <tr> <td>2</td> <td>mag1</td> <td>MAG of motor 1 valid</td> <td>MAG of motor 1 invalid</td> </tr> <tr> <td>3</td> <td>mag2</td> <td>MAG of motor 2 valid</td> <td>MAG of motor 2 invalid</td> </tr> <tr> <td>4</td> <td>enc1</td> <td>ENC of motor 1 valid</td> <td>ENC of motor 1 invalid</td> </tr> <tr> <td>5</td> <td>enc2</td> <td>ENC of motor 2 valid</td> <td>ENC of motor 2 invalid</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>dssm</td> <td>Speedometer valid</td> <td>Speedometer invalid</td> </tr> <tr> <td>9</td> <td>dslm</td> <td>Load meter valid</td> <td>Load meter invalid</td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	dslm	dssm	7	6	5	4	3	2	1	0	<input type="checkbox"/>	<input type="checkbox"/>	enc2	enc1	mag2	mag1	plg2	plg1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	plg1	PLG of motor 1 valid	PLG of motor 1 invalid	1	plg2	PLG of motor 2 valid	PLG of motor 2 invalid	2	mag1	MAG of motor 1 valid	MAG of motor 1 invalid	3	mag2	MAG of motor 2 valid	MAG of motor 2 invalid	4	enc1	ENC of motor 1 valid	ENC of motor 1 invalid	5	enc2	ENC of motor 2 valid	ENC of motor 2 invalid	6				7				8	dssm	Speedometer valid	Speedometer invalid	9	dslm	Load meter valid	Load meter invalid	A				B				C				D				E				F					
F	E	D	C	B	A	9	8																																																																																																		
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	dslm	dssm																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
<input type="checkbox"/>	<input type="checkbox"/>	enc2	enc1	mag2	mag1	plg2	plg1																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	plg1	PLG of motor 1 valid	PLG of motor 1 invalid																																																																																																						
1	plg2	PLG of motor 2 valid	PLG of motor 2 invalid																																																																																																						
2	mag1	MAG of motor 1 valid	MAG of motor 1 invalid																																																																																																						
3	mag2	MAG of motor 2 valid	MAG of motor 2 invalid																																																																																																						
4	enc1	ENC of motor 1 valid	ENC of motor 1 invalid																																																																																																						
5	enc2	ENC of motor 2 valid	ENC of motor 2 invalid																																																																																																						
6																																																																																																									
7																																																																																																									
8	dssm	Speedometer valid	Speedometer invalid																																																																																																						
9	dslm	Load meter valid	Load meter invalid																																																																																																						
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																																																																				
3237 (PR)	SP037	SFNC5 Spindle function 5	<p>Set the spindle function 5 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>nstv</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td>plgo</td><td></td><td>enco</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>enco</td> <td>Encoder orientation invalid</td> <td>Encoder orientation valid</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>plgo</td> <td>PLG orientation invalid</td> <td>PLG orientation valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>nstv</td> <td>No-signal detection type (Always monitoring)</td> <td>Monitoring only in position loop or orientation-mode</td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8								nstv	7	6	5	4	3	2	1	0						plgo		enco	bit	Name	Meaning when set to 0	Meaning when set to 1	0	enco	Encoder orientation invalid	Encoder orientation valid	1				2	plgo	PLG orientation invalid	PLG orientation valid	3				4				5				6				7				8	nstv	No-signal detection type (Always monitoring)	Monitoring only in position loop or orientation-mode	9				A				B				C				D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																		
							nstv																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
					plgo		enco																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	enco	Encoder orientation invalid	Encoder orientation valid																																																																																																						
1																																																																																																									
2	plgo	PLG orientation invalid	PLG orientation valid																																																																																																						
3																																																																																																									
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8	nstv	No-signal detection type (Always monitoring)	Monitoring only in position loop or orientation-mode																																																																																																						
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									
3238 (PR)	SP038	SFNC6 Spindle function 6	<p>Set the spindle function 6 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>oplp</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td>pftm</td><td></td><td>alty</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>alty</td> <td>Deceleration stop during special alarm invalid</td> <td>Deceleration stop during special alarm valid</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>pftm</td> <td>Thread cutting position data invalid</td> <td>Thread cutting position data valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td>oplp</td> <td>Open loop operation invalid</td> <td>Open loop operation valid</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	oplp								7	6	5	4	3	2	1	0						pftm		alty	bit	Name	Meaning when set to 0	Meaning when set to 1	0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid	1				2	pftm	Thread cutting position data invalid	Thread cutting position data valid	3				4				5				6				7				8				9				A				B				C				D				E				F	oplp	Open loop operation invalid	Open loop operation valid	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																		
oplp																																																																																																									
7	6	5	4	3	2	1	0																																																																																																		
					pftm		alty																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid																																																																																																						
1																																																																																																									
2	pftm	Thread cutting position data invalid	Thread cutting position data valid																																																																																																						
3																																																																																																									
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8																																																																																																									
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F	oplp	Open loop operation invalid	Open loop operation valid																																																																																																						


8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																												
3239 (PR)	SP039	ATYP Amplifier type	Set the amplifier type. Set each amplifier type or "0". This parameter corresponds to MDS-B-SPJ2. <table border="1" data-bbox="627 446 1083 814"> <thead> <tr> <th>Parameter setting</th> <th>Amplifier type</th> </tr> </thead> <tbody> <tr><td>0000</td><td>--</td></tr> <tr><td>0001</td><td>SPJ2-02</td></tr> <tr><td>0002</td><td>SPJ2-04</td></tr> <tr><td>0003</td><td>SPJ2-075</td></tr> <tr><td>0004</td><td>SPJ2-15</td></tr> <tr><td>0005</td><td>SPJ2-22</td></tr> <tr><td>0006</td><td>SPJ2-37</td></tr> <tr><td>0007</td><td>SPJ2-55</td></tr> <tr><td>0008</td><td>SPJ2-75</td></tr> <tr><td>0009</td><td>SPJ2-110/110C</td></tr> </tbody> </table>	Parameter setting	Amplifier type	0000	--	0001	SPJ2-02	0002	SPJ2-04	0003	SPJ2-075	0004	SPJ2-15	0005	SPJ2-22	0006	SPJ2-37	0007	SPJ2-55	0008	SPJ2-75	0009	SPJ2-110/110C	0000 to FFFF HEX setting	0000																						
Parameter setting	Amplifier type																																																
0000	--																																																
0001	SPJ2-02																																																
0002	SPJ2-04																																																
0003	SPJ2-075																																																
0004	SPJ2-15																																																
0005	SPJ2-22																																																
0006	SPJ2-37																																																
0007	SPJ2-55																																																
0008	SPJ2-75																																																
0009	SPJ2-110/110C																																																
3240 (PR)	SP040	MTYP Motor type	This is valid when SP034 (SFNC2) bit 0 is set to 0. Refer to the following standard motors, and set the applicable motor number. <table border="1" data-bbox="609 1042 1133 1378"> <thead> <tr> <th>Parameter setting</th> <th>Motor type</th> <th>Maximum speed</th> <th>Corresponding amplifier</th> </tr> </thead> <tbody> <tr><td>1000</td><td></td><td></td><td></td></tr> <tr><td>1001</td><td>SJ-P0.2A</td><td>10000 r/min</td><td>SPJ2-02</td></tr> <tr><td>1002</td><td>SJ-P0.4A</td><td>10000 r/min</td><td>SPJ2-04</td></tr> <tr><td>1003</td><td>SJ-P0.75A</td><td>10000 r/min</td><td>SPJ2-075</td></tr> <tr><td>1004</td><td>SJ-P1.5A</td><td>10000 r/min</td><td>SPJ2-15</td></tr> <tr><td>1005</td><td>SJ-P2.2A</td><td>8000 r/min</td><td>SPJ2-22</td></tr> <tr><td>1006</td><td>SJ-P3.7A</td><td>8000 r/min</td><td>SPJ2-37</td></tr> <tr><td>1007</td><td>SJ-PF5.5-01</td><td>8000 r/min</td><td>SPJ2-55</td></tr> <tr><td>1008</td><td>SJ-PF7.5-01</td><td>8000 r/min</td><td>SPJ2-75</td></tr> <tr><td>1009</td><td>SJ-PF11-01</td><td>6000 r/min</td><td>SPJ2-110/110C</td></tr> </tbody> </table>	Parameter setting	Motor type	Maximum speed	Corresponding amplifier	1000				1001	SJ-P0.2A	10000 r/min	SPJ2-02	1002	SJ-P0.4A	10000 r/min	SPJ2-04	1003	SJ-P0.75A	10000 r/min	SPJ2-075	1004	SJ-P1.5A	10000 r/min	SPJ2-15	1005	SJ-P2.2A	8000 r/min	SPJ2-22	1006	SJ-P3.7A	8000 r/min	SPJ2-37	1007	SJ-PF5.5-01	8000 r/min	SPJ2-55	1008	SJ-PF7.5-01	8000 r/min	SPJ2-75	1009	SJ-PF11-01	6000 r/min	SPJ2-110/110C	0000 to FFFF HEX setting	0000
Parameter setting	Motor type	Maximum speed	Corresponding amplifier																																														
1000																																																	
1001	SJ-P0.2A	10000 r/min	SPJ2-02																																														
1002	SJ-P0.4A	10000 r/min	SPJ2-04																																														
1003	SJ-P0.75A	10000 r/min	SPJ2-075																																														
1004	SJ-P1.5A	10000 r/min	SPJ2-15																																														
1005	SJ-P2.2A	8000 r/min	SPJ2-22																																														
1006	SJ-P3.7A	8000 r/min	SPJ2-37																																														
1007	SJ-PF5.5-01	8000 r/min	SPJ2-55																																														
1008	SJ-PF7.5-01	8000 r/min	SPJ2-75																																														
1009	SJ-PF11-01	6000 r/min	SPJ2-110/110C																																														


8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																												
3241 (PR)	SP041	PTYP	Power supply type	When this unit is a signal connection axis with power supply unit, set this parameter. Set "0" for this parameter for the unit which is not a signal connection axis. Select a value from the following table according to the regenerative resistance being used.	0000 to FFFF HEX setting	0000																																																											
<table border="1"> <thead> <tr> <th>Setting value</th> <th>Regenerative resistance type</th> <th>Resistance value (Ω)</th> <th>Capacity (W)</th> </tr> </thead> <tbody> <tr> <td>0000</td> <td>-</td> <td>-</td> <td>-</td> </tr> <tr> <td>2000</td> <td>Not connected</td> <td>-</td> <td>-</td> </tr> <tr> <td>2100</td> <td>FCUA-RB04</td> <td>200</td> <td>60</td> </tr> <tr> <td>2200</td> <td>FCUA-RB075</td> <td>100</td> <td>80</td> </tr> <tr> <td>2300</td> <td>FCUA-RB15</td> <td>60</td> <td>120</td> </tr> <tr> <td>2400</td> <td>FCUA-RB22</td> <td>40</td> <td>155</td> </tr> <tr> <td>2500</td> <td>FCUA-RB37</td> <td>25</td> <td>185</td> </tr> <tr> <td>2600</td> <td>FCUA-RB55</td> <td>20</td> <td>340</td> </tr> <tr> <td>2700</td> <td>FCUA-RB75/2</td> <td>30/15</td> <td>340/680</td> </tr> <tr> <td>2800</td> <td>R-UNIT-1</td> <td>30</td> <td>700</td> </tr> <tr> <td>2900</td> <td>R-UNIT-2</td> <td>15</td> <td>700</td> </tr> <tr> <td>2A00</td> <td>R-UNIT-3</td> <td>15</td> <td>2100</td> </tr> <tr> <td>2B00</td> <td>R-UNIT-4</td> <td>10</td> <td>2100</td> </tr> <tr> <td>2C00</td> <td>R-UNIT-5</td> <td>10</td> <td>3100</td> </tr> </tbody> </table>				Setting value	Regenerative resistance type	Resistance value (Ω)	Capacity (W)	0000	-	-	-	2000	Not connected	-	-	2100	FCUA-RB04	200	60	2200	FCUA-RB075	100	80	2300	FCUA-RB15	60	120	2400	FCUA-RB22	40	155	2500	FCUA-RB37	25	185	2600	FCUA-RB55	20	340	2700	FCUA-RB75/2	30/15	340/680	2800	R-UNIT-1	30	700	2900	R-UNIT-2	15	700	2A00	R-UNIT-3	15	2100	2B00	R-UNIT-4	10	2100	2C00	R-UNIT-5	10	3100		
Setting value	Regenerative resistance type	Resistance value (Ω)	Capacity (W)																																																														
0000	-	-	-																																																														
2000	Not connected	-	-																																																														
2100	FCUA-RB04	200	60																																																														
2200	FCUA-RB075	100	80																																																														
2300	FCUA-RB15	60	120																																																														
2400	FCUA-RB22	40	155																																																														
2500	FCUA-RB37	25	185																																																														
2600	FCUA-RB55	20	340																																																														
2700	FCUA-RB75/2	30/15	340/680																																																														
2800	R-UNIT-1	30	700																																																														
2900	R-UNIT-2	15	700																																																														
2A00	R-UNIT-3	15	2100																																																														
2B00	R-UNIT-4	10	2100																																																														
2C00	R-UNIT-5	10	3100																																																														
(Note 1) This setting is used when using one FCUA-RB75/2 and when using two in parallel.																																																																	
3242 (PR)	SP042			Not used. Set to "0".	0	0																																																											
3243 (PR)	SP043			Not used. Set to "0".	0	0																																																											
3244 (PR)	SP044	TRANS	NC communication frequency	Set a frequency of data communication with NC.	0 to 32767	Standard: 0 Special: 1028																																																											
3245	SP045			Not used. Set to "0".	0	0																																																											
3246 (PR)	SP046	CSN2	Speed command dual cushion	For an acceleration/deceleration time constant defined in SP019 (CSN1) , this parameter is used to provide smooth movement only at the start of acceleration/deceleration. As the value of this parameter is smaller, it moves smoother but the acceleration/deceleration time becomes longer. To make this parameter invalid, set "0".	0 to 1000	0																																																											
3247 (PR)	SP047	SDTR	Speed detection reset value	Set the reset hysteresis width for a speed detection set value defined in SP020 (SDTS).	0 to 1000 (r/min)	30																																																											


8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items			Details	Setting range	Standard setting
3248 (PR)	SP048	SUT	Speed reach range	Set the speed deviation rate with respect to the commanded speed for output of the speed reach signal.	0 to 100 (%)	15
3249	SP049	TLM2	Torque limit 2	Set the torque limit rate for the torque limit signal 010.	1 to 120 (%)	20
3250	SP050	TLM3	Torque limit 3	Set the torque limit rate for the torque limit signal 011.	1 to 120 (%)	30
3251	SP051	TLM4	Torque limit 4	Set the torque limit rate for the torque limit signal 100.	1 to 120 (%)	40
3252	SP052	TLM5	Torque limit 5	Set the torque limit rate for the torque limit signal 101.	1 to 120 (%)	50
3253	SP053	TLM6	Torque limit 6	Set the torque limit rate for the torque limit signal 110.	1 to 120 (%)	60
3254	SP054	TLM7	Torque limit 7	Set the torque limit rate for the torque limit signal 111.	1 to 120 (%)	70
3255 (PR)	SP055	SETM	Excessive speed deviation timer	Set the timer value until the excessive speed deviation alarm is output. The value of this parameter should be longer than the acceleration/deceleration time.	0 to 60 (s)	12
3256	SP056	PYVR	Variable excitation (min value)	Set the minimum value of the variable excitation rate. Select a smaller value when gear noise is too high. However, a larger value is effective for impact response.	0 to 100 (%)	50
3257 (PR)	SP057	STOD	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3258 to 3262	SP058 to SP062			Not used. Set to "0".	0	0
3263 (PR)	SP063	OLT	Overload alarm detection time	Set the time constant for detection of the motor overload alarm.	0 to 1000 (s)	60
3264 (PR)	SP064	OLL	Overload alarm detection level	Set the detection level of the motor overload alarm.	0 to 120 (%)	110
3265 (PR)	SP065	VCGN 1	Target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP022 (VGNP1) at the maximum motor speed defined in SP017 (TSP).	0 to 100 (%)	100
3266 (PR)	SP066	VCSN 1	Change starting speed of variable speed loop proportional gain	Set the speed for starting change of speed loop proportional gain. 	0 to 32767 (r/min)	0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																	
3267 (PR)	SP067	VIGWA	Change starting speed of variable current loop gain	Set the speed for starting change of current loop gain.	0 to 32767 (r/min)	0																
3268 (PR)	SP068	VIGWB	Change ending speed of variable current loop gain	Set the speed for ending change of current loop gain.	0 to 32767 (r/min)	0																
3269 (PR)	SP069	VIGN	Target value of variable current loop gain	<p>Set the magnification of current loop gain (torque component and excitation component) for a change ending speed defined in SP068 (VIGWB). When this parameter is set to "0", the magnification is 1.</p>  <table border="1" data-bbox="662 1096 1165 1276"> <thead> <tr> <th>SP017 (TSP) Maximum motor speed</th> <th>SP067 (VIGWA)</th> <th>SP068 (VIGWB)</th> <th>SP069 (VIGN)</th> </tr> </thead> <tbody> <tr> <td>0 to 6000</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>6001 to 8000</td> <td>5000</td> <td>8000</td> <td>45</td> </tr> <tr> <td>8001 or more</td> <td>5000</td> <td>10000</td> <td>64</td> </tr> </tbody> </table>	SP017 (TSP) Maximum motor speed	SP067 (VIGWA)	SP068 (VIGWB)	SP069 (VIGN)	0 to 6000	0	0	0	6001 to 8000	5000	8000	45	8001 or more	5000	10000	64	0 to 32767 (1/16-fold)	0
SP017 (TSP) Maximum motor speed	SP067 (VIGWA)	SP068 (VIGWB)	SP069 (VIGN)																			
0 to 6000	0	0	0																			
6001 to 8000	5000	8000	45																			
8001 or more	5000	10000	64																			
3270	SP070			Not used. Set to "0".	0	0																
3271 (PR)	SP071	VR2WA	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0																
3272 (PR)	SP072	VR2WB																				
3273 (PR)	SP073	VR2GN																				
3274 (PR)	SP074	IGDEC																				
3275	SP075	R2KWS																				

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3276	SP076			Not used. Set to "0".	0	0
3277	SP077	TDSL	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3278 (PR)	SP078	FPWM				
3279 (PR)	SP079	ILMT				
3280	SP080					
3281	SP081	LMCA				
3282	SP082	LMCB				
3283 to 3286	SP083 to SP086			Not used. Set to "0".	0	0
3287 (PR)	SP087	DIQM	Target value of variable torque limit magnification at deceleration	Set the minimum value of variable torque limit at deceleration.	0 to 150 (%)	75
3288 (PR)	SP088	DIQN	Speed for starting change of variable torque limit magnification at deceleration	Set the speed for starting change of torque limit value at deceleration. 	0 to 32767 (r/min)	3000
3289 to 3292	SP089 to SP092			Not used. Set to "0".	0	0
3293 (PR)	SP093	ORE	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3294 (PR)	SP094			Not used. Set to "0".	0	0
3295 (PR)	SP095	VFAV	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																																																																					
3296 (PR)	SP096	EGAR	Encoder gear ratio	Set the gear ratio between the spindle end and the encoder end (except for the motor-built-in encoder) as indicated below.	-3 to 4	0																																																																																																				
				<table border="1"> <thead> <tr> <th>Setting value</th> <th>Gear ratio (deceleration)</th> <th>Setting value</th> <th>Gear ratio (Acceleration)</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>1 : 1</td> <td>-1</td> <td>1 : 2</td> </tr> <tr> <td>1</td> <td>1 : 1/2</td> <td>-2</td> <td>1 : 4</td> </tr> <tr> <td>2</td> <td>1 : 1/4</td> <td>-3</td> <td>1 : 3</td> </tr> <tr> <td>3</td> <td>1 : 1/8</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td>1 : 1/16</td> <td></td> <td></td> </tr> </tbody> </table>	Setting value	Gear ratio (deceleration)	Setting value	Gear ratio (Acceleration)	0	1 : 1	-1	1 : 2	1	1 : 1/2	-2	1 : 4	2	1 : 1/4	-3	1 : 3	3	1 : 1/8			4	1 : 1/16																																																																																
Setting value	Gear ratio (deceleration)	Setting value	Gear ratio (Acceleration)																																																																																																							
0	1 : 1	-1	1 : 2																																																																																																							
1	1 : 1/2	-2	1 : 4																																																																																																							
2	1 : 1/4	-3	1 : 3																																																																																																							
3	1 : 1/8																																																																																																									
4	1 : 1/16																																																																																																									
3297 (PR)	SP097	SPECO	Orientation specification	Set the orientation specifications in bit units.	0000 to FFFF HEX setting	0000																																																																																																				
				<table border="1"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>tlet</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td>fdir</td><td></td><td>pyfx</td><td>dmin</td><td>odi2</td><td>odi1</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>odi1</td> <td colspan="2">Orientation rotation direction 00: Previous (the direction in which the motor has so far rotated under speed control)</td> </tr> <tr> <td>1</td> <td>odi2</td> <td colspan="2">01: Forward rotation 10: Backward rotation 11: Prohibited (Same as setting value = 10)</td> </tr> <tr> <td>2</td> <td>dmin</td> <td>Dummy in-position invalid</td> <td>Dummy in-position valid</td> </tr> <tr> <td>3</td> <td>pyfx</td> <td>Excitation min. (50%) during orientation servo lock invalid</td> <td>Excitation min. (50%) during orientation servo lock valid</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Encoder detector polarity: +</td> <td>Encoder detector polarity: -</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>tlet</td> <td>Turret indexing invalid</td> <td>Turret indexing valid</td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8								tlet	7	6	5	4	3	2	1	0			fdir		pyfx	dmin	odi2	odi1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	odi1	Orientation rotation direction 00: Previous (the direction in which the motor has so far rotated under speed control)		1	odi2	01: Forward rotation 10: Backward rotation 11: Prohibited (Same as setting value = 10)		2	dmin	Dummy in-position invalid	Dummy in-position valid	3	pyfx	Excitation min. (50%) during orientation servo lock invalid	Excitation min. (50%) during orientation servo lock valid	4				5	fdir	Encoder detector polarity: +	Encoder detector polarity: -	6				7				8	tlet	Turret indexing invalid	Turret indexing valid	9				A				B				C				D				E				F					
F	E	D	C	B	A	9	8																																																																																																			
							tlet																																																																																																			
7	6	5	4	3	2	1	0																																																																																																			
		fdir		pyfx	dmin	odi2	odi1																																																																																																			
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																							
0	odi1	Orientation rotation direction 00: Previous (the direction in which the motor has so far rotated under speed control)																																																																																																								
1	odi2	01: Forward rotation 10: Backward rotation 11: Prohibited (Same as setting value = 10)																																																																																																								
2	dmin	Dummy in-position invalid	Dummy in-position valid																																																																																																							
3	pyfx	Excitation min. (50%) during orientation servo lock invalid	Excitation min. (50%) during orientation servo lock valid																																																																																																							
4																																																																																																										
5	fdir	Encoder detector polarity: +	Encoder detector polarity: -																																																																																																							
6																																																																																																										
7																																																																																																										
8	tlet	Turret indexing invalid	Turret indexing valid																																																																																																							
9																																																																																																										
A																																																																																																										
B																																																																																																										
C																																																																																																										
D																																																																																																										
E																																																																																																										
F																																																																																																										
3298 (PR)	SP098	VGOP	Speed loop gain proportional term in orientation mode	Set the speed loop proportional gain in orientation mode. When the gain is increased, rigidity is improved in the orientation stop but vibration and sound become larger.	0 to 1000 (1/s)	63																																																																																																				
3299 (PR)	SP099	VGOI	Orientation mode speed loop gain integral term	Set the speed loop integral gain in orientation mode.	0 to 1000 (0.1 1/s)	60																																																																																																				
3300 (PR)	SP100	VGOD	Orientation mode speed loop gain delay advance term	Set the a loop gain delay advance gain in orientation mode. When this parameter is set to "0", PI control is exercised.	0 to 1000 (0.1 1/s)	15																																																																																																				

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items			Details	Setting range	Standard setting
3301 (PR)	SP101	DINP	Orientation advance in-position width	When using the orientation in-position advance function, set the in-position width that is larger than the normal in-position width defined in SP004 (OINP).	1 to 2880 (1/16°)	16
3302 (PR)	SP102	OODR	Excessive error value in orientation mode	Set the excessive error width in orientation mode.	1 to 32767 (1/4 pulse) (1 pulse= 0.088°)	32767
3303 (PR)	SP103	FTM	Index positioning completion OFF time timer	Set the time for forcedly turn OFF the index positioning completion signal (different from the orientation completion signal) after the leading edge of the indexing start signal.	1 to 10000 (ms)	200
3304 (PR)	SP104	TLOR	Torque limit value for orientation servo locking	Set the torque limit value for orientation in-position output. If the external torque limit signal is input the torque limit value set by this parameter is made invalid.	1 to 120 (%)	100
3305 (PR)	SP105	IQG0	Current loop gain magnification 1 in orientation mode	Set the magnification for current loop gain (torque component) at orientation completion.	1 to 1000 (%)	100
3306	SP106	IDG0	Current loop gain magnification 2 in orientation mode	Set the magnification for current loop gain (excitation component) at orientation completion.	1 to 1000 (%)	100
3307	SP107	CSP2	Deceleration rate 2 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 001. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0
3308	SP108	CSP3	Deceleration rate 3 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 010. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0
3309 (PR)	SP109	CSP4	Deceleration rate 4 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 011. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0
3310 (PR)	SP110	WCML	Turret index command magnification	The integer magnification (gear ratio 1 : N) for the index position command (0 to 359) is set.	0 to 32767 (fold)	0
3311	SP111	WDEL	Turret index deceleration magnification	The magnification for the orientation deceleration rate is set using 256 as 1.	0 to 32767 (1/256 -fold)	0
3312	SP112	WCLP	Turret index clamp speed	The max. speed during indexing is set. This becomes the max. speed of the motor when set to "0".	0 to 32767 (r/min)	0


8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3313 (PR)	SP113	WINP	Turret index in-position width	The position error range is set in which an orientation (indexing) completed signal is output during turret indexing. This becomes the same as SP004 (OINP) when set to "0".	0 to 32767 (1/16°)	0
3314	SP114	OPER	Orientation pulse miss check value	An alarm "5C" will occur if the pulse miss value in the orientation stop exceed this setting value. (Note that this is invalid when set to "0".) In this parameter, set the value to fulfill the following conditions. SP114 setting value > 1.5 × SP004 (orientation in-position width)	0 to 32767 (360°/4096)	0
3315	SP115	OSP2	Orientation changeover speed limit value 2	When the door interlock spindle speed clamp signal is ON, this setting is used instead of OSP(SP005), CZRN(SP149) and TZRN(SP214). (Note that SP149 and SP214 are used only for the M65V.)	0 to 32767 (r/min)	0
3316	SP116	OPYVR	Fixed control constants	Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3317	SP117	ORUT				
3318	SP118	ORCT	Number of orientation retry times	Set the number of times to retry when an orientation or feedback error occurs. The warning (A9) is issued while retrying orientation, and an alarm (5C) is issued when the set number of times is exceeded.	0 to 100 (time)	0
3319 to 3376	SP119 to SP176			Not used. Set to "0".	0	0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																																																																				
3377 (PR)	SP177	SPECS Spindle synchronous specifications	Set the spindle synchronous specifications in bit units. <table border="1" style="width:100%; text-align:center; border-collapse: collapse;"> <tr> <td style="width:12.5%;">F</td><td style="width:12.5%;">E</td><td style="width:12.5%;">D</td><td style="width:12.5%;">C</td><td style="width:12.5%;">B</td><td style="width:12.5%;">A</td><td style="width:12.5%;">9</td><td style="width:12.5%;">8</td> </tr> <tr> <td style="border: 1px solid black; height: 15px;"></td><td style="border: 1px solid black; height: 15px;"></td><td style="border: 1px solid black; height: 15px;">odx8</td><td style="border: 1px solid black; height: 15px;"></td><td style="border: 1px solid black; height: 15px;"></td><td style="border: 1px solid black; height: 15px;"></td><td style="border: 1px solid black; height: 15px;"></td><td style="border: 1px solid black; height: 15px;"></td> </tr> <tr> <td style="width:12.5%;">7</td><td style="width:12.5%;">6</td><td style="width:12.5%;">5</td><td style="width:12.5%;">4</td><td style="width:12.5%;">3</td><td style="width:12.5%;">2</td><td style="width:12.5%;">1</td><td style="width:12.5%;">0</td> </tr> <tr> <td style="border: 1px solid black; height: 15px;"></td><td style="border: 1px solid black; height: 15px;"></td><td style="border: 1px solid black; height: 15px;">fdir</td><td style="border: 1px solid black; height: 15px;"></td><td style="border: 1px solid black; height: 15px;">pyfx</td><td style="border: 1px solid black; height: 15px;"></td><td style="border: 1px solid black; height: 15px;"></td><td style="border: 1px solid black; height: 15px;">fclx</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center; border-collapse: collapse;"> <thead> <tr> <th>bit</th><th>Name</th><th>Meaning when set to 0</th><th>Meaning when set to 1</th></tr> </thead> <tbody> <tr><td>0</td><td>fclx</td><td>Closed loop</td><td>Semi-closed loop</td></tr> <tr><td>1</td><td></td><td></td><td></td></tr> <tr><td>2</td><td></td><td></td><td></td></tr> <tr><td>3</td><td>pyfx</td><td>Normal excitation</td><td>Position loop excitation fixed (strong)</td></tr> <tr><td>4</td><td></td><td></td><td></td></tr> <tr><td>5</td><td>fdir</td><td>Position detector polarity (+)</td><td>Position detector polarity (-)</td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td><td></td></tr> <tr><td>D</td><td>odx8</td><td>Magnification of excessive error width x 8 times invalid</td><td>Magnification of excessive error width x 8 times valid</td></tr> <tr><td>E</td><td></td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td><td></td></tr> </tbody> </table>	F	E	D	C	B	A	9	8			odx8						7	6	5	4	3	2	1	0			fdir		pyfx			fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop	1				2				3	pyfx	Normal excitation	Position loop excitation fixed (strong)	4				5	fdir	Position detector polarity (+)	Position detector polarity (-)	6				7				8				9				A				B				C				D	odx8	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid	E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																		
		odx8																																																																																																							
7	6	5	4	3	2	1	0																																																																																																		
		fdir		pyfx			fclx																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	fclx	Closed loop	Semi-closed loop																																																																																																						
1																																																																																																									
2																																																																																																									
3	pyfx	Normal excitation	Position loop excitation fixed (strong)																																																																																																						
4																																																																																																									
5	fdir	Position detector polarity (+)	Position detector polarity (-)																																																																																																						
6																																																																																																									
7																																																																																																									
8																																																																																																									
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D	odx8	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid																																																																																																						
E																																																																																																									
F																																																																																																									
3378 (PR)	SP178	VGSP Spindle synchronous speed loop gain proportional term	Set the speed loop proportional gain in spindle synchronization mode.	0 to 1000 (1/s)	63																																																																																																				
3379 (PR)	SP179	VGSI Spindle synchronous speed loop gain integral term	Set the speed loop integral gain in spindle synchronization mode.	0 to 1000 (0.1 1/s)	60																																																																																																				
3380 (PR)	SP180	VGSD Spindle synchronous speed loop gain delay advance term	Set the speed loop delay advance gain in spindle synchronization mode. When this parameter is set to "0", PI control is exercised.	0 to 1000 (0.1 1/s)	15																																																																																																				
3381 (PR)	SP181	VCGS Target value of variable speed loop proportional gain at spindle synchronization	Set the magnification of speed loop proportional gain with respect to SP178 (VGSP) at the maximum speed defined in SP017 (TSP) at spindle synchronization.	0 to 100 (%)	100																																																																																																				


8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3382 (PR)	SP182	VCSS	Change starting speed of variable speed loop proportional gain at spindle synchronization	Set the speed for starting change of speed loop proportional gain at spindle synchronization. 	0 to 32767 (r/min)	0
3383	SP183	SYNV	Sync matching speed at spindle synchronization	For changeover from the speed loop to the position loop at spindle synchronization, set a speed command error range for output of the sync speed matching signal.	0 to 1000 (r/min)	20
3384 (PR)	SP184	FFCS	Acceleration rate feed forward gain at spindle synchronization	Set the acceleration rate feed forward gain at spindle synchronization. This parameter is used only with the SPJ2.	0 to 1000 (%)	0
3385	SP185	SINP	Spindle sync in-position width	Set the position error range for output of the in-position signal at spindle synchronization.	1 to 2880 (1/16°)	16
3386 (PR)	SP186	SODR	Excessive error width at spindle synchronization	Set the excessive error width at spindle synchronization.	1 to 32767 (1/4 pulse) (1 pulse =0.088°)	32767
3387 (PR)	SP187	IQGS	Current loop gain magnification1 at spindle synchronization	Set the magnification of current loop gain (torque component) at spindle synchronization.	1 to 1000 (%)	100
3388 (PR)	SP188	IDGS	Current loop gain magnification 2 at spindle synchronization	Set the magnification of current loop gain (excitation component) at spindle synchronization.	1 to 1000 (%)	100
3389 to 3392	SP189 to SP192			Not used. Set to "0".	0	0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting																																																																																																												
3393 (PR)	SP193	SPECT	Synchronous tapping specifications Set the synchronous tapping specifications in bit units. <table border="1" style="width:100%; text-align:center; border-collapse: collapse;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>zrtn</td><td>ptyp</td><td>od8x</td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td>fdir</td><td>cdir</td><td>pyfx</td><td></td><td></td><td>fclx</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center; border-collapse: collapse;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr><td>0</td><td>fclx</td><td>Closed loop</td><td>Semi-closed loop</td></tr> <tr><td>1</td><td></td><td></td><td></td></tr> <tr><td>2</td><td></td><td></td><td></td></tr> <tr><td>3</td><td>pyfx</td><td>Normal excitation</td><td>Position loop excitation fixed (strong)</td></tr> <tr><td>4</td><td>cdir</td><td>Command polarity (+)</td><td>Command polarity (-)</td></tr> <tr><td>5</td><td>fdir</td><td>Position detector polarity (+)</td><td>Position detector polarity (-)</td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td><td></td></tr> <tr><td>D</td><td>od8x</td><td>Magnification of excessive error width x 8 times invalid</td><td>Magnification of excessive error width x 8 times valid</td></tr> <tr><td>E</td><td>ptyp</td><td>Position control switch type: After zero point return</td><td>Position control switch type: After deceleration stop</td></tr> <tr><td>F</td><td>zrtn</td><td>Zero point return direction: CCW</td><td>Zero point return direction: CW</td></tr> </tbody> </table>	F	E	D	C	B	A	9	8	zrtn	ptyp	od8x														7	6	5	4	3	2	1	0			fdir	cdir	pyfx			fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop	1				2				3	pyfx	Normal excitation	Position loop excitation fixed (strong)	4	cdir	Command polarity (+)	Command polarity (-)	5	fdir	Position detector polarity (+)	Position detector polarity (-)	6				7				8				9				A				B				C				D	od8x	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid	E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop	F	zrtn	Zero point return direction: CCW	Zero point return direction: CW	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																										
zrtn	ptyp	od8x																																																																																																															
7	6	5	4	3	2	1	0																																																																																																										
		fdir	cdir	pyfx			fclx																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	fclx	Closed loop	Semi-closed loop																																																																																																														
1																																																																																																																	
2																																																																																																																	
3	pyfx	Normal excitation	Position loop excitation fixed (strong)																																																																																																														
4	cdir	Command polarity (+)	Command polarity (-)																																																																																																														
5	fdir	Position detector polarity (+)	Position detector polarity (-)																																																																																																														
6																																																																																																																	
7																																																																																																																	
8																																																																																																																	
9																																																																																																																	
A																																																																																																																	
B																																																																																																																	
C																																																																																																																	
D	od8x	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid																																																																																																														
E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop																																																																																																														
F	zrtn	Zero point return direction: CCW	Zero point return direction: CW																																																																																																														
3394 (PR)	SP194	VGTP	Synchronous tapping speed loop gain proportional term	Set the speed loop proportional gain in synchronous tapping mode.	0 to 1000 (1/s)	63																																																																																																											
3395 (PR)	SP195	VGTI	Synchronous tapping speed loop gain integral term	Set the speed loop integral gain in synchronous tapping mode.	0 to 1000 (0.1 1/s)	60																																																																																																											
3396 (PR)	SP196	VGTD	Synchronous tapping speed loop gain delay advance term	Set the speed loop delay advance gain in synchronous tapping mode. When this parameter is set to "0", PI control is exercised.	0 to 1000 (0.1 1/s)	15																																																																																																											
3397	SP197			Not used. Set to "0".	0	0																																																																																																											
3398 (PR)	SP198	VCGT	Target value of variable speed loop proportional gain at synchronous tapping	Set the magnification of speed loop proportional gain with respect to SP194 (VGTP) at the maximum motor speed defined in SP017 (TSP) at synchronous tapping.	0 to 100 (%)	100																																																																																																											

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting
3399 (PR)	SP199	VCST	Change starting speed of variable speed loop proportional gain at synchronous tapping. 	0 to 32767 (r/min)	0
3400 (PR)	SP200	FFC1	Synchronous tapping acceleration feed forward gain (gear 1)	0 to 1000 (%)	0
3401 (PR)	SP201	FFC2	Synchronous tapping acceleration feed forward gain (gear 2)	0 to 1000 (%)	0
3402 (PR)	SP202	FFC3	Synchronous tapping acceleration feed forward gain (gear 3)	0 to 1000 (%)	0
3403 (PR)	SP203	FFC4	Synchronous tapping acceleration feed forward gain (gear 4)	0 to 1000 (%)	0
3404 to 3413	SP204 to SP213		Not used. Set to "0".	0	0
3414	SP214	TZRN	Synchronous tapping zero point return speed This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the zero point return speed used when the speed loop changes to the position loop.	0 to 500 (r/min)	50
3415	SP215	TPDT	Synchronous tapping zero point return deceleration rate This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the deceleration rate where the machine starts to decelerate when it returns to the target stop point during synchronous tapping zero point return. When the machine tends to overshoot at the stop point set a smaller value.	1 to 10000 (pulse)	1
3416	SP216	TPST	Synchronous tapping zero point return shift amount This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the synchronous tapping zero point position.	0 to 4095	0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items		Details	Setting range	Standard setting	
3417	SP217	TINP	Synchronous tapping in-position width	Set the position error range in which in-position signal is output during synchronize tapping.	1 to 2880 (1/16°)	16
3418 (PR)	SP218	TODR	Excessive error width at synchronous tapping	Set the excessive error width at synchronous tapping.	1 to 32767 (pulse) (1 pulse =0.088°)	32767
3419 (PR)	SP219	IQGT	Current loop gain magnification 1 at synchronous tapping	Set the magnification of current loop gain (torque component) during synchronous tapping.	1 to 1000 (%)	100
3420 (PR)	SP220	IDGT	Current loop gain magnification 2 at synchronous tapping	Set the magnification of current loop gain (excitation component) during synchronous tapping.	1 to 1000 (%)	100
3421 to 3424	SP221 to SP224			Not used. Set to "0".	0	0
3425	SP225	OXKPH	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3426	SP226	OXKPL				
3427	SP227	OXVKP				
3428	SP228	OXVKI				
3429	SP229	OXSFT				
3430	SP230					
3431	SP231					
3432	SP232					
3433 (PR)	SP233	JL				

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items			Details	Setting range	Standard setting
3434 (PR)	SP234	OBS1	Disturbance observer low path filter frequency	Set the frequency of the low path filter for when the disturbance observer is valid. Setting $(1/s) = 2\pi f$ f: Approx. 1.5 times the disturbance frequency	0 to 1000 (1/s)	0
3435 (PR)	SP235	OBS2	Disturbance observer gain	Set the gain for the disturbance observer.	0 to 500 (%)	0
3436 to 3452	SP236 to SP252			Not used. Set to "0".	0	0
3453	SP253	DA1NO	D/A output channel 1 data number	Set the output data number for channel 1 of the D/A output function. When the setting value is "0", the output is speedometer. Refer to "8.5.1 D/A OUTPUT SPESIFICATIONS".	-32768 to 32767	0
3454	SP254	DA2NO	D/A output channel 2 data number	Set the output data number for channel 2 of the D/A output function. When the setting value is "0", the output is load meter. Refer to "8.5.1 D/A OUTPUT SPESIFICATIONS".	-32768 to 32767	0
3455	SP255	DA1MPY	DA output channel 1 magnification	Set the data magnification for channel 1 of the D/A output function. The output magnification is (setting value)/256. When set to "0", the output magnification becomes 1-fold, in the same manner as when "256" is set. Refer to "8.5.1 D/A OUTPUT SPESIFICATIONS".	-32768 to 32767 (1/256-fold)	0
3456	SP256	DA2MPY	DA output channel 2 magnification	Set the data magnification for channel 2 of the D/A output function. The output magnification is (setting value)/256. When set to "0", the output magnification becomes 1-fold, in the same manner as when "256" is set. Refer to "8.5.1 D/A OUTPUT SPESIFICATIONS".	-32768 to 32767 (1/256-fold)	0

8. Spindle Parameters
8.2 MDS-B-SPJ2

No.	Items			Details	Setting range	Standard setting
3457 (PR) to 3520 (PR)	SP257 to SP320	RPM BSD	Motor constant (H coil)	<p>This parameter is valid only in the following two conditional cases:</p> <p>(a) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=0 Set the motor constants when using a special motor, not described in the SP040 (MTYP) explanation and when not using the coil changeover motor.</p> <p>(b) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=1 Set the motor constant of the H coil of the coil changeover motor.</p> <p>(Note) It is not allowed for the user to change the setting.</p>	0000 to FFFF HEX setting	0000
3521 (PR) to 3584 (PR)	SP321 to SP384	RPML BSDL	Motor constant (L coil)	<p>This parameter is valid only in the following conditional case:</p> <p>(a) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=1 Set the motor constant of the L coil of the coil changeover motor.</p> <p>(Note) It is not allowed for the user to change the setting.</p>	0000 to FFFF HEX setting	0000

8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

The spindle parameter setting and display method will differ according to the NC being used, so refer to Instruction Manual for each NC and the following spindles.

MELDAS AC Servo and Spindle MDS-A Series MDS-B Series Specifications Manual BNP-B3759
MELDAS AC Servo and Spindle MDS-C1 Series Specifications Manual BNP-C3000

For parameters marked with a (PR) in the tables, turn the NC power OFF after setting. The parameters will be valid after the power is turned ON again.

The "fixed control constants" and "fixed control bits" in this section are set by Mitsubishi.

⚠ CAUTION

⚠ Do not make remarkable adjustments or changes of the parameters as the operation may become unstable.

⚠ In the explanation on bits, set all bits not used, including blank bits, to "0".

No.	Items		Details	Setting range	Standard setting
3201	SP001	PGM Magnetic sensor and motor built-in encoder orientation position loop gain	As the set value is larger, the orientation time becomes shorter and servo rigidity is increased. However, vibration is increased and the machine becomes likely to overshoot.	0 to 1000 (0.1 1/s)	100
3202	SP002	PGE Encoder orientation position loop gain	As the set value is larger, the orientation time becomes shorter and servo rigidity is increased. However, vibration is increased and the machine becomes likely to overshoot.	0 to 1000 (0.1 1/s)	100
3203	SP003	PGC0 C-axis non-cutting position loop gain	Set the position loop gain in C-axis non-cutting mode. During non-cutting (rapid traverse, etc.) with the C axis control, this position loop gain setting is valid.	1 to 100 (1/s)	15
3204	SP004	OINP Orientation in-position width	Set the position error range in which an orientation completion signal is output.	1 to 2880 (1/16 °)	16
3205 (PR)	SP005	OSP Orientation mode changing speed limit value	Set the motor speed limit value to be used when the speed loop is changed to the position loop in orientation mode. When this parameter is set to "0", SP017 (TSP) becomes the limit value.	0 to 32767 (r/min)	0
3206	SP006	CSP Orientation mode deceleration rate	As the set value is larger, the orientation time becomes shorter. However, the machine becomes likely to overshoot.	1 to 1000	20

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3207	SP007	OPST	In-position shift amount for orientation	Set the stop position for orientation. (i)Motor built-in encoder, encoder: Set the value by dividing 360° by 4096. (ii)Magnetic sensor: Divide -5° to +5° by 1024 and put 0° for 0.	(i) 0 to 4095 (ii) -512 to 512	0
3208	SP008			Not used. Set to "0".	0	0
3209	SP009	PGT	Synchronized tapping Position loop gain	Set the spindle position loop gain in synchronized tapping mode.	1 to 100 (1/s)	15
3210	SP010	PGS	Spindle synchronous position loop gain	Set the spindle position loop gain in spindle synchronization mode.	1 to 100 (1/s)	15
3211 to 3216	SP011 to SP016			Use not possible.	0	0
3217 (PR)	SP017	TSP	Maximum motor speed	Set the maximum motor speed of the spindle.	1 to 32767 (r/min)	6000
3218 (PR)	SP018	ZSP	Motor zero speed	Set the motor speed for which zero-speed output is performed.	1 to 1000 (r/min)	50
3219 (PR)	SP019	CSN1	Speed cushion 1	Set the time constant for a speed command from "0" to the maximum speed. (This parameter is invalid in position loop mode.)	1 to 32767 (10ms)	30
3220 (PR)	SP020	SDTS	Speed detection set value	Set the motor speed so for which speed detection output is performed. Usually, the setting value is 10% of SP017 (TSP).	0 to 32767 (r/min)	600
3221	SP021	TLM1	Torque limit 1	Set the torque limit rate for torque limit signal 001.	0 to 120 (%)	10
3222 (PR)	SP022	VGNP1	Speed loop gain proportional term under speed control	Set the speed loop proportional gain in speed control mode. When the gain is increased, response is improved but vibration and sound become larger.	0 to 1000 (1/s)	63
3223 (PR)	SP023	VGNI1	Speed loop gain integral term under speed control	Set the speed loop integral gain in speed control mode. Usually, set a value in proportion to SP022 (VGNP1).	0 to 1000 (0.1 1/s)	60

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items			Details	Setting range	Standard setting
3224	SP024			Use not possible.	0	0
3225 (PR)	SP025	GRA1	Spindle gear teeth count 1	Set the number of gear teeth of the spindle corresponding to gear 000.	1 to 32767	1
3226 (PR)	SP026	GRA2	Spindle gear teeth count 2	Set the number of gear teeth of the spindle corresponding to gear 001.	1 to 32767	1
3227 (PR)	SP027	GRA3	Spindle gear teeth count 3	Set the number of gear teeth of the spindle corresponding to gear 010.	1 to 32767	1
3228 (PR)	SP028	GRA4	Spindle gear teeth count 4	Set the number of gear teeth of the spindle corresponding to gear 011.	1 to 32767	1
3229 (PR)	SP029	GRB1	Motor shaft gear teeth count 1	Set the number of gear teeth of the motor shaft corresponding to gear 000.	1 to 32767	1
3230 (PR)	SP030	GRB2	Motor shaft gear teeth count 2	Set the number of gear teeth of the motor shaft corresponding to gear 001.	1 to 32767	1
3231 (PR)	SP031	GRB3	Motor shaft gear teeth count 3	Set the number of gear teeth of the motor shaft corresponding to gear 010.	1 to 32767	1
3232 (PR)	SP032	GRB4	Motor shaft gear teeth count 4	Set the number of gear teeth of the motor shaft corresponding to gear 011.	1 to 32767	1

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																												
3233 (PR)	SP033	SFNC1 Spindle function 1	<p>Set the spindle function 1 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>poff</td><td>hzs</td><td></td><td>ront</td><td></td><td></td><td>pycal</td><td>pychg</td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td>pyst</td><td>pyoff</td><td></td><td></td><td></td><td>sftk</td><td>dflt</td><td>1a2m</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>1a2m</td> <td>1 amplifier 2 motor function: Invalid</td> <td>1 amplifier 2 motor function: Valid</td> </tr> <tr> <td>1</td> <td>dflt</td> <td>Default motor: Main</td> <td>Default motor: Sub</td> </tr> <tr> <td>2</td> <td>sftk</td> <td>SF-TK card invalid</td> <td>SF-TK card valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td>pyoff</td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td>7</td> <td>pyst</td> <td colspan="2"></td> </tr> <tr> <td>8</td> <td>pychg</td> <td colspan="2"></td> </tr> <tr> <td>9</td> <td>pycal</td> <td>(Conventional specifications)</td> <td>High-speed rate deceleration method valid for minimum excitation rate</td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td>C</td> <td>ront</td> <td>Normal ready ON</td> <td>High-speed ready ON</td> </tr> <tr> <td>D</td> <td></td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td>E</td> <td>hzs</td> <td>Gate OFF by high-cycle zero speed invalid</td> <td>Gate OFF by high-cycle zero speed valid</td> </tr> <tr> <td>F</td> <td>poff</td> <td>Contactorm hold at NC power OFF invalid</td> <td>Contactorm hold at NC power OFF valid</td> </tr> </tbody> </table> <p>(Note) When SPH is used, bit 0 and bit 1 will be invalid.</p>	F	E	D	C	B	A	9	8	poff	hzs		ront			pycal	pychg									7	6	5	4	3	2	1	0	pyst	pyoff				sftk	dflt	1a2m	bit	Name	Meaning when set to 0	Meaning when set to 1	0	1a2m	1 amplifier 2 motor function: Invalid	1 amplifier 2 motor function: Valid	1	dflt	Default motor: Main	Default motor: Sub	2	sftk	SF-TK card invalid	SF-TK card valid	3				4				5				6	pyoff	This is used by Mitsubishi. Set to "0" unless particularly designated.		7	pyst			8	pychg			9	pycal	(Conventional specifications)	High-speed rate deceleration method valid for minimum excitation rate	A				B		This is used by Mitsubishi. Set to "0" unless particularly designated.		C	ront	Normal ready ON	High-speed ready ON	D		This is used by Mitsubishi. Set to "0" unless particularly designated.		E	hzs	Gate OFF by high-cycle zero speed invalid	Gate OFF by high-cycle zero speed valid	F	poff	Contactorm hold at NC power OFF invalid	Contactorm hold at NC power OFF valid	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																										
poff	hzs		ront			pycal	pychg																																																																																																										
7	6	5	4	3	2	1	0																																																																																																										
pyst	pyoff				sftk	dflt	1a2m																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	1a2m	1 amplifier 2 motor function: Invalid	1 amplifier 2 motor function: Valid																																																																																																														
1	dflt	Default motor: Main	Default motor: Sub																																																																																																														
2	sftk	SF-TK card invalid	SF-TK card valid																																																																																																														
3																																																																																																																	
4																																																																																																																	
5																																																																																																																	
6	pyoff	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																															
7	pyst																																																																																																																
8	pychg																																																																																																																
9	pycal	(Conventional specifications)	High-speed rate deceleration method valid for minimum excitation rate																																																																																																														
A																																																																																																																	
B		This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																															
C	ront	Normal ready ON	High-speed ready ON																																																																																																														
D		This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																															
E	hzs	Gate OFF by high-cycle zero speed invalid	Gate OFF by high-cycle zero speed valid																																																																																																														
F	poff	Contactorm hold at NC power OFF invalid	Contactorm hold at NC power OFF valid																																																																																																														

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																				
3234 (PR)	SP034	SFNC2 Spindle function 2	<p>Set the spindle function 2 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td> </td><td> </td><td> </td><td> </td><td>mkc2</td><td>mkch</td><td>invm</td><td>mts1</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>mts1</td> <td>Special motor constant invalid</td> <td>Special motor constant setting valid</td> </tr> <tr> <td>1</td> <td>invm</td> <td>A general-purpose motor FV control invalid</td> <td>A general-purpose motor FV control valid</td> </tr> <tr> <td>2</td> <td>mkch</td> <td>Coil switch function invalid</td> <td>Coil switch function valid</td> </tr> <tr> <td>3</td> <td>mkc2</td> <td>Coil switch specification 2 invalid</td> <td>Coil switch specification 2 valid (Note1) (Note2)</td> </tr> <tr><td>4</td><td> </td><td> </td><td> </td></tr> <tr><td>5</td><td> </td><td> </td><td> </td></tr> <tr><td>6</td><td> </td><td> </td><td> </td></tr> <tr><td>7</td><td> </td><td> </td><td> </td></tr> <tr><td>8</td><td> </td><td> </td><td> </td></tr> <tr><td>9</td><td> </td><td> </td><td> </td></tr> <tr><td>A</td><td> </td><td> </td><td> </td></tr> <tr><td>B</td><td> </td><td> </td><td> </td></tr> <tr><td>C</td><td> </td><td> </td><td> </td></tr> <tr><td>D</td><td> </td><td> </td><td> </td></tr> <tr><td>E</td><td> </td><td> </td><td> </td></tr> <tr><td>F</td><td> </td><td> </td><td> </td></tr> </tbody> </table> <p>(Note1) To validate bit3(mkc2), NC side needs to prepare. (Note2) Always turn the bit2 at the same time to use bit3.</p>	F	E	D	C	B	A	9	8									7	6	5	4	3	2	1	0					mkc2	mkch	invm	mts1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	mts1	Special motor constant invalid	Special motor constant setting valid	1	invm	A general-purpose motor FV control invalid	A general-purpose motor FV control valid	2	mkch	Coil switch function invalid	Coil switch function valid	3	mkc2	Coil switch specification 2 invalid	Coil switch specification 2 valid (Note1) (Note2)	4				5				6				7				8				9				A				B				C				D				E				F				0000 to FFFF HEX setting	000C
F	E	D	C	B	A	9	8																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
				mkc2	mkch	invm	mts1																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	mts1	Special motor constant invalid	Special motor constant setting valid																																																																																																						
1	invm	A general-purpose motor FV control invalid	A general-purpose motor FV control valid																																																																																																						
2	mkch	Coil switch function invalid	Coil switch function valid																																																																																																						
3	mkc2	Coil switch specification 2 invalid	Coil switch specification 2 valid (Note1) (Note2)																																																																																																						
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8																																																																																																									
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									
3235 (PR)	SP035	SFNC3 Spindle function 3	<p>Set the spindle function 3 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td> </td><td> </td><td> </td><td> </td><td>lbsd</td><td>hbsd</td><td>lwid</td><td>hwid</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>hwid</td> <td>H-coil wide-range constant output invalid</td> <td>H-coil wide-range constant output valid</td> </tr> <tr> <td>1</td> <td>lwid</td> <td>L-coil wide-range constant output invalid</td> <td>L-coil wide-range constant output valid</td> </tr> <tr> <td>2</td> <td>hbsd</td> <td>H-coil base slide invalid</td> <td>H-coil base slide valid</td> </tr> <tr> <td>3</td> <td>lbsd</td> <td>L-coil base slide invalid</td> <td>L-coil base slide valid</td> </tr> <tr><td>4</td><td> </td><td> </td><td> </td></tr> <tr><td>5</td><td> </td><td> </td><td> </td></tr> <tr><td>6</td><td> </td><td> </td><td> </td></tr> <tr><td>7</td><td> </td><td> </td><td> </td></tr> <tr> <td>8</td> <td> </td> <td>(Used with SPJ.)</td> <td> </td> </tr> <tr><td>9</td><td> </td><td> </td><td> </td></tr> <tr><td>A</td><td> </td><td> </td><td> </td></tr> <tr><td>B</td><td> </td><td> </td><td> </td></tr> <tr><td>C</td><td> </td><td> </td><td> </td></tr> <tr><td>D</td><td> </td><td> </td><td> </td></tr> <tr><td>E</td><td> </td><td> </td><td> </td></tr> <tr><td>F</td><td> </td><td> </td><td> </td></tr> </tbody> </table>	F	E	D	C	B	A	9	8									7	6	5	4	3	2	1	0					lbsd	hbsd	lwid	hwid	bit	Name	Meaning when set to 0	Meaning when set to 1	0	hwid	H-coil wide-range constant output invalid	H-coil wide-range constant output valid	1	lwid	L-coil wide-range constant output invalid	L-coil wide-range constant output valid	2	hbsd	H-coil base slide invalid	H-coil base slide valid	3	lbsd	L-coil base slide invalid	L-coil base slide valid	4				5				6				7				8		(Used with SPJ.)		9				A				B				C				D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
				lbsd	hbsd	lwid	hwid																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	hwid	H-coil wide-range constant output invalid	H-coil wide-range constant output valid																																																																																																						
1	lwid	L-coil wide-range constant output invalid	L-coil wide-range constant output valid																																																																																																						
2	hbsd	H-coil base slide invalid	H-coil base slide valid																																																																																																						
3	lbsd	L-coil base slide invalid	L-coil base slide valid																																																																																																						
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8		(Used with SPJ.)																																																																																																							
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																					
3236 (PR)	SP036	SFNC4	Spindle function 4	<p>Set the spindle function 4 in bit units.</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:12.5%; text-align:center;">F</td><td style="width:12.5%; text-align:center;">E</td><td style="width:12.5%; text-align:center;">D</td><td style="width:12.5%; text-align:center;">C</td><td style="width:12.5%; text-align:center;">B</td><td style="width:12.5%; text-align:center;">A</td><td style="width:12.5%; text-align:center;">9</td><td style="width:12.5%; text-align:center;">8</td> </tr> <tr> <td style="width:12.5%;"></td><td style="width:12.5%;"></td><td style="width:12.5%;"></td><td style="width:12.5%;"></td><td style="width:12.5%;"></td><td style="width:12.5%;"></td><td style="width:12.5%; text-align:center;">dslm</td><td style="width:12.5%; text-align:center;">dssm</td> </tr> </table> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:12.5%; text-align:center;">7</td><td style="width:12.5%; text-align:center;">6</td><td style="width:12.5%; text-align:center;">5</td><td style="width:12.5%; text-align:center;">4</td><td style="width:12.5%; text-align:center;">3</td><td style="width:12.5%; text-align:center;">2</td><td style="width:12.5%; text-align:center;">1</td><td style="width:12.5%; text-align:center;">0</td> </tr> <tr> <td style="width:12.5%;"></td><td style="width:12.5%;"></td><td style="width:12.5%; text-align:center;">enc2</td><td style="width:12.5%; text-align:center;">enc1</td><td style="width:12.5%; text-align:center;">mag2</td><td style="width:12.5%; text-align:center;">mag1</td><td style="width:12.5%; text-align:center;">plg2</td><td style="width:12.5%; text-align:center;">plg1</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:5%;">bit</th> <th style="width:15%;">Name</th> <th style="width:40%;">Meaning when set to 0</th> <th style="width:40%;">Meaning when set to 1</th> </tr> </thead> <tbody> <tr><td>0</td><td>plg1</td><td>PLG of motor 1 valid</td><td>PLG of motor 1 invalid</td></tr> <tr><td>1</td><td>plg2</td><td>PLG of motor 2 valid</td><td>PLG of motor 2 invalid</td></tr> <tr><td>2</td><td>mag1</td><td>MAG of motor 1 valid</td><td>MAG of motor 1 invalid</td></tr> <tr><td>3</td><td>mag2</td><td>MAG of motor 2 valid</td><td>MAG of motor 2 invalid</td></tr> <tr><td>4</td><td>enc1</td><td>ENC of motor 1 valid</td><td>ENC of motor 1 invalid</td></tr> <tr><td>5</td><td>enc2</td><td>ENC of motor 2 valid</td><td>ENC of motor 2 invalid</td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td>dssm</td><td>Speedometer output valid</td><td>Speedometer output invalid</td></tr> <tr><td>9</td><td>dslm</td><td>Load meter output valid</td><td>Load meter output invalid</td></tr> <tr><td>A</td><td></td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td><td></td></tr> <tr><td>E</td><td></td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td><td></td></tr> </tbody> </table>	F	E	D	C	B	A	9	8							dslm	dssm	7	6	5	4	3	2	1	0			enc2	enc1	mag2	mag1	plg2	plg1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	plg1	PLG of motor 1 valid	PLG of motor 1 invalid	1	plg2	PLG of motor 2 valid	PLG of motor 2 invalid	2	mag1	MAG of motor 1 valid	MAG of motor 1 invalid	3	mag2	MAG of motor 2 valid	MAG of motor 2 invalid	4	enc1	ENC of motor 1 valid	ENC of motor 1 invalid	5	enc2	ENC of motor 2 valid	ENC of motor 2 invalid	6				7				8	dssm	Speedometer output valid	Speedometer output invalid	9	dslm	Load meter output valid	Load meter output invalid	A				B				C				D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																			
						dslm	dssm																																																																																																			
7	6	5	4	3	2	1	0																																																																																																			
		enc2	enc1	mag2	mag1	plg2	plg1																																																																																																			
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																							
0	plg1	PLG of motor 1 valid	PLG of motor 1 invalid																																																																																																							
1	plg2	PLG of motor 2 valid	PLG of motor 2 invalid																																																																																																							
2	mag1	MAG of motor 1 valid	MAG of motor 1 invalid																																																																																																							
3	mag2	MAG of motor 2 valid	MAG of motor 2 invalid																																																																																																							
4	enc1	ENC of motor 1 valid	ENC of motor 1 invalid																																																																																																							
5	enc2	ENC of motor 2 valid	ENC of motor 2 invalid																																																																																																							
6																																																																																																										
7																																																																																																										
8	dssm	Speedometer output valid	Speedometer output invalid																																																																																																							
9	dslm	Load meter output valid	Load meter output invalid																																																																																																							
A																																																																																																										
B																																																																																																										
C																																																																																																										
D																																																																																																										
E																																																																																																										
F																																																																																																										
3237 (PR)	SP037	SFNC5	Spindle function 5	<p>Set the spindle function 5 in bit units.</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:12.5%; text-align:center;">F</td><td style="width:12.5%; text-align:center;">E</td><td style="width:12.5%; text-align:center;">D</td><td style="width:12.5%; text-align:center;">C</td><td style="width:12.5%; text-align:center;">B</td><td style="width:12.5%; text-align:center;">A</td><td style="width:12.5%; text-align:center;">9</td><td style="width:12.5%; text-align:center;">8</td> </tr> <tr> <td style="width:12.5%; text-align:center;">splg</td><td style="width:12.5%; text-align:center;">dplg</td><td style="width:12.5%;"></td><td style="width:12.5%;"></td><td style="width:12.5%;"></td><td style="width:12.5%; text-align:center;">noplg</td><td style="width:12.5%; text-align:center;">nsno</td><td style="width:12.5%; text-align:center;">nosg</td> </tr> </table> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:12.5%; text-align:center;">7</td><td style="width:12.5%; text-align:center;">6</td><td style="width:12.5%; text-align:center;">5</td><td style="width:12.5%; text-align:center;">4</td><td style="width:12.5%; text-align:center;">3</td><td style="width:12.5%; text-align:center;">2</td><td style="width:12.5%; text-align:center;">1</td><td style="width:12.5%; text-align:center;">0</td> </tr> <tr> <td style="width:12.5%;"></td><td style="width:12.5%;"></td><td style="width:12.5%;"></td><td style="width:12.5%;"></td><td style="width:12.5%;"></td><td style="width:12.5%; text-align:center;">plgo</td><td style="width:12.5%; text-align:center;">mago</td><td style="width:12.5%; text-align:center;">enco</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:5%;">bit</th> <th style="width:15%;">Name</th> <th style="width:40%;">Meaning when set to 0</th> <th style="width:40%;">Meaning when set to 1</th> </tr> </thead> <tbody> <tr><td>0</td><td>enco</td><td>Encoder orientation invalid</td><td>Encoder orientation valid</td></tr> <tr><td>1</td><td>mago</td><td>Magnetic sensor orientation invalid</td><td>Magnetic sensor orientation valid</td></tr> <tr><td>2</td><td>plgo</td><td>PLG orientation invalid</td><td>PLG orientation valid</td></tr> <tr><td>3</td><td></td><td></td><td></td></tr> <tr><td>4</td><td></td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td>nosg</td><td>No-signal detection type (Always monitoring)</td><td>Monitoring only in position loop or orientation-mode</td></tr> <tr><td>9</td><td>nsno</td><td>No-signal detection valid</td><td>No-signal detection invalid</td></tr> <tr><td>A</td><td>noplg</td><td>Constant monitor of PLG-Z phase no-signal invalid</td><td>Constant monitor of PLG-Z phase no-signal valid</td></tr> <tr><td>B</td><td></td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td><td></td></tr> <tr><td>E</td><td>dplg</td><td colspan="2">This is used by Mitsubishi.</td></tr> <tr><td>F</td><td>splg</td><td colspan="2">Set to "0" unless particularly designated.</td></tr> </tbody> </table> <p>(Note) For bit0 to 2, do not set two bits or more to "1" at the same time.</p>	F	E	D	C	B	A	9	8	splg	dplg				noplg	nsno	nosg	7	6	5	4	3	2	1	0						plgo	mago	enco	bit	Name	Meaning when set to 0	Meaning when set to 1	0	enco	Encoder orientation invalid	Encoder orientation valid	1	mago	Magnetic sensor orientation invalid	Magnetic sensor orientation valid	2	plgo	PLG orientation invalid	PLG orientation valid	3				4				5				6				7				8	nosg	No-signal detection type (Always monitoring)	Monitoring only in position loop or orientation-mode	9	nsno	No-signal detection valid	No-signal detection invalid	A	noplg	Constant monitor of PLG-Z phase no-signal invalid	Constant monitor of PLG-Z phase no-signal valid	B				C				D				E	dplg	This is used by Mitsubishi.		F	splg	Set to "0" unless particularly designated.		0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																			
splg	dplg				noplg	nsno	nosg																																																																																																			
7	6	5	4	3	2	1	0																																																																																																			
					plgo	mago	enco																																																																																																			
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																							
0	enco	Encoder orientation invalid	Encoder orientation valid																																																																																																							
1	mago	Magnetic sensor orientation invalid	Magnetic sensor orientation valid																																																																																																							
2	plgo	PLG orientation invalid	PLG orientation valid																																																																																																							
3																																																																																																										
4																																																																																																										
5																																																																																																										
6																																																																																																										
7																																																																																																										
8	nosg	No-signal detection type (Always monitoring)	Monitoring only in position loop or orientation-mode																																																																																																							
9	nsno	No-signal detection valid	No-signal detection invalid																																																																																																							
A	noplg	Constant monitor of PLG-Z phase no-signal invalid	Constant monitor of PLG-Z phase no-signal valid																																																																																																							
B																																																																																																										
C																																																																																																										
D																																																																																																										
E	dplg	This is used by Mitsubishi.																																																																																																								
F	splg	Set to "0" unless particularly designated.																																																																																																								

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																																																																																																
3238 (PR)	SP038	SFNC6 Spindle function 6	<p>Set the spindle function 6 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>oplp</td><td>lmx</td><td>iqsv</td><td>XFzs</td><td>dcsn</td><td>lmnp</td><td>pl80</td><td>sdt2</td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td>vfbs</td><td>orm</td><td>adin</td><td>tdn</td><td>plg2</td><td>pftm</td><td></td><td>alty</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <p>For MDS-C1-SP/SPH</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>alty</td> <td>Deceleration stop during special alarm invalid</td> <td>Deceleration stop during special alarm valid</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>pftm</td> <td>Encoder feedback serial communication invalid</td> <td>Encoder feedback serial communication valid</td> </tr> <tr> <td>3</td> <td>plg2</td> <td>Semi-closed pulse output signal ×2 invalid</td> <td>Semi-closed pulse output signal ×2 valid</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td>adin</td> <td>Interpolation during thread cutting invalid</td> <td>Interpolation during thread cutting valid</td> </tr> <tr> <td>6</td> <td>orm</td> <td>Orientation start memo invalid</td> <td>Orientation start memo valid</td> </tr> <tr> <td>7</td> <td>vfbs</td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td>8</td> <td>sdt2</td> <td>(Follows SFNC6-bitC setting)</td> <td>Set output 2 to 2nd speed detection output</td> </tr> <tr> <td>9</td> <td>pl80</td> <td>MHE90K detector's 180 wave PLG</td> <td>180 wave PLG other than MHE90K</td> </tr> <tr> <td>A</td> <td>lmnp</td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td>B</td> <td>dcsn</td> <td>Dual cushion during acceleration/ deceleration valid</td> <td>Dual cushion during acceleration/ deceleration invalid</td> </tr> <tr> <td>C</td> <td>XFzs</td> <td>Set output 2 to MP scale low (L) speed mode</td> <td>Set output 2 to zero speed output</td> </tr> <tr> <td>D</td> <td>iqsv</td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated</td> </tr> <tr> <td>E</td> <td>lmx</td> <td colspan="2"></td> </tr> <tr> <td>F</td> <td>oplp</td> <td>Open loop operation invalid</td> <td>Open loop operation valid</td> </tr> </tbody> </table> <p>For MDS-B-SP/SPH</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>alty</td> <td>Deceleration stop during special alarm invalid</td> <td>Deceleration stop during special alarm valid</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>pftm</td> <td>Encoder feedback serial communication invalid</td> <td>Encoder feedback serial communication valid</td> </tr> <tr> <td>3</td> <td>plg2</td> <td>Semi-closed pulse output signal ×2 invalid</td> <td>Semi-closed pulse output signal ×2 valid</td> </tr> <tr> <td>4</td> <td>tdn</td> <td colspan="2">Fixed control bit</td> </tr> <tr> <td>5</td> <td>adin</td> <td colspan="2"></td> </tr> <tr> <td>6</td> <td>orm</td> <td>Orientation start memo invalid</td> <td>Orientation start memo valid</td> </tr> <tr> <td>7</td> <td>vfbs</td> <td colspan="2"></td> </tr> <tr> <td>8</td> <td>sdt2</td> <td colspan="2"></td> </tr> <tr> <td>9</td> <td>pl80</td> <td colspan="2"></td> </tr> <tr> <td>A</td> <td>lmnp</td> <td colspan="2">Fixed control bit</td> </tr> <tr> <td>B</td> <td>dcsn</td> <td colspan="2"></td> </tr> <tr> <td>C</td> <td>XFzs</td> <td colspan="2"></td> </tr> <tr> <td>D</td> <td>iqsv</td> <td colspan="2"></td> </tr> <tr> <td>E</td> <td>lmx</td> <td colspan="2"></td> </tr> <tr> <td>F</td> <td>oplp</td> <td>Open loop operation invalid</td> <td>Open loop operation valid</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	oplp	lmx	iqsv	XFzs	dcsn	lmnp	pl80	sdt2									7	6	5	4	3	2	1	0	vfbs	orm	adin	tdn	plg2	pftm		alty	bit	Name	Meaning when set to 0	Meaning when set to 1	0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid	1				2	pftm	Encoder feedback serial communication invalid	Encoder feedback serial communication valid	3	plg2	Semi-closed pulse output signal ×2 invalid	Semi-closed pulse output signal ×2 valid	4				5	adin	Interpolation during thread cutting invalid	Interpolation during thread cutting valid	6	orm	Orientation start memo invalid	Orientation start memo valid	7	vfbs	This is used by Mitsubishi. Set to "0" unless particularly designated.		8	sdt2	(Follows SFNC6-bitC setting)	Set output 2 to 2nd speed detection output	9	pl80	MHE90K detector's 180 wave PLG	180 wave PLG other than MHE90K	A	lmnp	This is used by Mitsubishi. Set to "0" unless particularly designated.		B	dcsn	Dual cushion during acceleration/ deceleration valid	Dual cushion during acceleration/ deceleration invalid	C	XFzs	Set output 2 to MP scale low (L) speed mode	Set output 2 to zero speed output	D	iqsv	This is used by Mitsubishi. Set to "0" unless particularly designated		E	lmx			F	oplp	Open loop operation invalid	Open loop operation valid	bit	Name	Meaning when set to 0	Meaning when set to 1	0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid	1				2	pftm	Encoder feedback serial communication invalid	Encoder feedback serial communication valid	3	plg2	Semi-closed pulse output signal ×2 invalid	Semi-closed pulse output signal ×2 valid	4	tdn	Fixed control bit		5	adin			6	orm	Orientation start memo invalid	Orientation start memo valid	7	vfbs			8	sdt2			9	pl80			A	lmnp	Fixed control bit		B	dcsn			C	XFzs			D	iqsv			E	lmx			F	oplp	Open loop operation invalid	Open loop operation valid	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																																																																																														
oplp	lmx	iqsv	XFzs	dcsn	lmnp	pl80	sdt2																																																																																																																																																																														
7	6	5	4	3	2	1	0																																																																																																																																																																														
vfbs	orm	adin	tdn	plg2	pftm		alty																																																																																																																																																																														
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																																																																																																		
0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid																																																																																																																																																																																		
1																																																																																																																																																																																					
2	pftm	Encoder feedback serial communication invalid	Encoder feedback serial communication valid																																																																																																																																																																																		
3	plg2	Semi-closed pulse output signal ×2 invalid	Semi-closed pulse output signal ×2 valid																																																																																																																																																																																		
4																																																																																																																																																																																					
5	adin	Interpolation during thread cutting invalid	Interpolation during thread cutting valid																																																																																																																																																																																		
6	orm	Orientation start memo invalid	Orientation start memo valid																																																																																																																																																																																		
7	vfbs	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																																																																																																			
8	sdt2	(Follows SFNC6-bitC setting)	Set output 2 to 2nd speed detection output																																																																																																																																																																																		
9	pl80	MHE90K detector's 180 wave PLG	180 wave PLG other than MHE90K																																																																																																																																																																																		
A	lmnp	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																																																																																																			
B	dcsn	Dual cushion during acceleration/ deceleration valid	Dual cushion during acceleration/ deceleration invalid																																																																																																																																																																																		
C	XFzs	Set output 2 to MP scale low (L) speed mode	Set output 2 to zero speed output																																																																																																																																																																																		
D	iqsv	This is used by Mitsubishi. Set to "0" unless particularly designated																																																																																																																																																																																			
E	lmx																																																																																																																																																																																				
F	oplp	Open loop operation invalid	Open loop operation valid																																																																																																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																																																																																																		
0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid																																																																																																																																																																																		
1																																																																																																																																																																																					
2	pftm	Encoder feedback serial communication invalid	Encoder feedback serial communication valid																																																																																																																																																																																		
3	plg2	Semi-closed pulse output signal ×2 invalid	Semi-closed pulse output signal ×2 valid																																																																																																																																																																																		
4	tdn	Fixed control bit																																																																																																																																																																																			
5	adin																																																																																																																																																																																				
6	orm	Orientation start memo invalid	Orientation start memo valid																																																																																																																																																																																		
7	vfbs																																																																																																																																																																																				
8	sdt2																																																																																																																																																																																				
9	pl80																																																																																																																																																																																				
A	lmnp	Fixed control bit																																																																																																																																																																																			
B	dcsn																																																																																																																																																																																				
C	XFzs																																																																																																																																																																																				
D	iqsv																																																																																																																																																																																				
E	lmx																																																																																																																																																																																				
F	oplp	Open loop operation invalid	Open loop operation valid																																																																																																																																																																																		

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items			Details	Setting range	Standard setting																																				
3239 (PR)	SP039	ATYP	Amplifier type	Set the amplifier type. Set each amplifier type or "0" <table border="1" data-bbox="587 370 1045 981"> <thead> <tr> <th>Parameter setting</th> <th>Amplifier type</th> </tr> </thead> <tbody> <tr><td>0000</td><td>—</td></tr> <tr><td>0001</td><td>SP-075</td></tr> <tr><td>0002</td><td>SP-15</td></tr> <tr><td>0003</td><td>SP-22</td></tr> <tr><td>0004</td><td>SP-37</td></tr> <tr><td>0005</td><td>SP-55</td></tr> <tr><td>0006</td><td>SP-75</td></tr> <tr><td>0007</td><td>SP-110</td></tr> <tr><td>0008</td><td>SP-150</td></tr> <tr><td>0009</td><td>SP-185</td></tr> <tr><td>000A</td><td>SP-220</td></tr> <tr><td>000B</td><td>SP-260</td></tr> <tr><td>000C</td><td>SP-300</td></tr> <tr><td>000D</td><td>SP (H)-370</td></tr> <tr><td>000E</td><td>SP (H)-450</td></tr> <tr><td>000F</td><td>SP-04</td></tr> <tr><td>0010</td><td>SP-550</td></tr> </tbody> </table>	Parameter setting	Amplifier type	0000	—	0001	SP-075	0002	SP-15	0003	SP-22	0004	SP-37	0005	SP-55	0006	SP-75	0007	SP-110	0008	SP-150	0009	SP-185	000A	SP-220	000B	SP-260	000C	SP-300	000D	SP (H)-370	000E	SP (H)-450	000F	SP-04	0010	SP-550	0000 to FFFF HEX setting	0000
Parameter setting	Amplifier type																																									
0000	—																																									
0001	SP-075																																									
0002	SP-15																																									
0003	SP-22																																									
0004	SP-37																																									
0005	SP-55																																									
0006	SP-75																																									
0007	SP-110																																									
0008	SP-150																																									
0009	SP-185																																									
000A	SP-220																																									
000B	SP-260																																									
000C	SP-300																																									
000D	SP (H)-370																																									
000E	SP (H)-450																																									
000F	SP-04																																									
0010	SP-550																																									

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items			Details	Setting range	Standard setting																																																																																																																																				
3240 (PR)	SP040	MTYP	Motor type	<p>This parameter is valid when SP034 (SFNC2) bit0 is set to "0". Set the appropriate motor number from the standard motors listed below.</p> <table border="1" data-bbox="592 446 1102 1462"> <thead> <tr> <th>Parameter setting</th> <th>Motor type</th> <th>Maximum speed</th> <th>Corre-sponding amplifier</th> </tr> </thead> <tbody> <tr><td>0000</td><td></td><td></td><td></td></tr> <tr><td>0001</td><td>SJ-2.2A</td><td>10000 r/min</td><td>SP-22</td></tr> <tr><td>0002</td><td>SJ-3.7A</td><td>10000 r/min</td><td>SP-37</td></tr> <tr><td>0003</td><td>SJ-5.5A</td><td>8000 r/min</td><td>SP-55</td></tr> <tr><td>0004</td><td>SJ-7.5A</td><td>8000 r/min</td><td>SP-75</td></tr> <tr><td>0005</td><td>SJ-11A</td><td>6000 r/min</td><td>SP-110</td></tr> <tr><td>0006</td><td>SJ-15A</td><td>6000 r/min</td><td>SP-150</td></tr> <tr><td>0007</td><td>SJ-18.5A</td><td>6000 r/min</td><td>SP-185</td></tr> <tr><td>0008</td><td>SJ-22A</td><td>4500 r/min</td><td>SP-220</td></tr> <tr><td>0009</td><td>SJ-26A</td><td>4500 r/min</td><td>SP-260</td></tr> <tr><td>000A</td><td>SJ-30A</td><td>4500 r/min</td><td>SP-300</td></tr> <tr><td>000B</td><td></td><td></td><td></td></tr> <tr><td>000C</td><td></td><td></td><td></td></tr> <tr><td>000D</td><td></td><td></td><td></td></tr> <tr><td>000E</td><td></td><td></td><td></td></tr> <tr><td>000F</td><td></td><td></td><td></td></tr> <tr><td>0010</td><td></td><td></td><td></td></tr> <tr><td>0011</td><td>SJ-N0.75A</td><td>10000 r/min</td><td>SP-075</td></tr> <tr><td>0012</td><td>SJ-N1.5A</td><td>10000 r/min</td><td>SP-15</td></tr> <tr><td>0013</td><td>SJ-N2.2A</td><td>10000 r/min</td><td>SP-22</td></tr> <tr><td>0014</td><td>SJ-N3.7A</td><td>10000 r/min</td><td>SP-37</td></tr> <tr><td>0015</td><td>SJ-N5.5A</td><td>8000 r/min</td><td>SP-55</td></tr> <tr><td>0016</td><td>SJ-N7.5A</td><td>8000 r/min</td><td>SP-75</td></tr> <tr><td>0017</td><td></td><td></td><td></td></tr> <tr><td>0018</td><td></td><td></td><td></td></tr> <tr><td>0019</td><td></td><td></td><td></td></tr> <tr><td>001A</td><td></td><td></td><td></td></tr> <tr><td>001B</td><td>SJ-J2.2A</td><td>10000 r/min</td><td>SP-22</td></tr> <tr><td>001C</td><td>SJ-J3.7A</td><td>10000 r/min</td><td>SP-37</td></tr> <tr><td>001D</td><td>SJ-J5.5A</td><td>8000 r/min</td><td>SP-55</td></tr> <tr><td>001E</td><td>SJ-J7.5A</td><td>8000 r/min</td><td>SP-75</td></tr> <tr><td>001F</td><td></td><td></td><td></td></tr> </tbody> </table>	Parameter setting	Motor type	Maximum speed	Corre-sponding amplifier	0000				0001	SJ-2.2A	10000 r/min	SP-22	0002	SJ-3.7A	10000 r/min	SP-37	0003	SJ-5.5A	8000 r/min	SP-55	0004	SJ-7.5A	8000 r/min	SP-75	0005	SJ-11A	6000 r/min	SP-110	0006	SJ-15A	6000 r/min	SP-150	0007	SJ-18.5A	6000 r/min	SP-185	0008	SJ-22A	4500 r/min	SP-220	0009	SJ-26A	4500 r/min	SP-260	000A	SJ-30A	4500 r/min	SP-300	000B				000C				000D				000E				000F				0010				0011	SJ-N0.75A	10000 r/min	SP-075	0012	SJ-N1.5A	10000 r/min	SP-15	0013	SJ-N2.2A	10000 r/min	SP-22	0014	SJ-N3.7A	10000 r/min	SP-37	0015	SJ-N5.5A	8000 r/min	SP-55	0016	SJ-N7.5A	8000 r/min	SP-75	0017				0018				0019				001A				001B	SJ-J2.2A	10000 r/min	SP-22	001C	SJ-J3.7A	10000 r/min	SP-37	001D	SJ-J5.5A	8000 r/min	SP-55	001E	SJ-J7.5A	8000 r/min	SP-75	001F				0000 to FFFF HEX setting	0000
Parameter setting	Motor type	Maximum speed	Corre-sponding amplifier																																																																																																																																							
0000																																																																																																																																										
0001	SJ-2.2A	10000 r/min	SP-22																																																																																																																																							
0002	SJ-3.7A	10000 r/min	SP-37																																																																																																																																							
0003	SJ-5.5A	8000 r/min	SP-55																																																																																																																																							
0004	SJ-7.5A	8000 r/min	SP-75																																																																																																																																							
0005	SJ-11A	6000 r/min	SP-110																																																																																																																																							
0006	SJ-15A	6000 r/min	SP-150																																																																																																																																							
0007	SJ-18.5A	6000 r/min	SP-185																																																																																																																																							
0008	SJ-22A	4500 r/min	SP-220																																																																																																																																							
0009	SJ-26A	4500 r/min	SP-260																																																																																																																																							
000A	SJ-30A	4500 r/min	SP-300																																																																																																																																							
000B																																																																																																																																										
000C																																																																																																																																										
000D																																																																																																																																										
000E																																																																																																																																										
000F																																																																																																																																										
0010																																																																																																																																										
0011	SJ-N0.75A	10000 r/min	SP-075																																																																																																																																							
0012	SJ-N1.5A	10000 r/min	SP-15																																																																																																																																							
0013	SJ-N2.2A	10000 r/min	SP-22																																																																																																																																							
0014	SJ-N3.7A	10000 r/min	SP-37																																																																																																																																							
0015	SJ-N5.5A	8000 r/min	SP-55																																																																																																																																							
0016	SJ-N7.5A	8000 r/min	SP-75																																																																																																																																							
0017																																																																																																																																										
0018																																																																																																																																										
0019																																																																																																																																										
001A																																																																																																																																										
001B	SJ-J2.2A	10000 r/min	SP-22																																																																																																																																							
001C	SJ-J3.7A	10000 r/min	SP-37																																																																																																																																							
001D	SJ-J5.5A	8000 r/min	SP-55																																																																																																																																							
001E	SJ-J7.5A	8000 r/min	SP-75																																																																																																																																							
001F																																																																																																																																										

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																																																																																																							
3241 (PR)	SP041	PTYP Power supply type	<p>Power supply type</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="text-align:center">F</td><td style="text-align:center">E</td><td style="text-align:center">D</td><td style="text-align:center">C</td><td style="text-align:center">B</td><td style="text-align:center">A</td><td style="text-align:center">9</td><td style="text-align:center">8</td> </tr> <tr> <td colspan="4" style="text-align:center">amp</td> <td colspan="4" style="text-align:center">rtyp</td> </tr> <tr> <td style="text-align:center">7</td><td style="text-align:center">6</td><td style="text-align:center">5</td><td style="text-align:center">4</td><td style="text-align:center">3</td><td style="text-align:center">2</td><td style="text-align:center">1</td><td style="text-align:center">0</td> </tr> <tr> <td colspan="8" style="text-align:center">ptyp</td> </tr> </table> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:5%;">bit</th> <th colspan="10">Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td colspan="10" rowspan="3">When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.</td> </tr> <tr> <td>1</td> </tr> <tr> <td>2</td> </tr> <tr> <td>3</td> <td colspan="10"> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:5%;">Set-ting</th> <th style="width:10%;">0x</th> <th style="width:10%;">1x</th> <th style="width:10%;">2x</th> <th style="width:10%;">3x</th> <th style="width:10%;">4x</th> <th style="width:10%;">5x</th> <th style="width:10%;">6x</th> <th style="width:10%;">7x</th> <th style="width:10%;">8x</th> </tr> </thead> <tbody> <tr> <td>x0</td> <td>Not used</td> <td></td> <td></td> <td>CV-300</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x1</td> <td></td> <td>CV-110</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-10</td> </tr> <tr> <td>x2</td> <td></td> <td></td> <td>CV-220</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-15</td> </tr> <tr> <td>x3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-22</td> </tr> <tr> <td>x4</td> <td>CV-37</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-37</td> </tr> <tr> <td>x5</td> <td></td> <td>CV-150</td> <td></td> <td></td> <td>CV-450</td> <td>CV-550</td> <td></td> <td></td> <td></td> </tr> <tr> <td>x6</td> <td>CV-55</td> <td></td> <td>CV-260</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-55</td> </tr> <tr> <td>x7</td> <td></td> <td></td> <td></td> <td>CV-370</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x8</td> <td>CV-75</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-75</td> </tr> <tr> <td>x9</td> <td></td> <td>CV-185</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-90</td> </tr> </tbody> </table> </td> <td data-bbox="1157 284 1310 1615">0000 to FFFF HEX setting</td> <td data-bbox="1310 284 1463 1615">0000</td> </tr> <tr> <td data-bbox="134 1615 220 1763">3242 (PR)</td> <td data-bbox="220 1615 309 1763">SP042</td> <td data-bbox="309 1615 579 1763">CRNG C-axis detector range</td> <td data-bbox="579 1615 1157 1763"> <p>This parameter is used to set the C-axis detector range. Set "0" for this parameter. "2" is used by Mitsubishi for testing.</p> </td> <td data-bbox="1157 1615 1310 1763">0 to 7</td> <td data-bbox="1310 1615 1463 1763">0</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	amp				rtyp				7	6	5	4	3	2	1	0	ptyp								bit	Explanation										0	When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.										1	2	3	<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:5%;">Set-ting</th> <th style="width:10%;">0x</th> <th style="width:10%;">1x</th> <th style="width:10%;">2x</th> <th style="width:10%;">3x</th> <th style="width:10%;">4x</th> <th style="width:10%;">5x</th> <th style="width:10%;">6x</th> <th style="width:10%;">7x</th> <th style="width:10%;">8x</th> </tr> </thead> <tbody> <tr> <td>x0</td> <td>Not used</td> <td></td> <td></td> <td>CV-300</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x1</td> <td></td> <td>CV-110</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-10</td> </tr> <tr> <td>x2</td> <td></td> <td></td> <td>CV-220</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-15</td> </tr> <tr> <td>x3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-22</td> </tr> <tr> <td>x4</td> <td>CV-37</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-37</td> </tr> <tr> <td>x5</td> <td></td> <td>CV-150</td> <td></td> <td></td> <td>CV-450</td> <td>CV-550</td> <td></td> <td></td> <td></td> </tr> <tr> <td>x6</td> <td>CV-55</td> <td></td> <td>CV-260</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-55</td> </tr> <tr> <td>x7</td> <td></td> <td></td> <td></td> <td>CV-370</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x8</td> <td>CV-75</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-75</td> </tr> <tr> <td>x9</td> <td></td> <td>CV-185</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-90</td> </tr> </tbody> </table>										Set-ting	0x	1x	2x	3x	4x	5x	6x	7x	8x	x0	Not used			CV-300						x1		CV-110							CR-10	x2			CV-220						CR-15	x3									CR-22	x4	CV-37								CR-37	x5		CV-150			CV-450	CV-550				x6	CV-55		CV-260						CR-55	x7				CV-370						x8	CV-75								CR-75	x9		CV-185							CR-90	0000 to FFFF HEX setting	0000	3242 (PR)	SP042	CRNG C-axis detector range	<p>This parameter is used to set the C-axis detector range. Set "0" for this parameter. "2" is used by Mitsubishi for testing.</p>	0 to 7	0
F	E	D	C	B	A	9	8																																																																																																																																																																																					
amp				rtyp																																																																																																																																																																																								
7	6	5	4	3	2	1	0																																																																																																																																																																																					
ptyp																																																																																																																																																																																												
bit	Explanation																																																																																																																																																																																											
0	When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.																																																																																																																																																																																											
1																																																																																																																																																																																												
2																																																																																																																																																																																												
3	<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:5%;">Set-ting</th> <th style="width:10%;">0x</th> <th style="width:10%;">1x</th> <th style="width:10%;">2x</th> <th style="width:10%;">3x</th> <th style="width:10%;">4x</th> <th style="width:10%;">5x</th> <th style="width:10%;">6x</th> <th style="width:10%;">7x</th> <th style="width:10%;">8x</th> </tr> </thead> <tbody> <tr> <td>x0</td> <td>Not used</td> <td></td> <td></td> <td>CV-300</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x1</td> <td></td> <td>CV-110</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-10</td> </tr> <tr> <td>x2</td> <td></td> <td></td> <td>CV-220</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-15</td> </tr> <tr> <td>x3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-22</td> </tr> <tr> <td>x4</td> <td>CV-37</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-37</td> </tr> <tr> <td>x5</td> <td></td> <td>CV-150</td> <td></td> <td></td> <td>CV-450</td> <td>CV-550</td> <td></td> <td></td> <td></td> </tr> <tr> <td>x6</td> <td>CV-55</td> <td></td> <td>CV-260</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-55</td> </tr> <tr> <td>x7</td> <td></td> <td></td> <td></td> <td>CV-370</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x8</td> <td>CV-75</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-75</td> </tr> <tr> <td>x9</td> <td></td> <td>CV-185</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-90</td> </tr> </tbody> </table>										Set-ting	0x	1x	2x	3x	4x	5x	6x	7x	8x	x0	Not used			CV-300						x1		CV-110							CR-10	x2			CV-220						CR-15	x3									CR-22	x4	CV-37								CR-37	x5		CV-150			CV-450	CV-550				x6	CV-55		CV-260						CR-55	x7				CV-370						x8	CV-75								CR-75	x9		CV-185							CR-90	0000 to FFFF HEX setting	0000																																																																		
Set-ting	0x	1x	2x	3x	4x	5x	6x	7x	8x																																																																																																																																																																																			
x0	Not used			CV-300																																																																																																																																																																																								
x1		CV-110							CR-10																																																																																																																																																																																			
x2			CV-220						CR-15																																																																																																																																																																																			
x3									CR-22																																																																																																																																																																																			
x4	CV-37								CR-37																																																																																																																																																																																			
x5		CV-150			CV-450	CV-550																																																																																																																																																																																						
x6	CV-55		CV-260						CR-55																																																																																																																																																																																			
x7				CV-370																																																																																																																																																																																								
x8	CV-75								CR-75																																																																																																																																																																																			
x9		CV-185							CR-90																																																																																																																																																																																			
3242 (PR)	SP042	CRNG C-axis detector range	<p>This parameter is used to set the C-axis detector range. Set "0" for this parameter. "2" is used by Mitsubishi for testing.</p>	0 to 7	0																																																																																																																																																																																							



8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3243 (PR)	SP043	TRNG	Synchronous tapping, spindle synchronous detector range	This parameter is used to set the synchronous tapping or spindle synchronous detector range. Set "0" for this parameter.	0 to 7	0
3244 (PR)	SP044	TRANS	NC communication frequency	Set a frequency of data communication with NC.	0 to 32767	Standard: 0 Special: 1028
3245	SP045	CSNT	Dual cushion timer	Set the cycle to add the increment values in the dual cushion process. When this setting value is increased, the dual cushion will increase, and the changes in the speed during acceleration/deceleration will become gradual.	0 to 1000 (ms)	0
3246 (PR)	SP046	CSN2	Speed command dual cushion	For an acceleration/deceleration time constant defined in SP019 (CSN1), this parameter is used to provide smooth movement only at the start of acceleration/deceleration. As the value of this parameter is smaller, it moves smoother but the acceleration/deceleration time becomes longer. To make this parameter invalid, set "0".	0 to 1000	0
3247 (PR)	SP047	SDTR	Speed detection reset value	Set the reset hysteresis width for a speed detection set value defined in SP020 (SDTS).	0 to 1000 (r/min)	30
3247 (PR)	SP047	SDTR	Speed detection reset value	Set the reset hysteresis width for a speed detection set value defined in SP020 (SDTS).	0 to 1000 (r/min)	30
3248 (PR)	SP048	SUT	Speed reach range	Set the speed deviation rate with respect to the commanded speed for output of the speed reach signal.	0 to 100 (%)	15
3249	SP049	TLM2	Torque limit 2	Set the torque limit rate for the torque limit signal 010.	1 to 120 (%)	20
3250	SP050	TLM3	Torque limit 3	Set the torque limit rate for the torque limit signal 011.	1 to 120 (%)	30
3251	SP051	TLM4	Torque limit 4	Set the torque limit rate for the torque limit signal 100.	1 to 120 (%)	40
3252	SP052	TLM5	Torque limit 5	Set the torque limit rate for the torque limit signal 101.	1 to 120 (%)	50
3253	SP053	TLM6	Torque limit 6	Set the torque limit rate for the torque limit signal 110.	1 to 120 (%)	60
3254	SP054	TLM7	Torque limit 7	Set the torque limit rate for the torque limit signal 111.	1 to 120 (%)	70

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3255 (PR)	SP055	SETM	Excessive speed deviation timer	Set the timer value until the excessive speed deviation alarm is output. The value of this parameter should be longer than the acceleration/deceleration time.	0 to 60 (s)	12
3256	SP056	PYVR	Variable excitation (min value)	Set the minimum value of the variable excitation rate. Select a smaller value when gear noise is too high. However, a larger value is effective for impact response.	0 to 100 (%)	50
3257 (PR)	SP057	STOD	Constant → excessive judgment value	Set the value for judging when changing from a constant to excessive speed command.	0 to 50 (r/min)	0
3258 (PR)	SP058	SDT2	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3259 (PR)	SP059	MKT	Winding change-over base shut-off timer	Set the base shut-off time for contactor switching at winding changeover. Note that the contactor may be damaged with burning if the value of this parameter is too small.	50 to 10000 (ms)	150
3260 (PR)	SP060	MKT2	Current limit timer after winding change-over	Set the current limit time to be taken after completion of contactor switching at winding changeover.	0 to 10000 (ms)	500
3261 (PR)	SP061	MKIL	Current limit value after winding change-over	Set the current limit value during a period defined in SP060 (MKT2) after completion of contactor switching at winding changeover.	0 to 120 (%)	75
3262	SP062			Not used. Set to "0".	0	0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH


No.	Items		Details	Setting range	Standard setting
3263 (PR)	SP063	OLT	Overload alarm detection time	Set the time constant for detection of the motor overload alarm.	0 to 1000 (s) 60
3264 (PR)	SP064	OLL	Overload alarm detection level	Set the detection level of the motor overload alarm.	0 to 120 (%) 110
3265 (PR)	SP065	VCGN1	Target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP022 (VGNP1) at the maximum motor speed defined in SP017 (TSP).	0 to 100 (%) 100
3266 (PR)	SP066	VCSN1	Change starting speed of variable speed loop proportional gain	Set the speed when the speed loop proportional gain change starts. 	0 to 32767 (r/min) 0
3267 (PR)	SP067	VIGWA	Change starting speed of variable current loop gain	Set the speed where the current loop gain change starts.	0 to 32767 (r/min) 0
3268 (PR)	SP068	VIGWB	Change ending speed of variable current loop gain	Set the speed where the current loop gain change ends.	0 to 32767 (r/min) 0
3269 (PR)	SP069	VIGN	Target value of variable current loop gain	Set the magnification of current loop gain (torque component and excitation component) for a change ending speed defined in SP068 (VIGWB). When this parameter is set to "0", the magnification is 1. 	0 to 32767 (1/16-fold) 0

SP017 (TSP) Maximum motor speed	SP067 (VIGWA)	SP068 (VIGWB)	SP069 (VIGN)
0 to 6000	0	0	0
6001 to 8000	5000	8000	45
8001 or more	5000	10000	64

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																				
3270	SP070	FHz	Machine resonance suppression filter frequency	When machine vibration occurs in speed and position control, set the frequency of the required vibration suppression. Note that a value of 100Hz or more is set. Set to "0" when not used.	0 to 3000 (Hz)	0																																																																																																			
3271 (PR)	SP071	VR2WA	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0																																																																																																			
3272 (PR)	SP072	VR2WB																																																																																																							
3273 (PR)	SP073	VR2GN																																																																																																							
3274 (PR)	SP074	IGDEC																																																																																																							
3275	SP075	R2KWS	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td align="center">F</td><td align="center">E</td><td align="center">D</td><td align="center">C</td><td align="center">B</td><td align="center">A</td><td align="center">9</td><td align="center">8</td> </tr> <tr> <td align="center"> </td><td align="center"> </td><td align="center"> </td><td align="center"> </td><td align="center"> </td><td align="center"> </td><td align="center"> </td><td align="center">r2ini</td> </tr> <tr> <td align="center">7</td><td align="center">6</td><td align="center">5</td><td align="center">4</td><td align="center">3</td><td align="center">2</td><td align="center">1</td><td align="center">0</td> </tr> <tr> <td align="center"> </td><td align="center"> </td><td align="center"> </td><td align="center">r2am</td><td align="center">r2lm</td><td align="center">r2dn</td><td align="center">no51</td><td align="center">r2ch</td> </tr> </table> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>bit</th><th>Name</th><th>Meaning when set to 0</th><th>Meaning when set to 1</th></tr> </thead> <tbody> <tr> <td align="center">0</td><td>r2ch</td><td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td></tr> <tr> <td align="center">1</td><td>no51</td><td colspan="2"></td></tr> <tr> <td align="center">2</td><td>r2dm</td><td colspan="2"></td></tr> <tr> <td align="center">3</td><td>r2lm</td><td colspan="2"></td></tr> <tr> <td align="center">4</td><td>r2am</td><td colspan="2"></td></tr> <tr> <td align="center">5</td><td></td><td></td><td></td></tr> <tr> <td align="center">6</td><td></td><td></td><td></td></tr> <tr> <td align="center">7</td><td></td><td></td><td></td></tr> <tr> <td align="center">8</td><td>r2ini</td><td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated</td></tr> <tr> <td align="center">9</td><td></td><td></td><td></td></tr> <tr> <td align="center">A</td><td></td><td></td><td></td></tr> <tr> <td align="center">B</td><td></td><td></td><td></td></tr> <tr> <td align="center">C</td><td></td><td></td><td></td></tr> <tr> <td align="center">D</td><td></td><td></td><td></td></tr> <tr> <td align="center">E</td><td></td><td></td><td></td></tr> <tr> <td align="center">F</td><td></td><td></td><td></td></tr> </tbody> </table>	F	E	D	C	B	A	9	8								r2ini	7	6	5	4	3	2	1	0				r2am	r2lm	r2dn	no51	r2ch	bit	Name	Meaning when set to 0	Meaning when set to 1	0	r2ch	This is used by Mitsubishi. Set to "0" unless particularly designated.		1	no51			2	r2dm			3	r2lm			4	r2am			5				6				7				8	r2ini	This is used by Mitsubishi. Set to "0" unless particularly designated		9				A				B				C				D				E				F					
F	E	D	C	B	A	9	8																																																																																																		
							r2ini																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
			r2am	r2lm	r2dn	no51	r2ch																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	r2ch	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																							
1	no51																																																																																																								
2	r2dm																																																																																																								
3	r2lm																																																																																																								
4	r2am																																																																																																								
5																																																																																																									
6																																																																																																									
7																																																																																																									
8	r2ini	This is used by Mitsubishi. Set to "0" unless particularly designated																																																																																																							
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									
3276	SP076	FONS	Machine resonance suppression filter operation speed	When the vibration increases in motor stop (ex. in orientation stop) when the machine vibration suppression filter is operated by SP070, operate the machine vibration suppression filter at a speed of this parameter or more. When set to "0", this is validated for all speeds.	0 to 32767 (r/min)	0																																																																																																			
3277 (PR)	SP077	TDSL	Fixed control constant	Set by Mitsubishi. Set "14" unless designated in particular.		14																																																																																																			
3278 (PR)	SP078	FPWM	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0																																																																																																			
3279 (PR)	SP079	ILMT																																																																																																							

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3280	SP080			Use not possible.	0	0
3281	SP081	LMCA	Fixed control constant	This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3282	SP082	LMCB				
3283	SP083					
3284 to 3286	SP084 to SP086			Use not possible.	0	0
3287 (PR)	SP087	DIQM	Target value of variable torque limit magnification at deceleration	Set the minimum value of variable torque limit at deceleration.	0 to 150 (%)	75
3288 (PR)	SP088	DIQN	Speed for starting change of variable torque limit magnification at deceleration	Set the speed where the torque limit value at deceleration starts to change. 	0 to 32767 (r/min)	3000
3289	SP089			Use not possible.	0	0
3290	SP090			Use not possible.	0	0
3291	SP091	OFSN	Motor PLG forward rotation offset compensation	Set the PLG offset value for the forward rotation. Normally set to "0".	-2048 to 2047 (-1mv)	0
3292	SP092	OFSI	Motor PLG reverse rotation offset compensation	Set the PLG offset value for the reverse rotation. Normally set to "0".	-2048 to 2047 (-1mv)	0
3293 (PR)	SP093	ORE	Tolerable pulse check error	Set this when detecting the pulse detector's pulse mistakes. (Valid only for full close control.)	0 to 32767	0
3294 (PR)	SP094	LMAV	Load meter output filter	Set the filter time constant of load meter output. When "0" is set, a filter time constant is set to 100ms.	0 to 32767 (2ms)	0
3295 (PR)	SP095	VFAV	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																																																																																																																																																																																																																																																																																					
3296 (PR)	SP096	EGAR Encoder gear ratio	Set the gear ratio between the spindle end and the encoder end (except for the motor-built-in encoder) as indicated below. <table border="1" data-bbox="635 438 1131 639" style="margin-left: 20px;"> <thead> <tr> <th>Setting value</th> <th>Gear ratio (deceleration)</th> <th>Setting value</th> <th>Gear ratio (acceleration)</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>1 : 1</td> <td>-1</td> <td>1 : 2</td> </tr> <tr> <td>1</td> <td>1 : 1/2</td> <td>-2</td> <td>1 : 4</td> </tr> <tr> <td>2</td> <td>1 : 1/4</td> <td>-3</td> <td>1 : 3</td> </tr> <tr> <td>3</td> <td>1 : 1/8</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td>1 : 1/16</td> <td></td> <td></td> </tr> </tbody> </table>	Setting value	Gear ratio (deceleration)	Setting value	Gear ratio (acceleration)	0	1 : 1	-1	1 : 2	1	1 : 1/2	-2	1 : 4	2	1 : 1/4	-3	1 : 3	3	1 : 1/8			4	1 : 1/16			-3 to 4	0																																																																																																																																																																																																																																																																																																																																													
Setting value	Gear ratio (deceleration)	Setting value	Gear ratio (acceleration)																																																																																																																																																																																																																																																																																																																																																																							
0	1 : 1	-1	1 : 2																																																																																																																																																																																																																																																																																																																																																																							
1	1 : 1/2	-2	1 : 4																																																																																																																																																																																																																																																																																																																																																																							
2	1 : 1/4	-3	1 : 3																																																																																																																																																																																																																																																																																																																																																																							
3	1 : 1/8																																																																																																																																																																																																																																																																																																																																																																									
4	1 : 1/16																																																																																																																																																																																																																																																																																																																																																																									
3297 (PR)	SP097	SPECO Orientation specification	Set the orientation specifications in bit <u>urfits</u> . <table border="1" data-bbox="627 706 1163 868" style="margin-left: 20px;"> <thead> <tr> <th colspan="2">E</th> <th colspan="2">D</th> <th colspan="2">C</th> <th colspan="2">B</th> <th colspan="2">A</th> <th colspan="2">9</th> <th colspan="2">8</th> </tr> <tr> <th>ostp</th><th>orze</th><th>ksft</th><th>gchg</th><th></th><th></th><th>ips2</th><th>zdir</th><th></th><th></th><th></th><th></th><th></th><th></th> </tr> <tr> <th colspan="2">7</th><th colspan="2">6</th><th colspan="2">5</th><th colspan="2">4</th><th colspan="2">3</th><th colspan="2">2</th><th colspan="2">1</th> </tr> <tr> <th>vg8x</th><th>mdir</th><th>fdir</th><th>osc1</th><th>pyfx</th><th>dmin</th><th>odi2</th><th>odi1</th><th colspan="6"></th> </tr> </thead> <tbody> <tr> <td colspan="14">(Note) Always set "0" for the empty bits.</td> </tr> <tr> <th>bit</th><th>Name</th><th colspan="2">Meaning when set to 0</th><th colspan="2">Meaning when set to 1</th><td colspan="7"></td> </tr> <tr> <td>0</td><td>odi1</td><td colspan="2">Orientation rotation direction</td><td colspan="2">00: Previous (the direction in which the motor has so far rotated under speed control)</td><td colspan="7"></td> </tr> <tr> <td>1</td><td>odi2</td><td colspan="2">01: Forward rotation</td><td colspan="2">10: Backward rotation</td><td colspan="7"></td> </tr> <tr> <td></td><td></td><td colspan="2">11: Prohibited (Same as setting value = 10)</td><td colspan="7"></td> </tr> <tr> <td>2</td><td>dmin</td><td colspan="2">Orientation in-position advance invalid</td><td colspan="2">Orientation in-position advance valid</td><td colspan="7"></td> </tr> <tr> <td>3</td><td>pyfx</td><td colspan="2">Excitation min. (50%) during orientation servo lock invalid</td><td colspan="2">Excitation min. (50%) during orientation servo lock valid</td><td colspan="7"></td> </tr> <tr> <td>4</td><td>osc1</td><td colspan="2">Indexing speed clamp invalid</td><td colspan="2">Indexing speed clamp valid</td><td colspan="7"></td> </tr> <tr> <td>5</td><td>fdir</td><td colspan="2">Encoder detector polarity: +</td><td colspan="2">Encoder detector polarity: -</td><td colspan="7"></td> </tr> <tr> <td>6</td><td>mdir</td><td colspan="2">Magnetic sensor polarity: +</td><td colspan="2">Magnetic sensor polarity: -</td><td colspan="7"></td> </tr> <tr> <td>7</td><td>vg8x</td><td colspan="2">Speed gain *1/8 during torque limit valid</td><td colspan="2">Speed gain *1/8 during torque limit invalid</td><td colspan="7"></td> </tr> <tr> <td>8</td><td></td><td colspan="2"></td><td colspan="2"></td><td colspan="7"></td> </tr> <tr> <td>9</td><td>zdir</td><td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td><td colspan="2"></td><td colspan="7"></td> </tr> <tr> <td>A</td><td>ips2</td><td colspan="2">2nd in-position invalid</td><td colspan="2">2nd in-position valid</td><td colspan="7"></td> </tr> <tr> <td>B</td><td></td><td colspan="2"></td><td colspan="2"></td><td colspan="7"></td> </tr> <tr> <td>C</td><td>gchg</td><td colspan="2">Gain changeover during orientation invalid</td><td colspan="2">Gain changeover during orientation valid</td><td colspan="7"></td> </tr> <tr> <td>D</td><td>ksft</td><td colspan="2">Orientation virtual target shift invalid</td><td colspan="2">Orientation virtual target shift valid</td><td colspan="7"></td> </tr> <tr> <td>E</td><td>orze</td><td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td><td colspan="2"></td><td colspan="7"></td> </tr> <tr> <td>F</td><td>ostp</td><td colspan="2"></td><td colspan="2"></td><td colspan="7"></td> </tr> <tr> <td colspan="2"></td><td colspan="12" style="text-align: center;">In-position advance (bit 2)</td> </tr> <tr> <td colspan="2"></td><td colspan="6" style="text-align: center;">0 (invalid)</td><td colspan="6" style="text-align: center;">1 (valid)</td> </tr> <tr> <td rowspan="2" style="writing-mode: vertical-rl; transform: rotate(180deg);">Second in-position</td> <td>0 (Invalid)</td> <td colspan="6">In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=1</td> <td colspan="6">In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=0</td> </tr> <tr> <td>1 (Valid)</td> <td colspan="6">In-position signal in DINP width=1 Control output 4/ bit 4=1 Second in-position signal in OINP width = 0 Control output 4/ bit F=1</td> <td colspan="6"></td> </tr> </tbody> </table>	E		D		C		B		A		9		8		ostp	orze	ksft	gchg			ips2	zdir							7		6		5		4		3		2		1		vg8x	mdir	fdir	osc1	pyfx	dmin	odi2	odi1							(Note) Always set "0" for the empty bits.														bit	Name	Meaning when set to 0		Meaning when set to 1									0	odi1	Orientation rotation direction		00: Previous (the direction in which the motor has so far rotated under speed control)									1	odi2	01: Forward rotation		10: Backward rotation											11: Prohibited (Same as setting value = 10)									2	dmin	Orientation in-position advance invalid		Orientation in-position advance valid									3	pyfx	Excitation min. (50%) during orientation servo lock invalid		Excitation min. (50%) during orientation servo lock valid									4	osc1	Indexing speed clamp invalid		Indexing speed clamp valid									5	fdir	Encoder detector polarity: +		Encoder detector polarity: -									6	mdir	Magnetic sensor polarity: +		Magnetic sensor polarity: -									7	vg8x	Speed gain *1/8 during torque limit valid		Speed gain *1/8 during torque limit invalid									8													9	zdir	This is used by Mitsubishi. Set to "0" unless particularly designated.											A	ips2	2nd in-position invalid		2nd in-position valid									B													C	gchg	Gain changeover during orientation invalid		Gain changeover during orientation valid									D	ksft	Orientation virtual target shift invalid		Orientation virtual target shift valid									E	orze	This is used by Mitsubishi. Set to "0" unless particularly designated.											F	ostp														In-position advance (bit 2)														0 (invalid)						1 (valid)						Second in-position	0 (Invalid)	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=1						In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=0						1 (Valid)	In-position signal in DINP width=1 Control output 4/ bit 4=1 Second in-position signal in OINP width = 0 Control output 4/ bit F=1												0000 to FFFF HEX setting	0000
E		D		C		B		A		9		8																																																																																																																																																																																																																																																																																																																																																														
ostp	orze	ksft	gchg			ips2	zdir																																																																																																																																																																																																																																																																																																																																																																			
7		6		5		4		3		2		1																																																																																																																																																																																																																																																																																																																																																														
vg8x	mdir	fdir	osc1	pyfx	dmin	odi2	odi1																																																																																																																																																																																																																																																																																																																																																																			
(Note) Always set "0" for the empty bits.																																																																																																																																																																																																																																																																																																																																																																										
bit	Name	Meaning when set to 0		Meaning when set to 1																																																																																																																																																																																																																																																																																																																																																																						
0	odi1	Orientation rotation direction		00: Previous (the direction in which the motor has so far rotated under speed control)																																																																																																																																																																																																																																																																																																																																																																						
1	odi2	01: Forward rotation		10: Backward rotation																																																																																																																																																																																																																																																																																																																																																																						
		11: Prohibited (Same as setting value = 10)																																																																																																																																																																																																																																																																																																																																																																								
2	dmin	Orientation in-position advance invalid		Orientation in-position advance valid																																																																																																																																																																																																																																																																																																																																																																						
3	pyfx	Excitation min. (50%) during orientation servo lock invalid		Excitation min. (50%) during orientation servo lock valid																																																																																																																																																																																																																																																																																																																																																																						
4	osc1	Indexing speed clamp invalid		Indexing speed clamp valid																																																																																																																																																																																																																																																																																																																																																																						
5	fdir	Encoder detector polarity: +		Encoder detector polarity: -																																																																																																																																																																																																																																																																																																																																																																						
6	mdir	Magnetic sensor polarity: +		Magnetic sensor polarity: -																																																																																																																																																																																																																																																																																																																																																																						
7	vg8x	Speed gain *1/8 during torque limit valid		Speed gain *1/8 during torque limit invalid																																																																																																																																																																																																																																																																																																																																																																						
8																																																																																																																																																																																																																																																																																																																																																																										
9	zdir	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																																																																																																																																																																																																																																																																																								
A	ips2	2nd in-position invalid		2nd in-position valid																																																																																																																																																																																																																																																																																																																																																																						
B																																																																																																																																																																																																																																																																																																																																																																										
C	gchg	Gain changeover during orientation invalid		Gain changeover during orientation valid																																																																																																																																																																																																																																																																																																																																																																						
D	ksft	Orientation virtual target shift invalid		Orientation virtual target shift valid																																																																																																																																																																																																																																																																																																																																																																						
E	orze	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																																																																																																																																																																																																																																																																																								
F	ostp																																																																																																																																																																																																																																																																																																																																																																									
		In-position advance (bit 2)																																																																																																																																																																																																																																																																																																																																																																								
		0 (invalid)						1 (valid)																																																																																																																																																																																																																																																																																																																																																																		
Second in-position	0 (Invalid)	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=1						In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=0																																																																																																																																																																																																																																																																																																																																																																		
	1 (Valid)	In-position signal in DINP width=1 Control output 4/ bit 4=1 Second in-position signal in OINP width = 0 Control output 4/ bit F=1																																																																																																																																																																																																																																																																																																																																																																								

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3298 (PR)	SP098	VGOP	Speed loop gain proportional term in orientation mode	Set the speed loop proportional gain in orientation mode. When the gain is increased, rigidity is improved in the orientation stop but vibration and sound become larger.	0 to 1000 (1/s)	63
3299 (PR)	SP099	VGOI	Orientation mode speed loop gain integral term	Set the speed loop integral gain in orientation mode.	0 to 1000 (0.1 1/s)	60
3300 (PR)	SP100	VGOD	Orientation mode speed loop gain delay advance term	Set a loop gain delay advance gain in orientation mode. When this parameter is set to "0", PI control is applied.	0 to 1000 (0.1 1/s)	15
3301 (PR)	SP101	DINP	Orientation advance in-position width	When using the orientation in-position advance function, set the in-position width that is larger than the normal in-position width defined in SP004 (OINP).	1 to 2880 (1/16°)	16
3302 (PR)	SP102	OODR	Excessive error value in orientation mode	Set the excessive error width in orientation mode.	0 to 32767 (1/4 pulse) (1 pulse= 0.088°)	32767
3303 (PR)	SP103	FTM	Index positioning completion OFF time timer	Set the time for forcibly turn OFF the index positioning completion signal (different from the orientation completion signal) after the leading edge of the indexing start signal.	0 to 10000 (ms)	200
3304 (PR)	SP104	TLOR	Torque limit value for orientation servo locking	Set the torque limit value for orientation in-position output. If the external torque limit signal is input, the torque limit value set by this parameter is made invalid.	0 to 120 (%)	100
3305 (PR)	SP105	IQG0	Current loop gain magnification 1 in orientation mode	Set the magnification for current loop gain (torque component) at orientation completion.	1 to 1000 (%)	100
3306 (PR)	SP106	IDG0	Current loop gain magnification 2 in orientation mode	Set the magnification for current loop gain (excitation component) at orientation completion.	1 to 1000 (%)	100
3307	SP107	CSP2	Deceleration rate 2 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 001. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting
3308	SP108	CSP3	Deceleration rate 3 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 010. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000 0
3309	SP109	CSP4	Deceleration rate 4 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 011. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000 0
3310 to 3313	SP110 to SP113			Use not possible.	0
3314	SP114	OPER	Orientation pulse miss check value	An alarm "5C" will occur if the pulse miss value at the orientation stop exceeds this setting value. (Note that this is invalid when set to "0".) In this parameter, set the value to fulfill the following conditions. SP114 setting value > 1.5 × SP004 (orientation in-position width)	0 to 32767 (360°/4096) 0
3315	SP115	OSP2	Orientation motor speed clamp value 2	When the orientation clamp speed is changed by the control input, this parameter setting will be used instead of SP005: OSP. Indexing speed clamp valid This parameter is used when (SP097: SPEC0-bit4 = 1).	0 to 32767 (r/min) 0
3316	SP116	OPYVR	Minimum excitation value after changeover (2nd minimum excitation rate)	Minimum excitation rate when position control input or external input is selected.	0 to 100 (%) 0
3317	SP117	ORUT		This is used by Mitsubishi. Set to "0" unless particularly designated.	0 0
3318	SP118	ORCT	Number of orientation retry times	Set the number of times to retry when an orientation or feedback error occurs. The warning (A9) is issued while retrying orientation, and an alarm (5C) is issued when the set number of times is exceeded.	0 to 100 (time) 0
3319	SP119	MPGH	Orientation position gain H winding compensation magnification	Set the compensation magnification of the orientation position loop gain for the H winding. H winding orientation position loop gain = SP001 (or SP002) × SP119/256 When set to "0", will become the same as SP001 or SP002.	0 to 2560 (1/256-fold) 0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting
3320	SP120	MPGL	Orientation position gain L winding compensation magnification Set the compensation magnification of the orientation position loop gain for the L winding. L winding orientation position loop gain = SP001 (or SP002) × SP120/256 When set to "0", will become the same as SP001 or SP002.	0 to 2560 (1/256-fold)	0
3321	SP121	MPCSH	Orientation deceleration rate H winding compensation magnification Set the compensation magnification of the orientation deceleration rate for the H winding. Orientation deceleration rate for the H winding = SP006 × SP121/256 When set to "0", will become the same as SP006.	0 to 2560 (1/256-fold)	0
3322	SP122	MPCSL	Orientation deceleration rate L winding compensation magnification Set the compensation magnification of the orientation deceleration rate for the L winding. Orientation deceleration rate for the L winding = SP006 × SP122/256 When set to "0", will become the same as SP006.	0 to 2560 (1/256-fold)	0
3323	SP123	MGD0	Magnetic sensor output peak value This parameter is used for adjustment of orientation operation of the magnetic sensor. Set the output peak value of the magnetic sensor. If a gap between the sensor and the magnetizing element is small, increase the value of this parameter. If it is large, decrease the value of this parameter.	1 to 10000	Standard magnetizing element: 542 Small magnetizing element: 500
3324	SP124	MGD1	Magnetic sensor linear zone width This parameter is used for adjustment of orientation operation of the magnetic sensor. Set the linear zone width of the magnetic sensor. If the radius of the mounted magnetizing element is large, decrease the value of this parameter. If it is small, increase the value of this parameter.	1 to 10000	Standard magnetizing element: 768 Small magnetizing element: 440

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																				
3325	SP125	MGD2	Magnetic sensor switching point	1 to 10000	Standard magnetizing element: 384 Small magnetizing element: 220																																																																																																				
3326 to 3328	SP126 to SP128		Use not possible.	0	0																																																																																																				
3329 (PR)	SP129	SPECC	C-axis specifications Set the C-axis specifications in bit units. <table style="width: 100%; border-collapse: collapse; margin-bottom: 5px;"> <tr> <td style="text-align: center;">F</td><td style="text-align: center;">E</td><td style="text-align: center;">D</td><td style="text-align: center;">C</td><td style="text-align: center;">B</td><td style="text-align: center;">A</td><td style="text-align: center;">9</td><td style="text-align: center;">8</td> </tr> <tr> <td style="text-align: center;">zrtn</td><td style="text-align: center;">ptyp</td><td style="text-align: center;">fb9x</td><td style="text-align: center;">zrtd</td><td style="text-align: center;">zrn2</td><td style="text-align: center;"></td><td style="text-align: center;">zdir</td><td style="text-align: center;">ztyp</td> </tr> </table> <table style="width: 100%; border-collapse: collapse; margin-bottom: 5px;"> <tr> <td style="text-align: center;">7</td><td style="text-align: center;">6</td><td style="text-align: center;">5</td><td style="text-align: center;">4</td><td style="text-align: center;">3</td><td style="text-align: center;">2</td><td style="text-align: center;">1</td><td style="text-align: center;">0</td> </tr> <tr> <td style="text-align: center;">vg8x</td><td style="text-align: center;"></td><td style="text-align: center;">fdir</td><td style="text-align: center;"></td><td style="text-align: center;">phos</td><td style="text-align: center;">rtrn</td><td style="text-align: center;">adin</td><td style="text-align: center;">fclx</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 5px;"> <thead> <tr> <th style="text-align: center;">bit</th> <th style="text-align: center;">Name</th> <th style="text-align: center;">Meaning when set to 0</th> <th style="text-align: center;">Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">fclx</td> <td>Closed loop</td> <td>Semi-closed loop (Gear 1 : 1 only)</td> </tr> <tr> <td style="text-align: center;">1</td> <td style="text-align: center;">adin</td> <td>Interpolation A/D compensation invalid</td> <td>Interpolation A/D compensation valid</td> </tr> <tr> <td style="text-align: center;">2</td> <td style="text-align: center;">rtrn</td> <td>Position monitor during ready OFF invalid</td> <td>Position monitor during ready OFF valid</td> </tr> <tr> <td style="text-align: center;">3</td> <td style="text-align: center;">phos</td> <td>Normal (no compensation)</td> <td>Vx4 synchronization compensation valid</td> </tr> <tr> <td style="text-align: center;">4</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">5</td> <td style="text-align: center;">fdir</td> <td>Position detector polarity (+)</td> <td>Position detector polarity (-)</td> </tr> <tr> <td style="text-align: center;">6</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">7</td> <td style="text-align: center;">vg8x</td> <td>Speed gain × 1/8 during torque limit valid</td> <td>Speed gain × 1/8 during torque limit invalid</td> </tr> <tr> <td style="text-align: center;">8</td> <td style="text-align: center;">ztyp</td> <td>Z-phase type: Normal start up</td> <td>Z-phase type: Start up only</td> </tr> <tr> <td style="text-align: center;">9</td> <td style="text-align: center;">zdir</td> <td>Z-phase rising polarity (+)</td> <td>Z-phase rising polarity (-)</td> </tr> <tr> <td style="text-align: center;">A</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">B</td> <td style="text-align: center;">zrn2</td> <td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td> </tr> <tr> <td style="text-align: center;">C</td> <td style="text-align: center;">zrtd</td> <td colspan="2"></td> </tr> <tr> <td style="text-align: center;">D</td> <td style="text-align: center;">fb9x</td> <td>Speed feedback Standard (PLG)</td> <td>Speed feedback 90,000 pulse detector</td> </tr> <tr> <td style="text-align: center;">E</td> <td style="text-align: center;">ptyp</td> <td>Position control switch type: After zero point return</td> <td>Position control switch type: After deceleration stop</td> </tr> <tr> <td style="text-align: center;">F</td> <td style="text-align: center;">zrtn</td> <td>Zero point return direction: CCW</td> <td>Zero point return direction: CW</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	zrtn	ptyp	fb9x	zrtd	zrn2		zdir	ztyp	7	6	5	4	3	2	1	0	vg8x		fdir		phos	rtrn	adin	fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)	1	adin	Interpolation A/D compensation invalid	Interpolation A/D compensation valid	2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid	3	phos	Normal (no compensation)	Vx4 synchronization compensation valid	4				5	fdir	Position detector polarity (+)	Position detector polarity (-)	6				7	vg8x	Speed gain × 1/8 during torque limit valid	Speed gain × 1/8 during torque limit invalid	8	ztyp	Z-phase type: Normal start up	Z-phase type: Start up only	9	zdir	Z-phase rising polarity (+)	Z-phase rising polarity (-)	A				B	zrn2	This is used by Mitsubishi. Set to "0" unless particularly designated.		C	zrtd			D	fb9x	Speed feedback Standard (PLG)	Speed feedback 90,000 pulse detector	E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop	F	zrtn	Zero point return direction: CCW	Zero point return direction: CW		0000
F	E	D	C	B	A	9	8																																																																																																		
zrtn	ptyp	fb9x	zrtd	zrn2		zdir	ztyp																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
vg8x		fdir		phos	rtrn	adin	fclx																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)																																																																																																						
1	adin	Interpolation A/D compensation invalid	Interpolation A/D compensation valid																																																																																																						
2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid																																																																																																						
3	phos	Normal (no compensation)	Vx4 synchronization compensation valid																																																																																																						
4																																																																																																									
5	fdir	Position detector polarity (+)	Position detector polarity (-)																																																																																																						
6																																																																																																									
7	vg8x	Speed gain × 1/8 during torque limit valid	Speed gain × 1/8 during torque limit invalid																																																																																																						
8	ztyp	Z-phase type: Normal start up	Z-phase type: Start up only																																																																																																						
9	zdir	Z-phase rising polarity (+)	Z-phase rising polarity (-)																																																																																																						
A																																																																																																									
B	zrn2	This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																							
C	zrtd																																																																																																								
D	fb9x	Speed feedback Standard (PLG)	Speed feedback 90,000 pulse detector																																																																																																						
E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop																																																																																																						
F	zrtn	Zero point return direction: CCW	Zero point return direction: CW																																																																																																						
3330	SP130	PGC1	First position loop gain for cutting on C-axis	1 to 100 (1/s)	15																																																																																																				
3331	SP131	PGC2	Second position loop gain for cutting on C-axis	1 to 100 (1/s)	15																																																																																																				

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3332	SP132	PGC3	Third position loop gain for cutting on C-axis	Set the position loop gain when the third gain is selected for C-axis cutting.	1 to 100 (1/s)	15
3333	SP133	PGC4	Stop position loop gain for cutting on C-axis	Set the position loop gain for stopping when carrying out C-axis cutting.	1 to 100 (1/s)	15
3334 (PR)	SP134	VGCP0	C-axis non-cutting speed loop gain proportional item	Set the speed loop proportional gain in C-axis non-cutting mode.	0 to 5000 (1/s)	63
3335 (PR)	SP135	VGCI0	C-axis non-cutting speed loop gain integral item	Set the speed loop integral gain in C-axis non-cutting mode.	0 to 5000 (0.1 1/s)	60
3336 (PR)	SP136	VGCD0	C-axis non-cutting speed loop gain delay advance item	Set the speed loop delay advance gain in C-axis non-cutting mode. When this parameter is set to "0", PI control is exercised.	0 to 5000 (0.1 1/s)	15
3337 (PR)	SP137	VGCP1	First speed loop gain proportional item for C-axis cutting	Set the speed loop proportional gain when the first gain is selected for C-axis cutting.	0 to 5000 (1/s)	63
3338 (PR)	SP138	VGCI1	First speed loop gain integral item for cutting on C-axis	Set the speed loop integral gain when the first gain is selected for C-axis cutting.	0 to 5000 (0.1 1/s)	60
3339 (PR)	SP139	VGCD1	First speed loop gain delay advance item for cutting on C-axis	Set the speed loop delay advance gain when the first gain is selected for curing on the C-axis. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15
3340 (PR)	SP140	VGCP2	Second speed loop gain proportional item for cutting on C-axis	Set the speed loop proportional gain when the second gain is selected for C-axis cutting.	0 to 5000 (1/s)	63

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3341 (PR)	SP141	VGCI2	Second speed loop gain integral item for cutting on C-axis	Set the speed loop integral gain when the second gain is selected for C-axis cutting.	0 to 5000 (0.1 1/s)	60
3342 (PR)	SP142	VGCD2	Second speed loop gain delay advance item for cutting on C-axis	Set the speed loop delay advance gain when the second gain is selected for C-axis cutting. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15
3343 (PR)	SP143	VGCP3	Third speed loop gain proportional item for cutting on C-axis	Set the speed loop proportional gain when the third gain is selected for C-axis cutting.	0 to 5000 (1/s)	63
3344 (PR)	SP144	VGCI3	Third speed loop gain integral item for cutting on C-axis	Set the speed loop integral gain when the third gain is selected for C-axis cutting.	0 to 5000 (0.1 1/s)	60
3345 (PR)	SP145	VGCD3	Third speed loop gain delay advance item for cutting on C-axis	Set the speed loop delay advance gain when the third gain is selected for C-axis cutting. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15
3346 (PR)	SP146	VGCP4	Speed loop gain proportional item for stop of cutting on C-axis	Set the speed loop proportional gain when C-axis cutting is stopped.	0 to 5000 (1/s)	63
3347 (PR)	SP147	VGCI4	Speed loop gain integral item for stop of cutting on C-axis	Set the speed loop integral gain when C-axis cutting is stopped.	0 to 5000 (0.1 1/s)	60
3348 (PR)	SP148	VGCD4	Speed loop gain delay advance item for stop of cutting on C-axis	Set the speed loop delay advance gain when C-axis cutting is stopped. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3349	SP149	CZRN	C-axis zero point return speed	This parameter is valid when SP129 (SPECC) bitE is set to "0". Set the zero point return speed used when the speed loop changes to the position loop.	1 to 500 (r/min)	50
3350	SP150	CPDT	C-axis zero point return deceleration point	This parameter is valid when SP129 (SPECC) bitE is set to "0". Set the deceleration rate where the machine starts to decelerate when it returns to the target stop point during C-axis zero point return. When the machine tends to overshoot at the stop point, set the smaller value.	1 to 10000	1
3351	SP151	CPSTL	C-axis zero point return shift amount (low byte)	This parameter is valid when SPECC (SP129) bitE is set to "0". Set the C-axis zero point position.	HEX setting 00000000 to FFFFFFFF (1/1000°)	H: 0000 L: 0000
3352	SP152	CPSTH	C-axis zero point return shift amount (high byte)			
3354 (PR)	SP154	CODRL	Excessive error width on C-axis (low byte)	Set the excessive error width on the C-axis.	HEX setting 00000000 to FFFFFFFF (1/1000°)	H: 0001 L: D4C0
3355 (PR)	SP155	CODRH	Excessive error width on C-axis (high byte)			
3356	SP156	OVSH	C-axis overshoot compensation	Set this to prevent overshooting when shifting from movement to stopping with C-axis control. (Set this referring to the load meter display when overshooting occurred.)	0 to 1000 (0.1%)	0
3357 to 3358	SP157 to SP158			Not used. Set to "0".	0	0
3359	SP159	CPY0	C-axis non-cutting variable excitation ratio	Set the minimum value of variable excitation ratio for non-cutting on the C-axis .	0 to 100 (%)	50
3360	SP160	CPY1	C-axis cutting variable excitation ratio	Set the minimum variable excitation ratio for cutting on the C-axis.	0 to 100 (%)	100


8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3361 (PR)	SP161	IQGC0	Current loop gain magnification 1 for non-cutting on C-axis	Set the magnification of current loop gain (torque component) for C-axis non-cutting.	1 to 1000 (%)	100
3362 (PR)	SP162	IDGC0	Current loop gain magnification 2 for non-cutting on C-axis	Set the magnification of current loop gain (excitation component) for C-axis non-cutting.	1 to 1000 (%)	100
3363 (PR)	SP163	IQGC1	Current loop gain magnification 1 for cutting on C-axis	Set the magnification of current loop gain (torque component) for C-axis cutting.	1 to 1000 (%)	100
3364 (PR)	SP164	IDGC1	Current loop gain magnification 2 for cutting on C-axis	Set the magnification of current loop gain (excitation component) for C-axis cutting.	1 to 1000 (%)	100
3365	SP165	PG2C	C-axis position loop gain 2	Set the second position loop gain when high-gain control is carried out for control of the C-axis. This parameter is applied to all the operation modes of C-axis control. When this function is not used, assign "0".	0 to 999 (1/s)	0
3366	SP166	PG3C	C-axis position loop gain 3	Set the third position loop gain when high-gain control is carried out for control of the C-axis. This parameter is applied to all the operation modes of C-axis control. When this function is not used, assign "0".	0 to 999 (1/s)	0
3367 (PR)	SP167	PGU	Position loop gain for increased spindle holding force	Set the position loop gain for when the disturbance observer is valid.	0 to 100 (1/s)	15
3368 (PR)	SP168	VGUP	Speed loop gain proportional item for increased spindle holding force	Set the speed loop gain proportional item for when the disturbance observer is valid.	0 to 5000 (1/s)	63
3369 (PR)	SP169	VGUI	Speed loop gain integral item for increased spindle holding force	Set the speed loop gain integral item for when the disturbance observer is valid.	0 to 5000 (0.1 1/s)	60

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																					
3370 (PR)	SP170	VGUD	Speed loop gain delay advance item for increased spindle holding force	Set the speed loop gain delay advance item for when the disturbance observer is valid.	0 to 5000 (0.1 1/s)	15																																																																																																				
3371 to 3376	SP171 to SP176			Not used. Set to "0".	0	0																																																																																																				
3377 (PR)	SP177	SPECS	Spindle synchronous specifications	Set the spindle synchronous specifications in bit units. <table border="1" style="margin-left: 20px;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td></td><td></td><td>Odx8</td><td></td><td></td><td></td><td></td><td>phos</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td>fdir</td><td></td><td>pyfx</td><td>rtrn</td><td>adin</td><td>fclx</td> </tr> </table> <table border="1" style="margin-left: 20px; margin-top: 10px;"> <thead> <tr> <th>bit</th><th>Name</th><th>Meaning when set to 0</th><th>Meaning when set to 1</th></tr> </thead> <tbody> <tr> <td>0</td><td>fclx</td><td>Closed loop</td><td>Semi-closed loop</td></tr> <tr> <td>1</td><td>adin</td><td>Interpolation A/D compensation invalid</td><td>Interpolation A/D compensation valid</td></tr> <tr> <td>2</td><td>rtrn</td><td>Position monitor during ready OFF invalid</td><td>Position monitor during ready OFF valid</td></tr> <tr> <td>3</td><td>pyfx</td><td>Normal excitation</td><td>Position loop excitation fixed (strong)</td></tr> <tr> <td>4</td><td></td><td></td><td></td></tr> <tr> <td>5</td><td>fdir</td><td>Position detector direction (positive direction)</td><td>Position detector direction (negative direction)</td></tr> <tr> <td>6</td><td></td><td></td><td></td></tr> <tr> <td>7</td><td></td><td></td><td></td></tr> <tr> <td>8</td><td></td><td></td><td></td></tr> <tr> <td>9</td><td></td><td></td><td></td></tr> <tr> <td>A</td><td></td><td></td><td></td></tr> <tr> <td>B</td><td></td><td></td><td></td></tr> <tr> <td>C</td><td></td><td></td><td></td></tr> <tr> <td>D</td><td>odx8</td><td>Magnification of excessive error width × 8 times invalid</td><td>Magnification of excessive error width × 8 times valid</td></tr> <tr> <td>E</td><td></td><td></td><td></td></tr> <tr> <td>F</td><td></td><td>(Used with SPJ)</td><td></td></tr> </tbody> </table>	F	E	D	C	B	A	9	8			Odx8					phos	7	6	5	4	3	2	1	0			fdir		pyfx	rtrn	adin	fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop	1	adin	Interpolation A/D compensation invalid	Interpolation A/D compensation valid	2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid	3	pyfx	Normal excitation	Position loop excitation fixed (strong)	4				5	fdir	Position detector direction (positive direction)	Position detector direction (negative direction)	6				7				8				9				A				B				C				D	odx8	Magnification of excessive error width × 8 times invalid	Magnification of excessive error width × 8 times valid	E				F		(Used with SPJ)		0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																			
		Odx8					phos																																																																																																			
7	6	5	4	3	2	1	0																																																																																																			
		fdir		pyfx	rtrn	adin	fclx																																																																																																			
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																							
0	fclx	Closed loop	Semi-closed loop																																																																																																							
1	adin	Interpolation A/D compensation invalid	Interpolation A/D compensation valid																																																																																																							
2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid																																																																																																							
3	pyfx	Normal excitation	Position loop excitation fixed (strong)																																																																																																							
4																																																																																																										
5	fdir	Position detector direction (positive direction)	Position detector direction (negative direction)																																																																																																							
6																																																																																																										
7																																																																																																										
8																																																																																																										
9																																																																																																										
A																																																																																																										
B																																																																																																										
C																																																																																																										
D	odx8	Magnification of excessive error width × 8 times invalid	Magnification of excessive error width × 8 times valid																																																																																																							
E																																																																																																										
F		(Used with SPJ)																																																																																																								
3378 (PR)	SP178	VGSP	Spindle synchronous speed loop gain proportional term	Set the speed loop proportional gain in spindle synchronous mode.	0 to 1000 (1/s)	63																																																																																																				
3379 (PR)	SP179	VGSI	Spindle synchronous speed loop gain integral term	Set the speed loop integral gain in spindle synchronous mode.	0 to 1000 (0.1 1/s)	60																																																																																																				


8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3380 (PR)	SP180	VGSD	Spindle synchronous speed loop gain delay advance term	Set the speed loop delay advance gain in spindle synchronous mode. When this parameter is set to "0", PI control is applied.	0 to 1000 (0.1 1/s)	15
3381 (PR)	SP181	VCGS	Spindle synchronous Target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP178 (VGSP) at the maximum speed defined in SP017 (TSP) in spindle synchronous mode.	0 to 100 (%)	100
3382 (PR)	SP182	VCSS	Spindle synchronous Change starting speed of variable speed loop proportional gain	Set the speed when the speed loop proportional gain change starts in the spindle synchronous mode. 	0 to 32767 (r/min)	0
3383	SP183	SYNV	Spindle synchronous Sync matching speed	For changeover from the speed loop to the position loop in the spindle synchronous mode, set a speed command error range for output of the synchronous speed matching signal.	0 to 1000 (r/min)	20
3384 (PR)	SP184	FFCS	Spindle synchronous Acceleration rate feed forward gain	Set the acceleration rate feed forward gain in the spindle synchronous mode. This parameter is used only with the SPJ2.	0 to 1000 (%)	0
3385	SP185	SINP	Spindle synchronous In-position width	Set the position error range for output of the in-position signal in the spindle synchronous mode.	1 to 2880 (1/16°)	16
3386 (PR)	SP186	SODR	Spindle synchronous Excessive error width	Set the excessive error width in the spindle synchronous mode.	1 to 32767 (pulse) (1 pulse =0.088°)	32767
3387 (PR)	SP187	IQGS	Spindle synchronous Current loop gain magnification1	Set the magnification of current loop gain (torque component) in the spindle synchronous mode.	1 to 1000 (%)	100

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting																																																																																																					
3388 (PR)	SP188	IDGS	Spindle synchronous Current loop gain magnification 2	Set the magnification of current loop gain (excitation component) in the spindle synchronous mode.	1 to 1000 (%)	100																																																																																																				
3389	SP189	PG2S	Spindle synchronous Position loop gain 2	Set the second position loop gain when high-gain control is carried out in the spindle synchronous mode. When this parameter function is not used, set to "0".	0 to 999 (1/s)	0																																																																																																				
3390	SP190	PG3S	Spindle synchronous Position loop gain 3	Set the third position loop gain when high-gain control is carried out in the spindle synchronous mode. When this parameter function is not used, set to "0".	0 to 999 (1/s)	0																																																																																																				
3391	SP191			Use not possible.	0	0																																																																																																				
3392	SP192			Not used. Set to "0".																																																																																																						
3393 (PR)	SP193	SPECT	Synchronized tapping specifications	Set the synchronized tapping specifications in bit units. <table border="1" style="margin-left: 20px;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>zrtn</td><td>ptyp</td><td>od8x</td><td></td><td></td><td></td><td></td><td>phos</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td>fdir</td><td>cdir</td><td>pyfx</td><td></td><td>adin</td><td>fclx</td> </tr> </table> <table border="1" style="margin-left: 20px;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>fclx</td> <td>Closed loop</td> <td>Semi-closed loop (Gear 1 : 1 only)</td> </tr> <tr> <td>1</td> <td>adin</td> <td>Interpolation A/D compensation invalid</td> <td>Interpolation A/D compensation valid</td> </tr> <tr> <td>2</td> <td>rtrn</td> <td>Position monitor during ready OFF invalid</td> <td>Position monitor during ready OFF valid</td> </tr> <tr> <td>3</td> <td>pyfx</td> <td>Normal excitation</td> <td>Position loop excitation fixed (strong)</td> </tr> <tr> <td>4</td> <td>cdir</td> <td>Command polarity (+)</td> <td>Command polarity (-)</td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Position detector polarity (+)</td> <td>Position detector polarity (-)</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>phos</td> <td>Normal (no compensation)</td> <td>Synchronized tapping position compensation valid</td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td>od8x</td> <td>Magnification of excessive error width × 8 times invalid</td> <td>Magnification of excessive error width × 8 times valid</td> </tr> <tr> <td>E</td> <td>ptyp</td> <td>Position control switch type: After zero point return</td> <td>Position control switch type: After deceleration stop</td> </tr> <tr> <td>F</td> <td>zrtn</td> <td>Zero point return direction: CCW</td> <td>Zero point return direction: CW</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	zrtn	ptyp	od8x					phos	7	6	5	4	3	2	1	0			fdir	cdir	pyfx		adin	fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)	1	adin	Interpolation A/D compensation invalid	Interpolation A/D compensation valid	2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid	3	pyfx	Normal excitation	Position loop excitation fixed (strong)	4	cdir	Command polarity (+)	Command polarity (-)	5	fdir	Position detector polarity (+)	Position detector polarity (-)	6				7				8	phos	Normal (no compensation)	Synchronized tapping position compensation valid	9				A				B				C				D	od8x	Magnification of excessive error width × 8 times invalid	Magnification of excessive error width × 8 times valid	E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop	F	zrtn	Zero point return direction: CCW	Zero point return direction: CW	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																			
zrtn	ptyp	od8x					phos																																																																																																			
7	6	5	4	3	2	1	0																																																																																																			
		fdir	cdir	pyfx		adin	fclx																																																																																																			
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																							
0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)																																																																																																							
1	adin	Interpolation A/D compensation invalid	Interpolation A/D compensation valid																																																																																																							
2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid																																																																																																							
3	pyfx	Normal excitation	Position loop excitation fixed (strong)																																																																																																							
4	cdir	Command polarity (+)	Command polarity (-)																																																																																																							
5	fdir	Position detector polarity (+)	Position detector polarity (-)																																																																																																							
6																																																																																																										
7																																																																																																										
8	phos	Normal (no compensation)	Synchronized tapping position compensation valid																																																																																																							
9																																																																																																										
A																																																																																																										
B																																																																																																										
C																																																																																																										
D	od8x	Magnification of excessive error width × 8 times invalid	Magnification of excessive error width × 8 times valid																																																																																																							
E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop																																																																																																							
F	zrtn	Zero point return direction: CCW	Zero point return direction: CW																																																																																																							

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3394 (PR)	SP194	VGTP	Synchronized tapping speed loop gain proportional term	Set the speed loop proportional gain in synchronized tapping mode.	0 to 1000 (1/s)	63
3395 (PR)	SP195	VGTI	Synchronized tapping speed loop gain integral term	Set the speed loop integral gain in synchronized tapping mode.	0 to 1000 (0.1 1/s)	60
3396 (PR)	SP196	VGTD	Synchronized tapping speed loop gain delay advance term	Set the speed loop delay advance gain in synchronized tapping mode. When this parameter is set to "0", PI control is applied.	0 to 1000 (0.1 1/s)	15
3397	SP197			This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3398 (PR)	SP198	VCGT	Synchronized tapping target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP194 (VGTP) at the maximum motor speed defined in SP017 (TSP) in synchronized tapping mode.	0 to 100 (%)	100
3399 (PR)	SP199	VCST	Synchronized tapping change starting speed of variable speed loop proportional gain	Set the speed where the speed loop proportional gain change starts during synchronized tapping. 	0 to 32767 (r/min)	0
3400 (PR)	SP200	FFC1	Synchronized tapping acceleration feed forward gain (gear 1)	Set the acceleration feed forward gain for selection of gear 000 during synchronized tapping. This parameter should be used when an error of relative position to Z-axis servo is large.	0 to 1000 (%)	0
3401 (PR)	SP201	FFC2	Synchronized tapping acceleration feed forward gain (gear 2)	Set the acceleration feed forward gain for selection of gear 001 during synchronized tapping.	0 to 1000 (%)	0
3402 (PR)	SP202	FFC3	Synchronized tapping acceleration feed forward gain (gear 3)	Set the acceleration feed forward gain for selection of gear 010 during synchronized tapping.	0 to 1000 (%)	0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3403 (PR)	SP203	FFC4	Synchronized tapping acceleration feed forward gain (gear 4)	Set the acceleration feed forward gain for selection of gear 011 during synchronized tapping.	0 to 1000 (%)	0
3404 to 3413	SP204 to SP213			Not used. Set to "0".	0	0
3414	SP214	TZRN	Synchronized tapping zero point return speed	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the zero point return speed used when the speed loop changes to the position loop.	0 to 500 (r/min)	50
3415	SP215	TPDT	Synchronized tapping zero point return deceleration rate	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the deceleration rate where the machine starts to decelerate when it returns to the target stop point during synchronized tapping zero point return. When the machine tends to overshoot at the stop point set a smaller value.	0 to 10000 (pulse)	1
3416	SP216	TPST	Synchronized tapping zero point return shift amount	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the synchronized tapping zero point position.	0 to 4095	0
3417	SP217	TINP	Synchronized tapping in-position width	Set the position error range for output of the in-position during synchronized tapping.	1 to 2880 (1/16°)	16
3418 (PR)	SP218	TODR	Synchronized tapping excessive error width	Set the excessive error width during synchronized tapping.	1 to 32767 (pulse) (1 pulse = 0.088°)	32767
3419 (PR)	SP219	IQGT	Synchronized tapping current loop gain magnification 1	Set the magnification of current loop gain (torque component) during synchronized tapping.	1 to 1000 (%)	100
3420 (PR)	SP220	IDGT	Synchronized tapping current loop gain magnification 2	Set the magnification of current loop gain (excitation component) during synchronized tapping.	1 to 1000 (%)	100

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3421	SP221	PG2T	Synchronized tapping position loop gain 2	Set the second position loop gain when high-gain control is applied during synchronized tapping. When this parameter is not used, set to "0".	0 to 999 (1/s)	0
3422	SP222	PG3T	Synchronized tapping position loop gain 3	Set the third position loop gain when high-gain control is applied during synchronized tapping. When this parameter is not used, set to "0".	0 to 999 (1/s)	0
3423	SP223	SPDV	Speed monitor speed	Set the spindle limit speed in the door open state. (Invalid when 0 is set.) If the spindle end speed exceeds this setting value when the door is open, the speed monitor error (5E) will occur.	0 to 800 (r/min)	0
3424	SP224	SPDF	Speed monitor time	Set the time (continuous) to detect alarms. (Detected instantly when 0 is set.)	0 to 2813 (3.5ms)	0
3425	SP225	OXKPH	Position loop gain magnification after orientation gain changeover (H coil)	If gain changeover is valid (SP097: SPEC0-bitC=1) during orientation, set the magnification of each gain changed to after in-position.	0 to 2560 (1/256-fold)	0
3426	SP226	OXKPL	Position loop gain magnification after orientation gain changeover (L coil)		0 to 2560 (1/256-fold)	0
3427	SP227	OXVKP	Speed loop proportional gain magnification after orientation gain changeover		0 to 2560 (1/256-fold)	0
3428	SP228	OXVKI	Speed loop cumulative gain magnification after orientation gain changeover	If gain changeover is valid (SP097: SPEC0-bitC=1) during orientation, set the magnification of each gain changed to after in-position.	0 to 2560 (1/256-fold)	0
3429	SP229	OXSTF	Orientation virtual target shift amount	Set the amount to shift the target position when orientation virtual target position is valid (SP097: SPEC0-bitD=1).	0 to 2048 (360°/4096)	0
3430 to 3432	SP230 to SP232			Use not possible.		

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3433 (PR)	SP233	JL	Disturbance observer general inertia scale Setting value = $\frac{\text{Motor inertia} + \text{load inertia}}{\text{Motor inertia}} \times 100$ (Normally, set "100" or more. When less than "50" is set, the setting will be invalid.)	0 to 5000 (%)	0	
3434 (PR)	SP234	OBS1	Disturbance observer low path filter frequency Setting (1/s) = $2\pi f$ f: Approx. 1.5 times the disturbance frequency	0 to 1000 (1/s)	0	
3435 (PR)	SP235	OBS2	Disturbance observer gain	0 to 500 (%)	0	
3436	SP236	OBS3		This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3437	SP237			Not used. Set to "0".	0	0
3438 to 3441	SP238 to SP241			Use not possible.	0	0
3442	SP242	Vavx		This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3443	SP243	UTTM			0	0
3444	SP244	OPLP			0	0
3445	SP245	PGHS			0	0
3446	SP246	TEST			0	0
3447 to 3448	SP247 to SP248			Use not possible.	0	0
3449	SP249	SM0	Speed meter speed	Set the motor rotation speed when the speed meter 10V is output. When set to "0", this parameter becomes the same as SP017 (TSP).	0 to 32767 (r/min)	0
3450	SP250	LM0	Load meter voltage	Set the voltage when the load meter 120% is output. When set to "0", this becomes 10V.	0 to 10 (V)	0
3451 to 3452	SP251 to SP252			Use not possible.	0	0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items		Details	Setting range	Standard setting	
3453	SP253	DA1NO	D/A output channel 1 data number	Set the output data number for channel 1 of the D/A output function. When set to "0", the output is speedometer. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767	0
3454	SP254	DA2NO	D/A output channel 2 data number	Set the output data number for channel 2 of the D/A output function. When set to "0", the output is load meter. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767	0
3455	SP255	DA1MPY	DA output channel 1 magnification	Set the data magnification for channel 1 of the D/A output function. The output magnification is the setting value divided by 256. When set to "0", the output magnification becomes 1-fold, in the same manner as when "256" is set. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767 (1/256-fold)	0
3456	SP256	DA2MPY	DA output channel 2 magnification	Set the data magnification for channel 2 of the D/A output function. The output magnification is the setting value divided by 256. When set to "0", the output magnification becomes 1-fold, in the same manner as when "256" is set. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767 (1/256-fold)	0

8. Spindle Parameters
8.3 MDS-B-SP/SPH, MDS-C1-SP/SPH

No.	Items			Details	Setting range	Standard setting
3457 (PR) to 3520 (PR)	SP257 to SP320	RPM BSD	Motor constant (H coil)	<p>This parameter is valid only in the following two conditional cases:</p> <p>(a) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=0 Set the motor constants when using a special motor, not described in the SP040 (MTYP) explanation and when not using the coil changeover motor.</p> <p>(b) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=1 Set the motor constant of the H coil of the coil changeover motor.</p> <p>(Note) It is not allowed for the user to change the setting.</p>	0000 to FFFF HEX setting	0000
3521 (PR) to 3584 (PR)	SP321 to SP384	RPML BSDL	Motor constant (L coil)	<p>This parameter is valid only in the following conditional case:</p> <p>(a) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=1 Set the motor constant of the L coil of the coil changeover motor.</p> <p>(Note) It is not allowed for the user to change the setting.</p>	0000 to FFFF HEX setting	0000

8. Spindle Parameters
8.4 MDS-C1-SPM

8.4 MDS-C1-SPM

The spindle parameter setting and display method will differ according to the NC being used, so refer to Instruction Manual for each NC and the following spindles.

MELDAS AC Servo and Spindle MDS-C1 Series Specifications Manual BNP-C3000

For parameters marked with a (PR) in the tables, turn the NC power OFF after setting. The parameters will be valid after the power is turned ON again.

The "fixed control constants" and "fixed control bits" in this section are set by Mitsubishi.

⚠ CAUTION

- ⚠ Do not make remarkable adjustments or changes of the parameters as the operation may become unstable.
- ⚠ In the explanation on bits, set all bits not used, including blank bits, to "0".

No.	Items	Details	Setting range	Standard setting	
3201	SP001 PGM	Magnetic sensor and motor built-in encoder orientation position loop gain	As the set value is larger, the orientation time becomes shorter and servo rigidity is increased. However, vibration is increased and the machine becomes likely to overshoot.	0 to 2000 (0.1 1/s)	100
3202	SP002 PGE	Encoder orientation position loop gain	As the set value is larger, the orientation time becomes shorter and servo rigidity is increased. However, vibration is increased and the machine becomes likely to overshoot.	0 to 2000 (0.1 1/s)	100
3203	SP003 PGC0	C-axis non-cutting position loop gain	Set the position loop gain in C-axis non-cutting mode. During non-cutting (rapid traverse, etc.) with the C axis control, this position loop gain setting is valid.	1 to 200 (1/s)	15
3204	SP004 OINP	Orientation in-position width	Set the position error range in which an orientation completion signal is output.	1 to 2880 (1/16 °)	16
3205 (PR)	SP005 OSP	Orientation mode changing speed limit value	Set the motor speed limit value to be used when the speed loop is changed to the position loop in orientation mode. When this parameter is set to "0", SP017 (TSP) becomes the limit value.	0 to 32767 (r/min)	0
3206	SP006 CSP	Orientation mode deceleration rate	As the set value is larger, the orientation time becomes shorter. However, the machine becomes likely to overshoot.	1 to 1000	20
3207	SP007 OPST	In-position shift amount for orientation	Set the stop position for orientation. (i) Motor built-in encoder, encoder: Set the value by dividing 360° by 4096. (ii) Magnetic sensor: Divide -5° to +5° by 1024 and put 0° for 0.	(i) 0 to 4095 (ii) -512 to 512	0
3208	SP008		Not used. Set to "0".	0	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3209	SP009	PGT	Synchronized tapping Position loop gain	Set the spindle position loop gain in synchronized tapping mode.	1 to 200 (1/s)	15
3210	SP010	PGS	Spindle synchronous position loop gain	Set the spindle position loop gain in spindle synchronization mode.	1 to 200 (1/s)	15
3211 to 3216	SP011 to SP016			Use not possible.	0	0
3217 (PR)	SP017	TSP	Maximum motor speed	Set the maximum motor speed of the spindle.	1 to 32767 (r/min)	6000
3218 (PR)	SP018	ZSP	Motor zero speed	Set the motor speed for which zero-speed output is performed.	1 to 1000 (r/min)	50
3219 (PR)	SP019	CSN1	Speed cushion 1	Set the time constant for a speed command from "0" to the maximum speed. (This parameter is invalid in position loop mode.)	1 to 32767 (10ms)	30
3220 (PR)	SP020	SDTS	Speed detection set value	Set the motor speed so for which speed detection output is performed. Usually, the setting value is 10% of SP017 (TSP).	0 to 32767 (r/min)	600
3221	SP021	TLM1	Torque limit 1	Set the torque limit rate for torque limit signal 001.	0 to 120 (%)	10
3222 (PR)	SP022	VGNP1	Speed loop gain proportional term under speed control	Set the speed loop proportional gain in speed control mode. When the gain is increased, response is improved but vibration and sound become larger.	0 to 1000 (1/s)	63
3223 (PR)	SP023	VGNI1	Speed loop gain integral term under speed control	Set the speed loop integral gain in speed control mode. Usually, set a value in proportion to SP022 (VGNP1).	0 to 1000 (0.1 1/s)	60
3224	SP024			Use not possible.	0	0
3225 (PR)	SP025	GRA1	Spindle gear teeth count 1	Set the number of gear teeth of the spindle corresponding to gear 000.	1 to 32767	1
3226 (PR)	SP026	GRA2	Spindle gear teeth count 2	Set the number of gear teeth of the spindle corresponding to gear 001.	1 to 32767	1
3227 (PR)	SP027	GRA3	Spindle gear teeth count 3	Set the number of gear teeth of the spindle corresponding to gear 010.	1 to 32767	1
3228 (PR)	SP028	GRA4	Spindle gear teeth count 4	Set the number of gear teeth of the spindle corresponding to gear 011.	1 to 32767	1
3229 (PR)	SP029	GRB1	Motor shaft gear teeth count 1	Set the number of gear teeth of the motor shaft corresponding to gear 000.	1 to 32767	1

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items			Details	Setting range	Standard setting																																																																																																												
3230 (PR)	SP030	GRB2	Motor shaft gear teeth count 2	Set the number of gear teeth of the motor shaft corresponding to gear 001.	1 to 32767	1																																																																																																												
3231 (PR)	SP031	GRB3	Motor shaft gear teeth count 3	Set the number of gear teeth of the motor shaft corresponding to gear 010.	1 to 32767	1																																																																																																												
3232 (PR)	SP032	GRB4	Motor shaft gear teeth count 4	Set the number of gear teeth of the motor shaft corresponding to gear 011.	1 to 32767	1																																																																																																												
3233 (PR)	SP033	SFNC1	Spindle function 1	Set the spindle function 1 in bit units. <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>poff</td><td></td><td></td><td>ront</td><td></td><td></td><td>pycal</td><td>pychg</td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td>pyst</td><td>pyoff</td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> </table> (Note) Always set "0" for the empty bits. <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr><td>0</td><td></td><td></td><td></td></tr> <tr><td>1</td><td></td><td></td><td></td></tr> <tr><td>2</td><td></td><td></td><td></td></tr> <tr><td>3</td><td></td><td></td><td></td></tr> <tr><td>4</td><td></td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td><td></td></tr> <tr><td>B</td><td></td><td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td></tr> <tr><td>C</td><td>ront</td><td>Normal ready ON</td><td>High-speed ready ON</td></tr> <tr><td>D</td><td></td><td colspan="2">This is used by Mitsubishi. Set to "0" unless particularly designated.</td></tr> <tr><td>E</td><td></td><td></td><td></td></tr> <tr><td>F</td><td>poff</td><td>Contactora hold at NC power OFF invalid</td><td>Contactora hold at NC power OFF valid</td></tr> </tbody> </table>	F	E	D	C	B	A	9	8	poff			ront			pycal	pychg									7	6	5	4	3	2	1	0	pyst	pyoff							bit	Name	Meaning when set to 0	Meaning when set to 1	0				1				2				3				4				5				6				7				8				9				A				B		This is used by Mitsubishi. Set to "0" unless particularly designated.		C	ront	Normal ready ON	High-speed ready ON	D		This is used by Mitsubishi. Set to "0" unless particularly designated.		E				F	poff	Contactora hold at NC power OFF invalid	Contactora hold at NC power OFF valid	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																											
poff			ront			pycal	pychg																																																																																																											
7	6	5	4	3	2	1	0																																																																																																											
pyst	pyoff																																																																																																																	
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																															
0																																																																																																																		
1																																																																																																																		
2																																																																																																																		
3																																																																																																																		
4																																																																																																																		
5																																																																																																																		
6																																																																																																																		
7																																																																																																																		
8																																																																																																																		
9																																																																																																																		
A																																																																																																																		
B		This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																																
C	ront	Normal ready ON	High-speed ready ON																																																																																																															
D		This is used by Mitsubishi. Set to "0" unless particularly designated.																																																																																																																
E																																																																																																																		
F	poff	Contactora hold at NC power OFF invalid	Contactora hold at NC power OFF valid																																																																																																															

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																				
3234 (PR)	SP034	SFNC2 Spindle function 2	<p>Set the spindle function 2 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;"></td><td style="width:20px; height:20px;">mkc2</td><td style="width:20px; height:20px;">mkch</td><td style="width:20px; height:20px;">Mk3c</td><td style="width:20px; height:20px;">mts1</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>mts1</td> <td>Special motor constant invalid</td> <td>Special motor constant setting valid</td> </tr> <tr> <td>1</td> <td>Mk3c</td> <td>3-step coil changeover function invalid</td> <td>3-step coil changeover function valid</td> </tr> <tr> <td>2</td> <td>mkch</td> <td>Coil switch function invalid</td> <td>Coil switch function valid</td> </tr> <tr> <td>3</td> <td>mkc2</td> <td>Coil switch specification 2 invalid</td> <td>Coil switch specification 2 valid (Note1) (Note2)</td> </tr> <tr><td>4</td><td></td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td><td></td></tr> <tr><td>E</td><td></td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td><td></td></tr> </tbody> </table> <p>(Note1) To validate bit3(mkc2), NC side needs to prepare. (Note2) Always turn the bit2 at the same time to use bit3.</p>	F	E	D	C	B	A	9	8									7	6	5	4	3	2	1	0					mkc2	mkch	Mk3c	mts1	bit	Name	Meaning when set to 0	Meaning when set to 1	0	mts1	Special motor constant invalid	Special motor constant setting valid	1	Mk3c	3-step coil changeover function invalid	3-step coil changeover function valid	2	mkch	Coil switch function invalid	Coil switch function valid	3	mkc2	Coil switch specification 2 invalid	Coil switch specification 2 valid (Note1) (Note2)	4				5				6				7				8				9				A				B				C				D				E				F				0000 to FFFF HEX setting	000C
F	E	D	C	B	A	9	8																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
				mkc2	mkch	Mk3c	mts1																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	mts1	Special motor constant invalid	Special motor constant setting valid																																																																																																						
1	Mk3c	3-step coil changeover function invalid	3-step coil changeover function valid																																																																																																						
2	mkch	Coil switch function invalid	Coil switch function valid																																																																																																						
3	mkc2	Coil switch specification 2 invalid	Coil switch specification 2 valid (Note1) (Note2)																																																																																																						
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8																																																																																																									
9																																																																																																									
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items			Details	Setting range	Standard setting																																																																																																				
3235 (PR)	SP035	SFNC3	Spindle function 3	<p>Set the spindle function 3 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td>mwid</td><td>lwid</td><td>hwid</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>hwid</td> <td>H coil output characteristics change invalid</td> <td>H coil output characteristics change valid</td> </tr> <tr> <td>1</td> <td>lwid</td> <td>L coil output characteristics change invalid</td> <td>L coil output characteristics change valid</td> </tr> <tr> <td>2</td> <td>mwid</td> <td>M coil output characteristics change invalid</td> <td>M coil output characteristics change valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td></td> <td colspan="2">(Used with SPJ.)</td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	7	6	5	4	3	2	1	0	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	mwid	lwid	hwid	bit	Name	Meaning when set to 0	Meaning when set to 1	0	hwid	H coil output characteristics change invalid	H coil output characteristics change valid	1	lwid	L coil output characteristics change invalid	L coil output characteristics change valid	2	mwid	M coil output characteristics change invalid	M coil output characteristics change valid	3				4				5				6				7				8		(Used with SPJ.)		9				A				B				C				D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																			
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																																																																																																			
7	6	5	4	3	2	1	0																																																																																																			
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	mwid	lwid	hwid																																																																																																			
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																							
0	hwid	H coil output characteristics change invalid	H coil output characteristics change valid																																																																																																							
1	lwid	L coil output characteristics change invalid	L coil output characteristics change valid																																																																																																							
2	mwid	M coil output characteristics change invalid	M coil output characteristics change valid																																																																																																							
3																																																																																																										
4																																																																																																										
5																																																																																																										
6																																																																																																										
7																																																																																																										
8		(Used with SPJ.)																																																																																																								
9																																																																																																										
A																																																																																																										
B																																																																																																										
C																																																																																																										
D																																																																																																										
E																																																																																																										
F																																																																																																										

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																				
3236	SP036		Not used. Set to "0".																																																																																																						
3237 (PR)	SP037	SFNC5 Spindle function 5	<p>Set the spindle function 5 in bit units.</p> <table border="1" style="width: 100%; text-align: center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td>nsno</td><td>nosg</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td>plgo</td><td><input type="checkbox"/></td><td>enco</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width: 100%; text-align: center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>enco</td> <td>Encoder orientation invalid</td> <td>Encoder orientation valid</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>plgo</td> <td>PLG orientation invalid</td> <td>PLG orientation valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>nosg</td> <td>No-signal detection type (Always monitoring)</td> <td>Monitoring only in position loop or orientation-mode</td> </tr> <tr> <td>9</td> <td>nsno</td> <td>No-signal detection valid</td> <td>No-signal detection invalid</td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table> <p>(Note) For bit0 to 2, do not set two bits or more to "1" at the same time.</p>	F	E	D	C	B	A	9	8	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	nsno	nosg	7	6	5	4	3	2	1	0	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	plgo	<input type="checkbox"/>	enco	bit	Name	Meaning when set to 0	Meaning when set to 1	0	enco	Encoder orientation invalid	Encoder orientation valid	1				2	plgo	PLG orientation invalid	PLG orientation valid	3				4				5				6				7				8	nosg	No-signal detection type (Always monitoring)	Monitoring only in position loop or orientation-mode	9	nsno	No-signal detection valid	No-signal detection invalid	A				B				C				D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																		
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	nsno	nosg																																																																																																		
7	6	5	4	3	2	1	0																																																																																																		
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	plgo	<input type="checkbox"/>	enco																																																																																																		
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																						
0	enco	Encoder orientation invalid	Encoder orientation valid																																																																																																						
1																																																																																																									
2	plgo	PLG orientation invalid	PLG orientation valid																																																																																																						
3																																																																																																									
4																																																																																																									
5																																																																																																									
6																																																																																																									
7																																																																																																									
8	nosg	No-signal detection type (Always monitoring)	Monitoring only in position loop or orientation-mode																																																																																																						
9	nsno	No-signal detection valid	No-signal detection invalid																																																																																																						
A																																																																																																									
B																																																																																																									
C																																																																																																									
D																																																																																																									
E																																																																																																									
F																																																																																																									

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																												
3238 (PR)	SP038	SFNC6 Spindle function 6	<p>Set the spindle function 6 in bit units.</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td></td><td></td><td></td><td>XFzs</td><td></td><td></td><td>pl80</td><td>sdt2</td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td>hzm</td><td>orm</td><td></td><td>tdn</td><td>plg2</td><td>pftm</td><td></td><td>alty</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>alty</td> <td>Deceleration stop during special alarm invalid</td> <td>Deceleration stop during special alarm valid</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>pftm</td> <td>Encoder feedback serial communication invalid</td> <td>Encoder feedback serial communication valid</td> </tr> <tr> <td>3</td> <td>plg2</td> <td>Semi-closed pulse output signal x2 invalid</td> <td>Semi-closed pulse output signal x2 valid</td> </tr> <tr> <td>4</td> <td>tdn</td> <td>Fixed control bit</td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> </tr> <tr> <td>6</td> <td>orm</td> <td>Orientation start memo invalid</td> <td>Orientation start memo valid</td> </tr> <tr> <td>7</td> <td>hzm</td> <td>Fixed control bit</td> <td></td> </tr> <tr> <td>8</td> <td>sdt2</td> <td></td> <td></td> </tr> <tr> <td>9</td> <td>pl80</td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td>XFzs</td> <td>Fixed control bit</td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8				XFzs			pl80	sdt2									7	6	5	4	3	2	1	0	hzm	orm		tdn	plg2	pftm		alty	bit	Name	Meaning when set to 0	Meaning when set to 1	0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid	1				2	pftm	Encoder feedback serial communication invalid	Encoder feedback serial communication valid	3	plg2	Semi-closed pulse output signal x2 invalid	Semi-closed pulse output signal x2 valid	4	tdn	Fixed control bit		5				6	orm	Orientation start memo invalid	Orientation start memo valid	7	hzm	Fixed control bit		8	sdt2			9	pl80			A				B				C	XFzs	Fixed control bit		D				E				F				0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																										
			XFzs			pl80	sdt2																																																																																																										
7	6	5	4	3	2	1	0																																																																																																										
hzm	orm		tdn	plg2	pftm		alty																																																																																																										
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																														
0	alty	Deceleration stop during special alarm invalid	Deceleration stop during special alarm valid																																																																																																														
1																																																																																																																	
2	pftm	Encoder feedback serial communication invalid	Encoder feedback serial communication valid																																																																																																														
3	plg2	Semi-closed pulse output signal x2 invalid	Semi-closed pulse output signal x2 valid																																																																																																														
4	tdn	Fixed control bit																																																																																																															
5																																																																																																																	
6	orm	Orientation start memo invalid	Orientation start memo valid																																																																																																														
7	hzm	Fixed control bit																																																																																																															
8	sdt2																																																																																																																
9	pl80																																																																																																																
A																																																																																																																	
B																																																																																																																	
C	XFzs	Fixed control bit																																																																																																															
D																																																																																																																	
E																																																																																																																	
F																																																																																																																	

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																				
3239 (PR)	SP039	ATYP	Amplifier type	Set the amplifier type. Set each amplifier type or "0" <table border="1" data-bbox="592 370 1050 978"> <thead> <tr> <th>Parameter setting</th> <th>Amplifier type</th> </tr> </thead> <tbody> <tr><td>0000</td><td>—</td></tr> <tr><td>0001</td><td>—</td></tr> <tr><td>0002</td><td>—</td></tr> <tr><td>0003</td><td>—</td></tr> <tr><td>0004</td><td>—</td></tr> <tr><td>0005</td><td>—</td></tr> <tr><td>0006</td><td>—</td></tr> <tr><td>0007</td><td>SPM-110</td></tr> <tr><td>0008</td><td>SPM-150</td></tr> <tr><td>0009</td><td>SPM-185</td></tr> <tr><td>000A</td><td>SPM-220</td></tr> <tr><td>000B</td><td>SPM-260</td></tr> <tr><td>000C</td><td>SPM-300</td></tr> <tr><td>000D</td><td>(SPM-370)</td></tr> <tr><td>000E</td><td>(SPM-450)</td></tr> <tr><td>000F</td><td>—</td></tr> <tr><td>0010</td><td>—</td></tr> </tbody> </table> <p data-bbox="582 1002 1090 1069">(Note) (SPM-370) and (SPM-450) are used with MDS-B-SPM.</p>	Parameter setting	Amplifier type	0000	—	0001	—	0002	—	0003	—	0004	—	0005	—	0006	—	0007	SPM-110	0008	SPM-150	0009	SPM-185	000A	SPM-220	000B	SPM-260	000C	SPM-300	000D	(SPM-370)	000E	(SPM-450)	000F	—	0010	—	0000 to FFFF HEX setting	0000																																															
Parameter setting	Amplifier type																																																																																								
0000	—																																																																																								
0001	—																																																																																								
0002	—																																																																																								
0003	—																																																																																								
0004	—																																																																																								
0005	—																																																																																								
0006	—																																																																																								
0007	SPM-110																																																																																								
0008	SPM-150																																																																																								
0009	SPM-185																																																																																								
000A	SPM-220																																																																																								
000B	SPM-260																																																																																								
000C	SPM-300																																																																																								
000D	(SPM-370)																																																																																								
000E	(SPM-450)																																																																																								
000F	—																																																																																								
0010	—																																																																																								
3240 (PR)	SP040	MTYP	Motor type	<table border="1" data-bbox="596 1096 1134 1266"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td><td><input type="checkbox"/></td> </tr> </table> <table border="1" data-bbox="592 1325 1134 1768"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Details</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>motr</td> <td>Set the motor type. Set "0" when using a special motor.</td> </tr> <tr><td>1</td><td></td><td></td></tr> <tr><td>2</td><td></td><td></td></tr> <tr><td>3</td><td></td><td></td></tr> <tr><td>4</td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td></tr> <tr><td>E</td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td></tr> </tbody> </table>	F	E	D	C	B	A	9	8	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	7	6	5	4	3	2	1	0	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	bit	Name	Details	0	motr	Set the motor type. Set "0" when using a special motor.	1			2			3			4			5			6			7			8			9			A			B			C			D			E			F			0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																		
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																																																																																		
7	6	5	4	3	2	1	0																																																																																		
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																																																																																		
bit	Name	Details																																																																																							
0	motr	Set the motor type. Set "0" when using a special motor.																																																																																							
1																																																																																									
2																																																																																									
3																																																																																									
4																																																																																									
5																																																																																									
6																																																																																									
7																																																																																									
8																																																																																									
9																																																																																									
A																																																																																									
B																																																																																									
C																																																																																									
D																																																																																									
E																																																																																									
F																																																																																									

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																																																																																																																																											
3241 (PR)	SP041	PTYP Power supply type	<p>Power supply type</p> <table border="1" style="width:100%; text-align:center;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td colspan="4">amp</td> <td colspan="4">rtyp</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td colspan="8">ptyp</td> </tr> </table> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>bit</th> <th>Explanation</th> </tr> </thead> <tbody> <tr> <td>0</td> <td rowspan="3">When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.</td> </tr> <tr> <td>1</td> </tr> <tr> <td>2</td> </tr> <tr> <td>3</td> <td rowspan="10"> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>Set-ting</th> <th>0x</th> <th>1x</th> <th>2x</th> <th>3x</th> <th>4x</th> <th>5x</th> <th>6x</th> <th>7x</th> <th>8x</th> </tr> </thead> <tbody> <tr> <td>x0</td> <td>Not used</td> <td></td> <td></td> <td>CV-300</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x1</td> <td></td> <td>CV-110</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-10</td> </tr> <tr> <td>x2</td> <td></td> <td></td> <td>CV-220</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-15</td> </tr> <tr> <td>x3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-22</td> </tr> <tr> <td>x4</td> <td>CV-37</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-37</td> </tr> <tr> <td>x5</td> <td></td> <td>CV-150</td> <td></td> <td></td> <td>CV-450</td> <td>CV-550</td> <td></td> <td></td> <td></td> </tr> <tr> <td>x6</td> <td>CV-55</td> <td></td> <td>CV-260</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-55</td> </tr> <tr> <td>x7</td> <td></td> <td></td> <td></td> <td>CV-370</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x8</td> <td>CV-75</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-75</td> </tr> <tr> <td>x9</td> <td></td> <td>CV-185</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-90</td> </tr> </tbody> </table> </td> </tr> <tr> <td>8</td> <td rowspan="10">Set the regenerative resistor type when MDS-A-CR is used.</td> <td rowspan="10"> <table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>Set-ting</th> <th>Regenerative resistor model name</th> <th>Resistance value</th> <th>Capacity</th> </tr> </thead> <tbody> <tr> <td>0</td> <td colspan="3">MDS-C1-CV (Setting when using power supply regeneration)</td> </tr> <tr> <td>1</td> <td>GZG200W260HMJ</td> <td>26Ω</td> <td>80W</td> </tr> <tr> <td>2</td> <td>GZG300W130HMJ×2</td> <td>26Ω</td> <td>150W</td> </tr> <tr> <td>3</td> <td>MR-RB30</td> <td>13Ω</td> <td>300W</td> </tr> <tr> <td>4</td> <td>MR-RB50</td> <td>13Ω</td> <td>500W</td> </tr> <tr> <td>5</td> <td>GZG200W200HMJ×3</td> <td>6.7Ω</td> <td>350W</td> </tr> <tr> <td>6</td> <td>GZG300W200HMJ×3</td> <td>6.7Ω</td> <td>500W</td> </tr> <tr> <td>7</td> <td>R-UNIT-1</td> <td>30Ω</td> <td>700W</td> </tr> <tr> <td>8</td> <td>R-UNIT-2</td> <td>15Ω</td> <td>700W</td> </tr> <tr> <td>9</td> <td>R-UNIT-3</td> <td>15Ω</td> <td>2100W</td> </tr> <tr> <td>A to D</td> <td colspan="3">No setting</td> </tr> <tr> <td>E</td> <td colspan="3">Large capacity + ready ON high-speed sequence</td> </tr> <tr> <td>F</td> <td colspan="3">Ready ON high-speed sequence</td> </tr> </tbody> </table> </td> </tr> <tr> <td>9</td> <td rowspan="4">Always set to "0".</td> <td rowspan="4"></td> </tr> <tr> <td>A</td> </tr> <tr> <td>B</td> </tr> <tr> <td></td> </tr> <tr> <td>C</td> <td rowspan="4">Always set to "0".</td> <td rowspan="4"></td> </tr> <tr> <td>D</td> </tr> <tr> <td>E</td> </tr> <tr> <td>F</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	amp				rtyp				7	6	5	4	3	2	1	0	ptyp								bit	Explanation	0	When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.	1	2	3	<table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>Set-ting</th> <th>0x</th> <th>1x</th> <th>2x</th> <th>3x</th> <th>4x</th> <th>5x</th> <th>6x</th> <th>7x</th> <th>8x</th> </tr> </thead> <tbody> <tr> <td>x0</td> <td>Not used</td> <td></td> <td></td> <td>CV-300</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x1</td> <td></td> <td>CV-110</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-10</td> </tr> <tr> <td>x2</td> <td></td> <td></td> <td>CV-220</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-15</td> </tr> <tr> <td>x3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-22</td> </tr> <tr> <td>x4</td> <td>CV-37</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-37</td> </tr> <tr> <td>x5</td> <td></td> <td>CV-150</td> <td></td> <td></td> <td>CV-450</td> <td>CV-550</td> <td></td> <td></td> <td></td> </tr> <tr> <td>x6</td> <td>CV-55</td> <td></td> <td>CV-260</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-55</td> </tr> <tr> <td>x7</td> <td></td> <td></td> <td></td> <td>CV-370</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x8</td> <td>CV-75</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-75</td> </tr> <tr> <td>x9</td> <td></td> <td>CV-185</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-90</td> </tr> </tbody> </table>	Set-ting	0x	1x	2x	3x	4x	5x	6x	7x	8x	x0	Not used			CV-300						x1		CV-110							CR-10	x2			CV-220						CR-15	x3									CR-22	x4	CV-37								CR-37	x5		CV-150			CV-450	CV-550				x6	CV-55		CV-260						CR-55	x7				CV-370						x8	CV-75								CR-75	x9		CV-185							CR-90	8	Set the regenerative resistor type when MDS-A-CR is used.	<table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>Set-ting</th> <th>Regenerative resistor model name</th> <th>Resistance value</th> <th>Capacity</th> </tr> </thead> <tbody> <tr> <td>0</td> <td colspan="3">MDS-C1-CV (Setting when using power supply regeneration)</td> </tr> <tr> <td>1</td> <td>GZG200W260HMJ</td> <td>26Ω</td> <td>80W</td> </tr> <tr> <td>2</td> <td>GZG300W130HMJ×2</td> <td>26Ω</td> <td>150W</td> </tr> <tr> <td>3</td> <td>MR-RB30</td> <td>13Ω</td> <td>300W</td> </tr> <tr> <td>4</td> <td>MR-RB50</td> <td>13Ω</td> <td>500W</td> </tr> <tr> <td>5</td> <td>GZG200W200HMJ×3</td> <td>6.7Ω</td> <td>350W</td> </tr> <tr> <td>6</td> <td>GZG300W200HMJ×3</td> <td>6.7Ω</td> <td>500W</td> </tr> <tr> <td>7</td> <td>R-UNIT-1</td> <td>30Ω</td> <td>700W</td> </tr> <tr> <td>8</td> <td>R-UNIT-2</td> <td>15Ω</td> <td>700W</td> </tr> <tr> <td>9</td> <td>R-UNIT-3</td> <td>15Ω</td> <td>2100W</td> </tr> <tr> <td>A to D</td> <td colspan="3">No setting</td> </tr> <tr> <td>E</td> <td colspan="3">Large capacity + ready ON high-speed sequence</td> </tr> <tr> <td>F</td> <td colspan="3">Ready ON high-speed sequence</td> </tr> </tbody> </table>	Set-ting	Regenerative resistor model name	Resistance value	Capacity	0	MDS-C1-CV (Setting when using power supply regeneration)			1	GZG200W260HMJ	26Ω	80W	2	GZG300W130HMJ×2	26Ω	150W	3	MR-RB30	13Ω	300W	4	MR-RB50	13Ω	500W	5	GZG200W200HMJ×3	6.7Ω	350W	6	GZG300W200HMJ×3	6.7Ω	500W	7	R-UNIT-1	30Ω	700W	8	R-UNIT-2	15Ω	700W	9	R-UNIT-3	15Ω	2100W	A to D	No setting			E	Large capacity + ready ON high-speed sequence			F	Ready ON high-speed sequence			9	Always set to "0".		A	B		C	Always set to "0".		D	E	F
F	E	D	C	B	A	9	8																																																																																																																																																																																																																									
amp				rtyp																																																																																																																																																																																																																												
7	6	5	4	3	2	1	0																																																																																																																																																																																																																									
ptyp																																																																																																																																																																																																																																
bit	Explanation																																																																																																																																																																																																																															
0	When the CN4 connector of the drive unit and the power supply are connected, setting below is necessary. To validate the external emergency stop function, add 40h.																																																																																																																																																																																																																															
1																																																																																																																																																																																																																																
2																																																																																																																																																																																																																																
3	<table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>Set-ting</th> <th>0x</th> <th>1x</th> <th>2x</th> <th>3x</th> <th>4x</th> <th>5x</th> <th>6x</th> <th>7x</th> <th>8x</th> </tr> </thead> <tbody> <tr> <td>x0</td> <td>Not used</td> <td></td> <td></td> <td>CV-300</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x1</td> <td></td> <td>CV-110</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-10</td> </tr> <tr> <td>x2</td> <td></td> <td></td> <td>CV-220</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-15</td> </tr> <tr> <td>x3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-22</td> </tr> <tr> <td>x4</td> <td>CV-37</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-37</td> </tr> <tr> <td>x5</td> <td></td> <td>CV-150</td> <td></td> <td></td> <td>CV-450</td> <td>CV-550</td> <td></td> <td></td> <td></td> </tr> <tr> <td>x6</td> <td>CV-55</td> <td></td> <td>CV-260</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-55</td> </tr> <tr> <td>x7</td> <td></td> <td></td> <td></td> <td>CV-370</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>x8</td> <td>CV-75</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-75</td> </tr> <tr> <td>x9</td> <td></td> <td>CV-185</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>CR-90</td> </tr> </tbody> </table>	Set-ting	0x	1x	2x	3x	4x	5x	6x	7x	8x	x0	Not used			CV-300						x1		CV-110							CR-10	x2			CV-220						CR-15	x3										CR-22	x4	CV-37								CR-37	x5		CV-150			CV-450	CV-550				x6	CV-55		CV-260						CR-55	x7				CV-370						x8	CV-75								CR-75	x9		CV-185							CR-90																																																																																																																
Set-ting		0x	1x	2x	3x	4x	5x	6x	7x	8x																																																																																																																																																																																																																						
x0		Not used			CV-300																																																																																																																																																																																																																											
x1			CV-110							CR-10																																																																																																																																																																																																																						
x2				CV-220						CR-15																																																																																																																																																																																																																						
x3										CR-22																																																																																																																																																																																																																						
x4		CV-37								CR-37																																																																																																																																																																																																																						
x5			CV-150			CV-450	CV-550																																																																																																																																																																																																																									
x6		CV-55		CV-260						CR-55																																																																																																																																																																																																																						
x7					CV-370																																																																																																																																																																																																																											
x8	CV-75								CR-75																																																																																																																																																																																																																							
x9		CV-185							CR-90																																																																																																																																																																																																																							
8	Set the regenerative resistor type when MDS-A-CR is used.	<table border="1" style="width:100%; text-align:center;"> <thead> <tr> <th>Set-ting</th> <th>Regenerative resistor model name</th> <th>Resistance value</th> <th>Capacity</th> </tr> </thead> <tbody> <tr> <td>0</td> <td colspan="3">MDS-C1-CV (Setting when using power supply regeneration)</td> </tr> <tr> <td>1</td> <td>GZG200W260HMJ</td> <td>26Ω</td> <td>80W</td> </tr> <tr> <td>2</td> <td>GZG300W130HMJ×2</td> <td>26Ω</td> <td>150W</td> </tr> <tr> <td>3</td> <td>MR-RB30</td> <td>13Ω</td> <td>300W</td> </tr> <tr> <td>4</td> <td>MR-RB50</td> <td>13Ω</td> <td>500W</td> </tr> <tr> <td>5</td> <td>GZG200W200HMJ×3</td> <td>6.7Ω</td> <td>350W</td> </tr> <tr> <td>6</td> <td>GZG300W200HMJ×3</td> <td>6.7Ω</td> <td>500W</td> </tr> <tr> <td>7</td> <td>R-UNIT-1</td> <td>30Ω</td> <td>700W</td> </tr> <tr> <td>8</td> <td>R-UNIT-2</td> <td>15Ω</td> <td>700W</td> </tr> <tr> <td>9</td> <td>R-UNIT-3</td> <td>15Ω</td> <td>2100W</td> </tr> <tr> <td>A to D</td> <td colspan="3">No setting</td> </tr> <tr> <td>E</td> <td colspan="3">Large capacity + ready ON high-speed sequence</td> </tr> <tr> <td>F</td> <td colspan="3">Ready ON high-speed sequence</td> </tr> </tbody> </table>	Set-ting	Regenerative resistor model name	Resistance value	Capacity	0	MDS-C1-CV (Setting when using power supply regeneration)			1	GZG200W260HMJ	26Ω	80W	2	GZG300W130HMJ×2	26Ω	150W	3	MR-RB30	13Ω	300W	4	MR-RB50	13Ω	500W	5	GZG200W200HMJ×3	6.7Ω	350W	6	GZG300W200HMJ×3	6.7Ω	500W	7	R-UNIT-1	30Ω	700W	8	R-UNIT-2	15Ω	700W	9	R-UNIT-3	15Ω	2100W	A to D	No setting			E	Large capacity + ready ON high-speed sequence			F	Ready ON high-speed sequence																																																																																																																																																																								
Set-ting			Regenerative resistor model name	Resistance value	Capacity																																																																																																																																																																																																																											
0			MDS-C1-CV (Setting when using power supply regeneration)																																																																																																																																																																																																																													
1			GZG200W260HMJ	26Ω	80W																																																																																																																																																																																																																											
2			GZG300W130HMJ×2	26Ω	150W																																																																																																																																																																																																																											
3			MR-RB30	13Ω	300W																																																																																																																																																																																																																											
4			MR-RB50	13Ω	500W																																																																																																																																																																																																																											
5			GZG200W200HMJ×3	6.7Ω	350W																																																																																																																																																																																																																											
6			GZG300W200HMJ×3	6.7Ω	500W																																																																																																																																																																																																																											
7			R-UNIT-1	30Ω	700W																																																																																																																																																																																																																											
8	R-UNIT-2	15Ω	700W																																																																																																																																																																																																																													
9	R-UNIT-3	15Ω	2100W																																																																																																																																																																																																																													
A to D	No setting																																																																																																																																																																																																																															
E	Large capacity + ready ON high-speed sequence																																																																																																																																																																																																																															
F	Ready ON high-speed sequence																																																																																																																																																																																																																															
9	Always set to "0".																																																																																																																																																																																																																															
A																																																																																																																																																																																																																																
B																																																																																																																																																																																																																																
C	Always set to "0".																																																																																																																																																																																																																															
D																																																																																																																																																																																																																																
E																																																																																																																																																																																																																																
F																																																																																																																																																																																																																																

3242 (PR)	SP042	CRNG C-axis detector range	<p>This parameter is used to set the C-axis detector range. Set "0" for this parameter. "2" is used by Mitsubishi for testing.</p>	0 to 7	0
--------------	-------	----------------------------	--	--------	---

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting
3243 (PR)	SP043	TRNG	Synchronous tapping, spindle synchronous detector range	This parameter is used to set the synchronous tapping or spindle synchronous detector range. Set "0" for this parameter.	0 to 7 0
3244 (PR)	SP044	TRANS	NC communication frequency	Set a frequency of data communication with NC.	0 to 32767 Standard: 0 Special: 1028
3245	SP045	CSNT	Dual cushion timer	Set the cycle to add the increment values in the dual cushion process. When this setting value is increased, the dual cushion will increase, and the changes in the speed during acceleration/deceleration will become gradual.	0 to 1000 (ms) 0
3246 (PR)	SP046	CSN2	Speed command dual cushion	For an acceleration/deceleration time constant defined in SP019 (CSN1) , this parameter is used to provide smooth movement only at the start of acceleration/deceleration. As the value of this parameter is smaller, it moves smoother but the acceleration/deceleration time becomes longer. To make this parameter invalid, set "0".	0 to 1000 0
3247 (PR)	SP047	SDTR	Speed detection reset value	Set the reset hysteresis width for a speed detection set value defined in SP020 (SDTS).	0 to 1000 (r/min) 30
3248 (PR)	SP048	SUT	Speed reach range	Set the speed deviation rate with respect to the commanded speed for output of the speed reach signal.	0 to 100 (%) 15
3249	SP049	TLM2	Torque limit 2	Set the torque limit rate for the torque limit signal 010.	1 to 120 (%) 20
3250	SP050	TLM3	Torque limit 3	Set the torque limit rate for the torque limit signal 011.	1 to 120 (%) 30
3251	SP051	TLM4	Torque limit 4	Set the torque limit rate for the torque limit signal 100.	1 to 120 (%) 40
3252	SP052	TLM5	Torque limit 5	Set the torque limit rate for the torque limit signal 101.	1 to 120 (%) 50
3253	SP053	TLM6	Torque limit 6	Set the torque limit rate for the torque limit signal 110.	1 to 120 (%) 60
3254	SP054	TLM7	Torque limit 7	Set the torque limit rate for the torque limit signal 111.	1 to 120 (%) 70
3255 (PR)	SP055	SETM	Excessive speed deviation timer	Set the timer value until the excessive speed deviation alarm is output. The value of this parameter should be longer than the acceleration/deceleration time.	0 to 60 (s) 12


8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3256	SP056			Use not possible.	0	0
3257 (PR)	SP057	STOD	Constant → excessive judgment value	Set the value for judging when changing from a constant to excessive speed command.	0 to 50 (r/min)	0
3258 (PR)	SP058	SDT2	2nd speed detection speed	Set the speed for turning the 2nd speed detection ON. (This is valid only when SP038: SFNC6-bit8 is set to "1".) If the speed drops below this set speed, the 2nd speed detection will turn ON. When the speed reaches this set speed +15r/min or more, the 2nd speed detection will turn OFF. If SP034: SFNC2-bit1 is set to "1", this will be the medium-speed and high-speed coil changeover speed. The speed detection reset width follows the SP047 (speed detection reset width) setting.	0 to 32767 (r/min)	0
3259 (PR)	SP059	MKT	Winding changeover base shut-off timer	Set the base shut-off time for contactor switching at winding changeover. Note that the contactor may be damaged with burning if the value of this parameter is too small.	50 to 10000 (ms)	150
3260 (PR)	SP060	MKT2	Current limit timer after winding changeover	Set the current limit time to be taken after completion of contactor switching at winding changeover.	0 to 10000 (ms)	500
3261 (PR)	SP061	MKIL	Current limit value after winding changeover	Set the current limit value during a period defined in SP060 (MKT2) after completion of contactor switching at winding changeover.	0 to 120 (%)	75
3262	SP062			Not used. Set to "0".	0	0
3263 (PR)	SP063	OLT	Overload alarm detection time	Set the time constant for detection of the motor overload alarm.	0 to 1000 (s)	60
3264 (PR)	SP064	OLL	Overload alarm detection level	Set the detection level of the motor overload alarm.	0 to 180 (%)	110
3265 (PR)	SP065	VCGN1	Target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP022 (VGNP1) at the maximum motor speed defined in SP017 (TSP).	0 to 100 (%)	100

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																	
3266 (PR)	SP066	VCSN1	Change starting speed of variable speed loop proportional gain	Set the speed when the speed loop proportional gain change starts.	0 to 32767 (r/min)	0																
3267 (PR)	SP067	VIGWA	Change starting speed of variable current loop gain	Set the speed where the current loop gain change starts.	0 to 32767 (r/min)	0																
3268 (PR)	SP068	VIGWB	Change ending speed of variable current loop gain	Set the speed where the current loop gain change ends.	0 to 32767 (r/min)	0																
3269 (PR)	SP069	VIGN	Target value of variable current loop gain	Set the magnification of current loop gain (torque component and excitation component) for a change ending speed defined in SP068 (VIGWB). When this parameter is set to "0", the magnification is 1.	0 to 32767 (1/16-fold)	0																
				<table border="1"> <thead> <tr> <th>SP017 (TSP) Maximum motor speed</th> <th>SP067 (VIGWA)</th> <th>SP068 (VIGWB)</th> <th>SP069 (VIGN)</th> </tr> </thead> <tbody> <tr> <td>0 to 6000</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>6001 to 8000</td> <td>5000</td> <td>8000</td> <td>45</td> </tr> <tr> <td>8001 or more</td> <td>5000</td> <td>10000</td> <td>64</td> </tr> </tbody> </table>	SP017 (TSP) Maximum motor speed	SP067 (VIGWA)	SP068 (VIGWB)	SP069 (VIGN)	0 to 6000	0	0	0	6001 to 8000	5000	8000	45	8001 or more	5000	10000	64		
SP017 (TSP) Maximum motor speed	SP067 (VIGWA)	SP068 (VIGWB)	SP069 (VIGN)																			
0 to 6000	0	0	0																			
6001 to 8000	5000	8000	45																			
8001 or more	5000	10000	64																			
3270	SP070	FHz	Machine resonance suppression filter frequency	When machine vibration occurs in speed and position control, set the frequency of the required vibration suppression. Note that a value of 100Hz or more is set. Set to "0" when not used.	0 to 3000 (Hz)	0																
3271 to 3275	SP071 to SP075			Use not possible.	0	0																

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3276	SP076	FONS	Machine resonance suppression filter operation speed	When the vibration increases in motor stop (ex. in orientation stop) when the machine vibration suppression filter is operated by SP070, operate the machine vibration suppression filter at a speed of this parameter or more. When set to "0", this is validated for all speeds.	0 to 32767 (r/min)	0
3277 (PR)	SP077	TDSL	Fixed control constant	Set by Mitsubishi. Set "14" unless designated in particular.		14
3278 (PR)	SP078	FPWM	Fixed control constant	Set by Mitsubishi. Set "1" unless designated in particular.	1	1
3279	SP079			Use not possible.	0	0
3280	SP080	SWTD	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3281 to 3286	SP081 to SP086			Use not possible.	0	0
3287 (PR)	SP087	DIQM	Target value of variable torque limit magnification at deceleration	Set the minimum value of variable torque limit at deceleration.	0 to 150 (%)	75
3288 (PR)	SP088	DIQN	Speed for starting change of variable torque limit magnification at deceleration	Set the speed where the torque limit value at deceleration starts to change. 	0 to 32767 (r/min)	3000
3289 to 3292	SP089 to SP092			Use not possible.	0	0
3293 (PR)	SP093	ORE	Tolerable pulse check error	Set this when detecting the pulse detector's pulse mistakes. (Valid only for full close control.)	0 to 32767	0
3294 (PR)	SP094	LMAV	Load meter output filter	Set the filter time constant of load meter output. When "0" is set, a filter time constant is set to 100ms.	0 to 32767 (2ms)	0
3295 (PR)	SP095	VFAV	Fixed control constant	Set by Mitsubishi. Set "0" unless designated in particular.	0	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																																																																
3296 (PR)	SP096	EGAR Encoder gear ratio	Set the gear ratio between the spindle end and the encoder end (except for the motor-built-in encoder) as indicated below. <table border="1" data-bbox="614 438 858 639" style="margin: 10px auto;"> <thead> <tr> <th>Setting value</th> <th>Gear ratio (deceleration)</th> </tr> </thead> <tbody> <tr><td>0</td><td>1 : 1</td></tr> <tr><td>1</td><td>1 : 2</td></tr> <tr><td>2</td><td>1 : 4</td></tr> <tr><td>3</td><td>1 : 8</td></tr> <tr><td>4</td><td>1 : 16</td></tr> </tbody> </table> <p>(Note) Use a combination so that the encoder end is slower than the spindle end.</p>	Setting value	Gear ratio (deceleration)	0	1 : 1	1	1 : 2	2	1 : 4	3	1 : 8	4	1 : 16	0 to 4	0																																																																																																																																				
Setting value	Gear ratio (deceleration)																																																																																																																																																				
0	1 : 1																																																																																																																																																				
1	1 : 2																																																																																																																																																				
2	1 : 4																																																																																																																																																				
3	1 : 8																																																																																																																																																				
4	1 : 16																																																																																																																																																				
3297 (PR)	SP097	SPECO Orientation specification	Set the orientation specifications in bit units. <table border="1" data-bbox="614 827 1155 989" style="margin: 10px auto;"> <tr> <td colspan="2">E</td> <td colspan="2">D</td> <td colspan="2">C</td> <td colspan="2">B</td> <td colspan="2">A</td> <td colspan="2">9</td> <td colspan="2">8</td> </tr> <tr> <td>ostp</td><td>orze</td><td>ksft</td><td>gchg</td><td></td><td></td><td>ips2</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td colspan="2">7</td> <td colspan="2">6</td> <td colspan="2">5</td> <td colspan="2">4</td> <td colspan="2">3</td> <td colspan="2">2</td> <td colspan="2">1</td> <td colspan="2">0</td> </tr> <tr> <td>vg8x</td><td></td><td>fdir</td><td>osc1</td><td></td><td></td><td>dmin</td><td>odi2</td><td>odi1</td><td></td><td></td><td></td><td></td><td></td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" data-bbox="614 1123 1155 1741" style="margin: 10px auto;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>odi1</td> <td colspan="2">Orientation rotation direction</td> </tr> <tr> <td rowspan="3">1</td> <td rowspan="3">odi2</td> <td colspan="2">00: Previous (the direction in which the motor has so far rotated under speed control)</td> </tr> <tr> <td colspan="2">01: Forward rotation</td> </tr> <tr> <td colspan="2">10: Backward rotation</td> </tr> <tr> <td rowspan="2">2</td> <td rowspan="2">dmin</td> <td>Orientation in-position advance invalid</td> <td>Orientation in-position advance valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td>osc1</td> <td>Indexing speed clamp invalid</td> <td>Indexing speed clamp valid</td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Encoder detector polarity: +</td> <td>Encoder detector polarity: -</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td>vg8x</td> <td>Speed gain *1/8 during torque limit valid</td> <td>Speed gain *1/8 during torque limit invalid</td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td>ips2</td> <td>2nd in-position invalid</td> <td>2nd in-position valid</td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td>gchg</td> <td>Gain changeover during orientation invalid</td> <td>Gain changeover during orientation valid</td> </tr> <tr> <td>D</td> <td>ksft</td> <td>Orientation virtual target shift invalid</td> <td>Orientation virtual target shift valid</td> </tr> <tr> <td>E</td> <td>orze</td> <td colspan="2">This is used by Mitsubishi.</td> </tr> <tr> <td>F</td> <td>ostp</td> <td colspan="2">Set to "0" unless particularly designated.</td> </tr> </tbody> </table> <table border="1" data-bbox="614 1774 1123 2064" style="margin: 10px auto;"> <thead> <tr> <th colspan="4">In-position advance (bit 2)</th> </tr> <tr> <th colspan="2"></th> <th>0 (invalid)</th> <th>1 (valid)</th> </tr> </thead> <tbody> <tr> <td rowspan="2" style="writing-mode: vertical-rl; transform: rotate(180deg);">Second in-position</td> <td>0 (Invalid)</td> <td>In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=1</td> <td>In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=0</td> </tr> <tr> <td>1 (Valid)</td> <td></td> <td>In-position signal in DINP width=1 Control output 4/ bit 4=1 Second in-position signal in OINP width = 0 Control output 4/ bit F=1</td> </tr> </tbody> </table>	E		D		C		B		A		9		8		ostp	orze	ksft	gchg			ips2								7		6		5		4		3		2		1		0		vg8x		fdir	osc1			dmin	odi2	odi1						bit	Name	Meaning when set to 0	Meaning when set to 1	0	odi1	Orientation rotation direction		1	odi2	00: Previous (the direction in which the motor has so far rotated under speed control)		01: Forward rotation		10: Backward rotation		2	dmin	Orientation in-position advance invalid	Orientation in-position advance valid	3			4	osc1	Indexing speed clamp invalid	Indexing speed clamp valid	5	fdir	Encoder detector polarity: +	Encoder detector polarity: -	6				7	vg8x	Speed gain *1/8 during torque limit valid	Speed gain *1/8 during torque limit invalid	8				9				A	ips2	2nd in-position invalid	2nd in-position valid	B				C	gchg	Gain changeover during orientation invalid	Gain changeover during orientation valid	D	ksft	Orientation virtual target shift invalid	Orientation virtual target shift valid	E	orze	This is used by Mitsubishi.		F	ostp	Set to "0" unless particularly designated.		In-position advance (bit 2)						0 (invalid)	1 (valid)	Second in-position	0 (Invalid)	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=1	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=0	1 (Valid)		In-position signal in DINP width=1 Control output 4/ bit 4=1 Second in-position signal in OINP width = 0 Control output 4/ bit F=1	0000 to FFFF HEX setting	0000
E		D		C		B		A		9		8																																																																																																																																									
ostp	orze	ksft	gchg			ips2																																																																																																																																															
7		6		5		4		3		2		1		0																																																																																																																																							
vg8x		fdir	osc1			dmin	odi2	odi1																																																																																																																																													
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																																																																		
0	odi1	Orientation rotation direction																																																																																																																																																			
1	odi2	00: Previous (the direction in which the motor has so far rotated under speed control)																																																																																																																																																			
		01: Forward rotation																																																																																																																																																			
		10: Backward rotation																																																																																																																																																			
2	dmin	Orientation in-position advance invalid	Orientation in-position advance valid																																																																																																																																																		
		3																																																																																																																																																			
4	osc1	Indexing speed clamp invalid	Indexing speed clamp valid																																																																																																																																																		
5	fdir	Encoder detector polarity: +	Encoder detector polarity: -																																																																																																																																																		
6																																																																																																																																																					
7	vg8x	Speed gain *1/8 during torque limit valid	Speed gain *1/8 during torque limit invalid																																																																																																																																																		
8																																																																																																																																																					
9																																																																																																																																																					
A	ips2	2nd in-position invalid	2nd in-position valid																																																																																																																																																		
B																																																																																																																																																					
C	gchg	Gain changeover during orientation invalid	Gain changeover during orientation valid																																																																																																																																																		
D	ksft	Orientation virtual target shift invalid	Orientation virtual target shift valid																																																																																																																																																		
E	orze	This is used by Mitsubishi.																																																																																																																																																			
F	ostp	Set to "0" unless particularly designated.																																																																																																																																																			
In-position advance (bit 2)																																																																																																																																																					
		0 (invalid)	1 (valid)																																																																																																																																																		
Second in-position	0 (Invalid)	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=1	In-position signal in OINP width=1 Control output 4/ bit 4=1 Second in-position signal=0 Control output 4/ bit F=0																																																																																																																																																		
	1 (Valid)		In-position signal in DINP width=1 Control output 4/ bit 4=1 Second in-position signal in OINP width = 0 Control output 4/ bit F=1																																																																																																																																																		

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3298 (PR)	SP098	VGOP	Speed loop gain proportional term in orientation mode	Set the speed loop proportional gain in orientation mode. When the gain is increased, rigidity is improved in the orientation stop but vibration and sound become larger.	0 to 2000 (1/s)	63
3299 (PR)	SP099	VGOI	Orientation mode speed loop gain integral term	Set the speed loop integral gain in orientation mode.	0 to 2000 (0.1 1/s)	60
3300 (PR)	SP100	VGOD	Orientation mode speed loop gain delay advance term	Set a loop gain delay advance gain in orientation mode. When this parameter is set to "0", PI control is applied.	0 to 1000 (0.1 1/s)	15
3301 (PR)	SP101	DINP	Orientation advance in-position width	When using the orientation in-position advance function, set the in-position width that is larger than the normal in-position width defined in SP004 (OINP).	1 to 2880 (1/16°)	16
3302 (PR)	SP102	OODR	Excessive error value in orientation mode	Set the excessive error width in orientation mode.	0 to 32767 (1/4 pulse) (1 pulse= 0.088°)	32767
3303 (PR)	SP103	FTM	Index positioning completion OFF time timer	Set the time for forcedly turn OFF the index positioning completion signal (different from the orientation completion signal) after the leading edge of the indexing start signal.	0 to 10000 (ms)	200
3304 (PR)	SP104	TLOR	Torque limit value for orientation servo locking	Set the torque limit value for orientation in-position output. If the external torque limit signal is input, the torque limit value set by this parameter is made invalid.	0 to 120 (%)	100
3305 (PR)	SP105	IQG0	Current loop gain magnification 1 in orientation mode	Set the magnification for current loop gain (torque component) at orientation completion.	1 to 1000 (%)	100
3306 (PR)	SP106	IDG0	Current loop gain magnification 2 in orientation mode	Set the magnification for current loop gain (excitation component) at orientation completion.	1 to 1000 (%)	100
3307	SP107	CSP2	Deceleration rate 2 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 001. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0
3308	SP108	CSP3	Deceleration rate 3 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 010. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items			Details	Setting range	Standard setting
3309	SP109	CSP4	Deceleration rate 4 in orientation mode	Set the deceleration rate in orientation mode corresponding to the gear 011. When this parameter is set to "0", same as SP006 (CSP).	0 to 1000	0
3310 to 3313	SP110 to SP003			Use not possible.		0
3314	SP114	OPER	Orientation pulse miss check value	An alarm "5C" will occur if the pulse miss value at the orientation stop exceeds this setting value. (Note that this is invalid when set to "0".) In this parameter, set the value to fulfill the following conditions. SP114 setting value > 1.5 × SP004 (orientation in-position width)	0 to 32767 (360°/4096)	0
3315	SP115	OSP2	Orientation motor speed clamp value 2	When the orientation clamp speed is changed by the control input, this parameter setting will be used instead of SP005: OSP. Indexing speed clamp valid This parameter is used when (SP097: SPEC0-bit4 = 1).	0 to 32767 (r/min)	0
3316	SP116			Use not possible.	0	0
3317	SP117	ORUT		Set by Mitsubishi. Set "0" unless designated in particular.	0	0
3318	SP118	ORCT	Number of orientation retry times	Set the number of times to retry when an orientation or feedback error occurs. The warning (A9) is issued while retrying orientation, and an alarm (5C) is issued when the set number of times is exceeded.	0 to 100 (time)	0
3319	SP119	MPGH	Orientation position gain H winding compensation magnification	Set the compensation magnification of the orientation position loop gain for the H winding. H winding orientation position loop gain = SP001 (or SP002) × SP119/256 When set to "0", will become the same as SP001 or SP002.	0 to 2560 (1/256-fold)	0
3320	SP120	MPGL	Orientation position gain L winding compensation magnification	Set the compensation magnification of the orientation position loop gain for the L winding. L winding orientation position loop gain = SP001 (or SP002) × SP120/256 When set to "0", will become the same as SP001 or SP002.	0 to 2560 (1/256-fold)	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting
3321	SP121	MPCSH	Orientation deceleration rate H winding compensation magnification Set the compensation magnification of the orientation deceleration rate for the H winding. Orientation deceleration rate for the H winding = SP006 × SP121/256 When set to "0", will become the same as SP006.	0 to 2560 (1/256-fold)	0
3322	SP122	MPCSL	Orientation deceleration rate L winding compensation magnification Set the compensation magnification of the orientation deceleration rate for the L winding. Orientation deceleration rate for the L winding = SP006 × SP122/256 When set to "0", will become the same as SP006.	0 to 2560 (1/256-fold)	0
3323 to 3325	SP123 to SP125		Use not possible.	0	0
3326	SP126	MPGH	Orientation position gain M coil compensation Set this to set the orientation position loop gain for the coil changeover motor to the M coil's unique value.	0 to 2560 (1/256-fold)	0
3327	SP127	MPCSM	Orientation deceleration rate M coil compensation Set this to set the orientation deceleration rate for the coil motor to the M coil's unique value.	0 to 2560 (1/256-fold)	0
3328	SP128	OXKPM	Position loop gain magnification after orientation gain change-over (M coil) Set the M coil gain magnification to be used after in-position when gain changeover is valid (SP097: SPEC0-bitC=1) during orientation.	0 to 2560 (1/256-fold)	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items			Details	Setting range	Standard setting																																																																																																				
3329 (PR)	SP129	SPECC	C-axis specifications	<p>Set the C-axis specifications in bit units.</p> <table border="1" data-bbox="630 352 1161 513"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>zrtn</td><td>ptyp</td><td>fb9x</td><td>zrtd</td><td>zrn2</td><td></td><td>zdir</td><td>ztyp</td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td>vg8x</td><td></td><td>fdir</td><td></td><td>phos</td><td>rtrn</td><td></td><td>fclx</td> </tr> </table> <p>(Note) Always set "0" for the empty bits.</p> <table border="1" data-bbox="630 585 1161 1231"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>fclx</td> <td>Closed loop</td> <td>Semi-closed loop (Gear 1 : 1 only)</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>rtrn</td> <td>Position monitor during ready OFF invalid</td> <td>Position monitor during ready OFF valid</td> </tr> <tr> <td>3</td> <td>phos</td> <td>Normal (no compensation)</td> <td>Vx4 synchronization compensation valid</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Position detector polarity (+)</td> <td>Position detector polarity (-)</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td>vg8x</td> <td>Speed gain x 1/8 during torque limit valid</td> <td>Speed gain x 1/8 during torque limit invalid</td> </tr> <tr> <td>8</td> <td>ztyp</td> <td>Z-phase type: Normal start up</td> <td>Z-phase type: Start up only</td> </tr> <tr> <td>9</td> <td>zdir</td> <td>Z-phase rising polarity (+)</td> <td>Z-phase rising polarity (-)</td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td>zrn2</td> <td colspan="2">This is used by Mitsubishi.</td> </tr> <tr> <td>C</td> <td>zrtd</td> <td colspan="2">Set to "0" unless particularly designated.</td> </tr> <tr> <td>D</td> <td>fb9x</td> <td>Speed feedback Standard (PLG)</td> <td>Speed feedback 90,000 pulse detector</td> </tr> <tr> <td>E</td> <td>ptyp</td> <td>Position control switch type: After zero point return</td> <td>Position control switch type: After deceleration stop</td> </tr> <tr> <td>F</td> <td>zrtn</td> <td>Zero point return direction: CCW</td> <td>Zero point return direction: CW</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	zrtn	ptyp	fb9x	zrtd	zrn2		zdir	ztyp	7	6	5	4	3	2	1	0	vg8x		fdir		phos	rtrn		fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)	1				2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid	3	phos	Normal (no compensation)	Vx4 synchronization compensation valid	4				5	fdir	Position detector polarity (+)	Position detector polarity (-)	6				7	vg8x	Speed gain x 1/8 during torque limit valid	Speed gain x 1/8 during torque limit invalid	8	ztyp	Z-phase type: Normal start up	Z-phase type: Start up only	9	zdir	Z-phase rising polarity (+)	Z-phase rising polarity (-)	A				B	zrn2	This is used by Mitsubishi.		C	zrtd	Set to "0" unless particularly designated.		D	fb9x	Speed feedback Standard (PLG)	Speed feedback 90,000 pulse detector	E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop	F	zrtn	Zero point return direction: CCW	Zero point return direction: CW		0000
F	E	D	C	B	A	9	8																																																																																																			
zrtn	ptyp	fb9x	zrtd	zrn2		zdir	ztyp																																																																																																			
7	6	5	4	3	2	1	0																																																																																																			
vg8x		fdir		phos	rtrn		fclx																																																																																																			
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																							
0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)																																																																																																							
1																																																																																																										
2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid																																																																																																							
3	phos	Normal (no compensation)	Vx4 synchronization compensation valid																																																																																																							
4																																																																																																										
5	fdir	Position detector polarity (+)	Position detector polarity (-)																																																																																																							
6																																																																																																										
7	vg8x	Speed gain x 1/8 during torque limit valid	Speed gain x 1/8 during torque limit invalid																																																																																																							
8	ztyp	Z-phase type: Normal start up	Z-phase type: Start up only																																																																																																							
9	zdir	Z-phase rising polarity (+)	Z-phase rising polarity (-)																																																																																																							
A																																																																																																										
B	zrn2	This is used by Mitsubishi.																																																																																																								
C	zrtd	Set to "0" unless particularly designated.																																																																																																								
D	fb9x	Speed feedback Standard (PLG)	Speed feedback 90,000 pulse detector																																																																																																							
E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop																																																																																																							
F	zrtn	Zero point return direction: CCW	Zero point return direction: CW																																																																																																							
3330	SP130	PGC1	First position loop gain for cutting on C-axis	Set the position loop gain when the first gain is selected for C axis cutting.	1 to 200 (1/s)	15																																																																																																				

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3331	SP131	PGC2	Second position loop gain for cutting on C-axis	Set the position loop gain when the second gain is selected for C axis cutting.	1 to 200 (1/s)	15
3332	SP132	PGC3	Third position loop gain for cutting on C-axis	Set the position loop gain when the third gain is selected for C-axis cutting.	1 to 200 (1/s)	15
3333	SP133	PGC4	Stop position loop gain for cutting on C-axis	Set the position loop gain for stopping when carrying out C-axis cutting.	1 to 200 (1/s)	15
3334 (PR)	SP134	VGCP0*	C-axis non-cutting speed loop gain proportional item	Set the speed loop proportional gain in C-axis non-cutting mode.	0 to 5000 (1/s)	63
3335 (PR)	SP135	VGCI0	C-axis non-cutting speed loop gain integral item	Set the speed loop integral gain in C-axis non-cutting mode.	0 to 5000 (0.1 1/s)	60
3336 (PR)	SP136	VGCD0	C-axis non-cutting speed loop gain delay advance item	Set the speed loop delay advance gain in C-axis non-cutting mode. When this parameter is set to "0", PI control is exercised.	0 to 5000 (0.1 1/s)	15
3337 (PR)	SP137	VGCP1	First speed loop gain proportional item for C-axis cutting	Set the speed loop proportional gain when the first gain is selected for C-axis cutting.	0 to 5000 (1/s)	63
3338 (PR)	SP138	VGCI1	First speed loop gain integral item for cutting on C-axis	Set the speed loop integral gain when the first gain is selected for C-axis cutting.	0 to 5000 (0.1 1/s)	60
3339 (PR)	SP139	VGCD1	First speed loop gain delay advance item for cutting on C-axis	Set the speed loop delay advance gain when the first gain is selected for curing on the C-axis. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15
3340 (PR)	SP140	VGCP2	Second speed loop gain proportional item for cutting on C-axis	Set the speed loop proportional gain when the second gain is selected for C-axis cutting.	0 to 5000 (1/s)	63
3341 (PR)	SP141	VGCI2	Second speed loop gain integral item for cutting on C-axis	Set the speed loop integral gain when the second gain is selected for C-axis cutting.	0 to 5000 (0.1 1/s)	60
3342 (PR)	SP142	VGCD2	Second speed loop gain delay advance item for cutting on C-axis	Set the speed loop delay advance gain when the second gain is selected for C-axis cutting. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3343 (PR)	SP143	VGCP3	Third speed loop gain proportional item for cutting on C-axis	Set the speed loop proportional gain when the third gain is selected for C-axis cutting.	0 to 5000 (1/s)	63
3344 (PR)	SP144	VGCI3	Third speed loop gain integral item for cutting on C-axis	Set the speed loop integral gain when the third gain is selected for C-axis cutting.	0 to 5000 (0.1 1/s)	60
3345 (PR)	SP145	VGCD3	Third speed loop gain delay advance item for cutting on C-axis	Set the speed loop delay advance gain when the third gain is selected for C-axis cutting. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15
3346 (PR)	SP146	VGCP4	Speed loop gain proportional item for stop of cutting on C-axis	Set the speed loop proportional gain when C-axis cutting is stopped.	0 to 5000 (1/s)	63
3347 (PR)	SP147	VGCI4	Speed loop gain integral item for stop of cutting on C-axis	Set the speed loop integral gain when C-axis cutting is stopped.	0 to 5000 (0.1 1/s)	60
3348 (PR)	SP148	VGCD4	Speed loop gain delay advance item for stop of cutting on C-axis	Set the speed loop delay advance gain when C-axis cutting is stopped. When this parameter is set to "0", PI control is applied.	0 to 5000 (0.1 1/s)	15
3349	SP149	CZRN	C-axis zero point return speed	This parameter is valid when SP129 (SPECC) bitE is set to "0". Set the zero point return speed used when the speed loop changes to the position loop.	1 to 500 (r/min)	50
3350	SP150	CPDT	C-axis zero point return deceleration point	This parameter is valid when SP129 (SPECC) bitE is set to "0". Set the deceleration rate where the machine starts to decelerate when it returns to the target stop point during C-axis zero point return. When the machine tends to overshoot at the stop point, set the smaller value.	1 to 10000	1
3351	SP151	CPSTL	C-axis zero point return shift amount (low byte)	This parameter is valid when SPECC (SP129) bitE is set to "0". Set the C-axis zero point position.	HEX setting 00000000 to FFFFFFFF (1/1000°)	H: 0000 L: 0000
3352	SP152	CPSTH	C-axis zero point return shift amount (high byte)			

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3353	SP153	CINP	C-axis in-position width	Set the position error range in which the in-position signal is output on the C-axis.	0000 to FFFF (1/1000°) HEX setting	03E8
3354 (PR)	SP154	CODRL	Excessive error width on C-axis (low byte)	Set the excessive error width on the C-axis.	HEX setting 00000000 to FFFFFFFF (1/1000°)	H: 0001 L: D4C0
3355 (PR)	SP155	CODRH	Excessive error width on C-axis (high byte)			
3356	SP156	OVSH	C-axis overshoot compensation	Set this to prevent overshooting when shifting from movement to stopping with C-axis control. (Set this referring to the load meter display when overshooting occurred.)	0 to 1000 (0.1%)	0
3357	SP157			Not used. Set to "0".	0	0
3358	SP158			Not used. Set to "0".	0	0
3359	SP159			Use not possible.	0	0
3360	SP160			Use not possible.	0	0
3361 (PR)	SP161	IQGC0	Current loop gain magnification 1 for non-cutting on C-axis	Set the magnification of current loop gain (torque component) for C-axis non-cutting.	1 to 1000 (%)	100
3362 (PR)	SP162	IDGC0	Current loop gain magnification 2 for non-cutting on C-axis	Set the magnification of current loop gain (excitation component) for C-axis non-cutting.	1 to 1000 (%)	100
3363 (PR)	SP163	IQGC1	Current loop gain magnification 1 for cutting on C-axis	Set the magnification of current loop gain (torque component) for C-axis cutting.	1 to 1000 (%)	100
3364 (PR)	SP164	IDGC1	Current loop gain magnification 2 for cutting on C-axis	Set the magnification of current loop gain (excitation component) for C-axis cutting.	1 to 1000 (%)	100
3365	SP165	PG2C	C-axis position loop gain 2	Set the second position loop gain when high-gain control is carried out for control of the C-axis. This parameter is applied to all the operation modes of C-axis control. When this function is not used, assign "0".	0 to 999 (1/s)	0


8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3366	SP166	PG3C	C-axis position loop gain 3	Set the third position loop gain when high-gain control is carried out for control of the C-axis. This parameter is applied to all the operation modes of C-axis control. When this function is not used, assign "0".	0 to 999 (1/s)	0
3367 (PR)	SP167	PGU	Position loop gain for increased spindle holding force	Set the position loop gain for when the disturbance observer is valid.	0 to 100 (1/s)	15
3368 (PR)	SP168	VGUP	Speed loop gain proportional item for increased spindle holding force	Set the speed loop gain proportional item for when the disturbance observer is valid.	0 to 5000 (1/s)	63
3369 (PR)	SP169	VGUI	Speed loop gain integral item for increased spindle holding force	Set the speed loop gain integral item for when the disturbance observer is valid.	0 to 5000 (0.1 1/s)	60
3370 (PR)	SP170	VGUD	Speed loop gain delay advance item for increased spindle holding force	Set the speed loop gain delay advance item for when the disturbance observer is valid.	0 to 5000 (0.1 1/s)	15
3371 to 3376	SP171 to SP176			Not used. Set to "0".	0	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																													
3377 (PR)	SP177	SPECS	Spindle synchronous specifications	Set the spindle synchronous specifications in bit units. F E D C B A 9 8 <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%; text-align:center;">odx8</td> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%;"></td> <td style="width:12.5%; text-align:right;">phos</td> </tr> <tr> <td style="text-align:center;">7</td> <td style="text-align:center;">6</td> <td style="text-align:center;">5</td> <td style="text-align:center;">4</td> <td style="text-align:center;">3</td> <td style="text-align:center;">2</td> <td style="text-align:center;">1</td> <td style="text-align:center;">0</td> </tr> <tr> <td></td> <td></td> <td style="text-align:center;">fdir</td> <td></td> <td style="text-align:center;">mach</td> <td></td> <td></td> <td style="text-align:right;">fclx</td> </tr> </table> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:5%;">bit</th> <th style="width:15%;">Name</th> <th style="width:35%;">Meaning when set to 0</th> <th style="width:45%;">Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>fclx</td> <td>Closed loop</td> <td>Semi-closed loop</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td></td> <td></td> <td></td> </tr> <tr> <td>3</td> <td>mach</td> <td>Automatic coil change-over during spindle synchronization invalid</td> <td>Automatic coil change-over during spindle synchronization valid</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Position detector direction (positive direction)</td> <td>Position detector direction (negative direction)</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td>odx8</td> <td>Magnification of excessive error width x 8 times invalid</td> <td>Magnification of excessive error width x 8 times valid</td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td colspan="2" style="text-align:center;">(Used with SPJ)</td> </tr> </tbody> </table>			odx8					phos	7	6	5	4	3	2	1	0			fdir		mach			fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop	1				2				3	mach	Automatic coil change-over during spindle synchronization invalid	Automatic coil change-over during spindle synchronization valid	4				5	fdir	Position detector direction (positive direction)	Position detector direction (negative direction)	6				7				8				9				A				B				C				D	odx8	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid	E				F		(Used with SPJ)		0000 to FFFF HEX setting	0000
		odx8					phos																																																																																											
7	6	5	4	3	2	1	0																																																																																											
		fdir		mach			fclx																																																																																											
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																															
0	fclx	Closed loop	Semi-closed loop																																																																																															
1																																																																																																		
2																																																																																																		
3	mach	Automatic coil change-over during spindle synchronization invalid	Automatic coil change-over during spindle synchronization valid																																																																																															
4																																																																																																		
5	fdir	Position detector direction (positive direction)	Position detector direction (negative direction)																																																																																															
6																																																																																																		
7																																																																																																		
8																																																																																																		
9																																																																																																		
A																																																																																																		
B																																																																																																		
C																																																																																																		
D	odx8	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid																																																																																															
E																																																																																																		
F		(Used with SPJ)																																																																																																
3378 (PR)	SP178	VGSP	Spindle synchronous speed loop gain proportional term	Set the speed loop proportional gain in spindle synchronous mode.	0 to 2000 (1/s)	63																																																																																												
3379 (PR)	SP179	VGSI	Spindle synchronous speed loop gain integral term	Set the speed loop integral gain in spindle synchronous mode.	0 to 2000 (0.1 1/s)	60																																																																																												
3380 (PR)	SP180	VGSD	Spindle synchronous speed loop gain delay advance term	Set the speed loop delay advance gain in spindle synchronous mode. When this parameter is set to "0", PI control is applied.	0 to 1000 (0.1 1/s)	15																																																																																												
3381 (PR)	SP181	VCGS	Spindle synchronous Target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP178 (VGSP) at the maximum speed defined in SP017 (TSP) in spindle synchronous mode.	0 to 100 (%)	100																																																																																												


8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3382 (PR)	SP182	VCSS	Spindle synchronous Change starting speed of variable speed loop proportional gain	Set the speed when the speed loop proportional gain change starts in the spindle synchronous mode. 	0 to 32767 (r/min)	0
3383	SP183	SYNV	Spindle synchronous Sync matching speed	For changeover from the speed loop to the position loop in the spindle synchronous mode, set a speed command error range for output of the synchronous speed matching signal.	0 to 1000 (r/min)	20
3384 (PR)	SP184	FFCS	Spindle synchronous Acceleration rate feed forward gain	Set the acceleration rate feed forward gain in the spindle synchronous mode. This parameter is used only with the SPJ2.	0 to 1000 (%)	0
3385	SP185	SINP	Spindle synchronous In-position width	Set the position error range for output of the in-position signal in the spindle synchronous mode.	1 to 2880 (1/16°)	16
3386 (PR)	SP186	SODR	Spindle synchronous Excessive error width	Set the excessive error width in the spindle synchronous mode.	1 to 32767 (pulse) (1 pulse = 0.088°)	32767
3387 (PR)	SP187	IQGS	Spindle synchronous Current loop gain magnification 1	Set the magnification of current loop gain (torque component) in the spindle synchronous mode.	1 to 1000 (%)	100
3388 (PR)	SP188	IDGS	Spindle synchronous Current loop gain magnification 2	Set the magnification of current loop gain (excitation component) in the spindle synchronous mode.	1 to 1000 (%)	100
3389	SP189	PG2S	Spindle synchronous Position loop gain 2	Set the second position loop gain when high-gain control is carried out in the spindle synchronous mode. When this parameter function is not used, set to "0".	0 to 999 (1/s)	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting																																																																																																													
3390	SP190	PG3S	Spindle synchronous Position loop gain 3	Set the third position loop gain when high-gain control is carried out in the spindle synchronous mode. When this parameter function is not used, set to "0".	0 to 999 (1/s)	0																																																																																																												
3391	SP191			Use not possible.	0	0																																																																																																												
3392	SP192			Not used. Set to "0".																																																																																																														
3393 (PR)	SP193	SPECT	Synchronized tapping specifications	Set the synchronized tapping specifications in bit units. <table border="1" style="margin-left: 20px;"> <tr> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td> </tr> <tr> <td>zrtn</td><td>ptyp</td><td>od8x</td><td></td><td></td><td></td><td></td><td>phos</td> </tr> <tr> <td colspan="8"> </td> </tr> <tr> <td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td></td><td></td><td>fdir</td><td>cdir</td><td>pyfx</td><td>rtrn</td><td></td><td>fclx</td> </tr> </table> <table border="1" style="margin-left: 20px;"> <thead> <tr> <th>bit</th> <th>Name</th> <th>Meaning when set to 0</th> <th>Meaning when set to 1</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>fclx</td> <td>Closed loop</td> <td>Semi-closed loop (Gear 1 : 1 only)</td> </tr> <tr> <td>1</td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>rtrn</td> <td>Position monitor during ready OFF invalid</td> <td>Position monitor during ready OFF valid</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td>cdir</td> <td>Command polarity (+)</td> <td>Command polarity (-)</td> </tr> <tr> <td>5</td> <td>fdir</td> <td>Position detector polarity (+)</td> <td>Position detector polarity (-)</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>phos</td> <td>Normal (no compensation)</td> <td>Synchronized tapping position command compensation (for synchronization with high-gain servo)</td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td>od8x</td> <td>Magnification of excessive error width x 8 times invalid</td> <td>Magnification of excessive error width x 8 times valid</td> </tr> <tr> <td>E</td> <td>ptyp</td> <td>Position control switch type: After zero point return</td> <td>Position control switch type: After deceleration stop</td> </tr> <tr> <td>F</td> <td>zrtn</td> <td>Zero point return direction: CCW</td> <td>Zero point return direction: CW</td> </tr> </tbody> </table>	F	E	D	C	B	A	9	8	zrtn	ptyp	od8x					phos									7	6	5	4	3	2	1	0			fdir	cdir	pyfx	rtrn		fclx	bit	Name	Meaning when set to 0	Meaning when set to 1	0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)	1				2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid	3				4	cdir	Command polarity (+)	Command polarity (-)	5	fdir	Position detector polarity (+)	Position detector polarity (-)	6				7				8	phos	Normal (no compensation)	Synchronized tapping position command compensation (for synchronization with high-gain servo)	9				A				B				C				D	od8x	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid	E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop	F	zrtn	Zero point return direction: CCW	Zero point return direction: CW	0000 to FFFF HEX setting	0000
F	E	D	C	B	A	9	8																																																																																																											
zrtn	ptyp	od8x					phos																																																																																																											
7	6	5	4	3	2	1	0																																																																																																											
		fdir	cdir	pyfx	rtrn		fclx																																																																																																											
bit	Name	Meaning when set to 0	Meaning when set to 1																																																																																																															
0	fclx	Closed loop	Semi-closed loop (Gear 1 : 1 only)																																																																																																															
1																																																																																																																		
2	rtrn	Position monitor during ready OFF invalid	Position monitor during ready OFF valid																																																																																																															
3																																																																																																																		
4	cdir	Command polarity (+)	Command polarity (-)																																																																																																															
5	fdir	Position detector polarity (+)	Position detector polarity (-)																																																																																																															
6																																																																																																																		
7																																																																																																																		
8	phos	Normal (no compensation)	Synchronized tapping position command compensation (for synchronization with high-gain servo)																																																																																																															
9																																																																																																																		
A																																																																																																																		
B																																																																																																																		
C																																																																																																																		
D	od8x	Magnification of excessive error width x 8 times invalid	Magnification of excessive error width x 8 times valid																																																																																																															
E	ptyp	Position control switch type: After zero point return	Position control switch type: After deceleration stop																																																																																																															
F	zrtn	Zero point return direction: CCW	Zero point return direction: CW																																																																																																															

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3394 (PR)	SP194	VGTP	Synchronized tapping speed loop gain proportional term	Set the speed loop proportional gain in synchronized tapping mode.	0 to 2000 (1/s)	63
3395 (PR)	SP195	VGTI	Synchronized tapping speed loop gain integral term	Set the speed loop integral gain in synchronized tapping mode.	0 to 2000 (0.1 1/s)	60
3396 (PR)	SP196	VGTD	Synchronized tapping speed loop gain delay advance term	Set the speed loop delay advance gain in synchronized tapping mode. When this parameter is set to "0", PI control is applied.	0 to 1000 (0.1 1/s)	15
3397	SP197			Use not possible.	0	0
3398 (PR)	SP198	VCGT	Synchronized tapping target value of variable speed loop proportional gain	Set the magnification of speed loop proportional gain with respect to SP194 (VGTP) at the maximum motor speed defined in SP017 (TSP) in synchronized tapping mode.	0 to 100 (%)	100
3399 (PR)	SP199	VCST	Synchronized tapping change starting speed of variable speed loop proportional gain	Set the speed where the speed loop proportional gain change starts during synchronized tapping. 	0 to 32767 (r/min)	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items			Details	Setting range	Standard setting
3400 (PR)	SP200	FFC1	Synchronized tapping acceleration feed forward gain (gear 1)	Set the acceleration feed forward gain for selection of gear 000 during synchronized tapping. This parameter should be used when an error of relative position to Z-axis servo is large.	0 to 1000 (%)	0
3401 (PR)	SP201	FFC2	Synchronized tapping acceleration feed forward gain (gear 2)	Set the acceleration feed forward gain for selection of gear 001 during synchronized tapping.	0 to 1000 (%)	0
3402 (PR)	SP202	FFC3	Synchronized tapping acceleration feed forward gain (gear 3)	Set the acceleration feed forward gain for selection of gear 010 during synchronized tapping.	0 to 1000 (%)	0
3403 (PR)	SP203	FFC4	Synchronized tapping acceleration feed forward gain (gear 4)	Set the acceleration feed forward gain for selection of gear 011 during synchronized tapping.	0 to 1000 (%)	0
3404	SP204		Fixed control constant	This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3405	SP205					
3406	SP206	GCK	Reverse run detection error detection width	When the motor moves (including movement with external force), the motor overrun alarm (3E) will be detected even if the speed command is 0 (including position control stop command) during servo ON (gate ON). Set the movement amount to be detected as an alarm. 0: Detect with 10° motor movement amount (Recommended setting) 1: Detect with 20° motor movement amount 2: Detect with 40° motor movement amount	0/1/2	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting
3407	SP207	GDL Sequential mode startup timing	<p>To carry out spindle synchronization or C-axis control in the both-chuck state with no movement immediately after the power is turned ON, set this parameter so that the reverse run detection function will function correctly. Set so that servo ON timing for the opposing spindle has the combination of (1) and (2) shown in the drawing below.</p> <p>0: Servo turns ON simultaneously with servo ON command, and servo ON status is returned immediately.</p> <p>1: Gate turns ON at pattern (1) shown below, and servo ON status is returned two seconds later.</p> <p>2: Gate turns ON at pattern (2) shown below, and servo ON status is returned two seconds later.</p>	0/1/2	0
<p>The diagram illustrates the timing sequence for Servo ON. It shows five signals: Servo ON command, Gate ON, Servo ON (1), Servo ON (2), and Servo ON status. The Servo ON command is a single pulse. Gate ON occurs 700ms after the command. Servo ON (1) occurs 300ms after Gate ON. Servo ON (2) occurs 700ms after Gate ON. Servo ON status is returned 2 seconds after the Servo ON command.</p>					
3408	SP208	W2	This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3409 to 3413	SP209 to SP213		Not used. Set to "0".	0	0
3414	SP214	TZRN Synchronized tapping zero point return speed	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the zero point return speed used when the speed loop changes to the position loop.		
3415	SP215	TPDT Synchronized tapping zero point return deceleration rate	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the deceleration rate where the machine starts to decelerate when it returns to the target stop point during synchronized tapping zero point return. When the machine tends to overshoot at the stop point set a smaller value.	0 to 10000 (pulse)	1
3416	SP216	TPST Synchronized tapping zero point return shift amount	This parameter is valid when SP193 (SPECT) bitE is set to "0". Set the synchronized tapping zero point position.	0 to 4095	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3417	SP217	TINP	Synchronized tapping in-position width	Set the position error range for output of the in-position during synchronized tapping.	1 to 2880 (1/16°)	16
3418 (PR)	SP218	TODR	Synchronized tapping excessive error width	Set the excessive error width during synchronized tapping.	1 to 32767 (pulse) (1 pulse =0.088°)	32767
3419 (PR)	SP219	IQGT	Synchronized tapping current loop gain magnification 1	Set the magnification of current loop gain (torque component) during synchronized tapping.	1 to 1000 (%)	100
3420 (PR)	SP220	IDGT	Synchronized tapping current loop gain magnification 2	Set the magnification of current loop gain (excitation component) during synchronized tapping.	1 to 1000 (%)	100
3421	SP221	PG2T	Synchronized tapping position loop gain 2	Set the second position loop gain when high-gain control is applied during synchronized tapping. When this parameter is not used, set to "0".	0 to 999 (1/s)	0
3422	SP222	PG3T	Synchronized tapping position loop gain 3	Set the third position loop gain when high-gain control is applied during synchronized tapping. When this parameter is not used, set to "0".	0 to 999 (1/s)	0
3423	SP223	SPDV	Speed monitor speed	Set the spindle limit speed in the door open state. (Invalid when 0 is set.) If the spindle end speed exceeds this setting value when the door is open, the speed monitor error (5E) will occur.	0 to 800 (r/min)	0
3424	SP224	SPDF	Speed monitor time	Set the time (continuous) to detect alarms. (Detected instantly when 0 is set.)	0 to 2813 (3.5ms)	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items		Details	Setting range	Standard setting	
3425	SP225	OXKPH	Position loop gain magnification after orientation gain changeover (H coil)	If gain changeover is valid (SP097: SPEC0-bitC=1) during orientation, set the magnification of each gain changed to after in-position.	0 to 2560 (1/256-fold)	0
3426	SP226	OXKPL	Position loop gain magnification after orientation gain changeover (L coil)		0 to 2560 (1/256-fold)	0
3427	SP227	OXVKP	Speed loop proportional gain magnification after orientation gain changeover		0 to 2560 (1/256-fold)	0
3428	SP228	OXVKI	Speed loop cumulative gain magnification after orientation gain changeover	If gain changeover is valid (SP097: SPEC0-bitC=1) during orientation, set the magnification of each gain changed to after in-position.	0 to 2560 (1/256-fold)	0
3429	SP229	OXSFT	Orientation virtual target shift amount	Set the amount to shift the target position when orientation virtual target position is valid (SP097: SPEC0-bitD=1).	0 to 2048 (360°/4096)	0
3430 to 3432	SP230 to SP232			Use not possible.		
3433 (PR)	SP233	JL	Disturbance observer general inertia scale	Set the ratio of the motor inertia + load inertia and motor inertia. $\text{Setting value} = \frac{\text{Motor inertia} + \text{load inertia}}{\text{Motor inertia}} \times 100$ (Normally, set "100" or more. When less than "50" is set, the setting will be invalid.) To calculate speed loop gain with general inertia scale: The effective proportional gain and effective cumulative gain during the speed control are changed at the set scale.	0 to 5000 (%)	0
3434 (PR)	SP234	OBS1	Disturbance observer low path filter frequency	Set the frequency of the low path filter for when the disturbance observer is valid. $\text{Setting (1/s)} = 2\pi f$ f: Approx. 1.5 times the disturbance frequency	0 to 1000 (1/s)	0

8. Spindle Parameters
8.4 MDS-C1-SPM

No.	Items			Details	Setting range	Standard setting
3435 (PR)	SP235	OBS2	Disturbance observer gain	Set the gain for the disturbance observer.	0 to 500 (%)	0
3436	SP236	OBS3	Fixed control constant	This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3437	SP237	KSCP	Fixed control constant	This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3438	SP238	SEZR				
3439	SP239	SEZT				
3440	SP240			Use not possible.	0	0
3441	SP241			Use not possible.	0	0
3442	SP242	Vavx		This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3443	SP243	UTTM			0	0
3444	SP244	OPLP		Use not possible.	0	0
3445	SP245	PGHS		This is used by Mitsubishi. Set to "0" unless particularly designated.	0	0
3446	SP246	TEST			0	0
3447 to 3448	SP247 to SP248			Use not possible.	0	0
3449	SP249	SM0	Speed meter speed	Set the motor rotation speed when the speed meter 10V is output. When set to "0", this parameter becomes the same as SP017 (TSP).	0 to 32767 (r/min)	0
3450	SP250	LM0	Load meter voltage	Set the voltage when the load meter 120% is output. When set to "0", this becomes 10V.	0 to 10 (V)	0
3451 to 3452	SP251 to SP252			Use not possible.	0	0

8. Spindle Parameters
8.4 MDS-C1-SPM


No.	Items		Details	Setting range	Standard setting	
3453	SP253	DA1NO	D/A output channel 1 data number	Set the output data number for channel 1 of the D/A output function. When set to "0", the output is speedometer. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767	0
3454	SP254	DA2NO	D/A output channel 2 data number	Set the output data number for channel 2 of the D/A output function. When set to "0", the output is load meter. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767	0
3455	SP255	DA1MPY	DA output channel 1 magnification	Set the data magnification for channel 1 of the D/A output function. The output magnification is the setting value divided by 256. When set to "0", the output magnification becomes 1-fold, in the same manner as when "256" is set. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767 (1/256-fold)	0
3456	SP256	DA2MPY	DA output channel 2 magnification	Set the data magnification for channel 2 of the D/A output function. The output magnification is the setting value divided by 256. When set to "0", the output magnification becomes 1-fold, in the same manner as when "256" is set. Refer to "9.4 (1) For D/A output functions".	-32768 to 32767 (1/256-fold)	0
3457 (PR) to 3520 (PR)	SP257 to SP320	RPM BSD	Motor constant (H coil)	This parameter is valid only in the following two conditional cases: (a) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=0 Set the motor constants when using a special motor, not described in the SP040 (MTYP) explanation and when not using the coil changeover motor. (b) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=1 Set the motor constant of the H coil of the coil changeover motor. (Note) It is not allowed for the user to change the setting.	0000 to FFFF HEX setting	0000
3521 (PR) to 3584 (PR)	SP321 to SP384	RPML BSDL	Motor constant (L coil)	This parameter is valid only in the following conditional case: (a) In case that SP034 (SFNC2) bit0=1 and SP034 (SFNC2) bit2=1 Set the motor constant of the L coil of the coil changeover motor. (Note) It is not allowed for the user to change the setting.	0000 to FFFF HEX setting	0000

8.5 Supplement

8.5.1 D/A Output Specifications

(1) D/A output specifications

Item	Explanation
No. of channels	2ch
Output cycle	444μs (min. value)
Output precision	8bit
Output voltage range	0V to +5V (zero) to +10V, 0V to +10V during meter output
Output scale setting	1/256 to ±128 tiems
Output pins	CN9 connector MO1 = 9 pin MO2 = 19 pin GND = 11pin
Function	Phase current feedback output function U-phase current FB : 7



8. Spindle Parameters
8.5 Supplement

(2) Setting the output data

Input the No. of the data to be output to each D/A output channel.

#	No.	Abbrev	Parameter name
3453	SP253	DA1NO	D/A output channel 1 data No.
3454	SP254	DA2NO	D/A output channel 2 data No.

No.	Output data	Original data unit	Standard setting value for output scale (Setting values in SP255, SP256)	Standard output unit
0	ch1: Speed meter output	10V=max. speed (0=0V)	0	Depends on the max. speed
	ch2: Load meter output	10V=120% load (0=0V)	0	Rated 12%/V
1	-			
2	Current command	Rated 100% = 4096	8	Rated 20%/V
3	Current feedback	Rated 100% = 4096	8	Rated 20%/V
4	Speed feedback	r/min	13	500(r/min)/V
5	-			
6	Position droop	1° = (64000/65536)	671	10°/V
7	-			
8	Feedrate (FΔT)	1° = (64000/65536)	629 (When communicating by 3.5ms)	500(r/min)/V
9	-			
10	Position command	1° = (64000/65536)	19 (18.64)	360°/V
11	-			
12	Position feedback	1° = (64000/65536)	19 (18.64)	360°/V
13	-			
80	Control input 1	HEX	Bit correspondence	
81	Control input 2			
82	Control input 3			
83	Control input 4			
84	Control output 1	HEX	Bit correspondence	
85	Control output 2			
86	Control output 3			
87	Control output 4			

(3) Setting the output scale

#	No.	Abbrev	Parameter name
3455	SP255	DA1MPY	D/A output channel 1 magnification
3456	SP256	DA2MPY	D/A output channel 2 magnification

Usually, the standard setting value is set for the output scale (SV063, SV 064). When "0" is set, the output will be made as well as when "256" is set.

$$\text{DATA} \times \frac{\text{SP255}}{256} \times \frac{10 \text{ [V]}}{256 \text{ (8bit)}} + 5 \text{ [V] (offset)} = \text{Output voltage [V]}$$

(Example) When outputting the position droop with 10°/V.

$$\frac{640000}{65536} \times \frac{671}{256} \times \frac{10}{256} + 5 = 5.999 \text{ [V]}$$

9. MACHINE ERROR COMPENSATION

9.1 FUNCTION OUTLINE

Machine error compensation includes two independent functions: memorized pitch error compensation and memorized relative position compensation.

(1) Memorized pitch error compensation

According to the specified parameters, this method compensates an axis feed error caused by a ball screw pitch error, etc.

With the reference point defined as the base, set the compensation amount in the division points obtained by equally dividing the machine coordinates. (See Fig. 1. 1)

The compensation amount can be set by either the absolute or incremental system.

Select the desired method with the #4000:Pinc. Machine position is compensated between division points n and $n+1$ as much as compensation amount between them by linear approximation.




Fig. 1. 1 Relationship between the compensation amount and machine position

(2) Memorized relative position compensation

This method, according to the parameters specified in advance, compensates the relative position error between two orthogonal axes caused by deflection of the moving stand.

For this, as shown in Fig. 1. 2, specify the compensation amount in the compensation axis direction in the division points obtained by equally dividing the machine coordinates of the base axis.

The base axis is one of the two orthogonal axes to which relative position compensation applies. This axis is used as the criterion for relative-error measurement. The compensation axis is the coordinate axis that is orthogonal to the base axis. The compensation is actually made for this coordinate axis.

The section between division points n and $n+1$ is compensated smoothly by linear approximation.




Fig. 1. 2 Relationship between base and compensation axes

9. MACHINE ERROR COMPENSATION
9.1 FUNCTION OUTLINE

(SETUP PARAM 5. 1/15)

#	Item	Details	Setting range
4000 (PR)	Pinc	Machine error offset increment method	Specify whether to use the incremental amount method or absolute amount method when setting the machine error compensation data. 0: Absolute volume method 1: Incremental volume method

<1st axis>

#	Item	Details	Setting range
4001	cmpax	Basic axis	Specify the basic axis address for machine error compensation. 1) For pitch error compensation, set the name of the axis to be compensated. 2) For relative position compensation, set the name of the axis to be the base axis. Set as the "system No. + axis name" when using the multi-system. (Example) Z axis for 2nd system: 2Z
4002	drcax	Compensation axis	Set the compensation axis address for machine error compensation. 1) For pitch error compensation, set the same axis name as #4001 cmpax. 2) For relative position compensation, set the name of the axis to be actually compensated. Set as the "system No. + axis name" when using the multi-system. (Example) Z axis for 2nd system: 2Z
4003	rdvno	Division point number at reference point position	Set the compensation data No. corresponding to the reference point position. The reference point is actually the base, so there is no compensation No. Set the number that is decremented by 1.
4004	mdvno	Division point number at the most negative side	Set the compensation data No. that is on the farthest negative side.
4005	pdvno	Division point number at the most positive side	Set the compensation data No. that is on the farthest positive side.
4006	sc	Compensation scale factor	Set the compensation amount's scale.
4007	spcdv	Division interval	Set the interval to divide the basic axis. Each compensation data will be the compensation amount for each of these intervals.

9. MACHINE ERROR COMPENSATION
9.1 FUNCTION OUTLINE

<2nd axis>	<3rd axis>	<4th axis>	<5th axis>	<6th axis>	<7th axis>	<8th axis>	<9th axis>	<10th axis>	
4011	4021	4031	4041	4051	4061	4071	4081	4091	Set the parameters corresponding to the 1st axis' parameters 4001 to 4007 for each axis. A maximum of 6 axes can be controlled, but as the relative position is compensated, settings for 10 axes can be made.
4012	4022	4032	4042	4052	4062	4072	4082	4092	
4013	4023	4033	4043	4053	4063	4073	4083	4093	
4014	4024	4034	4044	4054	4064	4074	4084	4094	
4015	4025	4035	4045	4055	4065	4075	4085	4095	
4016	4026	4036	4046	4056	4066	4076	4086	4096	
4017	4027	4037	4047	4057	4067	4077	4087	4097	

(SETUP PARAM 5. 3/15) to (SETUP PARAM 5. 15/15)

#	Item	Details	Setting range
4101 • • • 5124		Set the compensation amount for each axis.	-128 to 127 The actual compensation amount will be the value obtained by multiplying the setting value with the compensation scale.

9.2 SETTING COMPENSATION DATA

Compensation data can be set according to either absolute or incremental system.

"#4000:Pinc" 0: Absolute system
 1: Incremental system

(1) Absolute system

Feed from the reference point to each division point is executed as shown in Fig. 2. 1. The following is obtained at this time. Set it as the compensation amount.

$$(\text{Specified position} - \text{Real machine position}) \times 2 \text{ (Unit of output)}$$

For example, assume that the feed from the reference point to the +100mm position is executed. Also, assume that the real machine position is 99.990mm. In this case, the following value is defined as the compensation amount used at the +100mm position:

$$(100000 - 99990) \times 2 = 20 \text{ pulses}$$

The resultant value is defined as the compensation amount. Assume that the real machine position resulting when feed to the -100mm position is executed, is -99.990mm. In this case, the following value is defined as the compensation amount used at the -100mm position:

$$(-100000 - (-99990)) \times 2 = -20 \text{ pulses}$$




Fig. 2. 1

(2) Incremental system

Fig. 2. 2 contains a machine position that is placed in the positive direction with respect to the reference point. Assume that feed from division n-1 to n (division interval) is executed. In this case, the following value is defined as the compensation amount:

$$(\text{Division interval} - \text{Actual movement distance}) \times 2 \text{ (Unit of output)}$$

- (3) Fig. 2. 3 contains a machine position that is placed in the negative direction with respect to the reference point. Assume that feed from division point n+1 to n by the division interval is executed. In this case, the following value is defined as the compensation amount:
 (Division interval + Actual movement distance) × 2 (Unit of output)




Fig. 2. 2




Fig. 2. 3


n: Division point compensation number
 1: Division interval

Unit : Unit of output
 Range : -128 to 127

(Note) The unit of output is used as the unit of setting. The actual unit of compensation pulses depends on the compensation scale factor.

9.3 EXAMPLE IN USING A LINEAR AXIS AS THE BASE AXIS

(1) When "mdvno" or "pdvno" exists at both ends of "rdvno":




Division point number	#4101	#4102	#4103	#4104	#4105	#4106	
Specified machine position	-300.000	-200.000	-100.000	100.000	200.000	300.000	
Real machine position	-299.999	-200.000	-100.003	100.002	200.002	299.999	
Compensation amount	Incremental	2	6	-6	-4	0	6
	Absolute	-2	0	6	-4	-4	2

rdvno	4103
mdvno	4101
pdvno	4106

If the setting range (mdvno to "pdvno") is exceeded, the compensation will be based on compensation amount at mdvno or "pdvno".

(2) When the range compensated is only the positive range:




Division point number		#4113	#4114	#4115	#4116	#4117
Compensation amount	Incremental	-4	2	0	6	2
	Absolute	-4	-2	-2	4	6

rdvno	4112
mdvno	4113
pdvno	4117

If the machine position exceeds "pdvno", the compensation will be based on the compensation amount at "pdvno". If the machine position is negative in this case, no compensation will be executed.


(3) When the range compensated is only the negative range:



Division point number		#4125	#4126	#4127	#4128	#4129	#4130	rdvno	4130
Compensation amount	Incremental	-2	2	6	2	0	-6	mdvno	4125
	Absolute	-2	-4	-2	4	6	6	pdvno	4130

If the machine position exceeds "mdvno", the compensation will be based on compensation amount at "mdvno".

(4) When compensation is executed in a range that contains no reference point:




Division point number		#4135	#4136	#4137	#4138	#4139	#4140
Compensation amount	Incremental			-2	-2	6	2
	Absolute			-2	-4	2	4

rdvno	4134
mdvno	4136
pdvno	4140

In this case, the compensation is executed in the range from "mdvno" to "pdvno". This setting rule applies also when the compensation is executed in a range which contains negative machine positions and no reference point.

9.4 EXAMPLE IN USING A ROTATION AXIS AS THE BASE AXIS



Division point number		#4123	#4124	#4125	#4126	#4127	#4128
Compensation amount	Incremental	-4	2	0	6	2	-6
	Absolute	-4	-2	-2	4	6	0

rdvno	4122
mdvno	4123
pdvno	4128

In this case, the sum of the compensation amounts set according to the incremental system is always "0". For the absolute system, the compensation amount at the terminal point (360 degrees) is always "0".

10. PLC CONSTANTS

10.1 PLC TIMER

10. PLC CONSTANTS

10.1 PLC TIMER

(SETUP PARAM 6. 1/14) to (SETUP PARAM 6. 2/14)

#	PLC device	Item	Details	Setting range
6000 ⋮ 6015	T000 ⋮ T015	10ms adding timer <10ms>	Set the time for the timer used in the PLC program (ladder). (Note) This setting value is valid when parameter "#6449 bit0" in the following "[BIT SELECT]" is set to "0".	0 to 32767 (×10ms)
6016 ⋮ 6095	T016 ⋮ T095	100ms adding timer <10ms>	Set the time for the timer used in the PLC program (ladder). (Note) This setting value is valid when parameter "#6449 bit0" in the following "[BIT SELECT]" is set to "0".	0 to 32767 (×100ms)
6096 ⋮ 6103	T096 ⋮ T103	100ms cumulative timer <100ms INC>	Set the time for the timer used in the PLC program (ladder). (Note) This setting value is valid when parameter "#6449 bit0" in the following "[BIT SELECT]" is set to "0".	0 to 32767 (×100ms)

(SETUP PARAM 6. 10/14) to (SETUP PARAM 6. 14/14)

#	PLC device	Item	Details	Setting range
6600 ⋮ 6999	R1200/bit0 R1250/bit0 R1224/bitF R1274/bitF	PLC timer expansion 10ms adding timer <10ms>	Set the time for the expanded PLC timer This is set for the timer coils: R1200 to R1224, and timer contacts: R1250 to R1274. A timer command can be issued to a contact other than the existing timer contacts (T0 to T103, Q0 to Q151).	0 to 32767 (×10ms)

10.2 PLC COUNTER

(SETUP PARAM 6. 3/14)

#	PLC device	Item	Details	Setting range
6200 ⋮ 6223	C000 ⋮ C023	Counter	Set the time for the counter used in the PLC program (ladder). (Note) This setting value is valid when parameter "#6449 bit1" in the following "[BIT SELECT]" is set to "0".	0 to 32767

10.3 PLC CONSTANTS

(SETUP PARAM 6. 4/14)

#	PLC device	Item	Details	Setting range
6301 6348	R2800,2801 R2894,2895	PLC constant	Set the value to be set in the data type R register used in the PLC program (ladder). Even if the data is set in the R register that corresponds to the PLC side when this parameter is displayed, the screen will not change. Enter a different screen once, and then select this screen again.	-99999999 to 99999999

(SETUP PARAM 6. 5/14)

#	PLC device	Item	Details	Setting range
6349 6396	R4900,4901 R4994,4995	PLC constant	Set the value to be set in the data type R register used in the PLC program (ladder). Even if the data is set in the R register that corresponds to the PLC side when this parameter is displayed, the screen will not change. Enter a different screen once, and then select this screen again.	-99999999 to 99999999

10.4 SELECTING THE PLC BIT

(SETUP PARAM 6. 6/14) to (SETUP PARAM 6. 7/14)

#	PLC device	Item	Details	Setting range
6401 6402 6495 6496	R2900-Low R2900-High R2947-Low R2947-High	Bit selection	This is the bit type parameter used in the PLC program (ladder). Even if the data is set in the R register that corresponds to the PLC side when this parameter is displayed, the screen will not change. Enter a different screen once, and then select this screen again. Some of the parameters following #6449 may be fixed according to the usage purpose. Refer to the PLC Program Development On-board Instruction Manual.	0: OFF 1: ON

(SETUP PARAM 6. 7/14) to (SETUP PARAM 6. 9/14)

#	PLC device	Item	Details	Setting range
6497 6498 6595 6596	R4400-Low R4400-High R4449-Low R4449-High	Bit selection expansion	This is the bit type parameter (expansion) used in the PLC program (ladder). Even if the data is set in the R register that corresponds to the PLC side when this parameter is displayed, the screen will not change. Enter a different screen once, and then select this screen again.	0: OFF 1: ON

10. PLC CONSTANTS
10.4 SELECTING THE PLC BIT

Table: "Contents of bit selection parameters #6449 to #6496"

	Symbol name	7	6	5	4	3	2	1		0
0	#6449 R2924 L	NC card Controller thermal alarm on	Setting display unit thermal alarm on	-		Counter C retention	Integrating timer T retention	PLC counter program on		PLC counter program on
1	#6450 R2924 H		External alarm message display	Alarm/operator change	Full screen display of message	-	Operator message on	1 R system	0 F system	Alarm message on
2	#6451 R2925 L	-	-	GX-Developer communication on	PLC development environment selection		Onboard editing not possible	-		Onboard on
3	#6452 R2925 H	-		GOT communication connection		Counter (fixed) retention	Integrating timer (fixed) retention			-
4	#6453 R2926 L	-	-	-	-	-	Message language change code			
5	#6454 R2926 H									
6	#6455 R2927 L	-	-	-	-	-	-	-	-	-
7	#6456 R2927 H	-	-	-	-	-	-	-	-	-
8	#6457 R2928 L	High-speed input specification 1								
9	#6458 R2928 H	High-speed input specification 2								
A	#6459 R2929 L	High-speed input specification 3 (Spare)								
B	#6460 R2929 H	High-speed input specification 4 (Spare)								
C	#6461 R2930 L	High-speed output specification 1								
D	#6462 R2930 H	High-speed output specification 2								
E	#6463 R2931 L	High-speed output specification 3 (Spare)								
F	#6464 R2931 H	High-speed output specification 4 (Spare)								

10. PLC CONSTANTS
10.4 SELECTING THE PLC BIT

	Symbol name	7	6	5	4	3	2	1	0
0	#6465 R2932 L	-	-	-	-	-	-	-	-
1	#6466 R2932 H	-	-	-	-	-	-	-	-
2	#6467 R2933 L	-	-	-	-	-	-	-	-
3	#6468 R2933 H								
4	#6469 R2934 L			Standard PLC parameter				-	MC alarm 4 output off
5	#6470 R2934 H								
6	#6471 R2935 L	-	-	-	-	-	-	-	-
7	#6472 R2935 H	-	-	-	-	-	-	-	-
8	#6473 R2936 L	-							-
9	#6474 R2936 H								
A	#6475 R2937 L								
B	#6476 R2937 H								
C	#6477 R2938 L								
D	#6478 R2938 H								
E	#6479 R2939 L								
F	#6480 R2939 H								

(Note 1) Be sure to set the bits indicated - and blanks to 0.

(Note 2) Parameters #6481 to #6496 are reserved for debugging by Mitsubishi.

11. MACRO LIST

(SETUP PARAM 7. 1/3)

#	Item	Details	Setting range (unit)										
7001 to 7091	M [01] to M [10]	<Code> Set the M code used for calling out the macro with the M command. This is valid when #1195 Mmac is set to 1.	1 to 9999										
7002 to 7092		<Type> Set the macro call out type. <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%; text-align: center;">0</td> <td>M98 PΔΔΔΔ; and equivalent value call</td> </tr> <tr> <td style="text-align: center;">1</td> <td>G65 PΔΔΔΔ; and equivalent value call</td> </tr> <tr> <td style="text-align: center;">2</td> <td>G66 PΔΔΔΔ; and equivalent value call</td> </tr> <tr> <td style="text-align: center;">3</td> <td>G66.1 PΔΔΔΔ; and equivalent value call</td> </tr> <tr> <td style="text-align: center;">others</td> <td>M98 PΔΔΔΔ; and equivalent value call</td> </tr> </table>	0	M98 PΔΔΔΔ; and equivalent value call	1	G65 PΔΔΔΔ; and equivalent value call	2	G66 PΔΔΔΔ; and equivalent value call	3	G66.1 PΔΔΔΔ; and equivalent value call	others	M98 PΔΔΔΔ; and equivalent value call	0 to 3
0	M98 PΔΔΔΔ; and equivalent value call												
1	G65 PΔΔΔΔ; and equivalent value call												
2	G66 PΔΔΔΔ; and equivalent value call												
3	G66.1 PΔΔΔΔ; and equivalent value call												
others	M98 PΔΔΔΔ; and equivalent value call												
7003 to 7093		<Program No.> Set the No. of the program to be called out.	1 to 99999999										
	M2mac	Set the type and program No. for when calling out the macro with the 2nd miscellaneous command. The macro will be called out with the #1170 M2name address command when #1198 M2mac is set to 1.											
7102		<Type> Same as the M call macro.	0 to 3										
7103		<Program No.> Same as the M call macro.	0 to 99999999										

(SETUP PARAM 7. 2/3)

#	Item	Details	Setting range (unit)
7201 to 7291	G [01] to G [10]	<Code> Set the G code to be used when calling the macro with a G command. Do not set a G code used in the system.	1 to 255
7202 to 7292		<Type> Same as the M call Marco.	0 to 3
7203 to 7293		<Program No.> Same as the M call Marco.	1 to 99999999
	Smac	Set the type and program No. for when calling the macro with an S command. This is valid when #1196 Smac is set to 1.	
7302		<Type> Same as the M call Marco.	0 to 3
7303		<Program No.> Same as the M call Marco.	1 to 99999999
	Tmac	Set the type and program No. for when calling the macro with a T command. This is valid when #1197 Tmac is set to 1.	
7312		<Type> Same as the M call macro.	0 to 3
7313		<Program No.> Same as the M call macro.	0 to 99999999

11. MACRO LIST

(SETUP PARAM 7. 3/3)

#	Item		Details	Setting range
7401	ASCII [01]	Valid	The ASCII code macro parameters (#7402 to 7405) are validated. 0: Invalid 1: Valid	0/1
7402		Code	Set the ASCII code used to call macros with the ASCII code.	L system: A, B, D, F, H, I, J, K, M, Q, R, S, T M system: A, B, F, H, I, K, M, Q, R, S, T
7403		Type	Set the macro call type. 0: M98, 1: G65, 2: G66, 3: G66.1	0 to 3
7404		Program No.	Set the number of the program called with macro call.	0 to 99999999
7405		Variable	When the call type is "0", set the variable number set after the ASCII code.	100 to 149
7411	ASCII [02]	Valid	The ASCII code macro parameters (#7412 to 7415) are validated. 0: Invalid 1: Valid	0/1
7412		Code	Set the ASCII code used to call macros with the ASCII code.	L system: A, B, D, F, H, I, J, K, M, Q, R, S, T M system: A, B, F, H, I, K, M, Q, R, S, T
7413		Type	Set the macro call type. 0: M98, 1: G65, 2: G66, 3: G66.1	0 to 3
7414		Program No.	Set the number of the program called with macro call.	0 to 99999999
7415		Variable	When the call type is "0", set the variable number set after the ASCII code.	100 to 149

12. POSITION SWITCH

12.1 OUTLINE OF FUNCTION

The position switch (PSW) is used as an alternate switch for the dog switch provided on an axis of the machine. The position switch uses parameters by which the names of axes and their corresponding coordinates indicating imaginary dog positions are defined in advance. When the machine reaches the imaginary dog position, a signal is output to the PLC interface. The position switch thus works as an imaginary dog switch.

(SETUP PARAM 8. 1/1)

#	Item		Details	Setting range (unit)
7500	Pcheck	High-speed switching of position switch	Specify whether to perform position switch area checking at high speeds. 0: Do not perform position switch area checking at high speed (do it the same as before). 1: Perform position switch area checking at high speed.	0/1
75□1	<axis>	Axis name	Specify the name of the axis for which a position switch is provided.	X, Y, Z, U, V, W, A, B, or C axis address
75□2	<dog1>	Imaginary dog position 1	When the machine enters the range between imaginary dog positions 1 and 2, a signal is output to the PLC. System 1 device X 270 System 2 device U0F0	-99999.999 to 99999.999 (0.001mm)
75□3	<dog2>	Imaginary dog position 2		
75□4	<check>	Selection of area check method	When position switch area checking at high speed is selected, specify the mode of area checking, i.e., whether to use the command type machine position or detector feedback position, for each position switch point. 0: Use the command type machine position as the machine position for position switch area checking. 1: Use the detector feedback position as the machine position for position switch area checking. Note: This parameter is valid only when 1 set in "#7500 Pcheck."	0/1




12. POSITION SWITCH
12.1 OUTLINE OF FUNCTION


Position switch numbers of PSW1 to PSW8 and signal devices

	<axis>	<dog1>	<dog2>	System 1 device	System 2 device
PSW1	#7501	#7502	#7503	X270	U0F0
PSW2	#7511	#7512	#7513	X271	U0F1
PSW3	#7521	#7522	#7523	X272	U0F2
PSW4	#7531	#7532	#7533	X273	U0F3
PSW5	#7541	#7542	#7543	X274	U0F4
PSW6	#7551	#7552	#7553	X275	U0F5
PSW7	#7561	#7562	#7563	X276	U0F6
PSW8	#7571	#7572	#7573	X277	U0F7





Instead of the dog switch provided on the machine axis, the coordinate values indicating imaginary dog positions (dog1 and dog2) on the coordinate axis of the axis name preset with axis are set with the position switches (PSW1 - PSW8). When the machine reaches the position, the signal is output to the device corresponding to the PLC interface.

Example of settings of dog1 and dog2 and operation

Setting of dog1 and dog2	dog1, dog2 position	Operation
dog1 < dog2		A signal is output between dog1 and dog2.
dog1 > dog2		A signal is output between dog1 and dog2.
dog1 = dog2		If dog1 equals dog2, the dog1 position triggers a signal.



12. POSITION SWITCH
12.2 CANCELING THE POSITION SWITCH

Setting of dog1 and dog2	dog1, dog2 position	Description
dog1 < dog2	 <p>(Example) dog1 = 30.000 dog2 = 330.000</p>	A signal is output between dog1 and dog2.
	 <p>(Example) dog1 = -30.000 dog2 = 30.000</p>	A signal is also output when dog1 is negative.
dog1 > dog2	 <p>(Example) dog1 = 330.000 dog2 = 30.000</p>	A signal is output between dog2 and dog1.
$ \text{dog1} - \text{dog2} \geq 360$	 <p>(Example) dog1 = 30.000 dog2 = 390.000</p>	A signal is kept output when the difference between dog1 and dog2 exceeds 360 degrees.

12.2 CANCELING THE POSITION SWITCH

To cancel the position switch, enter the number (#75□1) of the position switch to be canceled in # () of the setting field, enter a slash "/" in DATA (), then press the INPUT key. This deletes the axis name for the specified position switch, thus invalidating the position switch.

The data specified for <dog1> and <dog2> are still stored in memory. To validate the position switch again, therefore, it is enough to specify the axis name only.

13. AUXILIARY AXIS PARAMETER

Turn the NC power OFF after setting parameters indicated with a (PR) in the table. The setting will be validated after the power is turned ON again.

No.	Name	Details	Setting range	Default value																						
1 (PR)	MSR	Motor series	Set the motor series. This is automatically judged by the system when the default value (0000) is set.	0000 to FFFF (hexadecimal) 0000																						
2 (PR)	RTY	Regeneration option type	Set the regenerative resistor type. Do not set values without a description. <div style="text-align: center;"> <table border="1" style="display: inline-table; margin-bottom: 5px;"> <tr> <td style="padding: 2px 5px;">0</td> <td style="padding: 2px 5px;">0</td> <td style="padding: 2px 5px;">0</td> <td style="padding: 2px 5px;">0</td> </tr> </table> (Default value) </div> <table border="1" style="margin-left: auto; margin-right: auto; border-collapse: collapse;"> <thead> <tr> <th style="padding: 2px 5px;">Setting value</th> <th style="padding: 2px 5px;">Details</th> </tr> </thead> <tbody> <tr> <td style="text-align: center; padding: 2px 5px;">0</td> <td style="padding: 2px 5px;">Amplifier standard built-in resistor (10CT has no built-in resistor)</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">1</td> <td style="padding: 2px 5px;">Setting prohibited</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">2</td> <td style="padding: 2px 5px;">MR-RB032 (30W)</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">3</td> <td style="padding: 2px 5px;">MR-RB12 (100W)</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">4</td> <td style="padding: 2px 5px;">MR-RB32 (300W)</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">5</td> <td style="padding: 2px 5px;">MR-RB30 (300W)</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">6</td> <td style="padding: 2px 5px;">MR-RB50 (500W)</td> </tr> <tr> <td style="text-align: center; padding: 2px 5px;">7~F</td> <td style="padding: 2px 5px;"></td> </tr> </tbody> </table>	0	0	0	0	Setting value	Details	0	Amplifier standard built-in resistor (10CT has no built-in resistor)	1	Setting prohibited	2	MR-RB032 (30W)	3	MR-RB12 (100W)	4	MR-RB32 (300W)	5	MR-RB30 (300W)	6	MR-RB50 (500W)	7~F		
0	0	0	0																							
Setting value	Details																									
0	Amplifier standard built-in resistor (10CT has no built-in resistor)																									
1	Setting prohibited																									
2	MR-RB032 (30W)																									
3	MR-RB12 (100W)																									
4	MR-RB32 (300W)																									
5	MR-RB30 (300W)																									
6	MR-RB50 (500W)																									
7~F																										
3 (PR)	PC1	Motor side gear ratio (machine rotation ratio)	Set the No. of gear teeth on the motor side and the No. of gear teeth on the machine side as an integer reduced to its lowest terms.	1 to 32767	1																					
4 (PR)	PC2	Machine side gear ratio (motor rotation ratio)	Set the total gear ratio if there are multiple gear levels. For rotation axes, set the No. of motor rotation speed per machine rotation.	1 to 32767	1																					
5 (PR)	PIT	Feed pitch	Set 360 (default value) for rotation axes. Set the feed lead for linear axes.	1 to 32767 (° or mm)	360																					
6	INP	In-position detection width	In-position is detected when the position droop becomes this setting value or less.	1 to 32767 (1/1000° or μm)	50																					

13. AUXILIARY AXIS PARAMETER

No.	Name	Details	Setting range	Default value																										
7	ATU	Auto-tuning	Set the adjustment of the auto-tuning. Do not set values without a description.																											
<table border="1" style="margin: auto;"> <tr> <td>0</td> <td>1</td> <td>0</td> <td>2</td> </tr> </table> (Default setting value)					0	1	0	2																						
0	1	0	2																											
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;">Setting value</th> <th>Details</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>Low response (low-rigidity loads, loads which easily vibrate)</td> </tr> <tr> <td>2</td> <td>Standard setting value</td> </tr> <tr> <td>3</td> <td>Standard setting value</td> </tr> <tr> <td>4</td> <td>Standard setting value</td> </tr> <tr> <td>5</td> <td>High response (high-rigidity loads, loads which do not easily vibrate)</td> </tr> </tbody> </table> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;">Setting value</th> <th>Details</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>Standard</td> </tr> <tr> <td>2</td> <td>Large friction amount (set the position loop gain slightly lower)</td> </tr> </tbody> </table> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;">Setting value</th> <th>Details</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>Only auto-tuning PG2, VG2, VIC, and GD2.</td> </tr> <tr> <td>1</td> <td>Only auto-tuning PG1, PG2, VG1, VG2, VIC, and GD2 (total gain). (Standard setting)</td> </tr> <tr> <td>2</td> <td>No auto-tuning.</td> </tr> </tbody> </table>					Setting value	Details	1	Low response (low-rigidity loads, loads which easily vibrate)	2	Standard setting value	3	Standard setting value	4	Standard setting value	5	High response (high-rigidity loads, loads which do not easily vibrate)	Setting value	Details	0	Standard	2	Large friction amount (set the position loop gain slightly lower)	Setting value	Details	0	Only auto-tuning PG2, VG2, VIC, and GD2.	1	Only auto-tuning PG1, PG2, VG1, VG2, VIC, and GD2 (total gain). (Standard setting)	2	No auto-tuning.
Setting value	Details																													
1	Low response (low-rigidity loads, loads which easily vibrate)																													
2	Standard setting value																													
3	Standard setting value																													
4	Standard setting value																													
5	High response (high-rigidity loads, loads which do not easily vibrate)																													
Setting value	Details																													
0	Standard																													
2	Large friction amount (set the position loop gain slightly lower)																													
Setting value	Details																													
0	Only auto-tuning PG2, VG2, VIC, and GD2.																													
1	Only auto-tuning PG1, PG2, VG1, VG2, VIC, and GD2 (total gain). (Standard setting)																													
2	No auto-tuning.																													
8	PG1	Position loop gain 1	Set the position loop gain for the model loop. Determine the tracking ability regarding the position commands.	4 to 1000 (1/s)	70																									
9			(Not used.)		0																									
10	EMGt	Deceleration control time constant	Set the deceleration time from the clamp speed (Aspeed1). For normal rapid traverse, set the same value as the acceleration/deceleration time constant.	0 to 32768 (ms)	500																									
11			(Not used.)		0																									
12			(Not used.)		0																									
13	MBR	Vertical axis drop prevention time	Input the time the servo OFF is delayed during servo OFF command. Increase the setting by 100ms at a time and set the minimum value where the axis does not drop.	0 to 1000 (ms)	100																									
14	NCH	Notch filter No.	Set the frequency of the machine resonance suppression filter. Do not set values without a description.	<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <tr> <th style="width: 10%;">Setting value</th> <td>0</td> <td>1</td> <td>2</td> <td>3</td> <td>4</td> <td>5</td> <td>6</td> <td>7</td> </tr> <tr> <th>Frequency (Hz)</th> <td>No start</td> <td>1125</td> <td>563</td> <td>375</td> <td>282</td> <td>225</td> <td>188</td> <td>161</td> </tr> </table>		Setting value	0	1	2	3	4	5	6	7	Frequency (Hz)	No start	1125	563	375	282	225	188	161							
Setting value	0	1	2	3	4	5	6	7																						
Frequency (Hz)	No start	1125	563	375	282	225	188	161																						

13. AUXILIARY AXIS PARAMETER

No.	Name	Details	Setting range	Default value										
15		(Not used.)		0										
16	JIT	Jitter compensation Set the No. of ignored jitter compensation pulses. Do not set values without a description. <table border="1" data-bbox="529 491 1342 612"> <tr> <td>Setting value</td> <td>0</td> <td>1</td> <td>2</td> <td>3</td> </tr> <tr> <td>Number of ignore pulses</td> <td>No start</td> <td>1</td> <td>2</td> <td>3</td> </tr> </table>	Setting value	0	1	2	3	Number of ignore pulses	No start	1	2	3		
Setting value	0	1	2	3										
Number of ignore pulses	No start	1	2	3										
17		(Not used.)		0										
18		(Not used.)		0										
19	PG2	Position loop gain 2 Set the position loop gain of the actual loop. Determine the position responsiveness for external disturbance.	1 to 500 (1/s)	25										
20	VG1	Speed loop gain 1 Set the speed loop gain of the model loop. Determine the tracking ability regarding the speed commands.	20 to 5000 (1/s)	1200										
21	VG2	Speed loop gain 2 Set the speed loop gain of the actual loop. Determine the speed responsiveness for external disturbance.	20 to 8000 (1/s)	600										
22	VIC	Speed integral compensation Determine the characteristics of the speed low-frequency region.	1 to 1000 (ms)	20										
23	VDC	Speed differential compensation PI control normally results from a default value of 1000. Adjust the overshoot amount by lowering in increments of 20.	0 to 1000	1000										
24	DG2	Load inertia ratio Set the load inertia ratio for the motor inertia.	0.0 to 50.0 (fold)	2.0										
25		(Not used.)		0										
30 (PR)	MTY	Motor type Set the motor type. This is automatically judged by the system when the default value (0000) is set.	0000 to FFFF (hexadecimal)	0000										

13. AUXILIARY AXIS PARAMETER

No.	Name	Details	Setting range	Default value																																				
50	MD1	D/A output channel 1 data No.	Set the Nos. of the data to be output on D/A output channel 1. <div style="border: 1px solid black; display: inline-block; padding: 2px;">0 0 0 0</div> (Default setting value)																																					
		<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">Setting value</th> <th style="width: 50%;">Details</th> <th style="width: 40%;">Magnification</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>Speed feedback (with sign)</td> <td>Maximum rotation speed = 8V</td> </tr> <tr> <td>1</td> <td>Current feedback (with sign)</td> <td>Maximum current (torque) = 8V</td> </tr> <tr> <td>2</td> <td>Speed feedback (without sign)</td> <td>Maximum rotation speed = 8V</td> </tr> <tr> <td>3</td> <td>Current feedback (without sign)</td> <td>Maximum current (torque) = 8V</td> </tr> <tr> <td>4</td> <td>Current command</td> <td>Maximum current (torque) = 8V</td> </tr> <tr> <td>5</td> <td>Command FΔT</td> <td>100000 [degrees/min] = 10V</td> </tr> <tr> <td>6</td> <td>Position droop 1 (1/1)</td> <td>2048 [pulse] = 10V</td> </tr> <tr> <td>7</td> <td>Position droop 2 (1/4)</td> <td>8192 [pulse] = 10V</td> </tr> <tr> <td>8</td> <td>Position droop 3 (1/16)</td> <td>32768 [pulse] = 10V</td> </tr> <tr> <td>9</td> <td>Position droop 4 (1/32)</td> <td>65536 [pulse] = 10V</td> </tr> <tr> <td>A</td> <td>Position droop 5 (1/64)</td> <td>131072 [pulse] = 10V</td> </tr> </tbody> </table>	Setting value	Details	Magnification	0	Speed feedback (with sign)	Maximum rotation speed = 8V	1	Current feedback (with sign)	Maximum current (torque) = 8V	2	Speed feedback (without sign)	Maximum rotation speed = 8V	3	Current feedback (without sign)	Maximum current (torque) = 8V	4	Current command	Maximum current (torque) = 8V	5	Command FΔT	100000 [degrees/min] = 10V	6	Position droop 1 (1/1)	2048 [pulse] = 10V	7	Position droop 2 (1/4)	8192 [pulse] = 10V	8	Position droop 3 (1/16)	32768 [pulse] = 10V	9	Position droop 4 (1/32)	65536 [pulse] = 10V	A	Position droop 5 (1/64)	131072 [pulse] = 10V		
Setting value	Details	Magnification																																						
0	Speed feedback (with sign)	Maximum rotation speed = 8V																																						
1	Current feedback (with sign)	Maximum current (torque) = 8V																																						
2	Speed feedback (without sign)	Maximum rotation speed = 8V																																						
3	Current feedback (without sign)	Maximum current (torque) = 8V																																						
4	Current command	Maximum current (torque) = 8V																																						
5	Command FΔT	100000 [degrees/min] = 10V																																						
6	Position droop 1 (1/1)	2048 [pulse] = 10V																																						
7	Position droop 2 (1/4)	8192 [pulse] = 10V																																						
8	Position droop 3 (1/16)	32768 [pulse] = 10V																																						
9	Position droop 4 (1/32)	65536 [pulse] = 10V																																						
A	Position droop 5 (1/64)	131072 [pulse] = 10V																																						
51	MO1	D/A output channel 1 output offset	Set this value when the zero level of D/A output channel 1 is not suitable.	-999 to 999 (mV)	0																																			
52			(Not used.)		0																																			
53	MD2	D/A output channel 2 data No.	Set the Nos. of the data to be output on D/A output channel 2. The descriptions are the same as "50 MD1".	0000 to FFFF (hexadecimal)	0000																																			
54	MO2	D/A output channel 2 output offset	Set this value when the zero level of D/A output channel 2 is not suitable.	-999 to 999 (mV)	0																																			
55			(Not used.)		0																																			
100 (PR)	station	No. of indexing stations	Set the No. of stations. For linear axes, this value is expressed by: No. of divisions = No. of stations - 1.	2 to 360	2																																			

13. AUXILIARY AXIS PARAMETER

No.	Name	Details	Setting range	Default value																																																																																					
101 (PR)	Cont1 Control parameter 1	<p>This is a HEX setting parameter. Set bits without a description to their default values.</p> <table border="1" data-bbox="512 370 1437 478"> <tr> <td>bit</td> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td><td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td>Default value</td> <td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>1</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td> </tr> </table> <table border="1" data-bbox="512 526 1437 1507"> <thead> <tr> <th>bit</th> <th>Meaning when "0" is set</th> <th>Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td>0</td> <td></td> <td></td> </tr> <tr> <td>1</td> <td>High-speed zero point return after establishment of zero point.</td> <td>Dog-type return for each zero point return operation.</td> </tr> <tr> <td>2</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> </tr> <tr> <td>8</td> <td>Reference point return direction (+)</td> <td>Reference point return direction (-)</td> </tr> <tr> <td>9</td> <td>Rotation direction determined by operation control signal (DIR)</td> <td>Rotation direction in the shortcut direction</td> </tr> <tr> <td>A</td> <td>Machine basic position becomes the origin point</td> <td>Electrical zero point becomes the origin point</td> </tr> <tr> <td>B</td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> </tr> <tr> <td>D</td> <td>Coordinate zero point creation valid</td> <td>Zero point established at power supply ON position</td> </tr> <tr> <td>E</td> <td>Rotation direction in operation control signal (DIR) or in the shortcut direction</td> <td>Rotation direction in the random position command sign direction</td> </tr> <tr> <td>F</td> <td>Stopper direction is positioning direction</td> <td>Stopper direction is in the sign direction of the stopper amount</td> </tr> </tbody> </table>	bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0	Default value	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	bit	Meaning when "0" is set	Meaning when "1" is set	0			1	High-speed zero point return after establishment of zero point.	Dog-type return for each zero point return operation.	2			3			4			5			6			7			8	Reference point return direction (+)	Reference point return direction (-)	9	Rotation direction determined by operation control signal (DIR)	Rotation direction in the shortcut direction	A	Machine basic position becomes the origin point	Electrical zero point becomes the origin point	B			C			D	Coordinate zero point creation valid	Zero point established at power supply ON position	E	Rotation direction in operation control signal (DIR) or in the shortcut direction	Rotation direction in the random position command sign direction	F	Stopper direction is positioning direction	Stopper direction is in the sign direction of the stopper amount		
bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																																																																									
Default value	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0																																																																									
bit	Meaning when "0" is set	Meaning when "1" is set																																																																																							
0																																																																																									
1	High-speed zero point return after establishment of zero point.	Dog-type return for each zero point return operation.																																																																																							
2																																																																																									
3																																																																																									
4																																																																																									
5																																																																																									
6																																																																																									
7																																																																																									
8	Reference point return direction (+)	Reference point return direction (-)																																																																																							
9	Rotation direction determined by operation control signal (DIR)	Rotation direction in the shortcut direction																																																																																							
A	Machine basic position becomes the origin point	Electrical zero point becomes the origin point																																																																																							
B																																																																																									
C																																																																																									
D	Coordinate zero point creation valid	Zero point established at power supply ON position																																																																																							
E	Rotation direction in operation control signal (DIR) or in the shortcut direction	Rotation direction in the random position command sign direction																																																																																							
F	Stopper direction is positioning direction	Stopper direction is in the sign direction of the stopper amount																																																																																							

13. AUXILIARY AXIS PARAMETER

No.	Name	Details	Setting range	Default value																																																																																					
102 (PR)	Cont2 Control parameter 2	<p>This is a HEX setting parameter. Set bits without a description to their default values.</p> <table border="1"> <thead> <tr> <th>bit</th> <th>F</th> <th>E</th> <th>D</th> <th>C</th> <th>B</th> <th>A</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> <th>1</th> <th>0</th> </tr> </thead> <tbody> <tr> <td>Default value</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>1</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>1</td> <td>1</td> <td>0</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th>bit</th> <th>Meaning when "0" is set</th> <th>Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td>0</td> <td></td> <td></td> </tr> <tr> <td>1</td> <td>Error not corrected at servo OFF</td> <td>Error corrected at servo OFF</td> </tr> <tr> <td>2</td> <td>Linear axis</td> <td>Rotation axis</td> </tr> <tr> <td>3</td> <td>Station assignment direction CW</td> <td>Station assignment direction CCW</td> </tr> <tr> <td>4</td> <td>Uniform index</td> <td>Non-uniform index</td> </tr> <tr> <td>5</td> <td>DO channel standard assignment</td> <td>DO channel reverse assignment</td> </tr> <tr> <td>6</td> <td>2-wire detector communication</td> <td>4-wire detector communication</td> </tr> <tr> <td>7</td> <td>Incremental detection</td> <td>Absolute position detection</td> </tr> <tr> <td>8</td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> </tr> </tbody> </table>	bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0	Default value	0	0	0	0	0	0	0	0	1	0	0	0	0	1	1	0	bit	Meaning when "0" is set	Meaning when "1" is set	0			1	Error not corrected at servo OFF	Error corrected at servo OFF	2	Linear axis	Rotation axis	3	Station assignment direction CW	Station assignment direction CCW	4	Uniform index	Non-uniform index	5	DO channel standard assignment	DO channel reverse assignment	6	2-wire detector communication	4-wire detector communication	7	Incremental detection	Absolute position detection	8			9			A			B			C			D			E			F				
bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																																																																									
Default value	0	0	0	0	0	0	0	0	1	0	0	0	0	1	1	0																																																																									
bit	Meaning when "0" is set	Meaning when "1" is set																																																																																							
0																																																																																									
1	Error not corrected at servo OFF	Error corrected at servo OFF																																																																																							
2	Linear axis	Rotation axis																																																																																							
3	Station assignment direction CW	Station assignment direction CCW																																																																																							
4	Uniform index	Non-uniform index																																																																																							
5	DO channel standard assignment	DO channel reverse assignment																																																																																							
6	2-wire detector communication	4-wire detector communication																																																																																							
7	Incremental detection	Absolute position detection																																																																																							
8																																																																																									
9																																																																																									
A																																																																																									
B																																																																																									
C																																																																																									
D																																																																																									
E																																																																																									
F																																																																																									
103 (PR)	EmgCont Emergency stop control	<p>This is a HEX setting parameter. Set bits without a description to their default values.</p> <table border="1"> <thead> <tr> <th>bit</th> <th>F</th> <th>E</th> <th>D</th> <th>C</th> <th>B</th> <th>A</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> <th>1</th> <th>0</th> </tr> </thead> <tbody> <tr> <td>Default value</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>1</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th>bit</th> <th>Meaning when "0" is set</th> <th>Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>External emergency stop valid</td> <td>External emergency stop invalid (default value)</td> </tr> <tr> <td>1</td> <td>Dynamic brake stop at emergency stop</td> <td>Deceleration control stop at emergency stop</td> </tr> <tr> <td>2</td> <td>NC bus emergency stop input valid</td> <td>NC bus emergency stop input invalid</td> </tr> <tr> <td>3</td> <td>NC bus emergency stop output valid</td> <td>NC bus emergency stop output invalid</td> </tr> <tr> <td>4</td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> </tr> <tr> <td>6</td> <td></td> <td></td> </tr> <tr> <td>7</td> <td></td> <td></td> </tr> <tr> <td>8</td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> </tr> </tbody> </table>	bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0	Default value	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	bit	Meaning when "0" is set	Meaning when "1" is set	0	External emergency stop valid	External emergency stop invalid (default value)	1	Dynamic brake stop at emergency stop	Deceleration control stop at emergency stop	2	NC bus emergency stop input valid	NC bus emergency stop input invalid	3	NC bus emergency stop output valid	NC bus emergency stop output invalid	4			5			6			7			8			9			A			B			C			D			E			F				
bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																																																																									
Default value	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1																																																																									
bit	Meaning when "0" is set	Meaning when "1" is set																																																																																							
0	External emergency stop valid	External emergency stop invalid (default value)																																																																																							
1	Dynamic brake stop at emergency stop	Deceleration control stop at emergency stop																																																																																							
2	NC bus emergency stop input valid	NC bus emergency stop input invalid																																																																																							
3	NC bus emergency stop output valid	NC bus emergency stop output invalid																																																																																							
4																																																																																									
5																																																																																									
6																																																																																									
7																																																																																									
8																																																																																									
9																																																																																									
A																																																																																									
B																																																																																									
C																																																																																									
D																																																																																									
E																																																																																									
F																																																																																									

13. AUXILIARY AXIS PARAMETER

No.	Name		Details	Setting range	Default value
104 (PR)	tleng	Linear axis stroke length	Set the movement stroke length for linear axes. This is meaningless when setting non-uniform assignments or commanding random positions.	0.001 to 99999.999 (mm)	100.000
110	ZRNspeed	Reference point return speed	Set the clamp value of the feedrate when a reference point return is carried out. The feedrate becomes the manual operation speed of the parameter group selected at that time, but it is clamped by this parameter setting value.	1 to 100000 (°/min or mm/min)	1000
111	ZRNcreep	Reference point return creep speed	Set the approach speed to the reference point after dog detection during a reference point return.	1 to 65535 (°/min or mm/min)	200
112	grid mask	Grid mask	Set the amount that the dog is artificially extended. Set 1/2 the grid spacing as a standard.	0 to 65536 (1/1000° or μm)	0
113 (PR)	grspc	Grid spacing	Divide the grid spacing that is the conventional motor rotation movement amount into 2, 4, 8, or 16 divisions.	0 to 4 (1/2 ⁿ division)	0
114	ZRNshift	Reference point shift amount	Set the shift amount in a dog-type reference point return from the electric zero point determined on the grid to the reference point.	0 to 65536 (1/1000° or μm)	0
115	ST. ofset	Station offset	Set the distance (offset) from the reference point to station 1.	-99999.999 to 99999.999 (° or mm)	0.000
116 (PR)	ABS base	Absolute position zero point	When movement of the machine coordinate zero point from the origin point is required during absolute position initializing, set that movement amount.	-99999.999 to 99999.999 (° or mm)	0.000
117	Limit (+)	Soft limit (+)	Commands in the plus direction that exceed this setting value are not possible. If the machine is in a position exceeding the setting value, commands in the minus direction are possible. The soft limit function will not operate if Limit (+) and Limit (-) are set to the same value.	-99999.999 to 99999.999 (mm)	1.000
118	Limit (-)	Soft limit (-)	Commands in the minus direction that exceed this value are not possible. If the machine is in a position exceeding the setting value, commands in the plus direction are possible.	-99999.999 to 99999.999 (mm)	1.000

13. AUXILIARY AXIS PARAMETER

No.	Name	Details	Setting range	Default value																																																																																					
120	ABS Type	Absolute position detection parameter	<p>This parameter is set as a hexadecimal. Set the default value for bits that have no description.</p> <table border="1"> <tr> <td>bit</td> <td>F</td><td>E</td><td>D</td><td>C</td><td>B</td><td>A</td><td>9</td><td>8</td><td>7</td><td>6</td><td>5</td><td>4</td><td>3</td><td>2</td><td>1</td><td>0</td> </tr> <tr> <td>Default value</td> <td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>0</td><td>1</td><td>0</td><td>0</td> </tr> </table> <table border="1"> <thead> <tr> <th>bit</th> <th>Meaning when "0" is set</th> <th>Meaning when "1" is set</th> </tr> </thead> <tbody> <tr><td>0</td><td></td><td></td></tr> <tr><td>1</td><td>Dogless-type method initializing</td><td>Dog-type method initializing</td></tr> <tr><td>2</td><td>Mechanical stopper method initializing</td><td>Origin point alignment method initializing</td></tr> <tr><td>3</td><td>Electrical zero point direction (+)</td><td>Electrical zero point direction (-)</td></tr> <tr><td>4</td><td></td><td></td></tr> <tr><td>5</td><td></td><td></td></tr> <tr><td>6</td><td></td><td></td></tr> <tr><td>7</td><td></td><td></td></tr> <tr><td>8</td><td></td><td></td></tr> <tr><td>9</td><td></td><td></td></tr> <tr><td>A</td><td></td><td></td></tr> <tr><td>B</td><td></td><td></td></tr> <tr><td>C</td><td></td><td></td></tr> <tr><td>D</td><td></td><td></td></tr> <tr><td>E</td><td></td><td></td></tr> <tr><td>F</td><td></td><td></td></tr> </tbody> </table>		bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0	Default value	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	bit	Meaning when "0" is set	Meaning when "1" is set	0			1	Dogless-type method initializing	Dog-type method initializing	2	Mechanical stopper method initializing	Origin point alignment method initializing	3	Electrical zero point direction (+)	Electrical zero point direction (-)	4			5			6			7			8			9			A			B			C			D			E			F		
bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																																																																									
Default value	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0																																																																									
bit	Meaning when "0" is set	Meaning when "1" is set																																																																																							
0																																																																																									
1	Dogless-type method initializing	Dog-type method initializing																																																																																							
2	Mechanical stopper method initializing	Origin point alignment method initializing																																																																																							
3	Electrical zero point direction (+)	Electrical zero point direction (-)																																																																																							
4																																																																																									
5																																																																																									
6																																																																																									
7																																																																																									
8																																																																																									
9																																																																																									
A																																																																																									
B																																																																																									
C																																																																																									
D																																																																																									
E																																																																																									
F																																																																																									
123	ABS check	Absolute position power OFF tolerable movement value	0.000 to 99999.999 (° or mm)	0.000																																																																																					
130	backlash	Backlash compensation amount	0 to 9999 (1/1000° or μm)	0																																																																																					
132			(Not used.)	0																																																																																					
133			(Not used.)	0																																																																																					
134			(Not used.)	0																																																																																					
135			(Not used.)	0																																																																																					

13. AUXILIARY AXIS PARAMETER

< Operation parameter group 1 >

No.	Name	Details	Setting range	Default value
150	Aspeed1 Operation parameter group 1 Automatic operation speed	Set the feedrate during automatic operation when operation parameter group 1 is selected. This parameter is regarded as the clamp value for the automatic operation speeds and manual operation speeds of all operation groups. A speed exceeding Aspeed1 cannot be commanded, even if set in the parameters.	1 to 100000 (°/min or mm/min)	5000
151	Mspeed1 Operation parameter group 1 Manual operation speed	Set the feedrate during manual operation or JOG operation when operation parameter group 1 is selected.	1 to 100000 (°/min or mm/min)	2000
152	time1.1 Operation parameter group 1 Acceleration/deceleration time constant 1	Set the linear acceleration/deceleration time for Aspeed 1 (the operation parameter group 1 automatic operation speed (clamp speed)) when operation parameter group 1 is selected. When operating at speeds less than the clamp speed, the axis will linearly accelerate/decelerate at the inclination determined above. When this is set together with acceleration/deceleration time constant 2, S-shape acceleration/deceleration is carried out. In this case, set the acceleration/deceleration time of the linear part in this parameter.	1 to 9999 (ms)	100
153	time1.2 Operation parameter group 1 Acceleration/deceleration time constant 2	Set this parameter when carrying out S-shape acceleration/deceleration. When S-shape acceleration/deceleration is carried out, set the total time of the non-linear parts. When "1" is set in this parameter, linear acceleration/deceleration is carried out. In the handle feed operation mode, this set value is regarded as the time constant for the linear acceleration/deceleration.	1 to 999 (ms)	1

13. AUXILIARY AXIS PARAMETER

No.	Name	Details	Setting range	Default value
154	TL1 Operation parameter group 1 Torque limit value	Set the motor output torque limit value when operation parameter group 1 is selected. At the default value, the torque is limited at the maximum torque of the motor specification. Set the default value when torque limit is not especially required. In the stopper positioning operation mode, this becomes the torque limit value when positioning to the stopper starting coordinates.	1 to 500 (%)	500
155	OD1 Operation parameter group 1 Excessive error detection width	Set the excessive error detection width when operation parameter group 1 is selected. An alarm of excessive error (S03 0052) is detected when the position droop becomes larger than this setting value. In the stopper positioning operation mode, this becomes the excessive error detection width when positioning to the stopper starting coordinates.	0 to 32767 (° or mm)	100
156	just1 Operation parameter group 1 Set position output width	The signal indicating that the machine position is at any one of the stations is the set position reached (JST) signal. During automatic operation, the automatic set position reached (JSTA) signal is also output under the same conditions. Set the tolerable values at which these signals are output when operation parameter group 1 is selected. These signals turn OFF when the machine position is separated from the station by more than this value.	0.000 to 99999.999 (° or mm)	0.500
157	near1 Operation parameter group 1 Near set position output width	The signal indicating that the machine position is near any one of the station positions is the near set position (NEAR) signal. Set the tolerable value at which this signal is output when operation parameter group 1 is selected. This value is generally set wider than the set position output width. During operations, this is related to special commands when the station selection is "0".	0.000 to 99999.999 (° or mm)	1.000

13. AUXILIARY AXIS PARAMETER

< Operation parameter group 2 >

No.	Name	Details	Setting range	Default value	
158	Aspeed2	Operation parameter group 2 Automatic operation speed	Set the feedrate during automatic operation when operation parameter group 2 is selected.	1 to 100000 (°/min or mm/min)	5000
159	Mspeed2	Operation parameter group 2 Manual operation speed	Set the feedrate during manual operation or JOG operation when operation parameter group 2 is selected.	1 to 100000 (°/min or mm/min)	2000
160	time2.1	Operation parameter group 2 Acceleration/deceleration time constant 1	Set the linear acceleration/deceleration time for the operation parameter group 1 automatic operation speed (clamp speed) when operation parameter group 2 is selected. When operating at speeds less than the clamp speed, the axis will linearly accelerate/decelerate at the inclination determined above. When this is set together with acceleration/deceleration time constant 2, S-shape acceleration/deceleration is carried out. In this case, set the acceleration/deceleration time of the linear part in this parameter.	1 to 9999 (ms)	100
161	time2.2	Operation parameter group 2 Acceleration/deceleration time constant 2	Set this parameter when carrying out S-shape acceleration/deceleration. When S-shape acceleration/deceleration is carried out, set the total time of the non-linear parts. When 1 is set in this parameter, linear acceleration/deceleration is carried out. In the handle feed operation mode, this set value is regarded as the time constant for the linear acceleration/deceleration.	1 to 9999 (ms)	1

13. AUXILIARY AXIS PARAMETER

No.	Name		Details	Setting range	Default value
162	TL2	Operation parameter group 2 Torque limit value	Set the motor output torque limit value when operation parameter group 2 is selected. At the default value, the torque is limited at the maximum torque of the motor specifications. Set the default value when torque limit is not especially required. In the stopper positioning operation mode, this becomes the torque limit value during stopper operation.	1 to 500 (%)	500
163	OD2	Operation parameter group 2 Excessive error detection width	Set the excessive error detection width when operation parameter group 2 is selected. An excessive error alarm (S03 0052) is detected when the position droop becomes larger than this setting value. In the stopper positioning operation mode, this becomes the excessive error detection width during stopper operation.	0 to 32767 (° or mm)	100
164	just2	Operation parameter group 2 Set position output width	The signal indicating that the machine position is at any one of the stations is the set position reached (JST) signal. During automatic operation, the automatic set position reached (JSTA) signal is also output under the same conditions. Set the tolerable values at which these signals are output when operation parameter group 2 is selected. These signals turn OFF when the machine position is separated from the station by more than this value.	0.000 to 99999.999 (° or mm)	0.500
165	near2	Operation parameter group 2 Near set position output width	The signal indicating that the machine position is near any one of the station positions is the near set position (NEAR) signal. Set the tolerable values at which these signals are output when operation parameter group 2 is selected. These values are generally set wider than the set position output width. During operations, this is related to special commands when the station selection is "0".	0.000 to 99999.999 (° or mm)	1.000

13. AUXILIARY AXIS PARAMETER

< Operation parameter group 3 >

No.	Name	Details	Setting range	Default value	
166	Aspeed3	Operation parameter group 3 Automatic operation speed	Set the feedrate during automatic operation when operation parameter group 3 is selected.	1 to 100000 (°/min or mm/min)	5000
167	Mspeed3	Operation parameter group 3 Manual operation speed	Set the feedrate during manual operation or JOG operation when operation parameter group 3 is selected.	1 to 100000 (°/min or mm/min)	2000
168	time3.1	Operation parameter group 3 Acceleration/deceleration time constant 1	Set the linear acceleration/deceleration time for the operation parameter group 1 automatic operation speed (clamp speed) when operation parameter group 3 is selected. When operating at speeds less than the clamp speed, the axis will linearly accelerate/decelerate at the inclination determined above. When this is set together with acceleration/deceleration time constant 2, S-shape acceleration/deceleration is carried out. In this case, set the acceleration/deceleration time of the linear part in this parameter.	1 to 9999 (ms)	100
169	time3.2	Operation parameter group 3 Acceleration/deceleration time constant 2	Set this parameter when carrying out S-shape acceleration/deceleration. When S-shape acceleration/deceleration is carried out, set the total time of the non-linear parts. When 1 is set in this parameter, linear acceleration/deceleration is carried out. In the handle feed operation mode, this set value is regarded as the time constant for the linear acceleration/deceleration.	1 to 9999 (ms)	1

13. AUXILIARY AXIS PARAMETER

No.	Name		Details	Setting range	Default value
170	TL3	Operation parameter group 3 Torque limit value	Set the motor output torque limit value when operation parameter group 3 is selected. At the default value, the torque is limited at the maximum torque of the motor specifications. Set the default value when torque limit is not especially required. In the stopper positioning operation mode, this becomes the pressing torque limit value after completion of the positioning.	1 to 500 (%)	500
171	OD3	Operation parameter group 3 Excessive error detection width	Set the excessive error detection width when operation parameter group 3 is selected. An excessive error alarm (S03 0052) is detected when the position droop becomes larger than this setting value. In the stopper positioning operation mode, this becomes the excessive error detection width during pressing after completion of the positioning.	0 to 32767 (° or mm)	100
172	just3	Operation parameter group 3 Set position output width	The signal indicating that the machine position is at any one of the stations is the set position reached (JST) signal. During automatic operation, the automatic set position reached (JSTA) signal is also output under the same conditions. Set the tolerable values at which these signals are output when operation parameter group 3 is selected. These signals turn OFF when the machine position is separated from the station by more than this value.	0.000 to 99999.999 (° or mm)	0.500
173	near3	Operation parameter group 3 Near set position output width	The signal indicating that the machine position is near any one of the station positions is the near set position (NEAR) signal. Set the tolerable values at which these signals are output when operation parameter group 3 is selected. These values are generally set wider than the set position output width. During operations, this is related to special commands when the station selection is "0".	0.000 to 99999.999 (° or mm)	1.000

13. AUXILIARY AXIS PARAMETER

< Operation parameter group 4 >

No.	Name	Details	Setting range	Default value	
174	Aspeed 4	Operation parameter group 4 Automatic operation speed	Set the feedrate during automatic operation when operation parameter group 4 is selected.	1 to 100000 (°/min or mm/min)	5000
175	Mspeed 4	Operation parameter group 4 Manual operation speed	Set the feedrate during manual operation or JOG operation when operation parameter group 4 is selected.	1 to 100000 (°/min or mm/min)	2000
176	time4.1	Operation parameter group 4 Acceleration/deceleration time constant 1	Set the linear acceleration/deceleration time for the operation parameter group 1 automatic operation speed (clamp speed) when operation parameter group 4 is selected. When operating at speeds less than the clamp speed, the axis will linearly accelerate/decelerate at the inclination determined above. When this is set together with acceleration/deceleration time constant 2, S-shape acceleration/deceleration is carried out. In this case, set the acceleration/deceleration time of the linear part in this parameter.	1 to 9999 (ms)	100
177	time4.2	Operation parameter group 4 Acceleration/deceleration time constant 2	Set this parameter when carrying out S-shape acceleration/deceleration. When S-shape acceleration/deceleration is carried out, set the total time of the non-linear parts. When 1 is set in this parameter, linear acceleration/deceleration is carried out. In the handle feed operation mode, this set value is regarded as the time constant for the linear acceleration/deceleration.	1 to 9999 (ms)	1

13. AUXILIARY AXIS PARAMETER

No.	Name		Details	Setting range	Default value
178	TL4	Operation parameter group 4 Torque limit value	Set the motor output torque limit value when operation parameter group 4 is selected. At the default value, the torque is limited at the maximum torque of the motor specifications. Set the default value when torque limit is not especially required. In the stopper method initializing mode in absolute position detection systems, this becomes the torque limit value during stopper operation.	1 to 500 (%)	500
179	OD4	Operation parameter group 4 Excessive error detection width	Set the excessive error detection width when operation parameter group 4 is selected. An excessive error alarm (S03 0052) is detected when the position droop becomes larger than this setting value. In the stopper method initializing mode in absolute position detection systems, this becomes the excessive error detection width during stopper operation.	0 to 32767 (° or mm)	100
180	just4	Operation parameter group 4 Set position output width	The signal indicating that the machine position is at any one of the stations is the set position reached (JST) signal. During automatic operation, the automatic set position reached (JSTA) signal is also output under the same conditions. Set the tolerable values at which these signals are output when operation parameter group 4 is selected. These signals turn OFF when the machine position is separated from the station by more than this value.	0.000 to 99999.999 (° or mm)	0.500
181	near4	Operation parameter group 4 Near set position output width	The signal indicating that the machine position is near any one of the station positions is the near set position (NEAR) signal. Set the tolerable values at which these signals are output when operation parameter group 4 is selected. These values are generally set wider than the set position output width. During operations, this is related to special commands when the station selection is "0".	0.000 to 99999.999 (° or mm)	1.000

13. AUXILIARY AXIS PARAMETER

No.	Name	Details	Setting range	Default value																																																																																								
190	stpos2	Station 2 coordinate value	-99999.999 to 99999.999 (° or mm)	0.000																																																																																								
191	stpos3	Station 3 coordinate value																																																																																										
192	stpos4	Station 4 coordinate value																																																																																										
193	stpos5	Station 5 coordinate value																																																																																										
194	stpos6	Station 6 coordinate value																																																																																										
195	stpos7	Station 7 coordinate value																																																																																										
196	stpos8	Station 8 coordinate value																																																																																										
197	stpos9	Station 9 coordinate value																																																																																										
200	PSWcheck	PSW detection method	<p>This is a HEX setting parameter. Set bits without a description to their default values.</p> <table border="1"> <thead> <tr> <th>bit</th> <th>F</th> <th>E</th> <th>D</th> <th>C</th> <th>B</th> <th>A</th> <th>9</th> <th>8</th> <th>7</th> <th>6</th> <th>5</th> <th>4</th> <th>3</th> <th>2</th> <th>1</th> <th>0</th> </tr> </thead> <tbody> <tr> <td>Default value</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th>bit</th> <th>Position switch</th> <th>Meaning when "0" is set</th> <th>Meaning when "1" is set</th> </tr> </thead> <tbody> <tr> <td>0</td> <td>PSW1</td> <td rowspan="8">The position switch output is judged by the machine position of the command system.</td> <td rowspan="8">The position switch output is judged by the machine FB position (actual position).</td> </tr> <tr> <td>1</td> <td>PSW2</td> </tr> <tr> <td>2</td> <td>PSW3</td> </tr> <tr> <td>3</td> <td>PSW4</td> </tr> <tr> <td>4</td> <td>PSW5</td> </tr> <tr> <td>5</td> <td>PSW6</td> </tr> <tr> <td>6</td> <td>PSW7</td> </tr> <tr> <td>7</td> <td>PSW8</td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> </tr> <tr> <td>9</td> <td></td> <td></td> <td></td> </tr> <tr> <td>A</td> <td></td> <td></td> <td></td> </tr> <tr> <td>B</td> <td></td> <td></td> <td></td> </tr> <tr> <td>C</td> <td></td> <td></td> <td></td> </tr> <tr> <td>D</td> <td></td> <td></td> <td></td> </tr> <tr> <td>E</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0	Default value	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	bit	Position switch	Meaning when "0" is set	Meaning when "1" is set	0	PSW1	The position switch output is judged by the machine position of the command system.	The position switch output is judged by the machine FB position (actual position).	1	PSW2	2	PSW3	3	PSW4	4	PSW5	5	PSW6	6	PSW7	7	PSW8	8				9				A				B				C				D				E				F			
bit	F	E	D	C	B	A	9	8	7	6	5	4	3	2	1	0																																																																												
Default value	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0																																																																												
bit	Position switch	Meaning when "0" is set	Meaning when "1" is set																																																																																									
0	PSW1	The position switch output is judged by the machine position of the command system.	The position switch output is judged by the machine FB position (actual position).																																																																																									
1	PSW2																																																																																											
2	PSW3																																																																																											
3	PSW4																																																																																											
4	PSW5																																																																																											
5	PSW6																																																																																											
6	PSW7																																																																																											
7	PSW8																																																																																											
8																																																																																												
9																																																																																												
A																																																																																												
B																																																																																												
C																																																																																												
D																																																																																												
E																																																																																												
F																																																																																												

13. AUXILIARY AXIS PARAMETER

No.	Name	Details	Setting range	Default value	
201 202	PSW1dog1 PSW1dog2	PSW1 area setting 1 PSW1 area setting 2	When the machine position is in the region between region settings 1 and 2, the position switch of each No. will turn ON. Whether the value of setting 1 is larger than setting 2 (vice versa) does not affect the position switch operation. For rotation axes, the output turns ON at the region without including 0.000 degree.	-99999.999 to 99999.999 (° or mm)	0.000
203 204	PSW2dog1 PSW2dog2	PSW2 area setting 1 PSW2 area setting 2			
205 206	PSW3dog1 PSW3dog2	PSW3 area setting 1 PSW3 area setting 2			
207 208	PSW4dog1 PSW4dog2	PSW4 area setting 1 PSW4 area setting 2			
209 210	PSW5dog1 PSW5dog2	PSW5 area setting 1 PSW5 area setting 2			
211 212	PSW6dog1 PSW6dog2	PSW6 area setting 1 PSW6 area setting 2			
213 214	PSW7dog1 PSW7dog2	PSW7 area setting 1 PSW7 area setting 2			
215 216	PSW8dog1 PSW8dog2	PSW8 area setting 1 PSW8 area setting 2			
220	push	Stopper amount	Set the command stroke of the stopper operation during stopper positioning operations.	0.000 to 359.999 (° or mm)	0.000
221	pusht1	Stopper standby time	Set the standby time from the stopper starting coordinate positioning to the stopper operation start during stopper positioning operations.	0 to 9999 (ms)	0
222	pusht2	Stopper torque release time	Set the time from the completion of the stopper operation to the changeover of the stopper torque during stopper positioning operations.	0 to 9999 (ms)	0
223	pusht3	Set position signal output delay time	Set the time from the completion of the stopper operation to the output of the automatic set position reached (JSTA), set position reached (JST), and near set position (NEAR) signals during stopper positioning operations.	0 to 9999 (ms)	0

III PLC DEVICES

1. PLC INTERFACE INPUT X

The spindle related devices are described in the section "5. Other PLC Interfaces".

CNC → PLC (GX Developer)

Table 4-1-1 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X180	X4C0	RDY1	Servo ready 1st axis	X188	X4C8	AX1	Axis selected 1st axis
X181	X4C1	RDY2	Servo ready 2nd axis	X189	X4C9	AX2	Axis selected 2nd axis
X182	X4C2	RDY3	Servo ready 3rd axis	X18A	X4CA	AX3	Axis selected 3rd axis
X183	X4C3	RDY4	Servo ready 4th axis	X18B	X4CB	AX4	Axis selected 4th axis
X184	X4C4	RDY5	Servo ready 5th axis	X18C	X4CC	AX5	Axis selected 5th axis
X185	X4C5	RDY6	Servo ready 6th axis	X18D	X4CD	AX6	Axis selected 6th axis
X186	X4C6	RDY7	Servo ready 7th axis	X18E	X4CE	AX7	Axis selected 7th axis
X187	X4C7	RDY8	Servo ready 8th axis	X18F	X4CF	AX8	Axis selected 8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X190	X4D0	MVP1	In plus motion +1st axis	X198	X4D8	MVM1	In minus motion -1st axis
X191	X4D1	MVP2	In plus motion +2nd axis	X199	X4D9	MVM2	In minus motion -2nd axis
X192	X4D2	MVP3	In plus motion +3rd axis	X19A	X4DA	MVM3	In minus motion -3rd axis
X193	X4D3	MVP4	In plus motion +4th axis	X19B	X4DB	MVM4	In minus motion -4th axis
X194	X4D4	MVP5	In plus motion +5th axis	X19C	X4DC	MVM5	In minus motion -5th axis
X195	X4D5	MVP6	In plus motion +6th axis	X19D	X4DD	MVM6	In minus motion -6th axis
X196	X4D6	MVP7	In plus motion +7th axis	X19E	X4DE	MVM7	In minus motion -7th axis
X197	X4D7	MVP8	In plus motion +8th axis	X19F	X4DF	MVM8	In minus motion -8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X1A0	X4E0	ZP11	1st reference position reached 1st axis	X1A8	X4E8	ZP21	2nd reference position reached 1st axis
X1A1	X4E1	ZP12	2nd axis	X1A9	X4E9	ZP22	2nd axis
X1A2	X4E2	ZP13	3rd axis	X1AA	X4EA	ZP23	3rd axis
X1A3	X4E3	ZP14	4th axis	X1AB	X4EB	ZP24	4th axis
X1A4	X4E4	ZP15	5th axis	X1AC	X4EC	ZP25	5th axis
X1A5	X4E5	ZP16	6th axis	X1AD	X4ED	ZP26	6th axis
X1A6	X4E6	ZP17	7th axis	X1AE	X4EE	ZP27	7th axis
X1A7	X4E7	ZP18	8th axis	X1AF	X4EF	ZP28	8th axis

1. PLC INTERFACE INPUT X

CNC → PLC (GX Developer)

Table 4-1-2 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X1B0	X4F0	ZP31	3rd reference position reached 1st axis	X1B8	X4F8	ZP41	4th reference position reached 1st axis
X1B1	X4F1	ZP32	2nd axis	X1B9	X4F9	ZP42	2nd axis
X1B2	X4F2	ZP33	3rd axis	X1BA	X4FA	ZP43	3rd axis
X1B3	X4F3	ZP34	4th axis	X1BB	X4FB	ZP44	4th axis
X1B4	X4F4	ZP35	5th axis	X1BC	X4FC	ZP45	5th axis
X1B5	X4F5	ZP36	6th axis	X1BD	X4FD	ZP46	6th axis
X1B6	X4F6	ZP37	7th axis	X1BE	X4FE	ZP47	7th axis
X1B7	X4F7	ZP38	8th axis	X1BF	X4FF	ZP48	8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X1C0	X500			X1C8	X508		— —
X1C1	X501			X1C9	X509		— —
X1C2	X502	SSE	Search & start (error)	X1CA	X50A		— —
X1C3	X503		Search & start (search)	X1CB	X50B		— —
X1C4	X504		Power OFF request (SP regeneration circuit err)	X1CC	X50C		— —
X1C5	X505			X1CD	X50D		— —
X1C6	X506			X1CE	X50E		— —
X1C7	X507			X1CF	X50F		— —

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st SP	2nd SP			1st sys	2nd sys		
X1D0	X510		— —	X1D8	X518	NR F1	Near reference position 1st axis
X1D1	X511		— —	X1D9	X519	NR F2	2nd axis
X1D2	X512			X1DA	X51A	NR F3	3rd axis
X1D3	X513			X1DB	X51B	NR F4	4th axis
X1D4	X514			X1DC	X51C	NR F5	5th axis
X1D5	X515	SD2	Speed detect 2	X1DD	X51D	NR F6	6th axis
X1D6	X516	MCSA	In M coil selected	X1DE	X51E	NR F7	7th axis
X1D7	X517		Index positioning complete	X1DF	X51F	NR F8	8th axis

— — : Reserved for the system.

1. PLC INTERFACE INPUT X

CNC → PLC (GX Developer)

Table 4-1-3 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X1E0	X520	JO	In jog mode	X1E8	X528	MEMO	In memory mode
X1E1	X521	HO	In handle mode	X1E9	X529	TO	In tape mode
X1E2	X522	SO	In incremental mode	X1EA	X52A		— —
X1E3	X523	PTPO	In manual random feed mode	X1EB	X52B	DO	In MDI mode
X1E4	X524	ZRNO	In reference position return mode	X1EC	X52C		— —
X1E5	X525	ASTO	In automatic initial set mode	X1ED	X52D		In direct operation ▲
X1E6	X526		In JOG-handle simultaneous mode	X1EE	X52E		
X1E7	X527			X1EF	X52F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X1F0	X530	MA	Controller ready complete	X1F8	X538	DEN	Motion command complete
X1F1	X531	SA	Servo ready complete	X1F9	X539	TIMP	All axes in-position
X1F2	X532	OP	In auto operation "run"	X1FA	X53A	TSMZ	All axes smoothing zero
X1F3	X533	STL	In auto operation "start"	X1FB	X53B		— —
X1F4	X534	SPL	In auto operation "pause"	X1FC	X53C	CXFIN	Manual random feed complete
X1F5	X535	RST	In "reset"	X1FD	X53D		
X1F6	X536	CXN	In manual random feed	X1FE	X53E		
X1F7	X537	RWD	In rewind	X1FF	X53F		In high-speed mode (G05)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X200	X540	RPN	In rapid traverse	X208	X548	INCH	In inch unit select
X201	X541	CUT	In cutting feed	X209	X549	DLKN	In display lock
X202	X542	TAP	In tapping	X20A	X54A	F1DN	F1-digit commanded
X203	X543	THRD	In thread cutting	X20B	X54B	TLFO	In tool life management
X204	X544	SYN	In synchronous feed	X20C	X54C	SUPP	Spindle speed upper limit over
X205	X545	CSS	In constant surface speed	X20D	X54D	SLOW	Spindle speed lower limit over
X206	X546	SKIP	In skip	X20E	X54E	TLOV	Tool life over
X207	X547	ZRNN	In reference position return	X20F	X54F	BATAL	Battery alarm

— — : Reserved for the system.

▲ : For specific manufacturers.

1. PLC INTERFACE INPUT X

CNC → PLC (GX Developer)

Table 4-1-4 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X210	X550	AL1	NC alarm 1	X218	X558	F11	F1-digit No.1
X211	X551	AL2	NC alarm 2 (Servo alarm)	X219	X559	F12	F1-digit No.2
X212	X552	AL3	NC alarm 3 (Program error)	X21A	X55A	F14	F1-digit No.4
X213	X553	AL4	NC alarm 4 (Operation error)	X21B	X55B	—	(Always "0")
X214	X554	SIGE	S-analog gear No. illegal	X21C	X55C		Waiting between part systems
X215	X555	SOVE	S-analog max./min. command value over	X21D	X55D		
X216	X556	SNGE	S-analog no gear selected	X21E	X55E		
X217	X557	ASLE	Illegal axis selected	X21F	X55F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X220	X560	DM00	M code independent output M00	X228	X568		(EF)
X221	X561	DM01	M01	X229	X569	MMS	Manual numerical command
X222	X562	DM02	M02	X22A	X56A		— —
X223	X563	DM30	M30	X22B	X56B	TCP	Tool change position return complete
X224	X564			X22C	X56C	TCRQ	New tool change
X225	X565	GR1	Spindle gear shift 1	X22D	X56D		— —
X226	X566	GR2	Spindle gear shift 2	X22E	X56E		
X227	X567	—	(Always "0")	X22F	X56F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X230	X570	MF1	M function strobe 1	X238	X578	TF1	T function strobe 1
X231	X571	MF2	M function strobe 2	X239	X579	—	— —
X232	X572	MF3	M function strobe 3	X23A	X57A	—	— —
X233	X573	MF4	M function strobe 4	X23B	X57B	—	— —
X234	X574	SF1	S function strobe 1	X23C	X57C	BF1	2nd M function strobe 1
X235	X575	SF2	S function strobe 2	X23D	X57D	—	— —
X236	X576	SF3	S function strobe 3	X23E	X57E	—	— —
X237	X577	SF4	S function strobe 4	X23F	X57F	—	— —

— — : Reserved for the system.

1. PLC INTERFACE INPUT X

CNC → PLC (GX Developer)

Table 4-1-5 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st SP	2nd SP			1st SP	2nd SP		
X240	X580		Spindle 2nd in-position	X248	X588	SMA	Spindle ready-ON
X241	X581	CDO	Current detect	X249	X589	SSA	Spindle servo-ON
X242	X582	VRO	Speed detect	X24A	X58A	SEMG	Spindle emergency stop
X243	X583	FLO	In spindle alarm	X24B	X58B	SSRN	Spindle forward run
X244	X584	ZSO	Zero speed	X24C	X58C	SSRI	Spindle reverse run
X245	X585	USO	Up-to-speed	X24D	X58D	SZPH	Z-phase passed
X246	X586	ORAO	Spindle in-position	X24E	X58E	SIMP	Position loop in-position
X247	X587	LCSA	In L coil selected	X24F	X58F	STLQ	Torque limit

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X250	X590		— —	X258	X598		— —
X251	X591		— —	X259	X599		— —
X252	X592		— —	X25A	X59A		— —
X253	X593		— —	X25B	X59B		— —
X254	X594		— —	X25C	X59C		— —
X255	X595		— —	X25D	X59D		— —
X256	X596		— —	X25E	X59E		— —
X257	X597		— —	X25F	X59F		— —

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X260	X5A0	CHOP	In chopping start	X268	X5A8		Load monitor In teaching/monitor execution ▲
X261	X5A1	CHP1	Basic position - upper dead center point	X269	X5A9		Teaching mode valid ▲
X262	X5A2	CHP2	Upper dead center point - bottom dead point	X26A	X5AA		Monitor mode valid ▲
X263	X5A3	CHP3	Bottom dead center point - upper dead point	X26B	X5AB		Adaptive control valid ▲
X264	X5A4	CHP4	Upper dead center point - basic position	X26C	X5AC		
X265	X5A5	CHPMD	In chopping mode	X26D	X5AD	TRVE	Tap retract possible
X266	X5A6			X26E	X5AE	PCNT	No. of work machining over
X267	X5A7			X26F	X5AF	ABSW	Absolute position warning

— — : Reserved for the system.

▲ : For specific manufacturers.

1. PLC INTERFACE INPUT X

CNC → PLC (GX Developer)

Table 4-1-6 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X270	X5B0	PSW1	Position switch 1	X278	X5B8		— —
X271	X5B1	PSW2	Position switch 2	X279	X5B9		— —
X272	X5B2	PSW3	Position switch 3	X27A	X5BA		— —
X273	X5B3	PSW4	Position switch 4	X27B	X5BB		— —
X274	X5B4	PSW5	Position switch 5	X27C	X5BC		— —
X275	X5B5	PSW6	Position switch 6	X27D	X5BD		— —
X276	X5B6	PSW7	Position switch 7	X27E	X5BE		— —
X277	X5B7	PSW8	Position switch 8	X27F	X5BF		— —

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X280	X5C0	ZSF1	Zero point initialization set completed 1st axis	X288	X5C8	ZSE1	Zero point initialization set error completed 1st axis
X281	X5C1	ZSF2	2nd axis	X289	X5C9	ZSE2	2nd axis
X282	X5C2	ZSF3	3rd axis	X28A	X5CA	ZSE3	3rd axis
X283	X5C3	ZSF4	4th axis	X28B	X5CB	ZSE4	4th axis
X284	X5C4	ZSF5	5th axis	X28C	X5CC	ZSE5	5th axis
X285	X5C5	ZSF6	6th axis	X28D	X5CD	ZSE6	6th axis
X286	X5C6	ZSF7	7th axis	X28E	X5CE	ZSE7	7th axis
X287	X5C7	ZSF8	8th axis	X28F	X5CF	ZSE8	8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X290	X5D0	ILI1	In current limit 1st axis	X298	X5D8	ILA1	Current limit reached 1st axis
X291	X5D1	ILI2	2nd axis	X299	X5D9	ILA2	2nd axis
X292	X5D2	ILI3	3rd axis	X29A	X5DA	ILA3	3rd axis
X293	X5D3	ILI4	4th axis	X29B	X5DB	ILA4	4th axis
X294	X5D4	ILI5	5th axis	X29C	X5DC	ILA5	5th axis
X295	X5D5	ILI6	6th axis	X29D	X5DD	ILA6	6th axis
X296	X5D6	ILI7	7th axis	X29E	X5DE	ILA7	7th axis
X297	X5D7	ILI8	8th axis	X29F	X5DF	ILA8	8th axis

— — : Reserved for the system.

1. PLC INTERFACE INPUT X

CNC → PLC (GX Developer)

Table 4-1-7 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X2A0	X5E0		In polygon mode (Spindle-NC axis)	X2A8	X5E8		
X2A1	X5E1	AL5	NC alarm 5	X2A9	X5E9		
X2A2	X5E2		In polygon mode (Spindle-Spindle)	X2AA	X5EA		
X2A3	X5E3		Spindle-spindle polygon synchronization complete	X2AB	X5EB		
X2A4	X5E4			X2AC	X5EC		
X2A5	X5E5			X2AD	X5ED		
X2A6	X5E6			X2AE	X5EE		
X2A7	X5E7			X2AF	X5EF		For HVS control (position err detect) ▲

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X2B0	X5F0		Up-to-speed 1st axis	X2B8	X5F8		Unclamp command 1st axis
X2B1	X5F1		2nd axis	X2B9	X5F9		2nd axis
X2B2	X5F2		3rd axis	X2BA	X5FA		3rd axis
X2B3	X5F3		4th axis	X2BB	X5FB		4th axis
X2B4	X5F4		5th axis	X2BC	X5FC		5th axis
X2B5	X5F5		6th axis	X2BD	X5FD		6th axis
X2B6	X5F6		7th axis	X2BE	X5FE		7th axis
X2B7	X5F7		8th axis	X2BF	X5FF		8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X2C0	X600	RTAP	In synchronized tapping selection (M command)	X2C8	X608	ENB	Spindle enable
X2C1	X601		In small diameter deep hole cycle	X2C9	X609		
X2C2	X602		INC high-speed retract function valid state ▲	X2CA	X60A		
X2C3	X603		In INC high-speed retract function operation ▲	X2CB	X60B		
X2C4	X604		Optimum pecking function valid state ▲	X2CC	X60C		
X2C5	X605		In optimum pecking function operation ▲	X2CD	X60D		
X2C6	X606		Load monitor function valid state ▲	X2CE	X60E		
X2C7	X607		In load monitor function operation ▲	X2CF	X60F		

▲ : For specific manufacturers.

1. PLC INTERFACE INPUT X

CNC → PLC (GX Developer)

Table 4-1-8 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X2D0	X610		In barrier valid (left)	X2D8	X618		
X2D1	X611		In barrier valid (right)	X2D9	X619		
X2D2	X612			X2DA	X61A		
X2D3	X613			X2DB	X61B		
X2D4	X614			X2DC	X61C		
X2D5	X615			X2DD	X61D		
X2D6	X616			X2DE	X61E		
X2D7	X617			X2DF	X61F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X2E0	X620		In cross machining control 1st axis	X2E8	X628		In synchronous/ superimposition control 1st axis
X2E1	X621		2nd axis	X2E9	X629		2nd axis
X2E2	X622		3rd axis	X2EA	X62A		3rd axis
X2E3	X623		4th axis	X2EB	X62B		4th axis
X2E4	X624		5th axis	X2EC	X62C		5th axis
X2E5	X625		6th axis	X2ED	X62D		6th axis
X2E6	X626		7th axis	X2EE	X62E		7th axis
X2E7	X627		8th axis	X2EF	X62F		8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X2F0	X630			X2F8	X638		
X2F1	X631			X2F9	X639		
X2F2	X632			X2FA	X63A		
X2F3	X633			X2FB	X63B		
X2F4	X634			X2FC	X63C		
X2F5	X635			X2FD	X63D		
X2F6	X636			X2FE	X63E		
X2F7	X637			X2FF	X63F		

1. PLC INTERFACE INPUT X

CNC → PLC (GX Developer)

Table 4-1-9 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X300	X9C0	DROPNS	Door open enable	X308	—	SPSYN1	In spindle synchronous control
X301	X9C1			X309	—	FSPRV	Spindle rotation speed synchronization complete
X302	—		MELDASNET diagnosis output complete	X30A	—	FSPPH	Spindle phase synchronization complete
X303	X9C3	NETSMP	MELDASNET in sampling	X30B	—	SPSYN2	In spindle synchronous control 2 (D)
X304	—	RPIN	In remote program input	X30C	—		— —
X305	—	RPFIN	Remote program input complete	X30D	—		— —
X306	—	RPERR	Remote program input error	X30E	—	SPCMP	Chuck close confirmation
X307	—		In tool ID communication ▲	X30F	—		Power OFF required after parameter change

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st SP	2nd SP		
X310	—		— —	X318	X9D8		In magnetic bearing ready ON
X311	—		— —	X319	X9D9		In magnetic bearing servo ON
X312	—		— —	X31A	X9DA		— —
X313	—		— —	X31B	X9DB		— —
X314	—		— —	X31C	X9DC		In magnetic bearing warning
X315	—		— —	X31D	X9DD		— —
X316	—		— —	X31E	X9DE		— —
X317	—		— —	X31F	X9DF		In magnetic bearing alarm

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X320	—		Door open enable 1-2	X328	X9E8		
X321	—		— —	X329	X9E9		
X322	X9E2			X32A	X9EA		
X323	X9E3			X32B	X9EB		
X324	X9E4			X32C	X9EC		
X325	X9E5			X32D	X9ED		
X326	X9E6			X32E	X9EE		
X327	X9E7			X32F	X9EF		

— — : Reserved for the system.

▲ : For specific manufacturers.

1. PLC INTERFACE INPUT X

CNC → PLC (GX Developer)

Table 4-1-10 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X330	X9F0			X338	X9F8		
X331	X9F1			X339	X9F9		
X332	X9F2			X33A	X9FA		
X333	X9F3			X33B	X9FB		
X334	X9F4			X33C	X9FC		
X335	X9F5			X33D	X9FD		
X336	X9F6			X33E	X9FE		
X337	X9F7			X33F	X9FF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X340	XA00			X348	XA08		
X341	XA01			X349	XA09		
X342	XA02			X34A	XA0A		
X343	XA03			X34B	XA0B		
X344	XA04			X34C	XA0C		
X345	XA05			X34D	XA0D		
X346	XA06			X34E	XA0E		
X347	XA07			X34F	XA0F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X350	XA10			X358	XA18		
X351	XA11			X359	XA19		
X352	XA12			X35A	XA1A		
X353	XA13			X35B	XA1B		
X354	XA14			X35C	XA1C		
X355	XA15			X35D	XA1D		
X356	XA16			X35E	XA1E		
X357	XA17			X35F	XA1F		

1. PLC INTERFACE INPUT X

CNC → PLC (GX Developer)

Table 4-1-11 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X360	XA20			X368	XA28		
X361	XA21			X369	XA29		
X362	XA22			X36A	XA2A		
X363	XA23			X36B	XA2B		
X364	XA24			X36C	XA2C		
X365	XA25			X36D	XA2D		
X366	XA26			X36E	XA2E		
X367	XA27			X36F	XA2F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X370	XA30			X378	XA38		
X371	XA31			X379	XA39		
X372	XA32			X37A	XA3A		
X373	XA33			X37B	XA3B		
X374	XA34			X37C	XA3C		
X375	XA35			X37D	XA3D		
X376	XA36			X37E	XA3E		
X377	XA37			X37F	XA3F		

1. PLC INTERFACE INPUT X

CNC → PLC (GX Developer)

Table 4-1-12 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
X940	X950	ENB	Spindle enable	X948	X958		
X941	X951			X949	X959		
X942	X952			X94A	X95A		
X943	X953			X94B	X95B		
X944	X954			X94C	X95C		
X945	X955			X94D	X95D		
X946	X956			X94E	X95E		
X947	X957			X94F	X95F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
XA40	XA60	SUPP	Spindle speed upper limit over	XA48	XA68		— —
XA41	XA61	SLOW	Spindle speed lower limit over	XA49	XA69		— —
XA42	XA62	SIGE	S-analog gear No. illegal	XA4A	XA6A		
XA43	XA63	SOVE	S-analog max./min. command value over	XA4B	XA6B		
XA44	XA64	SNGE	S-analog no gear selected	XA4C	XA6C		
XA45	XA65	GR1	Spindle gear shift command 1	XA4D	XA6D	SD2	Speed detect 2
XA46	XA66	GR2	Spindle gear shift command 2	XA4E	XA6E	MCSA	In M coil selected
XA47	XA67	—	(Always "0")	XA4F	XA6F		Index positioning complete

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
XA50	XA70		2nd in-position (D)	XA58	XA78	SMA	Spindle ready-ON
XA51	XA71	CDO	Current detect	XA59	XA79	SSA	Spindle servo-ON
XA52	XA72	VRO	Speed detect	XA5A	XA7A	SEMG	Spindle emergency stop
XA53	XA73	FLO	In spindle alarm	XA5B	XA7B	SSRN	Spindle forward run
XA54	XA74	ZSO	Zero speed	XA5C	XA7C	SSRI	Spindle reverse run
XA55	XA75	USO	Up-to-speed	XA5D	XA7D		Z-phase passed
XA56	XA76	ORAO	Spindle in-position	XA5E	XA7E	SIMP	Position loop in-position
XA57	XA77	LCSA	In L coil selected	XA5F	XA7F	STLQ	Torque limit

— — : Reserved for the system.

1. PLC INTERFACE INPUT X

CNC → PLC (PLC4B)

Table 4-1-1 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X180	U0	RDY1	Servo ready 1st axis	X188	U8	AX1	Axis selected 1st axis
X181	U1	RDY2	Servo ready 2nd axis	X189	U9	AX2	Axis selected 2nd axis
X182	U2	RDY3	Servo ready 3rd axis	X18A	UA	AX3	Axis selected 3rd axis
X183	U3	RDY4	Servo ready 4th axis	X18B	UB	AX4	Axis selected 4th axis
X184	U4	RDY5	Servo ready 5th axis	X18C	UC	AX5	Axis selected 5th axis
X185	U5	RDY6	Servo ready 6th axis	X18D	UD	AX6	Axis selected 6th axis
X186	U6	RDY7	Servo ready 7th axis	X18E	UE	AX7	Axis selected 7th axis
X187	U7	RDY8	Servo ready 8th axis	X18F	UF	AX8	Axis selected 8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X190	U10	MVP1	In plus motion +1st axis	X198	U18	MVM1	In minus motion -1st axis
X191	U11	MVP2	In plus motion +2nd axis	X199	U19	MVM2	In minus motion -2nd axis
X192	U12	MVP3	In plus motion +3rd axis	X19A	U1A	MVM3	In minus motion -3rd axis
X193	U13	MVP4	In plus motion +4th axis	X19B	U1B	MVM4	In minus motion -4th axis
X194	U14	MVP5	In plus motion +5th axis	X19C	U1C	MVM5	In minus motion -5th axis
X195	U15	MVP6	In plus motion +6th axis	X19D	U1D	MVM6	In minus motion -6th axis
X196	U16	MVP7	In plus motion +7th axis	X19E	U1E	MVM7	In minus motion -7th axis
X197	U17	MVP8	In plus motion +8th axis	X19F	U1F	MVM8	In minus motion -8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X1A0	U20	ZP11	1st reference position reached 1st axis	X1A8	U28	ZP21	2nd reference position reached 1st axis
X1A1	U21	ZP12	2nd axis	X1A9	U29	ZP22	2nd axis
X1A2	U22	ZP13	3rd axis	X1AA	U2A	ZP23	3rd axis
X1A3	U23	ZP14	4th axis	X1AB	U2B	ZP24	4th axis
X1A4	U24	ZP15	5th axis	X1AC	U2C	ZP25	5th axis
X1A5	U25	ZP16	6th axis	X1AD	U2D	ZP26	6th axis
X1A6	U26	ZP17	7th axis	X1AE	U2E	ZP27	7th axis
X1A7	U27	ZP18	8th axis	X1AF	U2F	ZP28	8th axis

1. PLC INTERFACE INPUT X

CNC → PLC (PLC4B)

Table 4-1-2 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X1B0	U30	ZP31	3rd reference position reached 1st axis	X1B8	U38	ZP41	4th reference position reached 1st axis
X1B1	U31	ZP32	2nd axis	X1B9	U39	ZP42	2nd axis
X1B2	U32	ZP33	3rd axis	X1BA	U3A	ZP43	3rd axis
X1B3	U33	ZP34	4th axis	X1BB	U3B	ZP44	4th axis
X1B4	U34	ZP35	5th axis	X1BC	U3C	ZP45	5th axis
X1B5	U35	ZP36	6th axis	X1BD	U3D	ZP46	6th axis
X1B6	U36	ZP37	7th axis	X1BE	U3E	ZP47	7th axis
X1B7	U37	ZP38	8th axis	X1BF	U3F	ZP48	8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X1C0	U40			X1C8	U48		— —
X1C1	U41			X1C9	U49		— —
X1C2	U42	SSE	Search & start (error)	X1CA	U4A		— —
X1C3	U43		Search & start (search)	X1CB	U4B		— —
X1C4	U44		Power OFF request (SP regeneration circuit err)	X1CC	U4C		— —
X1C5	U45			X1CD	U4D		— —
X1C6	U46			X1CE	U4E		— —
X1C7	U47			X1CF	U4F		— —

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st SP	2nd SP			1st sys	2nd sys		
X1D0	U50		— —	X1D8	U58	NR F1	Near reference position 1st axis
X1D1	U51		— —	X1D9	U59	NR F2	2nd axis
X1D2	U52			X1DA	U5A	NR F3	3rd axis
X1D3	U53			X1DB	U5B	NR F4	4th axis
X1D4	U54			X1DC	U5C	NR F5	5th axis
X1D5	U55	SD2	Speed detect 2	X1DD	U5D	NR F6	6th axis
X1D6	U56	MCSA	In M coil selected	X1DE	U5E	NR F7	7th axis
X1D7	U57		Index positioning complete	X1DF	U5F	NR F8	8th axis

— — : Reserved for the system.

1. PLC INTERFACE INPUT X

CNC → PLC (PLC4B)

Table 4-1-3 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X1E0	U60	JO	In jog mode	X1E8	U68	MEMO	In memory mode
X1E1	U61	HO	In handle mode	X1E9	U69	TO	In tape mode
X1E2	U62	SO	In incremental mode	X1EA	U6A		— —
X1E3	U63	PTPO	In manual random feed mode	X1EB	U6B	DO	In MDI mode
X1E4	U64	ZRNO	In reference position return mode	X1EC	U6C		— —
X1E5	U65	ASTO	In automatic initial set mode	X1ED	U6D		In direct operation ▲
X1E6	U66		In JOG-handle simultaneous mode	X1EE	U6E		
X1E7	U67			X1EF	U6F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X1F0	U70	MA	Controller ready complete	X1F8	U78	DEN	Motion command complete
X1F1	U71	SA	Servo ready complete	X1F9	U79	TIMP	All axes in-position
X1F2	U72	OP	In auto operation "run"	X1FA	U7A	TSMZ	All axes smoothing zero
X1F3	U73	STL	In auto operation "start"	X1FB	U7B		— —
X1F4	U74	SPL	In auto operation "pause"	X1FC	U7C	CXFIN	Manual random feed complete
X1F5	U75	RST	In "reset"	X1FD	U7D		
X1F6	U76	CXN	In manual random feed	X1FE	U7E		
X1F7	U77	RWD	In rewind	X1FF	U7F		In high-speed mode (G05)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X200	U80	RPN	In rapid traverse	X208	U88	INCH	In inch unit select
X201	U81	CUT	In cutting feed	X209	U89	DLKN	In display lock
X202	U82	TAP	In tapping	X20A	U8A	F1DN	F1-digit commanded
X203	U83	THRD	In thread cutting	X20B	U8B	TLFO	In tool life management
X204	U84	SYN	In synchronous feed	X20C	U8C	SUPP	Spindle speed upper limit over
X205	U85	CSS	In constant surface speed	X20D	U8D	SLOW	Spindle speed lower limit over
X206	U86	SKIP	In skip	X20E	U8E	TLOV	Tool life over
X207	U87	ZRNN	In reference position return	X20F	U8F	BATAL	Battery alarm

— — : Reserved for the system.

▲ : For specific manufacturers.

1. PLC INTERFACE INPUT X

CNC → PLC (PLC4B)

Table 4-1-4 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X210	U90	AL1	NC alarm 1	X218	U98	F11	F1-digit No.1
X211	U91	AL2	NC alarm 2 (Servo alarm)	X219	U99	F12	F1-digit No.2
X212	U92	AL3	NC alarm 3 (Program error)	X21A	U9A	F14	F1-digit No.4
X213	U93	AL4	NC alarm 4 (Operation error)	X21B	U9B	—	(Always "0")
X214	U94	SIGE	S-analog gear No. illegal	X21C	U9C		Waiting between part systems
X215	U95	SOVE	S-analog max./min. command value over	X21D	U9D		
X216	U96	SNGE	S-analog no gear selected	X21E	U9E		
X217	U97	ASLE	Illegal axis selected	X21F	U9F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X220	UA0	DM00	M code independent output M00	X228	UA8		(EF)
X221	UA1	DM01	M01	X229	UA9	MMS	Manual numerical command
X222	UA2	DM02	M02	X22A	UA		— —
X223	UA3	DM30	M30	X22B	UAB	TCP	Tool change position return complete
X224	UA4			X22C	UAC	TCRQ	New tool change
X225	UA5	GR1	Spindle gear shift 1	X22D	UAD		— —
X226	UA6	GR2	Spindle gear shift 2	X22E	UAE		
X227	UA7	—	(Always "0")	X22F	UAF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X230	UB0	MF1	M function strobe 1	X238	UB8	TF1	T function strobe 1
X231	UB1	MF2	M function strobe 2	X239	UB9	—	— —
X232	UB2	MF3	M function strobe 3	X23A	UBA	—	— —
X233	UB3	MF4	M function strobe 4	X23B	UBB	—	— —
X234	UB4	SF1	S function strobe 1	X23C	UBC	BF1	2nd M function strobe 1
X235	UB5	SF2	S function strobe 2	X23D	UBD	—	— —
X236	UB6	SF3	S function strobe 3	X23E	UBE	—	— —
X237	UB7	SF4	S function strobe 4	X23F	UBF	—	— —

— — : Reserved for the system.

1. PLC INTERFACE INPUT X

CNC → PLC (PLC4B)

Table 4-1-5 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st SP	2nd SP			1st SP	2nd SP		
X240	UC0		Spindle 2nd in-position	X248	UC8	SMA	Spindle ready-ON
X241	UC1	CDO	Current detect	X249	UC9	SSA	Spindle servo-ON
X242	UC2	VRO	Speed detect	X24A	UCA	SEMG	Spindle emergency stop
X243	UC3	FLO	In spindle alarm	X24B	UCB	SSRN	Spindle forward run
X244	UC4	ZSO	Zero speed	X24C	UCC	SSRI	Spindle reverse run
X245	UC5	USO	Up-to-speed	X24D	UCD	SZPH	Z-phase passed
X246	UC6	ORAO	Spindle in-position	X24E	UCE	SIMP	Position loop in-position
X247	UC7	LCSA	In L coil selected	X24F	UCF	STLQ	Torque limit

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X250	UD0		— —	X258	UD8		— —
X251	UD1		— —	X259	UD9		— —
X252	UD2		— —	X25A	UDA		— —
X253	UD3		— —	X25B	UDB		— —
X254	UD4		— —	X25C	UDC		— —
X255	UD5		— —	X25D	UDD		— —
X256	UD6		— —	X25E	UDE		— —
X257	UD7		— —	X25F	UDF		— —

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X260	UE0	CHOP	In chopping start	X268	UE8		Load monitor In teaching/monitor execution output ▲
X261	UE1	CHP1	Basic position - upper dead center point	X269	UE9		Teaching mode valid ▲
X262	UE2	CHP2	Upper dead center point - bottom point	X26A	UEA		Monitor mode valid ▲
X263	UE3	CHP3	Bottom dead center point - upper point	X26B	UEB		Adaptive control valid ▲
X264	UE4	CHP4	Upper dead center point - basic position	X26C	UEC		
X265	UE5	CHPMD	In chopping mode	X26D	UED	TRVE	Tap retract possible
X266	UE6			X26E	UEE	PCNT	No. of work machining over
X267	UE7			X26F	UEF	ABSW	Absolute position warning

— — : Reserved for the system.

▲ : For specific manufacturers.

1. PLC INTERFACE INPUT X

CNC → PLC (PLC4B)

Table 4-1-6 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X270	UF0	PSW1	Position switch 1	X278	UF8		— —
X271	UF1	PSW2	Position switch 2	X279	UF9		— —
X272	UF2	PSW3	Position switch 3	X27A	UFA		— —
X273	UF3	PSW4	Position switch 4	X27B	UFB		— —
X274	UF4	PSW5	Position switch 5	X27C	UFC		— —
X275	UF5	PSW6	Position switch 6	X27D	UFD		— —
X276	UF6	PSW7	Position switch 7	X27E	UFE		— —
X277	UF7	PSW8	Position switch 8	X27F	UFF		— —

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X280	U100	ZSF1	Zero point initialization set completed 1st axis	X288	U108	ZSE1	Zero point initialization set error completed 1st axis
X281	U101	ZSF2	2nd axis	X289	U109	ZSE2	2nd axis
X282	U102	ZSF3	3rd axis	X28A	U10A	ZSE3	3rd axis
X283	U103	ZSF4	4th axis	X28B	U10B	ZSE4	4th axis
X284	U104	ZSF5	5th axis	X28C	U10C	ZSE5	5th axis
X285	U105	ZSF6	6th axis	X28D	U10D	ZSE6	6th axis
X286	U106	ZSF7	7th axis	X28E	U10E	ZSE7	7th axis
X287	U107	ZSF8	8th axis	X28F	U10F	ZSE8	8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X290	U110	ILI1	In current limit 1st axis	X298	U118	ILA1	Current limit reached 1st axis
X291	U111	ILI2	2nd axis	X299	U119	ILA2	2nd axis
X292	U112	ILI3	3rd axis	X29A	U11A	ILA3	3rd axis
X293	U113	ILI4	4th axis	X29B	U11B	ILA4	4th axis
X294	U114	ILI5	5th axis	X29C	U11C	ILA5	5th axis
X295	U115	ILI6	6th axis	X29D	U11D	ILA6	6th axis
X296	U116	ILI7	7th axis	X29E	U11E	ILA7	7th axis
X297	U117	ILI8	8th axis	X29F	U11F	ILA8	8th axis

— — : Reserved for the system.

1. PLC INTERFACE INPUT X

CNC → PLC (PLC4B)

Table 4-1-7 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X2A0	U120		In polygon mode (Spindle-NC axis)	X2A8	U128		
X2A1	U121	AL5	NC alarm 5	X2A9	U129		
X2A2	U122		In polygon mode (Spindle-Spindle)	X2AA	U12A		
X2A3	U123		Spindle-spindle polygon synchronization complete	X2AB	U12B		
X2A4	U124			X2AC	U12C		
X2A5	U125			X2AD	U12D		
X2A6	U126			X2AE	U12E		
X2A7	U127			X2AF	U12F		For HVS control (position err detect) ▲

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X2B0	U130		Up-to-speed 1st axis	X2B8	U138		Unclamp command 1st axis
X2B1	U131		2nd axis	X2B9	U139		2nd axis
X2B2	U132		3rd axis	X2BA	U13A		3rd axis
X2B3	U133		4th axis	X2BB	U13B		4th axis
X2B4	U134		5th axis	X2BC	U13C		5th axis
X2B5	U135		6th axis	X2BD	U13D		6th axis
X2B6	U136		7th axis	X2BE	U13E		7th axis
X2B7	U137		8th axis	X2BF	U13F		8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X2C0	U140	RTAP	In synchronized tapping selection (M command)	X2C8	U148	ENB	Spindle enable
X2C1	U141		In small diameter deep hole cycle	X2C9	U149		
X2C2	U142		INC high-speed retract function valid state ▲	X2CA	U14A		
X2C3	U143		In INC high-speed retract function operation ▲	X2CB	U14B		
X2C4	U144		Optimum pecking function valid state ▲	X2CC	U14C		
X2C5	U145		In optimum pecking function operation ▲	X2CD	U14D		
X2C6	U146		Load monitor function valid state ▲	X2CE	U14E		
X2C7	U147		In load monitor function operation ▲	X2CF	U14F		

▲ : For specific manufacturers.

1. PLC INTERFACE INPUT X

CNC → PLC (PLC4B)

Table 4-1-8 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X2D0	U150		In barrier valid (left)	X2D8	U158		
X2D1	U151		In barrier valid (right)	X2D9	U159		
X2D2	U152			X2DA	U15A		
X2D3	U153			X2DB	U15B		
X2D4	U154			X2DC	U15C		
X2D5	U155			X2DD	U15D		
X2D6	U156			X2DE	U15E		
X2D7	U157			X2DF	U15F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X2E0	U160		In cross machining control 1st axis	X2E8	U168		In synchronous/ superimposition control 1st axis
X2E1	U161		2nd axis	X2E9	U169		2nd axis
X2E2	U162		3rd axis	X2EA	U16A		3rd axis
X2E3	U163		4th axis	X2EB	U16B		4th axis
X2E4	U164		5th axis	X2EC	U16C		5th axis
X2E5	U165		6th axis	X2ED	U16D		6th axis
X2E6	U166		7th axis	X2EE	U16E		7th axis
X2E7	U167		8th axis	X2EF	U16F		8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X2F0	U170			X2F8	U178		
X2F1	U171			X2F9	U179		
X2F2	U172			X2FA	U17A		
X2F3	U173			X2FB	U17B		
X2F4	U174			X2FC	U17C		
X2F5	U175			X2FD	U17D		
X2F6	U176			X2FE	U17E		
X2F7	U177			X2FF	U17F		

1. PLC INTERFACE INPUT X

CNC → PLC (PLC4B)

Table 4-1-9 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X300	I380	DROPNS	Door open enable	X308	—	SPSYN1	In spindle synchronous control
X301	I381			X309	—	FSPRV	Spindle rotation speed synchronization complete
X302	—		MELDASNET diagnosis output complete	X30A	—	FSPPH	Spindle phase synchronization complete
X303	I383	NETSMP	MELDASNET in sampling	X30B	—	SPSYN2	In spindle synchronous control 2 (D)
X304	—	RPIN	In remote program input	X30C	—		— —
X305	—	RPFIN	Remote program input complete	X30D	—		— —
X306	—	RPERR	Remote program input error	X30E	—	SPCMP	Chuck close confirmation
X307	—		In tool ID communication ▲	X30F	—		Power OFF required after parameter change

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st SP	2nd SP		
X310	—		— —	X318	I398		In magnetic bearing ready ON
X311	—		— —	X319	I399		In magnetic bearing servo ON
X312	—		— —	X31A	I39A		— —
X313	—		— —	X31B	I39B		— —
X314	—		— —	X31C	I39C		In magnetic bearing warning
X315	—		— —	X31D	I39D		— —
X316	—		— —	X31E	I39E		— —
X317	—		— —	X31F	I39F		In magnetic bearing alarm

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X320	—		Door open enable 1-2	X328	I3A8		
X321	—		— —	X329	I3A9		
X322	I3A2			X32A	I3AA		
X323	I3A3			X32B	I3AB		
X324	I3A4			X32C	I3AC		
X325	I3A5			X32D	I3AD		
X326	I3A6			X32E	I3AE		
X327	I3A7			X32F	I3AF		

— — : Reserved for the system.

▲ : For specific manufacturers.

1. PLC INTERFACE INPUT X

CNC → PLC (PLC4B)

Table 4-1-10 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X330	I3B0			X338	I3B8		
X331	I3B1			X339	I3B9		
X332	I3B2			X33A	I3BA		
X333	I3B3			X33B	I3BB		
X334	I3B4			X33C	I3BC		
X335	I3B5			X33D	I3BD		
X336	I3B6			X33E	I3BE		
X337	I3B7			X33F	I3BF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X340	I3C0			X348	I3C8		
X341	I3C1			X349	I3C9		
X342	I3C2			X34A	I3CA		
X343	I3C3			X34B	I3CB		
X344	I3C4			X34C	I3CC		
X345	I3C5			X34D	I3CD		
X346	I3C6			X34E	I3CE		
X347	I3C7			X34F	I3CF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X350	I3D0			X358	I3D8		
X351	I3D1			X359	I3D9		
X352	I3D2			X35A	I3DA		
X353	I3D3			X35B	I3DB		
X354	I3D4			X35C	I3DC		
X355	I3D5			X35D	I3DD		
X356	I3D6			X35E	I3DE		
X357	I3D7			X35F	I3DF		

1. PLC INTERFACE INPUT X

CNC → PLC (PLC4B)

Table 4-1-11 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X360	I3E0			X368	I3E8		
X361	I3E1			X369	I3E9		
X362	I3E2			X36A	I3EA		
X363	I3E3			X36B	I3EB		
X364	I3E4			X36C	I3EC		
X365	I3E5			X36D	I3ED		
X366	I3E6			X36E	I3EE		
X367	I3E7			X36F	I3EF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
X370	I3F0			X378	I3F8		
X371	I3F1			X379	I3F9		
X372	I3F2			X37A	I3FA		
X373	I3F3			X37B	I3FB		
X374	I3F4			X37C	I3FC		
X375	I3F5			X37D	I3FD		
X376	I3F6			X37E	I3FE		
X377	I3F7			X37F	I3FF		

1. PLC INTERFACE INPUT X

CNC → PLC (PLC4B)

Table 4-1-12 (PLC4B)

Device No.				Device No.			
3rd SP	4th SP	Abbrev.	Signal name	3rd SP	4th SP	Abbrev.	Signal name
I300	I310	ENB	Spindle enable	I308	I318		
I301	I311			I309	I319		
I302	I312			I30A	I31A		
I303	I313			I30B	I31B		
I304	I314			I30C	I31C		
I305	I315			I30D	I31D		
I306	I316			I30E	I31E		
I307	I317			I30F	I31F		

Device No.				Device No.			
3rd SP	4th SP	Abbrev.	Signal name	3rd SP	4th SP	Abbrev.	Signal name
S000	S040	SUPP	Spindle speed upper limit over	S008	S048		— —
S001	S041	SLOW	Spindle speed lower limit over	S009	S049		— —
S002	S042	SIGE	S-analog gear No. illegal	S00A	S04A		
S003	S043	SOVE	S-analog max./min. command value over	S00B	S04B		
S004	S044	SNGE	S-analog no gear selected	S00C	S04C		
S005	S045	GR1	Spindle gear shift command 1	S00D	S04D	SD2	Speed detect 2
S006	S046	GR2	Spindle gear shift command 2	S00E	S04E	MCSA	In M coil selected
S007	S047	—	(Always "0")	S00F	S04F		Index positioning complete

Device No.				Device No.			
3rd SP	4th SP	Abbrev.	Signal name	3rd SP	4th SP	Abbrev.	Signal name
S010	S050		2nd in-position (D)	S018	S058	SMA	Spindle ready-ON
S011	S051	CDO	Current detect	S019	S059	SSA	Spindle servo-ON
S012	S052	VRO	Speed detect	S01A	S05A	SEMG	Spindle emergency stop
S013	S053	FLO	In spindle alarm	S01B	S05B	SSRN	Spindle forward run
S014	S054	ZSO	Zero speed	S01C	S05C	SSRI	Spindle reverse run
S015	S055	USO	Up-to-speed	S01D	S05D		Z-phase passed
S016	S056	ORAO	Spindle in-position	S01E	S05E	SIMP	Position loop in-position
S017	S057	LCSA	In L coil selected	S01F	S05F	STLQ	Torque limit

— — : Reserved for the system.

2. PLC INTERFACE INPUT R

The spindle related devices are described in the section "5. Other PLC Interfaces".

CNC → PLC

Table 4-2-1

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st SP	2nd SP		
R0	—	AI1	Analog input	R8	R208		Spindle command rotation speed input
R1	—	AI2	Analog input	R9	R209		
R2	—	AI3	Analog input	R10	R210		Spindle command final data (rotation speed)
R3	—	AI4	Analog input	R11	R211		
R4	—		— —	R12	R212		Spindle command final data (12-bit binary)
R5	—		— —	R13	R213		
R6	—		— —	R14	R214		
R7	—		— —	R15	R215		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R16	—		KEY IN 1	R24	R224		M code data 3
R17	—		FULL KEY IN	R25	R225		
R18	R218		Spindle actual speed	R26	R226		M code data 4
R19	R219			R27	R227		
R20	R220		M code data 1	R28	R228		S code data 1
R21	R221			R29	R229		
R22	R222		M code data 2	R30	R230		S code data 2
R23	R223			R31	R231		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R32	R232		S code data 3	R40	R240		— —
R33	R233			R41	R241		
R34	R234		S code data 4	R42	R242		— —
R35	R235			R43	R243		
R36	R236		T code data 1	R44	R244		2nd M function data 1
R37	R237			R45	R245		
R38	R238		— —	R46	R246		— —
R39	R239			R47	R247		

— — : Reserved for the system.

2. PLC INTERFACE INPUT R

CNC → PLC

Table 4-2-2

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R48	R248		— —	R56	—		Battery drop cause
R49	R249			R57	—		Temperature warning cause
R50	R250		— —	R58	—		5V/24V error cause
R51	R251			R59	R259		Adaptive control override output ▲
R52	R252		Load monitor warning axis ▲	R60	R260		CNC complete standby status output
R53	R253		Load monitor alarm axis ▲	R61	R261		
R54	R254		Load monitor data alarm information ▲	R62	R262		In initialization
R55	R255		Group in tool life management	R63	R263		Initialization incomplete

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R64	—		Display information	R72	—		User macro output #1032
R65	—			R73	—		(Note 1)
R66	—			R74	—		User macro output #1033
R67	—			R75	—		
R68	—		PLC main scan time	R76	—		User macro output #1034
R69	—		Emergency stop cause	R77	—		
R70	—		DIO card information	R78	—		User macro output #1035
R71	R271		Program execution state (editing related) ▲	R79	—		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R80	—		Add-on (expansion) operation board input signal 1	R88	R288		Near reference position (per reference position)
R81	—		signal 2	R89	R289		
R82	—		signal 3	R90	R290		Presetter contact
R83	—		signal 4	R91	R291		Presetter interlock
R84	—		M-NET OT check	R92	R292		
R85	R285			R93	R293		
R86	—		PC high-speed process time	R94	R294		
R87	R287			R95	R295		

— — : Reserved for the system.

▲ : For specific manufacturers.

(Note 1) #1032 to #1035 are output from the PLC, and the direction is the opposite of the other R registers.

2. PLC INTERFACE INPUT R

CNC → PLC

Table 4-2-3

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R96	—		CNC software version code				
R97	—						
R98	—						
R99	—						

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R372							
R373							
R374							
R375							
R376							
R377							
R378				R458	—		Control unit temperature
R379				R459	—		— —

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R460	—		Clock data Month/Year	R472	—		— —
R461	—		Hour/Date	R473	—		— —
R462	—		Second /Minute	R474	—		Spindle synchronous control Phase error output
R463	—		— —	R475	—		Phase error 1 (degree) (including shift calc.)
R464	R468		Area signal X axis ON/OFF ▲	R476	—		Phase error 2 (degree) (excluding shift calc.)
R465	R469		Area signal Z axis ON/OFF ▲	R477	—		Phase error monitor
R466	R470		Area signal X axis (-) ON/OFF ▲	R478	—		Phase error monitor (lower limit)
R467	R471		Area signal Z axis (-) ON/OFF ▲	R479	—		Phase error monitor (upper limit)

— — : Reserved for the system.

▲ : For specific manufacturers.

2. PLC INTERFACE INPUT R

CNC → PLC

Table 4-2-4

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R480	R484		Takt time (ms) (Low)	R488	—		Tool ID communication error information ▲
R481	R485		Takt time (ms) (High)	R489	—		MELDASNET diagnosis output cause
R482	R486		Takt time (min) (Low)	R490	—		Spindle synchronous control Phase offset data
R483	R487		Takt time (min) (High)	R498	R499		For HVS control (position err detect) ▲

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R614	R616		Tool life usage data				
R615	R617						

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
				R645	—		— —

— — : Reserved for the system.

▲ : For specific manufacturers.

2. PLC INTERFACE INPUT R

CNC → PLC

Table 4-2-5

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R670	R680		Load monitor status ▲	R678	R688		Load monitor status ▲
R671	R681		Load monitor status ▲	R679	R689		Load monitor status ▲
R672	R682		Load monitor status ▲				
R673	R683		Load monitor status ▲				
R674	R684		Load monitor status ▲				
R675	R685		Load monitor status ▲				
R676	R686		Load monitor status ▲				
R677	R687		Load monitor status ▲				

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R690	—		— —				

— — : Reserved for the system.

▲ : For specific manufacturers.

2. PLC INTERFACE INPUT R

CNC → PLC

Table 4-2-6

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R1100	R1116		Servo deflection amount 1st axis	R1108	R1124		Servo deflection amount 5th axis
R1101	R1117			R1109	R1125		
R1102	R1118		2nd axis	R1110	R1126		6th axis
R1103	R1119			R1111	R1127		
R1104	R1120		3rd axis	R1112	R1128		7th axis
R1105	R1121			R1113	R1129		
R1106	R1122		4th axis	R1114	R1130		8th axis
R1107	R1123			R1115	R1131		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R1350	—		Synchronous control error amount 1st axis (L)	R1358	—		Synchronous control error amount 5th axis (L)
R1351	—		1st axis (H)	R1359	—		5th axis (H)
R1352	—		2nd axis (L)	R1360	—		6th axis (L)
R1353	—		2nd axis (H)	R1361	—		6th axis (H)
R1354	—		3rd axis (L)	R1362	—		7th axis (L)
R1355	—		3rd axis (H)	R1363	—		7th axis (H)
R1356	—		4th axis (L)	R1364	—		8th axis (L)
R1357	—		4th axis (H)	R1365	—		8th axis (H)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R1366	—		Synchronous control error amount (spare) (L)	R1374	—		Synchronous control error amount (spare) (L)
R1367	—		(spare) (H)	R1375	—		(spare) (H)
R1368	—		(spare) (L)	R1376	—		(spare) (L)
R1369	—		(spare) (H)	R1377	—		(spare) (H)
R1370	—		(spare) (L)				
R1371	—		(spare) (H)				
R1372	—		(spare) (L)				
R1373	—		(spare) (H)				

2. PLC INTERFACE INPUT R

CNC → PLC

Table 4-2-7

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R1502	—		Remote program input error information				
R1503	—		MELDAS-NET output				

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R2896	R1892		No. of work machining (current) (Low-order)				
R2897	R1893		(High-order)				
R2898	R1894		No. of work machining (max.) (Low-order)				
R2899	R1895		(High-order)				

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
R4500	R4520		Spindle command	R4508	R4528		
R4501	R4521		rotation speed input	R4509	R4529		
R4502	R4522		Spindle command final data (rotation speed)	R4510	R4530		
R4503	R4523			R4511	R4531		
R4504	R4524		Spindle command final data (12-bit binary)	R4512	R4532		
R4505	R4525			R4513	R4533		
R4506	R4526		Spindle actual speed	R4514	R4534		
R4507	R4527			R4515	R4535		

2. PLC INTERFACE INPUT R

CNC → PLC

Table 4-2-8

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
R4516	R4536						
R4517	R4537						
R4518	R4538						
R4519	R4539						

3. PLC INTERFACE OUTPUT Y

The spindle related devices are described in the section "5. Other PLC Interfaces".

PLC → CNC (GX Developer)

Table 4-3-1 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y180	Y540	DTCH1	Control axis detach 1st axis	Y188	Y548	* SVF1	Servo OFF 1st axis
Y181	Y541	DTCH2	2nd axis	Y189	Y549	* SVF2	Servo OFF 2nd axis
Y182	Y542	DTCH3	3rd axis	Y18A	Y54A	* SVF3	Servo OFF 3rd axis
Y183	Y543	DTCH4	4th axis	Y18B	Y54B	* SVF4	Servo OFF 4th axis
Y184	Y544	DTCH5	5th axis	Y18C	Y54C	* SVF5	Servo OFF 5th axis
Y185	Y545	DTCH6	6th axis	Y18D	Y54D	* SVF6	Servo OFF 6th axis
Y186	Y546	DTCH7	7th axis	Y18E	Y54E	* SVF7	Servo OFF 7th axis
Y187	Y547	DTCH8	8th axis	Y18F	Y54F	* SVF8	Servo OFF 8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y190	Y550	MI1	Mirror image 1st axis	Y198	Y558	* +EDT1	External deceleration +1st axis
Y191	Y551	MI2	Mirror image 2nd axis	Y199	Y559	* +EDT2	+2nd axis
Y192	Y552	MI3	Mirror image 3rd axis	Y19A	Y55A	* +EDT3	+3rd axis
Y193	Y553	MI4	Mirror image 4th axis	Y19B	Y55B	* +EDT4	+4th axis
Y194	Y554	MI5	Mirror image 5th axis	Y19C	Y55C	* +EDT5	+5th axis
Y195	Y555	MI6	Mirror image 6th axis	Y19D	Y55D	* +EDT6	+6th axis
Y196	Y556	MI7	Mirror image 7th axis	Y19E	Y55E	* +EDT7	+7th axis
Y197	Y557	MI8	Mirror image 8th axis	Y19F	Y55F	* +EDT8	+8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y1A0	Y560	* -EDT1	External deceleration -1st axis	Y1A8	Y568	* +AIT1	Auto interlock +1st axis
Y1A1	Y561	* -EDT2	-2nd axis	Y1A9	Y569	* +AIT2	+2nd axis
Y1A2	Y562	* -EDT3	-3rd axis	Y1AA	Y56A	* +AIT3	+3rd axis
Y1A3	Y563	* -EDT4	-4th axis	Y1AB	Y56B	* +AIT4	+4th axis
Y1A4	Y564	* -EDT5	-5th axis	Y1AC	Y56C	* +AIT5	+5th axis
Y1A5	Y565	* -EDT6	-6th axis	Y1AD	Y56D	* +AIT6	+6th axis
Y1A6	Y566	* -EDT7	-7th axis	Y1AE	Y56E	* +AIT7	+7th axis
Y1A7	Y567	* -EDT8	-8th axis	Y1AF	Y56F	* +AIT8	+8th axis

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-2 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y1B0	Y570	* -AIT1	Auto interlock -1st axis	Y1B8	Y578	* +MIT1	Manual interlock +1st axis
Y1B1	Y571	* -AIT2	-2nd axis	Y1B9	Y579	* +MIT2	+2nd axis
Y1B2	Y572	* -AIT3	-3rd axis	Y1BA	Y57A	* +MIT3	+3rd axis
Y1B3	Y573	* -AIT4	-4th axis	Y1BB	Y57B	* +MIT4	+4th axis
Y1B4	Y574	* -AIT5	-5th axis	Y1BC	Y57C	* +MIT5	+5th axis
Y1B5	Y575	* -AIT6	-6th axis	Y1BD	Y57D	* +MIT6	+6th axis
Y1B6	Y576	* -AIT7	-7th axis	Y1BE	Y57E	* +MIT7	+7th axis
Y1B7	Y577	* -AIT8	-8th axis	Y1BF	Y57F	* +MIT8	+8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y1C0	Y580	* -MIT1	Manual interlock -1st axis	Y1C8	Y588	AMLK1	Auto machine lock 1st axis
Y1C1	Y581	* -MIT2	-2nd axis	Y1C9	Y589	AMLK2	2nd axis
Y1C2	Y582	* -MIT3	-3rd axis	Y1CA	Y58A	AMLK3	3rd axis
Y1C3	Y583	* -MIT4	-4th axis	Y1CB	Y58B	AMLK4	4th axis
Y1C4	Y584	* -MIT5	-5th axis	Y1CC	Y58C	AMLK5	5th axis
Y1C5	Y585	* -MIT6	-6th axis	Y1CD	Y58D	AMLK6	6th axis
Y1C6	Y586	* -MIT7	-7th axis	Y1CE	Y58E	AMLK7	7th axis
Y1C7	Y587	* -MIT8	-8th axis	Y1CF	Y58F	AMLK8	8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y1D0	Y590	MMLK1	Manual machine lock 1st axis	Y1D8	Y598	+J1	Feed axis select +1st axis
Y1D1	Y591	MMLK2	2nd axis	Y1D9	Y599	+J2	+2nd axis
Y1D2	Y592	MMLK3	3rd axis	Y1DA	Y59A	+J3	+3rd axis
Y1D3	Y593	MMLK4	4th axis	Y1DB	Y59B	+J4	+4th axis
Y1D4	Y594	MMLK5	5th axis	Y1DC	Y59C	+J5	+5th axis
Y1D5	Y595	MMLK6	6th axis	Y1DD	Y59D	+J6	+6th axis
Y1D6	Y596	MMLK7	7th axis	Y1DE	Y59E	+J7	+7th axis
Y1D7	Y597	MMLK8	8th axis	Y1DF	Y59F	+J8	+8th axis

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-3 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y1E0	Y5A0	-J1	Feed axis select -1st axis	Y1E8	Y5A8	CHPS	Chopping
Y1E1	Y5A1	-J2	-2nd axis	Y1E9	Y5A9		
Y1E2	Y5A2	-J3	-3rd axis	Y1EA	Y5AA		
Y1E3	Y5A3	-J4	-4th axis	Y1EB	Y5AB		
Y1E4	Y5A4	-J5	-5th axis	Y1EC	Y5AC		
Y1E5	Y5A5	-J6	-6th axis	Y1ED	Y5AD		
Y1E6	Y5A6	-J7	-7th axis	Y1EE	Y5AE		
Y1E7	Y5A7	-J8	-8th axis	Y1EF	Y5AF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y1F0	Y5B0	MAE1	Manual/Auto simultaneous valid 1st axis	Y1F8	Y5B8		— —
Y1F1	Y5B1	MAE2	2nd axis	Y1F9	Y5B9		
Y1F2	Y5B2	MAE3	3rd axis	Y1FA	Y5BA	RSST	Search & start
Y1F3	Y5B3	MAE4	4th axis	Y1FB	Y5BB		Magazine index check valid (ATC high-speed)
Y1F4	Y5B4	MAE5	5th axis	Y1FC	Y5BC		Spindle orientation complete standby valid (ATC high-speed)
Y1F5	Y5B5	MAE6	6th axis	Y1FD	Y5BD		
Y1F6	Y5B6	MAE7	7th axis	Y1FE	Y5BE		
Y1F7	Y5B7	MAE8	8th axis	Y1FF	Y5BF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y200	Y5C0	ZSL1	Reference position select 1	Y208	Y5C8	J	Jog mode
Y201	Y5C1	ZSL2	Reference position select 2	Y209	Y5C9	H	Handle mode
Y202	Y5C2			Y20A	Y5CA	S	Incremental mode
Y203	Y5C3			Y20B	Y5CB	PTP	Manual random feed mode
Y204	Y5C4			Y20C	Y5CC	ZRN	Reference position return mode
Y205	Y5C5			Y20D	Y5CD	AST	Auto initialization mode
Y206	Y5C6			Y20E	Y5CE		
Y207	Y5C7		Reference position select method	Y20F	Y5CF		

— — : Reserved for the system.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-4 (GX Developer)

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y210	Y5D0	MEM	Memory mode	Y218	Y5D8	ST	Auto operation "start" command
Y211	Y5D1	T	Tape mode	Y219	Y5D9	* SP	Auto operation "pause" command
Y212	Y5D2		— —	Y21A	Y5DA	SBK	Single block
Y213	Y5D3	D	MDI mode	Y21B	Y5DB	* BSL	Block start interlock
Y214	Y5D4		— —	Y21C	Y5DC	* CSL	Cutting block start interlock
Y215	Y5D5		Direct operation mode ▲	Y21D	Y5DD	DRN	Dry run
Y216	Y5D6			Y21E	Y5DE		
Y217	Y5D7			Y21F	Y5DF	ERD	Error detect

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y220	Y5E0	NRST1	NC reset 1	Y228	Y5E8	TLM	Tool length measurement 1
Y221	Y5E1	NRST2	NC reset 2	Y229	Y5E9	TLMS	Tool length measurement 2 (L system)
Y222	Y5E2	RRW	Reset & rewind	Y22A	Y5EA		Synchronization correction mode
Y223	Y5E3	* CDZ	Chamfering	Y22B	Y5EB	PRST	Program restart
Y224	Y5E4	ARST	Auto restart	Y22C	Y5EC	PB	Playback
Y225	Y5E5	GFIN	Gear shift complete	Y22D	Y5ED	UIT	Macro interrupt
Y226	Y5E6	FIN1	M function finish 1	Y22E	Y5EE	RT	Rapid traverse
Y227	Y5E7	FIN2	M function finish 2	Y22F	Y5EF		— —

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y230	Y5F0	ABS	Manual absolute	Y238	—	* KEY1	Data protect key 1
Y231	Y5F1	DLK	Display lock	Y239	—	* KEY2	Data protect key 2
Y232	Y5F2		F1-digit speed change valid	Y23A	—	* KEY3	Data protect key 3
Y233	Y5F3	CRQ	Recalculation request	Y23B	—	—	— —
Y234	—	RHD1	Integration time input 1	Y23C	—	PDISP	Program display during operation
Y235	—	RHD2	Integration time input 2	Y23D	Y5FD		Inclined axis control valid
Y236	Y5F6	PIT	PLC interrupt signal	Y23E	Y5FE		Inclined axis control: No Z axis compensation
Y237	Y5F7			Y23F	Y5FF	BDT1	Optional block skip

— — : Reserved for the system.

▲ : For specific manufacturers.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-5 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y240	Y600	—	— —	Y248	Y608	HS11	1st handle axis No.
Y241	Y601	—	— —	Y249	Y609	HS12	
Y242	Y602	—	— —	Y24A	Y60A	HS14	
Y243	Y603	—	— —	Y24B	Y60B	HS18	
Y244	Y604	—	— —	Y24C	Y60C	HS116	
Y245	Y605	—	— —	Y24D	Y60D		
Y246	Y606	—	— —	Y24E	Y60E		
Y247	Y607	—	— —	Y24F	Y60F	HS1S	1st handle valid

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y250	Y610	HS21	2nd handle axis No.	Y258	Y618	HS31	3rd handle axis No.
Y251	Y611	HS22		Y259	Y619	HS32	
Y252	Y612	HS24		Y25A	Y61A	HS34	
Y253	Y613	HS28		Y25B	Y61B	HS38	
Y254	Y614	HS216		Y25C	Y61C	HS316	
Y255	Y615			Y25D	Y61D		
Y256	Y616		Y25E	Y61E			
Y257	Y617	HS2S	2nd handle valid	Y25F	Y61F	HS3S	3rd handle valid

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y260	Y620	FBE1	Manual feedrate B valid 1st axis	Y268	Y628	CX11	Manual random feed 1st axis No.
Y261	Y621	FBE2	2nd axis	Y269	Y629	CX12	
Y262	Y622	FBE3	3rd axis	Y26A	Y62A	CX14	
Y263	Y623	FBE4	4th axis	Y26B	Y62B	CX18	
Y264	Y624	FBE5	5th axis	Y26C	Y62C	CX116	
Y265	Y625	FBE6	6th axis	Y26D	Y62D		(Always "0")
Y266	Y626	FBE7	7th axis	Y26E	Y62E		(Always "0")
Y267	Y627	FBE8	8th axis	Y26F	Y62F	CX1S	Manual random feed 1st axis valid

— — : Reserved for the system.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-6 (GX Developer)

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y270	Y630	CX21	Manual random feed 2nd axis No.	Y278	Y638	CX31	Manual random feed 3rd axis No.
Y271	Y631	CX22		Y279	Y639	CX32	
Y272	Y632	CX24		Y27A	Y63A	CX34	
Y273	Y633	CX28		Y27B	Y63B	CX38	
Y274	Y634	CX216		Y27C	Y63C	CX316	
Y275	Y635		(Always "0")	Y27D	Y63D		(Always "0")
Y276	Y636		(Always "0")	Y27E	Y63E		(Always "0")
Y277	Y637	CX2S	Manual random feed 2nd axis valid	Y27F	Y63F	CX3S	Manual random feed 3rd axis valid

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st SP	2nd SP	Abbrev.	Signal name
Y280	Y640	CXS1	Smoothing off	Y288	Y648	SP1	Spindle override 1
Y281	Y641	CXS2	Axis independent	Y289	Y649	SP2	Spindle override 2
Y282	Y642	CXS3	EX.F/MODAL.F	Y28A	Y64A	SP4	Spindle override 4
Y283	Y643	CXS4	G0/G1	Y28B	Y64B		
Y284	Y644	CXS5	MC/WK	Y28C	Y64C		
Y285	Y645	CXS6	ABS/INC	Y28D	Y64D		
Y286	Y646	*CXS7	Stop	Y28E	Y64E		
Y287	Y647	CXS8	Strobe	Y28F	Y64F	SPS	Spindle override method select

Device No.				Device No.			
1st SP	2nd SP	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y290	Y650	GI1	Spindle gear select 1	Y298	Y658	OVC	Override cancel
Y291	Y651	GI2	Spindle gear select 2	Y299	Y659	OVSL	Manual override valid
Y292	Y652	—	(Always "0")	Y29A	Y65A	AFL	Miscellaneous function lock
Y293	Y653			Y29B	Y65B		
Y294	Y654	SSTP	Spindle stop	Y29C	Y65C	TRV	Tap retract
Y295	Y655	SSFT	Spindle gear shift	Y29D	Y65D	RTN	Reference position retract
Y296	Y656	SORC	Oriented spindle speed command	Y29E	Y65E		
Y297	Y657			Y29F	Y65F	QEMG	PLC emergency stop

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-7 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y2A0	Y660	* FV1	Cutting feedrate override	Y2A8	Y668	ROV1	Rapid traverse speed override
Y2A1	Y661	* FV2		Y2A9	Y669	ROV2	
Y2A2	Y662	* FV4		Y2AA	Y66A		
Y2A3	Y663	* FV8		Y2AB	Y66B		
Y2A4	Y664	* FV16		Y2AC	Y66C		
Y2A5	Y665			Y2AD	Y66D		
Y2A6	Y666	FV2E	2nd cutting feedrate override valid	Y2AE	Y66E		
Y2A7	Y667	FVS	Cutting feedrate override method select	Y2AF	Y66F	ROVS	Rapid traverse speed override method select

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y2B0	Y670	* JV1	Manual feedrate	Y2B8	Y678	PCF1	Feedrate least increment
Y2B1	Y671	* JV2		Y2B9	Y679	PCF2	
Y2B2	Y672	* JV4		Y2BA	Y67A	JSYN	Jog synchronous feed valid
Y2B3	Y673	* JV8		Y2BB	Y67B	JHAN	Jog•handle synchronous
Y2B4	Y674	* JV16		Y2BC	Y67C		Each axis manual feedrate B valid
Y2B5	Y675			Y2BD	Y67D		— —
Y2B6	Y676			Y2BE	Y67E		— —
Y2B7	Y677	JVS	Manual feedrate method select	Y2BF	Y67F		— —

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y2C0	Y680	MP1	Handle/Incremental feed multiplication	Y2C8	Y688	TAL1	Tool alarm 1/Tool-skip tool
Y2C1	Y681	MP2		Y2C9	Y689	TAL2	Tool alarm 2 (M system)
Y2C2	Y682	MP4		Y2CA	Y68A	TCEF	Data count valid
Y2C3	Y683			Y2CB	Y68B	TLFI	Tool life management input (M system)
Y2C4	Y684			Y2CC	Y68C	TRST	Tool change reset (L system)
Y2C5	Y685			Y2CD	Y68D		
Y2C6	Y686		— —	Y2CE	Y68E		
Y2C7	Y687	MPS	Handle/Incremental feed multiplication method select	Y2CF	Y68F		

— — : Reserved for the system.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-8 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st SP	2nd SP			1st SP	2nd SP		
Y2D0	Y690	SRN	Spindle forward run start	Y2D8	Y698		
Y2D1	Y691	SRI	Spindle reverse run start	Y2D9	Y699		
Y2D2	Y692	TL1	Torque limit 1	Y2DA	Y69A		C axis gain L
Y2D3	Y693	TL2	Torque limit 2	Y2DB	Y69B		C axis gain H
Y2D4	Y694	WRN	Spindle forward run index	Y2DC	Y69C		C axis zero point return
Y2D5	Y695	WRI	Spindle reverse run index	Y2DD	Y69D		
Y2D6	Y696	ORC	Spindle orient command	Y2DE	Y69E	LRSM	M coil selection
Y2D7	Y697	LRSL	L coil selection	Y2DF	Y69F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y2E0	—	* PCD1	PLC axis near point detect 1st axis	Y2E8	—	SPSYC	Spindle synchronization cancel
Y2E1	—	* PCD2	PLC axis near point detect 2nd axis	Y2E9	—	SPCMP C	Chuck close
Y2E2	—		— —	Y2EA	—		
Y2E3	—		— —	Y2EB	—		
Y2E4	—	PCH1	PLC axis 1st handle valid	Y2EC	—		
Y2E5	—	PCH2	PLC axis 2nd handle valid	Y2ED	—		
Y2E6	—	PCH3	PLC axis 3rd handle valid	Y2EE	—		
Y2E7	Y6A7			Y2EF	—		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y2F0	Y6B0		— —	Y2F8	—	CRTFN	CRT changeover complete
Y2F1	Y6B1		— —	Y2F9	Y6B9	CSRON	Screen display request
Y2F2	Y6B2		— —	Y2FA	Y6BA		
Y2F3	Y6B3		— —	Y2FB	Y6BB	NETST P	MELDASNET sampling stop
Y2F4	Y6B4		— —	Y2FC	—	SMPTR G	Data sampling trigger
Y2F5	Y6B5		— —	Y2FD	—	MTBT	PLC snapshot
Y2F6	Y6B6		— —	Y2FE	—	DISP1	Display changeover \$1
Y2F7	Y6B7		— —	Y2FF	—	DISP2	Display changeover \$2

— — : Reserved for the system.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-9 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y300	Y6C0	AZS1	Zero point initialization set mode 1st axis	Y308	Y6C8	ZST1	Zero point initialization set start 1st axis
Y301	Y6C1	AZS2	2nd axis	Y309	Y6C9	ZST2	2nd axis
Y302	Y6C2	AZS3	3rd axis	Y30A	Y6CA	ZST3	3rd axis
Y303	Y6C3	AZS4	4th axis	Y30B	Y6CB	ZST4	4th axis
Y304	Y6C4	AZS5	5th axis	Y30C	Y6CC	ZST5	5th axis
Y305	Y6C5	AZS6	6th axis	Y30D	Y6CD	ZST6	6th axis
Y306	Y6C6	AZS7	7th axis	Y30E	Y6CE	ZST7	7th axis
Y307	Y6C7	AZS8	8th axis	Y30F	Y6CF	ZST8	8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y310	Y6D0		Current limit mode 1	Y318	Y6D8		Current limit changeover 1st axis
Y311	Y6D1		Current limit mode 2	Y319	Y6D9		2nd axis
Y312	Y6D2		(Same as above, spare)	Y31A	Y6DA		3rd axis
Y313	Y6D3	LDWT	Load monitor Teaching/ monitor execution ▲	Y31B	Y6DB		4th axis
Y314	Y6D4		Load monitor Teaching mode select ▲	Y31C	Y6DC		5th axis
Y315	Y6D5		Load monitor Monitor mode select ▲	Y31D	Y6DD		6th axis
Y316	Y6D6		Load monitor Alarm reset ▲	Y31E	Y6DE		7th axis
Y317	Y6D7		Load monitor Warning reset ▲	Y31F	Y6DF		8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y320	Y6E0		Droop release request 1st axis	Y328	Y6E8		— —
Y321	Y6E1		2nd axis	Y329	Y6E9		Ext. workpiece coordinate measurement 2nd axis
Y322	Y6E2		3rd axis	Y32A	Y6EA		— —
Y323	Y6E3		4th axis	Y32B	Y6EB		— —
Y324	Y6E4		5th axis	Y32C	Y6EC		— —
Y325	Y6E5		6th axis	Y32D	Y6ED		— —
Y326	Y6E6		7th axis	Y32E	Y6EE		— —
Y327	Y6E7		8th axis	Y32F	Y6EF		— —

— — : Reserved for the system.

▲ : For specific manufacturers.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-10 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y330	Y6F0	DTCH2 1	Control axis detach 2 1st axis	Y338	Y6F8		Unclamp complete 1st axis
Y331	Y6F1	DTCH2 2	2nd axis	Y339	Y6F9		2nd axis
Y332	Y6F2	DTCH2 3	3rd axis	Y33A	Y6FA		3rd axis
Y333	Y6F3	DTCH2 4	4th axis	Y33B	Y6FB		4th axis
Y334	Y6F4	DTCH2 5	5th axis	Y33C	Y6FC		5th axis
Y335	Y6F5	DTCH2 6	6th axis	Y33D	Y6FD		6th axis
Y336	Y6F6	DTCH2 7	7th axis	Y33E	Y6FE		7th axis
Y337	Y6F7	DTCH2 8	8th axis	Y33F	Y6FF		8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y340	Y700		Each axis reference position return 1st axis	Y348	Y708	* ZRIT	2nd reference position return interlock
Y341	Y701		2nd axis	Y349	Y709		Adaptive control execution ▲
Y342	Y702		3rd axis	Y34A	Y70A		Small diameter deep hole drilling cycle
Y343	Y703		4th axis	Y34B	Y70B		— —
Y344	Y704		5th axis	Y34C	Y70C		INC high-speed retract function valid ▲
Y345	Y705		6th axis	Y34D	Y70D		Optimum pecking function valid ▲
Y346	Y706		7th axis	Y34E	Y70E		Load monitor function valid ▲
Y347	Y707		8th axis	Y34F	Y70F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st SP	2nd SP			1st sys	2nd sys		
Y350	Y710	SWS	Spindle command selection	Y358	Y718		Waiting ignore
Y351	Y711			Y359	Y719		Spindle-spindle polygon cancel
Y352	Y712			Y35A	Y71A		Synchronous tapping command polarity reversal
Y353	Y713			Y35B	Y71B		Spindle OFF mode
Y354	Y714			Y35C	Y71C		
Y355	Y715			Y35D	Y71D		
Y356	Y716			Y35E	Y71E		
Y357	Y717	MPCSL	PLC coil changeover	Y35F	Y71F		

— — : Reserved for the system.

▲ : For specific manufacturers.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-11 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y360	Y720		Cross machining control request	Y368	Y728		1st axis
Y361	Y721			Y369	Y729		2nd axis
Y362	Y722			Y36A	Y72A		3rd axis
Y363	Y723			Y36B	Y72B		4th axis
Y364	Y724			Y36C	Y72C		5th axis
Y365	Y725			Y36D	Y72D		6th axis
Y366	Y726			Y36E	Y72E		7th axis
Y367	Y727			Y36F	Y72F		8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y370	Y730		Position switch 1 interlock	Y378	Y738		Barrier valid (left)
Y371	Y731		Position switch 2 interlock	Y379	Y739		Barrier valid (right)
Y372	Y732		Position switch 3 interlock	Y37A	Y73A		Tool presetter sub-side valid
Y373	Y733		Position switch 4 interlock	Y37B	Y73B		
Y374	Y734		Position switch 5 interlock	Y37C	Y73C		
Y375	Y735		Position switch 6 interlock	Y37D	Y73D		
Y376	Y736		Position switch 7 interlock	Y37E	Y73E		
Y377	Y737		Position switch 8 interlock	Y37F	Y73F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st SP	2nd SP		
Y380	—		Door open	Y388	YCC8		Magnetic bearing servo ON command
Y381	YCC1		Door open II	Y389	YCC9		Magnetic bearing tool unclamp
Y382	YCC2		Door open signal input (spindle speed monitor)	Y38A	YCCA		— —
Y383	YCC3		Door interlock spindle speed clamp	Y38B	YCCB		— —
Y384	—	RPN	Remote program input start	Y38C	YCCC		— —
Y385	—		Tool ID data read ▲	Y38D	YCCD		— —
Y386	—		Tool ID data write ▲	Y38E	YCCE		— —
Y387	—		Tool ID data erase ▲	Y38F	YCCF		— —

— — : Reserved for the system.

▲ : For specific manufacturers.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-12 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y390	—		Tool IC new read ▲	Y398	—	SPSY	Spindle synchronous control
Y391	—		Tool IC exchange read ▲	Y399	—	SPPHS	Spindle phase synchronous control
Y392	—			Y39A	—		Spindle synchronous rotation direction
Y393	—			Y39B	—	SSPHM	Phase shift calculation request
Y394	—			Y39C	—	SSPHF	Phase offset request
Y395	—		— —	Y39D	—	SPDRP O	Error temporary cancel
Y396	—			Y39E	—		
Y397	—		— —	Y39F	—		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y3A0	YCE0		PLC skip 1	Y3A8	YCE8	SYNC1	Synchronous control request 1st axis
Y3A1	YCE1		PLC skip 2	Y3A9	YCE9	SYNC2	2nd axis
Y3A2	YCE2		PLC skip 3	Y3AA	YCEA	SYNC3	3rd axis
Y3A3	YCE3		PLC skip 4	Y3AB	YCEB	SYNC4	4th axis
Y3A4	YCE4		PLC skip 5	Y3AC	YCEC	SYNC5	5th axis
Y3A5	YCE5		PLC skip 6	Y3AD	YCED	SYNC6	6th axis
Y3A6	YCE6		PLC skip 7	Y3AE	YCEE	SYNC7	7th axis
Y3A7	YCE7		PLC skip 8	Y3AF	YCEF	SYNC8	8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y3B0	YCF0	PILE1	Superimposition control request 1st axis	Y3B8	—		Door open II 1-2
Y3B1	YCF1	PILE2	2nd axis	Y3B9	—		— —
Y3B2	YCF2	PILE3	3rd axis	Y3BA	—		Door open signal input 1-2
Y3B3	YCF3	PILE4	4th axis	Y3BB	—		— —
Y3B4	YCF4	PILE5	5th axis	Y3BC	YCFC		
Y3B5	YCF5	PILE6	6th axis	Y3BD	YCFD		
Y3B6	YCF6	PILE7	7th axis	Y3BE	YCFE		
Y3B7	YCF7	PILE8	8th axis	Y3BF	YCFE		

— — : Reserved for the system.

▲ : For specific manufacturers.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-13 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y3C0	YD00			Y3C8	YD08		
Y3C1	YD01			Y3C9	YD09		
Y3C2	YD02			Y3CA	YD0A		
Y3C3	YD03			Y3CB	YD0B		
Y3C4	YD04			Y3CC	YD0C		
Y3C5	YD05			Y3CD	YD0D		
Y3C6	YD06			Y3CE	YD0E		
Y3C7	YD07			Y3CF	YD0F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y3D0	YD10			Y3D8	YD18		
Y3D1	YD11			Y3D9	YD19		
Y3D2	YD12			Y3DA	YD1A		
Y3D3	YD13			Y3DB	YD1B		
Y3D4	YD14			Y3DC	YD1C		
Y3D5	YD15			Y3DD	YD1D		
Y3D6	YD16			Y3DE	YD1E		
Y3D7	YD17			Y3DF	YD1F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y3E0	YD20			Y3E8	YD28		
Y3E1	YD21			Y3E9	YD29		
Y3E2	YD22			Y3EA	YD2A		
Y3E3	YD23			Y3EB	YD2B		
Y3E4	YD24			Y3EC	YD2C		
Y3E5	YD25			Y3ED	YD2D		
Y3E6	YD26			Y3EE	YD2E		
Y3E7	YD27			Y3EF	YD2F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y3F0	YD30			Y3F8	YD38		
Y3F1	YD31			Y3F9	YD39		
Y3F2	YD32			Y3FA	YD3A		
Y3F3	YD33			Y3FB	YD3B		
Y3F4	YD34			Y3FC	YD3C		
Y3F5	YD35			Y3FD	YD3D		
Y3F6	YD36			Y3FE	YD3E		
Y3F7	YD37			Y3FF	YD3F		

3. PLC INTERFACE OUTPUT Y

PLC → CNC (GX Developer)

Table 4-3-14 (GX Developer)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
YD40	YD50	SWS	Spindle selection	YD48	YD58	GFIN	Gear shift complete
YD41	YD51			YD49	YD59		
YD42	YD52			YD4A	YD5A		
YD43	YD53			YD4B	YD5B		
YD44	YD54			YD4C	YD5C		
YD45	YD55			YD4D	YD5D		
YD46	YD56			YD4E	YD5E		
YD47	YD57	MPCSL	PLC coil changeover	YD4F	YD5F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
YD80	YDA0	SP1	Spindle override 1	YD88	YDA8	GI1	Spindle gear selection input 1
YD81	YDA1	SP2	Spindle override 2	YD89	YDA9	GI2	Spindle gear selection input 2
YD82	YDA2	SP4	Spindle override 4	YD8A	YDAA	—	(Always "0")
YD83	YDA3			YD8B	YDAB		
YD84	YDA4			YD8C	YDAC	SSTP	Spindle stop
YD85	YDA5			YD8D	YDAD	SSFT	Spindle gear shift
YD86	YDA6			YD8E	YDAE	SORC	Oriented spindle speed command
YD87	YDA7	SPS	Spindle override method select	YD8F	YDAF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
YD90	YDB0	SRN	Spindle forward run start	YD98	YDB8		
YD91	YDB1	SRI	Spindle reverse run start	YD99	YDB9		
YD92	YDB2	TL1	Torque limit 1	YD9A	YDBA		C axis gain L
YD93	YDB3	TL2	Torque limit 2	YD9B	YDBB		C axis gain H
YD94	YDB4	WRN	Spindle forward run index	YD9C	YDBC		C axis reference position return
YD95	YDB5	WRI	Spindle reverse run index	YD9D	YDBD		
YD96	YDB6	ORC	Spindle orientation command	YD9E	YDBE	LRSM	M coil selection
YD97	YDB7	LRSL	L coil selection	YD9F	YDBF		

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-1 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y180	W0	DTCH1	Control axis detach 1st axis	Y188	W8	* SVF1	Servo OFF 1st axis
Y181	W1	DTCH2	2nd axis	Y189	W9	* SVF2	Servo OFF 2nd axis
Y182	W2	DTCH3	3rd axis	Y18A	WA	* SVF3	Servo OFF 3rd axis
Y183	W3	DTCH4	4th axis	Y18B	WB	* SVF4	Servo OFF 4th axis
Y184	W4	DTCH5	5th axis	Y18C	WC	* SVF5	Servo OFF 5th axis
Y185	W5	DTCH6	6th axis	Y18D	WD	* SVF6	Servo OFF 6th axis
Y186	W6	DTCH7	7th axis	Y18E	WE	* SVF7	Servo OFF 7th axis
Y187	W7	DTCH8	8th axis	Y18F	WF	* SVF8	Servo OFF 8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y190	W10	MI1	Mirror image 1st axis	Y198	W18	* +EDT1	External deceleration +1st axis
Y191	W11	MI2	Mirror image 2nd axis	Y199	W19	* +EDT2	+2nd axis
Y192	W12	MI3	Mirror image 3rd axis	Y19A	W1A	* +EDT3	+3rd axis
Y193	W13	MI4	Mirror image 4th axis	Y19B	W1B	* +EDT4	+4th axis
Y194	W14	MI5	Mirror image 5th axis	Y19C	W1C	* +EDT5	+5th axis
Y195	W15	MI6	Mirror image 6th axis	Y19D	W1D	* +EDT6	+6th axis
Y196	W16	MI7	Mirror image 7th axis	Y19E	W1E	* +EDT7	+7th axis
Y197	W17	MI8	Mirror image 8th axis	Y19F	W1F	* +EDT8	+8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y1A0	W20	* -EDT1	External deceleration -1st axis	Y1A8	W28	* +AIT1	Auto interlock +1st axis
Y1A1	W21	* -EDT2	-2nd axis	Y1A9	W29	* +AIT2	+2nd axis
Y1A2	W22	* -EDT3	-3rd axis	Y1AA	W2A	* +AIT3	+3rd axis
Y1A3	W23	* -EDT4	-4th axis	Y1AB	W2B	* +AIT4	+4th axis
Y1A4	W24	* -EDT5	-5th axis	Y1AC	W2C	* +AIT5	+5th axis
Y1A5	W25	* -EDT6	-6th axis	Y1AD	W2D	* +AIT6	+6th axis
Y1A6	W26	* -EDT7	-7th axis	Y1AE	W2E	* +AIT7	+7th axis
Y1A7	W27	* -EDT8	-8th axis	Y1AF	W2F	* +AIT8	+8th axis

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-2 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y1B0	W30	* -AIT1	Auto interlock -1st axis	Y1B8	W38	* +MIT1	Manual interlock +1st axis
Y1B1	W31	* -AIT2	-2nd axis	Y1B9	W39	* +MIT2	+2nd axis
Y1B2	W32	* -AIT3	-3rd axis	Y1BA	W3A	* +MIT3	+3rd axis
Y1B3	W33	* -AIT4	-4th axis	Y1BB	W3B	* +MIT4	+4th axis
Y1B4	W34	* -AIT5	-5th axis	Y1BC	W3C	* +MIT5	+5th axis
Y1B5	W35	* -AIT6	-6th axis	Y1BD	W3D	* +MIT6	+6th axis
Y1B6	W36	* -AIT7	-7th axis	Y1BE	W3E	* +MIT7	+7th axis
Y1B7	W37	* -AIT8	-8th axis	Y1BF	W3F	* +MIT8	+8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y1C0	W40	* -MIT1	Manual interlock -1st axis	Y1C8	W48	AMLK1	Auto machine lock 1st axis
Y1C1	W41	* -MIT2	-2nd axis	Y1C9	W49	AMLK2	2nd axis
Y1C2	W42	* -MIT3	-3rd axis	Y1CA	W4A	AMLK3	3rd axis
Y1C3	W43	* -MIT4	-4th axis	Y1CB	W4B	AMLK4	4th axis
Y1C4	W44	* -MIT5	-5th axis	Y1CC	W4C	AMLK5	5th axis
Y1C5	W45	* -MIT6	-6th axis	Y1CD	W4D	AMLK6	6th axis
Y1C6	W46	* -MIT7	-7th axis	Y1CE	W4E	AMLK7	7th axis
Y1C7	W47	* -MIT8	-8th axis	Y1CF	W4F	AMLK8	8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y1D0	W50	MMLK1	Manual machine lock 1st axis	Y1D8	W58	+J1	Feed axis select +1st axis
Y1D1	W51	MMLK2	2nd axis	Y1D9	W59	+J2	+2nd axis
Y1D2	W52	MMLK3	3rd axis	Y1DA	W5A	+J3	+3rd axis
Y1D3	W53	MMLK4	4th axis	Y1DB	W5B	+J4	+4th axis
Y1D4	W54	MMLK5	5th axis	Y1DC	W5C	+J5	+5th axis
Y1D5	W55	MMLK6	6th axis	Y1DD	W5D	+J6	+6th axis
Y1D6	W56	MMLK7	7th axis	Y1DE	W5E	+J7	+7th axis
Y1D7	W57	MMLK8	8th axis	Y1DF	W5F	+J8	+8th axis

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-3 (PLC4B)

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y1E0	W60	-J1	Feed axis select -1st axis	Y1E8	W68	CHPS	Chopping
Y1E1	W61	-J2	-2nd axis	Y1E9	W69		
Y1E2	W62	-J3	-3rd axis	Y1EA	W6A		
Y1E3	W63	-J4	-4th axis	Y1EB	W6B		
Y1E4	W64	-J5	-5th axis	Y1EC	W6C		
Y1E5	W65	-J6	-6th axis	Y1ED	W6D		
Y1E6	W66	-J7	-7th axis	Y1EE	W6E		
Y1E7	W67	-J8	-8th axis	Y1EF	W6F		

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y1F0	W70	MAE1	Manual/Auto simultaneous valid 1st axis	Y1F8	W78		— —
Y1F1	W71	MAE2	2nd axis	Y1F9	W79		
Y1F2	W72	MAE3	3rd axis	Y1FA	W7A	RSST	Search & start
Y1F3	W73	MAE4	4th axis	Y1FB	W7B		Magazine index check valid (ATC high-speed)
Y1F4	W74	MAE5	5th axis	Y1FC	W7C		Spindle orientation complete standby valid (ATC high-speed)
Y1F5	W75	MAE6	6th axis	Y1FD	W7D		
Y1F6	W76	MAE7	7th axis	Y1FE	W7E		
Y1F7	W77	MAE8	8th axis	Y1FF	W7F		

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y200	W80	ZSL1	Reference position select 1	Y208	W88	J	Jog mode
Y201	W81	ZSL2	Reference position select 2	Y209	W89	H	Handle mode
Y202	W82			Y20A	W8A	S	Incremental mode
Y203	W83			Y20B	W8B	PTP	Manual random feed mode
Y204	W84			Y20C	W8C	ZRN	Reference position return mode
Y205	W85			Y20D	W8D	AST	Auto initialization mode
Y206	W86			Y20E	W8E		
Y207	W87		Reference position select method	Y20F	W8F		

— — : Reserved for the system.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-4 (PLC4B)

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y210	W90	MEM	Memory mode	Y218	W98	ST	Auto operation "start" command
Y211	W91	T	Tape mode	Y219	W99	* SP	Auto operation "pause" command
Y212	W92		— —	Y21A	W9A	SBK	Single block
Y213	W93	D	MDI mode	Y21B	W9B	* BSL	Block start interlock
Y214	W94		— —	Y21C	W9C	* CSL	Cutting block start interlock
Y215	W95		Direct operation mode ▲	Y21D	W9D	DRN	Dry run
Y216	W96			Y21E	W9E		
Y217	W97			Y21F	W9F	ERD	Error detect

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y220	WA0	NRST1	NC reset 1	Y228	WA8	TLM	Tool length measurement 1
Y221	WA1	NRST2	NC reset 2	Y229	WA9	TLMS	Tool length measurement 2 (L system)
Y222	WA2	RRW	Reset & rewind	Y22A	WAA		Synchronization correction mode
Y223	WA3	* CDZ	Chamfering	Y22B	WAB	PRST	Program restart
Y224	WA4	ARST	Auto restart	Y22C	WAC	PB	Playback
Y225	WA5	GFIN	Gear shift complete	Y22D	WAD	UIT	Macro interrupt
Y226	WA6	FIN1	M function finish 1	Y22E	WAE	RT	Rapid traverse
Y227	WA7	FIN2	M function finish 2	Y22F	WAF		— —

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y230	WB0	ABS	Manual absolute	Y238	—	* KEY1	Data protect key 1
Y231	WB1	DLK	Display lock	Y239	—	* KEY2	Data protect key 2
Y232	WB2		F1-digit speed change valid	Y23A	—	* KEY3	Data protect key 3
Y233	WB3	CRQ	Recalculation request	Y23B	—	—	— —
Y234	—	RHD1	Integration time input 1	Y23C	—	PDISP	Program display during operation
Y235	—	RHD2	Integration time input 2	Y23D	WBD		Inclined axis control valid
Y236	WB6	PIT	PLC interrupt signal	Y23E	WBE		Inclined axis control: No Z axis compensation
Y237	WB7			Y23F	WBF	BDT1	Optional block skip

— — : Reserved for the system.

▲ : For specific manufacturers.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-5 (PLC4B)

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y240	WC0	—	— —	Y248	WC8	HS11	1st handle axis No.
Y241	WC1	—	— —	Y249	WC9	HS12	
Y242	WC2	—	— —	Y24A	WCA	HS14	
Y243	WC3	—	— —	Y24B	WCB	HS18	
Y244	WC4	—	— —	Y24C	WCC	HS116	
Y245	WC5	—	— —	Y24D	WCD		
Y246	WC6	—	— —	Y24E	WCE		
Y247	WC7	—	— —	Y24F	WCF	HS1S	1st handle valid

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y250	WD0	HS21	2nd handle axis No.	Y258	WD8	HS31	3rd handle axis No.
Y251	WD1	HS22					
Y252	WD2	HS24					
Y253	WD3	HS28					
Y254	WD4	HS216					
Y255	WD5			Y25D	WDD		
Y256	WD6			Y25E	WDE		
Y257	WD7	HS2S	2nd handle valid	Y25F	WDF	HS3S	3rd handle valid

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y260	WE0	FBE1	Manual feedrate B valid 1st axis	Y268	WE8	CX11	Manual random feed 1st axis No.
Y261	WE1	FBE2	2nd axis	Y269	WE9	CX12	
Y262	WE2	FBE3	3rd axis	Y26A	WEA	CX14	
Y263	WE3	FBE4	4th axis	Y26B	WEB	CX18	
Y264	WE4	FBE5	5th axis	Y26C	WEC	CX116	
Y265	WE5	FBE6	6th axis	Y26D	WED		(Always "0")
Y266	WE6	FBE7	7th axis	Y26E	WEE		(Always "0")
Y267	WE7	FBE8	8th axis	Y26F	WEF	CX1S	Manual random feed 1st axis valid

— — : Reserved for the system.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-6 (PLC4B)

Device No.			Signal name	Device No.			Signal name
1st sys	2nd sys	Abbrev.		1st sys	2nd sys	Abbrev.	
Y270	WF0	CX21	Manual random feed 2nd axis No.	Y278	WF8	CX31	Manual random feed 3rd axis No.
Y271	WF1	CX22		Y279	WF9	CX32	
Y272	WF2	CX24		Y27A	WFA	CX34	
Y273	WF3	CX28		Y27B	WFB	CX38	
Y274	WF4	CX216		Y27C	WFC	CX316	
Y275	WF5		(Always "0")	Y27D	WFD		(Always "0")
Y276	WF6		(Always "0")	Y27E	WFE		(Always "0")
Y277	WF7	CX2S	Manual random feed 2nd axis valid	Y27F	WFF	CX3S	Manual random feed 3rd axis valid

Device No.			Signal name	Device No.			Signal name
1st sys	2nd sys	Abbrev.		1st SP	2nd SP	Abbrev.	
Y280	W100	CXS1	Smoothing off	Y288	W108	SP1	Spindle override 1
Y281	W101	CXS2	Axis independent	Y289	W109	SP2	Spindle override 2
Y282	W102	CXS3	EX.F/MODAL.F	Y28A	W10A	SP4	Spindle override 4
Y283	W103	CXS4	G0/G1	Y28B	W10B		
Y284	W104	CXS5	MC/WK	Y28C	W10C		
Y285	W105	CXS6	ABS/INC	Y28D	W10D		
Y286	W106	*CXS7	Stop	Y28E	W10E		
Y287	W107	CXS8	Strobe	Y28F	W10F	SPS	Spindle override method select

Device No.			Signal name	Device No.			Signal name
1st SP	2nd SP	Abbrev.		1st sys	2nd sys	Abbrev.	
Y290	W110	GI1	Spindle gear select 1	Y298	W118	OVC	Override cancel
Y291	W111	GI2	Spindle gear select 2	Y299	W119	OVSL	Manual override valid
Y292	W112	—	(Always "0")	Y29A	W11A	AFL	Miscellaneous function lock
Y293	W113			Y29B	W11B		
Y294	W114	SSTP	Spindle stop	Y29C	W11C	TRV	Tap retract
Y295	W115	SSFT	Spindle gear shift	Y29D	W11D	RTN	Reference position retract
Y296	W116	SORC	Oriented spindle speed command	Y29E	W11E		
Y297	W117			Y29F	W11F	QEMG	PLC emergency stop

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-7 (PLC4B)

Device No.			Signal name	Device No.			Signal name
1st sys	2nd sys	Abbrev.		1st sys	2nd sys	Abbrev.	
Y2A0	W120	* FV1	Cutting feedrate override	Y2A8	W128	ROV1	Rapid traverse speed override
Y2A1	W121	* FV2		Y2A9	W129	ROV2	
Y2A2	W122	* FV4		Y2AA	W12A		
Y2A3	W123	* FV8		Y2AB	W12B		
Y2A4	W124	* FV16		Y2AC	W12C		
Y2A5	W125			Y2AD	W12D		
Y2A6	W126	FV2E	2nd cutting feedrate override valid	Y2AE	W12E		
Y2A7	W127	FVS	Cutting feedrate override method select	Y2AF	W12F	ROVS	Rapid traverse speed override method select

Device No.			Signal name	Device No.			Signal name
1st sys	2nd sys	Abbrev.		1st sys	2nd sys	Abbrev.	
Y2B0	W130	* JV1	Manual feedrate	Y2B8	W138	PCF1	Feedrate least increment
Y2B1	W131	* JV2		Y2B9	W139	PCF2	
Y2B2	W132	* JV4		Y2BA	W13A	JSYN	Jog synchronous feed valid
Y2B3	W133	* JV8		Y2BB	W13B	JHAN	Jog•handle synchronous
Y2B4	W134	* JV16		Y2BC	W13C		Each axis manual feedrate B valid
Y2B5	W135			Y2BD	W13D		— —
Y2B6	W136			Y2BE	W13E		— —
Y2B7	W137	JVS	Manual feedrate method select	Y2BF	W13F		— —

Device No.			Signal name	Device No.			Signal name
1st sys	2nd sys	Abbrev.		1st sys	2nd sys	Abbrev.	
Y2C0	W140	MP1	Handle/Incremental feed multiplication	Y2C8	W148	TAL1	Tool alarm 1/Tool-skip tool
Y2C1	W141	MP2		Y2C9	W149	TAL2	Tool alarm 2 (M system)
Y2C2	W142	MP4		Y2CA	W14A	TCEF	Data count valid
Y2C3	W143			Y2CB	W14B	TLFI	Tool life management input (M system)
Y2C4	W144			Y2CC	W14C	TRST	Tool change reset (L system)
Y2C5	W145			Y2CD	W14D		
Y2C6	W146		— —	Y2CE	W14E		
Y2C7	W147	MPS	Handle/Incremental feed multiplication method select	Y2CF	W14F		

— — : Reserved for the system.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-8 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st SP	2nd SP			1st SP	2nd SP		
Y2D0	W150	SRN	Spindle forward run start	Y2D8	W158		
Y2D1	W151	SRI	Spindle reverse run start	Y2D9	W159		
Y2D2	W152	TL1	Torque limit 1	Y2DA	W15A		C axis gain L
Y2D3	W153	TL2	Torque limit 2	Y2DB	W15B		C axis gain H
Y2D4	W154	WRN	Spindle forward run index	Y2DC	W15C		C axis zero point return
Y2D5	W155	WRI	Spindle reverse run index	Y2DD	W15D		
Y2D6	W156	ORC	Spindle orient command	Y2DE	W15E	LRSM	M coil selection
Y2D7	W157	LRSL	L coil selection	Y2DF	W15F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y2E0	—	* PCD1	PLC axis near point detect 1st axis	Y2E8	—	SPSYC	Spindle synchronization cancel
Y2E1	—	* PCD2	PLC axis near point detect 2nd axis	Y2E9	—	SPCMP C	Chuck close
Y2E2	—		— —	Y2EA	—		
Y2E3	—		— —	Y2EB	—		
Y2E4	—	PCH1	PLC axis 1st handle valid	Y2EC	—		
Y2E5	—	PCH2	PLC axis 2nd handle valid	Y2ED	—		
Y2E6	—	PCH3	PLC axis 3rd handle valid	Y2EE	—		
Y2E7	W167			Y2EF	—		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y2F0	W170		— —	Y2F8	—	CRTFN	CRT changeover complete
Y2F1	W171		— —	Y2F9	W179	CSRON	Screen display request
Y2F2	W172		— —	Y2FA	W17A		
Y2F3	W173		— —	Y2FB	W17B	NETST P	MELDASNET sampling stop
Y2F4	W174		— —	Y2FC	—	SMPTR G	Data sampling trigger
Y2F5	W175		— —	Y2FD	—	MTBT	PLC snapshot
Y2F6	W176		— —	Y2FE	—	DISP1	Display changeover \$1
Y2F7	W177		— —	Y2FF	—	DISP2	Display changeover \$2

— — : Reserved for the system.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-9 (PLC4B)

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y300	W180	AZS1	Zero point initialization set mode 1st axis	Y308	W188	ZST1	Zero point initialization set start 1st axis
Y301	W181	AZS2	2nd axis	Y309	W189	ZST2	2nd axis
Y302	W182	AZS3	3rd axis	Y30A	W18A	ZST3	3rd axis
Y303	W183	AZS4	4th axis	Y30B	W18B	ZST4	4th axis
Y304	W184	AZS5	5th axis	Y30C	W18C	ZST5	5th axis
Y305	W185	AZS6	6th axis	Y30D	W18D	ZST6	6th axis
Y306	W186	AZS7	7th axis	Y30E	W18E	ZST7	7th axis
Y307	W187	AZS8	8th axis	Y30F	W18F	ZST8	8th axis

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y310	W190		Current limit mode 1	Y318	W198		Current limit changeover 1st axis
Y311	W191		Current limit mode 2	Y319	W199		2nd axis
Y312	W192		(Same as above, spare)	Y31A	W19A		3rd axis
Y313	W193	LDWT	Load monitor Teaching/ monitor execution ▲	Y31B	W19B		4th axis
Y314	W194		Load monitor Teaching mode select ▲	Y31C	W19C		5th axis
Y315	W195		Load monitor Monitor mode select ▲	Y31D	W19D		6th axis
Y316	W196		Load monitor Alarm reset ▲	Y31E	W19E		7th axis
Y317	W197		Load monitor Warning reset ▲	Y31F	W19F		8th axis

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
Y320	W1A0		Droop release request 1st axis	Y328	W1A8		— —
Y321	W1A1		2nd axis	Y329	W1A9		Ext. workpiece coordinate measurement 2nd axis
Y322	W1A2		3rd axis	Y32A	W1AA		— —
Y323	W1A3		4th axis	Y32B	W1AB		— —
Y324	W1A4		5th axis	Y32C	W1AC		— —
Y325	W1A5		6th axis	Y32D	W1AD		— —
Y326	W1A6		7th axis	Y32E	W1AE		— —
Y327	W1A7		8th axis	Y32F	W1AF		— —

— — : Reserved for the system.

▲ : For specific manufacturers.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-10 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y330	W1B0	DTCH2 1	Control axis detach 2 1st axis	Y338	W1B8		Unclamp complete 1st axis
Y331	W1B1	DTCH2 2	2nd axis	Y339	W1B9		2nd axis
Y332	W1B2	DTCH2 3	3rd axis	Y33A	W1BA		3rd axis
Y333	W1B3	DTCH2 4	4th axis	Y33B	W1BB		4th axis
Y334	W1B4	DTCH2 5	5th axis	Y33C	W1BC		5th axis
Y335	W1B5	DTCH2 6	6th axis	Y33D	W1BD		6th axis
Y336	W1B6	DTCH2 7	7th axis	Y33E	W1BE		7th axis
Y337	W1B7	DTCH2 8	8th axis	Y33F	W1BF		8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y340	W1C0		Each axis reference position return 1st axis	Y348	W1C8	* ZRIT	2nd reference position return interlock
Y341	W1C1		2nd axis	Y349	W1C9		Adaptive control execution ▲
Y342	W1C2		3rd axis	Y34A	W1CA		Small diameter deep hole drilling cycle
Y343	W1C3		4th axis	Y34B	W1CB		— —
Y344	W1C4		5th axis	Y34C	W1CC		INC high-speed retract function valid ▲
Y345	W1C5		6th axis	Y34D	W1CD		Optimum pecking function valid ▲
Y346	W1C6		7th axis	Y34E	W1CE		Load monitor function valid ▲
Y347	W1C7		8th axis	Y34F	W1CF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st SP	2nd SP			1st sys	2nd sys		
Y350	W1D0	SWS	Spindle selection	Y358	W1D8		Waiting ignore
Y351	W1D1			Y359	W1D9		Spindle-spindle polygon cancel
Y352	W1D2			Y35A	W1DA		Synchronous tapping command polarity reversal
Y353	W1D3			Y35B	W1DB		Spindle OFF mode
Y354	W1D4			Y35C	W1DC		
Y355	W1D5			Y35D	W1DD		
Y356	W1D6			Y35E	W1DE		
Y357	W1D7	MPCSL	PLC coil changeover	Y35F	W1DF		

— — : Reserved for the system.

▲ : For specific manufacturers.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-11 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y360	W1E0		Cross machining control request	Y368	W1E8		
			1st axis				
Y361	W1E1		2nd axis	Y369	W1E9		
Y362	W1E2		3rd axis	Y36A	W1EA		
Y363	W1E3		4th axis	Y36B	W1EB		
Y364	W1E4		5th axis	Y36C	W1EC		
Y365	W1E5		6th axis	Y36D	W1ED		
Y366	W1E6		7th axis	Y36E	W1EE		
Y367	W1E7		8th axis	Y36F	W1EF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y370	W1F0		Position switch 1 interlock	Y378	W1F8		Barrier valid (left)
Y371	W1F1		Position switch 2 interlock	Y379	W1F9		Barrier valid (right)
Y372	W1F2		Position switch 3 interlock	Y37A	W1FA		Tool presetter sub-side valid
Y373	W1F3		Position switch 4 interlock	Y37B	W1FB		
Y374	W1F4		Position switch 5 interlock	Y37C	W1FC		
Y375	W1F5		Position switch 6 interlock	Y37D	W1FD		
Y376	W1F6		Position switch 7 interlock	Y37E	W1FE		
Y377	W1F7		Position switch 8 interlock	Y37F	W1FF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st SP	2nd SP		
Y380	—		Door open	Y388	J588		Magnetic bearing servo ON command
Y381	J581		Door open II	Y389	J589		Magnetic bearing tool unclamp
Y382	J582		Door open signal input (spindle speed monitor)	Y38A	J58A		— —
Y383	J583		Door interlock spindle speed clamp	Y38B	J58B		— —
Y384	—	RPN	Remote program input start	Y38C	J58C		— —
Y385	—		Tool ID data read ▲	Y38D	J58D		— —
Y386	—		Tool ID data write ▲	Y38E	J58E		— —
Y387	—		Tool ID data erase ▲	Y38F	J58F		— —

— — : Reserved for the system.

▲ : For specific manufacturers.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-12 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y390	—		Tool IC new read ▲	Y398	—	SPSY	Spindle synchronous control
Y391	—		Tool IC exchange read ▲	Y399	—	SPPHS	Spindle phase synchronous control
Y392	—			Y39A	—		Spindle synchronous rotation direction
Y393	—			Y39B	—	SSPHM	Phase shift calculation request
Y394	—			Y39C	—	SSPHF	Phase offset request
Y395	—		— —	Y39D	—	SPDRP O	Error temporary cancel
Y396	—			Y39E	—		
Y397	—		— —	Y39F	—		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y3A0	J5A0		PLC skip 1	Y3A8	J5A8	SYNC1	Synchronous control request 1st axis
Y3A1	J5A1		PLC skip 2	Y3A9	J5A9	SYNC2	2nd axis
Y3A2	J5A2		PLC skip 3	Y3AA	J5AA	SYNC3	3rd axis
Y3A3	J5A3		PLC skip 4	Y3AB	J5AB	SYNC4	4th axis
Y3A4	J5A4		PLC skip 5	Y3AC	J5AC	SYNC5	5th axis
Y3A5	J5A5		PLC skip 6	Y3AD	J5AD	SYNC6	6th axis
Y3A6	J5A6		PLC skip 7	Y3AE	J5AE	SYNC7	7th axis
Y3A7	J5A7		PLC skip 8	Y3AF	J5AF	SYNC8	8th axis

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y3B0	J5B0	PILE1	Superimposition control request 1st axis	Y3B8	—		Door open II 1-2
Y3B1	J5B1	PILE2	2nd axis	Y3B9	—		— —
Y3B2	J5B2	PILE3	3rd axis	Y3BA	—		Door open signal input 1-2
Y3B3	J5B3	PILE4	4th axis	Y3BB	—		— —
Y3B4	J5B4	PILE5	5th axis	Y3BC	J5BC		
Y3B5	J5B5	PILE6	6th axis	Y3BD	J5BD		
Y3B6	J5B6	PILE7	7th axis	Y3BE	J5BE		
Y3B7	J5B7	PILE8	8th axis	Y3BF	J5BF		

— — : Reserved for the system.

▲ : For specific manufacturers.

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-13 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y3C0	J5C0			Y3C8	J5C8		
Y3C1	J5C1			Y3C9	J5C9		
Y3C2	J5C2			Y3CA	J5CA		
Y3C3	J5C3			Y3CB	J5CB		
Y3C4	J5C4			Y3CC	J5CC		
Y3C5	J5C5			Y3CD	J5CD		
Y3C6	J5C6			Y3CE	J5CE		
Y3C7	J5C7			Y3CF	J5CF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y3D0	J5D0			Y3D8	J5D8		
Y3D1	J5D1			Y3D9	J5D9		
Y3D2	J5D2			Y3DA	J5DA		
Y3D3	J5D3			Y3DB	J5DB		
Y3D4	J5D4			Y3DC	J5DC		
Y3D5	J5D5			Y3DD	J5DD		
Y3D6	J5D6			Y3DE	J5DE		
Y3D7	J5D7			Y3DF	J5DF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y3E0	J5E0			Y3E8	J5E8		
Y3E1	J5E1			Y3E9	J5E9		
Y3E2	J5E2			Y3EA	J5EA		
Y3E3	J5E3			Y3EB	J5EB		
Y3E4	J5E4			Y3EC	J5EC		
Y3E5	J5E5			Y3ED	J5ED		
Y3E6	J5E6			Y3EE	J5EE		
Y3E7	J5E7			Y3EF	J5EF		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
Y3F0	J5F0			Y3F8	J5F8		
Y3F1	J5F1			Y3F9	J5F9		
Y3F2	J5F2			Y3FA	J5FA		
Y3F3	J5F3			Y3FB	J5FB		
Y3F4	J5F4			Y3FC	J5FC		
Y3F5	J5F5			Y3FD	J5FD		
Y3F6	J5F6			Y3FE	J5FE		
Y3F7	J5F7			Y3FF	J5FF		

3. PLC INTERFACE OUTPUT Y

PLC → CNC (PLC4B)

Table 4-3-14 (PLC4B)

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
J600	J610	SWS	Spindle selection	J608	J618	GFIN	Gear shift complete
J601	J611			J609	J619		
J602	J612			J60A	J61A		
J603	J613			J60B	J61B		
J604	J614			J60C	J61C		
J605	J615			J60D	J61D		
J606	J616			J60E	J61E		
J607	J617	MPCSL	PLC coil changeover	J60F	J61F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
S020	S060	SP1	Spindle override 1	S028	S068	G11	Spindle gear selection input 1
S021	S061	SP2	Spindle override 2	S029	S069	G12	Spindle gear selection input 2
S022	S062	SP4	Spindle override 4	S02A	S06A	—	(Always "0")
S023	S063			S02B	S06B		
S024	S064			S02C	S06C	SSTP	Spindle stop
S025	S065			S02D	S06D	SSFT	Spindle gear shift
S026	S066			S02E	S06E	SORC	Oriented spindle speed command
S027	S067	SPS	Spindle override method select	S02F	S06F		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
S030	S070	SRN	Spindle forward run start	S038	S078		
S031	S071	SRI	Spindle reverse run start	S039	S079		
S032	S072	TL1	Torque limit 1	S03A	S07A		C axis gain L
S033	S073	TL2	Torque limit 2	S03B	S07B		C axis gain H
S034	S074	WRN	Spindle forward run index	S03C	S07C		C axis reference position return
S035	S075	WRI	Spindle reverse run index	S03D	S07D		
S036	S076	ORC	Spindle orientation command	S03E	S07E	LRSM	M coil selection
S037	S077	LRSL	L coil selection	S03F	S07F		

4. PLC INTERFACE OUTPUT R

The spindle related devices are described in the section "5. Other PLC Interfaces".

PLC → CNC

Table 4-4-1

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R100	—	AO1	Analog output	R108	R308		Spindle command rotation speed output
R101	—	AO2	Analog output	R109	R309		
R102	—	AO3	Analog output	R110	R310	SLSP	Spindle command selection
R103	—	AO4	Analog output	R111	R311		
R104	—		— —	R112	—		KEY OUT 1
R105	—		— —	R113	R313		
R106	—		— —	R114	R314		
R107	—		— —	R115	R315		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R116	R316		Load monitor Axis selection ▲	R124	R324		Encoder selection
R117	R317		Load monitor Load change rate detection axis ▲	R125	R325		C axis selection
R118	R318		Load monitor Teaching data sub-No. ▲	R126	R326		
R119	R319		Adaptive control Basic axis selection ▲	R127	R327		
R120	R320		Each axis reference position select	R128	R328		
R121	R321		Each axis reference position return interlock (ATC time reduction)	R129	R329		
R122	R322		Editing state input ▲	R130	R330		PLC interrupt program number
R123	R323			R131	R331		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R132	R332		1st cutting feedrate override	R140	R340		Handle/Incremental feed multiplication
R133	R333		2nd cutting feedrate override	R141	R341		
R134	R334		Rapid traverse override	R142	R342		Manual random feed 1st axis movement data
R135	R335	CHPOV	Chopping override	R143	R343		
R136	R336		Manual feedrate	R144	R344		Manual random feed 2nd axis movement data
R137	R337				R145	R345	
R138	R338		Manual feedrate B	R146	R346		Manual random feed 3rd axis movement data
R139	R339				R147	R347	

— — : Reserved for the system.

▲ : For specific manufacturers.

4. PLC INTERFACE OUTPUT R

PLC → CNC

Table 4-4-2

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R148	R348		S analog override	R156	R356		OT ignored
R149	R349		Multi-point orientation position data	R157	R357		Near-point ignored
R150	R350		Tool group number designation	R158	—		Alarm message I/F 1
R151	R351			R159	—		Alarm message I/F 2
R152	—		Load meter 1	R160	—		Alarm message I/F 3
R153	—			R161	—		Alarm message I/F 4
R154	—		Load meter 2	R162	—		Operator message I/F
R155	—			—	R363		Board communication state ▲

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R164	R364		— —	R172	—		User macro output #1132 (Note 1)
R165	R365		— —	R173	—		
R166	R366		— —	R174	—		User macro output #1133
R167	R367			R175	—		
R168	R368			R176	—		User macro output #1134
R169	R369			R177	—		
R170	R370		Search & start program No.	R178	—		User macro output #1135
R171	R371			R179	—		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R180	—		Add-on (expansion) operation board output 1	R188	R388		Special display unit interface
R181	—		Add-on (expansion) operation board output 2	R189	R389		— —
R182	—		Add-on (expansion) operation board output 3	R190	R390		— —
R183	—		— — (spare)	R191	R391		
R184	R384			R192	R392		Ext. workpiece coordinate offset measurement tool compensation No. (Note 2)
R185	R385		Current limit changeover	R193	R393		
R186	R386		Wear compensation No. (tool presetter)	R194	R394		Ext. workpiece coordinate offset measurement tool No. (Note 2)
R187	R387		— —	R195	R395		

— — : Reserved for the system.

▲ : For specific manufacturers.

(Note 1) #1132 to #1135 are input signals to the PLC, and the direction is opposite of the other registers.

(Note 2) When the chuck barrier is checked, these are the "Selected tool compensation No. (main):R192, 193" and the "Selected tool No.(main):R194, 195"

4. PLC INTERFACE OUTPUT R

PLC → CNC

Table 4-4-3

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
R196	—		User PLC version code				
R197	—						
R198	—						
R199	—						

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
R400	R416		Each axis manual feedrate B 1st axis	R408	R424		Each axis manual feedrate B 5th axis
R401	R417			R409	R425		
R402	R418		Each axis manual feedrate B 2nd axis	R410	R426		Each axis manual feedrate B 6th axis
R403	R419			R411	R427		
R404	R420		Each axis manual feedrate B 3rd axis	R412	R428		Each axis manual feedrate B 7th axis
R405	R421			R413	R429		
R406	R422		Each axis manual feedrate B 4th axis	R414	R430		Each axis manual feedrate B 8th axis
R407	R423			R415	R431		

Device No.				Device No.			
1st sys	2nd sys	Abbrev.	Signal name	1st sys	2nd sys	Abbrev.	Signal name
				R435	R436		Synchronous control operation method selection

4. PLC INTERFACE OUTPUT R

PLC → CNC

Table 4-4-4

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R438	—		Tool I/D R/W pot No. designation ▲	R446	—		Spindle synchronous control Basic spindle select
R439	—		Large diameter tool information ▲	R447	—		Synchronous spindle select
R440	—		Tool weight (spindle tool) ▲	R448	—		Phase shift amount
R441	—		Tool weight (standby tool) ▲	R449	—		
R442	—		Unset tool information ▲	R450	—		
R443	—		Tool IC communication process results ▲	R451	—		
R444	—		— —	R452	—		
R445	—		— —	R453	—		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R560	R568		Ext. machine coordinate system compensation data				
			1st axis				
R561	R569		2nd axis				
R562	R570		3rd axis				
R563	R571		4th axis				
R564	R572		5th axis				
R565	R573		6th axis				
R566	R574		7th axis				
R567	R575		8th axis				

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R627	—		Skip retract valid				
R628	—		Skip retract amount				
R629	—						
R630	—		Skip retract speed				
R631	—						

— — : Reserved for the system.

▲ : For specific manufacturers.

4. PLC INTERFACE OUTPUT R

PLC → CNC

Table 4-4-5

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R650	—		Direct screen selection	R658	—		APLC version
R651	—		Direct screen selection	R659	—		
R652	—		Direct screen selection				
R653	—		Direct screen selection	R669	—		Cutting performance estimation I/F ▲
R656	—		APLC version				
R657	—						

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R1000	R1050	—	Selected tool compensation No.(sub) wear No. (sub)	R1008	R1058	—	— —
R1001	R1051	—		R1009	R1059		
R1002	R1052	—		R1010	R1060		
R1003	R1053	—		R1011	R1061		
R1004	R1054	—	Tool mounting information (1 to 16)	R1012	R1062		
R1005	R1055	—	Tool mounting information (17 to 32)	R1013	R1063		
R1006	R1056	—	— —	R1014	R1064		
R1007	R1057	—	— —	R1015	R1065		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R1400	—		Remote program input No. (password No.)	R1896	—		Setup parameter lock I/F
R1401	—						
R1402							
R1403	—						
R1404	—		MELDAS-NET input				

— — : Reserved for the system.

▲ : For specific manufacturers.

4. PLC INTERFACE OUTPUT R

PLC → CNC

Table 4-4-6

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
R4600	R4620		Spindle command rotation speed output	R4608	R4628		
R4601	R4621			R4609	R4629		
R4602	R4622			R4610	R4630		
R4603	R4623			R4611	R4631		
R4604	R4624		S-analog override	R4612	R4632		
R4605	R4625		Multi-point orientation position data	R4613	R4633		
R4606	R4626	SLSP	Spindle selection signal	R4614	R4634		
R4607	R4627			R4615	R4635		

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
3rd SP	4th SP			3rd SP	4th SP		
R4616	R4636						
R4617	R4637						
R4618	R4638						
R4619	R4639						

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R4732			User PLC version code 2				
R4733							
R4734							
R4735							
R4736							
R4737							
R4738							

Device No.		Abbrev.	Signal name	Device No.		Abbrev.	Signal name
1st sys	2nd sys			1st sys	2nd sys		
R5461	R5470		Tool life management data sort ▲				
R5461	R5471		No. of registered tool life management items ▲				

▲ : For specific manufacturers.

5. OTHER PLC INTERFACES

(1) IO link

Table 4-6-1

Device No.	Master side	Slave side
Output data		
R1460 to R1467	Output 0 (common for all slaves)	Output (each slave axis)
R1468 to R1475	Output 1 (slave station 1)	Not used
R1476 to R1483	Output 2 (slave station 2)	Not used
R1484 to R1491	Output 3 (slave station 3)	Not used
R1492 to R1499	Output 4 (slave station 4)	Not used
Input data		
R1560 to R1567	Not used	Input 0 (common for all slaves)
R1568 to R1575	Input 1 (slave station 1)	Input (each slave axis)
R1576 to R1583	Input 2 (slave station 2)	Not used
R1584 to R1591	Input 3 (slave station 3)	Not used
R1592 to R1599	Input 4 (slave station 4)	Not used
R1559	IO link communication state	

(2) M-NET

Table 4-6-2

Device No.	Signal name
X380 to X47F	Serial input
Y400 to Y4FF	Serial output
Serial connection operation state	
R1880	No. of framing error occurrences
R1881	No. of parity error occurrences
R1882	No. of overrun error occurrences
R1883	No. of illegal transmission data detections
R1884	Error No. register
R1885	No. of illegal transmission data detections
R1886	Reception preparation sequence
R1887	Reception preparation sequence
R1888	Reception preparation sequence
R1889	Reception preparation sequence

(3) MELSEC bus connection

Table 4-6-3

Device No.	Signal name
X380 to X47F	Input
R4000 to R4095	
Y400 to Y4FF	Output
R4200 to R4327	
R1880	Current timeout counter
R1881	Maximum timeout counter after power ON
R1882	Maximum timeout counter after system startup (backed up)

(4) CC-Link

Table 4-6-4

Device name	Device range
X	X0 to X1FF (Avoid overlapping with the range for real I/O)
Y	Y0 to Y1FF (Avoid overlapping with the range for real I/O)
M	M0 to M8191
L	L0 to L255
D	D0 to D1023
R	R4000 to R4499, R6400 to R7199

Input No.	Signal name	Output No.	Signal name
X480	Unit error	Y500	Refresh command
X481	Data link state at host station	Y501	(Prohibited to use)
X482	Parameter setting status	Y502	
X483	Data link status at other station	Y503	
X484	Unit reset acceptance completed	Y504	Unit reset request
X485	(Prohibited to use)	Y505	(Prohibited to use)
X486	Data link startup normal completion	Y506	Data link start request
X487	Data link startup error completion	Y507	(Prohibited to use)
X488	Data link startup by EEPROM parameter normal completion	Y508	Data link startup request from EEPROM parameter
X489	Data link startup by EEPROM parameter error completion	Y509	(Prohibited to use)
X48A	Parameter registration to EEPROM normal completion	Y50A	Parameter registration request to EEPROM
X48B	Parameter registration to EEPROM error completion	Y50B	(Prohibited to use)
X48C		Y50C	
X48D	(Prohibited to use)	Y50D	
X48E		Y50E	
X48F	Unit ready	Y50F	
X490		Y510	
X491		Y511	
X492		Y512	
X493		Y513	
X494		Y514	
X495		Y515	
X496		Y516	
X497	(Prohibited to use)	Y517	
X498		Y518	
X499		Y519	
X49A		Y51A	
X49B		Y51B	
X49C		Y51C	
X49D		Y51D	
X49E		Y51E	
X49F		Y51F	

5. OTHER PLC INTERFACES

(5) J2-CT link

Table 4-6-5

Device No.	bit	Abbrev.	Signal name
			R1784

Signal name	J2CT control command 4	J2CT control command 3	J2CT control command 2	J2CT control command 1	J2CT control command L	J2CT control command H
Abbrev.	CTCM4	CTCM3	CTCM2	CTCM1	CTCML	CTCMH
J2CT 1st axis	R1700	R1701	R1702	R1703	R1704	R1705
J2CT 2nd axis	R1706	R1707	R1708	R1709	R1710	R1711
J2CT 3rd axis	R1712	R1713	R1714	R1715	R1716	R1717
J2CT 4th axis	R1718	R1719	R1720	R1721	R1722	R1723

Device No.	bit	Abbrev.	Signal name
			R1656
	bit1		J2CT 2nd axis in operation adjustment mode
	bit2		J2CT 3rd axis in operation adjustment mode
	bit3		J2CT 4th axis in operation adjustment mode

Signal name	J2CT status 4	J2CT status 3	J2CT status 2	J2CT status 1
Abbrev.	CTST4	CTST3	CTST2	CTST1
J2CT 1st axis	R1600	R1601	R1602	R1603
J2CT 2nd axis	R1604	R1605	R1606	R1607
J2CT 3rd axis	R1608	R1609	R1610	R1611
J2CT 4th axis	R1612	R1613	R1614	R1615

(6) Other file registers (R)

Table 4-6-6

Device No.	Signal name	
	M system	L system
R700 to R999	Computer link interfaces	
R2800 to R2895	PLC constant parameters (corresponds to parameters #6301 to #6348)	
R2900 to R2947	PLC bit selection parameters (corresponds to parameters #6401 to #6496)	
R2950 to R2999	ATC command control information	-
R2970, R2971	-	Tool compensation No. for tool length measurement 2
R3000 to R3719	ATC registration tools	-
R3000 to R3639	-	Life management data (\$1, \$2)
R3720 to R3735	Life management interfaces	-
R4400 to R4449	Expansion bit selection parameters (corresponds to parameters #6448 to #6596)	
R4900 to R4995	Expansion PLC constant parameters (corresponds to parameters #6349 to #6396)	
R5000 to R5099	Special table interfaces	
R5480 to R6279	-	Tool life management data with spare tool

5. OTHER PLC INTERFACES

(7) Other inputs/outputs (X, Y)

Table 4-6-7

Device No.	Signal name
X140 to X15F	PLC switch input 1 to 32
X178 to X17F	Skip input 1 to 8 for monitor
Y160 to Y17F	PLC switch for reversed display 1 to 32

(8) Fixed (semi-fixed) devices

Table 4-6-8

Device No.	Signal name
X108	NC reset Reset is input (Y222, etc.) to the NC based on this signal.
X18 to X1B	Reference position return near-point detection 1 to 4
X20 to X23	Stroke end (-) 1 to 4
X28 to X2B	Stroke end (+) 1 to 4
X5C to X5F	Reference position return near-point detection 5 to 8
X64 to X67	Stroke end (-) 5 to 8
X6C to X6F	Stroke end (+) 5 to 8

(9) Maintenance

Table 4-6-9

Device No.	Signal name
R1850	CRC count (servo #1)
R1851	CRC count (servo #2)
R1852	Address illegal (servo #1)
R1853	Address illegal (servo #2)
R1854	CRC count (display unit)
R1855	Address illegal (display unit)

(10) Software timer

Table 4-6-10

Device No.	Signal name
R1200 to R1224	Expansion timer coil (corresponds to #6600 to #6999)
R1250 to R1274	Expansion timer contact (corresponds to #6600 to #6999)

5. OTHER PLC INTERFACES

(11) Spindle related devices

CNC -> PLC (GX Developer)

Table 4-6-11

Device No.				Abbrev.	Signal name
1st sys	2nd sys				
X1C4	X504				Power OFF request (spindle regeneration circuit error)
X234	X574			SF1	S function strobe 1
X235	X575			SF2	S function strobe 2
X236	X576			SF3	S function strobe 3
X237	X577			SF4	S function strobe 4
X2A0	X5E0				In polygon mode (Spindle-NC axis)
X2A2	X5E2				In polygon mode (Spindle-Spindle)
X2A3	X5E3				Spindle-spindle polygon synchronization complete
X308	—			SPSYN1	In spindle synchronous control
X309	—			FSPRV	Spindle rotation speed synchronization complete
X30A	—			FSPPH	Spindle phase synchronization complete
X30B	—			SPSYN2	In spindle synchronous control 2 (D)
X30E	—			SPCMP	Chuck close confirmation

Device No.				Abbrev.	Signal name
1st SP	2nd SP	3rd SP	4th SP		
X1D0	X510	XA48	XA68		— —
X1D1	X511	XA49	XA69		— —
X1D5	X515	XA4D	XA6D	SD2	Speed detect 2
X1D6	X516	XA4E	XA6E	MCSA	In M coil selected
X1D7	X517	XA4F	XA6F		Index positioning complete
X20C	X54C	XA40	XA60	SUPP	Spindle rotation speed upper limit over
X20D	X54D	XA41	XA61	SLOW	Spindle rotation speed lower limit over
X214	X554	XA42	XA62	SIGE	S-analog gear No. illegal
X215	X555	XA43	XA63	SOVE	S-analog max./min. command value over
X216	X556	XA44	XA64	SNGE	S-analog no gear selected
X225	X565	XA45	XA65	GR1	Spindle gear shift 1
X226	X566	XA46	XA66	GR2	Spindle gear shift 2
X227	X567	XA47	XA67	—	(Always "0")
X240	X580	XA50	XA70		Spindle 2nd in-position
X241	X581	XA51	XA71	CDO	Current detect
X242	X582	XA52	XA72	VRO	Speed detect
X243	X583	XA53	XA73	FLO	In spindle alarm
X244	X584	XA54	XA74	ZSO	Zero speed
X245	X585	XA55	XA75	USO	Up-to-speed
X246	X586	XA56	XA76	ORAO	Spindle in-position
X247	X587	XA57	XA77	LCSA	In L coil selected
X248	X588	XA58	XA78	SMA	Spindle ready-ON
X249	X589	XA59	XA79	SSA	Spindle servo-ON
X24A	X58A	XA5A	XA7A	SEMG	Spindle emergency stop

5. OTHER PLC INTERFACES

Device No.				Abbrev.	Signal name
1st SP	2nd SP	3rd SP	4th SP		
X24B	X58B	XA5B	XA7B	SSRN	Spindle forward run
X24C	X58C	XA5C	XA7C	SSRI	Spindle reverse run
X24D	X58D	XA5D	XA7D		Z-phase passed
X24E	X58E	XA5E	XA7E	SIMP	Position loop in-position
X24F	X58F	XA5F	XA7F	STLQ	Torque limit
X2C8	X608	X940	X950	ENB	Spindle enable
X318	X9D8				In magnetic bearing ready ON
X319	X9D9				In magnetic bearing servo ON
X31C	X9DC				In magnetic bearing warning
X31F	X9DF				In magnetic bearing alarm

— — : Reserved for the system.

CNC -> PLC (PLC4B)

Table 4-6-11

Device No.				Abbrev.	Signal name
1st sys	2nd sys				
X1C4	U44				Power OFF request (spindle regeneration circuit error)
X234	UB4			SF1	S function strobe 1
X235	UB5			SF2	S function strobe 2
X236	UB6			SF3	S function strobe 3
X237	UB7			SF4	S function strobe 4
X2A0	U120				In polygon mode (Spindle-NC axis)
X2A2	U122				In polygon mode (Spindle-Spindle)
X2A3	U123				Spindle-spindle polygon synchronization complete
X308	—			SPSYN1	In spindle synchronous control
X309	—			FSPRV	Spindle rotation speed synchronization complete
X30A	—			FSPPH	Spindle phase synchronization complete
X30B	—			SPSYN2	In spindle synchronous control 2 (D)
X30E	—			SPCMP	Chuck close confirmation

Device No.				Abbrev.	Signal name
1st SP	2nd SP	3rd SP	4th SP		
X1D0	U50	S008	S048		— —
X1D1	U51	S009	S049		— —
X1D5	U55	S00D	S04D	SD2	Speed detect 2
X1D6	U56	S00E	S04E	MCSA	In M coil selected
X1D7	U57	S00F	S04F		Index positioning complete
X20C	U8C	S000	S040	SUPP	Spindle rotation speed upper limit over
X20D	U8D	S001	S041	SLOW	Spindle rotation speed lower limit over
X214	U94	S002	S042	SIGE	S-analog gear No. illegal
X215	U95	S003	S043	SOVE	S-analog max./min. command value over
X216	U96	S004	S044	SNGE	S-analog no gear selected

— — : Reserved for the system.

5. OTHER PLC INTERFACES

Device No.				Abbrev.	Signal name
1st SP	2nd SP	3rd SP	4th SP		
X225	UA5	S005	S045	GR1	Spindle gear shift 1
X226	UA6	S006	S046	GR2	Spindle gear shift 2
X227	UA7	S007	S047	—	(Always "0")
X240	UC0	S010	S050		Spindle 2nd in-position
X241	UC1	S011	S051	CDO	Current detect
X242	UC2	S012	S052	VRO	Speed detect
X243	UC3	S013	S053	FLO	In spindle alarm
X244	UC4	S014	S054	ZSO	Zero speed
X245	UC5	S015	S055	USO	Up-to-speed
X246	UC6	S016	S056	ORAO	Spindle in-position
X247	UC7	S017	S057	LCSA	In L coil selected
X248	UC8	S018	S058	SMA	Spindle ready-ON
X249	UC9	S019	S059	SSA	Spindle servo-ON
X24A	UCA	S01A	S05A	SEMG	Spindle emergency stop
X24B	UCB	S01B	S05B	SSRN	Spindle forward run
X24C	UCC	S01C	S05C	SSRI	Spindle reverse run
X24D	UCD	S01D	S05D		Z-phase passed
X24E	UCE	S01E	S05E	SIMP	Position loop in-position
X24F	UCF	S01F	S05F	STLQ	Torque limit
X2C8	U148	I300	I310	ENB	Spindle enable
X318	I398				In magnetic bearing ready ON
X319	I399				In magnetic bearing servo ON
X31C	I39C				In magnetic bearing warning
X31F	I39F				In magnetic bearing alarm

5. OTHER PLC INTERFACES

CNC → PLC

Device No.				Abbrev.	Signal name
1st sys	2nd sys				
R28	R228				S code data 1
R29	R229				
R30	R230				S code data 2
R31	R231				
R32	R232				S code data 3
R33	R233				
R34	R234				S code data 4
R35	R235				
R474	—				Spindle synchronous control Phase error output
R475	—				Spindle synchronous control Phase error 1 (degree) (including shift calc.)
R476	—				Spindle synchronous control Phase error 2 (degree) (excluding shift calc.)
R477	—				Spindle synchronous control Phase error monitor
R478	—				Spindle synchronous control (lower limit) Phase error monitor
R479	—				Spindle synchronous control (upper limit) Phase error monitor
R490	—				Spindle synchronous control Phase offset data

Device No.				Abbrev.	Signal name
1st SP	2nd SP	3rd SP	4th SP		
R8	R208	R4500	R4520		Spindle command rotation speed input
R9	R209	R4501	R4521		
R10	R210	R4502	R4522		Spindle command final data (rotation speed)
R11	R211	R4503	R4523		
R12	R212	R4504	R4524		Spindle command final data (12-bit binary)
R13	R213	R4505	R4525		
R18	R218	R4506	R4526		Spindle actual speed
R19	R219	R4507	R4527		

5. OTHER PLC INTERFACES

PLC → CNC (GX Developer)

Device No.				Abbrev.	Signal name
1st sys	2nd sys				
Y1FC	Y5BC				Spindle orientation complete standby valid (ATC high-speed)
Y2E8	—			SPSYC	Spindle synchronous control cancel
Y2E9	—			SPCMPC	Chuck close
Y359	Y719				Spindle-spindle polygon cancel
Y35A	Y71A				Synchronized tapping command polarity reversal
Y382	YCC2				Door open signal input (spindle speed monitor)
Y383	YCC3				Door interlock spindle speed clamp
Y398	—			SPSY	Spindle synchronous control
Y399	—			SPPHS	Spindle phase synchronous control
Y39A	—				Spindle synchronous rotation direction
Y39B	—			SSPHM	Phase shift calculation request
Y39C	—			SSPHF	Phase offset request
Y39D	—			SRDRPO	Error temporary cancel

Device No.				Abbrev.	Signal name
1st SP	2nd SP	3rd SP	4th SP		
Y225	Y5E5	YD48	YD58	GFIN	Gear shift complete
Y288	Y648	YD80	YDA0	SP1	Spindle override 1
Y289	Y649	YD81	YDA1	SP2	Spindle override 2
Y28A	Y64A	YD82	YDA2	SP4	Spindle override 4
Y28F	Y64F	YD87	YDA7	SPS	Spindle override method select
Y290	Y650	YD88	YDA8	GI1	Spindle gear select 1
Y291	Y651	YD89	YDA9	GI2	Spindle gear select 2
Y292	Y652	YD8A	YDAA	—	(Always "0")
Y294	Y654	YD8C	YDAC	SSTP	Spindle stop
Y295	Y655	YD8D	YDAD	SSFT	Spindle gear shift
Y296	Y656	YD8E	YDAE	SORC	Oriented spindle speed command
Y2D0	Y690	YD90	YDB0	SRN	Spindle forward run start
Y2D1	Y691	YD91	YDB1	SRI	Spindle reverse run start
Y2D2	Y692	YD92	YDB2	TL1	Torque limit 1
Y2D3	Y693	YD93	YDB3	TL2	Torque limit 2
Y2D4	Y694	YD94	YDB4	WRN	Spindle forward run index
Y2D5	Y695	YD95	YDB5	WRI	Spindle reverse run index
Y2D6	Y696	YD96	YDB6	ORC	Spindle orient command
Y2D7	Y697	YD97	YDB7	LRSL	L coil selection
Y2DA	Y69A	YD9A	YDBA		C axis gain L
Y2DB	Y69B	YD9B	YDBB		C axis gain H
Y2DC	Y69C	YD9C	YDBC		C axis zero point return
Y2DE	Y69E	YD9E	YDBE	LRSM	M coil selection
Y350	Y710	YD40	YD50	SWS	Spindle selection
Y357	Y717	YD47	YD57	MPCSL	PLC coil changeover

5. OTHER PLC INTERFACES

Device No.				Abbrev.	Signal name
1st SP	2nd SP	3rd SP	4th SP		
Y388	YCC8				Magnetic bearing servo ON command
Y389	YCC9				Magnetic bearing tool clamp
Y38A	YCCA				— —
Y38B	YCCB				— —
Y38C	YCCC				— —
Y38D	YCCD				— —
Y38E	YCCE				— —
Y38F	YCCF				— —

PLC → CNC (PLC4B)

Device No.				Abbrev.	Signal name
1st sys	2nd sys				
Y1FC	W7C				Spindle orientation complete standby valid (ATC high-speed)
Y2E8	—			SPSYC	Spindle synchronous control cancel
Y2E9	—			SPCMPC	Chuck close
Y359	W1D9				Spindle-spindle polygon cancel
Y35A	W1DA				Synchronized tapping command polarity reversal
Y382	J582				Door open signal input (spindle speed monitor)
Y383	J583				Door interlock spindle speed clamp
Y398	—			SPSY	Spindle synchronous control
Y399	—			SPPHS	Spindle phase synchronous control
Y39A	—				Spindle synchronous rotation direction
Y39B	—			SSPHM	Phase shift calculation request
Y39C	—			SSPHF	Phase offset request
Y39D	—			SRDRPO	Error temporary cancel

Device No.				Abbrev.	Signal name
1st SP	2nd SP	3rd SP	4th SP		
Y225	WA5	J608	J618	GFIN	Gear shift complete
Y288	W108	S020	S060	SP1	Spindle override 1
Y289	W109	S021	S061	SP2	Spindle override 2
Y28A	W10A	S022	S062	SP4	Spindle override 4
Y28F	W10F	S027	S067	SPS	Spindle override method select
Y290	W110	S028	S068	GI1	Spindle gear select 1
Y291	W111	S029	S069	GI2	Spindle gear select 2
Y292	W112	S02A	S06A	—	(Always "0")
Y294	W114	S02C	S06C	SSTP	Spindle stop
Y295	W115	S02D	S06D	SSFT	Spindle gear shift
Y296	W116	S02E	S06E	SORC	Oriented spindle speed command
Y2D0	W150	S030	S070	SRN	Spindle forward run start
Y2D1	W151	S031	S071	SRI	Spindle reverse run start
Y2D2	W152	S032	S072	TL1	Torque limit 1
Y2D3	W153	S033	S073	TL2	Torque limit 2

5. OTHER PLC INTERFACES

Device No.				Abbrev.	Signal name
1st SP	2nd SP	3rd SP	4th SP		
Y2D4	W154	S034	S074	WRN	Spindle forward run index
Y2D5	W155	S035	S075	WRI	Spindle reverse run index
Y2D6	W156	S036	S076	ORC	Spindle orient command
Y2D7	W157	S037	S077	LRSL	L coil selection
Y2DA	W15A	S03A	S07A		C axis gain L
Y2DB	W15B	S03B	S07B		C axis gain H
Y2DC	W15C	S03C	S07C		C axis zero point return
Y2DE	W15E	S03E	S07E	LRSM	M coil selection
Y350	W1D0	J600	J610	SWS	Spindle selection
Y357	W1D7	J607	J617	MPCSL	PLC coil changeover
Y388	J588				Magnetic bearing servo ON command
Y389	J589				Magnetic bearing tool clamp
Y38A	J58A				— —
Y38B	J58B				— —
Y38C	J58C				— —
Y38D	J58D				— —
Y38E	J58E				— —
Y38F	J58F				— —

PLC → CNC

Device No.				Abbrev.	Signal name
1st Sys	2nd Sys				
R124	R324				Encoder selection
R446	—				Spindle synchronous control Basic spindle select
R447	—				Synchronous spindle select
R448	—				Phase shift amount

Device No.				Abbrev.	Signal name
1st SP	2nd SP	3rd SP	4th SP		
R108	R308	R4600	R4620		Spindle command rotation speed output
R109	R309	R4601	R4621		
R110	R310	R4606	R4626	SLSP	Spindle command selection
R148	R348	R4604	R4624		S analog override
R149	R349	R4605	R4625		Multi-point orientation position data

Revision History

Date of revision	Manual No.	Revision details
Apr. 2002	BNP-B2229B	First edition created.
Feb. 2003	BNP-B2229C	<ul style="list-style-type: none">• Servo alarm and spindle alarm names were standardized.• Servo parameters were overall reviewed. (Chapter 7 to 9 → Chapter 7)• Revisions to comply with M60S Series Version B3• Mistakes corrected.
Aug. 2004	BNP-B2229D	<ul style="list-style-type: none">• Revised to comply with M60S system software versions C0, C1.
Dec. 2009	BNP-B2229E	<ul style="list-style-type: none">• Corrected the items below. #1284 ext20 bit: 0 Spindle speed clamp check P134 G96 Clamp Err. M01 1043 No spindle speed clamp• Mistakes corrected.

Notice

Every effort has been made to keep up with software and hardware revisions in the contents described in this manual. However, please understand that in some unavoidable cases simultaneous revision is not possible. Please contact your Mitsubishi Electric dealer with any questions or comments regarding the use of this product.

Duplication Prohibited

This manual may not be reproduced in any form, in part or in whole, without written permission from Mitsubishi Electric Corporation.

© 2002-2009 MITSUBISHI ELECTRIC CORPORATION
ALL RIGHTS RESERVED

 **MITSUBISHI ELECTRIC CORPORATION**
HEAD OFFICE : TOKYO BUILDING,2-7-3 MARUNOUCHI,CHIYODA-KU,TOKYO 100-8310,JAPAN

MODEL	M60/60S series
MODEL CODE	008-162
Manual No.	BNP-B2229E(ENG)